Anchorage, ACO Field Approval Work Aid

AIRWORTHINESS COMPLIANCE CHECKLIST:

ALTERNATE FUEL AND OIL LINE FABRICATIONAND INSTALLATION

I HAVE DETERMINED THE PLANNED ALTERATION TO BE IN COMPLIANCE WITH PARAGRAPH C, CHECKLIST APPLICABILI	ITY.

IA SIGNATURE	DATE
AIRCRAFT MAKE	MODEL
SERIAL# N#	

TABLE 4-1. Relocation of Engine Oil Cooler - Checklist Qualifications for Approved Data Review.

Item [1] Completed Initials	Planned FAA Approval Method			ect nted	CFR)	R)	Item to Consider or	DER Authority [3] (ref.	Other Guidance	
	DER 8110-3	FSDO ASI, 337, Block 3	Other (AC 43.13)	Subje Evalua	Subject Evaluated	Evaluate (14 CFF (CAR)	Intent of the regulation	8110.37	AC Orders Policy	AC 43- 13-1B/2A
				Loads	23.301	3.171	 LIMit load is maximum in service Analysis to LIM must produce no yield. Weight for test = bracket structure + associated hoses + oil in hoses. 			
				Factor of Safety	23.303	3.172	• ULTimate = LIMit load * 1.50 (50% margin of safety)			
				Strength and deformation	23.305	3.173	LIM with no yield. ULT with no failure.			
				Proof of Structure	23.307	3.174	• LIMit loads are determined by flight (man. & gust) and landing loads. For lack of this data the loads from 23.561 may be used (but not required).			
				Materials and Workmanship	23.603	3.292	 All materials must meet approved specifications. Hoses in fire area per TSO-C53a, type C/D. All non-standard aircraft hardware to be substantiated. Baffle material to withstand engine heat (ie. silicone impregnated fiberglass). Grommets, firewall bulkhead fittings, etc. 			
				Inspection Provisions	23.611	3.296	Inspection and servicing must be accomplished in an appropriate manner.			
				Fuel Flow	23.955	3.433	Use hose of equal or greater size.			

		Fuel System Lines and Fittings	23.993	3.550	 Support line so that no excessive vibration occurs. Provisions for flexibility for relative motion. Limitations of flexible hose. 		
		Fuel System Components	23.994	-	Protect hoses from wheels up landing (tric gear)		
		Fuel System Drains	23.999	3.553	Do not create new 'low spots'		
		Oil System Drain	23.1017	3.570	 Excessive vibration Flow rate, install equal or larger size. Breather lines must; not allow condensation to freeze and obstruct line not constitute fire hazard from foaming. not allow omitted oil from striking windshield. not discharge into induction air intake. not be prone to blockage by ice. 	AC 20-40	
		Instruction for Continued Aiworthiness	23.1529	-	See separate guidance.		
	****			******	• END *******************		