

- Figure 2.2.E General Description of Caisson N2  
Figure 2.2.F General Description of Caisson N3  
Figure 2.2.G General Description of Caisson Y1  
Figure 2.2.H General Description of Caisson Y2  
Figure 2.2.I General Description of Caisson Y3  
Figure 3.1.A Analysis Models  
Figure 3.1.B Element from a Beam Subjected to Pure Bending  
Figure 3.1.C Interpretation of Ultimate Strength for Fabricated Steel Cylinder Under Bending  
Figure 3.1.D(a) Assumed Elastic-Plastic Behavior of Steel  
Figure 3.1.D(b) Behavior of a Cylindrical Section in Bending  
Figure 3.1.E Behavior of a Cylindrical Section in Bending With Axial Load  
Figure 3.1.F Comparison of Moment Profiles  
Figure 3.1.G Computation of Residual Lean Angle  
Figure 3.1.H Lean at Mudline vs Load Factor  
Figure 3.3.A Residual Lean Angle vs Water Depth  
Figure 3.3.B Residual Lean Angle vs Water Depth  
Figure 3.3.C Residual Lean Angle vs Water Depth  
Figure 3.3.D Residual Lean Angle vs Water Depth  
Figure 3.3.E Residual Lean Angle vs Pile Diameter  
Figure 3.3.F Residual Lean Angle vs Pile Diameter

## 1.0 Introduction

On August 24, and 25, 1992 Hurricane Andrew passed through a region of the Gulf of Mexico that is densely populated with oil and gas structures. While most of these structures survived with minor or no damage, several structures were severely damaged or collapsed.

According to data gathered by the Mineral Management Service, MMS, about 100 caisson structures were tilted to various degrees during the passage of Hurricane Andrew. The MMS selected Barnett and Casbarian Inc.(BCI) to perform a study to develop an acceptance criteria for those caisson structures tilted by a storm and to develop guidelines for repair of those structures which do not meet the acceptance criteria. This report provides the results of that study.

## 1.1 Executive Summary

BCI's work scope included the following tasks: 1) data gathering and assimilation, 2) development of an acceptance criteria, and 3) damage assessment and repair guidelines. The primary concern of this study evolved to be the establishment of an acceptance criteria by which caissons which have been exposed to extreme environmental condition may be judged to be acceptable for future operations without any remediation.

A typical caisson structure has an outer caisson which is usually driven 100 to 300 feet into the seabed and has a series of inner production casings. The structural response is dominated by the outer caisson compared to all of the internal casings; thus, unless otherwise noted, caisson will refer to the outer tubular member of the caisson structure.

The data gathering stage was aided by the staff of the MMS in Metairie and resulted in obtaining data on damaged and undamaged caissons from three of the operating companies whose structures were within the path of Hurricane Andrew.

An extreme wave response analysis was performed using data for nine actual caisson structures provided by the operating companies and was performed on several idealized or equivalent caisson structures. The study of the equivalent structures was for various water depths, soil conditions, caisson size and penetration depths. Shown in Figure 1.1.A(a) is the conceptual plot of environmental load versus residual lean angle. As shown in part (b) of the figure, the lean angle may be due to straining of the steel caisson, the failure of the soil, or a combination of both.

The acceptance criteria focuses on structural integrity of the outer member or caisson structure rather than the inner casings and well strings. Except for the condition where massive soil failure occurs, unacceptable strain occurs in the caisson before it occurs in the casings. For the yielding caisson, the fundamental acceptance criteria assumed for this study is that the strain in the caisson be less than that which causes local buckling. An environmentally loaded caisson which is strained less than buckling should be capable of withstanding significant additional environmental loadings.

Based on the analyses of the actual caissons reported herein, the allowable residual lean of a caisson structure ranges from 1 to 6 degrees, depending of the specific design details of the caisson and the soil condition. We believe the analytical tools available to us to perform the analyses and the assumptions utilized, provide conservative results. Since our results could not be calibrated against actual field tests, we recommend that an allowable residual lean of 3 degrees is acceptable. A greater value will require a Level III (Reference 1) type underwater inspection and detailed calculations to show that a greater angle of lean is acceptable.

As revealed in the analysis of equivalent caissons, short, very thick walled caissons may have sufficient strength to not yield before massive soil failure. For this type of failure the operations of the well system is the constraining factor. Those constraints were not addressed in this report.

## 1.2 Report Layout

The major sections of the report include; 1) data gathering, 2) extreme wave response, 3) acceptance criteria and 4) damage assessment). The figures and tables associated with each section following the text of the section.





Figure 1.1.A  
Overview Of Caisson Failure

## 2.0 Data Gathering

### 2.1 Structures Within Hurricane Andrew Path

The data in Table 2.1.A is based on data provided by the Minerals Management Service(Ref. 1). It is not intended to be comprehensive, but does indicate the types of caissons that were damaged and the types of damage that were observed. The critical observation from these data was that lean greater than 15 degrees was measured for several of the caissons after Hurricane Andrew.

In order to gain an insight into the impact of Hurricane Andrew on the population of caisson structures, Barnett and Casbarian Inc.'s data base on platforms was interrogated for the resulting data shown in Table 2.1.B. Table 2.1.B lists all minimum structures within a fifty mile distance from the path (Ref. 2) of Hurricane Andrew. (This data base was developed from information obtained from the MMS). Unfortunately, it was not possible to distinguish between single caissons and other minimal structures. The constraints listed at the first of Table 2.1.B were used in the extraction of the caissons and the minimal structures from the structures data base.

The values from Table 2.1.B are used to generate the data shown in Figure 2.1.A. That figure is a plot of minimal structures versus distance from the path. The most significant observation from this plot is that about 40% of the minimal structures within 10 miles of the path were damaged. The fact that many structures in the hurricane path were undamaged indicates that the response of caisson structures is highly variable.

## 2.2 Structures Selected for Detailed Evaluation

Three operators were requested to supply information on some of their caisson structures which were within the Hurricane Andrew path. Data on both damaged and undamaged structures were received. As the intent of this study was to address structures which are representative of a larger population, the caisson structures listed in Table 2.2.A were selected for analysis. Table 2.2.A lists the general dimensions of the caisson as well as the hurricane damage. In Table 2.2.B are listed the configuration of the inner casings. Some of the data was unavailable. However, it is assumed from the data shown that none of the caissons are grouted to the first inner casing and that only the L1, L2 and L3 structures may have loading on the caisson from the inner casings. In order to make some assessment of the impact of potential loading of the inner casings on the caisson behavior, Ref. 9 was used to obtain the estimate (650 kips) shown in Table 2.2.B. In later reporting of results the caisson evaluations without casing loading are labeled L1, L2 and L3; and the results with loading are labeled as L1\*, L2\* and L3\*.

In Figures 2.2.A-I are the data for each of the nine caissons. Shown are the configuration, the deck loading, the wave load profile, and the soil description that was used for the each of the analyses presented in Section 3.

TABLE 2.1.A  
WELL STRUCTURES DAMAGED BY HURRICANE ANDREW

Type  
 C - Caisson, Damaged  
 J - Minimal Structure, Damaged  
 - Undamaged

Type		Area	Block	ft	Structure Name	Installed Year	Distance to Path, Miles	Damage Description	Operator
1	J	PL	0019	30	WG#14	81	11	Leaning 25°	Murphy
2	J	PL	0020	29	WG#13	67	11	0° to 1° Lean	Murphy
3	J	SS	0093	25	WG#12	77	4	Leaning 30°	Murphy
4	J	SS	0093	32	#53	87	4	Toppled	Murphy
5	J	SS	0108	20	SAT#10	61	7	Leaning 5°	Chevron
6	J	SS	0112	47	#5	86	0	Leaning 6°	Murphy
7	J	SS	0114	46	#50	84	2	Toppled	Murphy
8	J	SS	0114	50	#57	86	2	Toppled	Murphy
9	J	SS	0114	51	#60	85	3	Leaning 80°	Murphy
10	J	SS	0114	53	#61	86	3	Leaning 10°	Murphy
11	J	SS	0117	53	#3	82	2	Leaning 20°	Murphy
12	J	SS	0119	43	WG#5	73	2	Leaning 2.5°	Murphy
13	J	SS	0134	60	20	85	8	Toppled	Murphy
14	J	SS	0136	56	#1	83	4	Leaning 30°	Murphy
15	J	ST	0086	110	#20	83	22	Toppled	Odeco
16	J	ST	143	?	A1,A2,A3	?	1?	Toppled	Hall-Hous
17	J	ST	144	?	A1,A2	?	1?	Toppled	Hall-Hous
18	C	PL	0009	40	WG#4	80	15	Leaning 5°	Mobil
19	C	PL	0009	40	9	85	14	Toppled	Mobil
20	C	PL	0010	35	#18	87	12	Toppled	Mobil
21	C	PL	0010	40	17	84	13	Leaning 12°	Mobil
22	C	PL	0011	37	#22	84	13	Leaning 2°	Mobil
23	C	PL	0012	25	#12, 15	64	12	Toppled	Murphy
24	C	PL	0012	25	#18	85	14	Leaning 2°	Murphy
25	C	PL	0012	28	WG#7	63	12	Toppled	Murphy
26	C	PL	0012	28	#43	87	12	Leaning 7°	Murphy
27	C	PL	0012	38	#23	78	13	Leaning 3°	Murphy
28	C	PL	0019	28	WG#37	81	12	Leaning 4°	Murphy
29	C	PL	0019	30	#33,39,42	81	11	Leaning 8°	Murphy
30	C	PL	0019	30	#35	81	12	Leaning 5°	Murphy
31	C	PL	0019	32	#44	85	11	Leaning 5°	Murphy
32	C	PL	0019	?	48	?	11?	Leaning 20°	Murphy
33	C	PL	0020	28	WG#15&27	68	11	Leaning 15°-27°	Murphy
34	C	PL	0020	28	38	85	11	Leaning 3°	Murphy
35	C	PL	0020	29	#33	85	11	Leaning 7°	Murphy
36	C	PL	0020	30	#28&29	81	11	Leaning 7°	Murphy
37	C	PL	0020	30	#36	85	11	Leaning 5°	Murphy
38	C	PL	0020	30	#32	85	11	Leaning 4°	Murphy
39	C	PL	0020	30	#35	86	11	Leaning 2°	Murphy
40	C	PL	0020	30	40,42,46	86	11	Leaning 9°	Murphy
41	C	PL	0020	30	39	87	11	Leaning 5°	Murphy
42	C	PL	0020	32	WG 8 &25	63	11	Toppled	Murphy
43	C	SS	0069	30	#8	84	10	Leaning 10°	Chevron
44	C	SS	0090	33	#2	86	6	Leaning 2°	Murphy
45	C	SS	0090	?	56	?	97	Leaning 10°	Murphy
46	C	SS	0092	24	#3 & #5	90	8	Leaning 3°	Murphy
47	C	SS	0092	?	7	?	8?	Leaning 25°	Murphy
48	C	SS	0092	?	8	?	8?	Leaning 2°	Murphy
49	C	SS	0093	20	#49	88	6	Leaning 1°	Murphy
50	C	SS	0093	25	33	78	5	Leaning 4°	Murphy
51	C	SS	0093	25	#32	78	5	Leaning 5°	Murphy
52	C	SS	0093	25	#38	83	6	Leaning 3°	Murphy

TABLE 2.1.A  
WELL STRUCTURES DAMAGED BY HURRICANE ANDREW

Type

- C - Caisson, Damaged  
J - Minimal Structure, Damaged  
- Undamaged

Type	Area	Block	ft	Structure Name	Year	Installed	Distance to Path, Miles	Damage Description		Operator
53	C	SS	0093	28	47	85	6	Leaning 3°		Murphy
54	C	SS	0093	28	0	89	5	Leaning 3°		Murphy
55	C	SS	0093	28	#45 CAISSON	90	6	Leaning 1°		Murphy
56	C	SS	0093	30	#37	84	4	Leaning 5°		Murphy
57	C	SS	0093	45	#39	82	5	Leaning 4°		Murphy
58	C	SS	0094	22	#23 or S	87	4	Leaning 4°		Murphy
59	C	SS	0094	30	19	81	4	Leaning 4°		Murphy
60	C	SS	0094	32	#17	79	3	Leaning 4°		Murphy
61	C	SS	0094	50	WG#20	79	4	Leaning 4°		Murphy
62	C	SS	0099	21	#2	61	7	Broken at Mudline		Chevron
63	C	SS	0112	48	S(S1&S2)	86	0	Leaning 5°		Murphy
64	C	SS	0112	48	#6	87	0	Leaning 5°		Murphy
65	C	SS	0112	?	4&7	?	17	Leaning 5°		Murphy
66	C	SS	0113	39	WG#19	67	3	Toppled		Murphy
67	C	SS	0113	40	WG #35	80	3	Leaning 15°		Murphy
68	C	SS	0113	41	WG#41	85	2	Leaning 10°		Murphy
69	C	SS	0113	45	45	90	1	Toppled		Murphy
70	C	SS	0113	46	#40	84	2	Leaning 10°		Murphy
71	C	SS	0113	47	#47 - 49	89	1	Leaning 48°		Murphy
72	C	SS	0113	47	48	89	1	Toppled		Murphy
73	C	SS	0113	?	51	?	37	Leaning 15°		Murphy
74	C	SS	0113	?	52	?	37	Leaning 5°		Murphy
75	C	SS	0113	49	29,32	78	2	Leaning 2.5°		Murphy
76	C	SS	0113	50	#46	86	2	Toppled		Murphy
77	C	SS	0114	40	#55	81	2	Leaning 45°		Murphy
78	C	SS	0114	40	WG#43	81	4	Leaning 45°		Murphy
79	C	SS	0114	41	WG #41	80	3	Leaning 30°		Murphy
80	C	SS	0114	50	WG38	76	3	Toppled		Murphy
81	C	SS	0114	50	WG#39&9	79	2	Leaning 5°		Murphy
82	C	SS	0114	?	1	?	47	Toppled		Murphy
83	C	SS	0114	?	36	?	47	Toppled		Murphy
84	C	SS	0114	50	#51	82	3	Leaning 30°		Murphy
85	C	SS	0114	50	#46	83	2	Leaning 35°		Murphy
86	C	SS	0114	51	#12 WELL	67	2	Leaning 15°		Murphy
87	C	SS	0114	52	#9	65	2	Toppled		Murphy
88	C	SS	0114	55	#47	82	2	Leaning 4°		Murphy
89	C	SS	0117	50	#2	81	2	Leaning 30°		Murphy
90	C	SS	0117	55	#5&#6	89	2	Leaning 10°		Murphy
91	C	SS	0117	55	#7	90	1	Leaning 45°		Murphy
92	C	SS	0118	50	NO.3	79	0	Leaning 5°		Murphy
93	C	SS	0118	50	WG #4	79	0	Leaning 10°		Murphy
94	C	SS	0118	7	9	?	17	Toppled		Murphy
95	C	SS	0119	45	14	82	2	Leaning 10°		Murphy
96	C	SS	0119	47	#9	82	2	Leaning 5°		Murphy
97	C	SS	0119	48	#21	86	3	Leaning 10°		Murphy
98	C	SS	0119	50	WG#15	76	2	Leaning 3°		Murphy
99	C	SS	0120	35	3	84	6	Leaning 5°		Murphy
100	C	SS	0120	35	WG#2	83	5	Leaning 5°		Murphy
101	C	SS	0120	40	NO.4	79	4	Leaning 2°		Murphy
102	C	SS	0120	40	4	83	4	Leaning 20°		Murphy
103	C	SS	0120	40	#1	83	4	Leaning 5°		Murphy
104	C	SS	0120	41	NO.5	79	3	Leaning 2°		Murphy
105	C	SS	0120	42	#3	78	3	Leaning 5°		Murphy
106	C	SS	0120	42	#13	87	3	Leaning 15°		Murphy

TABLE 2.1.A  
WELL STRUCTURES DAMAGED BY HURRICANE ANDREW

Type  
 C - Caisson, Damaged  
 J - Minimal Structure, Damaged  
 - Undamaged

Type	Area	Block	W.D.		Installed Year	Distance to Path, Miles	Damage Description	Operator	
			ft	Structure Name					
107	C	SS	0120	47	#5	84	5	Leaning 2°	Murphy
108	C	SS	0134	43	1	83	9	Leaning 5°	Murphy
109	C	SS	0134	43	3	83	7	Leaning 5°	Murphy
110	C	SS	0134	43	4	83	9	Leaning 5°	Murphy
111	C	SS	0134	44	6	83	8	Leaning 3°	Murphy
112	C	SS	0134	45	2	83	8	Leaning 5°	Murphy
113	C	SS	0134	45	5	83	7	Leaning 5°	Murphy
114	C	SS	0134	45	9	84	8	Leaning 5°	Murphy
115	C	SS	0134	45	#8	84	7	Leaning 5°	Murphy
116	C	SS	0134	45	#10	84	9	Leaning 5°	Murphy
117	C	SS	0134	60	#7	83	8	Leaning 45°	Murphy
118	C	SS	0134	60	#11	84	9	Leaning 5°	Murphy
119	C	SS	0134	60	#12	84	9	Leaning 5°	Murphy
120	C	SS	0134	60	#13	84	8	Leaning 5°	Murphy
121	C	SS	0134	60	#14	84	7	Leaning 5°	Murphy
122	C	SS	0134	?	#15	?	??	Leaning 5°	Murphy
123	C	SS	0134	?	#17	?	??	Leaning 5°	Murphy
124	C	SS	0134	60	#18	84	9	Leaning 5°	Murphy
125	C	SS	0134	60	16	84	8	Leaning 5°	Murphy
126	C	SS	0135	44	#10	83	7	Leaning 10°	Murphy
127	C	SS	0135	45	#5	82	6	Leaning 5°	Murphy
128	C	SS	0135	45	#4	83	7	Leaning 5°	Murphy
129	C	SS	0135	46	6	83	7	Leaning 5°	Murphy
130	C	SS	0135	50	#3	82	5	Leaning 5°	Murphy
131	C	SS	0135	55	#12	83	6	Leaning 5°	Murphy
132	C	SS	0135	55	#13	84	8	Leaning 5°	Murphy
133	C	SS	0135	65	7	83	6	Leaning 3°	Murphy
134	C	SS	0135	113	WG#8	83	8	Leaning 5°	Murphy
135	C	SS	0136	50	#2	87	4	Leaning 20°	Murphy
136	C	SS	0136	50	3	87	6	Toppled	Murphy
137	C	SS	0166	60	#2	84	8	Leaning 20°	Murphy
138	C	SS	0166	60	#1	85	9	Leaning 12°	Murphy
139	C	SS	0166	7	#3	?	??	Leaning 2°	Murphy
140	C	SS	0167	50	#8 PLATFORM	90	10	Leaning 8°	Murphy
141	C	SS	0167	80	#5	70	10	Leaning 7°	Murphy
142	C	SS	0167	80	#7	78	10	Leaning 7°	Murphy
143	C	SS	0167	?	#9	?	10?	Leaning 35°	Murphy
144	C	ST	0052	60	12,14,15	77	17	Severed 5' above Mud Line	Chevron
145	C	ST	0086	92	12	84	23	Toppled	Odeco

128 Number of Caissons Damaged  
 17 Number of Minimal Structures Damaged

145 Total Number of Structures

**MMS Caisson Study**  
**Well Structures Within 50 Miles of Hurricane Andrew**  
**Data Base Construction**

**Data Base from Minerals Management Services, MMS**

The filters listed below were used to obtain the final print output:

All data base structures were included between State Plane Coordinates:  
X=1,780,205 and X=2,428,144

Structures with heliports were excluded

Structures with living quarters were excluded

Structures with production equipment were excluded

Structures with power generation were excluded

Structures with gas compression were excluded

Structures with storage tanks were excluded

Major structures were excluded

Structures with more than 3 well slots were excluded

Structures with water depths more than 150' were excluded

Structures more than 50 miles from the storm track were excluded

Structures that were listed as being removed were excluded

Table 2.1.B

TABLE 2.1.B  
WELL STRUCTURES WITHIN 50 MILES OF HURRICANE ANDREW

Type

C - Caisson, Damaged

? - Distance uncertain

J - Minimal Structure, Damaged

- Undamaged

W.D.	Type	Area	Block	ft.	Structure Name	Installed Year	Distance to Path, miles	Damage Description	Operator
1		BM	0002	40	28	69	40		Chevron
2		BM	0002	45	#42	73	41		Chevron
3		BM	0002	47	1368 #43	73	40		Chevron
4		BM	0002	50	9	61	40		Chevron
5		BM	0002	50	50	84	40		Chevron
6		BM	0003	30	#12	71	39		Chevron
7		BM	0003	42	#28	84	40		Chevron
8	EI	0010	9	4	4	82	4		Chevron
9	EI	0024	13	7	7	82	5		Amerada Hess
10	EI	0026	17	5	5	88	9		Murphy
11	EI	0026	20	2	2	80	11		Texaco Inc.
12	EI	0026	20	4	4	86	10		Murphy
13	EI	0028	20	#6	#6	89	10		Texaco Inc.
14	EI	0028	20	8	8	90	10		Texaco Inc.
15	EI	0028	12	#2 CAISSON	#2 CAISSON	88	6		Texaco Inc.
16	EI	0032	12	6	6	64	1		Kerr-McGee
17	EI	0032	12	19	19	69	1		Union Oil
18	EI	0032	12	8	8	64	2		Union Oil
19	EI	0032	12	18	18	65	1		Union Oil
20	EI	0032	12	16	16	64	2		Union Oil
21	EI	0032	12	17	17	65	1		Union Oil
22	EI	0032	12	11	11	57	2		Union Oil
23	EI	0032	12	9	9	65	2		Union Oil
24	EI	0032	12	20	20	72	2		Union Oil
25	EI	0032	12	10	10	65	1		Union Oil
26	EI	0032	12	15	15	64	2		Union Oil
27	EI	0032	12	5	5	59	2		Union Oil
28	EI	0032	14	NO. 14	NO. 14	58	1		Union Oil
29	EI	0033	10	1	1	83	3		Cockrell Oil
30	EI	0033	10	2	2	86	3		Cockrell Oil
31	EI	0033	10	3 CAISSON	3 CAISSON	88	3		Cockrell Oil
32	EI	0038	10	1	1	75	4		Marathon
33	EI	0038	10	2 & 5	2 & 5	76	5		Marathon
34	EI	0038	10	6	6	76	4		Marathon
35	EI	0038	10	10	10	78	3		Marathon
36	EI	0038	10	12	12	78	4		Marathon
37	EI	0038	10	14	14	78	3		Marathon
38	EI	0038	11	3	3	76	3		Marathon
39	EI	0041	15	1	1	83	2		Marathon
40	EI	0042	14	4	4	83	3		Chevron
41	EI	0042	15	6	6	84	2		Pennzoil
42	EI	0044	21	4	4	84	6		Pennzoil
43	EI	0045	21	5	5	85	9		General Atlantic Resources
44	EI	0045	22	#8	#8	89	9		Seagull Energy
45	EI	0047	21	11	11	87	10		Seagull Energy
46	EI	0047	23	8	8	81	11		Murphy
47	EI	0047	23	9	9	81	11		Murphy
48	EI	0051	20	1	1	61	8		Murphy
49	EI	0051	21	2	2	61	8		Mobil
50	EI	0051	22	4	4	63	8		Mobil
51	EI	0052	25	4	4	81	5		Mobil
52	EI	0052	25	5	5	82	6		Pennzoil
53	EI	0053	21	2	2	59	6		Pennzoil

TABLE 2.1.B  
WELL STRUCTURES WITHIN 50 MILES OF HURRICANE ANDREW

Type

C - Caisson, Damaged

? - Distance uncertain

J - Minimal Structure, Damaged

- Undamaged

Type	Area	Block	W.D. ft.	Structure Name	Installed Year	Distance to		Damage Description	Operator
						Path, miles			
54	EI	0053	21	#6	86	4			Pennzoil
55	EI	0058	9	1	82	1			Marathon
56	EI	0058	11	#2	89	2			Marathon
57	EI	0058	11	#3	90	2			Marathon
58	EI	0057	10	1	74	4			Marathon
59	EI	0057	10	2	74	4			Marathon
60	EI	0057	12	4	75	2			Marathon
61	EI	0057	12	6	76	3			Marathon
62	EI	0057	14	3	75	3			Marathon
63	EI	0057	29	12	82	3			Marathon
64	EI	0058	10	1	76	4			Marathon
65	EI	0058	12	2	76	4			Marathon
66	EI	0062	25	3	83	4			Marathon
67	EI	0062	25	4	83	4			Hunt Oil
68	EI	0063	22	2	79	6			Hunt Oil
69	EI	0063	22	5	83	6			Hunt Oil
70	EI	0064	22	4	73	7			Hunt Oil
71	EI	0064	25	1	71	8			Chevron
72	EI	0074	18	3	72	11			Chevron
73	EI	0074	18	#4 & #5	72	11			Chevron
74	EI	0076	22	4	85	7			Chevron
75	EI	0076	28	1	84	6			Hunt Oil
76	EI	0076	28	2	84	6			Hunt Oil
77	EI	0077	22	4	80	5			Hunt Oil
78	EI	0077	22	9	83	7			Hunt Oil
79	EI	0077	22	10	84	5			Hunt Oil
80	EI	0077	23	5	81	5			Hunt Oil
81	EI	0077	25	2 A	56	5			Hunt Oil
82	EI	0077	25	6	83	5			Hunt Oil
83	EI	0089	30	11	67	16			Gulfstream Resources
84	EI	0089	30	19	83	18			Gulfstream Resources
85	EI	0090	22	9	70	19			Gulfstream Resources
86	EI	0090	22	0228-10	82	19			Gulfstream Resources
87	EI	0090	22	11	83	18			Gulfstream Resources
88	EI	0093	20	8	68	19			Gulfstream Resources
89	EI	0093	22	2	59	19			Gulfstream Resources
90	EI	0093	23	9	82	19			Gulfstream Resources
91	EI	0093	25	11	83	19			Gulfstream Resources
92	EI	0093	25	12	84	19			Gulfstream Resources
93	EI	0094	33	1	84	20			Gulfstream Resources
94	EI	0095	17	3	67	17			Gulfstream Resources
95	EI	0095	19	5	70	17			Gulfstream Resources
96	EI	0095	19	12	71	17			Gulfstream Resources
97	EI	0095	20	9	71	17			Gulfstream Resources
98	EI	0095	22	8	71	17			Gulfstream Resources
99	EI	0097	25	#1 CAISSON	89	14			Gulfstream Resources
100	EI	0100	23	JC19	61	9			NERCO
101	EI	0100	23	18/30	61	9			Shell
102	EI	0100	23	JA15	61	8			Shell
103	EI	0100	23	13	60	8			Shell
104	EI	0100	23	7	60	8			Shell
105	EI	0100	23	4	60	8			Shell
106	EI	0105	24	5	61	9			Shell
107	EI	0105	24	2	61	10			Mobil
108	EI	0105	24	F	79	10			Mobil
									Mobil

TABLE 2.1.B  
WELL STRUCTURES WITHIN 50 MILES OF HURRICANE ANDREW

Type

C - Calson, Damaged

7 - Distance uncertain

J - Minimal Structure, Damaged

- Undamaged

W.D.

Installed

Distance to

Path, miles

Damage Description

Type	Area	Block	ft.	Structure Name	Year	Path, miles	Damage Description	Operator
109	EI	0105	24	3	61	10		Mobil
110	EI	0107	28	4	90	15		NERCO
111	EI	0107	31	3	87	14		Atlantic Richfield
112	EI	0108	26	7	85	15		NERCO
113	EI	0108	26	9	87	15		NERCO
114	EI	0116	48	G	89	20		Mobil
115	EI	0116	50	#10	87	20		Mobil
116	EI	0116	50	#11	88	20		Mobil
117	EI	0116	50	#12	89	20		Mobil
118	EI	0119	33	13	64	13		Mobil
119	EI	0119	34	16	64	13		Mobil
120	EI	0119	35	4	62	14		Mobil
121	EI	0119	35	8	62	14		Mobil
122	EI	0119	35	15	64	13		Mobil
123	EI	0119	36	14	64	13		Mobil
124	EI	0119	36	5	62	14		Mobil
125	EI	0119	36	32	84	14		Mobil
126	EI	0119	38	#30	89	14		Mobil
127	EI	0119	37	7	62	14		Mobil
128	EI	0119	37	12	64	13		Mobil
129	EI	0119	37	26	67	14		Mobil
130	EI	0119	38	M-4	89	14		Mobil
131	EI	0119	38	11	63	13		Mobil
132	EI	0119	45	27	68	14		Mobil
133	EI	0120	36	3	66	13		Mobil
134	EI	0120	36	7	69	13		Mobil
135	EI	0120	36	11 CAISSON	88	13		Mobil
136	EI	0125	40	3 & 4	72	14		Mobil
137	EI	0125	40	#5	89	14		Mobil
138	EI	0125	41	2	60	15		Mobil
139	EI	0126	40	5	64	15		Mobil
140	EI	0126	40	7	70	15		Mobil
141	EI	0128	52	5	84	20		Mobil
142	EI	0128A	51	3	59	21		Shell
143	EI	0128A	51	4	59	21		Shell
144	EI	0128A	51	5	59	21		Shell
145	EI	0128A	56	6	59	21		Shell
146	EI	0128A	60	19	87	21		Shell
147	EI	0129	52	1	59	20		Mobil
148	EI	0159	70	#1	81	30		Amerada Hess
149	EI	0189	65	1	56	22		Shell
150	EI	0189	65	2	59	22		Shell
151	EI	0189	65	3	59	22		Shell
152	EI	0189	65	4	59	22		Shell
153	EI	0189	65	6	59	22		Shell
154	EI	0189	65	8	60	22		Shell
155	EI	0189	113	4	66	40		DelMar Operating, Inc.
156	EI	0214	107	2	76	33		Chevron
157	EI	0224	135	#2	89	45		Amoco
158	EI	0230	123	CC	78	37		Chevron
159	GI	0028	24	SAT#14	73	42		Chevron
160	GI	0026	42	SAT#1	57	43		Chevron
161	GI	0037	50	#22	69	40		Chevron
162	PL	0009	35	#7	81	14		Chevron
163	C	PL	0009	40	WG#4	80	15	Mobil
							Leaning 5°	Mobil

TABLE 2.1.B  
WELL STRUCTURES WITHIN 50 MILES OF HURRICANE ANDREW

Type

C - Caisson, Damaged

? - Distance uncertain

J - Minimal Structure, Damaged

- Undamaged

W.D.

Installed

Distance to

Type	Area	Block	ft.	Structure Name	Year	Path, miles	Damage Description	Operator
164		PL	0009	40	WG#6	80	13	
165		PL	0009	40	8	82	15	
166	C	PL	0009	40	9	85	14	
167		PL	0010	35	15	83	14	Toppled
168		PL	0010	35	#19	83	12	
169	C	PL	0010	35	#18	87	12	Toppled
170		PL	0010	40	#11	80	14	
171		PL	0010	40	14	81	14	
172		PL	0010	40	2924#2	81	14	
173	C	PL	0010	40	17	84	13	Leaning 12°
174		PL	0010	40	WG #20	88	14	
175		PL	0011	24	WG#15	69	11	
176		PL	0011	28	WG#7	66	12	
177		PL	0011	35	WG#10	67	12	
178		PL	0011	35	#24	85	12	
179	C	PL	0011	37	#22	84	13	Leaning 2°
180		PL	0011	40	17	78	11	
181		PL	0011	40	#18	78	12	
182	C	PL	0012	25	#12, 15	64	12	Toppled
183		PL	0012	25	#16/17	80	13	
184	C	PL	0012	25	#18	85	14	Leaning 2°
185	C	PL	0012	28	WG#7	63	12	Toppled
186	C	PL	0012	28	#43	87	12	Leaning 7°
187		PL	0012	30	#25	81	13	
188		PL	0012	30	#32	84	14	
189		PL	0012	30	#19	85	14	
190		PL	0012	30	20	85	13	
191		PL	0012	32	NO.29	79	14	
192		PL	0012	32	NO.30	79	13	
193		PL	0012	32	C-1	85	14	
194		PL	0012	34	WG #28	84	13	
195		PL	0012	35	22	78	13	
196		PL	0012	35	#31	79	14	Leaning 2°
197		PL	0012	35	#26	79	13	
198		PL	0012	35	WG #33 & #42	79	13	
199		PL	0012	35	F (35)	84	13	
200	C	PL	0012	36	#23	78	13	Leaning 3°
201		PL	0012	36	#24-C	79	14	
202		PL	0012	36	#27	79	13	
203		PL	0012	36	37	85	14	
204		PL	0019	27	21&52	73	11	
205		PL	0019	28	#22/#38	73	11	
206		PL	0019	28	WG#6/#7	61	11	
207	C	PL	0019	28	WG#37	81	12	Leaning 4°
208	J	PL	0019	30	WG#14	81	11	Leaning 25°
209	C	PL	0019	30	#33,39,42	81	11	Leaning 8°
210	C	PL	0019	30	#35	81	12	Leaning 5°
211		PL	0019	32	25,26 WG	75	11	
212	C	PL	0019	32	#44	85	11	Leaning 5°
213		PL	0019	45	29	80	10	
214		PL	0019	45	34	80	10	
215	C	PL	0019	117	48	?		Leaning 20°
216	C	PL	0020	28	WG#15&27	68	11	Leaning 15°-27°
217	C	PL	0020	28	38	85	11	Leaning 3°
218	J	PL	0020	29	WG#13	67	11	0° to 1° Lean

TABLE 2.1.B  
WELL STRUCTURES WITHIN 50 MILES OF HURRICANE ANDREW

Type

C - Caisson, Damaged

? - Distance uncertain

J - Minimal Structure, Damaged

- Undamaged

Type	Area	Block	ft.	Structure Name	Installed Year	Distance to Path, miles	Damage Description		Operator
219	PL	0020	29	WG#9(12)	67	11			Murphy
220	C	PL	0020	29	#33	85	11		Murphy
221		PL	0020	30	WG#24	71	11		Murphy
222	C	PL	0020	30	#28&29	81	11		Murphy
223	C	PL	0020	30	#38	85	11	Leaning 7°	Murphy
224	C	PL	0020	30	#32	85	11	Leaning 5°	Murphy
225	C	PL	0020	30	#35	86	11	Leaning 4°	Murphy
226	C	PL	0020	30	40,42,46	86	11	Leaning 2°	Murphy
227	C	PL	0020	30	39	87	11	Leaning 9°	Murphy
228		PL	0020	31	WG#17	70	11	Leaning 5°	Murphy
229	C	PL	0020	32	WG 8 &25	83	11	Toppled	Murphy
230		PL	0023	61	1238#1	62	10		Stone Petroleum
231		PL	0023	61	1244#1	62	10		Stone Petroleum
232		SM	0011	62	11	66	34		Forcenergy Gas
233		SM	0011	68	29	70	34		Forcenergy Gas
234		SM	0011	68	21	67	34		Forcenergy Gas
235		SM	0011	68	17	67	33		Forcenergy Gas
236		SM	0011	68	15	67	34		Forcenergy Gas
237		SM	0011	68	14	67	33		Forcenergy Gas
238		SM	0011	68	13	67	33		Forcenergy Gas
239		SM	0011	68	24	68	34		Forcenergy Gas
240		SM	0011	68	50	86	34		Forcenergy Gas
241		SM	0011	70	16	67	34		Forcenergy Gas
242		SM	0011	70	48	72	34		Forcenergy Gas
243		SM	0011	70	1	62	34		Forcenergy Gas
244		SM	0048	100	5	87	42		Forcenergy Gas
245		SM	0229	20	141	88	13		Pennzoil
246		SM	0236	14	#144	89	14		Texaco
247		SM	0236	14	#160	89	15		Texaco
248		SM	0236	14	#161	89	14		Texaco
249		SM	0236	18	128	85	14		Texaco
250		SM	0236	18	139	87	14		Texaco
251		SM	0236	18	142	88	15		Texaco
252		SM	0236	20	100	83	14		Texaco
253		SM	0238	20	101	83	13		Texaco
254		SM	0236	20	107	84	14		Texaco
255		SM	0236	20	138	88	15		Texaco
256		SM	0236	20	1	82	15		Texaco
257		SM	0238	18	133	85	10		Texaco
258		SM	0238	18	129/130	85	10		Texaco
259		SM	0238	18	137	85	10		Texaco
260		SM	0239	17	143	88	9		Texaco
261		SM	0239	18	91	85	10		Texaco
262		SM	0239	18	132	85	10		Texaco
263		SM	0241	23	301	82	13		Texaco
264		SM	0241	23	302	83	12		Texaco
265		SM	0242	20	111	84	15		Texaco
266		SM	0256	25	1	87	20		Pennzoil
267		SS	0014	10	#2	85	8		Kerr-McGee
268		SS	0014	12	WG#1	66	6		Kerr-McGee
269		SS	0026	8	WG#4	69	9		Four Star Oil & Gas
270		SS	0026	9	#9	75	9		Four Star Oil & Gas
271		SS	0026	10	10	79	9		Four Star Oil & Gas
272		SS	0026	10	NO.12	79	9		Four Star Oil & Gas
273		SS	0028	10	#13	82	9		Four Star Oil & Gas

TABLE 2.1.B  
WELL STRUCTURES WITHIN 50 MILES OF HURRICANE ANDREW

Type

C - Caisson, Damaged

? - Distance uncertain

J - Minimal Structure, Damaged

- Undamaged

Type	Area	Block	ft.	Structure Name	Installed Year	Distance to Path, miles		Damage Description	Operator
274		SS 0026	10	#1	87	10			Phillips
275		SS 0027	9	#2	81	8			Kerr-McGee
276		SS 0027	15	#4	82	8			Kerr-McGee
277		SS 0028	12	#6-(I-1)	59	5			Kerr-McGee
278		SS 0028	12	WG#23	65	5			Kerr-McGee
279		SS 0028	12	WG#29	67	5			Kerr-McGee
280		SS 0028	12	#4-(G-1)	58	5			Kerr-McGee
281		SS 0028	12	WG#30	67	5			Kerr-McGee
282		SS 0028	12	#34	78	5			Kerr-McGee
283		SS 0029	12	#3-(U-1)	62	5			Kerr-McGee
284		SS 0029	12	WG#B	68	5			Kerr-McGee
285		SS 0029	13	WG#8	65	5			Kerr-McGee
286		SS 0030	18	#11 CAISSON	88	1			Kerr-McGee
287		SS 0032	15	#19	85	1			Kerr-McGee
288		SS 0032	15	#20	89	1			Kerr-McGee
289		SS 0032	18	#14	75	3			Kerr-McGee
290		SS 0032	19	1	64	1			Kerr-McGee
291		SS 0032	19	#15	75	3			Kerr-McGee
292		SS 0032	19	WG#18	77	3			Kerr-McGee
293		SS 0033	15	#8	76	2			Kerr-McGee
294		SS 0033	17	D	50	0			Kerr-McGee
295		SS 0033	19	WG #11	78	2			Kerr-McGee
296		SS 0037	9	#2	89	8			Aquila Energy
297		SS 0063	25	#21	85	7			Mobil
298		SS 0063	33	#9	82	6			Mobil
299		SS 0063	33	#10	83	7			Mobil
300		SS 0064	25	#1	82	10			Chvron
301		SS 0068	26	#5	89	11			Chvron
302		SS 0068	28	#3	85	11			Chvron
303		SS 0066	30	#1	85	10			Chvron
304		SS 0066	30	#2	85	10			Chvron
305		SS 0068	40	#1	79	11			Chvron
306		SS 0069	26	#10	85	9			Mobil
307		SS 0069	27	#4	83	11			Chvron
308		SS 0069	27	#5	84	10			Chvron
309		SS 0069	27	#7	84	10			Chvron
310		SS 0089	29	#6	84	10			Chvron
311	C	SS 0069	30	#8	84	10	Leaning 10°		Chvron
312		SS 0069	30	#9	84	10			Chvron
313		SS 0069	30	#11	85	9			Chvron
314		SS 0069	35	#13	89	10			Chvron
315		SS 0072	30	23	84	5			Chvron
316		SS 0072	32	#13	77	4			Mobil
317		SS 0072	40	#17	78	4			Mobil
318	C	SS 0090	33	#2	86	6	Leaning 2°		Murphy
319	C	SS 0090	97	56	?		Leaning 10°		Murphy
320	C	SS 0092	24	#3 & #5	90	8	Leaning 3°		Murphy
321	C	SS 0092	87	7	?		Leaning 25°		Murphy
322	C	SS 0092	87	8	?		Leaning 2°		Murphy
323		SS 0093	20	44	83	6			Murphy
324	C	SS 0093	20	#49	88	6	Leaning 1°		Murphy
325		SS 0093	22	WG#13	72	6			Murphy
326		SS 0093	22	M-1	84	6			Murphy
327		SS 0093	23	#40	83	6			Murphy
328		SS 0093	24	WG#22	72	7			Murphy

TABLE 2.1.B  
WELL STRUCTURES WITHIN 50 MILES OF HURRICANE ANDREW

Type

C - Caisson, Damaged

? - Distance uncertain

J - Minimal Structure, Damaged

- Undamaged

Type	Area	Block	W.D. ft.	Structure Name	Installed Year	Distance to Path, miles	Damage Description		Operator
329	SS	0093	24	WG#17	72	7			Murphy
330	SS	0093	24	WG#18	72	7			Murphy
331	SS	0093	24	29	77	5			Murphy
332	SS	0093	24	#35	79	5			Murphy
333	SS	0093	25	WG18(2B)	72	7			Murphy
334	C	SS	0093	25	33	78	5	Leaning 4°	Murphy
335	C	SS	0093	25	#32	78	5	Leaning 5°	Murphy
336	J	SS	0093	25	WG#12	77	4	Leaning 30°	Murphy
337	C	SS	0093	25	#38	83	6	Leaning 3°	Murphy
338		SS	0093	25	48	85	8		Murphy
339		SS	0093	26	WG#9	70	5		Murphy
340		SS	0093	28	WG#6	69	4		Murphy
341		SS	0093	28	#31	82	5		Murphy
342	C	SS	0093	28	47	85	6	Leaning 3°	Murphy
343	C	SS	0093	28	0	89	5	Leaning 3°	Murphy
344	C	SS	0093	28	#45 CAISSON	90	6	Leaning 1°	Murphy
345	C	SS	0093	30	#37	84	4	Leaning 5°	Murphy
346		SS	0093	32	#51	86	6		Murphy
347	J	SS	0093	32	#53	87	4	Toppled	Murphy
348	C	SS	0093	45	#39	82	5	Leaning 4°	Murphy
349	C	SS	0094	22	#23 or S	87	4	Leaning 4°	Murphy
350		SS	0094	29	WG#8	70	4		Murphy
351	C	SS	0094	30	19	81	4	Leaning 4°	Murphy
352	C	SS	0094	32	#17	79	3	Leaning 4°	Murphy
353	C	SS	0094	50	WG#20	79	4	Leaning 4°	Murphy
354		SS	0094	50	N	88	3		Murphy
355		SS	0098	17	#1	86	4		Chevron
356		SS	0099	20	SAT #7	76	6		Chevron
357	C	SS	0099	21	#2	61	7	Broken at Mudline	Chevron
358		SS	0100	23	#1	87	7		Chevron
359		SS	0108	20	SAT#22	62	7		Chevron
360		SS	0108	20	SAT#27	63	7		Chevron
361		SS	0108	20	SAT#34	65	7		Chevron
362		SS	0108	20	SAT#9	61	7		Chevron
363		SS	0108	20	SAT#20	62	7		Chevron
364	J	SS	0108	20	SAT#10	61	7	Leaning 5°	Chevron
365		SS	0108	20	SAT #12	61	7		Chevron
366		SS	0108	20	SAT#15	61	7		Chevron
367		SS	0108	20	CB	60	7		Chevron
368		SS	0108	20	CP	86	7		Chevron
369		SS	0108	21	SAT#19	62	8		Chevron
370		SS	0108	21	SAT#23	62	8		Chevron
371		SS	0108	21	SAT#25	63	8		Chevron
372		SS	0108	21	SAT#32	64	7		Chevron
373		SS	0108	21	SAT #39	69	7		Chevron
374		SS	0108	22	SAT#16	61	7		Chevron
375		SS	0108	22	SAT#21	62	8		Chevron
376		SS	0108	22	SAT#28	63	8		Chevron
377		SS	0108	22	SAT#31	64	7		Chevron
378		SS	0108	22	SAT#36	67	7		Chevron
379		SS	0108	25	#41	89	7		Chevron
380		SS	0108	25	#42	89	7		Chevron
381	J	SS	0112	47	#5	86	0	Leaning 6°	Murphy
382	C	SS	0112	48	S(S1&S2)	86	0	Leaning 5°	Murphy
383	C	SS	0112	48	#6	87	0	Leaning 5°	Murphy

TABLE 2.1.B  
WELL STRUCTURES WITHIN 50 MILES OF HURRICANE ANDREW

Type

C - Caisson, Damaged

? - Distance uncertain

J - Minimal Structure, Damaged

- Undamaged

Type	Area	Block	ft.	Structure Name	Installed Year	Distance to Path, miles		Damage Description	Operator
384	C	SS	0112	17	4&7	?		Leaning 5°	Murphy
385	C	SS	0113	39	WG#19	67	3	Toppled	Murphy
386	C	SS	0113	40	WG #35	80	3	Leaning 15°	Murphy
387	C	SS	0113	41	WG#41	85	2	Leaning 10°	Murphy
388	C	SS	0113	45	45	90	1	Toppled	Murphy
389	C	SS	0113	46	#40	84	2	Leaning 10°	Murphy
390	C	SS	0113	47	#47 - 49	89	1	Leaning 48°	Murphy
391	C	SS	0113	47	48	89	1	Toppled	Murphy
392	C	SS	0113	37	51	?		Leaning 15°	Murphy
393	C	SS	0113	37	52	?		Leaning 5°	Murphy
394		SS	0113	48	WG16(17&18)	67	2		Murphy
395	C	SS	0113	49	29,32	78	2	Leaning 2.5°	Murphy
396	C	SS	0113	50	#46	86	2	Toppled	Murphy
397	C	SS	0114	40	#55	81	2	Leaning 45°	Murphy
398	C	SS	0114	40	WG#43	81	4	Leaning 45°	Murphy
399	C	SS	0114	41	WG #41	80	3	Leaning 30°	Murphy
400		SS	0114	42	WG#11	66	4		Murphy
401	J	SS	0114	46	#50	84	2	Toppled	Murphy
402		SS	0114	47	#49	85	2		Murphy
403		SS	0114	49	WG#15	69	3		Murphy
404	C	SS	0114	50	WG38	76	3		Murphy
405	C	SS	0114	50	WG#39&9	79	2	Toppled	Murphy
406	C	SS	0114	47	1	?		Leaning 5°	Murphy
407	C	SS	0114	47	38	?		Toppled	Murphy
408	C	SS	0114	50	#51	82	3	Toppled	Murphy
409	C	SS	0114	50	#46	83	2	Leaning 30°	Murphy
410	J	SS	0114	50	#57	86	2	Leaning 35°	Murphy
411	C	SS	0114	51	#12 WELL	67	2	Toppled	Murphy
412	J	SS	0114	51	#80	85	3	Leaning 15°	Murphy
413	C	SS	0114	52	#9	65	2	Leaning 80°	Murphy
414	J	SS	0114	53	#61	86	3	Toppled	Murphy
415	C	SS	0114	55	#47	82	2	Leaning 10°	Murphy
416		SS	0115	50	NO.2	78	5		Murphy
417	C	SS	0117	50	#2	81	2		Mesa
418	J	SS	0117	53	#3	82	2	Leaning 30°	Murphy
419	C	SS	0117	55	#5&#6	89	2	Leaning 20°	Murphy
420	C	SS	0117	55	#7	90	1	Leaning 10°	Murphy
421	C	SS	0118	50	NO.3	79	0	Leaning 45°	Murphy
422	C	SS	0118	50	WG #4	79	0	Leaning 5°	Murphy
423		SS	0118	50	#6	80	0	Leaning 10°	Murphy
424	C	SS	0118	17	9	?			Murphy
425	J	SS	0119	43	WG#5	73	2	Toppled	Murphy
426		SS	0119	45	WG-12	75	1	Leaning 2.5°	Murphy
427	C	SS	0119	45	14	82	2	Leaning 10°	Murphy
428	C	SS	0119	47	#9	82	2	Leaning 5°	Murphy
429	C	SS	0119	48	#21	86	3	Leaning 10°	Murphy
430	C	SS	0119	50	WG#15	76	2	Leaning 3°	Murphy
431	C	SS	0120	35	3	84	6	Leaning 5°	Murphy
432	C	SS	0120	35	WG#2	83	5	Leaning 5°	Murphy
433	C	SS	0120	40	NO.4	79	4	Leaning 2°	Murphy
434		SS	0120	40	NO.7	79	5		Murphy
435	C	SS	0120	40	4	83	4	Leaning 20°	Murphy
436	C	SS	0120	40	#1	83	4	Leaning 5°	Murphy
437	C	SS	0120	41	NO.5	79	3	Leaning 2°	Murphy
438	C	SS	0120	42	#3	78	3	Leaning 5°	Murphy

TABLE 2.1.B  
WELL STRUCTURES WITHIN 50 MILES OF HURRICANE ANDREW

Type

C - Caisson, Damaged

? - Distance uncertain

J - Minimal Structure, Damaged

- Undamaged

Type	Area	Block	ft.	Structure Name	Year	Distance to		Damage Description	Operator
						W.D.	Installed		
439	C	SS	0120	42	#13	87	3	Leaning 15°	Murphy
440	C	SS	0120	47	#5	84	5	Leaning 2°	Murphy
441		SS	0133	37	#4	85	10		
442		SS	0133	40	#3	85	9		W & T Offshore
443	C	SS	0134	43	1	83	9	Leaning 5°	W & T Offshore
444	C	SS	0134	43	3	83	7	Leaning 5°	Murphy
445	C	SS	0134	43	4	83	9	Leaning 5°	Murphy
446	C	SS	0134	44	6	83	8	Leaning 5°	Murphy
447	C	SS	0134	45	2	83	8	Leaning 3°	Murphy
448	C	SS	0134	45	5	83	7	Leaning 5°	Murphy
449	C	SS	0134	45	9	84	8	Leaning 5°	Murphy
450	C	SS	0134	45	#8	84	7	Leaning 5°	Murphy
451	C	SS	0134	45	#10	84	9	Leaning 5°	Murphy
452	C	SS	0134	60	#7	83	8	Leaning 5°	Murphy
453	C	SS	0134	60	#11	84	9	Leaning 45°	Murphy
454	C	SS	0134	60	#12	84	9	Leaning 5°	Murphy
455	C	SS	0134	60	#13	84	8	Leaning 5°	Murphy
456	C	SS	0134	60	#14	84	7	Leaning 5°	Murphy
457	C	SS	0134	77	#15	?		Leaning 5°	Murphy
458	C	SS	0134	77	#17	?		Leaning 5°	Murphy
459	C	SS	0134	60	#18	84	9	Leaning 5°	Murphy
460	J	SS	0134	60	20	84	9	Leaning 5°	Murphy
461	C	SS	0134	60	16	85	8	Toppled	Murphy
462	C	SS	0135	44	#10	83	7	Leaning 5°	Murphy
463	C	SS	0135	45	#5	82	6	Leaning 10°	Murphy
464	C	SS	0135	45	#4	83	7	Leaning 5°	Murphy
465	C	SS	0135	46	6	83	7	Leaning 5°	Murphy
466	C	SS	0135	50	#3	82	5	Leaning 5°	Murphy
467	C	SS	0135	55	#12	83	6	Leaning 5°	Murphy
468	C	SS	0135	55	#13	84	8	Leaning 5°	Murphy
469	C	SS	0135	65	7	83	6	Leaning 5°	Murphy
470	C	SS	0135	113	WG#8	83	6	Leaning 3°	Murphy
471	C	SS	0136	50	#2	87	4	Leaning 5°	Murphy
472	C	SS	0136	50	3	87	6	Leaning 20°	Murphy
473	J	SS	0136	56	#1	83	4	Toppled	Murphy
474		SS	0146	45	#3	85	11	Leaning 30°	Murphy
475		SS	0154	60	#22	88	19		Phillips
476	C	SS	0168	60	#2	84	8		Pennzoil
477	C	SS	0168	60	#1	85	9	Leaning 20°	Murphy
478	C	SS	0168	97	#3	?		Leaning 12°	Murphy
479	C	SS	0167	50	#8 PLATFORM	90	10	Leaning 2°	Murphy
480	C	SS	0187	80	#5	70	10	Leaning 8°	Murphy
481	C	SS	0187	80	#7	78	10	Leaning 7°	Murphy
482	C	SS	0167	107	#9	7		Leaning 7°	Murphy
483		SS	0169	65	WG #9	78	13	Leaning 35°	Murphy
484		SS	0176	98	#7 CAISSON	90	27		Chevron
485		SS	0177	92	#5	84	26		Pennzoil
486		SS	0177	92	#7 CAISSON	90	25		Amoco
487		SS	0181	45	C	83	18		Amoco
488		SS	0183	66	F	83	15		Chevron
489		SS	0205	107	WG#4 & #5	71	24		Chevron
490		SS	0209	100	3	66	15		Torch Operating
491		SS	0218	107	WG#4	69	20		Union Oil
492		SS	0239	130	#4	85	23		Torch Operating
493		ST	0021	34	WG#78	65	35		Kerr-McGee
									Chevron

TABLE 2.1.B  
WELL STRUCTURES WITHIN 50 MILES OF HURRICANE ANDREW

Type  
 C - Caisson, Damaged  
 J - Minimal Structure, Damaged  
 - Undamaged

Type	Area	Block	ft.	Structure Name	Installed Year	Distance to		Damage Description	Operator
						Path, miles			
494	ST	0021	35	WG#20	60	34			Chevron
495	ST	0021	35	WG#24	61	35			Chevron
496	ST	0021	36	WG#80	65	35			Chevron
497	ST	0021	36	WG#79	66	35			Chevron
498	ST	0021	36	WG-8	58	34			Chevron
499	ST	0021	36	WG#58	63	34			Chevron
500	ST	0021	36	WG#31	61	34			Chevron
501	ST	0021	37	WG#6	58	34			Chevron
502	ST	0021	37	WG#1	58	34			Chevron
503	ST	0021	37	WG#5	58	34			Chevron
504	ST	0021	38	WG#95	66	33			Chevron
505	ST	0021	38	WG#85	82	35			Chevron
506	ST	0021	38	WG#28	61	35			Chevron
507	ST	0021	38	WG#59	82	35			Chevron
508	ST	0021	39	WG#10	59	34			Chevron
509	ST	0021	39	#111	66	34			Chevron
510	ST	0021	39	WG#2	58	34			Chevron
511	ST	0021	40	WG#15	59	34			Chevron
512	ST	0021	40	WG#12	59	34			Chevron
513	ST	0021	40	WG#13	59	34			Chevron
514	ST	0021	40	WG#17	59	34			Chevron
515	ST	0021	40	WG#21	60	33			Chevron
516	ST	0021	40	WG#27	61	34			Chevron
517	ST	0021	40	WG#32	61	34			Chevron
518	ST	0021	40	#124	89	34			Chevron
519	ST	0021	43	WG#40	62	33			Chevron
520	ST	0021	43	WG#108	70	34			Chevron
521	ST	0021	44	WG#47	62	33			Chevron
522	ST	0021	45	WG#92	68	33			Chevron
523	ST	0021	45	WG#110	71	34			Chevron
524	ST	0021	45	WG#66	65	34			Chevron
525	ST	0021	46	WG#100	67	33			Chevron
526	ST	0021	46	WG#94	66	33			Chevron
527	ST	0021	46	WG#91	66	33			Chevron
528	ST	0021	46	WG#90	67	34			Chevron
529	ST	0021	46	WG#69	64	33			Chevron
530	ST	0021	46	WG#67	64	34			Chevron
531	ST	0021	46	116&51	63	33			Chevron
532	ST	0021	46	WG#54	63	34			Chevron
533	ST	0021	46	88,89,93	66	34			Chevron
534	ST	0021	47	WG#109	70	34			Chevron
535	ST	0021	47	WG#75	65	34			Chevron
536	ST	0021	47	WG#55	63	33			Chevron
537	ST	0021	48	WG#99	67	33			Chevron
538	ST	0021	48	WG#86	65	33			Chevron
539	ST	0021	48	WG#82&98	67	34			Chevron
540	ST	0021	48	WG#81	65	34			Chevron
541	ST	0021	48	71,72,7	65	34			Chevron
542	ST	0021	48	WG#97	67	33			Chevron
543	ST	0021	48	WG#87	65	34			Chevron
544	ST	0021	49	WG#84	65	33			Chevron
545	ST	0021	49	WG#76&77	65	33			Chevron
546	ST	0021	49	WG#63	63	33			Chevron
547	ST	0021	49	WG#68	64	33			Chevron
548	ST	0021	50	WG#101	67	33			Chevron

TABLE 2.1.B  
WELL STRUCTURES WITHIN 50 MILES OF HURRICANE ANDREW

Type

C - Caisson, Damaged

? - Distance uncertain

J - Minimal Structure, Damaged

- Undamaged

Type	Area	Block	ft.	Structure Name	Installed Year	Distance to		Damage Description	Operator
						Path, miles			
549	ST	0021	50	WG#102	67	34			Chevron
550	ST	0022	48	WG#7	73	34			Chevron
551	ST	0023	48	16	65	38			Chevron
552	ST	0023	50	9&20	64	37			Chevron
553	ST	0024	47	#20	84	40			Chevron
554	ST	0024	48	18	80	39			Chevron
555	ST	0027	48	SAT#8	66	34			Chevron
556	ST	0027	48	WG#5	66	34			Chevron
557	ST	0027	48	WG#2	66	34			Chevron
558	ST	0027	48	WG#12	66	34			Chevron
559	ST	0027	48	WG#9	66	34			Chevron
560	ST	0027	48	WG#4	66	34			Chevron
561	ST	0027	48	WG#3	66	34			Chevron
562	ST	0027	48	WG#7&#13	66	34			Chevron
563	ST	0027	48	WG#1	66	34			Chevron
564	ST	0027	49	WG#17	68	34			Chevron
565	ST	0027	50	WG#11	66	34			Chevron
566	ST	0027	50	WG#16	67	34			Chevron
567	ST	0027	51	WG-24	77	34			Chevron
568	ST	0027	57	WG#18	71	33			Chevron
569	ST	0028	50	WG#10	66	33			Chevron
570	ST	0028	50	WG#1	64	33			Chevron
571	ST	0028	50	WG#6	65	33			Chevron
572	ST	0028	50	WG#8	65	32			Chevron
573	ST	0028	50	WG#5	65	33			Chevron
574	ST	0028	50	WG#13	67	32			Chevron
575	ST	0028	50	WG#3	64	33			Chevron
576	ST	0028	50	WG#2	64	33			Chevron
577	ST	0028	50	WG#4	64	33			Chevron
578	ST	0028	50	WG#12	67	33			Chevron
579	ST	0034	50	#8	83	22			Kerr-McGee
580	ST	0034	52	#2/#3	83	21			Kerr-McGee
581	ST	0034	52	#4	83	21			Kerr-McGee
582	ST	0034	52	#8	83	20			Kerr-McGee
583	ST	0034	52	#11	89	21			Kerr-McGee
584	ST	0034	53	#9	84	20			Kerr-McGee
585	ST	0035	48	#5	87	23			Chevron
586	ST	0035	50	#3 CAISSON	88	21			Chevron
587	ST	0035	50	#6	87	22			Chevron
588	ST	0050	55	#4	80	21			Kerr-McGee
589	ST	0050	58	C	80	19			Kerr-McGee
590	ST	0050	58	#6	81	21			Kerr-McGee
591	ST	0051	58	SAT #4	67	18			Chevron
592	ST	0051	58	SAT#3	76	18			Chevron
593	ST	0051	58	#4	86	20			Chevron
594	ST	0051	58	5	87	20			Chevron
595	ST	0051	60	9&12(1240)	85	20			Chevron
596	ST	0051	60	#5,#7,#8	77	18			Chevron
597	ST	0051	60	#10&#11	84	18			Chevron
598	ST	0051	60	#23	88	19			Chevron
599	ST	0052	50	SAT.#3	72	17			Chevron
600	ST	0052	54	#20	83	17			Chevron
601	ST	0052	58	10,16,18	77	18			Chevron
602	ST	0052	60	CB	75	16			Chevron
603	C	ST	0052	60	12,14,15	77	17	Severed 5' above Mud Line	Chevron

TABLE 2.1.B  
WELL STRUCTURES WITHIN 50 MILES OF HURRICANE ANDREW

Type

C - Caisson, Damaged

? - Distance uncertain

J - Minimal Structure, Damaged

- Undamaged

Type	Area	Block	ft.	Structure Name	Installed Year	Distance to Path, miles		Damage Description	Operator
604	ST	0052	60	17	82	17			Chevron
605	ST	0052	61	#21	89	17			Chevron
606	ST	0053	60	#5	87	17			Union Oil
607	ST	0053	65	#4	83	17			Union Oil
608	ST	0083	84	WG#2	89	25			Murphy
609	ST	0083	86	WG#1	90	25			Odeco
610	ST	0083	87	WG#3	71	25			Murphy
611	ST	0083	90	WG#13	71	24			Murphy
612	ST	0083	90	WG#14	70	25			Murphy
613	ST	0083	92	#9 CAISSON	90	24			Murphy
614	ST	0087	61	WG#2	67	17			Exxon
615	ST	0072	62	#3	63	9			Gas Transportation
616	C	ST	0086	92	12	84	23	Toppled	Odeco
617	ST	0086	92	3	82	22			Odeco
618	ST	0086	100	#24	85	23			Odeco
619	J	ST	0086	110	#20	83	22	Toppled	Odeco
620	J	ST	143	17	A1,A2,A3	?		Toppled	Hall-Hous
621	J	ST	144	17	A1,A2	?		Toppled	Hall-Hous
622		ST	0145	90	A	88	2		Hughes Eastern Petroleum

128 Number of Damaged Caissons  
17 Number of Damaged Minimal Structures

622 Total Number of Structures

TABLE 2.2.A

## SUMMARY OF CHARACTERISTICS OF SELECTED ACTUAL CAISSENS

No.	I.D. No.	Water Depth ft	Diameter in	Thickness in	Yield Stress ksi	Penetration Below Mud ft	Hurricane Damage
1	L1	37.5	33	1.250	42	118.5	20 deg lean*
2	L2	36	30	1.750	42	195	Failed 30' below mudline
3	L3	34	30	1.750	42	119	11 deg lean*
4	N1	40	48	1.875	42	108	None
5	N2	17	72	0.750	42	75	None
6	N3	60	96	1.250	55	100	Severed 5' above Mudline
7	Y1	46	48	1.750	42	100	Toppled
8	Y2	53	48	2.000	42	100	15 deg. lean
9	Y3	53	72	2.250	42	130	After repair

## Notes:

1. \* - damage during Hurricane Camille  
Other damage during Hurricane Andrew


TABLE 2.2.B


SUMMARY OF CHARACTERISTICS OF INNER CASING CHARACTERISTICS  
OF SELECTED ACTUAL CAISSENS

Casing No.	CAISSON I.D. in	L1, L1* @Caisson Tip	L2, L2* @Caisson Tip	L3, L3* @Caisson Tip	N1	N2	N3	Y1	Y2	Y3
0	Diameter, in Grouted	33 Only(a)	30 Only(a)	48 Only(a)	72 Yes?	72 Yes?	48 No	48 Yes?	48 Yes	72 Yes
0/1	Driven	No	No	?	No	No	No	No	No	No
1	Diameter, in	20	20	?	?	?	?	30	30	48
1	Thickness, in	0.438	0.438	?	?	?	?	0.75	0.5	?
1	Length, ft	1012	1012	?	?	?	?	328	460	150
2	Diameter, in	13.375	13.375	?	?	?	?	16	16	30
2	Weight, lb/ft	68	68	?	?	?	?	65	65	157
2	Length, ft	4508	4508	4508	?	?	?	695	750	328
3	Diameter, in	9.625	9.625	9.625	?	?	?	10.75	10.75	16
3	Weight, lb/ft	47	47	47	?	?	?	40	40	65
3	Length, ft	11500	11500	11500	?	?	?	4284	2000	695
4	Diameter, in							7.625	7.625	10.75
4	Weight, lb/ft							33	26	40
4	Length, ft							10761	5722	4284
	Caisson Axial Load from Casings, kip*									
		650 for L1*	650 for L2*	650 for L3*	0 for L1	0 for L2	0 for L3	0	0	0

a - Assumed to be ungrouted


**FIGURE 2.1.A**  
**DAMAGED CAISSIONS AND MINIMUM STRUCTURES**  
**vs.**  
**DISTANCE FROM PATH OF HURRICANE ANDREW**






NOTE: ELEVATION NOT TO SCALE

FIGURE 2.2.A  
GENERAL DESCRIPTION OF CAISSON L1




**FIGURE 2.2.B**  
**GENERAL DESCRIPTION OF CAISSON L2**

NOTE: ELEVATION NOT TO SCALE



NOTE: ELEVATION NOT TO SCALE

FIGURE 2.2.C  
GENERAL DESCRIPTION OF CAISSON L3



NOTE: ELEVATION NOT TO SCALE

FIGURE 2.2.D  
GENERAL DESCRIPTION OF CAISSON N1






FIGURE 2.2.E  
GENERAL DESCRIPTION OF CAISSON N2



NOTE: ELEVATION NOT TO SCALE

**GENERAL DESCRIPTION OF CAISSON N3**

**FIGURE 2.2.F**



NOTE: ELEVATION NOT TO SCALE

FIGURE 2.2.G  
GENERAL DESCRIPTION OF CAISSON Y1




FIGURE 2.2.H  
GENERAL DESCRIPTION OF CAISSON Y2




FIGURE 2.2!  
GENERAL DESCRIPTION OF CAISSON Y3

### 3.0 Extreme Wave Response of Caissons

In this section is reported the development of the analysis models and the results of using those models to estimate the residual lean after an extreme wave loading event.

#### 3.1 Analysis Models

In Figure 3.1.A are shown the generic models for the actual caissons and for the equivalent caissons.

For the actual caissons, the lateral load was based on API-RP2A, 20th Edition, (Reference 3), using the design level wave height, current, hydrodynamic coefficients, etc. The vertical load includes the deck load, the weight of the caisson and, in some cases, a portion of the weight of the casings.

The soil is modelled using the guidelines in Reference 3, along with the assumption that the static soil response is appropriate for the expected large deflections. As none of the caissons are grouted, the stiffness of the structure is assumed to be only that of the outer caisson.

For the equivalent caissons, all of the defining parameters are simplified so that the response can be presented in terms of the fewest variables. These simplifications include:

1. Representation of the lateral load as a concentrated load at the mean water line. This simplification is focused on the assumption that the wave load profile yields a center of pressure approximately at the mean water line.
2. Only uniform diameter and wall thickness are considered.

3. The soil is assumed to be adequately represented as a clay with linearly increasing shear strength.
4. All axial loads are ignored.

### Model Features

In the following paragraphs are discussed the features of the analysis models for the yielding steel caisson and for the non-yielding caisson.

The behavior of a incremental length of caisson is shown in Figure 3.1.B. This figure shows the relationship among the diameter, the curvature, the radius of curvature, the outer fiber strain, and the bending moment; all based on the fundamental assumption of plane sections remaining plane.

For a simple tubular, Figure 3.1.C (reproduced from data in Figure C 3.3.2-1 of Ref. 3) presents an estimate of the ultimate bending moment versus the variable,  $F_y \cdot D/t$ . Also in Figure 3.1.C is the normalized curvature value versus  $F_y \cdot D/t$ . For a given value of  $F_y \cdot D/t$ , the value for the ultimate moment and the ultimate strain are considered to be allowable since they are estimates of the maximum values that may occur without any local buckling. The reduction in the moment curve from its maximum normalized value of 1.27 is primarily due to the ovalling of the section.

For this study the stress-strain for the steel is assumed to be elastic-plastic as shown in Figure 3.1.D(a). Several References (e.g. 4, 5 and 6) report the "simplified" normalized moment versus the normalized curvature shown in Figure 3.1.D(b) for no axial load. These analyses do not recognize the ovalling of the section or the potential for local buckling of the section.

Because we wish to account for the axial load, to limit the strain to less than the local buckling value, and to account for the section ovaling during bending, the "Behavior" curve shown in Figure 3.1.E(b) was developed as follows:

1. The "Simplified" curve, A, in Figure 3.1.E(b) was developed using the LPILE+ (Ref. 7) program for values of curvature up to the allowable value shown in Figure 3.1.C.
2. LPILE+ does not recognize the reduced value of the ultimate moment shown in Figure 3.1.C. Thus, a linear bias factor, B, was developed as shown in Figure 3.1.E(a).
3. The "Behavior" curve in Figure 3.1.E(b) was developed by multiplying the Curve A time the bias factor, B.

#### Approximate Method for Caisson Response:

The LPILE+ program solves the yielding steel caisson problem with restrictions on loading conditions, soil representation, ultimate bending moment capacity and non-uniformity of caisson diameter and wall thickness. Thus, an "approximate" method was developed for computing the non-linear behavior of the caisson based on the assumption that the bending moment, even along the yielding length, for a yielding caisson is very nearly equal to that computed for a non-yielding caisson. The accuracy of this assumption is indicated in Figure 3.1.F which presents plots of the bending moments from the LPILE+ program for the following two cases:

1. With Caisson Yielding - The maximum moment is the ultimate moment.
2. Without Caisson Yielding - The maximum moment is the same value as the ultimate moment (case 1) but the yield stress has been artificially increased so that no yielding occurs.

Given that the moment profiles of the yielding and the non-yielding caissons are comparable, the StruCADC program (Ref. 8) could have been used to develop the moment profile (curve A, Figure 3.1.F) for the condition (case 2) of the maximum moment equal to the ultimate moment. The StruCADC program does not allow yielding of the steel caisson. However, StruCADC does have good capability for handling the multiple sized sections of the caisson and for developing the appropriate wave loading. A decision was made to proceed from this point with StruCADC in place of LPILE+ for the bulk of the computations. A comparison to be presented later, shows this "approximate" response compared with the "exact" response from LPILE+.

#### Computation of Residual Lean Angle:

StruCADC was used in combination with a spreadsheet, to compute the residual lean of the caisson when the maximum strain was equal to the maximum allowable strain without local buckling. Shown in Figure 3.1.G is the response of a caisson when the maximum moment (location B) has a value equal to the ultimate moment. The locations at which only the outer fibers are yielded are indicated as A and C (see Figure 3.1.G). The computation of the residual lean angle is also indicated in Figure 3.1.G. Note that the assumption implicit in those calculations is that the soil offers no restraint to the elastic recovery of the caisson and that the permanent lean at location C is zero for the loaded condition. This estimate of the residual lean is judged to be low as some permanent soil deformation should occur.

The residual lean angles are shown in Figure 3.1.F for the two moment curves shown. Comparison of these angles indicate that the "approximate" method underestimates the residual lean angle by about 12 percent as compared to an "exact" method.

The lean angle at the mudline versus the applied lateral load is shown in Figure 3.1.H for the caisson whose moment diagrams are presented in Figure 3.1.F. The lean angle is 2.12 degrees when the caisson first yields. The StruCADC program computes only 2.83

degrees lean for the condition when the bending moment is equal to the ultimate allowable moment. Of course, no yielding occurs in the StruCAD model. The maximum mudline lean angle (6.65 degrees) from LPILE+(the "exact" method) for 42 ksi compares favorably with that (5.86 degrees) obtained from the approximate method. The estimate (5.86 degrees) of the maximum lean angle is obtained from the addition of the residual lean angle (3.74 degrees) and the yield angle (2.12 degrees).

The "approximate" analysis model discussed above is judged to yield acceptable estimates based on the comparison with the "exact" model. The assumption of the lack of restraint or restoring force of the soil is an uncertainty for either the "approximate" or "exact" analysis model that has not been resolved. An upper bound estimate of the residual lean angle would be the maximum lean angle.

### 3.2. Actual Caisson Structures

The residual lean angle at the mudline is shown in Table 3.2.A for each of the nine actual caissons analyzed. The values for the residual lean are computed per the equation shown in Figure 3.1.G. The "linear part" of the maximum lean is computed by the StruCAD program with the lateral load factor scaled to result in the maximum moment at location B equal to the ultimate moment of the most strained section. The maximum lean angle is the sum of the linear (non-yielded portion below the mudline) part and the non-linear (residual lean angle) part. Also, shown in Table 3.2.A are the values for the 48" X 1.600" equivalent caisson used to validate the approximate method.

Note that none of the actual caissons are expected to exhibit large values of lean due to soil failure without having yielding in the steel caisson.

### 3.3 Equivalent Caisson Structures

Parametric analyses were performed to study the effects of water depth, caisson diameter, caisson thickness, caisson depth below the mudline and the soil conditions on the residual lean. Table 3.3.A lists the parameters that were considered for this study.

In Figures 3.3.A-D are shown the residual lean versus water depth for various values of diameter, diameter to thickness ratio, soil shear strength, and caisson penetration below the mudline. The two sets of soil parameters are expected to bound the values of the nine actual caissons. Because of the apparent lack of sensitivity to water depth, the values in Figures 3.3.A-D for 50 ft of water depth are plotted in Figures 3.3.E and F as lean angle versus caisson diameter for very soft soil and soft soil, respectfully.

Table 3.2.A  
LEAN ANGLE AT MUDLINE FOR ACTUAL CAISSENS


		ANGLE at MUDLINE, degrees			
No.	I.D. No.	Yield Y	Residual R	Linear S	Maximum M1 R + Y
1	L1	2.24	1.49	2.93	3.73
2	L2	2.98	1.54	3.64	4.52
3	L3	2.64	2.48	3.58	5.12
4	N1	1.15	0.61	1.64	1.76
5	N2	0.94	0.94	1.01	1.88
6	N3	2.49	0.21	2.76	2.70
7	Y1	1.72	3.88	2.26	5.60
8	Y2	1.85	0.44	2.21	2.29
9	Y3	2.03	0.97	2.55	3.00
10	L1*	1.85	1.29	2.42	3.14
11	L2*	2.41	1.21	2.87	3.62
12	L3*	2.27	2.32	3.09	4.59
13	48 x 1.600 "Approximate"	2.12	3.74	-	5.86
14	48 x 1.600 "Exact"	2.12	4.20	-	6.65

\* - Includes some loading from inner casings  
See Figure 3.1.1.H for definitions of angles

Table 3.3.A


Characteristics of Equivalent Caisson Structures for Parametric Study

Water Depth, ft	20	80	
Diameter, in	30	48	72
D/T			
Diameter to Thickness Ratio	20	60	90
Penetration, ft.	100	200	
Soil Shear Strength,(linear)		Very Soft Clay	Soft Clay
@Mudline,ksf		0.1	0.4
@ -100 ft, ksf		0.5	1.2



ACTUAL CAISSENS

(a)



EQUIVALENT CAISSENS

(b)

Figure 3.1.A  
Analysis Models

$$\varepsilon = \frac{d\theta}{dx} \eta = \Phi \eta$$

$$\varepsilon_0 = \frac{d\theta}{dx} \frac{D}{2} = \Phi \frac{D}{2}$$





Figure 3.1.B  
Element From A Beam Subjected  
To Pure Bending



$M$  = BENDING MOMENT  
 $F_y$  = YIELD STRESS, k.s.i.  
 $D$  = DIAMETER  
 $t$  = THICKNESS  
 $\phi$  = CURVATURE  
 $u$  = ULTIMATE  
 $y$  = YIELD

Figure 3.1.C  
Interpretation Of Ultimate Strength For  
Fabricated Steel Cylinder Under Bending







Figure 3.1.D




(a)



(b)

Figure 3.1.E  
Behavior Of A Cylindrical Section In Bending  
With Axial Load



$\beta_R = 3.74$  DEGREES, CURVE A ("APPROXIMATE")

$\beta_R = 4.20$  DEGREES, CURVE B ("EXACT")

$$\frac{M_u}{M_y} = 1.27$$


$$D = 48"$$

$$t = 1.600 \text{ in.}$$

SOIL = SOFT CLAY; 0.25 KSF @ MUDLINE

1.92 KSF @ PILE TIP

Figure 3.1.F  
Comparison Of Moment Profiles



$$\beta_R = \beta_{RESIDUAL} = \int_A^C \frac{d\theta}{dx} dx - \int_A^C \left. \frac{d\theta}{dx} \right|_{YIELD} dx$$

Figure 3.1.G  
Computation Of Residual Lean Angle

$D = 48$  IN.  
 $T = 1.600$  IN.  
 $\sigma_y = 42$  KSI  
 $WD = 100'$   
 PENETRATION = 200'  
 SOIL = SOFT CLAY; 0.25 KSF @ MUDLINE  
           1.92 KSF @ PILE TIP

$\beta_R = 3.74$  DEGREES; (MOMENT DIAGRAM A, FIGURE 3.1.F)  
 $\beta_s = 2.83$  DEGREES; (MUDLINE ANGLE FROM NON-YIELDING CAISSON ANALYSIS)  
 $\beta_{mf} = 5.86$  DEGREES; (MAXIMUM MUDLINE ANGLE ESTIMATE)  
 $\beta_{m2} = 6.65$  DEGREES; (MAXIMUM MUDLINE ANGLE FROM LPILE+)




Figure 3.1.H  
Lean At Mudline vs Load Factor

RESIDUAL LEAN,  $\beta$   
 VS.  
 WATER DEPTH, W.D.  
 PILE PENETRATION = 200 FT.  
 SOIL TYPE: VERY SOFT CLAY




Figure 3.3.A

RESIDUAL LEAN,  $\beta$   
 VS.  
 WATER DEPTH, W.D.  
 PILE PENETRATION = 100 FT.  
 SOIL TYPE: VERY SOFT CLAY




Figure 3.3.B

RESIDUAL LEAN,  $\beta$   
VS.  
WATER DEPTH, W.D.  
PILE PENETRATION = 200 FT.  
SOIL TYPE: SOFT CLAY





Figure 3.3.C


RESIDUAL LEAN,  $\beta$   
 VS.  
 WATER DEPTH, W.D.  
 PILE PENETRATION = 100 FT.  
 SOIL TYPE: SOFT CLAY




W.D., WATER DEPTH, FT.

Figure 3.3.D

**FIGURE 3.3.E**  
**RESIDUAL LEAN ANGLE vs. PILE DIAMETER**  
**50' WATER DEPTH**  
**VERY SOFT CLAY**



**FIGURE 3.3.F**  
**RESIDUAL LEAN ANGLE vs. PILE DIAMETER**  
**50' WATER DEPTH**  
**SOFT CLAY**



## 4.0 Development of Acceptance Criteria

### 4.1 General Observations of Response

The computed angle of lean of the all of caissons appear to be very low compared to the observed values. Post Hurricane Andrew lean was observed to be greater than 15 degrees on many caissons; whereas, the analysis model developed in this report would have predicted total failure of the caisson because the local yielding would have been well beyond the local buckling value.

The equivalent caisson study is believed to show proper trends. The allowable lean angle will increases with the softer soil. The allowable lean angle increase with decreasing values of diameter to thickness( $D/t$ ) ratios. For the same  $D/t$  ratio, the allowable lean angle decreases with increasing caisson diameter. For small  $D/t$  values, lower than those for the actual caissons, massive soil failure was predicted prior to caisson yielding.

### 4.2 Acceptance Criteria Guidelines

The analysis results of the actual caissons which are reported in Table 3.2.A show that the residual lean angle for these caissons is quite small. The assumption that the residual lean angle is due to only the permanent deformation of the yielded steel caisson is likely to underestimate the actual residual lean angle. Inelastic soil deformation could cause a residual lean angle, even without caisson yielding. Thus, the actual, allowable residual angle may be closer to the maximum lean. From Table 3.2.A, the maximum lean estimates vary between 1.88 degrees and 5.60 degrees.

The residual lean angles for the actual caissons appears to be slightly correlated such that lower diameter caissons have larger allowable lean angles. This observation is also made from the equivalent caisson study. However, no trends in the data for the actual caissons were outstanding. Thus, acceptance of the residual lean for a particular

damaged caisson needs to be based on all of the available data related to the design. If no known damage beyond the buckling strain is known to exist, and if the design details are relatively close to those used in this analysis, then a residual lean angle of about 3 degrees is judged to be acceptable. Otherwise, a detailed inspection and evaluation analysis program should be the basis of acceptance.

## 5.0 Damage Assessment and Repair Guidelines

Because of the limited information on the damage of the caissons only very general guidelines for damage assessment and repair can be given. The fundamental assumption for assessing the allowable lean angles is that the caisson yield strain should be less than that corresponding to local buckling. This very localized condition, high stress condition could result in local fracture of the caisson. If the lean angle of a caisson exceeds about 3 degrees or if the design details are substantially different from those caissons used in this study then a detailed damage assessment should be undertaken.

An appropriate damage assessment could be an analysis similar to that outlined in this report. If the analysis indicates that local buckling did occur then an inspection verification would be in order.

The repair of a tilted or overstressed caisson should be based on an engineering analysis which reflects the proposed repairs. Simulation of a straightening load could be performed using procedures similar to those outlined herein. If local buckling was not present then the straightening process could proceed if desired. If local damage, such as local buckling, did occur, then repairs should be made either prior to or after straightening.

The placement of a larger caisson over a damaged caisson has been implemented in some cases. This process should be acceptable if the final configuration meets the required design criteria.

**References:**

1. Data Received during meeting between Sid Gelpi, Barnett and Casbarian Inc., and various personnel of the Minerals Management Service, February 22, 1994.
2. Stone, Gregory, W., John M. Grymes III, Kevin D. Robbins, Steven G. Underwood, Gregory D. Steyer and Robert A. Muller, 1993. " A Chronologic Overview of Climatological and Hydrological Aspects Associated with Hurricane Andrew and Its Morphological Effects Along the Louisiana Coast, USA", SHORE AND BEACH 61(2):2-12.
3. API Recommended Practice RP2A Planning, Designing and Constructing Fixed Offshore Platforms - Working Stress Design, Twentieth Edition, July 1, 1994.
4. Matthys, R.D., "Theoretical Analysis of Circular Pipe Columns in the Inelastic Range", Master of Science Thesis, Architectural Engineering, University of Texas, June, 1962.
5. "The Plastic Methods of Structural Analysis", Neal,B.G., John Wiley & Sons, Inc., 1963.
6. "Plastic Analysis of Structures", Hodge, P.G.,Jr., Robert E. Drieger Publishing Co., 1981.
7. "LPILE+", Reese, L.C. and Wang, S.-T., Ensoft Inc., Austin, Texas, 1993.
8. "StruCADC", Version 3D, Zentech Inc., Houston, Texas
9. Stahl B. and Baur, M.P., "Design Methodology for Offshore Platform Conductors", OTC 3920, 1980