

Calvert Cliffs 1

3Q/2003 Plant Inspection Findings

Initiating Events

Significance:  Nov 22, 2002

Identified By: NRC

Item Type: FIN Finding

Failure to take adequate corrective actions for poor quality welds on reactor coolant pump support systems

CEG did not adequately complete identified corrective actions in response to a weld deficiency in the component cooling water (CCW) line to a Unit 2 reactor coolant pump (RCP) in October 2001. The incomplete corrective actions, due to missed inspections of some welds in the RCP support systems, contributed to a failed weld in a lube oil line to a RCP and a Unit 1 reactor trip in July 2002.

Inspection Report# : [2002012\(pdf\)](#)

Mitigating Systems

Significance:  Mar 29, 2003

Identified By: NRC

Item Type: NCV NonCited Violation

Untimely & inadequate corr. actions to prevent 4kV breaker auxiliary switch failure. The condition review for SBM switches used in other applications have been inadequate and incompl. since 1996.

A self-revealing NCV was documented regarding CCNP's inadequate and untimely corrective actions to prevent recurrence of SBM-type auxiliary switch failure as required by 10 CFR 50, Appendix B, Criteria XVI, "Corrective Action". The finding is considered a PI&R cross-cutting issue due to the failure to prevent recurrent SBM-type switch failures and due to inadequate and incomplete extent of condition reviews since CCNPP's review of industry operating experience regarding degraded and defective GE SBM switches in 1996.

The inspectors determined that this event was more than minor because the finding represented an actual loss of the safety function, for 28 days, for the 1B EDG to be capable of providing emergency electrical power to the 14 4kV vital emergency bus. The safety significance of this finding was very low because of a plant design feature that allows the Unit 2 motor driven auxiliary feedwater pump to supply the Unit 1 steam generators during a station blackout (no AC power) at Unit 1. (Section 40A3).

Inspection Report# : [2003002\(pdf\)](#)

Barrier Integrity

Emergency Preparedness

Significance:  Mar 29, 2003

Identified By: NRC

Item Type: FIN Finding

EAL initiating conditions caused delays in declar. approp. emerg. classifi. during simulator as a drill. The EALS & Oper. procedures in lieu of plant conditions alone contributed to this issue.

The inspectors identified a finding that the CCNPP emergency action level (EAL) initiating conditions, as written, caused delays and an incorrect emergency classification declaration during a simulator scenario evaluated as a drill. A contributing cause of this finding was that the content of CCNPP's EALs incorporated plant conditions and operator implementation of procedures as initiating conditions in lieu of using plant conditions alone as the EAL initiating conditions.

This issue was determined to be more than minor because if left uncorrected it could become a more significant safety concern regarding the potential untimely public notification of an emergency. This finding was classified as Green (of very low safety significance) after NRC management review since the Emergency Preparedness (EP) Significance Determination Process (SDP) did not apply. (Section 1EP6)

Inspection Report# : [2003002\(pdf\)](#)

Occupational Radiation Safety

Public Radiation Safety

Physical Protection

Miscellaneous

Significance: N/A Nov 22, 2002

Identified By: NRC

Item Type: FIN Finding

Based on the sample selected for review, the PI&R team concluded that implementation of the corrective action program was adequate.

Based on the sample selected for review, the team concluded that the implementation of the Constellation Energy Group (CEG) corrective action program was adequate. In general, personnel identified problems and entered them into the corrective action program at an appropriate threshold. However, the team identified several minor valve packing and pump seal leaks within the Unit 1 and Unit 2 emergency core cooling system (ECCS) pump rooms that were not identified and captured in CEG's corrective action program.

CEG generally prioritized and completed evaluations in a timely fashion and evaluated problems in adequate detail

commensurate with the safety significance. The evaluations reasonably identified the causes of the problem, the extent of the condition, and provided for corrective actions to address the causes. The evaluations of equipment problems generally included operability assessments of sufficient depth to conclude that equipment remained capable of performing its safety functions. CEG also assessed reportability requirements appropriately.

CEG corrective actions and improvement initiatives were generally effective in improving equipment reliability and human performance. However, inadequate corrective action follow through for a Unit 2 reactor coolant pump (RCP) support system weld deficiency contributed to a Unit 1 reactor trip. The team also noted that CEG was not fully effective in resolving some recurrent equipment deficiencies. CEG's self-assessments and corrective action program audits identified similar findings.

Inspection Report# : [2002012\(pdf\)](#)

Last modified : February 05, 2004