



200-398A

# National Transportation Safety Board

Washington, D.C. 20594

## Safety Recommendation

---

**Date:** JUL 17 1995

**In Reply Refer To:** M-95-7

Mr. Juan H. Kelly  
Chairman  
International Chamber of Shipping  
2-5 Minories  
London EC3N IBJ  
England

---

About 2041 on November 6, 1993, the Netherlands Antilles passenger ship NOORDAM and the Maltese bulk carrier MOUNT YMITOS collided in international waters 3.9 miles south of the entrance to the Mississippi River near Southwest Pass, Louisiana. The NOORDAM, carrying 1,730 passengers and crew, was preparing to embark a bar pilot and proceed upriver to the Port of New Orleans. The MOUNT YMITOS was outbound from the Mississippi River, had disembarked its bar pilot, and was heading for open sea. Nine crewmembers on the NOORDAM sustained minor injuries. No one on the MOUNT YMITOS was injured, and no deaths resulted from this accident. Damage to both vessels was substantial.<sup>1</sup>

The safety fairways established in these waters are narrow and are surrounded by oil production platforms. Between 5,000 and 6,000 vessels, each exceeding 100 gross tons, transit the area annually on their way to and from ports along the Mississippi. In addition, many smaller vessels operating in the offshore oil and commercial fishing industries cross the fairways at odd angles and at unpredictable times. The Safety Board found that despite these hazardous conditions, the officers on the NOORDAM's bridge were not maintaining a proper lookout for approaching traffic, either by sight or by radar.

---

<sup>1</sup> For more detailed information, read Marine Accident Report--*Collision of the Netherlands Antilles Passenger Ship NOORDAM and the Maltese Bulk Carrier MOUNT YMITOS in the Gulf of Mexico, November 6, 1993* (NTSB/MAR-95-01).

6545A

The junior third officer, senior second officer, chief officer, and master of the NOORDAM were licensed deck officers with extensive shipboard experience and training. They had attended maritime universities, and all had demonstrated professional competencies that led to their employment and advancement at Holland America. Nonetheless, basic seamanship and watchstanding discipline simply were not being observed on the NOORDAM's bridge during the 40 minutes preceding the accident.

About 2001, the senior second officer altered course to overtake another ship. He assumed that the other ship would maintain its course and speed but did not attempt to confirm this assumption by using the radiotelephone or sounding the internationally recognized whistle signals. About 2014, the other ship unexpectedly altered course into the path of the NOORDAM. The senior second officer was forced to take evasive action, became concerned about a collision, and called the master's cabin. However, neither the master nor the chief officer, who was on call, had told the senior second officer that they would be having dinner in the chief engineer's cabin. When the senior second officer received no answer, he sent the junior third officer to find either the chief officer or the master. By the time the chief officer arrived on the bridge, the NOORDAM had overtaken the other ship but was heading for a nearby cluster of oil production platforms.

About 2030, 11 minutes before the collision, the junior third officer relieved the senior second officer as officer of the watch. During the change-of-watch briefing, the two officers did not discuss plans for embarking the pilot. They did not discuss the chief officer's role during the final approach to the sea buoy. They did not discuss the proximity of vessel traffic or other hazards to navigation, including the lighted oil production platforms. Although they said that they were looking at the radar, no sighting of the MOUNT YMITOS or any of the other vessels ahead occurred during the briefing. Moreover, the chief officer was on the bridge and was scheduled to assume the conn within a few minutes. He knew that the change-of-watch briefing was taking place, but he did not participate.

About 2035, 6 minutes before the collision, the chief officer ordered the helmsman to apply right rudder and alter course to starboard toward the sea buoy. Thus, the chief officer took over the watch without a word to the junior third officer, and the junior third officer said nothing to him. The chief officer said that before beginning the turn, he had looked toward the sea buoy but did not see the MOUNT YMITOS. The MOUNT YMITOS could not have been more than 1.5 miles away and should have been clearly visible from the bridge of the NOORDAM.

The chief officer testified that after he had begun the turn, he saw the green sidelight of an approaching vessel. No one else on the bridge saw the green light, and the chief officer did not bring it to anyone's attention. The chief officer had not visually observed the vessel's masthead lights, which would have verified its heading, and he had not tracked the vessel with the ARPA or radar. Nonetheless, he assumed that the vessel was on a course parallel and reciprocal to that of the NOORDAM, that it would pass down the NOORDAM's starboard side, and that he would not have to take evasive action. The chief officer did not recognize the risk

of collision until about 2038, when the fourth officer (who was not on duty) saw the vessel's red sidelight. By then, however, the two ships were less than 0.5 mile apart and closing at a rate of about 23 knots.

The deficiencies in bridge watchstanding performance revealed by this investigation underscore the importance of maintaining bridge discipline, delegating duties consistent with navigation and traffic conditions, and detecting any deterioration in watchstanding performance that could place the vessel at risk. The bridge officers on the NOORDAM did not recognize the extent to which their performance had deteriorated.

Passage planning is an important aspect of safe navigation. The watchstanders on the NOORDAM had plotted a trackline that complied with the guidance in the International Chamber of Shipping *Bridge Procedures Guide* and in Section 2360 of the Holland America *Masters' and Deck Officers' Operating Regulation No. 400*. However, these two documents do not address the communication aspects of implementing the plan; that is, the fact that watchstanders need to communicate with each other and that each officer needs to know his own role during the transit and the roles of others on the bridge. The failure of the chief officer, the senior second officer, and the junior third officer to communicate important information during the 11 minutes preceding the accident left them ill-prepared to conduct a proper bridge watch. The Safety Board concludes that if passage planning standards that require a discussion between the master and the watchstanders before entering restricted waters had been developed and implemented, the risk of an accident would have been reduced. The Board believes that international standards should incorporate a requirement for such discussions. Therefore, the National Transportation Safety Board recommends that the International Chamber of Shipping:

Amend the "Passage Planning" section of its *Bridge Procedures Guide* to require a discussion between the master and his bridge watchstanders before entering restricted waters to ensure that each member of the watch understands his role and those of the other bridge team members when executing the passage plan.  
(Class II, Priority Action) (M-95-7)

Also, the Safety Board issued Safety Recommendations M-95-5 and -6 to the U.S. Coast Guard, M-95-8 and -9 to the International Council of Cruise Lines, and M-95-10 through -12 to Holland America Line Westours Inc.

The National Transportation Safety Board is an independent Federal agency with the statutory responsibility "to promote transportation safety by conducting independent accident investigations and by formulating safety improvement recommendations" (Public Law 93-633). The Safety Board is vitally interested in any action taken as a result of its safety recommendations. Therefore, it would appreciate a response from you regarding action taken or contemplated with respect to the recommendation in this letter. Please refer to Safety Recommendation M-95-7 in your reply. If you need additional information, you may call (202) 382-6864.

Chairman HALL, Vice Chairman FRANCIS, and Member HAMMERSCHMIDT concurred in this recommendation.

By:   
Jim Hall  
Chairman