

Log R-397A  
AI-4

NATIONAL TRANSPORTATION SAFETY BOARD  
WASHINGTON, D.C.

ISSUED: March 5, 1982

-----  
Forwarded to:

Mr. W. J. Taylor  
President and Chief Executive Officer  
Illinois Central Gulf Railroad Company  
233 North Michigan Avenue  
Chicago, Illinois 60601

SAFETY RECOMMENDATION(S)

R-82-2

-----  
The National Transportation Safety Board has found in 20 derailments investigated since 1976 that the probable cause was a track turnout component malfunction or that such a malfunction was a contributing factor to the probable cause. Eleven of these 20 derailments occurred on 4 railroads, while the other 9 derailments were individual to 9 other railroads. (See attachment.) All of these accidents met or exceeded the criteria for investigation by the Safety Board. 1/ These accidents resulted in 2 deaths, 23 injuries, and individual property damage in excess of \$1 million. The potential for any of these derailments to have been catastrophic is underscored by the fact that six of the accidents involved passenger trains. The release of hazardous materials, with ensuing evacuations, is also a danger in a freight train derailment.

The Federal Railroad Administration documented a total of 808 accidents 2/ reported by all railroads in 1980, which were caused by defects in frogs, switches, and track appliances.

The fact that two of these accidents occurred on the tracks of the Illinois Central Gulf Railroad Company indicates that the quality of current inspection practices or maintenance procedures, or both, for track turnouts, track crossings, and special trackwork may not be adequate. All of the Safety Board accident investigations also revealed that the defective conditions existed for an extended time before the accidents, further indicating an inadequate type or quality of inspection.


1/ Before 1978: derailments resulting in loss of life, freight train property damage exceeding \$500,000, and passenger train property damage exceeding \$10,000. After 1978: derailments resulting in loss of life, freight train property damage exceeding \$150,000, and all passenger train derailments.

2/ Any train accident exceeding \$2,900 in damage to railroad on-track equipment, signals, track, or track structures and roadbed.

Therefore, the National Transportation Safety Board recommends that the Illinois Central Gulf Railroad Company:

Evaluate the quality of existing inspection practices and maintenance procedures for track turnouts, track crossings, and special trackwork, and revise those practices and procedures where necessary to prevent derailments. (Class II, Priority Action) (R-82-2)

KING, Chairman, DRIVER, Vice Chairman, McADAMS, GOLDMAN, and BURSLEY, Members, concurred in this recommendation.

  
By: Jim Burnett  
Acting Chairman

Accidents Investigated With Track Turnout Component Malfunctions

<u>Date</u>	<u>Location</u>	<u>Railroad</u>	<u>Cause/Factor</u>
3-17-76	Knoxville, TN	Southern Ry.	Switch component failure; poor switch ties.
10-28-76	Thomasonville, CT	Amtrak	Spring frog failure due to deterioration.
12-26-76	Downington, PA	Amtrak	Material failure of switch ties.
7-15-77	Las Vegas, NM	A.T. & S.F.	Inadequate switch point maintenance.
1-18-78	Ravenden, AR	S.L. - S.F.	Damage to track frog from prior operations.
1-19-78	Holly, CO	A.T. & S.F.	Failure of spring switch due to inadequate maintenance.
3-23-78	Queens, NY	Conrail	Inadequate switch maintenance.
7-2-78	Pinole, CA	A.T. & S.F.	Switch not equipped with visible position indicator.
7-13-78	Paoli, PA	Amtrak	Improper switch stand securement.
12-8-78	Zurich, MT	B.N.	Failure of switch points due to deterioration.
1-12-79	Woodburn, IA	B.N.	Failure of switch points due to deterioration.
2-19-79	Covington, GA	Ga. RR	Damage to track frog from prior operations.
3-21-79	Alva, OK	A.T. & S.F.	Failure of switch points due to inadequate inspection and replacement policy.
5-22-79	Rock River, WY	U.P.	Improper installation of switch head blocks.
10-5-79	Chicago, IL	I.C.G.	Failure of track frog due to missing bolts.

<u>Date</u>	<u>Location</u>	<u>Railroad</u>	<u>Cause/Factor</u>
12-14-79	Benton, AR	Mo. Pac.	Failure of switch points due to deterioration.
12-17-79	Chicago, IL	I.C.G.	Failure of switch points; improper stock rail fit.
1-14-81	Estherwood, LA	So. Pac.	Switch rod failure due to deterioration.
3-20-81	Tyler, TX	S.L. - S.W.	Switch rod failure due to deterioration.
8-7-81	Bridgman, MI	C. & O.	Switch rod failure due to improper installation.