

U.S. CONSUMER PRODUCT SAFETY COMMISSION

4330 EAST WEST HIGHWAY

BETHESDA, MARYLAND 20814-4408

Todd A. Stevenson Director • Office of the Secretary Division of Information Management • Office of Information and Technology Tel: 301-504-6836 Fax: 301-504-0127 Email: <u>tstevenson@cpsc.gov</u>

August 21, 2008

CERTIFIED MAIL

Daniel Hogan, Esq. Law Offices of Robert A. Stutman 501 Office Center Drive Suite 300 Fort Washington, PA 19034

Re: FOIA Request 08-F-00607: American Power Conversion (APC) Power Supply Devices / Complaints, Reported Incidents, Investigations of Incidents and Commission's Office of Compliance and Field Operations Corrective Action or Recall File RP030081

Dear Mr. Hogan:

Thank you for your Freedom of Information Act ("FOIA") request seeking information from the U.S. Consumer Products Safety Commission ("Commission"). The records from the Commission files responsive to your request have been processed and copies of the releasable responsive records are enclosed. The enclosed records include file information generated by the Commission itself or its contractors for regulatory or enforcement purposes. These records are from law enforcement investigatory files designated RP030081, and include memoranda, correspondence, notes and documents. The Commission has established management systems under which supervisors are responsible for reviewing the work of their employees or contractors. The file information materials are final and have been prepared and accepted by the Commission's staff under such review systems. The Commission believes that it has taken reasonable steps to assure the accuracy of the information.

The enclosed records include Epidemiologic Investigation Reports with the underlying and supporting documentation. The Commission has received this information from its formal investigation systems. Through these systems the Commission hopes to learn when specific products are associated with illness, injury or death. The Commission believes that it has taken reasonable steps to assure the accuracy of this information. While conducting the interviews for the investigation reports, Commission staff or contractors have spoken with the individuals Daniel Hogan, Esq. Law Offices of Robert A. Stutman Page 2

involved or with others who witnessed or are familiar with the incidents. Where possible, Commission staff has examined the products reportedly involved in the incidents. Although the Commission has investigated the incidents described in the investigation reports, the Commission has not necessarily determined the cause of the incidents.

Also enclosed are records pertaining to product complaints and reported incidents that were submitted to the Commission by consumers and others. The consumers or submitters have confirmed the accuracy of the information in the complaints and reported incidents. The Commission has neither investigated the incidents nor conducted or obtained any evaluations of the products that corroborate the substance of the information contained in the complaints and reported incidents. In the complaints and reported incidents we have removed the identities of the complainants at their request.

We are withholding other records responsive to your request that are contained in the Commission's law enforcement investigatory file, RP030081, pursuant to the FOIA Exemptions 3, 4, and 5, 5 U.S.C. §§ 552(b)(3), (b)(4), and (b)(5), and sections 6(a)(2), 6(b)(1) and 25(c), of the Consumer Product Safety Act ("CPSA"), 15 U.S.C. §§ 2055(a)(2), and (b)(1) and §2074(c). FOIA Exemption 3 provides for the withholding from disclosure of matters that are specifically exempted from disclosure by another statute. In applying FOIA Exemption 3 to these records, we are relying in part on CPSA section 6(a)(2) to withhold files that contain proprietary and confidential information. Section 6(a)(2) prohibits the Commission from disclosing information that is exempt from disclosure under Exemption 4 of the FOIA. That exemption protects trade secrets and confidential commercial information directly related to a firm's business that the firm has not made public and whose disclosure could give a substantial commercial advantage to a competitor. The protected records include file materials containing submitted confidential commercial information, such as, submitted proprietary engineering and technical drawings, marketing processes, sales details and customer lists from the entire APC submission dated January 3, 2002 (sic).

We are also withholding the same records from the files pertaining to the negotiations with the company, according to the Commission regulations at 16 C.F.R. § 1101.33, and Exemption 3 of the FOIA and section 6(b)(1) of the CPSA, which prohibits the Commission from disclosing information about a consumer product that identifies a manufacturer or private labeler unless the Commission has taken "reasonable steps" to assure that the information is accurate, that disclosure is fair in the circumstances, and that disclosure will be reasonably related to effectuating the purposes of the laws that the Commission administers. It would not be fair in the circumstances to disclose a firm's notes, drafts or minutes of meetings to discuss and negotiate settlement agreements, when the company has requested confidentiality and such records are protected from disclosure pursuant to 16 C.F.R. § 1101.33. Specifically, we are withholding notes and draft materials that would reveal the settlement negotiations and discussions about the issues of the corrective action.

Certain preliminary internal Commission staff notes and analyses are also being withheld pursuant to FOIA Exemption 5. Exemption 5 provides for the withholding from disclosure of inter-agency and intra-agency memoranda which would not be available by law to a party other than an agency in litigation with the agency. The staff notes and analyses being Daniel Hogan, Esq. Law Offices of Robert A. Stutman Page 3

withheld are both predecisional and deliberative, consisting of recommendations, opinions, suggestions and analyses. Any factual materials in the memoranda not covered by some other exemption are inextricably intertwined with exempt materials or the disclosure of the factual materials would itself expose the deliberative process. We have determined that the disclosure of the law enforcement investigatory records responsive to your request would be contrary to the public interest. It would not be in the public interest to disclose these materials because disclosure would impair the frank exchange of views necessary with respect to such matters.

You will note that in the documents disclosed information that could identify injured parties has been deleted, because section 25(c) of the CPSA, 15 U.S.C. § 2074(c)(1), prohibits such disclosures without the consent of those individuals.

According to the Commission's FOIA regulations at 16 C.F.R. § 1015.7, a partial denial of access to records may be appealed within thirty (30) days of your receipt of this letter by writing to: FOIA APPEAL, General Counsel, ATTN: Office of the Secretary, U.S. Consumer Product Safety Commission, 4330 East West Highway, Bethesda, Maryland 20814-4408.

Processing this request, performing the file searches and preparing the information, cost the Commission \$50.00. In this instance, we have decided to waive all of the charges.

Sincerely, The Todd A. Stevenson

Enclosures

534602 SC 11 DA 104

FAX NO.

CONTENTS OF FILE CASE NO. <u>RP 03008</u>

TAB				<u>() () () () () () () () () () () () () (</u>			
	TELEPHONE LOG		PSA REQUEST FOR	MS			
	CASE LOG		PSA RESPONSE FO	RMS			
	COMPLIANCE OFFICER NOTES TO FIL	£	INDEPTH INVESTIC	GATIONS IDI AND IPII REPORTS			
	INITIAL SEC. 15 REPORT FROM FIRM		SAMPLE COLLECT	ION REPORT			
	INTERIM SEC. 15 REPORT FROM FIRM		CLOSED MEETING	MEMORANDUM			
	FULL SEC. 15 REPORT FROM FIRM		VOLUNTARY STAN	DARD AND TESTING REPORTS			
	CORRESPONDENCE TO COMPLIANCE	FROM FIRM	FIRM TESTING REP	ORTS/DATA			
	FULL REPORT (RP) LETTERS TO FIRM CARD	W/GREEN	PROGRESS REVIEW	REQUESTS AND REPORTS			
	CASE OPENING (CA) LETTERS TO FIRM W/GREEN CARD OTHER CORRESPONDENCE FROM COMPLIANCE TO FIRM PRELIMINARY DETERMINATION (PD) FORM		EFFECTIVENESS CHECKS REQUESTS AND REPORTS				
			MEMOS TO COMMISSION				
			CLOSE OUT LETTER				
	ACCEPT CAP FORM		CASE CLOSE FORM				
	PRESS RELEASE						
	CAP DOCUMENTS						
	<u>Krampy</u> ce officer:	APC		Peter Wexler CONTACT			
	Thick ISION ATTORNEY	FIRM ADDRESS		CONTACT ADDRESS			
Power PRODUCT	e	CITY,STATE AND		CTTY, STATE AND ZIP CODE 401-789-5735 x 225 TEL NO.			
HAZARD	ZARD FIRM WEBS		DDRESS	101 - 789 - 3710			

Assign No	From	insp Firm Name	insp Firm Addr	Insp Firm City	Notify Firm	Firm Follow	Recall Sign	Inventory Init	Inventory Notif
030328CRC6723	BRD	Office Depot	11001 Lee Hwy.	Fairfax, VA 22030	Y	Y	N	7	5
030328CRC6724	MKP	Comp-USA	826 S. Wheatley St.	Ridgeland, MS 39157	Y	Y	Y		0
030328CRC6725	MKP	Office Depot 358	6329 I-55 North	Jackson, MS 39213	Y	Y	Y	0	0
030328CRC6726	NJ	Staples	1491 Route 23 South	Wayne, NJ 07470	Y	*	Y	0	0
030328CRC6727	NJ	Office Depot	1465 US Highway 46 West	Little Falls, NJ 07424	Y	N	Y	7	7
030328CRC6728	BGB	Office Depot	3795 West Emporium Circle	Mesquite, Texas 75150	N	*	*	0	0
030328CRC6729	BGB	Circuit City	3733 West Emporium	Mesquite, Texas 75150	Y	Y	Y	2	2
030328CRC6730	BGB	Comp USA	1515 Town East Blvd. #168	Mesquite, Texas 75150	Y	Y	Y	279	188
030328CRC6731	BGB	Frys Electronics	12710 Executive Dr.	Dallas, Texas 75238	Y	Y	Y	14	10
03^^?8CRC6732	BGB	Staples	9222 E. RL Thorton Freeway	Dallas, Texas 75228	Y	Y	Y	0	0
030328CRC6733	WA	Office Depot	1751 Airport Way South	Seattle, WA 98184	Y	N	N	45	7
030328CRC6734	Gυ	PC OUTLET	P.O. BOX 20148	Barrigada, GU 96921	N	*	N	0	0
030328CRC6735	ID	Office Depot	3545 E. Fairview	Meridian, Idaho 83642	Y	Y	Y	0	5
030328CRC6736	ID	n/a			N	*	*		
030328CRC6737	ID	Staples, Inc. #622	1901 Caldwell Blvd	Nampa, ID 83651	Y	Y	Y	4	0
030422WRC5457	'ID	n/a			N	*	*		

.

•

0	0	0	7	0	0	0	0	0	0	0	0	0	0	Inventory Insp
0	0	0	2	0	0			0			0		0	Return Num

•

ł

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6723
	3. MIS: 31102
4. FROM: BRD Bini R. Dahlman	5. HOURS EXPENDED: 3 TRAVEL: 1
Investigator FOER Office	
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 04/05/2003
8. FIRM INSPECTED:	9. FIRM INITIATING THE RECALL:
Name: Office Depot	American Power Conversion 132 Fairgrounds Road
Address: 11001 Lee Hwy.	W. Kingston, RI 02892
City/St/Zip: Fairfax, VA 22030	
10. PRODUCT RECALLED:	11. HAZARD:
Uninterruptible Power Supply (UPS)	Fire hazard, internal failure can cause the unit to overheat and mell
12. TYPE OF COSIGNEE: Wholesaler 🗹 Retailer 🗌 Cor	nsumer 🗌 Other (Specify)
13. PERSON(S) INTERVIEWED:	
Name: Alfredo Oliver Title: Asst. Mgr.	Name: Sonia Carias Title: Service Mgr.
14. WAS FIRM NOTIFIED OF RECALL? ONO Yes METHO	DD / DATE: E-Mail 01/20/2003
RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?	No Yes (Notice Date): 01/20/2003
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? ON/A	No Yes
WAS PRODUCT TAKEN OFF SALE? 🔘 No 🌘 Yes D	ate: 01/20/2003
16. WAS SUB-RECALL INVOLVED? ON/A ON OYes	(If Yes, discuss details/mechanism under "REMARKS")
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P	LAN NOTIFICATION SIGNS POSTED? 🔿 N/A 🌒 No 🔿 Yes
18. INVENTORY OF RECALLED PRODUCT:	
a. Initial inventory received of the recalled product:	7
b. Inventory at time of notification:	5
c. Inventory at time of inspection: d. Number of Returns:	0 0
	· · · · · · · · · · · · · · · · · · ·
19. DISPOSITION OF RECALLED PRODUCT:	
Back-up power supply returned to manufacturer. NUMBER OF PRODUCTS DISPOSED: 5	
20. INJURIES OR COMPLAINTS: ON/A No OYes (If	Yes, report by separate memo)
21. REMARKS:	
Personnel at the Office Depot said they did not receive a recall sign	. A copy of the recall sign was provided, by this writer, for posting.
22. INVESTIGATOR AND DATE: Bini R. Dahlman	04/06/2003
23. ENDORSEMENT:	

i,

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6724
	3. MIS: 31102
4. FROM: MKP Mary K. Pigott	5. HOURS EXPENDED: 3 TRAVEL: 1
Investigator FOER Office	
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 05/21/2003
8. FIRM INSPECTED:	9. FIRM INITIATING THE RECALL:
Name: Comp-USA	American Power Conversion
Address: 826 S. Wheatley St.	132 Fairgrounds Road W. Kingston, RI 02892
City/St/Zip: Ridgeland, MS 39157	
10. PRODUCT RECALLED:	11. HAZARD:
Uninterruptible Power Supply (UPS)	Fire hazard, internal failure can cause the unit to overheat and mell
12. TYPE OF COSIGNEE: Wholesaler 🖌 Retailer 🗋 Cor	nsumer Other (Specify)
13. PERSON(S) INTERVIEWED:	
Name: Linda R. Laird Title: Front End Mgr.	Name: Title:
14. WAS FIRM NOTIFIED OF RECALL? () No Yes METH	OD / DATE: E-Mail 01/28/2003
RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?	-
	-
WAS PRODUCT TAKEN OFF SALE? 🌑 No 🔿 Yes D	tate: 00/00/0000
16. WAS SUB-RECALL INVOLVED? • N/A O No O Yes	(If Yes, discuss details/mechanism under "REMARKS")
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P	
18. INVENTORY OF RECALLED PRODUCT:	
a. Initial inventory received of the recalled product:	Unknown
b. Inventory at time of notification:	0
c. Inventory at time of inspection:	0
d. Number of Returns:	0
19. DISPOSITION OF RECALLED PRODUCT:	
No affected units in stock at time of notice.	
NUMBER OF PRODUCTS DISPOSED: 0	
20. INJURIES OR COMPLAINTS: ON/A ONO Yes (If	Yes, report by separate memo)
21. REMARKS:	<u> </u>
	units were marked with an "R" to indicate manufacture date after problem
was correctedsee recall notice.) At time of inspection, firm had abo	
22. INVESTIGATOR AND DATE: Mary K. Pigott	05/22/2003
23. ENDORSEMENT:	
· · · · · · · · · · · · · · · · · · ·	

i

(

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6725
	3. MIS: 31102
4. FROM: MKP Mary K. Pigott	5. HOURS EXPENDED: 3 TRAVEL: 1
Investigator FOER Office	
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 05/14/2003
8. FIRM INSPECTED:	9. FIRM INITIATING THE RECALL:
Name: Office Depot 358	American Power Conversion 132 Fairgrounds Road
Address: 6329 I-55 North City/St/Zip: Jackson, MS 39213	W. Kingston, RI 02892
· · · · · · · · · · · · · · · · · · ·	
	11. HAZARD:
Uninterruptible Power Supply (UPS)	Fire hazard, internal failure can cause the unit to overheat and mell
12. TYPE OF COSIGNEE: Wholesaler Retailer Cor	nsumer 🗌 Other (Specify)
13. PERSON(S) INTERVIEWED:	
Name: Jeffrey L. Ross Title: Store Manager	Name: Title:
14. WAS FIRM NOTIFIED OF RECALL? O No Yes METHO	OD / DATE: E-Mail 01/17/2003
RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?	No () Yes (Notice Date): 00/00/0000
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? ON/A	No 🔴 Yes
WAS PRODUCT TAKEN OFF SALE? 🌑 No 🔘 Yes D	Jate: 00/00/0000
16. WAS SUB-RECALL INVOLVED? • N/A O No O Yes	(If Yes, discuss details/mechanism under "REMARKS")
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P	
18. INVENTORY OF RECALLED PRODUCT:	
a. Initial inventory received of the recalled product:	0
b. Inventory at time of notification:	0
c. Inventory at time of inspection: d. Number of Returns:	0 0
19. DISPOSITION OF RECALLED PRODUCT: No recalled products in stock at time of notice	
NUMBER OF PRODUCTS DISPOSED: 0	
	Yes, report by separate memo)
21. REMARKS:	
Recall notice posted from 1/17/2003 to 4/02/2003.	
At time of inspection, there were two new units of the product in stor	ck. Not affected by the recall noticeshipped to firm 4/15/2003.
22. INVESTIGATOR AND DATE: Mary K. Pigott	05/14/2003
23. ENDORSEMENT:	

1

í

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6726
	3. MIS: 31102
4. FROM: NEW JERSEY State FOER Office	5. HOURS EXPENDED: 1 TRAVEL: 2
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 07/01/2003
8. FIRM INSPECTED: Name: Staples Address: 1491 Route 23 South City/St/Zip: Wayne, NJ 07470	9. FIRM INITIATING THE RECALL: American Power Conversion 132 Fairgrounds Road W. Kingston, RI 02892
10. PRODUCT RECALLED: Uninterruptible Power Supply (UPS)	11. HAZARD: Fire hazard, internal failure can cause the unit to overheat and mell
12. TYPE OF COSIGNEE: Wholesaler 🗹 Retailer 🗌 Cor	nsumer D Other (Specify)
13. PERSON(S) INTERVIEWED: Name: George Stickle Title: General Manag	Name: Title:
14. WAS FIRM NOTIFIED OF RECALL? O No Yes METHOR RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?	-
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? N/A WAS PRODUCT TAKEN OFF SALE? No Yes D	0
16. WAS SUB-RECALL INVOLVED? ON/A ONO Yes	(If Yes, discuss details/mechanism under "REMARKS")
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P	LAN NOTIFICATION SIGNS POSTED? ON/A ONO Yes
 18. INVENTORY OF RECALLED PRODUCT: a. Initial inventory received of the recalled product: b. Inventory at time of notification: c. Inventory at time of inspection: d. Number of Returns: 	0 0 0 0
19. DISPOSITION OF RECALLED PRODUCT: Had none when they where notified of recall. NUMBER OF PRODUCTS DISPOSED: 0	
20. INJURIES OR COMPLAINTS: ON/A No OYes (If	Yes, report by separate memo)
21. REMARKS: Store received an unknown quantity of recalled product which was a returns.	Il sold out at time of notification of recall. Store did post recall sign. No
22. STATE AND DATE:	NEW JERSEY 07/01/2003
23. ENDORSEMENT:	

1

1

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6727	
	3. MIS: 31102	
4. FROM: NEW JERSEY State FOER Office	5. HOURS EXPENDED: 1 TRAVEL: 2	
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 07/01/2003	
8. FIRM INSPECTED: Name: Office Depot Address: 1465 US Highway 46 West City/St/Zip: Little Falls, NJ 07424	9. FIRM INITIATING THE RECALL: American Power Conversion 132 Fairgrounds Road W. Kingston, RI 02892	
10. PRODUCT RECALLED: Uninterruptible Power Supply (UPS)	11. HAZARD: Fire hazard, internal failure can cause the unit to overheat an	d mell
12. TYPE OF COSIGNEE: Wholesaler 🖌 Retailer 🗌 Cor	nsumer Other (Specify)	
13. PERSON(S) INTERVIEWED: Name: Ron Evans Title: Manager	Name: Title:	
14. WAS FIRM NOTIFIED OF RECALL? ONO Yes METHOR RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?		
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? ON/A WAS PRODUCT TAKEN OFF SALE? No Yes D	0	
16. WAS SUB-RECALL INVOLVED? N/A ONO Yes	(If Yes, discuss details/mechanism under "REMARKS")	
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P		Yes
 18. INVENTORY OF RECALLED PRODUCT: a. Initial inventory received of the recalled product: b. Inventory at time of notification: c. Inventory at time of inspection: d. Number of Returns: 	7 7 0 0	
19. DISPOSITION OF RECALLED PRODUCT: Items where disposed of by A.P.C. Corporation. NUMBER OF PRODUCTS DISPOSED: 7		_
20. INJURIES OR COMPLAINTS: ONA No Yes (If	Yes, report by separate memo)	
21. REMARKS: Recall sign was posted. Subject had (4) of #350 and (3) of #500, all	returned to recalling firm.	
22. STATE AND DATE:	NEW JERSEY	07/01/2003
23. ENDORSEMENT:		

(

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6728					
	3. MIS: 31102					
4. FROM: BGB G. Brent Bradford	5. HOURS EXPENDED: 2 TRAVEL: 1					
Investigator FOCR Office						
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 04/04/2003					
8. FIRM INSPECTED:	9. FIRM INITIATING THE RECALL:					
Name: Office Depot	American Power Conversion					
Address: 3795 West Emponium Circle	132 Fairgrounds Road W. Kingston, RI 02892					
City/St/Zip: Mesquite, Texas 75150						
10. PRODUCT RECALLED:	11. HAZARD:					
Uninterruptible Power Supply (UPS)	Fire hazard, internal failure can cause the unit to overheat and mell					
12. TYPE OF COSIGNEE: Wholesaler 🗹 Retailer	Consumer Other (Specify)					
13. PERSON(S) INTERVIEWED:						
Name: Karen McGrew Title: Manager	Name: Title:					
14. WAS FIRM NOTIFIED OF RECALL? No OYes ME	THOD / DATE: 00/00/0000					
RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?	● No ○ Yes (Notice Date): 00/00/0000					
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? N/A	○ No ○ Yes					
WAS PRODUCT TAKEN OFF SALE? No 🚫 Yes	s Date: 00/00/0000					
16. WAS SUB-RECALL INVOLVED? N/A No Ye	es (If Yes, discuss details/mechanism under "REMARKS")					
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION						
18. INVENTORY OF RECALLED PRODUCT:						
a. Initial inventory received of the recalled product:	0					
b. Inventory at time of notification:	0					
c. Inventory at time of inspection: d. Number of Returns:	0 0					
19. DISPOSITION OF RECALLED PRODUCT:						
Did not receive the recalled models NUMBER OF PRODUCTS DISPOSED: 0						
20. INJURIES OR COMPLAINTS: N/A No Yes	(If Yes report by separate memo)					
21. REMARKS: Store Manager stated this store never received the recall notice	She reviewed the recall notice and stated her store did not carry the subject					
	Store Manager stated this store never received the recall notice. She reviewed the recall notice and stated her store did not carry the subject model models/serial numbers. Review of stock did not reveal any of the subject recalled products.					
22. INVESTIGATOR AND DATE: G. Brent Bradford	04/08/2003					
23. ENDORSEMENT:						

(.)

(

(

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6729				
	3. MIS: 31102				
4. FROM: BGB G. Brent Bradford	5. HOURS EXPENDED: 2 TRAVEL: 1				
Investigator FOCR Office					
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 04/04/2003				
8. FIRM INSPECTED:	9. FIRM INITIATING THE RECALL:				
Name: Circuit City	American Power Conversion				
Address: 3733 West Emporium	132 Fairgrounds Road W. Kingston, RI 02892				
City/St/Zip: Mesquite, Texas 75150					
10. PRODUCT RECALLED:	11. HAZARD:				
Uninterruptible Power Supply (UPS)	Fire hazard, internal failure can cause the unit to overheat and mell				
12. TYPE OF COSIGNEE: Wholesaler 🔽 Retailer 🗌 Con	nsumer 🗌 Other (Specify)				
13. PERSON(S) INTERVIEWED:					
Name: Noy Sphabmixay Title: Operations Mg	Name: Title:				
14. WAS FIRM NOTIFIED OF RECALL? 🔘 No 🌑 Yes METH	OD / DATE: Mail 01/22/2003				
RECALL NOTIFICATION PRESENTED TO INVESTIGATOR? \bigcirc	No Yes (Notice Date): 01/22/2003				
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? ON/A	No ● Yes				
WAS PRODUCT TAKEN OFF SALE? 🔘 No 🌘 Yes D	Pate: 01/22/2003				
16. WAS SUB-RECALL INVOLVED? ON/A ONO Yes	(If Yes, discuss details/mechanism under "REMARKS")				
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P					
18. INVENTORY OF RECALLED PRODUCT:					
a. Initial inventory received of the recalled product:	2				
b. Inventory at time of notification:	2				
c. Inventory at time of inspection: d. Number of Returns:	0				
19. DISPOSITION OF RECALLED PRODUCT: 2 units subject to recall returned to Circuit City distribution of					
NUMBER OF PRODUCTS DISPOSED: 2	enter for return to APC				
20. INJURIES OR COMPLAINTS: ON/A ONO Yes (If	Yes, report by separate memo)				
21. REMARKS:					
Operations Manager received recall and returned affected models w	with the serial numbers to Circuit City distribution center in Ardmore,OK for				
return to recalling firm APC. Review of stock did not reveal any of t	he subject recalled products.				
22. INVESTIGATOR AND DATE: G. Brent Bradford 04/08/2003					
23. ENDORSEMENT:					

i

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6730				
	3. MIS: 31102				
4. FROM: BGB G. Brent Bradford	5. HOURS EXPENDED: 2 TRAVEL: 1				
Investigator FOCR Office					
6. TYPE OF FOLLOW-UP: On-Site O Phone	7. DATE INSPECTED: 04/07/2003				
8. FIRM INSPECTED:	9. FIRM INITIATING THE RECALL: American Power Conversion				
Name: Comp USA	132 Fairgrounds Road				
Address: 1515 Town East Blvd. #168	W. Kingston, RI 02892				
City/St/Zip: Mesquite, Texas 75150					
10. PRODUCT RECALLED:	11. HAZARD:				
Uninterruptible Power Supply (UPS)	Fire hazard, internal failure can cause the unit to overheat and mell				
12. TYPE OF COSIGNEE: Wholesaler 🗹 Retailer 🗌 Cor	nsumer 🗌 Other (Specify)				
13. PERSON(S) INTERVIEWED:					
Name: Wayne Kubic Title: General Manag	Name: Title:				
14. WAS FIRM NOTIFIED OF RECALL? ON Ves METHO	OD / DATE: Mail 01/22/2003				
RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?	No Yes (Notice Date): 01/22/2003				
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? ON/A	No. A Yes				
WAS PRODUCT TAKEN OFF SALE? () No Yes D	-				
	(If Yes, discuss details/mechanism under "REMARKS")				
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P	LAN NOTIFICATION SIGNS POSTED? ON/A No Yes				
18. INVENTORY OF RECALLED PRODUCT:					
a. Initial inventory received of the recalled product:	279				
b. Inventory at time of notification:	188				
c. Inventory at time of inspection:	0				
d. Number of Returns:	0				
19. DISPOSITION OF RECALLED PRODUCT:					
Returned to recalling firm-some included not subject to recal	Il per HQ instructions				
NUMBER OF PRODUCTS DISPOSED: 188					
20. INJURIES OR COMPLAINTS: ON/A No Yes (If	Yes, report by separate memo)				
21. REMARKS:					
	rice for Comp USA. Firm also returned every product regardless of the				
model number and serial number. A number of units were returned not subject to the recall per HQ policy.					
22. INVESTIGATOR AND DATE: G. Brent Bradford 04/08/2003					
23. ENDORSEMENT:					

.

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6731
	3. MIS: 31102
4. FROM: BGB G. Brent Bradford	5. HOURS EXPENDED: 2 TRAVEL: 1
Investigator FOCR Office	
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 04/08/2003
8. FIRM INSPECTED:	9. FIRM INITIATING THE RECALL:
Name: Frys Electronics	American Power Conversion
Address: 12710 Executive Dr.	132 Fairgrounds Road W. Kingston, RI 02892
City/St/Zip: Dallas, Texas 75238	
10. PRODUCT RECALLED:	11. HAZARD:
Uninterruptible Power Supply (UPS)	Fire hazard, internal failure can cause the unit to overheat and mell
12. TYPE OF COSIGNEE: Wholesaler Retailer Cor	nsumer Other (Specify)
13. PERSON(S) INTERVIEWED:	
Name: Michael Mejorado Title: Manager	Name: Elaine Huch Title: Customer Serv
14. WAS FIRM NOTIFIED OF RECALL? 🔿 No 🌑 Yes METH	OD / DATE: Mail 00/00/0000
RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?	No Yes (Notice Date): 01/22/2003
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? ON/A	No • Yes
WAS PRODUCT TAKEN OFF SALE? 🔘 No 🌑 Yes D	ate: 01/22/2003
16. WAS SUB-RECALL INVOLVED? ONA NO Yes	(If Yes, discuss details/mechanism under "REMARKS")
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P	
18. INVENTORY OF RECALLED PRODUCT:	
a. Initial inventory received of the recalled product:	14
b. Inventory at time of notification:	10
c. Inventory at time of inspection:	0
d. Number of Returns:	0
19. DISPOSITION OF RECALLED PRODUCT:	
All units returned to recalling firm	
NUMBER OF PRODUCTS DISPOSED: 10	
20. INJURIES OR COMPLAINTS: ON/A No OYes (If	Yes, report by separate memo)
21. REMARKS:	
All units subject to the recall were returned to the recalling firm. No	units subject to the recall were in stock at time of visit.
22. INVESTIGATOR AND DATE: G. Brent Bradford	04/08/2003
23. ENDORSEMENT:	

ĺ

(

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6732	
	3. MIS: 31102	
4. FROM: BGB G. Brent Bradford	5. HOURS EXPENDED: 2 TRAVEL: 2	
Investigator FOCR Office		
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 04/08/2003	
8. FIRM INSPECTED:	9. FIRM INITIATING THE RECALL:	
Name: Staples	American Power Conversion 132 Fairgrounds Road	
Address: 9222 E. RL Thorton Freeway	W. Kingston, RI 02892	
City/St/Zip: Dallas, Texas 75228		
10. PRODUCT RECALLED:	11. HAZARD:	
Uninterruptible Power Supply (UPS)	Fire hazard, internal failure can cause the unit to overheat and mell	
12. TYPE OF COSIGNEE: Wholesaler 🔽 Retailer 🗌 Cor	nsumer 🗌 Other (Specify)	
13. PERSON(S) INTERVIEWED:		
Name: Humayun Khan Title: Sales Manager	Name: Title:	
14. WAS FIRM NOTIFIED OF RECALL? O No Yes METH	DD / DATE: Mail 01/22/2003	
RECALL NOTIFICATION PRESENTED TO INVESTIGATOR? \bigcirc	No Yes (Notice Date): 01/22/2003	
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? ON/A	No Yes	
WAS PRODUCT TAKEN OFF SALE? ONO OYes D	ate: 01/22/2003	
16. WAS SUB-RECALL INVOLVED? ON/A ONO Yes	(If Yes, discuss details/mechanism under "REMARKS")	
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION PLAN NOTIFICATION SIGNS POSTED? ON/A ON Yes		
18. INVENTORY OF RECALLED PRODUCT:		
a. Initial inventory received of the recalled product: 0		
b. Inventory at time of notification:	0	
c. Inventory at time of inspection:	0	
d. Number of Returns:	0	
19. DISPOSITION OF RECALLED PRODUCT:		
Store never received the recall models		
NUMBER OF PRODUCTS DISPOSED: 0		
20. INJURIES OR COMPLAINTS: ON/A No OYes (If	Yes, report by separate memo)	
21. REMARKS:		
Management stated this store never received the recalled models w any of the recalled products.	ith the subject serial numbers. A review of this firm's stock did not reveal	
22. INVESTIGATOR AND DATE: G. Brent Bradford 04/09/2003		
23. ENDORSEMENT:		

ſ

(

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6733	
	3. MIS: 31102	
4. FROM: WASHINGTON State FOWR Office	5. HOURS EXPENDED: 1.25 TRAVEL: 0.5	
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 04/15/2003	
8. FIRM INSPECTED: Name: Office Depot Address: 1751 Airport Way South City/St/Zip: Seattle, WA 98184	9. FIRM INITIATING THE RECALL: American Power Conversion 132 Fairgrounds Road W. Kingston, RI 02892	
10. PRODUCT RECALLED: Uninterruptible Power Supply (UPS)	11. HAZARD: Fire hazard, internal failure can cause the unit to overheat and mell	
12. TYPE OF COSIGNEE: Wholesaler 🖌 Retailer 🗌 Cor	nsumer 🗌 Other (Specify)	
13. PERSON(S) INTERVIEWED: Name: Jason Bennett Title: Business Mach	Name: Title: Business Mach	
14. WAS FIRM NOTIFIED OF RECALL? O No Stress METHOR RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?	_	
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? ON/A WAS PRODUCT TAKEN OFF SALE? No Yes D	No () Yes ate: 04/15/2003	
16. WAS SUB-RECALL INVOLVED? ONA NO Yes	(If Yes, discuss details/mechanism under "REMARKS")	
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P		
18. INVENTORY OF RECALLED PRODUCT: a. Initial inventory received of the recalled product: 45 b. Inventory at time of notification: 7 c. Inventory at time of inspection: 7 d. Number of Returns: 2		
19. DISPOSITION OF RECALLED PRODUCT: Returned to Vendor NUMBER OF PRODUCTS DISPOSED: 2		
20. INJURIES OR COMPLAINTS: ON/A No OYes (If	Yes, report by separate memo)	
21. REMARKS: No recall signs posted even though Mgr got ernail. Items still on shelf-removed in my presence.		
22. STATE AND DATE:	WASHINGTON 05/07/2003	
23. ENDORSEMENT:		

ť

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6734	
	3. MIS: 31102	
4. FROM: GUAM	5. HOURS EXPENDED: 1.5 TRAVEL: 0.5	
State FOWR Office		
6. TYPE OF FOLLOW-UP: On-Site OPhone	7. DATE INSPECTED: 05/22/2003	
8. FIRM INSPECTED:	9. FIRM INITIATING THE RECALL:	
Name: PC OUTLET	American Power Conversion 132 Fairgrounds Road	
Address: P.O. BOX 20148 City/St/Zip: Barrigada, GU 96921	W. Kingston, RI 02892	
10. PRODUCT RECALLED:	11. HAZARD:	
Uninterruptible Power Supply (UPS)	Fire hazard, internal failure can cause the unit to overheat and mell	
12. TYPE OF COSIGNEE: Wholesaler 🗹 Retailer 🗌 Cor	sumer Other (Specify)	
13. PERSON(S) INTERVIEWED:		
Name: MATTHWE HO Title: TECHNICAL M	Name: Title:	
14. WAS FIRM NOTIFIED OF RECALL? No Yes METHOR RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?		
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? N/A O WAS PRODUCT TAKEN OFF SALE? No O Yes D	`	
16. WAS SUB-RECALL INVOLVED? N/A ONO Yes	(If Yes, discuss details/mechanism under "REMARKS")	
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P		
18. INVENTORY OF RECALLED PRODUCT:		
 a. Initial inventory received of the recalled product: b. Inventory at time of notification: 	0	
c. Inventory at time of inspection:	0	
d. Number of Returns:	0	
19. DISPOSITION OF RECALLED PRODUCT:		
None available NUMBER OF PRODUCTS DISPOSED: 0		
20. INJURIES OR COMPLAINTS: ON/A NO Yes (If	Yes, report hy separate memo)	
21. REMARKS:		
Firm claims recalled products were never imported, sold, or made available for sale to consumers. Firm only carries Cyber Power-type products. The American Power Conversion Smart UPS (1200 model) was purchased and used by firm for internal office use on		
22. STATE AND DATE:	GUAM 06/18/2003	
23. ENDORSEMENT:		

1

1

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6735	
	3. MIS: 31102	
4. FROM: IDAHO	5. HOURS EXPENDED: 0.25 TRAVEL: 0.25	
State FOWR Office		
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 04/22/2003	
8. FIRM INSPECTED:	9. FIRM INITIATING THE RECALL:	
Name: Office Depot	American Power Conversion	
Address: 3545 E. Fairview	132 Fairgrounds Road W. Kingston, RI 02892	
City/St/Zip: Mendian, Idaho 83642		
10. PRODUCT RECALLED:	11. HAZARD:	
Uninterruptible Power Supply (UPS)	Fire hazard, internal failure can cause the unit to overheat and mell	
12. TYPE OF COSIGNEE: Wholesaler 🗹 Retailer 🗌 Con	nsumer 🗍 Other (Specify)	
13. PERSON(S) INTERVIEWED:		
Name: David Marsey Title: Manager	Name: Title: Manager	
14. WAS FIRM NOTIFIED OF RECALL? O No 🌒 Yes METHO	-	
RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?	No (Yes (Notice Date): 00/00/0000	
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? ONA	No Yes	
WAS PRODUCT TAKEN OFF SALE? 🔘 No 🌑 Yes Da	ate: 00/00/0000	
16. WAS SUB-RECALL INVOLVED? ON/A No OYes	(If Yes, discuss details/mechanism under "REMARKS")	
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION PI		
18. INVENTORY OF RECALLED PRODUCT:		
a. Initial inventory received of the recalled product:	0	
b. Inventory at time of notification:	5 0	
c. Inventory at time of inspection: d. Number of Returns:	0	
19. DISPOSITION OF RECALLED PRODUCT: Returned to APC		
NUMBER OF PRODUCTS DISPOSED: 5		
20. INJURIES OR COMPLAINTS: ON/A NO Yes (If)	Yes, report by separate memo)	
21. REMARKS:		
Mr. Marsey said as soon as he received the e-mail the products were out of there. The notice was posted according to him for the time stated on the notice. All products on the shelf were acceptable.		
22. STATE AND DATE:	IDAHO 04/23/2003	
23. ENDORSEMENT:		

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6736
	3. MIS: 31102
4. FROM: IDAHO State FOWR Office	5. HOURS EXPENDED: 0 TRAVEL: 0
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 03/28/2003
8. FIRM INSPECTED: Name: n/a Address: City/St/Zip:	9. FIRM INITIATING THE RECALL: American Power Conversion 132 Fairgrounds Road W. Kingston, RI 02892
10. PRODUCT RECALLED: Uninterruptible Power Supply (UPS)	11. HAZARD: Fire hazard, internal failure can cause the unit to overheat and mell
12. TYPE OF COSIGNEE: Wholesaler 🗹 Retailer 🗌 Cor	nsumer D Other (Specify)
13. PERSON(S) INTERVIEWED: Name: na Title:	Name: Title:
14. WAS FIRM NOTIFIED OF RECALL? No Yes METHOR RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?	
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? N/A WAS PRODUCT TAKEN OFF SALE? No Yes D	•
16. WAS SUB-RECALL INVOLVED? • N/A O No O Yes	(If Yes, discuss details/mechanism under "REMARKS")
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P	
 18. INVENTORY OF RECALLED PRODUCT: a. Initial inventory received of the recalled product: b. Inventory at time of notification: c. Inventory at time of inspection: d. Number of Returns: 	Unknown Unknown Unknown Unknown
19. DISPOSITION OF RECALLED PRODUCT: n/a NUMBER OF PRODUCTS DISPOSED: 0	
20. INJURIES OR COMPLAINTS: N/A ONO Yes (If)	Yes, report by separate memo)
21. REMARKS: Assignment cancelled.	
22. STATE AND DATE:	IDAHO 11/05/2003
23. ENDORSEMENT:	

.

ſ

1

.

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030328CRC6737	
	3. MIS: 31102	
4. FROM: IDAHO	5. HOURS EXPENDED: 1 TRAVEL: 1	
State FOWR Office		
6. TYPE OF FOLLOW-UP: On-Site OPhone	7. DATE INSPECTED: 05/08/2003	
8. FIRM INSPECTED: Name: Staples, Inc. #622	9. FIRM INITIATING THE RECALL: American Power Conversion	
Address: 1901 Caldwell Blvd City/St/Zip: Nampa, ID 83651	132 Fairgrounds Road W. Kingston, RI 02892	
10. PRODUCT RECALLED: Uninterruptible Power Supply (UPS)	11. HAZARD: Fire hazard, internal failure can cause the unit to overheat and mell	
12. TYPE OF COSIGNEE: Wholesaler 🗹 Retailer 🗌 Cor	nsumer Other (Specify)	
13. PERSON(S) INTERVIEWED: Name: Cleo DeLaRosa Title: Manager	Name: Title:	
14. WAS FIRM NOTIFIED OF RECALL? ONO Yes METHOR RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?		
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? ON/A OWAS PRODUCT TAKEN OFF SALE? No Yes D	-	
16. WAS SUB-RECALL INVOLVED? ONA NO Yes	(If Yes, discuss details/mechanism under "REMARKS")	
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P	LAN NOTIFICATION SIGNS POSTED? ON/A NO Yes	
18. INVENTORY OF RECALLED PRODUCT:		
a. Initial inventory received of the recalled product:	4	
 b. Inventory at time of notification: c. Inventory at time of inspection: 	0	
d. Number of Returns:	0	
19. DISPOSITION OF RECALLED PRODUCT:		
n/a NUMBER OF PRODUCTS DISPOSED: 0		
20. INJURIES OR COMPLAINTS: ON/A NO OYes (If	Yes, report by separate memo)	
21. REMARKS:		
22. STATE AND DATE:	IDAHO 08/13/2003	
23. ENDORSEMENT:		

í.

1. TO: [] ATTN: Recall Coordinator	2. RN/ID: RP030081 Assign No: 030422WRC5457
	3. MIS: 31102
4. FROM: IDAHO State FOWR Office	5. HOURS EXPENDED: 0 TRAVEL: 0
6. TYPE OF FOLLOW-UP: On-Site Phone	7. DATE INSPECTED: 04/22/2003
8. FIRM INSPECTED: Name: n/a Address: City/St/Zip:	9. FIRM INITIATING THE RECALL: American Power Conversion 132 Fairgrounds Road W. Kingston, RI 02892
10. PRODUCT RECALLED: Uninterruptible Power Supply (UPS)	11. HAZARD: Fire hazard, internal failure can cause the unit to overheat and mell
12. TYPE OF COSIGNEE: Wholesaler 🖌 Retailer 🗌 Cor	nsumer 🗌 Other (Specify)
13. PERSON(S) INTERVIEWED: Name: n/a Title:	Name: Title:
14. WAS FIRM NOTIFIED OF RECALL? No O Yes METHOR RECALL NOTIFICATION PRESENTED TO INVESTIGATOR?	OD / DATE: 00/00/0000 No Yes (Notice Date): 00/00/0000
15. DID FIRM FOLLOW RECALL INSTRUCTIONS? N/A WAS PRODUCT TAKEN OFF SALE? NO Yes D	-
16. WAS SUB-RECALL INVOLVED? N/A ONO Yes	(If Yes, discuss details/mechanism under "REMARKS")
17. WERE RECALL/REPURCHASE OR CORRECTIVE ACTION P	
 18. INVENTORY OF RECALLED PRODUCT: a. Initial inventory received of the recalled product: b. Inventory at time of notification: c. Inventory at time of inspection: d. Number of Returns: 	Unknown Unknown Unknown Unknown
19. DISPOSITION OF RECALLED PRODUCT: n/a NUMBER OF PRODUCTS DISPOSED: 0	
20. INJURIES OR COMPLAINTS: N/A ONO Yes (If	Yes, report by separate memo)
21. REMARKS: Assignment cancelled. Duplicate of 030328crc6722	
22. STATE AND DATE:	IDAHO 11/05/2003
23. ENDORSEMENT:	

<u>д</u>О

ł

Assignment 030328CRC6734 - American Power Cor

(

U.S. CONS	
	NOTICE OF INSPECTION
5/22/03	augatua, 3 ¹¹ - 16 + 27
2. TIME	20. Box 2816
	Fagatna, 3h Abtin
A. NAME AND TITLE OF INDIVIDUAL	T I I Maria
Watthew HO	Technical Manager
B. FIRM NAME PC Outlet	U
. TO C. NUMBER AND STREET ADDRESS	
P.O. Box 20148	
D. CITY, STATE AND ZIP CODE Barrigada, GU	969.21
Notice of Inspection is hereby given pursuant to:	
• Flammable Fabrics Act (15 U.S.C. 1191	l et sea.);
Federal Trade Commission Act (15 U.S.	
•	
	r Product Safety Act (15 U.S.C. 2065, 2068 and 2076)
	ug, and Cosmetic Act (21 U.S.C. 374(a)) [Authority for inspections on Packaging Act of 1970 (15 U.S.C. 1471 et seq.)] and/or
• Section 11(b) of the Federal Hazardous	Substances Act as Amended (15 U.S.C. 1270(b)).
	inspectional authority and for pertinent statutory language.
limited to records, reports, books, documents;	FORMATION TO BE OBTAINED AND/OR COPIED. ormation; to review and obtain copies of items including but not ; and labeling; and to obtain samples, in order to enforce or de- ed by the Consumer Product Safety Commission.
FREEDOM OF INFORMATION REQUIREMENTS	
Those from whom information is requested s	hould state whether any of the information submitted is believed
to contain or relate to a trade secret or other n confidential and whether any of the informatic Commission under the provisions of the Freed this claim of confidentiality must be in writing	natter which should be considered by the Commission to be on is believed to be entitled to exemption from disclosure by the om of Information Act (15 U.S.C. 552). Any statement asserting g, and any request for exemption of the information from dis-
closure must be made in accordance with the C Part 1015.	Commission's Freedom of Information Act regulations. 16 CFR
7. SIGNATURE (Authorized CPSC Official)	
\sim /.	
CPSC Form 296/9/79)	ina J. Lating Ettern
	*U S. GPO. 1997-422-364/60004

28036081 U.S. CONSUMER PRODUCT SAFETY COMMISSION 030328CRC 6724 NOTICE OF INSPECTION MKP 1. DATE 3. FROM (Area Office and Address) FOER- JACKSON, MS 5-21-03 101-924-8370 2. TIME PO BOX 167 n 2:00 CLINTON MS 39040 A NAME AND TITLE OF INDIVIDUAL R. Laird, Front End Manager 1001-956-1118 inda . FIRM NAM OMP-USA **4** TO C NUMBER BAG S. WHEATLEY ST. D. CITY, STATE AND ZIP CODE RIDGE LAND, MS • Flammable Fabrics Act (15 U.S.C. 1191 et seq.); • Federal Trade Commission Act (15 U.S.C. 41 et seq.); • Sections 16, 19 and 27 of the Consumer Product Safety Act (15 U.S.C. 2065, 2068 and 2076) • Section 704(a) of the Federal Food, Drug, and Cosmetic Act (21 U.S.C. 374(a)) [Authority for inspections in connection with the Poison Prevention Packaging Act of 1970 (15 U.S.C. 1471 et seq.)] and/or Section 11(b) of the Federal Hazardous Substances Act as Amended (15 U.S.C. 1270(b)). Refer to the back of this form for a discussion of inspectional authority and for pertinent statutory language. S. PURPOSES OF INSPECTION AND NATURE OF INFORMATION TO BE OBTAINED AND/OR COPIED. The purpose of this inspection is to obtain information; to review and obtain copies of items including but not limited to records, reports, books, documents; and labeling; and to obtain samples, in order to enforce or determine compliance with the Acts administered by the Consumer Product Safety Commission. 6. FREEDOM OF INFORMATION REQUIREMENTS Those from whom information is requested should state whether any of the information submitted is believed to contain or relate to a trade secret or other matter which should be considered by the Commission to be confidential and whether any of the information is believed to be entitled to exemption from disclosure by the Commission under the provisions of the Freedom of Information Act (15 U.S.C. 552). Any statement asserting this claim of confidentiality must be in writing, and any request for exemption of the information from disclosure must be made in accordance with the Commission's Freedom of Information Act regulations, 16 CFR Part 1015. CPEC Form 256 (\$/79) *U.S. GPO: 2000-464-086

	U.S. CONSUMER PRODUCT SAFETY COMMISSION NOTICE OF INSPECTION	030328CRC6725 MKP
1. DATE	3. FROM (Ares Office and Address)	
5-14-03 2. TIME 1 <u>0:50</u> a.mp.m.	FOER-Jackson, MS P.O. Box 167 Clinton, MS 39060	601-924-8370
	L. Ross - Store Manac	per
		601-957-6115
6329 I	55 North	·
D. CITY, STATE AND ZIP CO Jackson,		
Notice of Inspection is hereby give	en pursuant to:	
• Flammable Fabrics Act (15 U.S.C. 1191 et seq.);	
Federal Trade Commission	on Act (15 U.S.C. 41 et seq.);	
 Sections 16, 19 and 27 o 	f the Consumer Product Safety Act (15 U.S.C. 2065, 2	068 and 2076)
	deral Food, Drug, and Cosmetic Act (21 U.S.C. 374(a) oison Prevention Packaging Act of 1970 (15 U.S.C. 14)	
• Section 11(b) of the Fed	eral Hazardous Substances Act as Amended (15 U.S.C.	1270(b)).
Refer to the back of this form for	a discussion of inspectional authority and for pertinen	t statutory language.
5. PURPOSES OF INSPECTION AND	NATURE OF INFORMATION TO BE OBTAINED AND/OR	COPIED.
limited to records, reports, boo	is to obtain information; to review and obtain copies of ks, documents; and labeling; and to obtain samples, in cts administered by the Consumer Product Safety Com	order to enforce or de-
8. FREEDOM OF INFORMATION RE	QUIREMENTS	
Those from whom information to contain or relate to a trade se	is requested should state whether any of the information of the information of the information is ballowed to be considered by the	ion submitted is believed Commission to be

.

confidential and whether any of the information is believed to be entitled to exemption from disclosure by the Commission under the provisions of the Freedom of Information Act (15 U.S.C. 552). Any statement asserting this claim of confidentiality must be in writing, and any request for exemption of the information from disclosure must be made in accordance with the Commission's Freedom of Information Act regulations, 16 CFR Part 1015.

J

030328CRC6733 203608
U.S. CONSUMER PRODUCT SAFETY COMMISSION
NOTICE OF INSPECTION
1. DATE 3. FROM (/
Larry Kirchner
2 TIME 10842 SE 208th, #273
11'30 Kent, WA 98031
Jason Bennett, Busines Machines Rep.
Office Depot
4. YO C. NUMBER AND STREET ADDRESS
1751 Airport Way So
D. CITY, STATE AND ZIP CODE
Seattle WA 98134
Notice of Inspection is hereby given pursuant to:
 Flammable Fabrics Act (15 U.S.C. 1191 et seq.);
• Federal Trade Commission Act (15 U.S.C. 41 et seq.);
 Sections 16, 19 and 27 of the Consumer Product Safety Act (15 U.S.C. 2065, 2068 and 2076)
 Section 704(a) of the Federal Food, Drug, and Cosmetic Act (21 U.S.C. 374(a)) [Authority for inspections in connection with the Poison Prevention Packaging Act of 1970 (15 U.S.C. 1471 et seq.)] and/or
• Section 11(b) of the Federal Hazardous Substances Act as Amended (15 U.S.C. 1270(b)).
Refer to the back of this form for a discussion of inspectional authority and for pertinent statutory language.
The of the sector of the form for a well-the of impression and only and for perturber statutory anguage.
S. FURPOSES OF INSPECTION AND NATURE OF INFORMATION TO BE OBTAINED AND/OR COPIED.
The purpose of this inspection is to obtain information; to review and obtain copies of items including but not limited to records, reports, books, documents; and labeling; and to obtain samples, in order to enforce or de- termine compliance with the Acts administered by the Consumer Product Safety Commission.
& FREEDOM OF INFORMATION REQUIREMENTS
Those from whom information is requested should state whether any of the information submitted is believed
to contain or relate to a trade secret or other matter which should be considered by the Commission to be
confidential and whether any of the information is believed to be entitled to exemption from disclosure by the Commission under the provisions of the Freedom of Information Act (15 U.S.C. 552). Any statement asserting
this claim of confidentiality must be in writing, and any request for exemption of the information from dis-
dozure must be made in accordance with the Commission's Freedom of Information Act regulations. 16 CFR Part 1015.
7. SIGNATURE (Authorized CPSC Official)
harry Kirchner
CP3C Ferm 294(5/78)

(

33

.

	03631/1CPC.462
	U.S. CONSUMER PRODUCT SAFETY COMMISSION
	NOTICE OF INSPECTION
1. DATE	3. FROM (Area Office and Addr
15 April 2003	Larry Kirchner
	c/o Eugene Staebell, CPSC Officer
2. TIME	10842 SF 208th, #273 Kent, WA 98031
330	(253) 631-6806
A. NAME AND TITLE OF INC	
1 Rohm Bl	iss, Dept Manager
A FIRM NAME	
B. FIRM RAME	
Sears	
4. TO C. NUMBER AND STREET A	DDR ESS
765. Land	er
D. CITY. STATE AND ZIP CO	OE
Seattle, WA	GRNLL
L Leavie wi	tond
Notice of Inspection is hereby give	in pursuant to:
 Flammable Fabrics Act (15 U.S.C. 1191 et seq.);
- Endered Tends Commissio	ba Act (15 U.S.C. 41 et seg.);
 Federal Frade Commission 	Na Ace (15 0.5.0. +1 er seq.);
Sections 16, 19 and 27 o	f the Consumer Product Safety Act (15 U.S.C. 2065, 2068 and 2076)
 Section 704(a) of the Fee 	deral Food, Drug, and Cosmetic Act (21 U.S.C. 374(a)) [Authority for inspections
in connection with the P	oison Prevention Packaging Act of 1970 (15 U.S.C. 1471 er seq.)] and/or
 Section 11(b) of the Fed 	eral Hazardous Substances Act as Amended (15 U.S.C. 1270(b)).
Refer to the back of this form for	a discussion of inspectional authority and for pertinent statutory language.
5. PURPOSES OF INSPECTION AND	NATURE OF INFORMATION TO BE OBTAINED AND/OR COPIED,
limited to records, reports, boo	is to obtain information; to review and obtain copies of items including but not its, documents; and labeling; and to obtain samples, in order to enforce or de- cts administered by the Consumer Product Safety Commission.
1	
1	
& FREEDOM OF INFORMATION RE	QUIREMENTS
	a is requested should state whether any of the information submitted is believed
	ecret or other matter which should be considered by the Commission to be
Commission under the entries	If the information is believed to be entitled to exemption from disclosure by the $r_{\rm eff}$ of the Francesco of Information Act (151150, 557). Any entities a starting
this claim of confidentiality me	as of the Freedom of Information Act (15 U.S.C. 552). Any statement asserting at be in writing, and any request for exemption of the information from dis-
closure must be made in accord	ance with the Commission's Freedom of Information Act regulations, 16 CFR
Part 1015.	The state of the second of the
7. SIGNATURE (Authorized CPSC Off	
φ 1. ()	
harm Kuching	
CFSC Face 294 (9/79)	*U \$ GPO 1997-422-364/80004

1

A

(

030328CR-C6723

ł

í

U.S. CONSUMER PRODUCT SAFETY COMMISSION RP030081
NOTICE OF INSPECTION
1. DATE 3. FROM (Area Office and Address)
SAPLO3 Crsc
2 TIME 10'20 Washington DC
<u>/U / A.M.</u> P.M.
A. NAME AND TITLE OF INDIVIDUAL
Altredo K. Oliver, Asst Men.
B. FIRM NAME
Office De not
4. TO C. NUMBER AND STREET ADDRESS
1011 Lee thuy
D. CITY, STATE AND ZIP CODE
Finha VA 22030
Notice of Inspection is hereby given pursuant to:
• Flammable Fabrics Act (15 U.S.C. 1191 et seq.);
• Federal Trade Commission Act (15 U.S.C. 41 et seq.);
• Sections 16, 19 and 27 of the Consumer Product Safety Act (15 U.S.C. 2065, 2068 and 2076)
 Section 704(a) of the Federal Food, Drug, and Cosmetic Act (21 U.S.C. 374(a)) [Authority for inspections in connection with the Poison Prevention Packaging Act of 1970 (15 U.S.C. 1471 et seq.)] and/or
• Section 11(b) of the Federal Hazardous Substances Act as Amended (15 U.S.C. 1270(b)).
Refer to the back of this form for a discussion of inspectional authority and for pertinent statutory language.
5. PURPOSES OF INSPECTION AND NATURE OF INFORMATION TO BE OBTAINED AND/OR COPIED.
The purpose of this inspection is to obtain information; to review and obtain copies of items including but not limited to records, reports, books, documents; and labeling; and to obtain samples, in order to enforce or de- termine compliance with the Acts administered by the Consumer Product Safety Commission.
γ
6. FREEDOM OF INFORMATION REQUIREMENTS

Those from whom information is requested should state whether any of the information submitted is believed to contain or relate to a trade correct or other method. It is that is the information submitted is believed to contain or relate to a trade correct or other method.

INSHERIOFERIOLEANE HORIZINALES 2018 ENVEL	
DER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
omplete items 1, 2, 3. Also complete em 4 if Restricted Delivery is desired. rint your name and address on the reverse that we can return the card to you. ttach this card to the back of the mailpiece, r on the front if space permits. rticle Addressed to:	A. Signature X Addressee B. Received by (Printed Name) DAVIC DIDVIC The Office of Delivery DAVIC DIDVIC The Office of Delivery D. Is delivery address different from item 17 [2] Yes If YES, enter delivery address below: No
Peter Wexler Senior Attorney American Power Conversion Corp. 132 Fairgrounds Road W. Kingston, RI 02892	3. Service Type 2. Certified Mail Certified Mail Registered Return Receipt for Merchandise Dissured Mail C.O.D.
U	
	4. Restricted Delivery? (Extra Fee)
001 1940 0001 3421 5404	4. Restricted Delivery? (Extra Fee)

,

	U.S. Postal Service CERTIFIED MAIL RECEIPT (Construction of the service of the service)										
5404	0	200 200 200	K-an K-an		C	(JIETIN)	A	\$	Û	S	2005 2005 2007
3421			Postage Ifled Fee	\$	····-			-	_		
1			celpt Fee Required)		_	-		1	Postmark Here		
1000	Restricts (Endorse	ed Del ment i	ivery Fee Required)								
무	Total P	ostagi	a Fees	\$							
1940	Sent To	,		RF	203	00	180				
1007	Street, A or PO Bo	pt. No).;				********	****	-*-48884484		
	City, Sta			• • • • •							
	DC Com	- 20711	1_1		TOTAL .			0 0			



U.S. CONSUMER PRODUCT SAFETY COMMISSION

WASHINGTON, D.C. 20207

OFFICE OF COMPLIANCE Recalls and Compliance Division Email: mschoem@cpsc.gov Marc J. Schoem Director Tel:301-504-7520 Fax: 301-504-0359

Certified Mail/FAX (401) 789-3710

June 29, 2004

Peter Wexler Senior Attorney American Power Conversion Corp. 132 Fairgrounds Road W. Kingston, RI 02892

> Re: CPSC RP030081 American Power Conversion Corporation Uninterruptible Power Supplies

Back-UPS CS350 and Back-UPS CS500

Dear Mr. Wexler:

The U.S. Consumer Product Safety Commission staff has reviewed your firm's progress in carrying out the corrective action plan in the referenced matter. The Office of Compliance has determined that no further monitoring on the part of the staff is warranted. Therefore, acting under delegation from the Commission, the staff has closed the corrective action phase of this case. The Commission staff, however, will reopen this file if it finds that the public has not been adequately protected from the risk of injury presented by this product by the corrective actions taken by the firm.

To ensure our records are complete, please submit a final progress report indicating the number of products returned/repaired/replaced by consumers and your distribution chain. Attached is a progress report for your use. Please also advise us if there have been any additional incident/injury reports and claims and lawsuits pertaining to the recalled products since the announcement of the recall. The final progress report and the incident/injury/claim and lawsuit reports should be faxed to the attention of Marc Schoem at 301-504-0359 within five (5) days of your receipt of this letter.

The firm has a continuing obligation to inform the Commission of defects associated with this product which could create a substantial product hazard and of information which reasonably supports the conclusion that a product creates an unreasonable risk of serious injury Page 2

×

or death. If the firm receives any information affecting the scope, prevalence, or seriousness of the defect or hazard, it must report to this Office immediately.

The staff requests that the firm continue to implement its corrective action program until as many products as possible have been removed from the marketplace. Please continue to maintain your toll-free number as a means for consumers to reach you about your recall. Should the firm decide to change or discontinue the toll-free number, you must notify the Division of Recalls and Compliance and provide a new recall contact number for the firm. This information will be maintained by CPSC and provided to consumers and others seeking information on your recall.

If the firm receives information that might indicate that its corrective actions are not satisfactory in eliminating the defect or hazard or that the effectiveness of the recall program was less than what had been reported, it must report that information to the Division of Recalls and Compliance immediately.

Thank you for your cooperation in this matter.

Sincerely,

Man J.Schum

Marc J. Schoem Director Recalls and Compliance Division

Monthly Progress Report for Corrective Action Plan & Incident Update

CASE# RP030081		Compliance Officer: Jack Kramer			
Company Name: American Po	ower Conversion	Product: Uninterruptible Power Supply			
Reporting Dates, From:	<u>7/1/2003</u> To:	7/31/2003 Total of Affected Products: 1,036,472			

I) PRODUCTS CORRECTED/CAPTURED BY YOUR FIRM:

Location of Products	Total Products	Corrections This Period	Total Corrections	Percent Corrected
With Manufacturer	122,791	0	90,286	74%
With Distributor*	30,365	0	30,365	100%
With Retailers**	54,316		39,761	73%
With Consumers	829,000	6,668	210,801	25%
TOTAL:	1,036,472	6,668	371,213	36%
	*r)istributor # as originally reported w	as understated	

* Distributor # as originally reported was understated **Retail and Catalog Total -original Retail # was higher

II) NOTIFICATION MEASURES

III) CONSUMER AWARENESS

Number for This Reporting Period		Total	Number for This Reporting Period	Total
Billing Insert	0	0	Billing Insert	_
Direct Mail Letter	30,000 *	* 314,484	Direct Mail Letter	
Magazine	0	0	Magazine	
Newspaper	0	0	Newspaper	
Pediatician Poster	O PA	0	Pediatician Poster	
Phone Call	0	0	Phone Call	
Product Catalog	0	1,335,966	Product Catalog	
Radio	0	0	Radio	
Retail Store Poster	O O O	3000	Retail Store Poster	
Television	0	0	Television	
Web Site*	0	341,917	Web Site	
Post Office	0	0	Post Office	
Thrift Store	0	0	Thrift Store	
Other Email	0	1,722,677	Other	
			Total 0	41,198
	* Recall Page Hits			
	** includes 248,235 mail	ed in april		
IV) Calls to 800 Number	er/Correspondence			
# From Cus	tomers This Reporting Po	əriod	Total	
800 Number		1,293	54,591	
E-mail		105	5796	
Written Requests		No. of the second s	<30	
V/ Incident				

V) Incident Update:

.

	# For This Reporting Period	Totai
# Incidents	0	15
# Injuries	0	0
# Deaths	0	0





• • • •

September 3, 2003

SENT VIA FEDEX

Jack T. Kramer **Compliance** Officer **Recalls and Compliance** United States Consumer Product Safety Commission 4330 East West Highway Room 613 Bethesda, Maryland 20814

Re: CPSC RP030081, American Power Conversion Corporation ("APC") UPS

Dear Mr. Kramer:

Please find accompanying this letter APC's Monthly Progress Reports and Corrective Action Plan & Incident Updates ('Update Reports") for May 2003, June 2003 and July 2003.

If you have *A* ny question of would like to discuss this Update Report in greater detail please do not hesitate to contact me directly at (401) 789-5735 x2255.

Very truly/your

Peter Wexler Associate General Counsel American Power Conversion Corporation

American Power Conversion Corporation

PO Box 278 132 Fairgrounds Road West Kingston, RI 02892 Visit www.apcc.com

Call 401 789 5735 Fax 401 789 3710

APC is an equal opportunity employer which values workforce diversity. APC's quality system is ISO 9002 certified.

Monthly Progress Report for Corrective Action Plan & Incident Update

CASE# RF	CASE# RP030081			Compliance Officer: Jack Kramer			
Company Na	me: American Powe	r Conversion	Product:	Uninterruptible Po	ower Supply		
Reporting Da	ites, From:	_6/1/2003_To:	6/30/2003 Total of A	ffected Products:	1,036,472		

I) PRODUCTS CORRECTED/CAPTURED BY YOUR FIRM:

Location of Products	Total Products	Corrections This Period	Total Corrections	Percent Corrected
With Manufacturer	122,791	0	90,286	74%
With Distributor*	30,365	0	30,365	100%
With Retailers**	54,316	• · · · ·	39,761	73%
With Consumers	829,000	6,919	204,133	
TOTAL:	1,036,472	6,919	364,545	35%
	*r)istributor # as originally reported w	understated	

* Distributor # as originally reported was understated **Retail and Catalog Total -original Retail # was higher

II) NOTIFICATION MEASURES

. .

۰.

III) CONSUMER AWARENESS

Number for This Rep	orting Period	Total	Number for This Reporting	Period	Totai
Billing Insert	0	0	Billing Insert		
Direct Mail Letter	0	36,249	Direct Mail Letter		
Magazine	0	0	Magazine		
Newspaper	0	0	Newspaper		
Pediatician Poster	0		Pediatician Poster		
Phone Call	0		Phone Call		
Product Catalog	0	1,335,966	Product Catalog		
Radio	0	0	Radio		
Retail Store Poster	0	3000	Retail Store Poster		
Television	0	0	Television		
Web Site*	0	341.917	Web Site		
Post Office	0	0	Post Office		
Thrift Store	0.		Thrift Store		
Other Email	0	1,722,677	Other		
			Total	0	41,198

* Recall Page Hits

IV) Calls to 800 Number/Correspondence # From Customers This Reporting Period

# From Customers This	Total	
800 Number	1,134	53,298
E-mail	112	5687
Written Requests	0	<30
V) Incident Update:		

	# For This Reporting Period	Total
# Incidents	0	15
# Injuries	0	0
# Deaths	0	0





Monthly Progress Report for Corrective Action Plan & Incident Update

CASE# RP030081 **Compliance Officer: Jack Kramer** Company Name: American Power Conversion Product: Uninterruptible Power Supply Reporting Dates, From: 5/1/2003 To: 5/31/2003 Total of Affected Products: 1,036,472

I) PRODUCTS CORRECTED/CAPTURED BY YOUR FIRM:

Location of Products	Total Products	Corrections This Period	Total Corrections	Percent Corrected
With Manufacturer	122,791	0	90,286	74%
With Distributor*	30,365	0	30,365	100%
With Retailers**	54,316		39,761	73%
With Consumers	829,000	53,493 ***	197,214	24%
TOTAL:	1,036,472	53,493	357,626	35%
	*r	Vietributer # on originally reported w	an understated	

Distributor # as originally reported was understated

**Retail and Catalog Total -original Retail # was higher

*** includes 927 not previously included from April period

II) NOTIFICATION MEASURES

III) CONSUMER AWARENESS

Number for This Rep	orting Period	Total	Number for This Reporting Period	Total
Billing Insert	0	0	Billing Insert	
Direct Mail Letter	0	36,249	Direct Mail Letter	
Magazine	0	0.	 Magazine	
Newspaper	0	0	Newspaper	
Pediatician Poster	0	0	Pediatician Poster	
Phone Call	0		Phone Call	
Product Catalog	0	1,335,966	Product Catalog	
Radio	0	0	Radio	
Retail Store Poster	0	3000	Retail Store Poster	
Television	0	0	Television	
Web Site*		341,917	Web Site	
Post Office	0	0	Post Office	
Thrift Store	0	0	Thrift Store	
Other Email	0	1,722,677		
			Total	0 41,198

* Recall Page Hits

IV) Calls to 800 Number/Correspondence

# From Customers This	Total	
800 Number	2,605	52,1 64
E-mail	350	5575
Written Requests		<30
V) Incident Update: # For This	Total	
# Incidents	0	<u>15</u>
# Injuries	0	0
# Deaths	0	0

Monthly Progess Report for Corrective Action Plan & Incident Update Case #: RP030081 Compliance ficer: Jack Kramer

Company Name: American Power Conversion Reporting Dates, From: 06/01/2003 To: 06/30/2003 Product: Uninterruptible Power Sup

Total # of Affected Products: 1.036.472

I) PRODUCTS CORRECTED/CAPTURED BY YOUR FIRM:

Location of Products	Total Products	Corrections This Period	Total Corrections	Percent Corrected
with Manufacturers	122,791	······································	90,286	73.53%
with Distributors	30,365		30,365	100.00%
with Retailers	54,316		39,761	73.19%
with Consumers	829,000	6,919	204,133	24.62%
TOTAL:	1,036,472	6,919	364,545	35.17%

II) NOTIFICATION MEASURES:

(Using the categories listed below, record the number of notifications attempted by your firm during this reporting period and the total number of notifications to date.

III) CONSUMER AWARENESS:

(Using the categories listed below, record the way, by numerical quantity, consumers told you they learned of the corrective action, i.e. consumer received direct mail, read magazines, etc.)

Number for this Reporting Period	Total	Number for this Reporting Period	Total
Billing Insert	0	Billing Insert	0
Direct Mail Letter	232,912	Direct Mail Letter	0
Magazine	. 0	Magazine	0
Newspaper	0	Newspaper	0_
Pediatrician Poster	0	Pediatrician Poster	0
Phone Call	0	Phone Call	0_
Product Catalog	1,335,966	Product Catalog	0
Radio	0	Radio	0
Retail Store Poster	3,000	Retail Store Poster	0
Television	0	Television	0
Web Site	262,103	Web Site	0
Thrift Store	0	Thrift Store	0
Post Office	0	Post Office	0
Video News Release	0	Video News Release	0
Other/Unknown	1,722,677	Other/Unknown	55,172

IV) Call to 800 Number/Correspondence:

# For This Re	porting Period	Total
800 Number	1,134	40,218
E-mail	112	3,487
Written Requests		20
Web Site Hits		0

V) Incident Update:

	# For This Reporting Period	Total
# Incidents		5
# Injuries		0
# Deaths		0

Note: submit completed form by the FIRSTof EACH MONTH to Judy Smith, Recall Coordinator, at:

United States Consumer Product Safety Commission, Office of Compliance, 4330 EastWest Highway, Room 613, Bethesda, MD 20814 fax report to (301) 504-0359 or e-mail to jsmith@cpsc.gov. Address any guestions to Ms. Smith at (301) 504-7525

Monthly Progess Report for Corrective Action Plan & Incident Update Case #: RP030081

Compliance officer: Jack Kramer

Company Name: American Power Conversion **Reporting Dates, From:** 04/01/2003 **To:** 05/31/2003 Product: Uninterruptible Power Sup

1,036,472 Total # of Affected Products:

I) PRODUCTS CORRECTED/CAPTURED BY YOUR FIRM:

Location of Products	Total Products	Corrections This Period	Total Corrections	Percent Corrected
with Manufacturers	122,791		90,286	73.53%
with Distributors	30,365		30,365	100.00%
with Retailers	54,316		39,761	73.19%
with Consumers	829,000	53,493	197,214	23.79%
TOTAL:	1,036,472	53,493	357,626	34.50%

II) NOTIFICATION MEASURES:

(Using the categories listed below, record the number of notifications attempted by your firm during this reporting period and the total number of notifications to date.

III) CONSUMER AWARENESS:

(Using the categories listed below, record the way, by numerical quantity, consumers told you they learned of the corrective action, i.e. consumer received direct mail, read magazines, etc.)

Number for this Reporting Period	Total	Number for this Reporting Period	Total
Billing Insert	0	Billing Insert	0
Direct Mail Letter	232,912	Direct Mail Letter	0
Magazine	0	Magazine	0
Newspaper	0	Newspaper	0
Pediatrician Poster	0	Pediatrician Poster	0
Phone Call	0	Phone Call	0
Product Catalog	1,335,966	Product Catalog	0
Radio	0	Radio	0
Retail Store Poster	3,000	Retail Store Poster	0
Television	0	Television	0
Web Site	262,103	Web Site	0
Thrift Store	0	Thrift Store	0
Post Office	0	Post Office	0
Video News Release	0	Video News Release	0
Other/Unknown	1,722,677	Other/Unknown	55,172

IV) Call to 800 Number/Correspondence:

# For This Rep	Total	
800 Number	2,605	39,084
E-mail	350	3,375
Written Requests		20
Web Site Hits		0

V) Incident Update:

	# For This Reporting Period	Total
# Incidents # Injuri e s		<u>5</u> 0
# Deaths		<u> </u>

Note: submit completed form by the FIRSTof EACH MONTH to Judy Smith, Recall Coordinator, at:

United States Consumer Product Safety Commission,Office of Compliance,4330 EastWest Highway,Room 613,Bethesda, MD 20814 fax report to (301) 504-0359 or e-mail to jsmith@cpsc.gov. Address any questions to Ms. Smith at (301) 504-7525

Monthly Progress Report for Corrective Action Plan & Incident Update

CASE#	RP030081		Compliance Officer: Jack K	ramer
Company	Name: America	In Power Conversion	Product: Uninterruptible P	ower Supply
Reporting	Dates, From:	3/1/2003 To: 3/31/2	2003 Total of Affected Products:	1,036,472

I) PRODUCTS CORRECTED/CAPTURED BY YOUR FIRM:

Location of Products	Total Products	Corrections This Period	Total Corrections	Percent Corrected
With Manufacturer	122,791	9,572	90,286	74%
With Distributor*	30,365	0	30,365	100%
With Retailers**	54,316		39,761	73%
With Consumers	829,000	38,671	143,721	17%
TOTAL:	1,036,472	48,243	304,133	29%
	* Dief	ributor # as originally reported w	ras understated	

* Distributor # as originally reported was understated **Retail and Catalog Total -original Retail # was higher

II) NOTIFICATION MEASURES

III) CONSUMER AWARENESS

Number for This Rep	porting Period	Total	Number for This Reporting	Period	Total
Billing Insert	0	0	Billing Insert		
Direct Mail Letter	196,663	232,912	Direct Mail Letter		
Magazine	0	0	Magazine		
Newspaper	0	0	Newspaper		
Pediatician Poster	0	0	Pediatician Poster		
Phone Call	0	0	Phone Call		
Product Catalog	0	1,335,966	Product Catalog		**************************************
Radio	0	0	Radio		
Retail Store Poster	0	3000	Retail Store Poster	·	
Television	0	0	Television		
Web Site*	63,426	262,103	Web Site		
Post Office	0	0	Post Office		•
Thrift Store	0	0	Thrift Store		
Other Email	·	1,722,677	Other		
			Total	13,974	55,172

* Recall Page Hits

IV) Calls to 800 Number/Correspondence

# From Cu	Total	
800 Number	10,728	36,479
E-mail	750	3025
Written Requests	<10	<20

V) Incident Update:

	# For This Reporting Period	Total
# Incidents		14
# Injuries		0
# Deaths		0

;;() ;)







June 3, 2003

Jack T. Kramer Compliance Officer Recalls and Compliance United States Consumer Product Safety Commission 4330 East West Highway Room 613 Bethesda, Maryland 20814

Re: CPSC RP030081, American Power Conversion Corporation ("APC") UPS

Dear Mr. Kramer:

Please find accompanying this letter APC's Monthly Progress Report and Corrective Action Plan & Incident Update ('Update Report") for March 2003.

If you have any question of would like to discuss this Update Report in greater detail please do not hesitate to contact me directly at (401) 789-5735 x2255.

Peter Wexler Senior Counsel American Power Conversion Corporation

 American Power Conversion Corporation

 PO Box 278
 Call 401 789 5735

 132 Fairgrounds Road
 Fax 401 789 3710

 West Kingston, RI 02892
 Visit www.apcc.com

 APC is an equal opportunity employer which values workforce diversity.

 APCs quality system is ISO 9002 certified.

Monthly Progress Report for Corrective Action Plan & Incident Update

 CASE#
 RP030081
 Compliance Officer: Jack Kramer

 Company Name:
 <u>American Power Conversion</u>
 Product:
 Uninterruptible Power Supply

 Reporting Dates, From:
 <u>1/14/2003</u> To:
 <u>2/28/2003</u> Total of Affected Products:
 <u>1,036,472</u>

I) PRODUCTS CORRECTED/CAPTURED BY YOUR FIRM:

Location of Products	Total Products	Corrections This Period	Total Corrections	Percent Corrected
With Manufacturer	122,791	80,714	80,714	66%
With Distributor*	30,365	30,365	30,365	100%
With Retailers**	54,316	39,761	39761	73%
With Consumers	829,000	105,050	105,050	13%
TOTAL:	1,036,472	255,890	255,890	25%
	+ D:-+	بالمعاصم ويستعلل ومتأواتهم ومسافله ومعاديه	una una de vetete d	

* Distributor # as originally reported was understated **Retail and Catalog Total -original Retail # was higher

II) NOTIFICATION MEASURES

III) CONSUMER AWARENESS

Number for This Re	porting Period	Total	Number for This Reporting I	Period	Total
Billing Insert	0	0	Billing Insert		
Direct Mail Letter	36,249	36,249	Direct Mail Letter		
Magazine		0	 Magazine		
Newspaper	0		Newspaper		
Pediatician Poster	0	0	Pediatician Poster		
Phone Call		0	Phone Call		
Product Catalog	1,335,966	1,335,966	Product Catalog		
Radio	0	0	 Radio		
Retail Store Poster	3000	3000	Retail Store Poster		
Television	0	0	Television		
Web Site*	198,677	198,677	 Web Site		
Post Office	0	0	Post Office		
Thrift Store	0	0	 Thrift Store		
Other Email	1,722,677	1,722,677	Other –		
			Total	41,198	41,198
Post Office Thrift Store	0	0 0 1,722,677	Post Office Thrift Store Other	41,198	41,198

* Recall Page Hits

IV) Calls to 800 Number/Correspondence # From Customers This Reporting Period Total 800 Number 25,751 25,751 E-mail 2275 2275 Written Requests <10</td> <10</td> V) Incident Update: # For This Reporting Period Total

# Incidents	<u>کو</u>	0
# Injuries	0	0
# Deaths	<u> </u>	0





April 16, 2003

Jack T. Kramer Compliance Officer Recalls and Compliance United States Consumer Product Safety Commission 4330 East West Highway Room 613 Bethesda, Maryland 20814

Re: CPSC RP030081, American Power Conversion Corporation ("APC") UPS

Dear Mr. Kramer:

Please find accompanying this letter APC's Monthly Progress Report and Corrective Action Plan & Incident Update ('Update Report") for January and February 2003.

If you have any question of would like to discuss this Update Report in greater detail please do not hesizate to contact me directly at (401) 789-5735 x2255.

Very traily yours,

Peter Wexler Senior Counsel American Power Conversion Corporation

American Power Conversion Corporation

PO Box 278 Call 401 7 132 Fairgrounds Road Fax 401 78 West Kingston, RI 02892 Visit www

Call 401 789 5735 Fax 401 789 3710 Visit www.apcc.com

SENT VIA FEDEX

APC is an equal opportunity employer which values workforce diversity. APC's quality system is 1SO 9002 certified.

-01-789-5735,2255

CASE NUMBER: RP RP03 00 7

RECEIVED	BY:
DATE:	12/20/02
PRIORITY	: X

~>

DIVISION OF CORRECTIVE ACTIONS SECTION 15(b) REPORT WORKSHEET

FIRM: American Power

PHONE: 401-789-5735, 2255 FAX: 401-788-2766

ADDRESS:

CONTACT: Peter Wexler

TITLE:

ADDRESS [IF DIFFERENT FROM ABOVE] :

PHONE:

FAX:

PRODUCT:

NEISS CODE:

BRAND NAME/MODEL NO: BK 500 BK 350

UPC:

RETAIL PRICE: 79-112

CERTIFICATION/STANDARDS INFORMATION:

DEFECT/PROBLEM: Unit my short

HOW AND WHEN DISCOVERED:

HAZARD: fire

INJURIES: Done

DISCUSSION: [Include any information has at this point regarding extent of problem, testing information, firm's explanation]

FOR OFFICIAL USE ONLY

Page 2	
ADDITIONAL PRODUCT INFORMATION:	Imil
TOTAL NUMBER INVOLVED:	10000
WITH MFR:	\$ 5
WITH DISTRIBUTORS:	C
WITH RETAILERS:	
WITH CONSUMERS:	
DISTRIBUTION: <u>X</u> NATIONAL	REGIONAL
PRODUCTION/IMPORTATION DATES:	
DISTRIBUTION DATES:	

CORRECTIVE ACTION PLANNED OR UNDERWAY: [INCLUDE DATES]

INFORMATION RE ANY OTHER FIRMS INVOLVED: [E.G., IMPORTER, DISTRIBUTOR, RETAILERS, COMPONENT PART SUPPLIER]

.

FOR OFFICIAL USE ONLY



U.S. CONSUMER PRODUCT SAFETY COMMISSION

WASHINGTON, D.C. 20207

FEB - 6 2003

OFFICE OF COMPLIANCE Recalls and Compliance Division Email: jkramer@cpsc.gov

Jack Kramer Compliance Officer Tel:301-504-7604 Fax: 301-504-0359

Firm has not requested

Certified Mail/Facsimile 401.789.3710

Peter Wexler Senior Attorney American Power Conversion Corp. 132 Fairgrounds Road W. Kingston, RI 02892

Re:

CPSC RP030081 American Power Conversion Corporation Uninterruptible Power Supplies Back-UPS[®] CS 350 and Back-UPS[®] CS 500

Dear Mr. Wexler:

Thank you for your report of January 3, 2003 under section 15(b) of the Consumer Product Safety Act, 15 U.S.C. § 2064(b), and for promptly initiating a corrective action plan to address the reported problem. In your report you indicated that the power supply device of certain American Power Conversion Corporation (APCC) back-up power supplies can fail, resulting in the exterior of the case melting, which can pose a potential fire hazard.

The staff of the Office of Compliance of the U.S. Consumer Product Safety Commission reviewed the actions proposed by APCC concerning the back-up power supplies. Acting under delegation from the Commission, the staff has accepted the plan as adequate. The recall plan accepted by the staff includes the following actions:

- 1. Issue with CPSC a joint press release
- 2. Establish a toll-free number for consumers seeking information on the recall
- 3. Post notice of the recall on APCC's web page
- 4. Provide point of purchase posters to retailers that sold the recalled production attached

CPSC Hotline: 1-800-638-CPSC(2772) ★ CPSC's Web Site: http://www.cpsc.gov Fast Track Recall Program is a 1998 Innovations in American Government Award Winner Page 2 RP030081

- 5. Notify by mail consumers known to APCC, as purchasing the recalled products
- 6. Provide consumers with recalled products a redesigned product
- 7. Incorporate redesign in future production products

Please continue the corrective actions implemented and initiate any others contained in the plan accepted by the staff. The Office of Compliance will be monitoring the firm's corrective action plan. Please submit **monthly** progress reports of the recall, using the enclosed form, to U.S. Consumer Product Safety Commission, Office of Compliance, Judy Smith, 4330 East West Highway, Room 613, Bethesda, MD 20814-4408 by the first of each month or fax to (301) 504-0359. If you have any questions, please contact Judy Smith on (301) 504-7525. Please reference the CPSC file number in your response.

When your firm determines the corrective action plan has been implemented to the best of its ability and as many products as possible have been removed from the marketplace, it may submit a final progress report, referencing the file number, and request that the file be closed. At that time the staff will review the plan's progress and decide whether the file should be closed. The Office of Compliance will evaluate the effectiveness of the plan. The staff could seek broader corrective action if the corrective action plan does not prove effective. When the staff . closes its file on a recall, we ask that the firm continue its corrective action program until as many products as possible have been removed from the marketplace. Please continue to maintain your toll-free recall number as a means for consumers to reach you about your recall. Should the firm decide to change or discontinue its toll-free recall number, you must notify the Division of Recalls and Compliance and provide a new recall contact number for the firm. If the firm wishes to change the terms of the recall you must also discuss any proposal with us before it makes any change. This information will be maintained by CPSC and provided to consumers and others seeking information on your recall.

If the firm receives or learns of any information concerning other incidents or injuries, or information affecting the scope, prevalence or seriousness of the reported problem, it must report that information to this Office immediately. Additionally, if the firm receives information that might indicate that its corrective actions are not satisfactory in eliminating the problem or that the effectiveness of the corrective action program is less than has been anticipated, it must report that information to the Division of Recalls and Compliance immediately.

Section 6(b)(1) requires the Commission to give notice thirty days in advance of the intended disclosure of information that identifies the manufacturer or private labeler of a product. The staff is enclosing a summary of the corrective action plan. The Commission publishes a list of product recalls and other corrective actions initiated by firms in an Annual Report to Congress. This information is also occasionally used in lists for specific product categories. This letter gives the firm its opportunity under section 6(b)(1) of the Consumer Product Safety Act (CPSA), 15 U.S.C. § 2055(b)(1), and 16 C.F.R. Part 1101, to comment on the accuracy of the information.

Page 3 RP030081

The staff has made every effort to assure that the enclosed information is accurate. If, however, the firm believes that the information is not accurate, please send comments to me. The firm's comments must be received within twenty-three calendar days of your receipt of this certified letter if they are to be considered. Please include with any comments specific information to support any claim that the information is not accurate. If the Commission decides to disclose the information, unchanged, over any accuracy objections, it will give the firm ten (10) working days notice, as required by section 6(b)(2) of the CPSA, 15 U.S.C. § 2055(b)(2).

Thank you for your continued cooperation in this matter. If you have any questions, please contact me at 301-504-7604.

Sincerely,

ran

Jack Kramer Compliance Officer Recalls and Compliance Division

Enclosures:

Corrective Action Summary Progress Report Form Recall Checklist

cc:

Judith Hayes, CRC Judy Smith, CRC

Page 4 RP030081

Voluntary Corrective Action Plans Under Section 15 of the Consumer Product Safety Act and Section 15 of the Federal Hazardous Substances Act

The following is a list of voluntary corrective action plans recently accepted by the Commission (or the staff acting under authority delegated by the Commission). A firm's taking corrective action does not constitute admission by the firm that a substantial product hazard exists.

Space does not permit the staff to give a complete list of the specific model numbers of the products involved in each of these corrective actions. Consumers who believe that they have a product affected by one of these actions should follow the instructions given in this list or contact either the manufacturer or the Commission to determine if their product is one of those affected.

Voluntary Corrective Action Plans Under Section 15 of the Consumer Product Safety Act and Section 15 of the Federal Hazardous Substances Act

DATE	FIRM AND PRODUCT	ALLEGED HAZARD	REMEDY
00/00	American Power Conversion	Fire hazard, internal failure can	Replace recalled product with a
	W. Kingston, RI 02892	cause the unit to overheat and melt the exterior case, possible for ignition of nearby	redesigned unit
	Uninteruptable Power Supply, Back-UPS CS 500 and Back-UPS CS 350	combustibles	

Monthly Progress Report for Corrective Action Plan & Incident Update

CASE #: <u>RP030081</u> Company Name: <u>American Power Conversion</u> Reporting Dates, From: _____To: _____ Compliance Officer: <u>Jack Kramer</u>

Product: <u>Uninterruptible Power Supply (UPC)</u> Total# of Affected Products:

I) PRODUCTS CORRECTED/CAPTURED BY YOUR FIRM:

Location of Products	Total Products	Corrections This Period	Total Corrections	Percent Corrected
With Manufacturer				
With Distributor With Retailers				
With Consumers				
TOTAL:				

II) NOTIFICATION MEASURES:

(Using the categories listed below, records the numbers of notifications attempted by your firm during this reporting period, and records the total number of notifications to date.) III) CONSUMER AWARENESS: (Using the

categories below, record the way, by numerical quantity, Consumers told you they learned of the corrective action, i.e. consumer received direct mail, read magazine, etc.)

Number for This Reporting Period Billing Insert	Total	Number for This Reporting Period Billing Insert	Total
Direct Mail Letter		Direct Mail Letter	
Magazine		Magazine	
Newspaper		Newspaper	
Pediatrician Poster		Pediatrician Poster	
Phone Call		Phone Call	
Product Catalog		Product Catalog	
Radio		Radio	
Retail Store Poster		Retail Store Poster	
Television		Television	
Web Site		Web Site	· · · · · · · · · · · · · · · · · · ·
Post Office		Post Office	
Thrift Store		Thrift Store	
Other		Other	

	Number/Corre rom Customers T	his Reporting Period	Total	
0 Number				
mail				
ritten Requests				
V) Iı	icident Update			
•) •	of a change of a c		porting Period	Total
# Inc	idents		r 8	
# Inju				
# Dea	the			

NOTE: Submit completed form by the FIRST of EACH MONTH to Judy Smith, Recall Coordinator, at: United States Consumer Product Safety Commission, Office of Compliance 4330 East West Highway, Room 613 Bethesda, MD 20814

OR, fax report to (301) 504-0359 or e-mail to jsmith@cpsc.gov. Address any questions to Ms. Smith at 301- 504-7525

U.S. CONSUMER PRODUCT SAFETY COMMISSION Office of Compliance

Firm Name: American Power ConversionFile Number: RP030081Product: Uninterruptible Power Supply (UPC)Priority: x

CORRECTIVE ACTION PLAN:

A. Notice:

Event:

Date:

X press release

1/14/03

X direct mail

X point of purchase signs

X other (web posting)

B. Repair, replacement, refund:

repair approved by technical support

X replacement with product approved by technical support

refund

C. Procedures:

X Distribution chain recall _x_mfr/importer level _x_wholesaler/distributor level _x_retailer level _x_consumer level

X Mail in to firm

Return to retailer

X replace

Home visit At dealer At Retailer

X Home consumer is to send back recalled unit _X_ Toll-free line

Firm Name: American Power Conversion



File Number:RP030081

___Other (describe):

D. Effectiveness:

- Total Products Involved: 1,039,995 Corrected: 0
 - At Manufacturer: 122,791 Corrected: 0
 - At Distributors: 2,355 Corrected: 0
 - At Retailers: 59,697 Corrected: 0
 - With Consumers: 855,152 Corrected: 0
 - E. Decision on corrective action:
 - _x_ Accept CAP and Monitor x_ Fast Track Product Recall Case
 - Accept CAP and Close File (provide rationale)
 - Pursue further remedial action (provide rationale)
 - Refer to CAL
 - ____Refer to Commission with recommendation to accept CAP [Class A case]

CAP APPROVALS:	
Compliance Officer //15/03 Ris	1/15/13
Attorney	
Associate Director, CRC PhD 2/5/3	
Director, CRC (Only if CAP or CAP & Close approval)	

NEWS from CPSC

U.S. Consumer Product Safety Commission

Office of Information and Public Affairs

Washington, DC 20207

FOR IMMEDIATE RELEASE January 14, 2003 Release # 03-068 APC Recall Hotline: (866) 272-7359 CPSC Consumer Hotline: (800) 638-2772 CPSC Media Contact: Scott Wolfson, (301) 504-7051

CPSC, American Power Conversion Corp. Announce Recall of Back-Up Power Supply Systems

WASHINGTON, D.C. - In cooperation with the U.S. Consumer Product Safety Commission (CPSC), American Power Conversion Corporation (APC), of West Kingston, R.I., is voluntarily recalling about 900,000 back-up power supply devices. These devices are primarily used to protect computers in case of a power failure. The power supply device can fail, causing the unit to overheat, which may pose a fire hazard to consumers.

APC has received six reports of units overheating resulting in the melting of the unit's outer casing and three reports of minor property damage. No injuries have been reported.

The recalled Back-UPS® CS Uninterruptible Power Supply devices include the Back-UPS CS350 and the Back-UPS CS 500 models. The model number can be found on the front of the unit, along with the words, "Back-UPS CS" and "APC." In addition, one of the following numbers shows up on the bar code label located on the bottom of the unit: BK350, BK500, BK500BLK. The recalled power supply devices also have one of the following serial numbers - AB0048 through AB0251, BB0104 through BB0251, and JB0125 through JB0251 - which can be found on the bottom of the unit. Units with an "R" at the end of the serial number within the above ranges are not part of this recall.

Retailers, computer and electrical distributors, and catalogs nationwide sold the power supply devices from November 2000 through December 2002 for between \$70 and \$130.


Consumers should immediately stop using the power supply devices by turning off the power to all connected equipment, turning the Back- UPS CS off, and then unplugging it from the electrical outlet. To obtain a free replacement unit, consumers should contact the company at (866) APC-RELY (272-7359) between 9 a.m. and 5 p.m. ET Monday through Friday or log on to the company's website at <u>www.apc.com/rely</u>

American Power Conversion Corp. Recalls Back-Up Power Supply Systems



Send the link for this page to a friend! The U.S. Consumer Product Safety Commission protects the public from unreasonable risks of injury or death from 15,000 types of consumer products under the agency's jurisdiction. To report a dangerous product or a product-related injury, call CPSC's hotline at (800) 638-2772 or CPSC's teletypewriter at (800) 638-8270, or visit CPSC's web site at www.cpsc.gov/talk.html. Consumers can obtain this release and recall information at CPSC's web site at www.cpsc.gov/talk.html. Consumers can obtain this release and recall information at CPSC's web site at www.cpsc.gov/talk.html.

Safety Recall Notice APC Uninterruptible Power Supplies Back-UPS® CS 350 and CS 500





LABEL LOCATED AT THE BOTTOM OF THE UNIT

Affected Model#: BK 350, BK 500, BK 500BLK Only units where the <u>first six characters</u> of the serial number fall within the following ranges are affected

AB0048 through AB0251 BB0104 through BB0251 JB0125 through JB0251

Any units with an "R" at the end of the serial number are not part of the recall.

Potential Overheating and Fire Hazard Stop using immediately.

For a free replacement product call APC at:

866-272-7359

(Between 9 a.m. and 5 p.m. EST Monday through Friday)

or visit APC's Web site at www.apc.com

post until _____, 2003

In cooperation with the U.S. Consumer Product Safety Commission



Safety Recall Notice

APC Uninterruptible Power Supplies Back-UPS[®] CS 350 & CS 500

For a free replacement product call APC at:

866-272-7359

(Between 9 a.m. and 5 p.m. EST Monday through Friday) or visit APC's web-site at www.apc.com



Dear Partner:


APC has, in voluntary cooperation with the Consumer Products Safety Commission, initiated a recall on the Back-UPS CS 350 and Back-UPS CS 500 models only. Units affected were manufactured between November 20, 2000 and December 20, 2002 and are being recalled because the power supply device can fail, posing a risk of overheating and a potential fire hazard.

<u>APC has received has received six reports of the units overheating in Out of approximately 900,000 units shipped in</u> the United States, APC has received six reports of units overheating, including one report of melting through the <u>unit's outer casing</u>-resulting in a breach of the unit's outer casing. Three of the reported incidents resulted in minor property damage. No injuries have been reported.

The date code can be found in the serial number located on the label on the top of the display box or on the side of the master carton or on the bottom of the unit as shown below. Only units with serial numbers having the first six characters are affected:

AB0048 through AB0251 BB0104 through BB0251 JB0125 through JB0251

Any units with an "R" at the end of the serial number are not part of the recall.



LABEL LOCATED AT THE BOTTOM OF THE UNIT Affected SKU#: BK350, BK500, BK500BLK
Serial Number : Only units with serial numbers having the first six
characters are affected:
AB0048 through AB0251
BB0104 through BB0251
JB0125 through JB0251.
Any units with an "R" at the end of the serial number
are not part of the recall.

APC recommends that the user immediately remove the UPS unit from service by turning off all connected equipment, turning the UPS unit off, and then unplugging the unit from the electrical outlet.

To arrange a replacement, logon to your APC Reseller Personal Page. If you do not yet have a Personal Page, log onto the APC main page (at www.apc.com) and click on the reseller section to establish one, then follow the procedures outlined under "Back-UPS CS Transition."

Thank you for your understanding and cooperation.

Aaron Davis

January 22, 2003


Dear XXX Address

Safety Recall Notice

In cooperation with the U.S. Consumer Product Safety Commission (CPSC) APC, is voluntarily recalling certain uninterruptible power supplies (UPS), manufactured between November 2000 and December 2002. Our records show you purchased one or more of these units

PROBLEM: A possibility exists for overheating and fire, due to an internal component failure.

PRODUCT: Included are models BK350, BK500 and BK500BLK with the <u>first six</u> <u>characters</u> of the serial number in the ranges shown below. Model markings are located on the front of the unit and the serial numbers are located on the bottom of the unit. If an "R" follows your serial number then it is not part of the recall.



WHAT TO DO: Stop using immediately and remove the UPS unit from service by turning off all connected equipment, turning the UPS unit off, and then unplugging the unit from the electrical outlet. To obtain a free replacement consumers can visit APC on the web at www.apc.com/rely or call 800 APC-RELY (800 272-7359).

APC would like to apologize for any inconvenience that this may cause.

Thank you for your support.

Aaron Davis

Vice President Sales and Marketing

2

Kramer, Jack T.

From: Sent: To: Subject: Kramer, Jack T. Friday, January 10, 2003 7:45 AM 'Peter.Wexler@apcc.com' RE: FW: APC

Peter,

Prior to the 9:00 a.m. call please send me what APC considers its final versions of:

The CPSC press release

The APC press release

Letter going to consumers


Letter going to retailers

Two tier letter

In store poster

Information which will appear on APC's web page

Phone script used for the 800 number



Also, we need to work out a way to notify the 7 major retailers as soon as possible after the press release goes. Do you have e-mail addresses or fax numbers for them?

Yesterday the question was raised as to how many calls you might initially expect to receive. The answer is we can not answer, it depends on many factors including the amount of press coverage the recall gets. Typically in first couple of days you will be inundated with calls and will receive calls from people who don't own the product, repeat calls from the same consumers and media inquiries.

Best

Jack

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 5:25 PM To: JKramer@cpsc.gov Cc: Debbie.Grey@apcc.com; Joe.Loberti@apcc.com Subject: RE: FW: APC

Jack:

We can put melting in the press releases instead of breaching, but will have to work on the wording regarding how it 'melts through". Also, we took out the circuit board fails as that is not correct. Saying the unit fails is more accurate. Perhaps we could speak tomorrow at 9am and put these into final form. I will redraft and send them to you.

Peter,

"Kramer, Jack T." To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc: .gov> Subject: RE: FW: APC 01/09/2003 02:48 PM

Peter,

Public Affairs made some changes to the press release mainly they prefer not to use the term breach the case instead they prefer melted. Please make the same changes on APC's press release. Regarding APC's release the way I read it there were eight cases of the case melting. I don't think that is what you meant. Some questions, the model number are CS 500 and CS 350 however, the label shows BK 500? Attached are the revised CPSC press release and the revised two tier letter. Please give me a call so we can discuss.

Jack

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:43 PM To: JKramer@cpsc.gov Subject: RE: FW: APC

That is our plan

"Kramer, Jack

"'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com>



<JKramer@cpsc cc: .gov> Subject: RE: FW: APC 01/09/2003 01:39 PM

One more timing issue, when our press release goes the APC web-page needs to be up and running.

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:20 PM To: JKramer@cpsc.gov Subject: RE: FW: APC

Jack:

Here are the modified press releases for you review and sign off as well as the revised retail letter and store poster. For each we have used your comments and made some minor changes to ensure that they are factually correct. Please let us know if you have any comments or questions. The web site will be up and we will have picture to you by tomorrow. (See attached file: CPSC Press Release v11.doc)(See attached file: Retail

Letter v11.doc)(See attached file: APC Press Release v11.doc)(See attached file: store poster v11.doc)(See attached file: two tier reseller mailing v11.doc)

Regarding UL approval, they were notified of the change and a request was made to update our construction files on 12/27/02 by our regulatory engineers.

Peter

http://www.apc.com

(See attached file: Press Release.doc)(See attached file: two tier reseller mailing v11.doc)

						<u> </u>	
	EXCE NEWS	RELE/	ASE REV	IEW/CLI	EARANCE		
Date: January 10, 2003		Case/Re	Case/Recall#: RP030081 Type		e: Sect15 Recall		
Proposed Rele	ase Date: 1/15/03		Product	Uninterrupti	ble Power Supply	2 (UPQ) ر	
For Additional Information Contact:		Jack Kra	Jack Kramer (301)504-7604				
BACKGROUN	D/SUMMARY: Unit ca	n overheat	due to power	supply failure	potential for fire	x	
7	ext of the proposed release h				•		
	ons with this firm.	⊠Yes	No				
Photos availabl	e?	⊠Yes	No				
Clearance Office	Signatur	e	Approve	Disapprove	Date	6(b)	
Comp. Officer/Atty	ghan	e7 (S	~		1/10/03		
CE Assoc. Director	Ew Com-		~		1/10/3		
EXCE	Man Udr				1/10/03	nz	
EXPA				 			
OGC						_	
Chairman	<u> </u>		<u> </u>				
he 6(b)6 column ind Hazard (Hazard (Hadard (Hazard (Hazard (Hazard (Hazard (Hazard (H	is form and the attached relea icates clearance is in accorda Secon Id NRF Notification - o Sold in Canada If che Number called - corr otline Staff Briefed - o	nce with CPSC D ry: 104 Fire ndary: comments: n/ cwill be noti n/a cked, Health aments: work	irective 1450.2 cond Hazards/Elect /a fied by firm u Canada Conta king	erning whether the i rical pon release o	information is accurate ar	nd not mislead	

News from CPSC

U.S. Consumer Product Safety Commission

Office of Information and Public Affairs

For Immediate Release January 14, 2002 Release # 03-068 APC Recall Hotline: (800) 272-7359 CPSC Recall Hotline: (800) 638-2772 CPSC Media Contact: Scott Wolfson (301) 504-0580 Ext. 1189

Washington, D.C. 20207

CPSC, American Power Conversion Corp. Announce Recall of Back-Up Power Supply Systems


WASHINGTON, D.C. – In cooperation with the U.S. Consumer Product Safety Commission (CPSC), American Power Conversion Corporation. (APC), of West Kingston, R.I., is voluntarily recalling about 900,000 back-up power supply devices. These devices are primarily used to protect computers in case of a power failure. The power supply device can fail, causing the unit to overheat, which may pose a fire hazard to consumers.

APC has received six reports of units overheating resulting in the melting of the unit's outer casing and three reports of minor property damage. No injuries have been reported.

The recalled Back-UPS[®] CS Uninterruptible Power Supply devices include the Back-UPS CS350 and the Back-UPS CS 500 models in both 120-volt and 230-volt units. The model number can be found on the front of the unit, along with the words, "Back-UPS CS" and "APC." The recalled power supply devices also have one of the following serial numbers – AB0048 $\tau^{t_{APGG}}$ have a supply devices also have one of the following serial numbers – AB0048 through AB0251, BB0104 through BB0251, and JB0125 through JB0251 – which can be found on the bottom of the unit. These power supply devices were made in India. Units with an "R" at the end of the serial number within the above ranges are not part of this recall.

Retailers, computer and electrical distributors, and catalogs nationwide sold the power supply devices from November 2000 through December 2002 for between \$70 and \$130.

Consumers should immediately stop using the power supply devices by turning off the power to all connected equipment, turning the Back-UPS CS off, and then unplugging it from the electrical outlet. To obtain a free replacement unit, consumers should contact the company at (800) APC-RELY (272-7359) between 9 a.m. and 5 p.m. ET Monday through Friday or log on to the company's website at www.apc.com/rely.



To see a picture of the recalled product(s) and/or to establish a link from your web site to this press release on CPSC's web site, link to the following address: http://www.cpsc.gov/cpscpub/prerel/prhtml03/03XXX.html. The U.S. Consumer Product Safety Commission protects the public from unreasonable risks of injury or death from 15,000 types of consumer products under the agency's jurisdiction. To report a dangerous product or a product-related injury, call CPSC's hotline at (800) 638-2772 or CPSC's teletypewriter at (800) 638-8270, or visit CPSC's web site at http://www.cpsc.gov/talk.html. Consumers can obtain this release and recall information at CPSC's web site at http://www.cpsc.gov.

####

Receive Press Releases by Email: To subscribe to this convenient service, send an email containing your full name, position, organization, mailing address, email address, phone number and fax number to: kdulic@cpsc.gov.



Quick Report	Number: QR03-73				
Technical Analysis	Sample:				
DRAFT FOR OFFICIAL USE ONLY - DRAFT	Firm: American Power Conversion Corp. (APC)				
	Product: Uninterruptible Power Supply				
	CO: Jack Kramer				
General : According to the full report submitted by APC under the provisions of the CPSC's Fast Track recall program, the failure of a voltage regulator or a clamp circuit's field-effect transistor (FET) could result in overheating and burning of the unit's cover. Nine reports have been received of overheating extending beyond the interior of the device. The models affected are the BK350, BK500, BK500BLK, BK350EI and BK500EI.					
APC's proposed correction is to replace the voltage regulator with a "field-proven" component. For the potential clamp circuit failure, in-line fuses will be added to limit the amount of current that can be drawn into the output voltage transformer.					
Product Description : This product is an uninterruptible power supply. The device consists of input voltage surge protection circuitry, a battery with charging circuits, and an inverter to convert the DC battery output into AC power for electrical equipment. A control circuit monitors the input power and automatically switches to battery-generated output power in the event of input power loss. The product is UL-listed, the applicable voluntary standard being UL 1778, Uninterruptible Power Supply Equipment.					
Assessment/Conclusion : APC's report showed pictures of several of the failed units. Severe overheating can be seen in the area of the voltage regulator or the clamp circuit FETs. Failures of this sort discharge the battery through the printed circuit board (PCB) in this area. With the board is positioned very near the case, heat generated at the PCB is conducted to an exterior surface. The plastic case is rated V-0 (per UL 94). However, APC showed that the failures led to burning and melting of the case, exposing the hot PCB. One consumer reported that the failure started a fire in his home.					
For the voltage regulator problem, APC states that the voltage regulator component contains a latent defect. APC proposes to rework the PCB by removing the voltage regulator and installing a daughterboard PCB containing a field-proven regulator.					
APC's investigation of the failed clamp circuit FET determined that the layout of the PCB was a factor. A voltage regulator or clamp circuit failure would precipitate a failure in the FET that would, in turn, lead to a short-circuit in the UPS' inverter transformer. Excessive current in the windings would lead to overheating. APC proposes to add in-line fuses to disconnect electric power from the transformer in the event of a failed FET.					
Based on information supplied by APC both the voltage regulator change and the addition of in-line fuses appear to properly address the overheating problems experienced by their products.					
Performed by: Randy Butturini, Dat Electrical Engineer	e: 9 January, 2003				

50

Kramer, Jack T.

From:	Kramer, Jack T.
Sent:	Thursday, January 09, 2003 8:50 PM
То:	'Peter.Wexler@apcc.com '
Subject:	RE: FW: APC

sounds good I think we can work it out talk to you at 9

-----Original Message-----From: Peter.Wexler@apcc.com To: JKramer@cpsc.gov Cc: Debbie.Grey@apcc.com; Joe.Loberti@apcc.com Sent: 1/9/03 5:25 PM Subject: RE: FW: APC

Jack:

We can put melting in the press releases instead of breaching, but will have to work on the wording regarding how it 'melts through". Also, we took out the circuit board fails as that is not correct. Saying the unit fails is more accurate. Perhaps we could speak tomorrow at 9am and put these into final form. I will redraft and send them to you.

Peter,

"Kramer, Jack T." To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc: .gov> Subject: RE: FW: APC

> 01/09/2003 02:48 PM

Peter,

Public Affairs made some changes to the press release mainly they prefer not to use the term breach the case instead they prefer melted. Please make the same changes on APC's press release. Regarding APC's release the way I read it there were eight cases of the case melting. I don't

i

think that is what you meant. Some questions, the model number are CS 500 and CS 350 however, the label shows BK 500? Attached are the revised CPSC press release and the revised two tier letter. Please give me a call so we can discuss. Jack ----Original Message-----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:43 PM To: JKramer@cpsc.gov Subject: RE: FW: APC That is our plan "Kramer, Jack т." To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc: Subject: RE: FW: APC .gov> 01/09/2003 01:39 PM One more timing issue, when our press release goes the APC web-page needs to be up and running. ----Original Message-----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:20 PM To: JKramer@cpsc.gov Subject: RE: FW: APC

Jack:

Here are the modified press releases for you review and sign off as well

5 7

the revised retail letter and store poster. For each we have used your comments and made some minor changes to ensure that they are factually correct. Please let us know if you have any comments or questions. The web site will be up and we will have picture to you by tomorrow. (See attached file: CPSC Press Release v11.doc)(See attached file: Retail

Letter v11.doc)(See attached file: APC Press Release v11.doc)(See attached file: store poster v11.doc)(See attached file: two tier reseller mailing v11.doc)

Regarding UL approval, they were notified of the change and a request was made to update our construction files on 12/27/02 by our regulatory engineers.

Peter

as

http://www.apc.com

(See attached file: Press Release.doc)(See attached file: two tier reseller mailing v11.doc)

<<Press Release.doc>> <<two tier reseller mailing v11.doc>>

Kramer, Jack T.

From: Sent: To: Cc: Subject: Peter.Wexler@apcc.com Thursday, January 09, 2003 5:25 PM JKramer@cpsc.gov Debbie.Grey@apcc.com; Joe.Loberti@apcc.com RE: FW: APC



vl1....

Jack:

We can put melting in the press releases instead of breaching, but will have to work on the wording regarding how it 'melts through". Also, we took out the circuit board fails as that is not correct. Saying the unit fails is more accurate. Perhaps we could speak tomorrow at 9am and put

these into final form. I will redraft and send them to you.

Peter.,

"Kramer, Jack
"." To:
"'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com>
<JKramer@cpsc cc:
.gov> Subject: RE: FW: APC
01/09/2003
02:48 PM

Peter,

Public Affairs made some changes to the press release mainly they prefer not to use the term breach the case instead they prefer melted. Please make the same changes on APC's press release. Regarding APC's release the way I read it there were eight cases of the case melting. I don't think that is what you meant. Some questions, the model number are CS 500 and CS 350 however, the label shows BK 500? Attached are the revised CPSC press release and the revised two tier letter. Please give me a call so we can discuss.

Jack

-----Original Message-----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:43 PM To: JKramer@cpsc.gov Subject: RE: FW: APC

That is our plan

"Kramer, Jack T." To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc: .gov> Subject: RE: FW: APC

> 01/09/2003 01:39 PM

One more timing issue, when our press release goes the APC web-page needs to be up and running.

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:20 PM To: JKramer@cpsc.gov Subject: RE: FW: APC

Jack:

Here are the modified press releases for you review and sign off as well as the revised retail letter and store poster. For each we have used your comments and made some minor changes to ensure that they are factually correct. Please let us know if you have any comments or questions. The

 $\sim i$

web site will be up and we will have picture to you by tomorrow.

(See attached file: CPSC Press Release v11.doc)(See attached file: Retail Letter v11.doc)(See attached file: APC Press Release v11.doc)(See attached file: store poster v11.doc)(See attached file: two tier reseller mailing v11.doc)

Regarding UL approval, they were notified of the change and a request was made to update our construction files on 12/27/02 by our regulatory engineers.

Peter

http://www.apc.com

(See attached file: Press Release.doc)(See attached file: two tier reseller mailing v11.doc)

n .

Kramer, Jack T.

From: Sent: To: Subject: Kramer, Jack T. Thursday, January 09, 2003 3:30 PM 'Peter.Wexler@apcc.com' Phone Number

Peter

Starting Monday January 13, 2003 CPSC will be getting a new phone system with new phone numbers. You can reach me direct next week at 301.504.7604.

.

Jack

Kramer, Jack T.

From: Sent: To: Subject: Peter.Wexler@apcc.com Thursday, January 09, 2003 2:56 PM JKramer@cpsc.gov RE: FW: APC



v11.doc

Here is the customer letter as you had changed it with a rew minor edits (See attached file: Customer Letter v11.doc)

"Kramer, Jack

T." To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc:

.gov> Subject: RE: FW: APC

01/09/2003

01:49 PM

Is the letter to consumers still coming?

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:43 PM To: JKramer@cpsc.gov Subject: RE: FW: APC

That is our plan

"Kramer, Jack

1

n

To:

One more timing issue, when our press release goes the APC web-page needs to be up and running.

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:20 PM To: JKramer@cpsc.gov Subject: RE: FW: APC

Jack:

Here are the modified press releases for you review and sign off as well as the revised retail letter and store poster. For each we have used your comments and made some minor changes to ensure that they are factually correct. Please let us know if you have any comments or questions. The web site will be up and we will have picture to you by tomorrow.

(See attached file: CPSC Press Release v11.doc)(See attached file: Retail Letter v11.doc)(See attached file: APC Press Release v11.doc)(See attached file: store poster v11.doc)(See attached file: two tier reseller mailing v11.doc)

Regarding UL approval, they were notified of the change and a request was made to update our construction files on 12/27/02 by our regulatory engineers.

Peter

From: Sent: To: Subject: Kramer, Jack T. Thursday, January 09, 2003 2:54 PM 'Peter.Wexler@apcc.com' Technical Evaluation

Peter

Engineering Sciences reviewed your proposed product changes, which appear to be adequate.

Jack

From: Sent: To: Subject: Kramer, Jack T. Thursday, January 09, 2003 2:49 PM 'Peter.Wexler@apcc.com' RE: FW: APC





.doc vo tier reseller mailin; vll.... Peter,

Public Affairs made some changes to the press release mainly they prefer not to use the term breach the case instead they prefer melted. Please make the same changes on APC's press release. Regarding APC's release the way I read it there were eight cases of the case melting. I don't think that is what you meant. Some questions, the model number are CS 500 and CS 350 however, the label shows BK 500? Attached are the revised CPSC press release and the revised two tier letter. Please give me a call so we can discuss.

Jack

-----Original Message-----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:43 PM To: JKramer@cpsc.gov Subject: RE: FW: APC

That is our plan

"Kramer, Jack

T." To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc:

.gov> Subject: RE: FW: APC

01/09/2003

01:39 PM

From: Sent: To: Subject: Peter.Wexler@apcc.com Thursday, January 09, 2003 1:43 PM JKramer@cpsc.gov RE: FW: APC

That is our plan

"Kramer, Jack T." To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc: .gov> Subject: RE: FW: APC 01/09/2003 01:39 PM

One more timing issue, when our press release goes the APC web-page needs to be up and running. ----Original Message-----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:20 PM To: JKramer@cpsc.gov Subject: RE: FW: APC Jack: Here are the modified press releases for you review and sign off as well as the revised retail letter and store poster. For each we have used your comments and made some minor changes to ensure that they are factually correct. Please let us know if you have any comments or questions. The web site will be up and we will have picture to you by tomorrow.

(See attached file: CPSC Press Release v11.doc)(See attached file: Retail Letter v11.doc)(See attached file: APC Press Release v11.doc)(See attached file: store poster v11.doc)(See attached file: two tier reseller mailing

から

1

v11.doc)

Regarding UL approval, they were notified of the change and a request was made to update our construction files on 12/27/02 by our regulatory engineers.

Peter

From: Sent: To: Subject: Peter.Wexler@apcc.com Thursday, January 09, 2003 1:20 PM JKramer@cpsc.gov RE: FW: APC



Jack:

Here are the modified press releases for you review and sign off as well as

the revised retail letter and store poster. For each we have used your comments and made some minor changes to ensure that they are factually correct. Please let us know if you have any comments or questions. The web site will be up and we will have picture to you by tomorrow.

(See attached file: CPSC Press Release v11.doc)(See attached file: Retail Letter v11.doc)(See attached file: APC Press Release v11.doc)(See attached file: store poster v11.doc)(See attached file: two tier reseller mailing v11.doc)

Regarding UL approval, they were notified of the change and a request was made to update our construction files on 12/27/02 by our regulatory engineers.

Peter

One more timing issue, when our press release goes the APC web-page needs to be up and running.

-----Original Message-----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:20 PM To: JKramer@cpsc.gov Subject: RE: FW: APC

Jack:

Here are the modified press releases for you review and sign off as well as the revised retail letter and store poster. For each we have used your comments and made some minor changes to ensure that they are factually correct. Please let us know if you have any comments or questions. The web site will be up and we will have picture to you by tomorrow.

(See attached file: CPSC Press Release v11.doc)(See attached file: Retail Letter v11.doc)(See attached file: APC Press Release v11.doc)(See attached file: store poster v11.doc)(See attached file: two tier reseller mailing v11.doc)

Regarding UL approval, they were notified of the change and a request was made to update our construction files on 12/27/02 by our regulatory engineers.

Peter

as

Kramer, Jack T. From: Thursday, January 09, 2003 1:50 PM Sent: 'Peter.Wexler@apcc.com' To: RE: FW: APC Subject: Is the letter to consumers still coming? ----Original Message-----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:43 PM To: JKramer@cpsc.gov Subject: RE: FW: APC That is our plan "Kramer, Jack т. " To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc: Subject: RE: FW: APC .gov> 01/09/2003 01:39 PM One more timing issue, when our press release goes the APC web-page needs to be up and running. ----Original Message-----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:20 PM To: JKramer@cpsc.gov Subject: RE: FW: APC Jack: Here are the modified press releases for you review and sign off as well

the revised retail letter and store poster. For each we have used your

1

n

comments and made some minor changes to ensure that they are factually correct. Please let us know if you have any comments or questions. The web site will be up and we will have picture to you by tomorrow. (See attached file: CPSC Press Release v11.doc)(See attached file: Retail Letter v11.doc)(See attached file: APC Press Release v11.doc)(See attached file: store poster v11.doc)(See attached file: two tier reseller mailing v11.doc)

Regarding UL approval, they were notified of the change and a request was made to update our construction files on 12/27/02 by our regulatory engineers.

Peter

From:Kramer, Jack T.Sent:Thursday, January 09, 2003 1:39 PMTo:'Peter.Wexler@apcc.com'Subject:RE: FW: APC

One more timing issue, when our press release goes the APC web-page needs to be up and running.

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 1:20 PM To: JKramer@cpsc.gov Subject: RE: FW: APC

Jack:

Here are the modified press releases for you review and sign off as well as the revised retail letter and store poster. For each we have used your comments and made some minor changes to ensure that they are factually correct. Please let us know if you have any comments or questions. The web site will be up and we will have picture to you by tomorrow. (See attached file: CPSC Press Release v11.doc)(See attached file: Retail Letter v11.doc)(See attached file: APC Press Release v11.doc)(See attached file: store poster v11.doc)(See attached file: two tier reseller mailing v11.doc)

Regarding UL approval, they were notified of the change and a request was made to update our construction files on 12/27/02 by our regulatory engineers.

Peter

http://www.apc.com

1

From:Peter.Wexler@apcc.comSent:Thursday, January 09, 2003 10:04 AMTo:JKramer@cpsc.govCc:Ron.Catanzaro@apcc.comSubject:RE: FW: APC

Ron:

Can you get a jpg. of the unit.

"Kramer, Jack

	т. "	To:			
"'Peter.Wexler@apcc.com'" <peter.wexler@apcc.com></peter.wexler@apcc.com>					
	<jkramer@cpsc< td=""><td>cc:</td><td></td><td></td><td></td></jkramer@cpsc<>	cc:			
	.gov>	Subject:	RE:	FW:	APC

01/09/2003 09:35 AM

Peter,


One thing I need is a jpeg photo of the product. The word version of the photo will not work with our system

Jack

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Wednesday, January 08, 2003 1:25 PM To: JKramer@cpsc.gov Subject: Re: FW: APC

Jack -

Did you get the units?



.

Peter,

```
1st Draft Press Release
Jack
> -----Original Message-----
                Wolfson, Scott J.
> From:
                Wednesday, January 08, 2003 1:11 PM
> Sent:
                Kramer, Jack T.
RE: APC?
> To:
> Subject:
>
>
  <<apcc.doc>>
>
>
>
(See attached file: apcc.doc)
```

From: Sent: To: Subject:	Kramer, Jack T. Thursday, January 09, 200 'Peter.Wexler@apcc.com RE: FW: APC		
Importance:	High		
Peter,			
	eed is a jpeg photo o will not work with		. The word
Jack			
Original Message From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Wednesday, January 08, 2003 1:25 PM To: JKramer@cpsc.gov Subject: Re: FW: APC			
Jack -			
Did you get the unit	ts?		
	"Kramer, Jack		
"'Peter.Wexler@apcc.	T." .com'" <peter.wexler@ <jkramer@cpsc< td=""><td>To: apcc.com> cc:</td><td></td></jkramer@cpsc<></peter.wexler@ 	To: apcc.com> cc:	
	.gov>	Subject:	FW: APC
	01/08/2003		
	01:22 PM		

Peter,

1st Draft Press Release

Jack > ----Original Message----> From: Wolfson, Scott J.

From:Kramer, Jack T.Sent:Thursday, January 09, 2003 8:21 AMTo:'Peter.Wexler@apcc.com'Subject:RE: FW: APC

This morning is good

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Thursday, January 09, 2003 8:20 AM To: JKramer@cpsc.gov Subject: RE: FW: APC

Jack:

Can we get together today to discuss what you need to sign off.

Peter

	"Kramer, Jack		
'" <peter.wexler@ap< td=""><td>Т." СС.СОМ></td><td>To:</td><td>"'Peter.Wexler@apcc.com</td></peter.wexler@ap<>	Т." СС.СОМ>	To:	"'Peter.Wexler@apcc.com
	<jkramer@cpsc< td=""><td>cc:</td><td></td></jkramer@cpsc<>	cc:	
	.gov>	Subject	: RE: FW: APC
	01/08/2003		

08:13 PM

Peter the 14th is possible however, we need to work out several details

jack

-----Original Message-----From: Peter.Wexler@apcc.com To: JKramer@cpsc.gov Sent: 1/8/03 6:36 PM Subject: RE: FW: APC

Jack:

If possible, we would like to move the timing up to the 14th of January. We would like to set up a call with you for tomorrow to discuss our planning and seek your input. Please let me know what time works for you.

. .

.

Thank you.

Peter

From: Sent: To: Subject: Peter.Wexler@apcc.com Thursday, January 09, 2003 8:20 AM JKramer@cpsc.gov RE: FW: APC

Jack:

Can we get together today to discuss what you need to sign off.

08:13 PM

Peter

"Kramer, Jack T." To: "'Peter.Wexler@apcc.com '" <Peter.Wexler@apcc.com> <JKramer@cpsc cc: .gov> Subject: RE: FW: APC 01/08/2003

Peter the 14th is possible however, we need to work out several details

jack

----Original Message----From: Peter.Wexler@apcc.com To: JKramer@cpsc.gov Sent: 1/8/03 6:36 PM Subject: RE: FW: APC

Jack:

If possible, we would like to move the timing up to the 14th of January. We would like to set up a call with you for tomorrow to discuss our planning and seek your input. Please let me know what time works for you.

Thank you.

Peter

41

http://www.apc.com

•

From:Kramer, Jack T.Sent:Thursday, January 09, 2003 6:48 AMTo:'Peter.Wexler@apcc.com'Subject:RE: FW: APC

Importance:

High

Peter,

I see no problem with the 14th provided we can get the specifics in place. You asked about on-line registration here is an example from another recall. http://www.hp.com/hpinfo/newsroom/recalls.html

As far as, matching returned units to the individual consumers that is not necessary, we do ask that you can tell us the source i.e. consumer, retailer, distributor, etc.

Best

Jack

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Wednesday, January 08, 2003 6:36 PM To: JKramer@cpsc.gov Subject: RE: FW: APC

Jack:

If possible, we would like to move the timing up to the 14th of January. We would like to set up a call with you for tomorrow to discuss our planning and seek your input. Please let me know what time works for you.

Thank you.

Peter

From: Sent: To: Subject: Kramer, Jack T. Wednesday, January 08, 2003 8:14 PM 'Peter.Wexler@apcc.com ' RE: FW: APC

Peter the 14th is possible however, we need to work out several details

jack

-----Original Message-----From: Peter.Wexler@apcc.com To: JKramer@cpsc.gov Sent: 1/8/03 6:36 PM Subject: RE: FW: APC

Jack:

If possible, we would like to move the timing up to the 14th of January. We would like to set up a call with you for tomorrow to discuss our planning and seek your input. Please let me know what time works for you.

Thank you.

Peter

From: Sent: To: Subject: Peter.Wexler@apcc.com Wednesday, January 08, 2003 6:36 PM JKramer@cpsc.gov RE: FW: APC

Jack:

If possible, we would like to move the timing up to the 14th of January. We would like to set up a call with you for tomorrow to discuss our planning and seek your input. Please let me know what time works for you.

Thank you.

Peter

http://www.apc.com

 \sim

From: Sent: To: Subject: Kramer, Jack T. Wednesday, January 08, 2003 2:53 PM 'Peter.Wexler@apcc.com' RE: FW: APC

yes

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Wednesday, January 08, 2003 1:25 PM To: JKramer@cpsc.gov Subject: Re: FW: APC

Jack -

Did you get the units?

"Kramer, Jack

T." To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc: .gov> Subject: FW: APC

01/08/2003

01:22 PM

Peter,

1st Draft Press Release

```
Jack
> -----Original Message-----
> From: Wolfson, Scott J.
> Sent: Wednesday, January 08, 2003 1:11 PM
> To: Kramer, Jack T.
> Subject: RE: APC?
> 
< <<apre>c.doc>>
>
```

From: Sent: To: Subject: Peter Wexler@apcc.com Tuesday, January 07, 2003 2:49 PM JKramer@cpsc.gov RE: Public Notice

We will call you at 3pm. Also, do you a list of other countries recall requirements?

"Kramer, Jack

T." To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc:

.gov> Subject:

RE: Public Notice

1 .

01/07/2003

02:19 PM

Now is fine or Wednesday morning


----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Tuesday, January 07, 2003 2:17 PM To: JKramer@cpsc.gov Cc: Joe.Loberti@apcc.com Subject: Re: Public Notice

Jack,

Please let us know when would be a good time to discuss the suggested changes with you.

Thank you.

Peter



Peter,

Public Affairs is revising the press release. Attached are revisions to the letter to consumers, retailers and point of purchase poster. Please be sure to include the words "SAFETY RECALL" in large bold letters on the outside of the mailing envelope.

<<pre><<customer recall letter.doc>> <<Retail Letter.doc>>
<<store poster.doc>>
(See attached file: customer recall letter.doc)(See attached file:
Retail
Letter.doc)(See attached file: store poster.doc)

From: Sent: To: Subject: Peter.Wexler@apcc.com Wednesday, January 08, 2003 2:31 PM JKramer@cpsc.gov Re: FW: APC Datavalidation

Jack:

As we set up the system for return of units we have some questions. Our systems will track return of units by serial number in the affected ranges. We assume that this is sufficient. We cannot track by individual end-users as our business model is primarily through two step distribution and as some customers may have thousands of units (ie a distributor). We will

some customers may have thousands of units (ie a distributor). We will track unit numbers in, and the disposition of the units (re-worded or scrapped) Please confirm that this is acceptable as soon as you can.

Peter

1- 7

From: Sent: To: Subject: Peter.Wexler@apcc.com Wednesday, January 08, 2003 1:33 PM JKramer@cpsc.gov Re: FW: APC



Jack:

After review of the units returned to us, it is six incidents in the US not seven. The incident on 12/3/02 should not have been classified as the other incidents.

Peter

"Kramer, Jack
"T." To:
"'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com>
<JKramer@cpsc cc:
.gov> Subject: FW: APC
01/08/2003
01:22 PM

Peter,

lst Draft Press Release
Jack
> -----Original Message----> From: Wolfson, Scott J.
> Sent: Wednesday, January 08, 2003 1:11 PM
> To: Kramer, Jack T.
> Subject: RE: APC?
>
< <<apre>c.doc>>

> (See attached file: apcc.doc)

.

.

From: Sent: To: Subject: Peter.Wexler@apcc.com Wednesday, January 08, 2003 1:25 PM JKramer@cpsc.gov Re: FW: APC



Jack -

Did you get the units?

"Kramer, Jack

"'Peter.Wexler@apcc	T." .com'" <peter.wexler@ <jkramer@cpsc< th=""><th>To: apcc.com> cc:</th><th></th><th></th></jkramer@cpsc<></peter.wexler@ 	To: apcc.com> cc:		
	.gov>	Subject:	FW:	APC

01/08/2003 01:22 PM

Peter,

1st Draft Press Release

```
Jack
> ----Original Message-----
              Wolfson, Scott J.
> From:
               Wednesday, January 08, 2003 1:11 PM
> Sent:
               Kramer, Jack T.
> To:
> Subject:
                    RE: APC?
>
>
  <<apcc.doc>>
>
>
>
(See attached file: apcc.doc)
```

//

From: Sent: To: Subject: Kramer, Jack T. Wednesday, January 08, 2003 1:23 PM 'Peter.Wexler@apcc.com' FW: APC

Peter,

.

1st Draft Press Release

Jack

Original Me	essage
From:	Wolfson, Scott J.
Sent:	Wednesday, January 08, 2003 1:11 PM
То:	Kramer, Jack T.
Subject:	RE: APC?



> Sent: Wednesday, Sanuary 08, 2003 1:11 PM
> To: Kramer, Jack T.
> Subject: RE: APC?
>
< <<apcc.doc>>
>
</created file: apcc.doc)</pre>

r

From:Kramer, Jack T.Sent:Tuesday, January 07, 2003 2:35 PMTo:'Peter.Wexler@apcc.com'Subject:RE: Public Notice

3 pm is fine sorry no info on other countries

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Tuesday, January 07, 2003 2:49 PM To: JKramer@cpsc.gov Subject: RE: Public Notice

We will call you at 3pm. Also, do you a list of other countries recall requirements?

"Kramer, Jack T." To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc: .gov> Subject: RE: Public Notice 01/07/2003

Now is fine or Wednesday morning

-----Original Message-----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Tuesday, January 07, 2003 2:17 PM To: JKramer@cpsc.gov Cc: Joe.Loberti@apcc.com Subject: Re: Public Notice

02:19 PM

Jack,

Please let us know when would be a good time to discuss the suggested changes with you.

Thank you.

Peter

"Kramer, Jack

"'Peter.Wexler@apcc <peter.wexler@apcc.d< th=""><th></th><th>То:</th><th></th></peter.wexler@apcc.d<>		То:	
-	<jkramer@cpsc< td=""><td>cc:</td><td></td></jkramer@cpsc<>	cc:	
	.gov>	Subject:	Public Notice
	01/07/2003		

11:12 AM

Peter,

Public Affairs is revising the press release. Attached are revisions to the letter to consumers, retailers and point of purchase poster. Please be sure to include the words "SAFETY RECALL" in large bold letters on the outside of the mailing envelope.

<<pre><<customer recall letter.doc>> <<Retail Letter.doc>>
<<store poster.doc>>
(See attached file: customer recall letter.doc)(See attached file:
Retail
Letter.doc)(See attached file: store poster.doc)

From:Kramer, Jack T.Sent:Tuesday, January 07, 2003 2:20 PMTo:'Peter.Wexler@apcc.com'Subject:RE: Public Notice

Now is fine or Wednesday morning

----Original Message----From: Peter.Wexler@apcc.com [mailto:Peter.Wexler@apcc.com] Sent: Tuesday, January 07, 2003 2:17 PM To: JKramer@cpsc.gov Cc: Joe.Loberti@apcc.com Subject: Re: Public Notice

Jack,

Please let us know when would be a good time to discuss the suggested changes with you.

Thank you.

Peter

"Kramer, Jack

T." To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc:

.gov> Subject: Public Notice

5

01/07/2003

11:12 AM

Peter,

Public Affairs is revising the press release. Attached are revisions to the letter to consumers, retailers and point of purchase poster. Please be sure to include the words "SAFETY RECALL" in large bold letters on the outside of the mailing envelope.

1 ~





<<pre><<customer recall letter.doc>> <<Retail Letter.doc>>
<<store poster.doc>>
(See attached file: customer recall letter.doc)(See attached file:
Retail
Letter.doc)(See attached file: store poster.doc)

From: Sent: To: Cc: Subject: Peter.Wexler@apcc.com Tuesday, January 07, 2003 2:17 PM JKramer@cpsc.gov Joe.Loberti@apcc.com Re: Public Notice







letter.doc Jack,

Please let us know when would be a good time to discuss the suggested changes with you.

Thank you.

Peter

"Kramer, Jack

T." To: "'Peter.Wexler@apcc.com'" <Peter.Wexler@apcc.com> <JKramer@cpsc cc: .gov> Subject: Public Notice

01/07/2003

11:12 AM

Peter,

Public Affairs is revising the press release. Attached are revisions to the letter to consumers, retailers and point of purchase poster. Please be sure to include the words "SAFETY RECALL" in large bold letters on the outside of the mailing envelope.

<<pre><<customer recall letter.doc>> <<Retail Letter.doc>>
<<store poster.doc>>
(See attached file: customer recall letter.doc)(See attached file:

1 ~

Retail Letter.doc) (See attached file: store poster.doc)

From: Sent: To: Subject: Kramer, Jack T. Tuesday, January 07, 2003 11:13 AM 'Peter.Wexler@apcc.com' Public Notice

Peter,

Public Affairs is revising the press release. Attached are revisions to the letter to consumers, retailers and point of purchase poster. Please be sure to include the words "SAFETY RECALL" in large bold letters on the outside of the mailing envelope.



customer recall letter.doc Retail Letter.doc



1,4

Kramer, Jack T. Peter.Wexler@apcc.com From: Monday, January 06, 2003 3:19 PM Sent: jkramer@cpsc.gov To: Subject: CONFIDENTIAL CPSC Press Release Press Release v9.doc Retail Letter v9.doc customer recall letter v9.doc v9.doc This e-mail contains information considered confidential by American Power Conversion Corporation and is entitled to exemption from public disclosure under provisions of the Freedom of Information Act [15 U.S.C. 522 (B)] and Section 6 of the C.P.S.A. Jack: Per your voice-mail, please find attached the soft-copy of the documents as you requested. Please let me know if there is anything else we can provide by soft copy. Peter Wexler | - - - - -______ ---(See attached file: CPSC Press Release v9.doc) ---(See attached file: Press Release v9.doc) ---| (See attached file: Retail Letter v9.doc) _ _ _ | (See attached file: customer recall letter v9.doc) ------| _____ ---| _____ ---1

http://www.apc.com

.

.

11



U.S. CONSUMER PRODUCT SAFETY COMMISSION

WASHINGTON, D.C. 20207

OFFICE OF COMPLIANCE Recalls and Compliance Division Email: jkramer@cpsc.gov

DEC 2 3 2002

Jack T. Kramer Compliance Officer Tel:301-504-0608, Ext. 1247 Fax: 301-504-0359

Certified Mail/Facsimile 401.788.2766

Peter Wexler Senior Counsel American Power Conversion 132 Fairgrounds Road W. Kingston, RI 02892

Re:

CPSC RP030081 American Power Conversion Uninterruptible Power Supply

Dear Mr. Wexler:

Thank you for your report of December 23, 2002 under section 15(b) of the Consumer Product Safety Act, as amended (CPSA), 15 U.S.C. § 2064(b). In your report, you identified a potential problem with certain American Power Conversion, Uninterruptible Power Supplies. Specifically, the units can overheat and pose a potential fire hazard.

You also noted that the firm wishes to participate in the Commission's Fast Track Product Recall Program. This program, formerly called the No Preliminary Determination (No PD) Program, is described in the <u>Federal Register</u> of July 24, 1997, and in the enclosed materials. To participate in this program, your firm must initiate an acceptable corrective action plan no later than January 22, 2003, and you must also provide all of the information required to be included in a full report described at 16 C.F.R. § 1115(13)(d). If you have not done so already, we request that you provide a copy of your proposed corrective action plan (CAP), including all draft notice material, as soon as possible, but no later than January 7, 2003. To assure that the staff is able to evaluate the adequacy of the firm's proposed CAP prior to its initiation, please submit the requested full report information along with the proposed CAP.

When the corrective action program begins, the Office of Compliance will monitor the progress of the recall. The staff requests that the firm provide a list of retailers and distributors to whom your firm sold the product. The list should include firm name, address, and, if available,

CPSC Hotline: 1-800-638-CPSC(2772) ★ CPSC's Web Site: http://www.cpsc.gov Fast Track Recall Program is a 1998 Innovations in American Government Award Winner Page 2 RP030081

the number of units shipped to each firm. Please provide the list sorted by postal zip code or state.

Information Disclosure

Section 6(b)(5) of the CPSA, 15 U.S.C. § 2055(b)(5), prohibits the release of information submitted under section 15(b) of the CPSA unless a remedial action plan has been accepted in writing, a complaint has been issued, or a firm consents to such release.

If the firm submits any information that it considers to be a trade secret, or confidential commercial or financial information, it must mark it "confidential" in accordance with section 6(a)(3) of the CPSA, as amended, 15 U.S.C. § 2055(a)(3). The Commission may not disclose to the public trade secret information or proprietary commercial or financial data. If the firm does not request confidential treatment at the time of its submission, or within ten days thereafter, the staff will assume that it does not consider information in the submission to be a trade secret or otherwise exempt from disclosure under section 6(a) of the CPSA and the Freedom of Information Act, 5 U.S.C. § 552(b)(4).

Continuing Obligation

The firm has a continuing obligation to supplement or correct its "Full Report." If, after filing the "Full Report," the firm receives or learns of information concerning other incidents or injuries, or information that affects the scope, prevalence or seriousness of the defect or hazard, it must report that information to this Division immediately.

If you seek assistance or if you have any questions, you may contact me by telephone on (301) 504-0608, extension 1247. For all overnight and/or direct delivery services, please address the material to Office of Compliance, U.S. Consumer Product Safety Commission, Room 613, 4330 East West Highway, Bethesda, MD 20814-4408. The Office of Compliance telefax number is (301) 504-0359.

Sincerelv

Jack T. Kramer Compliance Officer Recalls and Compliance Division

18

Enclosure

CPSC Program Information Recall Checklist

cc: Consumer Product Safety Commission

· •

Page 3 RP030081

> Eastern Regional Center 201 Varick Street Room 903 New York, New York 10014-4811

> > 9

61-789-5735,2255

CASE NUMBER: RP RP03 00 7

BY:, ,
12/20/02
XX

د `

DIVISION OF CORRECTIVE ACTIONS SECTION 15(b) REPORT WORKSHEET

ADDRESS:

PHONE: 401-789-5735, 2255 FAX: 401-788-2766

CONTACT: Peter Wexler

TITLE:

ADDRESS [IF DIFFERENT FROM ABOVE] :

PHONE:

FAX:

PRODUCT:

NEISS CODE:

BRAND NAME/MODEL NO: BK 500 BK 350

UPC:

RETAIL PRICE: 79-112

CERTIFICATION/STANDARDS INFORMATION:

DEFECT/PROBLEM: Unit my shopt

HOW AND WHEN DISCOVERED:

HAZARD: fire

INJURIES: none

DISCUSSION: [Include any information has at this point regarding extent of problem, testing information, firm's explanation]

FOR OFFICIAL USE ONLY

Page 2

Ĩ

ADDITIONAL PRODUCT INFORMATION:	Imil
TOTAL NUMBER INVOLVED:	1 1000,00
WITH MFR:	8 5
WITH DISTRIBUTORS:	C
WITH RETAILERS:	
WITH CONSUMERS:	
DISTRIBUTION: <u>X</u> NATIONAL	REGIONAL
PRODUCTION/IMPORTATION DATES:	
DISTRIBUTION DATES:	

CORRECTIVE ACTION PLANNED OR UNDERWAY: [INCLUDE DATES]

INFORMATION RE ANY OTHER FIRMS INVOLVED: [E.G., IMPORTER, DISTRIBUTOR, RETAILERS, COMPONENT PART SUPPLIER]

TOD OFFICIAL HOR OFFICE





CONFIDENTIAL

D J ... - 6 M H: 23

January 3, 2002

Jack T. Kramer Compliance Officer Recalls and Compliance United States Consumer Product Safety Commission 4330 East West Highway Room 613 Bethesda, Maryland 20814 SENT VIA FEDEX

Re: CPSC RP030081, American Power Conversion ("APC") UPS

Dear Mr. Kramer:

Thank you for your letter of December 23, 2002 and the follow-on material that we received on December 30, 2002. In accordance with your letter, please find enclosed a copy of the "Full Report" and proposed corrective action plan ("CAP") as well as draft of notice material including but not limited to, press releases and point of sale posters. In regard to the press releases, we have provided both a draft CPSC press release based on the sample material provided by you and a draft APC press release. The APC press release is subject to change prior to release based on changes in APC's business outlook and regulatory requirements. Additionally, the information contained in Exhibit I of the Full Report is considered to be "near final".

Also, per your request, we have shipped to you twelve (12) APC uninterruptible power supply units that are representative of the following groups:

- 1. Three (3) have the PB137 regulator.
- 2. Three (3) have the initial change made to bypass the PB137 regulator
- 3. Three (3) have a new PCB board layout to remove the PCB regulator.
- 4. Three (3) units that incorporate all current design fixes eliminating the potential safety hazard that is the subject of the Full Report.

Please consider this letter as notice that APC considers the information supplied to the CPSC to date, as well as the Full Report, its content and this letter to be confidential information

 American Power Conversion
 Corporation

 PO Box 278
 Call 401 789 5735

 132 Fairgrounds Road
 Fax 401 789 3710

 West Kingston, RI 02892
 Visit www.apcc.com

 APC is an equal opportunity employer which values workforce diversity.

 APCs quality system is ISO 9002 certified.

12



CONFIDENTIAL

Mr. Jack Kramer January 3, 2002

_ **`**

and entitled to exemption from pul Act [15 U.S.C. 522 (B)] and Section

APC would like to ins any comments or Auestions direc

Very truly yours,

Peter Wexler Senior Counsel American Power Conversi

CC: Peter Mone -Baker

Pert apprais Z

7913.

FPP-272 7253

13

CONTENTS OF FILE CASE NO. <u>RF 030081</u>

	PSA REQUEST FO	DRMS
	PSA RESPONSE F	ORMS
		TGATIONS IDI AND IPII REPORTS
TRM	SAMPLE COLLEC	TION REPORT
FIRM	CLOSED MEETIN	G MEMORANDUM
м	VOLUNTARY ST	ANDARD AND TESTING REPORTS
NCE FROM FIRM	FIRM TESTING R	EPORTS/DATA
FIRM W/GREEN	PROGRESS REVIE	EW REQUESTS AND REPORTS
) FIRM W/GREEN	EFFECTIVENESS	CHECKS REQUESTS AND REPORTS
A COMPLIANCE		MISSION
(PD) FORM	CLOSE OUT LETT	ER
	CASE CLOSE FOR	
·		
<u>APC</u> FIRM		Peter Wexler CONTACT
FIRM ADDRESS		CONTACT ADDRESS
		CITY, STATE AND ZIP CODE <u>401-789-5735 x 27</u> TEL. NO.
FIRM WEBSITE	ADDRESS	TEL NO. 401 - 789 - 3710 FAX NO. 77
	FIRM FIRM ADDRESS	PSA RESPONSE F PSA RESPONSE F O FILE INDEPTH INVEST TIRM SAMPLE COLLEC FIRM CLOSED MEETTN M VOLUNTARY ST NCE FROM FIRM FIRM TESTING R FIRM W/GREEN FIRM TESTING R FIRM W/GREEN EFFECTIVENESS O FIRM W/GREEN EFFECTIVENESS A COMPLIANCE MEMOS TO COM (PD) FORM CLOSE OUT LETT CASE CLOSE FOR CASE CLOSE FOR CLOSE CLOSE CLOSE CLOSE FOR CLOSE CLOSE CLOS

030328CR-6723

D D D D D D D D D D D D D D D D D D D
U.S. CONSUMER PRODUCT SAFETY COMMISSION RP030081 NOTICE OF INSPECTION
1. DATE 3. FROM (Area Office and Address)
5 An 03 Crsc
Z TIME
10:30 p.m. DC
A. NAME AND TITLE OF INDIVIDUAL
Alfredo R. Oliver, Asst Man.
B. FIRM NAME Office Donot Sonio Capias, Custmen Sve
4. TO C. NUMBER AND STREET ADDRESS
1011 Jee Huy
D. CITY, STATE AND ZIP CODE
Tunka VA ZZOZO
Notice of Inspection is hereby given pursuant to:
• Flammable Fabrics Act (15 U.S.C. 1191 et seq.);
• Federal Trade Commission Act (15 U.S.C. 41 et seq.);
• Sections 16, 19 and 27 of the Consumer Product Safety Act (15 U.S.C. 2065, 2068 and 2076)
 Section 704(a) of the Federal Food, Drug, and Cosmetic Act (21 U.S.C. 374(a)) [Authority for inspections in connection with the Poison Prevention Packaging Act of 1970 (15 U.S.C. 1471 et seq.)] and/or
• Section 11(b) of the Federal Hazardous Substances Act as Amended (15 U.S.C. 1270(b)).
Refer to the back of this form for a discussion of inspectional authority and for pertinent statutory language.
5. PURPOSES OF INSPECTION AND NATURE OF INFORMATION TO BE OBTAINED AND/OR COPIED.
The purpose of this inspection is to obtain information; to review and obtain copies of items including but not limited to records, reports, books, documents; and labeling; and to obtain samples, in order to enforce or de- termine compliance with the Acts administered by the Consumer Product Safety Commission.
8. FREEDOM OF INFORMATION REQUIREMENTS


Those from whom information is requested should state whether any of the information submitted is believed 751


	 A state of the second se	
	J,	TCKK
⊐ Postage	\$	
Certified Fee		Postmar
Return Receipt Fee (Endorsement Required)		Here
Restricted Delivery Fee (Endorsement Required)		
Total Postage & Fees	\$	
Sent To	RP03 0	<u> </u>

ML

1

,





ហ		nly; No Insuranc	CEIPI e Coverage Provided)	
5 1 1			JK	
5735	Postage Certified Fee	\$		
E700	Return Heceipt Fee (Endorsement Required) Restricted Delivery Fee (Endorsement Required)		Postmark Here	
70	Total Postage & Fees	\$		
7000 16	Sent To Street, Apt. No.; or PO Bo City, State, ZIP+4	RP03c	æ8	

1. Task Number 020516CCC1529		2. Ir	vestigator's ID 9092		EPIDEMIOLOGIC
3. Office Code	4. Date of Accide YR MO DAY 2002 05 05		yr MO DAY	INVESTIGATION REPORT	
6. Synopsis of Accide		UP			
While a smoke alarn investigated the cause	n sounded and the se and discovered o unit that had been	one-foot long f plugged into a	lames and smoke e wall receptacle for	mitting fro five mont	ily house a male complainant om a surge protector/battery ths without incident. There wer n damages.
			Ex. 3,25 c	Y CO SN F1	BR 500 PLED percepte solo ascontetation obroos, devisions rullas not requested rthar fotice 3 19 03 H
7. Location (Home, School, etc) 1 - HOME			8. City WINDHAM		9. State (ME
			and Name	10C. Model Number BK350	
132 Fairgro W. Kingstor 11A. Second Product	POWER CONVERS	11B. Trade/Br	and Name		11C. Model Number
0557 -Computers 11D. Manufacturer Na NONE	me and Address				UNKNOWN
12. Age of Victim	13. Sex 1 - Male		14. Disposition 0 - No Injury		15. Injury Diagnosis 70 - No Injury
16. Body Part(s) Involved 99 - NO INJURY	17. Responde		18. Type of Investi 2 - Telephone	(Operational / Travel)	
20. Attachment(s) 9 - Multiple Attachme		. Case Source 7 - Consumer		22	2. Sample Collection Number
23. Permission to Disc	ose Name (Non N	EISS Cases Or	nty)		
🔿 Yes	🔿 No	🔘 Ve	rbal		
24 Daview Date	25. Reviewed By			26. Regi	onal Office Director
24. Review Date			1	Bruce	Schwartz
24. Review Date 06/12/2002	8930				

CPSC FORM 182 (12/96) Approved for use through 07/31/2003 OMB NO. 30410029

.

.

,

NOTE: The information in this report was obtained from the complainant during telephone conversations on May 21, 2002 and June 6, 2002.

PRE-INCIDENT

The male complainant explained that his home is a 10 year-old wooden framed two story single family home, that the electrical system is original from the time of construction and there have been no modifications, alterations or repairs to the system. He also explained that the electrical system contains a circuit breaker panel box that has functioned without incident and that there have been no problems with any other electric-powered appliances in the house.

The complainant explained that he purchased the surge protector/battery back-up combination unit new from a South Portland, Maine retail firm in early December 2001 for approximately \$100.00. He continued to explain that the unit was kept in its original retail package and stored in his home for three weeks prior to using it.

According to the complainant, the instruction pamphlet provided with the surge protector/battery back-up unit indicated that some assembly was required prior to use. He explained that he followed the directives of the instruction pamphlet, which included connecting a red wire to the internal battery, and plugging the power cord into a wall receptacle for eight hours in order to charge the battery.

The complainant explained that in late December 2001 (a few days after Christmas), he placed the surge protector/battery back-up unit on the uncovered wooden floor of a first story room in his home and plugged it into a 120-volt duplex style wall receptacle. He continued to explain that the product remained plugged in at this location until the date of the incident.

The complainant explained that the only appliances that he connected to the surge protector/battery back-up unit was a personal computer unit (PCU) and a monitor which were plugged into two of the of the three battery back-up outlets located on the rear panel. He continued to explain that he used none of the three surge only outlets located on the rear panel of the unit and that he did not utilize the USB port or the telephone ports of the surge protector/battery back-up unit.

He stated that prior to the incident the surge protector/battery back-up unit functioned well and also that there were no modifications, alterations or repairs made to the product. He explained that there have been no problems with other electric powered appliances in his home.

The complainant explained that on the date of the incident, after being away for approximately one hour, at approximately 4:30 PM he returned to his home at which time there were no signs of fire or smoke.

INCIDENT

According to the complainant, on May 5, 2002 at approximately 4:50 PM while investigating the cause of an activated smoke detector and the odor of burning plastic, he discovered one-foot-long flames and smoke emitting from the side panel of a surge protector/battery back-up combination unit.

POST INCIDENT

The complainant explained that he immediately pulled the power cord from the wall outlet to cut electric power, which caused the flames to subside. He then called the fire department by telephone to report the situation. There were no injuries sustained due to the incident.

According to the complainant, prior to the arrival of fire department personnel he removed the surge protector/battery back-up unit from inside of the house to the front yard. He explained that after he reentered the house he discovered that the incident did not cause the circuit breaker to trip He explained that upon arrival of the fire department personnel they inspected the scene, found no additional hazards, and departed.

The complainant stated that damage sustained due to the incident is valued at an estimated \$2,000 including the cost of new paint, replacing the computer components that were charred during the incident, cleaning and repairing the charred wooden floor, cleaning supplies to remove the smoke odor from the home, etc.

The complainant explained that the day following the incident he contacted the manufacturer by telephone to report the incident and to file a claim for reimbursement of the incident product and collateral damages. He continued to explain that the manufacturer issued him Claim #2037366 EPP #706623 and instructed him to return the incident product to them, which he did on May 23, 2002. He stated that all correspondence with the manufacturer was through telephone conversations except for one email that he sent to them itemizing the damages sustained due to the incident.

The complainant explained that the manufacturer provided him \$1,600.00 to cover the damage sustained by the incident and they also mailed him a new a new replacement surge protector/battery back-up unit. The complainant stated that he was very pleased with the responsiveness of the manufacturer.

SAMPLE COLLECTED

The consumer shipped the incident product to the manufacturer.

PRODUCT IDENTIFICATION

The product is an electric-powered surge protector/ battery back-up combination unit, consisting of what appear to be hardened plastic side and panels, off white in color with a gray colored rear panel, consisting of three battery back-up outlets, three surge only outlets, a USB cable jack and two telephone jacks. The letters "A P C" are molded into each of the unit's side panels. The unit measures approximately 6.5 inches high, 3.5-inches wide and 12-inches long, and weighs approximately 12 pounds. Information regarding additional labeling is not available.

The product was manufactured by: American Power Conversion, 132 Fairground Road, P.O. Box 278, West Kingston, RI 02892. The manufacturer's customer service telephone number is 1-800-800-4272.

According to the complainant the product is labeled as model BK350, Serial Number AD0115241578.

The incident product was purchased at Staples, 4143 Weston Avenue, South Portland, Maine, 04106.

PRODUCT STANDARDS

The standards for this product remain unknown.

ATTACHMENTS

- EXHIBIT 1 Photographs Figures 1.1-1.5 (The complainant provided these photographs)
- EXHIBIT 2 Windham Fire Department Incident Report

A request has been made with the complainant to sign and return a CPSC Authorization to Release Name form, which will be forwarded as an addendum to this report upon receipt.




Figure 1.1 Side view of incident product showing location from where fire and smoke was emitted.




Figure 1.2 View of top panel of incident unit.




Figure 1.3 View of incident unit with computer components that complainant claims were charred during the fire.





Figure 1.4 View of computer components that complainant claims were charred by fire during the incident.



ASSIGNMENT # 020516 CCC 1529

A C5180 ME 05/05/2002 04 FDID State Incident Date Static	التغنيبية المهيب سيستشتقيتنا اس	Change NFIRS-1 No Activity
✓ Street Address 7 ✓ Intersection Number ✓ In front of	HERITAGE ME 0	LANE Suffix
C Incident Type 440 Electrical wiring/equipment p D Aid Given or Received 1 □ Received Their FDID 2 □ Automatic Rec'vd 3 □ Given Their State 4 □ Automatic Given 0000000 N ▼ None Their Incident	E1 Dates & Times Mon. Day Year Alarm 05/05/02 Arrivat Control Last Unit Clear	E2 Shifts / Alarms 16:56 D 1 04 16:56 Shift Alarms Dist. 17:00 E3 Special Studies 00:00 ID# Value
F Actions Taken 86 Primary Action Taken (1) 45 Additional Action Taken (2) Additional Action Taken (3)	G1 Resources Apparatus Personnel Suppression 2 8 EMS 0 0 Other 2 5	G2 Dollar Loss & Values LOSSES: NONE Property 0 Contents 0 PRE-INCIDENT VALUE Property 0 Contents 0
Completed Modules H1 Casualties Deaths Fire 0 Civilian 0 H2 Detector Alerted Occupan 1 Yes 2 No U Unknown	Inj. 1 None Inj. 1 Natural Gas 2 Propane Gas 3 Gasoline 4 Kerosene 5 Diesel Fuel/Fuel Oli 6 Household Solvents 7 Motor Oli 8 Paint 0 Other	I Mixed Use Property NN Not Mixed 10 Assembly Use 20 Education Use 33 Medical Use 40 Residential Use 51 Row of Stores 53 Enclosed Mail 58 Business & Resid. 59 Office Use 60 Industrial Use 63 Military Use 65 Farm Use 00 Other Mixed Use
1st Company Print Test 1 to Arrive Print Test 2 E-7	J Property Use	419 1 or 2 family dwelling

Windham Fire Rescue Dent

_____ · · -

05/10/2002	11:27	892-0544
------------	-------	----------

	Windina in in	e Rescue Dept.		5/05/2002	0000683 0
K1 Person / Er	ntity Involved			(000)	892-5301
	•	Business name (if	applicable)	Phone	
- 19-19-19-19-19-19-19-19-19-19-19-19-19-1		отну	JACQUES		1 1
	Mr. Ms. Mrs. Fire		MI Last Name		Suffix
Sente	7		TAGE	LANE	1 1
	Number		or Highway	Street Ty	pe Suffix
NC OPT			Windham		
	Post Office Box	Apt./Suite/Room	City		
	ME	04062			
	State	Zip			
K2 Owner	Samens Pars	Business name (if			
		Business name (if	applicable)	Phon	9
	Mr. Ms. Mrs. Fi	st Name	MI Last Name		Suffix
	Number	Prefix Street	or Highway	Street Ty	be Suffix
	Deat Office Devi	Apt./Suite/Room			
	Post Office Box	Apt./Sulle/Room	City		
	State	Zlp			
OWNER REPOR		CIRCUIT BREAKER I	KE IS APC FCC RE DID NOT TRIP.		100A-2007 1-XP-N.
M Authorizatio	<u>x</u>		Lieutenant	Suppressio	05/05/2002
0517 Officer in charge I	<u>x</u>	θ\$	Lieutenant Position or Rank	Suppressio Assignment	<u>05/05/2002</u> Date
0517 Officer in charge II 0036	<u>x</u>				



July 23, 2002

SENT VIA FEDEX

Ann DeTemple Director United States Consumer Product Safety Commission National Injury Information Clearinghouse 4330 East West Highway Room 504 Bethesda, Maryland 20814

Re: 020516CCC1529

Dear Ms. DeTemple:

We appreciate having received your letter dated July 1, 2002 and the epidemiological investigation report under Task No. 020516CCC1529. In that report, you referenced an incident involving an American Power Conversion BK350, Serial No. AD0115241578, Back-UPS unit, which the individual who reported the incident had purchased and had used without incident from December 2001 until the date of the safety critical incident, May 5, 2002.

We have conducted an examination of the unit and have also reviewed our records regarding both functional failures and safety critical failures relating to this product line. We have determined that over 650,000 BK350 and BK500 units of this design were sold worldwide during the time period of approximately January 2001 through December 2001 with approximately 280,000 of the aforementioned number being sold in the Unites States. To date, we have only received two other notifications of a safety critical failure, one in the United States and one in the Philippines.

Up to this point in time, our investigation has led us to conclude that a third party manufactured voltage regulator (part number PB137ACV) used in the products, as a battery charger, contained a latent defect which might cause the product to functionally fail and in rare instances may, it appears, result in the type of safety critical incident referred to in the attachments to your letter of July 1, 2002. Although we have worked hard at duplicating this failure mode in our labs, we have been unable to replicate that type of safety critical failure during our in-house examination and testing of the product. Moreover, we are unaware of any reports or claims that any of the subject units have caused any injuries to persons.

Approximately thirteen months ago, when it was determined that some units experienced functional failures (the unit would shut down and not work) we, in cooperation with the manufacturer of the voltage regulator, investigated the problem. At our request, the manufacturer

American Power Conversion Corporation

PO Box 278 Call 401 789 5735 132 Fairgrounds Road Fax 401 789 3710 West Kingston, RI 02892 Visit www.apcc.com APC is an annal opportunity employer which values workforce diversity

APC is an equal opportunity employer which values workforce diversit APC's quality system is ISQ 9002 cerufied. Ms. Ann DeTemple July 23, 2002



attempted to remedy the latent defect by changing its manufacturing production process. However, after subsequent review and testing, we made the determination to redesign the printed circuit board of the units so as to eliminate the use of the PB137ACV voltage regulator in its entirety.

In light of the above disclosures, do you feel that we have a situation where the product creates a substantial product hazard or creates an unreasonable risk of death or serious injury? We would appreciate hearing from you in that regard as obviously our paramount desire is to ensure that our consumers are dealing with a product which will not cause personal injury to them.

We thank you very much for having brought this incident to our attention and look forward to hearing from you as to whether the Commission needs further information from us.

ulv vours.

Peter Wexler Senior Counsel American Power Conversion Corporation



5126

August 23, 2002

SENT VIA FEDEX

Ann DeTemple Director United States Consumer Product Safety Commission National Injury Information Clearinghouse 4330 East West Highway Room 504 Bethesda, Maryland 20814

Re: 020516CCC1529

Dear Ms. DeTemple:

This letter follows up our letter to you dated July 23, 2002 (a copy of which is enclosed) responding to your letter to American Power Conversion Corporation dated July 1, 2002.

We want to confirm that you received our previous letter and we still await your advice as to whether you feel that we have a situation where the product creates a substantial product hazard or creates an unreasonable risk of death or serious injury?

Very touly yours

Peter Wexler Senior Counsel American Power Conversion Corporation

\$29/02 Copy to Marc Sheem for handling -

 American Power Conversion
 Call 401 789 5735

 PO Box 278
 Call 401 789 5735

 132 Fairgrounds Road
 Fax 401 789 3710

 West Kingston, RI 02892
 Visit www.apcc.com

APC is an equal opportunity employer which values workforce diversity APC's quality system is ISO 9002 certified.



July 23, 2002

SENT VIA FEDEX

Ann DeTemple Director United States Consumer Product Safety Commission National Injury Information Clearinghouse 4330 East West Highway Room 504 Bethesda, Maryland 20814

Re: <u>020516CCC1529</u>

Dear Ms. DeTemple:

We appreciate having received your letter dated July 1, 2002 and the epidemiological investigation report under Task No. 020516CCC1529. In that report, you referenced an incident involving an American Power Conversion BK350, Serial No. AD0115241578, Back-UPS unit, which the individual who reported the incident had purchased and had used without incident from December 2001 until the date of the safety critical incident, May 5, 2002.

We have conducted an examination of the unit and have also reviewed our records regarding both functional failures and safety critical failures relating to this product line. We have determined that over 650,000 BK350 and BK500 units of this design were sold worldwide during the time period of approximately January 2001 through December 2001 with approximately 280,000 of the aforementioned number being sold in the Unites States. To date, we have only received two other notifications of a safety critical failure, one in the United States and one in the Philippines.

Up to this point in time, our investigation has led us to conclude that a third party manufactured voltage regulator (part number PB137ACV) used in the products, as a battery charger, contained a latent defect which might cause the product to functionally fail and in rare instances may, it appears, result in the type of safety critical incident referred to in the attachments to your letter of July 1, 2002. Although we have worked hard at duplicating this failure mode in our labs, we have been unable to replicate that type of safety critical failure during our in-house examination and testing of the product. Moreover, we are unaware of any reports or claims that any of the subject units have caused any injuries to persons.

Approximately thirteen months ago, when it was determined that some units experienced functional failures (the unit would shut down and not work) we, in cooperation with the manufacturer of the voltage regulator, investigated the problem. At our request, the manufacturer

 American Power Conversion Corporation

 PO Box 278
 Call 401 789 5735

 132 Fairgrounds Road
 Fax 401 789 3710

 West Kingston, RI 02892
 Visit www.apcc.com

 APC is an equal opportunity employer which values workforce diversity.
 APCs quality system is 150 9002 certified.

Ms. Ann DcTemple July 23, 2002



attempted to remedy the latent defect by changing its manufacturing production process. However, after subsequent review and testing, we made the determination to redesign the printed circuit board of the units so as to eliminate the use of the PB137ACV voltage regulator in its entirety.

In light of the above disclosures, do you feel that we have a situation where the product creates a substantial product hazard or creates an unreasonable risk of death or serious injury? We would appreciate hearing from you in that regard as obviously our paramount desire is to ensure that our consumers are dealing with a product which will not cause personal injury to them.

We thank you very much for having brought this incident to our attention and look forward to hearing from you as to whether the Commission needs further information from us.

fuly ye urs.

5

Peter Wexler Senior Counsel American Power Conversion Corporation



U.S. CONSUMER PRODUCT SAFETY COMMISSION WASHINGTON, DC 20207

Pamela McDonald Technical Information Specialist National Injury Information Clearinghouse Directorate for Epidemiology Tel: (301) 504-0424, x1324 Fax: (301) 504-0124 Email: omcdonald@cpsc.gov

August 29, 2002

Mr. Peter Wexler Senior Counsel American Power Conversion Corporation P.O. Box 278 132 Fairgrounds Road West Kingston, RI 02892

Dear Mr. Wexler:

Thank you for your follow-up to your July 23, 2002 letter. We have hand carried a copy of both of your letters of July 23, 2002 and August 23, 2002 to the Office of Compliance for a reply. You will be hearing from them directly concerning this matter.

If you have any questions concerning any of the information or if we can be of further assistance, please feel free to contact us.

Sincerely,

Panela Mc toxald

Pamela McDonald Technical Information Specialist



October 3, 2002

Pamela McDonald Technical Information Specialist United States Consumer Product Safety Commission National Injury Information Clearinghouse 4330 East West Highway Room 504 Bethesda, Maryland 20814

SENT VIA FEDEX

Re: 020516CCC1529

Dear Ms. McDonald:

This letter follows up your letter dated August 29, 2002 in which you indicated that a representative of the Office of Compliance would contact us.

To date, we have not been contacted and still await your advice.

eter Wexler

Senior Counsel American Power Conversion Corporation

American Power Conversion Corporation

 PO Box 278
 Call 401 789 5735

 132 Fairgrounds Road
 Fax 401 789 3710


 West Kingston, R1 02892
 Visit www.apcc.com

 APC is an equal opportunity employer which values workforce diversity.
 APC's quality system is 150 9002 certified.

****	****	-COMM. JOURNA	L- ************************************	**** DATE OCT-07-2002 ***** TIME 09:45 *** P.01
MOD E =	MEMOR	RY TRANSMISSI	DN	START=OCT-07 09:44 END=OCT-07 09:45
FILE	N0.=	196		
NO.	COM	ABBR/NTWK	STATION NAME/ TELEPHONE NO.	PAGES PRG.ND. PROGRAM NAME
001	DK	8	914017893710	882/882
*****	юкжжже	****	K*****	- **** *********

US Consumer Product Safety Commission 4330 East West Highway Bethesda, Maryland 20814 Fax: (301) 504-0025 Fax: (301) 504-0124

Fax Transmittal



This information is transmitted from a Panafax UF-755. If any pages are missing, or if the copies are illegible, please call (301) 504-0431, after 5:00pm call (301) 504-0666.

Concerning your request

CONDUMER INCODUCT INCIDENT ABIORI	CONSUMER	PRODUCT	INCIDENT	REPORT
-----------------------------------	----------	---------	----------	--------

Region: EASTERN

1.NAME OF RESPONDENT	2. PHONE NO. (HOME)	(WORK)	
Tim Jacques	207-892-5301	none	
3.STREET ADDRESS	4.CITY	ST	ZIPCODE
7 Heritage Lane	Windham	ME	04062
4a.EMAIL ADDRESS: CPSC			

Surge protector had been plugged in for several months when consumer smelled something burning and heard the smoke detector's - cont -

6. DATE 7 of incident(s) 05/05/2002	AGE/SEX	RY OR NEAR MIS O Y/M SCRIBE INJURY	SS, OBTAIN		8.IF VICTIM DIFFE RESPONDENT, PRO self RELATIONSHIP self		
9.DESCRIPTION OF PRODUCT back up for a computer/surge protector				10.BRAND NAME APC			
132 Fairground Rd. P.O Box 278 West Kingston, RI 02892			ISSUE 3	2 BK350 13.DEALER Staples unknow S. Portl	12.MODEL, SERIAL NUMBERS BK350 S# AD0115241578 13.DEALER'S NAME, ADDRESS & PHONE Staples unknown S. Portland, ME 00000 unknkown		
14. WAS THE PRODUCT DAMAGED, REPAIRED OR MODIFIED? YES IF YES, BEFORE OR AFTER THE INCIDENT? AFTER DESCRIBE: damaged: see narrative			T?	15. PRODUCT PURCHASED NEW DATE PURCHASED 1/2002 AGE 5 M 16. DOES PRODUCT HAVE WARNING LABELS? IF SO, NOTE: none			
MANUFACTURER? YES YES			YES	5 DISPOSITION		19.MAY WE USE YOUR NAME WITH THIS REPORT? YES	
			FOR ADMINI	STRATION USE			
20.DATE RECEIVED 05/06/2002	2	21.RECEIVED BY (NAME & OFFICE) mks/HL			22. DOCUMENT NO. H0250063A		
23.FOLLOW-UP ACTION				24. PRODUCT CODE(S) 4062			
				er's name & T: 5/06/2002			

Region: EASTERN

H0250063A

Narrative Continued

siren. After looking around consumer noticed that the surge protector had exploded and caught fire. Consumer called emergency services and the Windham Fire Department responded to the call (Report # not given).

Fire marshall noticed that the surge protector's circuit breaker did not trip. A computer and monitor had been plugged into the surge protector (no further information).

Consumer is concerned that the backup/surge protector is defective and poses a fire hazard. Consumer is also concerned that burning plastic from the surge protector poses an inhalation hazard.

Property damage estimate is \$3,000 USD

Unit's UL listed # unknown

Distributor Phone #:

CPSC Source: CPSC

	ies when the consum	9062 1. 5. Date Initiated YR MO DAY 2001 06 28 UPC ter's battery back up/surge su was approximately \$500.00 ir			EPIDEMIOLOGIC NVESTIGATION REPORT
810 6. Synopsis of Accid There were no inju	YR MO DAY 2001 06 06 ont or Complaint ies when the consum	YR MO DAY 2001 06 28 UPC ter's battery back up/surge su			
6. Synopsis of Accid	2001 06 06 ont or Complaint ies when the consum	2001 06 28 UPC ter's battery back up/surge su			REPORT
6. Synopsis of Accid	int or Complaint	UPC ter's battery back up/surge su			
There were no inju	ies when the consum	er's battery back up/surge su			·
			fire dan		
7. Location (Home, S	chool, etc)	8. City	8. City		
1 - HOME		WENDELL			MA
10A. First Product	1	10B. Trade/Brand Name			10C. Model Number
4062 - Electric Wire	Or Wiring Syst	SURGE SUPPRESSORS		_	BACK-UPS-500
132 Fairg	POWER CONVERSI punds Road n, RI 02892	ON 18. Trade/Brand Name EXTENSION CORDS	<u>-</u>	<u> </u>	11C. Model Number
11D. Manufacturer N NONE	ime and Address				
12. Age of Victim	13. Sex	14. Disposition		15.	Injury Diagnosis
51	1 - Male	0 - No Injury			0 - No Injury
16. Body Part(s) involved 99 - NO INJURY	17. Respondent		18. Type of Investigation 19		
20. Attachment(s)		Case Source	7	22. Sampl	9 / 0 e Collection Number
9 - Multiple Attachm		- Consumer Complaint			
23. Permission to Dis				·	
O Yes	No	Verbal			
24. Review Date	25. Reviewed By		26. R	egional Off	ice Director
	8930			e E. Schwa	
08/09/2001					Iment Number
08/09/2001 27. Distribution	sing, Joseph W.; Sch	wartz, Bruce E.		60246A	
Ves Review Date	No So So	🔿 Verbal	Bruc 28. S	ource Docu	irtz

1

CPSC FORM 182 (12/96) Approved for use through 07/31/2003 OMB NO. 30410029

010626CCC1697

Per J. Kramer, an exemplar was not purchased for this investigation. Although the model presently sold at retailers appears to be the same as the complainant's model, the internal components may be different, therefore an exemplar would not aid this investigation.

PRE-INCIDENT

The complainant, a 51-year-old male, purchased the battery backup/surge suppressor new in March of 1999, from an office store in New Jersey. The consumer's home is not complete, and he lives partially in the house and partially in a motor home situated next to the house. The surge suppressor system was installed in a 7' by 10' spare bedroom in the house. The consumer had several items plugged into the suppressor: Computer, monitor, printer, radio, phone/answering machine, clock radio and a speaker system.

The surge suppressor is plugged into a 10 amp extension cord. The consumer modified the extension cord by adding two outlets to it. He uses the second outlet to plug in power tools. The length and manufacturer of the extension cord are unknown.

The complainant was using his computer on the morning of 6 June 2001. He was hungry, and went to the motor home to make something to eat. Before leaving the room, he turned the computer off, using the computers on/off switch. When he left the house, the radio, the phone/answering machine, the clock radio and the speaker system remained on. He does not turn the suppressor off.

INCIDENT

Approximately 20 minutes after turning the computer off, the consumer smelled an electrical burning-type odor. He went back into the house and found smoke and a 1 foot high flame coming from the surge suppressor.

POST-INCIDENT

The complainant had saxophone glue stored next to the suppressor, and the glue ignited in the incident. The consumer used his jacket to smother the flames. He stated that the on/off switch was the most badly damaged area on the surge suppressor. He believes the fire started in this area. There were no injuries in the incident, but the consumer stated that he did not feel well after the incident.

The complainant contacted the suppressor manufacturer by phone (exact date unknown). He spoke with a customer service representative. The representative requested the consumer return his unit to the firm, so they could examine it. He was very surprised when he received a new unit from the manufacturer the following day. His unit had a two year warranty, and the warranty had expired three months prior to the incident. The consumer packaged his suppressor for its return to the manufacturer, leaving the battery inside.

010626CCC1697

The consumer phoned CPSC to report the incident. The CPSC representative requested information about the unit, the complainant removed the unit from the packaging. At this time, the unit ignited again. The consumer then removed the battery from the unit before shipping it back to the manufacturer. The complainant was interviewed for this report in early July 2001.

The consumer has been using the replacement unit. He stated that the replacement surge suppressor has been functioning normally. The new unit appears to be identical (on the outside) to the old unit.

The consumer requested that his name not be release with the report. An Authorization for Release of Name Form was sent to the consumer, but it has not yet been received.

SAMPLE COLLECTED

The sample was returned to the manufacturer and not available for collection.

PRODUCT IDENTIFICATION

The product is a battery backup surge suppressor manufactured by: American Power Conversion, 132 Fairground Road, West Kingston, RI 02892 The consumer purchased the suppressor at: Staples, Route 1, New Brunswick, NJ

The product is a surge suppressor and battery back up unit. It is called an uninterruptible power supply (UPS). It has three electrical outlets in it: Two of the outlets are power outage protectors, and the third is just surge suppressed. The unit has a "phone in" and "phone out" outlet protect the phone line. The unit states in part, "***APC***BACK-UPS-500***."

PRODUCT STANDARDS

This product is marked as UL Listed 42C2, E95463. Manufacturer website states that unit is UL and CSA approved.

ATTACHMENTS

Exhibit 1 – Page from Staples Catalog with Photograph of Unit Exhibit 2 – Information Regarding UPS Unit from Manufacturer Web Page




Exhibit 1.1 Copy of Staples Catalog Page with Photograph of Unit IDI #010626CCC1697




Exhibit 1.2 Close Up of Unit IDI #010626CCC1697

APC/Back-UPS - Product Information

Legendary Reliability E United States	НОМЕ		SEARCH	SII SITENAP SUPPORT		ew cart 3 - Log in Change country SELECTORS
Products >> UPS >> S	ackup	2	CALLS IN			
Product Information Model Information Features & Benefits Product Enhancements Service Programs Runtime Chart Product Literature (.pdf) Press Releases Customer References Back-UPS®					APC	

Exhibita

Reliable power protection for office and home office computers

The effects of power problems include keyboard lockup, complete data loss, hardware degradation, damaged motherboards, and more, making downtime inevitable. An APC Back-UPS instantly switches your computer to emergency battery backup power and allows you to work through brief power outages or to shut down your system in the event of an extended outage. High-performance surge suppression protects your computer from electrical noise and damaging power surges - even lightning.

Features & Benefits

Protection

Uninterruptible Power	Protects your data by supplying battery backup when power fails.
Lightning and Surge Protection	Shields hardware from damage.
Easy Overload Recovery	Push-button circuit breaker instead of a standard fuse, eliminates the need to return the unit to the factory for service.
Multipath Protection	With dedicated outlets for computer, monitor and peripherals everything is safe from the threat of bad power.
Internet Ready: Protection for Fax/Modem Connection	Protects internal and external modems, your motherboard and other system components with fax/modem line surge protection. (APC Back- UPS 500 and APC Back-UPS 650 models only)
Performance	
Performance User-renewable UPS System	With normal use, a UPS battery will last three to six years. APC's renewable UPS system eliminates the need for factory service and loss of protection by letting you replace batteries for a fraction of the cost of a new UPS.
User-renewable UPS	renewable UPS system eliminates the need for factory service and loss of protection by letting you replace batteries for a fraction of the cost of a new
User-renewable UPS System	renewable UPS system eliminates the need for factory service and loss of protection by letting you replace batteries for a fraction of the cost of a new UPS.
User-renewable UPS System Surge-only outlets BlockSafe™ Outlets/Cord	renewable UPS system eliminates the need for factory service and loss of protection by letting you replace batteries for a fraction of the cost of a new UPS. Are always on for convenience Accommodate even the largest transformer blocks without covering other

Back-UPS	management soltware section of the tegritional specifications for detailed information by part number.
Diagnostics	
Site Wiring Fault Indicator	Immediately warns you of wiring problems like improper grounds that could cause shocks or prevent the UPS from adequately suppressing surges. (120V units only)
Audible Alarms	Actively let you know if the unit is on battery, if the battery is low, or if there is an overload condition.
Warranty & Approvals	
APC "Best in Class" Longest Runtime Guarantee	APC Back-UPS will provide runtime which meets or exceeds that of any same VA UPS for desktop PC applications or your money back (<u>click here</u> <u>for details)</u> .
\$25,000 Lifetime Equipment Protection - Even Covers Lightning!	APC is the only manufacturer that guarantees its products will protect your properly connected equipment from lightning strikes for life. Should surge damage occur, APC will repair or replace up to \$25,000 of your equipment (valid in US and Canada, <u>click here for details)</u> .
Two-Year Comprehensive Product Warranty	All APC UPS products come with a comprehensive two-year warranty which covers all parts and labor, even those we don't make ourselves, like the battery.
Industry Approvals	UL & CSA approvals mean a safe, reliable solution to power problems.

Copyright @ American Power Conversion Corp., all rights reserved.

Rome | Products | <u>Support</u> | <u>Services</u> | <u>Selectors</u> <u>Shop APC | Contact | Search | Site Map</u>

Privacy Policy

Back-UPS Back-UPS 350, BK350J, BK350 Back-UPS 500, BK500JS, BK500 Back-UPS 300, BK300 Back-UPS 500, BK500M, BK650 Back-UPS 300, BK300MI, BK300 Back-UPS 500, BK500IACH Back-UPS 500, BK500MI Back-UPS 650, BK330MI, BK650

Task No.: 010626CCC1697

STATUS OF MISSING DOCUMENT

The purpose of this record is to notify the reader that the following document(s), which is/are missing from this report, will not be collected.

.

C

1. Authorization for Release	e of iname form from th	<u>ne consumer</u>	
2			
3.	t.		

...

The investigator indicates in the report that he/she requested a copy of the above listed document(s), but the document(s) was/were not yet available when the investigation report was completed. The investigator intended to forward the document(s) for attachment to this report when the requested material was obtained.

The investigator has made numerous attempts, since the original request, to collect a copy of the requested document(s) but has not been successful. Because of the problems associated with the collection of this material and our limited investigation resources, no additional efforts will be made to collect the missing document(s).

We apologize for any inconvenience the missing data may cause you.

D 1

A 11 1 17 17 17

Date: October 5, 2001	Investigator No.: 9062
Regional Office: FOER	Supervisor No.:8930



Ann De Temple Director, National Injury Information Clearinghouse Consumer Products Safety Commission Washington, D.C. 20207

RE:010626CCC1617

VIA FEDEX

March 7, 2002

Dear Ms. De Temple:

Thank you for your letter dated January 31, 2002 regarding an incident allegedly involving one our products. To date and to the best of our knowledge, our claims department has not been notified of any claim or complaint by the individuals involved. Therefore, we cannot comment until we are notified of the existence and nature of the incident by the persons involved and provided further information with which to conduct an analysis.

American Power Conversion Corporation takes the design and manufacture of its products extremely seriously. We appreciate the Consumer Products Safety Commission contacting us regarding this matter. If there is anything else we can do, please do not besitate to contact me directly at (401) 789-5735 x2255.

Once again, thank you for your letter.

Verv_truly_yours.

Peter Wexler Senior Counsel

CONSUMER PRODUCT INCIDENT REPORT	CONSUMER	PRODUCT	INCIDENT	REPORT
----------------------------------	----------	---------	----------	--------

Region: EASTERN

1.NAME OF RESPONDENT		2. PHONE NO. (HOME)	(WORK)	
Robert Roper		978-544-8480	same	
3.STREET ADDRESS		4.CITY	ST	ZIPCODE
P.O. Box 873		Wendell	MA	01379
4a.EMAIL ADDRESS:	broper99@prodogy.net			

5.DESCRIBE INCIDENT OR HAZARD, INCLUDING DATA ON INJURIES

The product is used as a back up power provider for a computer. The power suppressor was plugged into an heavy duty extension - cont -

6. DATE OF INCIDENT(S) 06/06/2001 9.DESCRIPTION OF electric uninterru	AGE/SE AND DI none	SCRIBE INJURY				RESPO	ATIONSHIP	
11.MFR/DISTRIBUT American Powe 132 Fairground West Kingston 800-800-4272 unknown	er Convers I Rd.	ion	ISSUE 3 06/18/200	8	13.DEALER'S Staples Route 1	K-UPS-500 NAME, ADI	DRESS & PHON	NE
14.WAS THE PRODU OR MODIFIED? IF YES, BEFO DESCRIBE: damaged: see	YE DRE OR AF		ENT?	<u> </u>	PRODUCT PUR DATE PURCH DOES PRODUC IF SO, NOTE UNKNOWN	T HAVE WAI	NEW 3/1999 RNING LABEL:	AGE 2 yr.2mos
17.HAVE YOU CONTACTED THE MANUFACTURER?18.IS THE PROP YES YES IF NOT, DO YOU PLAN TO CONTACT THEM?				STILL AVAID	LABLE?		19.MAY WE USE YOUR NAME WITH THIS REPORT? NO	
			FOR ADMIN	ISTR	ATION USE			
20.DATE RECEIVED 06/15/2001)	21.RECEIVED B	L.RECEIVED BY (NAME & OFFICE) Nar/HL			22. document no. H0160246A		
23.FOLLOW-UP ACT	TION					24. PRODUC 0557	CT CODE(S)	
25.DISTRIBUTION			26.ENDORS		s name & ti: /2001	TLE		

Narrative Continued

H0160246A

cord. Plugged into the same extension cord were an alarm clock radio, computer, boom box, speaker system, printer, phone, computer answering system, 41 watt light bulb and a clock. The only items turned on at he time of the incident were the computer's answering machine along with clock radio. The power suppressor is on continuously.

Consumer turned on computer to set up a program, but decided to turn it back off. 20 minutes later, while consumer was outside his home, he smelled an electrical burning type odor. Consumer rushed back inside and saw smoke along with 1' high flames coming from the surge suppressor. Consumer extinguished flames by smothering them with his jacket. The circuit breaker was tripped and there was no need to cut off the power to the unit.

6/2001 Consumer called and explained incident to manufacturer's rep. (name unknown) who asked consumer to send the surge suppressor back to manufacturer for testing. Rep. then offered to send new, identical replacement unit; consumer accepted offer.

Consumer received new unit. Consumer then packaged the old one to be sent back to manufacturer along with its battery.

While taking this report from consumer the packaged unit caught fire while consumer tried to read the UL listing number.

Unit's UL listing number is 42C2, E95463.

There was and estimated \$500 in damage due to the fire.

Distributor Phone #:

CPSC Source: DIRECTORY ASSIS.

H0160246A

T-38

If you have any changes, additions, or comments you wish to make concerning your attached report, please make them in the space below.

power) switch, the most damaged area. Suitely was , destroyed.

I confirm that the information in the attached report (including any changes, additions, or comments I have made) is accurate to the best of my knowledge and belief.



I request that you do not release my name.



You may release my name to the manufacturer but I request that you not release it to the general public.

You may release my name to the manufacturer and to the public.

1. Task Number 030710CCN0706			2. Investigator's ID WI			EPIDEMIOLOGIC		
3. Office Code	4. Date of Accid		5. Date Initiated			INVESTIGATION		
830	YR MO DA 2003 06 02	·	YR MO DAY 2003 07 10			REPORT		
6. Synopsis of Accide	ent or Complaint		UPC					
When he unplugged up and no power to	d the unit from the the computer. The ne wall outlet, it sta	wall outlet, l e complaina	he found the UPS was	not work puter fror nediately MER COM	ing as the m the UP y unplugg MENTS:Y OVERRI EXCISIONS/FO Revisions	ESNO LED:XATTACHED		
7. Location (Home, So 1 - HOME	chool, etc)		8. City			9. State		
10A. First Product		10B Trad	MIDDLETON			WI 10C. Model Number		
557 - Computers (ed	quipment And Elec		10B. Trade/Brand Name APC			BE350C		
132 Fairgro	I POWER CONVER bunds Road n, RI 02892		e/Brand Name			11C. Model Number		
0 11D. Manufacturer Na NONE	ame and Address	NONE				NONE		
12. Age of Victim 45	13. Sex 1 - Male		14. Disposition 0 - No Injury			15. Injury Diagno 70 - No Injury		Injury Diagnosis 0 - No Injury
16. Body Part(s) Involved 99 - NO INJURY	17. Respond		18. Type of Inves	(Operationa		Time Spent (Operational / Travel) 2.5 / 2.5		
20. Attachment(s) 9 - Multiple Attachme		1. Case So 07 - Consu	urce mer Complaint	22. Sample Collection Number 038305727				
23. Permission to Disc Yes	close Name (Non N	IEISS Case	s Only) Verbal					
24. Review Date 08/11/2003	25. Reviewed By 9068	/		26. Reg Eric B.		ice Director		
27. Distribution Moro, Robert E.; Poole, Georgia F.				28. Source Document Number 10370121A				

CPSC FORM 182 (12/96) Approved for use through 07/31/2003 OMB NO. 30410029

.

٠

,

03082

IDI 030710CCN0706

SUMMARY

The complainant decided to test his year-and-a- half-old uninterruptible power supply (UPS) device for his computer. When he unplugged the unit from the wall outlet, he found the UPS was not working as there was no battery back up and no power to the computer. The complainant unplugged the computer from the UPS and when he plugged the UPS back into the wall outlet, it started to smoke. The consumer immediately unplugged the UPS and prevented any injury or damage.

PRE-INCIDENT

On November 23, 2003 the complainant purchased an APC uninterruptible power supply, Battery Backup 350VA, Model BE350c from Circuit City in Madison, WI for approximately \$60.00. Following and attached as Exhibit "A" is a picture of this device.



The complainant was familiar with these devices, as he has used them in the past. However, he read the owner's manual prior to use. Attached as Exhibit "B" is a copy of the owner's manual for the UPS.

The complainant first plugged the UPS device into an outlet. He then plugged in a Gateway PS-100 computer system with monitor into the device along with a Panasonic answering machine, model KXTC1890B. The battery back up function of the device was not used much during the six months prior to the incident. The complainant used the computer on average one hour a month. The complainant noted that his house had been equipped with a whole house surge protector, reducing the probability of surges to any outlets in the house during a storm.

INCIDENT

Sometime in the last week of May or first week of June 2003 the complainant decided to hook up his laptop computer, a Toshiba 610 C-T, to the device and disconnected his Gateway computer. He then decided that he wanted to test out the backup function of the APC Back-Up UPS system. In addition to the Toshiba computer, he had his answering machine plugged into the unit as well. He first unplugged the unit from the outlet. He then checked his computer and saw that all power was cut from the laptop unit. This should not have happened if the back-up system was

IDI 030710CCN0706

-2-

working. He disconnected his answering machine and computer from the unit. He then plugged the unit back into the outlet, with nothing connected to it.

Within seconds, the complainant noticed a smell of burning plastic and saw that the UPS unit was smoking from the plugs. He believes the smoke was coming from the middle or innermost plugs on the unit. The complainant then unplugged the unit from the outlet and the smoke stopped. He monitored it for a few minutes, and saw that no fire had started and discontinued use.

POST-INCIDENT

On June 3, 2003 he contacted APC by telephone and spoke with a Renee in Tech Support. He explained what happened and she said that she would send a replacement. This tech representative stated that the product could have become defective if hit by a surge during a storm. The complainant told her this was unlikely, as his house was equipped with a whole house surge protector.

On July 8, 2003 the complainant contacted the Middleton Fire Department to see if they could evaluate the fire hazard of the product. The fire department responded that they could not evaluate the product and referred him to the U.S. Consumer Product Safety Commission (CPSC). On this same date, the complainant went on the Internet, found the website for CPSC and filed a complaint, which has prompted this follow up investigation.

This investigator contacted the complainant on July 10, 2003 and set up an on-site interview for July 16th. At the interview, the complainant advised that he had called APC again to see if he could turn the product over to CPSC and spoke with Todd, a supervisor in Tech Support. The supervisor told him that APC would prefer to get the product back to analyze and solve any problems, but if he wanted to turn it over to CPSC that was fine. This investigator collected the UPS from the complainant and later forwarded it to the Warehouse pending further review by Compliance.

PRODUCT IDENTIFICATION

The uniterruptible power supply is an APC Back-UPS ES Series Battery Backup 350VA 200 Watts, and Model BE350c. The UPS is charcoal gray in color with red and white lettering on the front. The front of the UPS has three, 3-pronged plug outlets on both sides. The UPS was manufactured by:

American Power Conversion 132 Fairgrounds Road West Kingston, RI 02892 (401)789-5735.

IDI 030710CCN0706

Labeling

On the front of the power supply is silver lettering which reads:

Battery Backup plus (lighting bolt symbol) Surge Protection Back-UPS ES 350 (lighting bold symbol) Surge Protection

APC (in red lettering) www.apc.com (in silver lettering)

On the lower left corner on front of power supply:

Power On, with an indicator light and button.

On back side of power supply, molded into plastic:

APC www.apc.com

Output model 350: 120V~, 2.9A, 60Hz, 200W Output model 500: 120V~, 4.2A, 60Hz, 300W Total Output Current: 12A

FCC Tested to comply with FCC Standards including Parts 15 & 68 FCC Reg. No. 1XHUSA-25571-XP-N Ringer Equivalence: 0.0

C UL® Listed 42C2 E95463

CAUTION: Risk of electrical shock, do not remove cover. No user serviceable parts inside. Refer servicing to qualified service personnel. For use in a controlled environment. Refer to manual for environmental conditions.

NOTICE:

The output of this device is not sinusoidal. It has a total harmonic distortion of 45% and a maximum single harmonic of 35%.

-3-

1DI 030710CCN0706

White label/sticker on the back of the power supply:

Made in Philippines (Laguna) Barcode BE350C Barcode NB0138310452

On back cover molded into plastic:

Contains sealed lead acid battery. Must be recycled or disposed of properly.

On back cover, on battery cover in silver lettering:

REMOVE SCREW TO ACCESS BATTERY

The black power cord has a 3-pronged plug. The lettering on the cord is as follows:

(UL) SJT E94024 AWG16X3C VW-1 105(degree symbol)C CHUNG KWANG CSA TYPE SJT LL65965 AWG16X3C 105(degree symbol)C FT2 544001

WARNINGS

Warnings & Cautions listed in the Important Safety Instructions of the owner's manual:

Electrical Safety

CAUTION: To reduce the risk of fire, connect only to a circuit provided with a 20 Amp maximum branch circuit overcurrent protection in accordance with the National Electrical Code ANSI?NFPA. Equipment must be connected to a grounded outlet. The equipment must be connected to a socket outlet that is in close proximity to the unit and is easily accessible.

CAUTION! Deenergizing Safety

If the equipment has an internal energy source (the battery), the output may be energized when the unit is not connected to an AC power outlet.

To deenerize pluggable equipment: first press the Off button for more than one second to switch the equipment off. Next disconnect the equipment from the AC power outlet. Finally, disconnect the battery.

To deenergize permanently wired equipment: set the power switch to standby. Next set the AC circuit breaker to standby. Then disconnect the batteries (including any expansion units). Finally, disconnect the AC power from the building power supply.

-4-

Pluggable equipment includes a protective earth conductor which carries the leakage current from the load devices (computer equipment). Total leakage current must not exceed 3.5 mA.

Use of this equipment in life support applications where failure of this equipment can reasonably be expected to cause the failure of the life support equipment or to significantly effect its safety or effectiveness is not recommended.

WARNING! Battery Safety

This equipment contains potentially hazardous voltages. Do not attempt to disassemble the unit. The only exception is for equipment containing batteries. Battery replacement using the procedures below is permissible. Except for the battery, the unit contains no user serviceable parts. Repairs are performed only by factory trained service personnel.

CAUTION: Do not dispose of batteries in a fire. The batteries may explode. CAUTION: Do not open or mutilate batteries. They contain an electrolyte which is toxic and harmful to the skin and eyes.

CAUTION: To avoid personal injury due to energy hazard, remove wrist watches and jewelry such as rings when replacing the batteries. Use tools with insulated handles. CAUTION: Replace batteries with the same number and type of batteries as originally installed in the equipment.

APPLICABLE STANDARDS

It is unknown if the manufacturer claims this product is in conformance with any voluntary industry standards that might apply to such products. However, printed on the unit is the following information:

C UL® Listed 42C2 E95463

ATTACHMENTS

Exhibit "A" – Picture of the UPS device


Exhibit "B" - Owners Manual / Safety Instructions

Exhibit "C" – Receipt for Sample


Exhibit "D" – Sample Collection Report - #03-830-5727


Exhibit "E" - Authorization to Release Name form


Exhibit "F" – Contact List



IDI 030710CCN0706 - Exhibit "A" APC Back-UPS ES Series Battery Backup 350VA 200 Watts, Model BE350c







Status Indications

The Back-UPS ES indicates operating status using a combination of visual and audible indicators.

Status	Visual Indications	Audible Indication	Alarm Terminates When	
On Line - UPS is supplying conditioned utility power to the load	Power On LED - ON	None	n/a	
On Battery - UPS is supplying battery power to the load connected to the Battery outlets	Power On LED - ON (off during beep)	Beeping 4 times every 30 seconds	UPS transfers back to On Line operation, or when UPS is turned off.	
Low Battery Warning - UPS is supplying battery power to the load connected to the Battery outlets and the battery is near exhuastion	Power On LED - Flashing	Rapid beeping (one second intervals)	UPS transfers back to On Line operation, or when UPS is turned off.	
Replace Battery - Battery needs to be checked and/or replaced, or battery is not connected	Power On LED - Flashing	Constant tone	UPS turned off with the power switch.	
Overload Shutdown - During On Battery operation a battery power supplied outlet overload was detected.	Power On LED - OFF	Constant tone	UPS turned off with the power switch.	
Sleep Mode - During On Battery operation the battery power has been completely exhuasted and the UPS is waiting for utility power to return to normal.	Power On LED - OFF	Beeping once every 4 seconds	UPS transfers back to On Line operation, or when UPS is turned off.	
Building Wiring Fault - Your building wiring presents a shock hazard that should be corrected by a licensed electrician.	Building Winng Fault LED (red) - ON	None	UPS is unplugged, or plugged into a properly wired outlet.	

See the Troubleshooting section for additional assistance.

990-9151A Revision 2 Copyright© 2001 American Power Conversion Corp.

an her overchulcolus.

Power On and Install Software

> APC, Back-UPS and PowerChute are registered trademarks of American Power Conversion Corp. All other trademarks are property of their respective owners.

Troubleshooting

Use the table below to solve minor Back-UPS ES installation or operation problems. Consult APC Online Technical Support or call APC Technical Support for assistance with problems that cannot be resolved using the table below:

 \sim

Problem	Probable Cause	Solution
No power available at the Surge Protection outlets.	The will portal Surge Protection outlets have been overloaded. Utility power not available at the wall outlet.	outlet Reduce the amount of equipment plugged into Surge Protection outlets. Ensure that the fuse or circuit breaker for the outlet is not tripped, and that the wall switch controlling the outlet (if any) is in the ON position.
c onfrecter regroup reordos es poveis	Equipment is concerted to the Surge Protection Sources The Back OP SES is portfolded. Power Store piles software has deformed to all the winklue (Broovie failure PT) The Back UP SES indicate the deformed to all the winklue (Broovie failure PT) Some temporary press to expect pil the steps.	Ensine that the equipment was want to stay powered during a power relaters in a plugged into the Battery Backup plus Sorge Protection outlets end Notaties and Protection outlets and verificading during the equipment plugged and the oblights of the unit are not overfoading the capacity of the unit. The end verificading come of the equipment and see of the problem conflictes at the problem of the Backup S ES is operating normally. The Backup S ES is operating normally at the Backup S ES is operating normally. Allowing the equipment are not overfoading to the backup S ES is operating normally. The analytic sector of the equipment and sector the equipment of the analytic sector of the equipment of the equipment of the analytic sector of the equipment of the analytic sector of the equipment
The On Line indicator is lit and the Back- UPS ES is beeping four times every 30 seconds.	The Back-UPS ES may require scripts. The Back-UPS ES is using battery.	Contact ATC Technical Support for furtige produces doming The Back-UPS ES is operating normally and using battery power. Once On Battery, you should save your current work, power down your equipment, and turn the unit OFF. Once normal power is restored, you may turn the unit back ON and power your equipment.
Building Wiring Fault indicator is lit.	Battery capacity stownabout 2 minutes on as vernarung, Your building wiring presents a shock hazard. Using the Back-UPS with this condition will void the warranty.	The Back DPS ES is about to should reach allow pattery charge conditions when a the unit beeps once every second the battery that about 2 minutes of power stremaining. Immediately power down your computer and furt the unit CPF. When the point power fermaining is a power stremaining is a power stremaining in mediately power down your computer and furt the unit CPF. When the point power fermaining is a power fermion of the power stremaining is a power stremaining in the unit of the unit of the power stremaining is a power stremaining in the unit of the unit of the power stremaining is a power stremaining in the unit of the u
	an reposition is for unit enhanged. Idlander vit mean begend or to some interview in the source of t	Allow the unErocharge by leaving it/plugged intrathe with Enterst 10 hours and a solution vages, the antoint on running excitable with decrease y or can replace the battery by ordering one at www.aoc.com Betterges also age numericable if the Batery by ordering one at www.aoc.com Betterges also age numericable if the Back UPS ES is placed near excessive hours at a

Specifications



Order Replacement Battery

Replace with an APC qualified battery. Replacement batteries can be ordered from www.apc.com (valid credit card required). Have your Back-UPS ES model number available when ordering. Your model number can be found on the bottom of the unit

Output	UPS Capacity (3 outlets)	350 VA / 200 W	500 VA / 300 W	
	Surge Capacity (6 outlets)	12 Amps (including UPS output)		
	Voltage On Battery	115 Vrms <u>+</u> 8% (step-approximated sine wave)		
1	Frequency - On Battery	60 Hz ± 1 Hz		
	Transfer Time	5 ms typical,	8 ms maximum	
Protection and Filter	AC Surge Protection	Full time,	375 joules	
	Telephone Surge Protection	Single lir	ne (2-wire)	
	EMI/RFI Filter	Full	l time	
	AC Input	Resettable of	circuit breaker	
Battery	Туре	Sealed, maintena	ance-free lead acid	
	Average Life	2 - 4 years depending on the number of discharg cycles and environmental temperature		
Physical	Net Weight	9.20 lb. (4,18 kg.)	13.25 lb. (6.02 kg.)	
	Size	3.3" (H) x 10.9" (W) x 6.9" (D) (8.382 x 27.686 x 17.526 cm)		
	Operating Temperature	+32°F to 104°	°F (0°C to 40°C)	
	Storage Temperature	+5°F to 113°F	(-15°C to 45°C)	
	Operating Relative Humidity	0 to 95% no	n-condensing	
	Operating Elevation	0 to 10,000 ft (3 to 3,000m)		
Safety/Regulatory	Safety Approvals	UL 1778 listed, cUL certified per CSA standard C22.2 No. 107.1		
	EMC Compliance	FCC part 68, FCC part 15 Class B Notice: This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.		

procedure is to replace the original unit with a factory reconditioned unit. Customers who must have the original unit back due to assigned asset tags and set depreciation schedules must declare such a need at first contact with APC Technical Support. APC will ship the replacement unit once the defective unit is received by the repair department or cross-ship upon the provision of a valid credit card number. The customer pays for shipping to APC, and APC pays ground freight transportation costs back to the customer.

Service

Please DO NOT RETURN Back-UPS ES to the place of purchase under any circumstances.

1. Consult the Troubleshooting section to eliminate common problems.

2. Verify the battery is connected (see *Connect Battery*) and that the Circuit Breaker is not tripped (see *Troubleshooting* section).

If you still have problems or questions, please contact APC via the internet or at one of the phone numbers listed below.

3. Before contacting APC, please be sure to record the date purchased, UPS model, and serial number (on bottom of unit).

4. Be prepared to troubleshoot the problem over the telephone with a Technical Support Representative. If this is not successful, the representative will issue a Return Material Authorization Number (RMA#) and a shipping address.

Pack the unit in its original packaging. If the original packaging is not available, ask APC Technical Support about obtaining a new set. Pack the unit properly to avoid damage in transit. Never use foam beads for packaging. Damage sustained in transit is not covered under warranty (insuring the package for full value is recommended).

8. Write the RMA# on the outside of the package.

9. Return the unit by insured carrier to the address given to you by APC Technical Support.

APC Contact Information

Online Technical Support	http://support.apc.com
Web Site	www.apc.com
USA/Canada	1.800.800.4272
Mexico	52.292.0253 / 52.292.0255
Brazil	. 0800.12.72.1
Worldwide	+1.401.789.5735



Safety

IMPORTANT SAFETY INSTRUCTIONS - SAVE THIS GUIDE

This Safety Guide contains important instructions that should be followed during installation and maintenance of the APC equipment and batteries. It is intended for APC customers who setup, install, relocate, or maintain APC equipment.

This equipment is intended for installation in a temperature-controlled indoor area (see the User's Manual for exact temperature range), free of conductive contaminants.

Electrical Safety

CAUTION: To reduce the risk of fire, connect only to a circuit provided with a 20 Amp maximum branch circuit overcurrent protection in accordance with the National Electrical Code ANSI/NFPA. Equipment must be connected to a grounded outlet. The equipment must be connected to a socket outlet that is in close proximity to the unit and is easily accessible.

CAUTION! Deenergizing Safety

- If the equipment has an internal energy source (the battery), the output may be energized when the unit is not connected to an AC power outlet.
- To deenergize pluggable equipment: first press the Off button for more than one second to switch the equipment off. Next disconnect the equipment from the AC power outlet. Finally, disconnect the battery.
- To deenergize permanently wired equipment: set the power switch to standby \bigcirc . Next set the AC circuit breaker to standby \bigcirc . Then disconnect the batteries (including any expansion units). Finally, disconnect the AC power from the building power supply.
- Pluggable equipment includes a protective earth conductor which carries the leakage current from the load devices (computer equipment). Total leakage current must not exceed 3.5 mA.
- Use of this equipment in life support applications where failure of this equipment can reasonably be expected to cause the failure of the life support equipment or to
 significantly effect its safety or effectiveness is not recommended.

WARNING! Battery Safety

• This equipment contains potentially hazardous voltages. Do not attempt to disassemble the unit. The only exception is for equipment containing batteries. Battery replacement using the procedures below is permissible. Except for the battery, the unit contains no user serviceable parts. Repairs are performed only by factory trained service personnel.



Batteries must be recycled. Deliver the battery to an appropriate recycling facility or ship it to the supplier in the new battery's packing material. See the new battery instructions for more information.

- CAUTION: Do not dispose of batteries in a fire. The batteries may explode.
- CAUTION: Do not open or mutilate batteries. They contain an electrolyte which is toxic and harmful to the skin and eyes.
- CAUTION: To avoid personal injury due to energy hazard, remove wrist watches and jewelry such as rings when replacing the batteries. Use tools with insulated handles.
- CAUTION: Replace batteries with the same number and type of batteries as originally installed in the equipment.

Replacement and Recycling of Batteries

See your dealer or the User Manual for information on replacement battery kits and battery recycling.

FCC Requirements

- The Federal Communications Commission (FCC) has established rules which permit this device to be directly connected to the telephone network. Standardized jacks are used for these connections. This equipment should not be used on party lines or coin lines.
- If this device is malfunctioning, it may also be causing harm to the telephone network; this device should be disconnected until the source of the problem can be determined and until repair has been made. If this is not done, the telephone company may temporarily disconnect service.
- The telephone company may make changes in its technical operations and procedures; if such changes affect the compatibility or use of this device, the telephone company is required to give adequate notice of the changes.
- If the telephone company requests information on what equipment is connected to their lines inform them of:
 - a) The telephone number that this unit is connected to,
 - b) The ringer equivalence number [0.0]
 - c) The USOC jack required [RJ11C], and
 - d) The FCC Registration Number
- Items (b) and (d) are indicated on the label. The ringer equivalence number (REN) is used to determine how many devices can be connected to your telephone line. In most areas, the sum of the RENs of all devices on any one line should not exceed five (5.0). If too many devices are attached, they may not ring properly.

"Equipment Protection Policy"

Whereas,

APC is committed to innovative solutions to real customer problems through engineering excellence and...

Whereas, APC offers the most cost effective, reliable power protection product available...

Therefore,

let it be known to all parties, that from this day forward, American Power Conversion Corp. demonstrates its commitment to guarantee customer confidence and user peace of mind.

American Power Conversion will repair or replace any equipment damaged by a surge or spike while connected to an APC unit covered by the Equipment Protection Policy*



Rodger B. Do

132 Fairgrounds Road, West Kingston, RI 02892 *Certain legal restrictions apply, see reverse side for details.

Rodger B. Dowdell, Jr., CEO, President

American Power Conversion's "Equipment Protection Policy'

THIS POLICY IS NOT A WARRANTY. REFER TO THE APC LIMITED WARRANTY FOR INFORMATION CONCERNING THE WARRANTY FOR YOUR APC PRODUCT. THE LIMITATIONS AND CONDITIONS CONTAINED IN THIS POLICY DO NOT AFFECT THE TERMS OF THE WARRANTY

"Equipment Protection Policy"

In the 50 US States and Canada Only for 120 Volts Products US Territories not included

if your electronic equipment is damaged by power line transients on an AC power line (120 Volt - see Note 1 below) while directly and properly connected to a standard APC product covered by the Equipment Protection Policy ("connected equipment"), and if all of the remaining conditions specified below are met, APC will, at APC's sole option, during the period specified below only, replace the APC product and either (a) pay for the repair of the connected equipment or (b) reimburse you for the fair market value, as determined by the then current price list of the Orion Blue Book (or equivalent), of the connected equipment, in an amount not to exceed the dollar limits stated below, if APC determines that the damage was caused by the failure of the APC product to protect against power line transients and/or where applicable, data line, telephone or CATV line transients. Power line transients that APC products have been designed to protect against, as recognized by industry standards, include spikes and surges on AC power lines. Protection from telephone line transients applies only to APC products which offer modern or fax line protection, and in cases in which such protection is available. telephone service equipment must include a properly installed and operating "primary protection" device at the service entrance (such devices are normally added during telephone installation) in order to be covered for telephone line transients. Protection of CATV (Cable Television) connected equipment from transients applies only to APC products which offer such protection, and in such cases, the CATV service must be properly grounded according to the codes set forth in the National Electrical Code (NEC) in order to be covered for CATV transients. Protection from data line transients applies only to APC UPS products which offer data line protection. This policy OPS products which offer data line protection. This proto-does not apply to the APC ProtectNet products. If you own APC ProtectNet products, please refer to the Supplemental Equipment Protection Policy included with your ProtectNet products.

Data Recovery Policy

If data is lost from the hard drive- in the protected computer due to a malfunction of a property connected APC product, APC will, at its sole discretion, provide data recovery services from Ontrack® data recovery tabs. This warranty will be offered to customers to the extent commercially reasonable, as determined by APC at its sole discretion. Ontrack will make every commercially reasonable effort to retrieve customer data, however, due to the nature of data loss, recovery is not guaranteed. The data recovery warranty is available on all APC products mentioned in the chart that follows with the exception of APC's Basic and Personal SurgeArrest® models. Data recovery is limited to physical hard drives within protected computing equipment. Expressly excluded from this warranty are any type of external storage devices.

APC reserves the right to determine whether the damage to the connected equipment is due to APC product failure by requesting that damaged equipment be sent to APC for inspection. This policy is in excess of, and applies only to the extent necessary beyond, any coverage for the connected equipment provided by other sources, including, but not limited to, any manufacturer's warranty, extended warranty coverage and home owner's insurance.

Equipment Protection Policy Dollar and Period Limits

For customers that meet the qualifications and conditions set forth in this policy, APC will provide reimbursement (cost of repair or fair market value) during the period limits and up to the dollar limits stated as follows:

Product*	Specific Model**	Dollar Limit	Period***
Basic Surge	P6	\$10,000	Lifetime
Basic Surge	P7T10/P7T6/P10V2	\$25,000	Lifetime
Personal SurgeArrest		\$50,000	Lifetime
Professional SurgeArren	st .	\$75,000	Lifetime
Network SurgeArrest	•	\$100,000	Lifetime
Performance SurgeArre	st	\$100,000	Lifetime
SurgeArrest Notebook	PNote1	\$15,000	Lifetime
SurgeArrest Notebook	Pro PNotePro/PNotePr	3 \$75,000	Lifetime
PowerManager		\$100,000	Lifetime
Back-UPS ES		\$50,000	Lifetime
Back-UPS Office		\$75,000	Lifetime
Back-UPS VS		\$75,000	Lifetime
Back-UPS CS		\$100,000	Lifetime
Back-UPS	BK850MC	\$100,000	Lifetima
Back-UPS LS		\$150,000	Lifetime
Back-UPS Pro		\$150,000	Lifetime
Line-R		\$75,000	Lifetime
Smart-UPS		\$150,000	Lifetime
Matrix-UPS		\$150,000	Lifetime

* All X-option products are excluded

"If blank, then all products in that family are covered with the exception of X-Option products

"Lifetime period is the life of the product while owned by the original purchaser ("you" or "purchaser")

Eligibility for coverage under the Equipment Protection Policy:

1. You must register the product by returning to APC the warranty card provided with the product within 10 days of purchase. All information must be filled in, and you should retain a copy for your records.

2. All connected equipment must be UL or CSA approved. 3. The APC product must be plugged into properly wired and grounded outlets; no extension cords, edapters, other ground wires, or electrical connections may be used, with the sole exception of other standard

APC 120 Volt products. The installation must not include power protection products made by any manufacturer other than APC. The Installation must comply with all applicable electrical and safety codes set forth pursuant to the most current National Electrical Code (NEC).

4. Any claim under the Equipment Protection Policy must be made within 10 days of the date of alleged damage to the connected equipment.

5. The Equipment Protection Policy covers only standard APC 120 Volt products used in the 50 US States and/or Canada (US Territories not included).

on the APC product you are returning.

3. Pack the APC product in its original packaging (or request packing materials from APC if the packaging has been discarded). Enclose the completed Equipment Protection Policy claim form and a copy of your sales

4. Mark the EPP RMA number clearly on the outside of box.

5. Ship the product (one way shipping charges paid by you) to the address given by the APC representative

What is not covered under the Equipment Protection Policy:

DAMAGE TO ELECTRONIC EQUIPMENT RESULTING FROM TRANSIENTS ON DATA LINES IS NOT COVERED UNLESS THE UPS OR SURGE PRODUCT OFFERS SUCH PROTECTION.

2. Restoration of lost data and reinstallation of software are not covered.

3. This policy does not cover damage from a cause other than AC power line transients, except for damage due to data line, telephone line or CATV transients, which is covered only if the APC product offers such protection and the unit is properly utilized. In addition, the following are expressly excluded from coverage:

DAMAGE CAUSED BY FAILURE TO PROVIDE A SUITABLE INSTALLATION ENVIRONMENT FOR THE PRODUCT (INCLUDING, BUT NOT LIMITED TO, LACK OF A PROPER SAFETY GROUND).

5. Damage caused by the use of the APC product for purposes other than those for which it was designed.

Damage caused by accidents, or disasters such as fire, flood, or wind.

7. Damage caused by abuse, misuse, alteration, modification, or negligence.

8. This policy is null and void if, in APC's view, the APC product has been tampered with or altered in any way.

9. EXCEPT AS EXPRESSLY PROVIDED IN THIS POLICY, IN NO CASE SHALL APC BE LIABLE UNDER THE TERMS OF THIS POLICY FOR ANY DAMAGES WHATSOEVER, INCLUDING, BUT NOT LIMITED TO, DIRECT, INDIRECT, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR MULTIPLE DAMAGES ARISING OUT OF THE USE OF THE APC PRODUCT OR DAMAGE TO THE CONNECTED EQUIPMENT, REGARDLESS OF THE LEGAL THEORY ON WHICH SUCH CLAIM IS BASED, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE. SUCH DAMAGES INCLUDE, BUT ARE NOT LIMITED TO, LOSS OF PROFITS, LOSS OF SAVINGS OR REVENUE, LOSS OF USE OF THE APC PRODUCT OR THE CONNECTED EQUIPMENT OR ANY ASSOCIATED EQUIPMENT. LOSS OF SOFTWARE, COST OF CAPITAL, COST OF ANY SUBSTITUTE EQUIPMENT, FACILITIES OR SERVICES, DOWNTIME, THE CLAIMS OF THIRD PARTIES, INCLUDING CUSTOMERS, AND INJURY TO PROPERTY

Submitting an Equipment Protection Policy Claim:

1. If all of the conditions for coverage are satisfied, call the APC customer service department at (800) 800-4APC and obtain an EPP RMA (Equipment Protection Policy Returned Material Authorization) number. APC will forward to you an Equipment Protection Policy claim form, which must be completed and filed within 30 days.

2. Mark the Equipment Protection Policy RMA number

receipt for the APC product in box.

handling your claim.

6. APC will evaluate the product to determine its level of functionality, and will examine the product for evidence of damage from AC power line transients (data line, telephone line or CATV transients, If applicable), (A) If APC's evaluation provides no evidence of damage from power line transients (data line, telephone line or CATV translents, If applicable), APC will send to the customer (i) a report summarizing the tests performed and (ii) a rejection of claim notice. (B) If the APC product shows evidence of damage from power line transients (data line, telephone line or CATV transients, if applicable), APC will request that all connected equipment for which an Equipment Protection Policy claim has been submitted, be sent for evaluation to either APC or an authorized service center. If it is determined that the connected equipment has been damaged from AC power line transients (data line, telephone line or CATV transients, It applicable), APC will, In its discretion, either authorize you to have the equipment repaired or reimburse you for the fair market value of the damaged equipment; up to the dollar limits stated above. Please save the damaged connected equipment or all damaged parts.

7. If you are authorized by APC to have the connected equipment repaired, the repair must be performed at a service center that is authorized by the manufacturer of the connected equipment. APC reserves the right to contact the authorized service center directly to discuss repair costs and damage to the connected equipment to determine if it was caused by AC power line transients (data line, telephone line or CATV transients, if applicable) and the right to request that the service center forward the connected equipment or components of the connected equipment to APC for inspection. Please notify the service center to save all damaged parts.

8. APC will, after determining that the damage was caused by the failure of the APC product to protect against AC power line transients (data line, telephone line or CATV transients, if applicable), issue payment to you, in its sole discretion, for either costs of repair or the fair market value of the connected equipment, up to the dollar limits stated above. APC reserves the right to require you to transfer title and deliver the connected equipment to APC if it chooses to reimburse you for the fair market value of the connected equipment

9. Unless modified in a writing signed by APC and you, the terms of this policy are understood to be the complete and exclusive agreement between the parties, superseding all prior agreements, oral and written, and all other communications between the parties relating to the sub-ject matter of this agreement. No employee of APC or any other party is authorized to make any representations beyond those made in this agreement concerning the Equipment Protection Policy.



132 Fairgrounds Road West Kingston, RJ 92892 Tel. (800)800-4APC/(401)7895735/Fax: (401)7893730

Software Instruction Sheet

- PowerChute plus 5.2.0.3J for Windows NT/2000J User's Guide (PCWNTUGJ.PDF), Installation Guide (PCWNTIGJ.PDF), and Release Notes (PCWNTRNJ.PDF)
- PowerChute plus 5.0.2 for Windows 95/98/Me User's Guide (Pc98ug.Pdf), Installation Guide (Pc98ig.Pdf), and Release Notes (Pc98rn.Pdf)

Reading and Printing the PDF Documentation

After the Installation, to read any .pdf file provided on the CD-ROM, you must have Adobe Acrobat Reader[®] version 3.0 or above. To install Acrobat Reader, located in the CD-ROM's acrobat\install folder:

- For your English-language operating system, run ar40eng.exe
- For your Japanese-language operating system, run ar405jpn.exe

Note: The installation program installs online help files and, if you choose the **Typical** installation option, the PDF files. You can also simply copy the PDF files to your own machine, or reference them directly from the CD-ROM.

APC Product Support on Web Sites, E-Mail, and Telephone

Technical support for this or any other APC product is available at no charge. You can contact APC Technical Support in any of the following ways:

Use the APC web site.

2

- http://www.apcc.com (Corporate Headquarters). Connect by links to APC web pages for specific countries and regions, each of which provides technical support information.

- http:///www.apcc.com/support/. Submit technical support requests.

Contact a local or regional APC Technical Support Center by telephone or e-mail.

- For e-mail addresses and local, country-specific, technical support telephone numbers worldwide, choose a country from the **Change Country** drop-down list in the home page of APC's corporate web site, http://www.apcc.com, and then **Contact** from the header bar.

- For e-mail addresses and technical support telephone numbers of major APC regional technical support centers, use the following list:

APC Headquarters (U.S. and Canada)	1-800 800-4272 (toll free)
Latin America	+1 401-789-5735 (United States) apetchla@apec.com
Europe, Middle East, Africa	+353 91 702020 (Ircland) apceurtech@apcc.com
Japan	03 5434 2021 jsupport@apcc.com

Contact the APC representative or other distributor from whom you purchased your UPS or APC software application for information on how to obtain local technical support.

November 2000

2

Software Products

The CD-ROM — APC part number 991-0072B — contains three PowerChute[®] plus applications:

PowerChute plus 5.2.1 for Windows NT/ Windows 2000 (this is the English-language version) It can be used with the following operating systems:

Software Instruction Sheet

- Windows NT Server 4.0, or Windows NT Workstation 4.0, Service Pack 3 (or above).
- Windows 2000
- PowerChute plus 5.2.0.3J for Windows NTJ/ Windows 2000J (this is the Japanese-language version) It can be used with the following Japanese operating systems:
 - Windows NT Server 4.0J, Service Pack 6a, or Windows 2000J, or Windows 2000J, Service Pack 1
- PowerChute plus 5.0.2 for Windows 95/98/Me, which you can use with any version of Windows 95, Windows 98, or Windows Me.

Initial Installation Instructions

To begin installing PowerChute *plus* on your machine, perform the following steps:

- 1) See the Back-UPS Uninterruptible Power Supply User's Guide to install your Back-UPS.
- Use the cable that came with your UPS to connect the UPS serial port to a communications port on your computer (see http://www.apcc.com/support/faq.cfin#5 for information on which APC cable works with which UPS).

Note: Make a note about which communication (COM) port you use on your machine. You will need to identify this port during the software installation.

- 3) Place the installation CD-ROM in your machine. Allow some time for the "Welcome to APC's Software Products CD Browser" window to display.
 - Note: If your machine does not automatically open the installation program (the "Welcome to APC's Software Products CD Browser" window), run the setup.exe file in the CD-ROM's root directory.
- 4) Click the Continue arrows button and subsequently click Yes, I Agree after reading the agreement.
- 5) After clicking on your target Windows operating system NT/2000, NT/2000J, or 95/98/Me the available Release Notes and Installation Help files are listed under "View Documentation". Clicking a listed document launches the document viewer (Adobe Acrobat Reader[®]) and displays the document in Portable Document Format (PDF).
- 6) Please read both files in turn. To continue installing, click on PowerChute *plus* with the version number under the **Install PowerChute...** heading (above **View Documentation**).

PowerChute *plus* Documents

The acrobat/manuals folder on the CD has the following documents in portable document format (PDF):

PowerChute plus 5.2.1 for Windows NT/Windows 2000 User's Guide (PCWNTUG.PDF), Installation Guide (PCWNTIG.PDF), and Release Notes (PCWNTRN.PDF)

Property Receipt TR-GE-23 (1/96)	710CCN0706 - Exhibit "C" - Sample Receipt
Case/Docket No: 101 030710 CCI	STATE OF WISCONSIN
Date: <u>7/10/03</u>	Department of Agriculture
Voluntarily Released	Trade and Consumer Protection
Subpoena 🛛	2811 Agriculture Drive
Page of	P.O. Box 8911
	Madison, WI. 53708 - 8911

This will acknowledge that the following article(s) were obtained from Denald Gibboard

Address	s: <u>[0[02]</u>	Wood Circle East Middleton		Telephone: ()
NO.	ITEM	DESCRIPTION	QUANTITY	ARTICLE NAME
	i	Bettery berging 450 VA 2000115		
2		FREARC FACE-UPS 55 Sepres		
3				
4				
5				
6				
7				
8.				
9				
10				
12				
13				
14				······································
15				

RELINQUISHED BY (SIGNATURE)	RECEIVED BY (SIGNATURE)	DATE RELEASED	ITEM NUMBER	LAB NUMBER	PLACEMENT

I acknowledge the return of item no.(s)_____

on this	day of		, 19	, by

(Name of person returning item(s))

(Signed) _____

IDI 030710CCN0706 - Ex	hibit "C" -	Sample Rece	
U.S. CONSUMER PRODUCT SAFETY COMMISSION		SW.North H SW.North H 2/Sichd, W15	
2. NAME OF INDIVIOUAL REINEM	3. TITLE OF INDIVIDUA		4.DATE 7/24/03
S. FIRM NAME, OF Agriculture,			6. SAMPLE NUMBER
7. NUMBER AND STREET. 2811 ALIVICULLUT & Dir 9. SAMPLES COLLECTED (Describe fully, List lot, serial, mo	Mac		53.708
Model: Baltery, Previously C. Investigo Donal	o) of the Federal Hazardou S.C. 1194(c) and (d) and/o lifections made in connecti is is hereby acknowledged Back - C -jes/46 BE-35 Back 46 Back 46 ator Rej Id Gib	is Substances Act (15 U.S.C. 1270(t or Section 704(c) of the Federal F on with the Puison Prevention Pac Sections cited are quoted on the r 1PS -4isked 42 -6C -350VA 200Wa7 kby kby kan KaM	and/or Sec- bod Drug and kaging Act of everse side of 95463 4 4 4 4 4 4 4 4 4 4 4 5 5 6 8 7 5 4 6 3 6 7 5 4 6 3 6 7 5 4 6 3 6 7 5 7 5 4 6 3 7 5 7 5 7 5 7 6 7 5 7 7 7 7 7 7 7 7 7 7 7 7 7
10. SAMPLES a. AMOUNT RECEIVED FOR SAMPLE	11. SAMPLES WERE	12. COLL a. MANYE (Print or type)	
	11. SAMPLES WERE		

DI 030710CCN0706 - E	xhibit "D" -	Sample	Collectio	n Repoi
U.S. C	Consumer Product Sa)	
1. Sample Flag	2. Date Collected 7/16/03		and Number: 03	
4a. Product Name	4b Model	4c NEISS	5. Assignmen	It Number
BATTERY BACKUP	BE350C	.0557	030710CCN0)706
6. Complete for Import Samples		7. MIS	8. Hours	tivity 1
Port of Entry: Country of Origin:		31102		avel1
Entry No. and Date:		9a Home RO	9b Collecting	RO
Customs Contact:		FOER	FOCR	
10. Sample Cost 11. In \$0.00 \$10.00	voice Value of Lot	12	2. Size of Lot	Units unt
13. Manufacturer/Importer # AME250 14. SI AMERICAN POWER CONVERSION INC. 132 FAIRGRONDS WEST KINGSTON , RI 02	hipper/Foreign Manu	D0 66	5. Dealer/Import B DNALD GIBBARD - 27 WOOD CIRCLE DDLETON, WI 535	CONSUMER EAST
16. Supporting documents attached: Invoice No. and Date: Shipping Record and Date: Affidavit Signer's name, title and date:		Date Si	hipped:	
350VA, Model BE350c, Made E95463. The unit is gray 18. Reason for collection/analysis needed: Possible fire hazard. 19. Summary of Field Screening: None.	in color with	red and w		
	The sample wa The sample re	s turned or	ver to this our custody	CPSC
"03-830-5727	<u></u>	5727 Rosemary P	errizo	8/11/03
23a. Sample delivered to:	23b Dat	B 24. Report/R FOER	lecord Sent to:	
SAMP CUST VIA UPS 25. Laboratory/Office: LSE CRC				
	WHSE 2		r	
26. Remarks: Attachments: Sample recei	lpt and narrat	zive.		
27. Related Samples: None				
28a Collector's name/title:	4	lector's signature		
Rosemary Perrizo Investigator				
Rosemary Femzo investigator	Pa	semary E	engo	8/10/03



PRODUCT IDENTIFICATION

there are three, 3-pronged plug receptacles on the front.

METHOD OF COLLECTION

locked residences until later shipment to the sample custodian via UPS on 8/11/03. Sample was labeled and sealed in a shipping carton.

IDI 030710CCN0706 - Exhibit "E" - Authorization to Release Name



U.S. CONSUMER PRODUCT SAFETY COMMISSION WASHINGTON, DC 20207

U.S. CONSUMER PRODUCT SAFETY COMMISSION

AUTHORIZATION FOR RELEASE OF NAME

Thank you for assisting us in collecting information on a potential product safety problem. The U. S. Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety problems.

We routinely forward this information to manufacturers and distributors to inform them of the involvement of their product in an incident situation. We also give the information to others requesting information about specific products or hazards. Manufacturers may need the individual's name so that they can obtain additional information on the product or incident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name. If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.

🔁 YES

Dunela Selfeal (Signature)

7/16/03 (Date)

IDI 030710CCN0706 - Exhibit "F" - Contact List

.

Donald Gibbard – Complainant 6627 Wood Circle East Middleton, WI 53562 (608) 831-1876



Ann DeTemple Director United States Consumer Product Safety Commission National Injury Information Clearinghouse 4330 East West Highway Room 504 Bethesda, Maryland 20814

RE: 030701CCN0667, 030710CCN**G**06, H0370020A, H0370053A October 22, 2003

SENT VIA FEDEX

Dear Ms. DeTemple:

Thank you for your letter dated August 29, 2003 regarding the above referenced incidents allegedly involving our products. In regards to Claims #030710CCN0706, we did receive a report from the customer, but the customer has not returned the unit so that we may conduct a failure analysis. In regards to Claims #030710CCN0706, we did receive a report from the customer and have received and reviewed the unit. Our analysis to date indicates a external overvolatge event to the surge unit was the root cause of the unit failure. We have offered to replace the customer's unit. We have very little information regarding Claim #H0370053A and have not received the unit for evaluation, however, it is our understanding that a new unit was sent to the customer. Finally, we have not, to the best of our knowledge, receive any claims or information related to Claim # 030701CCN0667.

We appreciate the Consumer Products Safety Commission contacting us regarding these matters. Please contact us immediately if there are any further developments in any of these cases. If there is anything else we can do, please do not hesitate to contact me directly at (401) 789-5735 x2255.

Once again, thank you for your letter.

uly vours.

Peter Wexler Associate General Counsel American Power Conversion Corporation

American Power Conversion Corporation

APC's quality system is ISO 9002 certified

PO Bax 278	Call 401 789 5735
132 Fairgrounds Road	Fax 401 789 3710
West Kingston, RI 02892	Visit www.apcc.com
APC is an equal opportunity emplo	over which values workforce diversity

Estelle, Gerri B.

From:Cohn, Murray S.Sent:Wednesday, July 09, 2003 3:22 PMTo:Incident Reports: Emerging Hazards, Internet Incident Reports; Clearinghouse; HazardCc:Pucciarelli, Ellen MSubject:Internet Form Complaint - Doc #I0370121

7/8/2003 5:20:24 PM

Name = Donald W. Gibbard Address = 6627 Wood Circle East City = Middleton State = WI Zip = 53562-2834 Email = DonGib@Chorus.Net Telephone = 608-831-1876 Name of Victim = Victim's Address = Victim's City = Victim's State = Victim's Zip = Victim's Telephone = JUL 1 0 2003

166UE 41 -

Incident Description: Manufacturer's Brand Name: APC Type of Product: Uninterruptible Power Supply Product Model number and Serial number: Back-UPS ES 350VA Model BE350C Ser. # NB0138310452 Product Purchase Date: Nov. 23, 2001 Purchase Location: Circuit City, Madison, WI Product Description: 350 VA Battery Backup and Surge Suppressor. UPC Code 731304105831 Total Output Current: 12 Amps Color: Gray

Problem: This UPS was in use for about 6 months, but the equipment plugged into it was seldom powered on. In late May or early June of 2003, I decided to test the battery backup feature by unplugging the unit from the wall while a portable computer was running off the AC power running thru the UPS. When I unplugged the UPS from the wall, there was no battery backup. The power was cutoff to the portable computer. I unplugged the portable computer from the UPS and then plugged the UPS back into the wall outlet. The UPS began emitting smoke out of one of its electrical outlets. Once I noticed the smoke, I unplugged the UPS from the wall. I do not know what would have happened if I hadn't unplugged the UPS from the electrical outlet. I believe there was a good chance that it would have started on fire. At this point, I still have the UPS.

Victim's age at time of incident = Victim's sex = Date of incident = June 2003 Product involved = Uninterruptible Power Supply - Battery Backup & Surge Suppressor Product brand name/manufacturer = APC Place where manufactured (City and State) = West Warwick, Rhode Island Product involved still available = Yes Product model and serial number = Back-UPS ES 350VA Model BE350C Ser. # NB0138310452 Date product purchased = Nov. 23, 2001 Name Release = Release name to manufacturer only If you have any changes, additions, or comments you wish to make concerning your attached report, please make them in the space below.

I confirm that the information in the attached report (including any changes, additions, or comments I have made) is accurate to the best of my knowledge and belief.

Denuld W Silfart Signature 7/22/03 Data

.-

I request that you do not release my name.



....

You may release my name to the manufacturer but I request that you not release it to the general public.

You may release my name to the manufacturer and to the public.

I0370121

2

1. Task Number		·	2. Investigator's I	 †**		
020520CWE5005			8232	5	}	EPIDEMIOLOGIC
3. Office Code	4. Date of Acci YR MO DA 2002 03 (AY	5. Date Initiated YR MO DAY 2002 05 22			INVESTIGATION REPORT
6. Synopsis of Acciden						
A fire ignited inside a extinguished the fire owner returned the pi manufacturer would r	with a wet towel ower supply to t	. Fire damag he manufacto	ge was confined to urer and received a	the power replacent replacent do co	BR NOTII OCTOBIO CONTRACTION CONTRACTOR CONTRACTOR	PIED Sa made Stached Revisions pt requested
7. Location (Home, Sci	hool, etc)	<u> </u>	B. City		7	9. State
1 - HOME			MILWAUKIE			OR
10A. First Product 557 - Computers (equ		1	ie/Brand Name			10C. Model Number APC-650 VA
Hunt Valley, 11A. Second Product	POWER COMPA		ie/Brand Name		·	11C. Model Number
0		NONE				NONE
11D. Manufacturer Nat NONE	me and Address	5				
12. Age of Victim 0	13. Sex 1 - Male		14. Dispositi 0 - No Injun	1		5. Injury Diagnosis 70 • No Injury
16. Body Part(s) Involved 99 - NO INJURY	17. Respon 1 - Victim/	ident Complainant	18. Type of h 2 - Telepho	7		
20. Attachment(s) 0 - No Attachments		21. Case So 07 - Consu	ource Imer Complaint		22. Samp	Ne Collection Number
23. Permission to Disc Ves	lose Name (Non No	NEISS Case	əs Oniy)) Verbal			
24. Review Date 06/30/2002	25. Reviewed B320	Ву			Regional Of Ink J. Nave	fice Director
27. Distribution	erfard, George V				Source Doc 255003A	ument Number

٠

-

CPSC FORM 182 (12/96) Approved for use through 07/31/2003 OMB NO. 30 10029

.

٠

The owner was the respondent. The owner was interviewed by telephone on 6/24/02.

Pre-event

The event occurred in a single family home located in a suburban neighborhood. A married couple occupies the home. The husband has a personal computer in the home office. The he purchased a back-up power supply to prevent the loss of data if electrical power to the computer was interrupted.

The husband said that he purchased the back-up power supply new approximately three years before the event. He said that the back-up power supply is plugged directly into the standard wall outlet. He said that he plugged his computer and monitor into the back-up power supply.

The husband said that the computer and monitor were the only items plugged into the back-up power supply. He said that the computer was a homemade Pentium-4 unit. He said that the monitor was a 19-inch model. He said that he used the computer approximately 20 hours per week. He said that the computer equipment was turned off when not in use.

The husband said that there were no problems with the computer, monitor or back-up power supply before the event. He said that the back-up power supply was not damaged, altered or repaired before the event. He said that the battery in the back-up power supply was the original unit and did not require replacement before the event.

Event

The husband said that the computer and monitor were turned off. He said that his wife was home alone at the time of the event. He said that she was working in the basement and came up to the kitchen for a cup of coffee. He said that she heard the smoke alarm sounding an alarm. He said that she checked the house and found flames eight to ten inches tall coming from the air vent holes in the back-up power supply.

The husband said that his wife smothered the fire with a wet towel. He said that fire damage was confined to the back-up power supply. He said that electrical feedback from the power supply apparently damaged the computer CPU during the fire. No injuries were associated with the event.

Post Event

The husband reported the event to his local fire department but did not require emergency assistance. The fire department fire department did not investigate the incident. The fire department referred the husband to CPSC.

page 2

The husband returned the power supply to the manufacturer after the event. He said that the manufacturer provided a new back-up power supply and paid for damage to his computer. He said that the manufacturer refused to disclose the reason for the fire inside the original back-up power supply.

Product Identification

Manufacturer: American Power Company Hunt Valley, MD

Brand: APC

Model: APC-650 VA

The respondent provided the product identification information. The product is a backup power supply for computers. The respondent said that the product contains a battery and electrical sensor circuits. The respondent said that the product provides temporary power to allow a desktop computer to shut down without the loss of data in the event of a loss of electrical power. The respondent said that he returned the fire-damaged unit to the manufacturer. The unit was not available for examination at the time of this investigation.

Standards Information

Standards information was not available.

Attachments

None



Ann De Temple National Injury Information Clearinghouse Consumer Products Safety Commission 4330 East West Highway, Room 504 Bethesda, MD 20814

August 20, 2002

RE: 020520CWE5005

VIA FEDEX

Dear Ms. De Temple:

Thank you for your letter dated July 31, 2002 regarding an incident on March 1, 2002 involving an APC BK650 MC Uninterruptible Supply manufactured by APC around October 1998. APC was informed of the incident by $M_1^{(b)(6)}$ on March 27, 2002 and APC and $M_2^{(b)(6)}$ reached resolution satisfactory to $M_2^{(b)(6)}$ soon thereafter. APC did have the opportunity to physically examine the unit and has preliminarily concluded that this unit was subjected to an externally generated large power surge on the AC power line possibly generated by a lighting strike.

American Power Conversion Corporation takes the design and manufacture of its products extremely seriously. We appreciate the Consumer Products Safety Commission contacting us regarding this matter. If there is anything else we can do, please do not hesitate to contact me directly at (401) 789-5735 x2255.

Once again, thank you for your letter.

ours.

Peter Wexler Senior Counsel American Power Conversion Corporation

 American Power Conversion Corporation

 PO Box 278
 CaH 401 789 5735

 132 Fairgrounds Road
 Fax 401 789 3710

 Wast Kingston, RI 02892
 Visir www.apcc.com

 APC 4 an equal coportunity ampluyer which values workforce diversity.
 APC 3 quality system x /80 8002 corbined.

			<u>A- 1</u>	
	CONSUME	R PRODUCT INCI		DRT
Name of Respondent (b)(6)		<u> </u>	ıkie, OR 9	(Work) Zip Code 7222
Thre responding the back-up from the de	dent report ile the com power supp vice. He sa	puter equipment ly was in the st aid that the fir	-up power was turned andby mode e was disc	computer supply d off. He said that e and flames erupted covered at an carly ly. No injuries were ISSUE 35 MAY 2 9 2002
. Date of incident(s)	. If injury or near miss	obtain	A If victim diff	erent from respondent, provide
C3/02		scribe injury	Name'. Relationship:	
. Description of Produc			10. Brend Nan	
1. Manufacturer/Distribut American Por Hunt Valley	wer Co.	Phone .	12 Model, Sei APC-65 13 Denier's M not sta	0 VA ame, Address, & Phone
14. Was the product dam Yes X No	aged, repaired or mod If yes, before or a		15. Product pi Date	urchased New Used Age 3 yrs
<i>Describe:</i> Fire da	mage during	incident	If so, Note:	uct have warning inbels? Yes Na Ot Stated
17. Heve you contacted t Yes No X If not, Do you plan to cor Yes No X		18. Is the product still available Yes X No If not, its c	? Ilsposition	19. May we use your name with this report? Yes No X
		FOR ADMINISTRAT		
0. Date Received 3/28/02	1. Received by (Name) J. Burchysk	·	22. Document	Na 0255003A
23. Follow-Up Action		0E5005	24. Produce Co 0557	Dde(s)
25. Distribution	S a: Fo	26 Endorser's	Name & Title)

-

1. Task Number			2. In	vestigator's ID 9093			EPIDEMIOLOGIC
030123CNE7732							INVESTIGATION
3. Office Code	4. Date of Accie YR MO DA	- ··· -		ate Initiated /R MO DAY			REPORT
810	2000 11 2	1		03 01 23			
6. Synapsis of Accid	ent or Complaint	<u> </u>	UPC				<u> </u>
normal use in the d	ispatch room of a l controlling two col	regional firel mputers and	hous l a fir	e. The product was e alarm decoding de	plug evice 00	ged into at the t <u>error stat</u> <u>ove</u> EXCISIONS	TEBNO RRIJEO;ATTACHED
7. Location (Home, S	-		8. Ci	-			9. State
5-OTHER PUBLIC		10B. Trad					10C. Model Number
10A. First Product 557 - Computers (e	automent And Elec	1	10/BT	ing Name			SU1000RM2U
•	-	11B. Trad		and Name			11C. Model Number UNKNOWN
11D. Manufacturer N NONE	ame and Address						
12. Age of Victim	13. Sex			14. Disposition			15. Injury Diagnosis
32	1 - Male			0 - No Injury			70 - No Injury
16. Body Part(s) Involved 99 - NO INJURY	17. Respond	dent Complainant	•	18. Type of Investig	gatio	n	19. Time Spent (Operational / Travel) 20 / 2
20. Attachment(s)	L	21. Case So				22. Sa	mple Collection Number
9 - Multiple Attachm	1	01 - Fire or		e Dept.			102257
23. Permission to Dis		<u> </u>	s On) Vei			L	
24. Review Date	25. Reviewed B			·····	26 P	enional	Office Director
03/12/2003	8342	3				ard J. N	
27. Distribution							Document Number
Lansing, Joseph W.	; Moro, Robert E.; ilbert; Naylis, Gerar		aries			100754	

CPSC FORM 182 (12/96) Approved for use through 07/31/2003 OMB NO. 30410029

·----

030123CNE7732 Page 1 of 3

BACKGROUND

This investigation was initiated 1/6/03 by CPSC Investigator in Salem, NH, at which time a sample was collected from the Massachusetts State Fire Marshal's Office, and an interview was conducted with the complainant, a Firefighter. Extenuating circumstances subsequently called for the transfer of records to the FOER Regional Office for completion and processing of this investigation. The complainant was contacted by telephone on 3/6/03, at which time additional information was obtained and reported herein.

PRE-INCIDENT

The complainant is a 32-year-old-male, employed jointly as a regional Firefighter, and as a Network Technician for the Massachusetts State Fire Marshal's Office.

Approximately January 2001, the complainant purchased an uninterruptible power supply backup device for use in the dispatch room of his regional firehouse. This was the first such model purchased, however, several different model units from the same manufacturer are deployed throughout the building with no prior incidents. The product is designed to provide a continuous power supply during outages, and return automatically to house current when normal power is restored.

The product operates off house current, with the power backup controlled by four sealed 12-volt rechargeable batteries. The product was plugged into a grounded three-hole duplex wall outlet on a dedicated 20-amp emergency powered circuit. Attached to the product were two custom 1-Ghz/Pentium-III computers, and one fire alarm decoding device. The product was situated on a metal storage rack inside a communications cabinet, in a room equipped with a commercial fire sprinkler/alarm system.

The product was in use as described continuously, 24 hours per day, seven days per week, since purchase. The product functioned as intended during approximately six power outages per year, each 10-20 minutes in duration, without incident.

Approximately 5:00 pm on the day of the incident, the complainant was in the dispatch room attending his duties.

INCIDENT

The complainant smelled and observed smoke coming from the communications cabinet, and traced the source to the product.

030123CNE7732 Page 2 of 3

POST-INCIDENT

The complainant switched off the unit, disconnected its power cord, and the smoking ceased. Smoke damage was confined to the product and its cabinet, and there was no fire spread, injury, sprinkler/alarm activation, or circuits tripped as a result of this incident.

The complainant removed the outer product casing and observed charning and melting of a plastic tray component in the circuit board area, which he identified as the smart slot. He stated that the component is intended to accept expansion accessories, which connect to surface interfaces when slid into the tray. He stated that no accessories were ever used with the product. The complainant stated that he unscrewed and removed the smart slot and observed further evidence of burning and melting to the circuit board directly beneath the component. He stated his opinion that the point of origin was a metal donut shaped component, approximately 1" in diameter, wrapped in copper wire and soldered to the circuit board. He was unable to technically identify this component but stated that it was the most significantly damaged.

The complainant documented the incident in an abbreviated fire report and turned the product over to the State Fire Marshal's Office for further investigation.

The complainant telephoned the manufacturer to report the incident, and requested a same model replacement, which was shipped out within two weeks, and has been in use since without further incident. The manufacturer requested that the incident product be returned for examination. This request was denied and the manufacturer was informed that a potential fire hazard investigation was ongoing by the State.

SAMPLES COLLECTED

On 1/6/03, the incident product was collected from the Massachusetts State Fire Marshal's Office under 03-810-2257, and submitted for potential fire hazard evaluation.

PRODUCT INFORMATION

a. Incident Product

The product is an APC brand uninterruptible power supply back-up device, Smart-Ups 1000, Model SU1000RM2U, Serial No.AS0046112551, marketed by American Power Conversion Inc., 132 Fairground Road, West Kingston, RI, 02892. The product operates off house current, with the power backup controlled by four, sealed and rechargeable 12-

030123CNE7732 Page 3 of 3

volt batteries identified by the complainant as "BB Battery *** Part No. BP7-12 *** 12V *** 7AH/20 Hour *** "

The product is silver with a white control panel, and measures approximately $17^{\circ}(w) \times 17^{\circ}(l) \times 3.25^{\circ}(h)$, and has a power cord with a molded three prong polarized plug. The product was purchased new in January 2001, for approximately \$1200 by mail order, the purchase specifics of which could not be ascertained.

The product contains labeling reading in part, "*** Smart-UPS 1000 *** APC *** <u>www.apcc.com</u> *** UNINTERRUPTIBLE POWER SUPPLY *** Model Number SU1000RM2U *** Serial Number AS0046112551 *** MODEL 1000 *** 670W *** UL LISTED 42C2 *** E95463 *** CSA LR 63938 *** ". Markings on the same model replacement carton indicate that the product is made in the Philippines.

b. Products attached to the APC Backup Device

Attached to the incident product were two 1-Ghz/Pentium III-computers, custom assembled to the complainant's specifications by Memory Plus Inc., 46 East Main Street, Westborough, MA 01581, with a power rating of 185-Watts/2.5 Amps.


Also attached to the incident product was one Keltron Model DMP703 fire alarm decoding device, manufactured by the Keltron Corporation, 225 Crescent Street, Waltham, MA 02453, with a power rating of 25 Watts/1.2 Amps.

c. Wall outlet

The incident product was attached to a grounded three-hole duplex wall outlet on a dedicated 20-amp emergency powered circuit. No other product information was available.

ATTACHMENTS

Exhibit # 1.1 - 1.10	Photographs of the incident product
Exhibit # 2	Collection Report 03-810-2256
Exhibit # 3	Abbreviated Fire Report No. 27328 dated 11/24/02
Exhibit #4	APC Product Replacement Tracking Document dated 11/25/02
Exhibit # 5	Contact Sheet
Exhibit # 6	Authorization to Release Name Form



Control panel with on and off switches

Exhibit 1.1 – Front view of product IDI 030123CNE7732




Exhibit 1.2 – Close-up front view of product IDI 030123CNE7732





Exhibit 1.3 – Rear view of product IDI 030123CNE7732



Plastic smart slot tray in circuit board area showed signs of charring and melting

Power cord wiring inside product

Exhibit 1.4 – Product with cover removed IDI 030123CNE7732




Exhibit 1.5 – Close-up of product with cover removed IDI 030123CNE 7732

Complainant stated that below melted smart slot tray in this area, was the most heavily damaged component, metal donut shaped, approximately 1-inch in diameter, wrapped in copper wire and soldered to the circuit board. He suspected this to be the point of origin.




Exhibit 1.6– Caution label on top of product IDI 030123CNE7732



Exhibit 1.7 Model and Serial Number identification on product IDI 030123CNE7732




Exhibit 1.8 – Labeling on back of product IDI 030123CNE7732



Exhibit 1.9– Labeling on fan area on back of product IDI 030123CNE7732






Exhibit 1.10 – Identification markings on product IDI 030123CNE7732

 		U.S. Consumer P SAMPLE C		ety Commis	sion	ay an
1.	Sample Flag	· · · · · · · · · · · · · · · · · · ·	·····		pe and	Number: 03-810-2257
4a .	Product Name	4b Model	4	c NEISS		5. Assignment Number
co	MP POWER SUPPLY	SU1000R		1 1		030123CNE7732
6.	Complete for Import Samples		7	. MIS	8. Hours	
	Port of Entry:		{3	1102		Activity <u>8</u> Travel <u>1</u>
1	Country of Origin: Entry No. and Date:		. +	a Home RO		9b Collecting RO
ŀ	Customs Contact:		1	OER		FOER
10.	Sample Cost	11. Invoice Value			12. Si	ze of Lot Units
	\$0.00		····-		1	unt
AM 132	Manufacturer/Importer # AME250 ERICAN POWER CONVERSION INC. 2 FAIRGRONDS EST KINGSTON, RI 02892	14. Shipper/Fore	ign Manufa	acturer	FIRE MA S	ealer/Import Broker # PROT ENG J. NUNNEMACHER TATE FIRE MARSHALS OF V, MA 01775
16.	Supporting documents attached:	۸, , , , , , , , , , , , , , , , , ,			.l	
	Invoice No. and Date:			Dat	e Shipp	
	Shipping Record and Date: Affidavit Signer's name, title and date					
	Product Identification:	NOT APPLICA	BLE			
18.	Sample consists of one number of AS0046112551 the product reflects th Reason for collection/analysis nee	and a model e manufactu ded: () FHSA	number rer as	of SU10 "America A ()FF	00RM2 n Pov	2U. Labeling on
10	Section 15 investigatio Summary of Field Screening:	n potential	Tire n	azard.		
20.	None. Sample size/Method of Collection: This sample was collect the MA State Fire Marsh	ed from Fir al's office	who obt	tained i	ť fro	om Matthew
04	Stockwell Sytems Techni	cian Inform				
	Identification on sample: 3-810-2257 SUB 1 I	DCB 1/6/03		fication on s 257 David C.		
	. Sample delivered to:		23b Date 2/3/03			ord Sent to;
25.	Laboratory/Office: LSE		SIU	- 0	ther	
26.	LSC Remarks: Exhibits 1.Receipt for sample da	CLD	WHSE X	<u>192</u> , , , , , , , , , , , , , , , , , , ,		
27.	Related Samples: None		·,			
28a	Collector's name/title:		28b Colle	ctor's signa	ture/da	ate:
Dav	vid C. Burns Investigat	or	Da	vie C.	ß.	unne 2/3/03
1	Reviewer's name/title: /erly J. Kohen Superviso)f		ewer's signa		
	EXHIBIT # 03 @123	2 Cpage CNE7732	105	-		

PRODUCT IDENTIFICATION

West Kingston, RI 02892. It is square in shape which measures approximately 17" in width and approx 17" in length and approx 3 1/4" in depth. It is primarily silver in color with an off white control panel. It appears to be made of metal, plastic and rubber. There is labeling on the back panel reflects a UL listing number of 42C2 and an E listing of E95463 and a CSA listing of LR63938. There is also a removable plastic control panel with labeling on the front of it which reads in part "SMART-UPS 1000 APC"

METHOD OF COLLECTION

Marshal's office, who also works for the Westborough, MA Fire Dept. Mr. Stockwell reported this power supply was involved in an incident at the Westborough, MA Fire Dept. The power supply was contained in the original packaging and box it came in from the manufacturer. The sample was brought back to the Salem, NH Resident Post where it was identified as per block 21 and was held under lock and key from the time it was collected until it was officially sealed on Feb 3, 2003. It was prepared for shipment to the CPSC sample custodian.

REMARKS

01/15/2003 14:16 5083660079

WESTBORD FIRE DEPT

PAGE Ø1

A 27'328 MA 11/24/20 FDID State Incident D	002 HQ			Deleta	
i chum mana itumidalarr		0002869	Exposure	Chang	ge Basic
B Location	Address o	on Wildland Form		us Tracl	
In front of Rear of Ai Adjacent to	2 Umber Prefix	Milk Street orough		ST Type 1581 ip Code	SUMAX
C Incident Type 111 Building fire D Aid Given or Received 1 T Received 2 Automatic Rec'vd 3 Given 4 Automatic Given 5 Other Ald Given N V None	Their State Co	Mon. Da Arm <u>1</u> rivel IV Arrival <u>1</u> rivel IV Control <u>1</u> at Unit - Last Unit 1	1/24/02	Time 17:11 5 17:11	Shifts / Alarms O O1 Shift Alarms Dist. Special Studies ID# Value
MA Only Critical Inc			nstances /		
F Actions Taken <u>11</u> Extinguish Primary Action Taken (1) <u>B6</u> Investigate Additional Action Taken (2) <u>Additional Action Taken (3)</u>	G1 Sur EM CH ⁺	Appointus ppression <u>1</u> IS <u>0</u>		LOSSES; Property Contents	Loss & Values NONE O F ENT VALUE O F O F O F O F O O F O O F O O F O O F O O F O O F O O F O O F O O F O
 ✓ Fire-2 ✓ Structure-3 ✓ Civ. Casualty-4 ✓ Fire Casualty-5 ✓ EMS-6 ✓ Hazmat-7 ✓ Wildland-8 ✓ Apparatus-9 ✓ Personnel-10 ✓ Appara 14 	H1 Casualfies Vone Deaths Inj. Fire Service Civilian H2 Detector Alerted Occupants 1 Yes 2 V No U Unknown	H3 Hazmat Relea N V None N V None Natural Ga Propane G S Propane G G Gasoline 4 Kerosene 5 Diesel Fue 6 Household 7 Motor Oil 8 Paint 0 Other	is iss i/Fuel Oil	NN No 10 As 20 Ed 33 Me 40 Re 51 Ro 58 Bu 59 Off 60 Inc 63 Fa	sembly Use lucation Use edical Use esidential Use w of Stores inclosed Mail eriness & Resid. fice Use fixistrial Use litary Use rm Use har Mixed Use
E-2 EXHIBI	17#3 (p 23CNE7	ege lafu)			aee Fire station


_ _

01/16/03 10:55 FAX 978 567 3199

01/15/2003 14:15 5083650079

WESTBORD FIRE DEPT

P4GE 03



	Westboroug	h Fire Dept	11/24		00028	
(1 Person / E	ntity Involved	Westborough F			08) 358-3040	
	_	Business name (if	applicable)	Ph	ene	
Check If	Prefix Fir	st Name	MI Last Name		Suffix	
- same	42	Milk		<u></u>		
address as	Number	Prefix Street	t or Highway	Street	Type Suffix	
incident	Dest OF Dest		Westborough	· · · · · · · · · · · · · · · · · · ·		
	Post Office Box	Apt./Suite/Room 01551	City			
	State	Zip				
<u> </u>						
Querer	C Same as Pen Involved	Business name (if	augharL1-V		10116	
	l	preneze usue (u 1	appricapie)	F)	1 1	1
Check if	Prafix F	inst Name	MI Last Name	والمتحد والمتح	Suffix	
- 1300	Franks 11	I I		1	1	1
address as	Number	Prefix Street	or Highway	Street	Type Suffix	.
incident		1 I				
	Post Office Box	Apt/Suite/Room	City tammaa (
	1	· · · · · · · · · · · · · · · · · · ·	Insurance C		-	
			Total Insura	וחכפ		
Remarks Noticed Smoke disconnecting po	State Coming from Cabin ower to the device	Zip net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabi	net in Watchroom and			was establishe	d by
Noticed Smoke	Coming from Cabin	net in Watchroom and			was establishe	d by
n Noticed Smoke	Coming from Cabin	net in Watchroom and			was establishe	d by
Noticed Smoke disconnecting po Authorization	Coming from Cabin ower to the device	net in Watchroom and	Alerted Building Occu	upants. Control		
Noticad Smoke disconnecting pa	Coming from Cabin ower to the device	net in Watchroom and	Alerted Building Occ	upants. Control		
Noticed Smoke disconnecting po Authorization	Coming from Cabin ower to the device	net in Watchroom and	Alerted Building Occu	upants. Control	11/25/2	002
Noticed Smoke disconnecting po Authorization	Coming from Cabi ower to the device on 	net in Watchroom and	Alerted Building Occu	upants. Control	<u>11/25/2</u> Date	002

Westborough F	ire Dept.	11/24/2002	0002889
1 Connective structure 1 2 Portable/mobile structure 2 3 Open structure 3 4 Air supported 4 5 Tent 5 6 Open platform (e.g. plens) 6 7 Underground structure 7 9 Connective structure 0	Building Status Under construction Occupied & operating Idle, not routinely used Under major renovation Vacent and secured Vacent and unseoured Being demolished Other Undetermined	13 Bidg Heig 2 Stories at or ab grade level 1 Stores below grade level	Size Structure
J1 Fine Origin 1 Below grade Story of Fire Origin J2 Fire Spread 2 Confined to room of origin 3 Confined to floor of origin 4 Confined to building of origin 5 Beyond building of origin	J3 No. of Stories Damag Count the ROOF as part of 0 Number of stories w/ (1 to 24% flame dam 0 Number of stories w/ (25 to 49% flame dat 0 Number of stories w/ (50 to 74% flame dat 0 Number of stories w/ (50 to 100% flame dat	f the highest story minor demage age) significant damage nage) heavy damage nage) extreme damage	K Material Contributing Most to Flame Spread No flame spread OR same es material first ignited OR unable to determine K1
L1 Presence of Detectors N GF None Present 1 J Present U Undetermined L2 Detector Type 1 Smoke 2 Friest 3 Combination smoke - heat 4 Sprinkler, water flow detection 5 More than 1 type present 0 T OtherUF Underdetermined	L3 Detector Power Sup 1 Bettery only 2 Hardwire only 3 Plug in 4 Hardwire with bettery 5 Piligin with bettery 6 Mechanical 7 Multiple Detectors & P 0 Other U Undetermined L4 Detector Operation 1 Pire too small to active 2 Operated 3 Failed to operate U Undetermined	phy L5 1 A 2 C 3 T 4 F U L 5 1 2 In 3 C 4 L 5 E 6 E 0 C	Detector Effectiveness Alerted occupants they resonded Decupants failed to respond There were no occupants failed to alert occupants failed to alert occupants indetermined Detector Failure Reason Power failure, shutoff mproper installation or placement Defective ack of maintenance, cleaning Detector missing or disconnected lattery discharged or dead Dther
 M1 Presence of Auto, Exting, System N None Present 1 Present M2 Type of Automatic Extinguishm 1 Wet pipe sprink. 6 Haloge 2 Dry pipe sprink. 7 CO2 sy 3 Other sprink sys 9 Other s 4 Dry cham, sys 9 U Undete 6 Foram system 	system 1 Operate 2 Operate 2 Operate 3 V Fire too 4 Failed to 5 Other 0 Other U Undeter	atic Extinguishment Operation d & effective ad & not effective small to activate o operate mined r of Sprinklers 0	M5 Failure Reason 1 System shut off 2 Not enough agant 3 Agent discharged but did not reach fire 4 Wrong type of system 5 Fina in unprotected area 6 System damaged 7 Lack of meintenance 8 Manual intervention 0 Other

-- .

AMERICAN POWER CONVERSION

. .

APC Returns 1600 Division Rd. Dock 25 West Warwick, Ri 02893 FAX (401) 789-3710

1 ٠

Date 11/25/2002 18:			RMA 743449 - 1
Contact Mathew Stockwe	Telephone 11 508-366-3040	Shipped Via	Cate Shipped
Ship to Town Of Westbo 34 West Main S	rough treet		
Westborough ,	MA 01581 USA		
SU1000RM2U	IN RMA CROSS	2	
Model AS0046	Warranty Status APC Acct		Repair Cost
Serial	Payment Method	Account Number	
	ļ		
	er using : UPS gro	ound	
Corrective Action			
		····	
	EXHIBIT #	4 (page 1 a	-f.1

-

030123CNE7732

030123CNE7732 Exhibit # 5

.

Contact Sheet

Jake Nunnemacher

Fire protection Engineer MA State Fire Marshal's Office State Road Stow, MA 01775

1/6/03 sample collection

Matthew R. Stockwell

Complainant (Firefighter-Westborough, MA (incident location) (Network Technician – MA State Fire Marshal's Office) State Road Stow, MA 01775 978-567-3124

.

1/6/03 interview at Fire Marshal's Office 3/6/03 follow-up telephone interview

FIRE MARSHAL OFFICE



U.S. CONSUMER PRODUCT SAFETY COMMISSION WASHINGTON, DC 20207

U.S. CONSUMER PRODUCT SAFETY COMMISSION

AUTHORIZATION FOR RELEASE OF NAME

Thank you for assisting us in collecting information on a potential product safety problem. The U. S. Consumer Product Safety Commission depends on concerned people to share product safety information with us. We maintain a record of this information, and use it to assist us in identifying and resolving product safety problems.

We routinely forward this information to manufacturers and distributors to inform them of the involvement of their product in an incident situation. We also give the information to others requesting information about specific products or hazards. Manufacturers may need the individual's name so that they can obtain additional information on the product or incident situation.

Would you please indicate on the bottom of this page whether you will allow us to disclose your name. If you request that your name remain confidential, we will of course, honor that request. After you have indicated your preference, please sign your name and date the document on the lines provided.

YES	, 0	NO	
(Signarure)	fin		<u>3/6/03</u> (Date)
$/ \bigcirc$	/		
			1 of 1]
	2123 CA		

1250 Holling - 600-638-0-9002770 - 125014 Web Site 1000/WWW 1050 10

TOTAL P.02

	CONSUME	R PRODU	CT INCIDE	NT REPO		
1. Name of Respondent			2. Telephone No.	(Hourse)	(Work)	_
Matthew R.	Stockwell				(978) 567-3124	:
3. Street Address			4. City	State	Zip Code	
	ire Marshal		Stow	MA	01775	
la. E-Mail Address						
5. Describe accident sit	untion or hezerd, includ	ing data on injurie	s. (Use second pad	necessary.)	
Mr. Stockwe Westborough computer po Department	ell who work h, MA Fire D ower supply	s for the epartment being use ing smoke	MA State reported d at the while in	Fire Ma an inc: Westbord use at SUE	arshal's and the ident in which a bugh, MA Fire the Westborough, MA ! 8	
				ې يه د.	cuud	
5. Date of Incident(s)	7. E injury or near miss	obtein	<u> </u>		erent from respondent, provide	
11-24-02	-	scribe injury		Name:		
9. Description of Produc		injury		Relationship: 10. Brand Nam		_
•	ible compute	r power s	upply.	APC	~	
11. Manufacturer/Distrib	outor Name, Address & i	hane		12. Model, Ser	la/ No. 's	
American Po	wer Convers	ion		SU1000		
132 Fairgro West Kingst	ounds Road :on, RI 0289:	2		Fire Pr Office Marshal	wee, Address, I Phone rot Eng J. Nunnemache of MA State Fire 1 1A 01775	er
14. Was the product dan Yes 🗶 No			<u></u>	15. Product pu Date	rchased New Used Age	
Describe: After t	the incident			16. Does prodi If so, Note:	uct have warning labels? Yes	Na
17. Have you contacted	the manufacturer?	18. Is the product	t still available?	• <u> </u>	15. May we use your name with this report?	
Yəs X No Yas, Do you plan to co Yəs No	vitact them? Other	Yes 🕷 No	li not, its dispo	stion	Yes No X	
20. Date Received	21. Received by (Name		INISTRATIO	N USE		
1/16/03	David C. Bu	-	ર	NO	31-00757	
23. Follow Up Action	SCNE 7-	132	<u> </u>	24, Product Ge	scle/s)	
EHDS/	FOER	3 K	24 Endorser's Nar	na & Title		
		1				

1. Task Number			2. Investigator's ID			
030129CCN0301			9076		EPIDEMIOLOGIC	
3. Office Code	4. Date of Acc YR MO D		5. Date Initiated YR MO DAY			INVESTIGATION REPORT
830	2003 01 2	25	2003 01 29			
8. Synopsis of Accide	int or Complaint	<u></u>	UPC 731304			
investigators datarm (UPS) was connecte	nined that the aread to a telephone	a-of-origin wa switching teri	hospital and resulted is in the area where a minut. The manufactu ject model was not in	i battery Ba arer of the L	ck-up P	.000 in damage. Fire ower Supply System recalled two other
			:		OVERED OVERED CIENCHE/FO Restaura	wen 260
7 Location (Home Sc	thank etc)		8. City			9. State
7. Location (Home, School, etc) 7 - INDUSTRIAL PLACE			NAPERVILLE			J. State
10A. First Product		10B Trad	B. Trade/Brand Name			10C. Model Number
557 - Computers (ed	nuinment And Fle	1				SMARTUPS 2200XLT
132 Fairgro W. Kingstor 11A. Second Product		11B. Trade	e/Brand Name			11C. Model Number
557 - Computers (equipment And Elec AP			BACK-UP BATTERY PACK 48V			SU48XLBP
	POWER CONVE					
12. Age of Victim	13. Sex		14. Disposition		15.	Injury Diagnosis
0	0 - Not Sta	ited	0 - No Injury		1	0 - No Injury
16. Body Part(s) Involved 99 - NO INJURY	17. Respon	dent Complainant	18. Type of Investigation		19.	Time Spent (Operational / Travel) 25 / 5
20. Attachment(s) 9 - Multiple Attachme		21. Case Sou	·ce {		22. Sample Collection Number	
23. Permission to Dise	l					
Ves	ciose Name (Non		Verbat			
24. Review Date	25. Reviewed I	<u> </u>	······································	28. Reci	onal Off	fice Director
03/14/2003	8929	-		Eric B. Ault		
27. Distribution Moro, Robert E.; Poole, Georgia F.				28. Source Document Number G0310294A		

CPSC FORM 182 (12/96) Approved for use through 07/31/2003 OMB NO. 30410029

•

\$

.

030331

,

SUMMARY:

A fire that started in the utility room of a hospital medical office suite caused more than \$200,000 in damage. Investigators determined that the point-of-origin of the fire was located where an un-interruptible power source (UPS) battery back-up unit for a telephone switching terminal was connected to a voltage inverter. A technician replaced the UPS unit with a new one and installed an add-on battery pack accessory the day before the fire occurred.

The manufacturer of the UPS unit involved voluntarily recalled two other models of UPS units on January 14, 2003, (#03-068) citing an overheating hazard with those models. The unit involved in this fire was apparently not included in the recall.

Insurance investigators collected the UPS unit, battery-pack, voltage converter, telephone terminal and various other items for examination and testing. A joint-examination of the items is planned in the future, but has not yet been scheduled. The Director of Safety for Edward Hospital stated that the investigators found that a manual had been left on top of the UPS, which supported combustion.

Note: The Fire Department in this jurisdiction will not provide copies of their investigation reports, unless they are subpoenaed. *At the time of this report, the joint examination of the subject UPS unit and other items has not yet been scheduled.

PRE-INCIDENT:

The location of the fire is a 4' x 8' utility room with a suspended ceiling, located in the center of the office suites of an orthopedic medical clinic, located on the fourth floor of Edward Hospital. The room contained various pieces of equipment, including a telephone-switching terminal with a monitor on top of it, a power converter connected to the terminal, a 208-volt un-interruptible power source (UPS) connected to the power converter, and a 48-volt add-on battery pack attached to the UPS unit. No fire sprinkler was installed in the room.

The ITS manager for the DuPage Medical Group, (the tenant medical clinic), replaced the un-interruptible power source (UPS) unit with a new one that he had purchased from a supplier on 01/14/03. He states that the unit was identical to the one that was installed before. In addition, he purchased an accessory add-on battery pack, which attaches to the UPS unit (to extend the battery time), from the same supplier and installed that on the same date. The UPS unit was located on the floor adjacent to the power converter, and the power converter was located between the UPS and the telephone terminal. The battery pack was located on top of the UPS unit. He stated that the UPS unit was plugged into a 208-volt receptacle by itself with a twist-lock type plug. The battery pack was plugged into a receptacle on the back of the UPS, and the UPS unit plugged into the power converter.

INCIDENT:

On 01/25/03 at 08:00 am, the Fire Department received a smoke alarm call from the hospital and responded. Upon arrival, they determined that the source of the smoke was in the utility room, made entry into the locked room through the wall and quickly extinguished the fire. Fire Department investigators determined that the point-of-origin of the fire was at the UPS unit. The flame and heat damage was contained within the utility room, however smoke damage extended throughout the entire suite.

POST-INCIDENT:

The day following the incident, fire and insurance company investigators jointly processed the fire scene and collected various evidence and equipment to be jointly tested and examined at a later date. The Fire Department and Edward Hospital officials estimated the damage was in excess of \$200,000.

On 02/28/03, the Fire Department investigator who responded to the fire contacted me by telephone and reported the incident to me. He stated that had occurred on Saturday morning at the Edward Hospital and that they had determined, and the insurance investigators that were present had agreed, that the source of the fire was the UPS unit. He stated that the insurance companies had taken the unit and were going to have it examined. He stated that they had discovered that the same manufacturer had recently recalled several UPS units, and they believed that this was one of the same units.

I met with the Director of Safety for Edward Hospital who stated that the point-of-origin of the fire had been the UPS unit at the heavy-duty output cable. He stated that the UPS unit was connected to a telephone switch in the utility closet in the clinic's office suite. He stated that the fire load had been from the floor up, and that a manual had been found on top of the UPS, and had supported combustion. A large number of additional manuals were also located in the room and no sprinkler head had been installed in the room. He further stated that an employee of the clinic manages their ITS function, and had just installed (replaced) the subject UPS unit the day before the fire. He further stated that the insurance investigators had indicated that they believed the unit involved was one of the ones that had been involved in the recent recall from the same manufacturer.

The Director provided me with a copy of the Fire Department incident report and with photographs of the scene taken when the investigators jointly processed the scene and collected the UPS and other evidence for later examination. He stated that the hospital had hired a fire investigator to represent them, and that the insurance company had retained an engineering firm to conduct the testing and to host the joint examination to be scheduled at a later time.

On the same date, I met with the Edward Hospital Safety Manager (who works for the Director) and accompanied him to the scene of the fire. None of the fire damage remained at that time and the office suite was in the process of being rehabilitated.

I contacted the Fire Investigator who was retained by Edward Hospital and spoke with him about the incident. He stated that the UPS unit was collected along with other items of evidence from the scene, including the electrical wiring and other equipment. He stated that the power converter was a 48 to 110-volt unit, and had been connected to the UPS unit with an umbilical. The UPS unit had been connected to a power outlet that was separate from any of the other pieces of equipment in the room.

He stated that the evidence collected, including the UPS unit, was currently stored at the engineering laboratory where a joint examination and testing was going to be conducted at some date in the future. He indicated that reports would not be completed until the evidence was examined. I informed him that I wished to be present when the examination took place, and he agreed to notify me when was scheduled so that I could attend. He subsequently provided me with a copy of the inventory of the items that were collected from the scene.

I contacted the ITS manager for the DuPage Medical Group (which operates the clinic) and interviewed him. He stated that he replaced the UPS unit with a new one, and had also added an accessory battery pack that was designed specifically for the unit to extend the battery time, on the day prior to the fire. He stated that the new UPS unit was identical to the one that it replaced, and that he purchased it and the battery pack from a supplier a short time before he installed it. He stated that he also purchased one of each of the two units for another location, but had not installed them.

He stated that between noon and 2:00 PM. on the day prior to the fire, he installed the UPS and battery pack in the utility room. He stated that he disconnected the old unit and installed the new one the same cables and plugs that had been attached to the original unit. He described the approximate locations of all of the equipment located in the area of origin prior to the fire. He stated that the UPS had been connected to a separate 208-volt receptacle with a twist-lock plug.

He stated that he did not recall having left anything on top of the UPS unit when he left, but if he did, it would have been the instruction manual for the unit. He provided me with copies of the shipping documents for the units that he had purchased, including the UPS and Battery Pack that he had installed at the fire scene.

NOTE: Although the UPS unit (and battery pack) were manufactured by the same firm, that issued a recent recall, the model number of the subject unit does not appear to be included in the recall (#03-068 - January 14, 2003).

NOTE: Engineering Firm location where the joint examination of the product and other items is going to be held:

-4-

Richard M. Hansen & Associates, Inc

950 DuPage Avenue Lombard, IL 60148 (630) 495-3853

PRODUCT IDENTIFICATION:

American Power Conversion (APC) brand:

• Un-interruptible Power Supply - 208Volt

Model:	SmartUPS - 2200XL 208V – 5RCPTL
Vendor Item#:	SU2200XLTNET
UPC:	731304007906

• **Battery Pack** – 48volt

Model:	SmartUPS – 48V BATTERY PACK
Vendor Item#:	SU48XLBP
UPC:	731304011637

VENDOR:

CDW Computer Centers 1 Technology Drive Swedesboro, NJ 08085

MANUFACTURER/ DISTRIBUTOR:

American Power Conversion Corporation West Kingston, RI

SAMPLES:

No samples were collected. The insurance companies involved collected the subject products for joint examination and testing at a future date.

ATTACHMENTS:


Exhibit 1: Photographs Building Floor Diagram Exhibit 2: Fire Department Incident Report Exhibit 3: Medical Group Invoices Exhibit 4: Product Data Exhibit 5: APC Recall Notice Exhibit 6: Exhibit 7: Fire Investigators Inventory Fire Investigation Report Exhibit 8: Exhibit 9: Contacts

Photo of equipment in area-of-origin. The UPS is pictured on right with the battery pack on top of it. The power converter is between the UPS and telephone terminal.







Battery pack is located on top of the UPS unit.





Photos depict heavy corrosion on ceiling area above the area where the UPS, battery pack, power converter and terminal were located.





-10-

Photo shows area behind the UPS and battery pack (on left).



Additional view behind terminal, converter and UPS (on extreme lower left)



-13-

Top of the battery pack viewed from the back toward wall. There appear to be indications that something was resting on top of the unit, and may have partially melted.



View looking down at the backside of the UPS with the battery pack on top. The wall behind the equipment is located at the upper right corner of this photo. The telephone terminal is pictured in the upper left corner.



-15-

The outlets located behind the units. The UPS was apparently plugged into the one pictured on the lower right.



Close-up view of the front of the battery pack.




-16-

•

Photo of the UPS and power converter connected together.




Photo of the UPS (bottom) and power converter connected together.



=FIRE-EXTINGUISH

USE STAIRS * DO NOT USE ELEVATORS



LINCHOLING CONCINCIALIUN KUUIES

030129CCN0301 EXHiBit #2 Building Dingram

030129 CCN0301 EXHIBIT #3

NAPERVILLE FIRE DEPARTMENT Incident Report Page 1 Prepared: 1/27/03, 9:46:56 Program: FI200L A DD132 IL 1/25/03 Sta #7 01-2003-0000645-000 NFIRS - 1 FDID State Incident date Station Incident number Basic в No 8465.04 Street address Yes Alternative location Census tract Location Emergency (b)(6) NAPERVILLE, IL, 60540 Address C Building fire Incident type . D None Aid given or received El Date Time E2 SHIFT 2 5 District 1 Alarm 1/25/03 B:00:38 Shift Alarme District Arrival 1/25/03 8:05:25 Controlled 0/00/00 0:00:00 Last unit cleared 1/25/03 10:45:21 F Excinguish Salvage & overhaul Primary action taken (1) Additional action taken (2) Evacuate area Additional action taken (3) Gl Yes Apparatus Personnel No Value G2 Losses Apparatus/ Suppression 25 Resource counts Froperty 8 100000 4000000 2 2000000 والمستحد والمستعان و 1 include aid Contents 150000 3 1 form used other received resources H1 Deaths Injuries H2 Detector elected occupants H3 None Fire service 0 0 Detector Hazardous materials release Civilian fire 0 С I Not mixed use J Clinics, Doctors offices, hemodialysis centers Mixed use property Property use X.2 ECWARD HOSPITAL Name Phone number Business name 801 S WASHINGTON ST, NAPERVILLE, IL, 60540 00000000 Address Cender Age Birth date Race M RICHARD MIKEL DC IC 1/25/03 Officer in charge Position or rank Assignment Date DAVID FERRERI 1/25/03 Lt Officer Member making report Position or rank Assignment Date

OFFICIAL DEPARTMENT COPY

OFFICIAL DEPARTMENT RECOI Naperville Fire Department 1380 Aurora Avenue Naperville, IL 60540

By: 1 Date: 1 127 03

NAPERVILLE FIRE DEPARTMENT Incident Report 2 Page Prepared: 1/27/03, 9:46:56 . Program: FI200L NFIRS - 2 A DD132 IL 1/25/03 Sta #7 01-2003-0003645-000 FDID State Incident date Station Incident number Fire B1 Not residential C None None Estimated number of Cn-site material 1 Material 1 storage use residential units B2 L Number of buildings involved B3 None Acres burned (outside fires) D1 Equipment or service area, other El Cause undetermined after investigation Area of fire origin Cause of Equition E2 Unspecified short-circuit arc D2 Arcing Heat source Factor 1 contributing to ignition E3 None D3 Storage supplies, other Item first ignited Human factors contributing to ignition No Spread confined to object of origin D4 Type of material first ignited, other Type of material first ignited F1 Electronic equipment, other F2 Undetermined Equipment power Equipment involved in ignition A.P.C. -F3 Stationary Equipment portability Brand UNKNOWN AT THIS TIME Medel SAME Serial number 2003 Equipment year G Trouble finding location Fire suppression factor 1 H1 None HZ Mobile property involved Mobile property type Mobile property make Mobile property model 0000 Year License plate State VIN

OFFICIAL DEPARTMENT COPY

CFFICIAL DEPARTMENT REC Naperville Fire Department 1380 Aurora Avenue Naperville, IL 60540

By: 1 Date: 117/03

NAPERVILLE FIRE DEPARTMENT Prepared: 1/27/03, 9:46:56	In	cident Report			÷	Page 3
Program: FI200L						
A DD132 IL 1/25/03 FDID State Incident dat		01-2003-0 Incident n)	Stru	NFIRS - 3 cture fire
Il Enclosed building Structure type		I2 Cocupied and o Building statu				
I3 4 Stories at/above grade Stor	l ies below grade	I4 10000 Total square f	eet			
J1 3 No Story of fire crigin Below		J3 Number of stories		Significant (25-49%)	-	Extreme (75-100%)
J2 Confined to room of origin Fize spread		damaged by flame	1	0	o	٥
Kl Storage supplies, other Item contributing most to fl	ame spread	K2 Plastic Type of		contributing	most to fl	ame spread
L1 Present Presence of detectors	L3 Hard wir Detector	e only power supply				
L2 Undetermined Detector type	L4 Undeterm Detector	ined operation				
M1 None present						

Presence of extinguishing system

-

OFFICIAL DEPARTMENT CCP/ By: A Date: 1,27,03 OFFICIAL DEPARTMENT RECORD Naperville Fire Department 1380 Aurora Avenue Naperville, IL 60540

.

NAFERVILLE FIRE DEPARTMENT Prepared: 1/27/03, 9:46:56 Program: FI200L

.

A DD1.32 IL 1/25/03 Sta #7 01-2003-0000645-000 FDID State Incident date Station Incident number Additional information County (001=Dupage / 002=Will) : 001 Dupage County Common Name EDWARD PHYSICIANS OF Method of alarm 2 Coded signal municipal fire alarm system Area (001=City, 002=Dist, 003=M/A) . . : 001 City .

Incident Report

OFFICIAL DEPARTMENT COPY

OFFICIAL DEPARTMENT RECORD Naperville File Department 1380 Aurora Avenue Nacarville, IL 60540

By: 1 Date: 1 127103

Page

4

NAPERVILLE FIRE DEPARTMENT Prepazed: 1/27/03, 9:46:56 Program: FI200L Incident Report

A DD132 IL 1/25/03 Sta #7 FDID State Incident date Station 01-2003-0000645-000 Incident number

Nagrative type: Incident

Narrative title Entry date Entered by employee ORIGINAL COMMENTS 1/25/03 589 DAVID FERRERI Engine 7 responded as part of a full still assignment to an activated alarm at a 4-story medical office building. Opon arrival I met with building maintenance and security personnel who told me there was a duct detector activation in the basement, and they thought it was due to a bad blower motor in an air-handling unit. There was an odor of something burning as I entered the stairwell and descended to the basement. I was shown the suspected bad motor (the HVAC system had been turned off by maintenance). The odor was of class A combustibles burning, not a motor. The alarm was down graded at this time at πy recommendation. Engine 7 and Ladder 7 companies began to search the area for another source, and after being unsuccessful, began moving upstairs. I checked the alarm panel and found that 3rd floor activations were indicated. Ladder 7 moved to the 3rd floor and reported smoke in the stairwell. I requested an upgrade in the alarm at this time. Heavier smoke was found in the 3rd floor lobby. The 3rd floor was unoccupied at the time and we had to contend with locked doors. A fully involved utility closet was found toward the center of the floor. A 2 1/2 hand line was used to easily control the fire. Heavy smoke filled the entire third floor. Other arriving fire companies assisted in smoke removal. Several windows were broken out in an effort to clear the smoke. Mechanical ventilation was also utilized. Smoke removal was also needed on the 2nd and 4th floors. Fire damage was contained to the utility closet and space directly above it. There was no fire spread to the 2nd or 4th floor. Though the building is fully sprinklered, there was not a sprinkler head in the utility closet, and there was no sprinkler activation. There were no injuries to civilians or firefighters. At the time of this report the fire cause in under investigation.

Narrative titleEntry dateEntered by employeeDollar Loss1/25/03843DANIEL J. VOILANDThe dollar loss and contents figures are estimates only. The FireDepartment is waiting to receive these figures from Edward Hospitalrepresentatives.

OFFICIAL DEPARTMENT RECC Naperville Site Coortmant 1380 Aurora Avenue Naperville, IL 60540

By: N Date: 1,27,03

OFFICIAL DEPARTMENT COPY

Page 5

Narratives

ORDER PACKING LIST



Computing Solutions Built for Business" www.com.com

PAGE 1 of 1

NELLYN CLINIC/ DMG	CDW COMPUTER CENTERS	01/14/03			538289
SPALDING DR	3310 WM RICHARDSON CT				
FL PEDIATRICS	SOUTH BEND, IN 46629				1
LAWRENCE					
ERVILLE, IL 60540				EE CODDING	L
TOMER CONTRACT JOHN					
1 EA 1	SU48XLBP 73130401			FOR SU2200XL	
			• • • • •		
CONFAM S/N: WS	VER ID: 015134808742847 60247130928				
OTAL NUMBER OF ITEMS: 1		CONTAINER ID	WEIGHT	NUMBER OF PIECES	
HIP VIA: FEDEX GROUND		015134808742847	74.50	1	
ACKER: JERRY WILSON					
			÷.		
;					
•		Computing Solutions			
		Bell for Resiness"			
		erval controls			
			ť		
			:		
			i		
			1		
			į		
			•		
			i		
			; 		

Computing Solo	lions		ORDER PACE	(ING LIST)
Built for Busine www.cdw.com	50 T		PAGI	E 1 of 1
A ELLYN CLINIC/ DMG SPALDING DR FL FEDIATRICS LAWRENCE 'ERVILLE, IL 60540 STOMER CONTACT JOHN STITCE UN CORDEN	SHIPPED FROM CDW COMPUTER CENTERS 1 1 ECHNOLOGY DRIVE SWEDESBORO, NJ 08085	01/14/03	CUSTOMEN BO BET	1
1 EA 1	SU2200XLTNET 73130400790	06 SMARTUPS 2200 XL	208V SRCPTL	
TOTAL NUMBER OF ITEMS: 1 SHIP VIA: WATKINS PACKER: TERRI PATTI		WCP-001112	WEIGHT NUMBER OF PIEC 156.00 NUMBER OF PIEC PIEC Day Day The D	

. **.** -

Sent By: GLEN ELLYN;

	r vr	ww.cdw.pont								PAGE 1	of 1
WIJAS	E DR	5	CDW 3310	D FROM COMPUTER CENTE WM RICHARDSON H BEND, IN 46628	RS CT			DATE SHIPPI 01/20/03		STOMER PO REF	1040 # 464769 70 cawranes 2
omer conta HPPED UM				VENDOR ITEM #	U	110			TEN DE	SCRIPTION	
1 EA	1	5 5		SU2200XLTNET	731304	¢007906	SMARTU	P\$ 2200 ×	L 208V	5RCPTL	
		N FREIGHTWAY	D: 400 723101	SU48XLBP 5167463	731304	011637	SMARTU CONTAI 40516		атт Рк WEIGHT 229.00	FOR SU2200XL NUMBER OF PIECES 2	3
									1		

APC Smart-UPS 2200VA XL 208V *O* 30129 CCN0301

ExHiBiT#5a

		How to Buy	View Ca	rt Örder	Stat
Legendary Reliability			Search	Contact	5 (
☞ 1000時間 強化 後水の芽類の	HOME		SUPPORT	SERVICES	S
Contraction of the Science of the Science of Science of the Scienc	No. 1 Contractor Sector States Contractor				

APC Smart-UPS 2200VA XL 208V

Part Number : SU2200XLTNET Estimated Resale Price : 1,150.00 USD *

Options (states Aug





Product Overview

Description

Features

Includes

UPC Code

Options

Optional Versions

Optional AC Connections

Optional Batteries

Optional Management Devices

- **Optional Service**
- **Optional Software**

Documentation

User Manual & Installation Guides

APC Smart-UPS XL, 2200VA/1600W, Input 208V/ Outpu Interface Port DB-9 RS-232, SmartSlot, Extended runtime

Automatic Voltage Regulation (AVR), Built-in SmartSlot, F Batteries, Intelligent Battery Management, Overload Indic Batt Indicator, Scalable Run Time, Software, User Replac batteries

User Manual, Smart UPS signalling RS-232 cable, CD wit

731304007906

Click here to view optional yersions.

Click here to view optional AC Connections.

Click here to view optional Batteries.

Click here to view optional Management Devices.

Click here to view optional Service.

Click here to view optional Software.

Smart-UPS and Smart-UPS RM - XL (Taiwan); User M Smart-UPS and Smart-UPS RM - XL; User Manual Smart-UPS and Smart-UPS RM - XLT 1400/2200/300 (208VAC); User Manual

Page 1 of 4

Communications & Management	
Interface port	DB-9 RS-232, SmartSlot
Available Smart Slot Interface Quantity	1
Control panel	LED status display with load and battery bar-graphs and (Battery : Replace Battery : and Overload Indicators
Audible alarm	Alarm when on battery : distinctive low battery alarm : cor delays
Emergency Power Off (EPO)	Optional
Included Software	PowerChute Smart-UPS Bundle
Output	
Output Output power capacity	2,200 VA
Output power capacity	1,600 Watts
Nominal output voltage	208 V
Output Voltage Note	2 NEMA 5-15R receptacles provide a total of 400VA at 12
Waveform type	SINE
	17
	(2)NEMA 5-15R
Output Connections	(1)NEMA L6-20R
	(2)NEMA 5-15R () (1)NEMA L6-20R () (2)NEMA L6-30R ()
Input	
Nominal input voltage	208 V
Input frequency	50/60 Hz +/- 3 Hz (auto sensing)
Input Connection Type	NEMA L6-20P
Cord Length	6 feet (1.83 meters)
Input voltage range for main operations	157 - 255 V
Input voltage adjustable range for main operations	
Surge Protection and Filtering	
Surge energy rating	480 joules
Filtering	Full time multi-pole noise filtering : 0.3% IEEE surge let-th clamping response time : meets UL 1449
Runtime	
Typical backup time at half load	33.9 minutes (800 Watts)

Batteries

Battery type electrolyte : leakproof Typical recharge time ** 3 hour(s) (1) RBC11 Replacement battery cartridge **Optional Battery** Click here to view other Batteries. APC Smart-UPS 2200VA XL 208V Extended run options for

Physical

Maximum height dimensions	17.00 inches (43.18 cm)
Maximum width dimensions	7.70 inches (19.56 cm)
Maximum depth dimensions	21.50 inches (54.61 cm)
Net weight	137.00 lbs (62.27 kg)
Shipping Weight	167.00 lbs (75.91 kg)
Shipping Height	22.00 inches (55.88 cm)
Shipping Width	15.00 inches (38.10 cm)
Shipping Depth	30.00 inches (76.20 cm)
Color	Beige

Environmental

Operating Environment	0 - 40 °C (
Operating Relative Humidity	0 - 95%
Operating Elevation	0-10000 fe
Storage Temperature	-15 - 45 °(
Storage Relative Humidity	0 - 95% N
Storage Elevation	0-50000 fe
Audible noise at 1 meter from surface of unit	53 dBA
Online thermal dissipation	275 BTU/I

Conformance

Approvais

Standard warranty

Equipment protection policy

9.7 minutes (1600 Watts)

Smart-UPS XL


Maintenance-free sealed Lead-Acid battery with suspende

(32 - 104°F) feet (0-3000 m) °C (5 - 113°F) Non-condensing feet (0-15000 m) /hr

CSA, FCC A, UL 1778 2 years repair or replace, optional on-site warranties avail optional extended warranties available Lifetime : \$150000

* Without TAX/VAT

** The time to recharge to 90% of full battery capacity following a discharge to shutdown using a load rated for 1/2 the full load rating of the UPS.



SmartSlot™

Allows you to install one of a varlety of optional accessory of available to customize and enhance the management of you UPS.

CellGuard** intelligent battery management

Actively increases battery life and system reliability using F ϵ technology, automatic battery and circuitry self-tests, and a diagnostics.

Line-Interactive Design

Provides greater performance, filtering, reliability and efficie conversion, on-line UPS units.

Battery

Average Run Time 9.7 Min

•

Enclosure Type	Plug-in module
Form Factor	Proprietary
Load Type	At full load
Recharge Time	3 Hour(s)
Technology	Lead acid
Туре	UPS battery
Cabinet	
Chassis Type	Proprietary cabinet
Cable	
Connectivity Details Form Factor	External
Connectivity Details Included Qty	1
Connectivity Details Length	6 Ft
Connectivity Details Type	Serial Cable, Power Cable
Dimensions	
Depth	21.5 In
Height	17 In
Weight	137.3 Lbs
Width	7. 7 In
Environmental Paran	neters
Humidity Range Operating	0 - 95%
Humidity Range Storage	0 - 95%
Max Altitude Operating	9840 Ft
Max Operating Temperature	104 °F
Max Storage Temperature	113 °F
Min Operating Temperature	32 °F
Min Storage Temperature	5 °F
Sound Emission	53 DBA
Header	
Compatibility	PC
Country Kits	Canada, Peru, Ecuador, Costa Rica, Panama, Dominican Republic, Falkla Angulila, Argentina, Colombia, Beliz Uruguay, Nicaragua, Jamaica, Guya Antigua and Barbuda, Brazli, Saudi Venezuela, Chile, Mexico, Puerto Ric Paraguay, Honduras, Guatemala, Ci Antilles, United States
Manufacturer	APC
Model	2200VA XL
Packaged Quantity	1
Product Line	APC Smart-UPS

Interface Provided

Connector Qty	1
Connector Type	9 pin D-Sub (DB-9)
Free	1
Gender	Male
Interface	RS-232
Qty	1
Туре	Management

Interface Required

Туре

Miscellaneous

Color	Beige
Compliant Standards	FCC Class A certified
Equipment Protection Value	150000 US Dollars
Features	Audible alarm
Rack Mounting Kit	Not available

None

Networking

Туре

Power Output Connectors Details

Connector Qty	1, 2
Connector Type	Power NEMA 5-15, Power NEMA L6-L6-30

None

Power Supply

Device Compliant Standards	CSA, UL 1449, UL 1778
Device Energy Rating	480 Joules
Device Form Factor	External
Device Frequency Required	50/60 Hz
Device Input Connector Qty	1
Device Input Connector Type	Power NEMA L6-20
Device Input Voltage Range	AC 157 - 255 V
Device Input Voltage Range (Adjustable)	AC 151 - 268 V
Device Output Connector Qty	5
Device Output Connector Type	Power NEMA L6-20, Power NEMA 5- L6-30
Device Power Provided	2200 VA
Device Surge Response Time	0 Ns
Device Surge Suppression	Standard
Оемсе Туре	UPS
Device UPS Output Waveform	Sinewave
Device Voltage	AC 208 V

http://www.cdw.com/shop/products/default.asp?EDC=085806

•

Provided Device Voltage Required	AC 208 V
Service	
Support Details Full Contract Period	2 years
Support Details Type	Limited warranty
Support Type	2 years warranty
Slot Provided	
Free Qty	1
Total Qty	1
Туре	SmartSlot
Slot Required	
Туре	None
Software	
Туре	APC PowerChute Smart-UPS Bundle

Copyright 2003 CDW Computer Centers, Inc. Terms and Conditions of Use | Terms and Conditions of Sale | Privacy Pledge



APC. Smart-UPS XL snip with APC's PowerChute plus UPS po and diagnostic software to provide network administrators v information and great flexibility in configuring UPS reaction By tailoring each UPS to the network environment you can s enhance network performance and reliability. Use your APC conjunction with PowerChute plus for maximum, custom pro addition to extensive unattended system shutdown, you'll gitesting/status, Remote UPS management and Environmente monitoring. Smart-UPS NET includes PowerChute Plus softw provides support for Windows® NT, 95, V3.1, Netware and Agent for Window NET and Netware.

APC's PowerNet SNMP Agent, included with PowerChute plus monitor and control the APC UPS's protecting servers along network data path. Smart-UPS includes PowerNet SNMP Age NT and Novell Netware.

With a Smart-UPS XL unit, mission-critical applications can a power outage, whether it lasts for a few seconds or several runtime (up to 100 hours) can be added by simply plugging

Because the batteries are packaged in an enclosure separate electronics, they operate at reduced temperatures. Battery enhanced through the use of a precision low-ripple float cha

For most extended-run UPSs, on-site repair requires an exp contract and a wait for factory authorized repair. In the case any user can safely plug in new batteries or replace faulty U battery enclosure in minutes.

1 . a

http://www.cdw.com/shop/products/default.asp?EDC=079111

Accessories

> Similar Products

Send to Associate

Battery	
Average Run Time	9.7 Min
Enclosure Type	Plug-in module
Form Factor	Proprietary
Load Type	At full load
Recharge Time	3 Hour(s)
Technology	Lead acid
Туре	UP5 battery
Cabinet	
Chassis Type	Proprietary cabinet
Cable	
Connectivity Details Form Factor	External
Connectivity Details Included Qty	1
Connectivity Details Length	6 Ft
Connectivity Details Type	Serial Cable, Power Cable
Dimensions	
Depth	21.5 In
Height	17 In
Weight	121.3 Lbs
Width	7.7 In
Environmental Parar	neters
Humidity Range Operating	0 - 95%
Humidity Range Storage	0 - 95%
Max Altitude Operating	9840 Ft
max motione operating	
Max Operating Temperature	104 °F
Max Operating	104 °F 113 °F
Max Operating Temperature Max Storage	
Max Operating Temperature Max Storage Temperature MIn Operating	113 ºF
Max Operating Temperature Max Storage Temperature MIn Operating Temperature Min Storage	113 °F 32 °F
Max Operating Temperature Max Storage Temperature Min Operating Temperature Min Storage Temperature	113 °F 32 °F 5 °F
Max Operating Temperature Max Storage Temperature Min Operating Temperature Min Storage Temperature Sound Emission	113 °F 32 °F 5 °F
Max Operating Temperature Max Storage Temperature Min Operating Temperature Min Storage Temperature Sound Emission Header	 113 °F 32 °F 5 °F 53 DBA PC Aruba, Chile, Mexico, Virgin Islands Falkland Isles, Guyana, Barbados, / Barbuda, Saudi Arabia, Argentina, I Guatemala, Costa Rica, Salvador, C Uruguay, Venezuela, Canada, Boliv Panama, Dominican Republic, Angu
Max Operating Temperature Max Storage Temperature Min Operating Temperature Min Storage Temperature Sound Emission Header Compatibility	 113 °F 32 °F 5 °F 53 DBA PC Aruba, Chile, Mexico, Virgin Islands Faikland Isles, Guyana, Barbados, A Barbuda, Saudi Arabia, Argentina, I Guatemala, Costa Rica, Salvador, C Uruguay, Venezuela, Canada, Boliv Panama, Dominican Republic, Angu States, Paraguay, Nicaragua, Jamai
Max Operating Temperature Max Storage Temperature Min Operating Temperature Min Storage Temperature Sound Emission Header Compatibility Country Kits	 113 °F 32 °F 5 °F 53 DBA PC Aruba, Chile, Mexico, Virgin Islands Faikland Isles, Guyana, Barbados, A Barbuda, Saudi Arabia, Argentina, I Guatemala, Costa Rica, Salvador, C Uruguay, Venezuela, Canada, Boliv Panama, Dominican Republic, Angu States, Paraguay, Nicaragua, Jamai Netherlands Antilles

٠

Pro	duct Line	APC Smart-UPS
In	terface Provided	
Co	nnector Qty	1
Co	nnector Type	9 pin D-Sub (DB-9)
Fre	e	1
Ge	nder	Male
Int	erface	RS-232
Qty	1	1
Ту	0e	Management
In	terface Required	
Ту	De	None
Mi	sceilaneous	
Coi	lor	Belge
Co	mpliant Standards	FCC Class A certified
Eq. Val	uipment Protection ue	150000 US Dollars
Fea	atures	Audible alarm
Rad	ck Mounting Kit	Not available
Ne	tworking	
тур	De	None
Po	wer Supply	
	vice Compliant Indards	UL 1778, UL 1449, CSA
De	vice Energy Rating	320 Joules
De	vice Form Factor	External
	vice Frequency quired	50/60 Hz
	vice Input Inector Qty	1
	vice Input mector Type	Power NEMA L5-30
	vice Input Voltage	AC 92 - 147 V
	vice Input Voltage Nge (Adjustable)	AC 86 - 154 V
Dev	vice Output mector Qty	8
	vice Output	Power NEMA 5-15
	vice Power Provided	2200 VA
	/ice Surge	0 Ns
	ponse Time	
Sup	vice Surge opression	Standard
	vice Type	UPS
Wa	vice UPS Output veform	Sinewave
	vice Voltage víded	AC 120 V
	rice Voltage Julired	AC 120 V

APC Smart-UPS XI. 48V Battery Pack 030129 CCN0301 EXHIBIT#56

HTTP/1.1 200 OK Server: Microsoft-IIS/5.0 Date: Thu, 13 Feb 2003 16:06:56 GMT Connection: close Content-type: text/html; charset=Windows-1252 Page-Completion-Status: Normal Set-Cookie: APCSITECODE=us; expires=Sat, 15-Mar-2003 11:06:57 GMT; path=/;

	Search	Contact	·* •
oeuare S	UPPORT	SERVICES	S
/	sourre S	DOULTS SUPPORT	DOULTS SUPPORT SERVICES

APC Smart-UPS XL 48V Battery Pack

Part Number : SU48XLBP Estimated Resale Price : 389.00 USD *

Ceptions (Laster Laster)

Product Overview





(Q 21


Product Overview	
Description	Extended run power protection for servers, networks, and telecommunic
Features	Cascading Capabilities, Hot Swap Batteries, Intelligent Battery Manager
UPC Code	731304011637
Options	
Optional Batteries	Click here to view optional <u>Batteries</u> .
Optional Service	Click here to view optional Service.
Documentation	
User Manual & Installation Guides	Smart-UPS Battery Systems - XL Battery Pack (Taiwan): Addendum
Battery	
Battery type	Maintenance-free sealed Lead-Acid battery with suspended electrolyte :
Expected Battery Life (years)	3 - 5
Physical	
Net weight	69.00 lbs (31.36 kg)
	8.50 inches (21.59 cm)

http://www.apcc.com/resource/include/techspec_index.cfm?base_sku=SU48XLBP

Print	C-mail	Options	
*Without TAX/VAT			
Standard warranty	2 years repair or replace		
Conformance			
Storage Elevation	0-50000 feet		
Storage Relative Humidity	0 - 95% Non-condensing		
Storage Temperature	-15 - 45 °C (5 - 113 °F)		
Operating Elevation	0-10000 feet		
Operating Relative Humidity	0 - 95 %		
Operating Temperature	0 - 40 °C (32 - 104 °F)		
Environmental			
Color	Beige		
Shipping Weight	73.00 lbs (33.18 kg)		
Maximum depth dimensions	17.30 inches (43.94 cm)		
Maximum width dimensions	6.70 inches (17.02 cm)		

Conjugue Sumerican Revention version Corp., all rights repensed

Reme | Fraductr | <u>Support</u> | Services | <u>Selectors</u> <u>How to Buy | Contact | Privacy Policy</u>



Battery

Enclosure Type

Voltage Provided

Form Factor

Technology Type

Cabinet Chassis Type

Depth Height

Weight

Width

Dimensions

Humidity Range Operating

Humidity Range Storage

Max Operating

Environmental Parameters

Max Altitude Operating 9840 Ft

External

Proprietary

Battery pack 48 V

Proprietary cabinet

Lead acid

17.3 In

69.2 Lbs

8.5 In

6.7 In

0 - 95%

0 - 95%

104 °F

Temperature	
Max Storage	113 °F
Temperature	22.05
Min Operating Temperature	32 °F
Min Storage	5°F
Temperature	
Header	
Compatibility	PC
Manufacturer	APC
Packaged Quantity	1
Miscellaneous	
Color	Beige
Networking	
Туре	Noлe
Derver Constru	
Power Supply	Need
Power Supply Device Type	None
•••	None
Device Type	None 2 years
Device Type	
Device Type Service Support Details Full Contract Period Support Details	
Device Type Service Support Details Full Contract Period Support Details Service Included	2 years Parts and labor
Device Type Service Support Details Full Contract Period Support Details Service Included Support Details Type	2 years Parts and labor Limited warranty
Device Type Service Support Details Full Contract Period Support Details Service Included	2 years Parts and labor
Device Type Service Support Details Full Contract Period Support Details Service Included Support Details Type Support Type	2 years Parts and labor Limited warranty
Device Type Service Support Details Full Contract Period Support Details Service Included Support Details Type Support Type Slot Provided	2 years Parts and labor Limited warranty 2 years warranty
Device Type Service Support Details Full Contract Period Support Details Service Included Support Details Type Support Type	2 years Parts and labor Limited warranty
Device Type Service Support Details Full Contract Period Support Details Service Included Support Details Type Support Type Slot Provided	2 years Parts and labor Limited warranty 2 years warranty
Device Type Service Support Details Full Contract Period Support Details Service Included Support Details Type Support Type Slot Provided Type	2 years Parts and labor Limited warranty 2 years warranty

Copyright 2003 CDW Computer Centers, Inc. Terms and Conditions of Use | Terms and Conditions of Sale | Privacy Pledge



American Power Conversion Voluntarily Recalls Two Uninterruptible Power Supply Models

WEST KINGSTON, R.I. -- January 14, 2003 -- American Power Conversion (Nasdaq: APCC) (APC), in cooperation with the Consumer Product Safety Commission, today announced a voluntary recall of two models in its Back-UPS® CS uninterruptible power supply (UPS) line due to potential safety issues that may result in overheating and represent a potential fire hazard. The total number of affected devices being recalled worldwide is approximately 2.1 million with approximately 900,000 devices recalled in the United States.

APC has received eight reports worldwide of units overheating resulting in the melting of the unit's outer easing, six of which occurred in the United States. Three of the reported incidents resulted in minor property damage. No injuries have been reported.

The recall is limited to two specific models in APC's Back-UPS CS product line - the Back-UPS CS 350 and the Back-UPS CS 500, in both 120-volt and 230-volt models. The affected units were manufactured between November 2000 and December 2002. The units were sold primarily through computer and electrical distribution, catalog and retail outlets worldwide. Consumers with affected units can identify them by the model markings on the front of the unit and by the serial numbers located on the bottom of the unit. Only units with serial numbers having the first six characters in the following ranges are affected:

AB0048 through AB0251

What's New

BB0104 through BB0251

JB0125 through JB0251

Any units with an "R" at the end of the serial number are not part of the recall.

APC recommends that the user immediately remove the UPS unit from service by turning off all connected equipment, turning the UPS unit off, and then unplugging the unit from the electrical outlet.

To learn more about the recall action and the process for replacing the affected units, users should visit www.apc.com or call 866 APC-RELY (866 272-7359).

APC has been working closely with the Consumer Product Safety Commission and other appropriate parties in this action, which does not affect any other APC devices.

"We remain highly confident in the overall safety and reliability of all of our products, and have been working diligently to ensure that this action results in a minimum inconvenience to our customers and channel partners," said Rodger B. Dowdell, Jr., APC president and CEO.

Safe Harbor Provision

This press release contains forward-looking statements as that term is defined in the Private Securities Litigation Reform Act of 1995. All statements in this press release that do not describe historical facts, such as statements concerning the Company's future plans or prospects and those contained in the "Business Outlook" section of the press release, are forward-looking statements. All forward-looking statements are not guarantees and are subject to risks and uncertainties that could cause actual results to differ from those projected. The factors that could cause actual results to differ materially include the following: costs incurred by the Company for the product recall are greater than or less than currently anticipated; actual audited fourth quarter 2002 results may differ from those currently anticipated; impact on order management and fulfillment, financial reporting and supply chain management processes as a result of the Company's reliance on a variety of computer systems, including Oracle 11i which was implemented in the first quarter 2001; the impact on demand, component availability and pricing, and logistics, and the disruption of Asian manufacturing operations that result from labor disputes, war, acts of terrorism or political instability; ramp up, expansion and rationalization of global manufacturing capacity; the discovery of a latent defect in any of the Company's products; the Company's ability to effectively align operating expenses and production capacity with the current demand environment; general worldwide economic conditions, and, in particular, the possibility that the PC and related markets decline more dramatically than currently anticipated; growth rates in the power protection industry and related industries, including but not limited to the PC, server, networking, telecommunications and enterprise hardware industries; competitive factors and pricing pressures; product mix changes and the potential negative impact on gross margins from such changes; changes in the seasonality of demand patterns; inventory risks due to shifts in market demand; component constraints, shortages and quality; risk of nonpayment of accounts receivable; the uncertainty of the litigation process including risk of an unexpected, unfavorable result of current or future litigation; and the risks described from time to time in the Company's filings with the Securities and Exchange Commission. The Company cautions readers not to place undue reliance on any such forward-looking statements, which speak only as of the date they are made. The Company disclaims any obligation to publicly update or revise any such statements to reflect any change in Company expectations or in events, conditions, or circumstances on which any such statements may be based, or that may affect the likelihood that actual results will differ from those set forth in the forward-looking statements.

About American Power Conversion

Founded in 1981, American Power Conversion (Nasdaq: APCC) (APC) is a leading provider of global, end-to-end infrastructure availability solutions. APC's comprehensive products and services offering, which is designed for both home and corporate environments, improves the availability, manageability and performance of sensitive electronic, network, communication and industrial equipment of all sizes. APC, which is headquartered in West Kingston, Rhode Island, reported sales of \$1.4 billion for the year ended December 31, 2001 and is a Fortune 1000 and S&P 500 company. All trademarks are the property of their owners.

Additional information about APC and its global end-to-end solutions can be found at www.apc.com or by calling 800-877-4080.

NEWS from CPSC

U.S. Consumer Product Safety Commission

Office of Information and Public Affairs

Washington, DC 20207

FOR IMMEDIATE RELEASE January 14, 2003 Release # 03-068 APC Recall Hotline: (866) 272-7359 CPSC Consumer Hotline: (800) 638-2772 CPSC Media Contact: Scott Wolfson, (301) 504-7051

CPSC, American Power Conversion Corp. Announce Recall of Back-Up Power Supply Systems


WASHINGTON, D.C. - In cooperation with the U.S. Consumer Product Safety Commission (CPSC), American Power Conversion Corporation (APC), of West Kingston, R.I., is voluntarily recalling about 900,000 back-up power supply devices. These devices are primarily used to protect computers in case of a power failure. The power supply device can fail, causing the unit to overheat, which may pose a fire hazard to consumers.

APC has received six reports of units overheating resulting in the melting of the unit's outer casing and three reports of minor property damage. No injuries have been reported.

The recalled Back-UPS® CS Uninterruptible Power Supply devices include the Back-UPS CS350 and the Back-UPS CS 500 models. The model number can be found on the front of the unit, along with the words, "Back-UPS CS" and "APC." In addition, one of the following numbers shows up on the bar code label located on the bottom of the unit: BK350, BK500, BK500BLK. The recalled power supply devices also have one of the following serial numbers - AB0048 through AB0251, BB0104 through BB0251, and JB0125 through JB0251 - which can be found on the bottom of the unit. Units with an "R" at the end of the serial number within the above ranges are not part of this recall.

Retailers, computer and electrical distributors, and catalogs nationwide sold the power supply devices from November 2000 through December 2002 for between \$70 and \$130.

Consumers should immediately stop using the power supply devices by turning off the power to all connected equipment, turning the Back- UPS CS off, and then unplugging it from the electrical outlet. To obtain a free replacement unit, consumers should contact the company at (866) APC-RELY (272-7359) between 9 a.m. and 5 p.m. ET Monday through Friday or log on to the company's website at



from 15,000 types of consumer products under the agency's jurisdiction. To report a dangerous product or a product-related lajury, call CPSC's hotine at (800) 638-2772 or CPSC's teletypewriter at (800) 638-8270, or visit CPSC's web site at the state of the site of the s



030129CCN0301 EXHIBIT 7

EFI Buginsering and Bres Investigations

303 Quad angl. Drive Suite 363 Bokinghrow 1, 11 60440 7: 800-69 + 19: 5 P: 630-6: -----

.

EFI FAX TRANSMITTAL

FAX 830 679 1535

DATE:	3-1-03
TO:	ALAN R. KERN
COMPANY:	CPSC
FAX NO:	775-667-7434
FROM:	JMUN20/EFI
COMMENTS:	
Please ful at	tached the last of ITONS collected
	Hospital including the Backing host
	PS unit. The JOINT EXAM has
	Schidulid YET! FEEL Free TO
call me .	4 you have Questions
	John
	NUMBER OF PAGES: 4

030129CCN0301 Exhibit 7 Inventory of items collected

Richard M. Hansen & Associates, Inc.

950 DuPage Avenu Lombard, IL 6014 (630) 495-385 Fax: (630) 495-394

Evidence File No. 03-1024 as of February 14, 2003

.....

Evidence No.	Eil<u>e No</u>,	Date Collected	Time Collected	Description
1	03-1024	1/26/03		AT&T switch
2	03-1024	1/28/03	1147 HRS	Qubet #2
3	03-1024	1/28/03	1147 HRS	Conduit to outlet #1
4	03-1024	1/28/03	1 153 HRS	Distribution panel
5	03-1024	1/28/03		Junction box & outlet
6	03-1024	1/28/03		Switch to fluorescent
7	03-1024	1/28/03	1611 HRS	Cullet
8	03-1024	1/28/03	1545 HRS	Fluorescent fixture
9	03-1024	1/28/03	1057 HRS	Ceiling fain housing
10	03-1024	1/28/03		foontified components
11	03-1024	1/28/03	915 HRS	Printer
12	03-1024	1/26/03	1045 HRS	CRT Mounting panels& cable
13	03-1024	1/28/03	937 HRS	Telephone
14	03-1024	1/28/03	1115 HR9	Documents from shelf
15	03-1024	1/28/03	1051 HRS	Telephone & Unidentified unit
16	03-1024	1/28/03	1130 HRS	Telephone blocks
17	03-1024	1/28/03		Oebris
18	03-1024	1/28/03	[110 HRS	Bag of debris
19	03-1024	1/26/03	1105 HRS	Bag of debris
20	03-1024	1/28/03		Junction box for five alarm
21	03-1024	1/26/03	1142 HRS	Transler unit
22	03-1024	1/26/03	1140 HRS	Emergency transfer
23	03-1024	1/26/03		Telephone jacks
24	03-1024	1/26/03	1141 HRS	Emergence transfer unit
25	03-1024	1/28/03		Debris from floor
26	03-1024	1/28/03		Glass remains
27	03-4024	1/28/03	1143 HRS	Transler unit component

-- --

Richard M. Hansen & Associates, Inc.

950 DuPage Avenue Lombard, IL 60148 (630) 496-3853 Fax: (630) 495-3947

7

Evidence File No. 03-1024 as of February 14, 2003

Evidence No. File No. Date Collected Time Collected

28	03-1024	1/28/03		UPS & unidentified control box
29	03-1024	1/26/03		Components from shelf
30	03-1024	1/28/03	1039 HRS	Front panel
31	03-1024	1/28/03		Osta reci
32	03-1024	1/28/03	1140 HRS	Shelf from east
33	03-1024	1/28/03	1145 HRS	Debris from shelf
34	03-1024	1/28/03	1151 HRS	UPS
35	03-1024	1/29/03		Cables from above telephone cluset
36	03-1024	2/14/03		Breaker

Description

84	CDWD Computing Solutions Built for Russiness				ORDER PACKIN	
PAGE	bwillbahv.com				PAGE 1	of 1
	GLEN ELLYN GLINIC/ DMG	COW COMPUTER CENTERS TECHNOLOGY DRIVE WEDESBORO, NJ 08085		01/14/03	CUSTOMEN PO REF	040 # 1
EFI MUNRO	CURTOMER DONTAGE NOHN TEM 1 A 1 A CONTAINER ID: SN: WS02501 SN: WS02501 SHIP VIA: WATKINS PACKER: TERRI PATTI	SU2200XLTNET 73130400790	6 SMARTU CONTAI WCP-00	IPS 2200 XL NER ID	208V 5RCPTL 208V 5RCPTL WEIGHT NUMBER OF PIECES 156.00 1	
8476355853	,	Bu Bu	mpatiog S ilt for Elast xv.chv.co	11:255		
14:06						
E002/10/E0			<u></u>			

Task Number: _030129CCN0301_

Date: ___03/13/03_____

Status of Missing Document(s)

As of this writing, official records that were requested for this investigation report could not be obtained. Should a document later become available, it will be attached to the investigation report.

1.	Fire Investigation Report – (Exhibit #8)
2.	
3.	
4.	
5.	
э.	·

Exhibit 9: 030129CCN0301

INVESTIGATIVE CONTACTS:

<u>NAME</u>	ADDRESS /PHONE	DATE
(b)(6) Fire Lieutenant	Naperville Fire Dept Naperville, IL (630) 420-6142	01/28/03
(b)(6) Director of Safety	Edward Hospital 801 S. Washington St. Naperville, IL 60540 (630) 527-7247	02/06/03 02/11/03
(b)(6) File Cillel	Edward Hospital Naperville, IL	02/11/03
ITS Manager	DuPage Medical Group 454 Pennsylvania Ave Glen Ellyn, IL 60137 (630) 545-3615	0212/03 03/11/03
ыка Fire Investigator	Engineering & Fire Investigations (EFI) 303 Quadrangle Dr. Suite 303 Bolingbrook, IL 60440 (847) 635-5053	02/13/03 02/14/03 03/01/03

.



Ann DeTemple Director United States Consumer Product Safety Commission National Injury Information Clearinghouse 4330 East West Highway Room 504 Bethesda, Maryland 20814 SENT VIA FEDEX

RE: 030129CCN0301, 76 310 310A H0310215A, 1031312A, C0325001A, H0310361A, 10310440

April 11, 2003

Dear Ms. De l'emple:

Thank you for your letter dated March 31, 2003 regarding the above referenced incidents allegedly involving our products. In regards to Claims #030129CCN0301 and #C0325001A, we have been notified by the customers of the incidents and our respective insurance companies are conducting formal investigations. With regard to Claim #H0310215A, it is our understanding that this issue has been resolved to the customer's satisfaction. Finally, we have not, to the best of our knowledge, receive any claims or information related to Claims #I031312A, #H0310361A and #I0310440.

American Power Conversion Corporation takes the design and manufacture of its products extremely seriously. We appreciate the Consumer Products Safety Commission contacting us regarding this matter. If there is anything else we can do, please do not hesitate to contact me directly at (401) 789-5735 x2255.

Once again, thank you for your letter.

Peter, Wexler Senior Counsel American Power Conversion Corporation

 American Power Conversion Corporation

 P0 Box 278
 Coll 401 789 5735

 132 Fairgrounds Road
 Fax 401 789 3710

 West Kingston, RI 02892
 Visit www.apcc.com

 APC is a squal opportunity employes wit chively workforce diversity.
 APCs quelity system is 50 602 curied.

rom:	Robin Ross	nrossjr@wi.rr.com}		
Sent:	Tuesday, Jai	uary 28, 2003 1:47	-T.D #	
fo:	Peggy Hama	nn		100 ml
c:	Alan Kem	61) 31 # 0294 A 030	129CCN0301
Subject:		a doctors' offices.htm		
-	-		ncident. Apparently it was start	ed by an APC brand
		pply unit. Assign to Al K	• • •	
Thanks	i			
S	Naparville	NAPERVILLE SU	IN: Mayors say county's O'Hare vote	· ** 29°
•	alibicagoNewaco		A DE NEVE SUIT Sun Publications	GET HOME
	rketplace	na na sense na sense na sense de la se La sense de la s		
Autos	ncipiero			TUESDAY JANUARY 28. 2003
Classifie		Fire damages docto	rs' offices	
JobPlace New Hor	+			
Real Est		SUN STAFF		VOTE: Should local prosecutors attempt to
Comm	unity News			negate former Gov. Ryan's
Local He			pus Saturday morning did more than \$250,00) commutations of death rov inmates?
Mileston	ies Morid News	worth of damage to a doctors' office	building at 100 Spaulding Drive.	SPECIAL SECTIONS
News in		Nanorville Fire Demutionant Distric	t Chief Richard I. Mikel renormal Saturday th	
Busines	-	Naperville Fire Department District Chief Richard J. Mikel reported Saturday that about 20 people were evacuated from the building. No one was injured. The fire		
Weather			t 8 a.m. on the third floor of the four-story	
O Columni	pinions etc	in the scene as suppression efforts b	d to a second alarm, bringing additional fire u coan. Mikel said in a oress release	
E-The Pe				The U.S. war State's new
Editorial	•	The responding 35 Naperville fire	ighters and 12 pieces of equipment brought th	
	o the Editor	fire under control in about 30 minut	¢\$.	FEATURED ADVERTISERS
Quick Po Mare Opin				
	& About		vice president of marketing and communication ibility that it was an electrical fire. The building	
Arts		in which outpatient services are pro	vided, is not attached to the hospital but is	_
Books	_	connected by an exterior tunnel. The investigating the cause of the fire.	c Naperville Fire Investigation team is	SUN PUBLICATIONS
Galendar Chicago				More Sun Publications you can read online:
Dining		01/26/03		[‡] Batavia Sun
	od Update		55	" Bolingbrook Sun " Downers Grove Sun
Home & I Just for I	•		FEB 0 4 2003	* Fox Valley Sun
Movies			FFBU	* Geneva Sun * Gien Eilyn Sun
Music			1	* Homer Sun * Lincoln-Way Sun
Televisio Travel				" Lisle Sun
Video Ga	77185		- 19 .	* Naperville Sun * Plainfield Sun
Videos			166UE	* St. Charles Sun
Web Wat			14-	* Wheaton Sun
Hear Local Fea	t & Home atures			GET DAILY HEADLINES
/28/03				HERBEITED

1. Task Number 030701CCN0667		2.	2. Investigator's ID 9032		EPIDEMIOLOGIC	
3. Office Code 4. Date of Accident		dent 5	Date Initiated		INVESTIGATION	
	YR MO DA		YR MO DAY		REPORT	
830	2003 06 0	1	2003 07 08			
5. Synopsis of Accid	ent or Complaint	UF	×C			
unit. They found the would no longer sliv had oozed out. The	at the plastic cases de out of the unit. 9 unit itself had acid	of all four of th Some of them) I burns on the i	_	and/or me ped off and bottom pla a fire.	Ited to the point they some electrolyte (acid) ite. Complainant was $\frac{1}{12} \frac{1}{12} \frac{1}{12}$	
. Location (Home, S	• •		City		9. State	
7 - INDUSTRIAL PL	ACE		INCOLN,		NE	
0A. First Product 557 - Computers (e			Trade/Brand Name RT-UPS UNINTERRUPTIBLE POWER		10C. Model Number SMART-UPS 1400RM	
132 Fairgr	PORATE HEADQU ounds Road on, RI 02892	11B. Trade/E	Brand Name		11C. Model Number	
	0 NON)NE		NONE	
0 11D. Manufacturer N NONE			14. Disposition		. Injury Diagnosis	
0 11D. Manufacturer N NONE	ame and Address 13. Sex 1 - Male		14. Disposition 0 - No Injury		. Injury Diagnosis 70 - No Injury	
D 11D. Manufacturer N NONE 12. Age of Victim 0	13. Sex	Jent				
0 11D. Manufacturer N NONE 12. Age of Victim 0 16. Body Part(s) Involved 99 - NO INJURY	13. Sex 1 - Male 17. Respond 2 - Eyewith	Jent	0 - No Injury 18. Type of Investigatio 2 - Telephone	on 19	70 - No Injury . Time Spent (Operational / Travel)	
0 11D. Manufacturer N NONE 12. Age of Victim 0 16. Body Part(s) Involved 99 - NO INJURY	13. Sex 1 - Male 17. Respond 2 - Eyewith	Jent ess	0 - No Injury 18. Type of Investigation 2 - Telephone Ce	on 19	70 - No Injury . Time Spent (Operational / Travel) 11 / 0	
0 11D. Manufacturer N NONE 12. Age of Victim 0 16. Body Part(s) Involved 99 - NO INJURY 20. Attachment(s) 1 - Photographs	13. Sex 1 - Male 17. Respond 2 - Eyewith	dent ess 21. Case Sourc 07 - Consume NEISS Cases C	0 - No Injury 18. Type of Investigatio 2 - Telephone r Complaint	on 19	70 - No Injury . Time Spent (Operational / Travel) 11 / 0	
0 11D. Manufacturer N NONE 12. Age of Victim 0 16. Body Part(s) Involved 99 - NO INJURY 20. Attachment(s) 1 - Photographs 23. Permission to Dis () Yes	13. Sex 1 - Male 17. Respond 2 - Eyewith close Name (Non	dent ess 21. Case Source 07 - Consume NEISS Cases C V	0 - No Injury 18. Type of Investigation 2 - Telephone ce r Complaint Dnly) erbal	on 19 22. Samp	70 - No Injury . Time Spent (Operational / Travel) 11 / 0	
0 11D. Manufacturer N NONE 12. Age of Victim 0 16. Body Part(s) Involved 99 - NO INJURY 20. Attachment(s) 1 - Photographs 23. Permission to Dis	13. Sex 1 - Male 17. Respond 2 - Eyewith 2 - Eyewith 2 - Eyewith 2 - Eyewith 2 - No	dent ess 21. Case Source 07 - Consume NEISS Cases C V	0 - No Injury 18. Type of Investigation 2 - Telephone r Complaint Only) erbal 26. F	on 19 22. Samp	70 - No Injury . Time Spent (Operational / Travel) 11 / 0 fe Collection Number	
0 11D. Manufacturer N NONE 12. Age of Victim 0 16. Body Part(s) Involved 99 - NO INJURY 20. Attachment(s) 1 - Photographs 23. Permission to Dis () Yes 24. Review Date	13. Sex 1 - Male 17. Respond 2 - Eyewith close Name (Non No 25. Reviewed B	dent ess 21. Case Source 07 - Consume NEISS Cases C V	0 - No Injury 18. Type of Investigation 2 - Telephone r Complaint Only) erbal 26. F Eric	22. Samp 22. Samp Regional Of 5 B. Ault	70 - No Injury . Time Spent (Operational / Travel) 11 / 0 le Collection Number	


03029

CPSC FORM 182 (12/98) Approved for use through 07/31/2003 OMB NO, 30410029

IDI: # 030701CCN0667 Smart-UPS 1400RM

IDENTITY OF RESPONDENT(S)

The respondents in this investigation are:



IDI # 030701CCN0667 Smart-UPS 1400RM Uninterruptible Power Supplies Page 1

PRE-INCIDENT

The Complainant's company has approximately 18 "American Power Conversion "Uninterruptible Power Supplies" (UPS's) installed in the company's network wiring closets and server racks. In general they have been very satisfied with them.

NOTE: APC Smart-UPS protects data by supplying reliable, network-grade power in either traditional Tower or Rack – optimized form factors for space constrained business critical applications; protects business critical fileservers, minicomputers, network switches and hubs, Point of Sales retail/bank office and ATM's.

Recently, June 2003, one of the units (a Smart-UPS 1400RM) indicated it needed to have the batteries replaced; they had replaced several battery replacements before just not on this unit.

INCIDENT

When attempting to remove the batteries from the unit, the batteries wouldn't budge, not even when pulled on quite hard. Over the weekend, the Complainant had his network administrator come in and replace the faulty unit with a working one. When they opened up the failed UPS, they found that the plastic cases of all four of the batteries had swollen up and/or melted to the point they would no longer slide out of the UPS. Some of them had the caps partially popped off and some electrolyte (acid) had oozed out.

POST-INCIDENT

The Complainant stated that the red "replace battery" light had come on two or three months before they tried to replace the batteries. He stated they were working under the assumption that the worst thing that would happen if they weren't replaced was that the UPS would no longer provide backup power. He thinks that the set of batteries came with the UPS. You can see (see Photo 1) the APC tag on the battery. There is a load meter and volt meter on this system; it has one LED bar graph on the front for system load, and a second one for battery voltage.

The Complainant had a similar incident (whose batteries were no more than six months old at the time of the incident) on a non-rack-mount Smart-UPS at his home. He smelled sulphur one morning and eventually tracked it down to the Smart-UPS. The batteries had

IDI # 030701CCN0667 Smart-UPS 1400RM Uninterruptible Power Supplies Page 2

swollen up and were hissing and sputtering acid out the caps and the whole unit was almost too hot to touch.

In a prior incident, the Complainant wrote to the company, APC, about the incident that occurred in his home. Complainant was told by the company that he would need to buy another unit since it was out of warranty. He then explained that he had been under the assumption that since the UPS measures its internal temperature, voltage, current draw, etc, it should have detected whatever the problem condition was and shut down or given an alarm; he has never received what he considers to be a satisfactory answer from the company. He stated the issue is not buying a new UPS. The issue is the fact that this unit might well have started a fire, burning down his house and killing his pets if they had not been home, noticed the problem and disconnected the UPS. Complainant was so frightened by this incident that they have not been using a UPS at home for the past year, simply because they are terrified of what might happen while they are gone from home.

The Complainant stated that the recent failure of one of the products at his company, in what appears to be a similar manner, has led him to think that what happened with the unit at home is not an isolated incident.

He stated that they contacted the manufacturer twice and they did not seem too concerned; they basically brushed it off by saying that it was an older unit, and they offered to dispose of the unit for his company free of charge.

The Complainant stated that he is not aware of any damage to his equipment; however, the UPS itself has some pretty good acid burns on the inside of the lid and inside the bottom plate. As hydrogen is explosive, he was somewhat concerned that the boiling batteries could have exploded or started a fire.

PRODUCT IDENTIFICATION

The product involved is an Uninterruptible Power Supply:

- Smart-UPS 1400 RM
- Serial # S95035753705

The Smart-UPS 1400RM consists of four 12V7AH-F2 batteries that go into the Smart-UPS 1400RM. The Complainant stated it is the size of a bread box and weighs approximately 200 pounds.

IDI # 030701CCN0667 Smart-UPS 1400RM Uninterruptible Power Supplies Page 3

The Complainant stated that he is not certain how old the Smart-UPS 1400RM unit is however, he thinks it might be at least a few years old and the batteries may have been original equipment.

APC Corporate Headquarters:

 132 Fairgrounds Road W. Kingston Rhode Island 02892 (800)788-2208

> Technical Support – 800-555-2725 Battery Sales – 800-300-7141 Customer Service – 877-800-4272 Government Team – 800-788-5414 - <u>www.govteam@apec.com</u> Website Info - <u>http://www.apec.com/products/family/index.cfm?id=165</u>

> > .


NOTE

"No other reports will be forthcoming." This is a telephone investigation rather than an On-Site due to distance.

ATTACHMENTS

- 1. Respondents
- 2. Internet Photo of the Smart-UPS
- 3. Photographs(8)


MART O		DEDIA PLACEING CLEARANC
Search	The Battery Experts	Call us toll-free
		Ed
TECHNIC AND		Quan
		Legin
> 2-Way Radio	SmartUPS 1400RM	8 8 (₁) 1 1 1
🤌 Aikaline (AA, Sv. etc)		
> Barcoris Scanner		
r Cancolder		
⇒ Camera	100 march 2010 A 2 1 20 - 5 2 1 20 - 5 2 -	
> Cell Phone	Four 12V7AH-F2 Batteries Code: SLA-12V7-F2-X4	5.04
> Cordens Phone	Price: \$47.80	
> Custom Sattery Pack	Quantity in Cart: none	
> Örgilat Camera		
> Electromics / Watch		
» Colf Castly	Add to cart	
> Hawker ODYSSEY	calcules shipping	
> Hearing Aid		ê. Ar
> Lapto-p Computer	UP3 Satteries > APC > SmartUPS 1400RM	
> Motorcycle / ATV		
> CPTIMA Belienes-		
> Rectargestics		
≫ Robelt		Hawk
> SLA / Gal Cell		
* Specially		
> 10:		
7 ()	Task# 030701CCN0667	
> vvheetonar	Exhibit 2	
m	Page 1 of 1	
		D.
> Battery Chargers	k	
> Battery Maintainers		
> Battery Met		
> Battery Teolets		
> Battery MinDer		
> Ostran Chargers		M821
> Dual Pro-		
* Pasitights		
> Jaina Produne		
> Junya Statlara		
> Power ly vertiens		
* Priority Stan		
> Soler Chargens		Sub:
		[
		E. I.



Task# 030701CCN0667 – Photo 1 – The UPS tag/APC tag on the battery.




Task # 030701 CCN0667 – Photo 2 – Top of the battery on the Smart-UPS 1400RM



Task# 030701CCN0667 - Photo 3 - Top of the Battery




Task# 030701CCN0667 - Photo 4 - Fuses



Task# 030701CCN0667 - Photo 5 - Closer view of the fuses.



Task# 030701CCN0667 - Photo 6 - Damaged UPS lid.



Task# 030701CCN0667 - Photo 7 - Close-up of the damaged UPS lid.



Task# 030701 CCN0667 - Photo 8 - Battery Tag



Ann DeTemple Director United States Consumer Product Safety Commission National Injury Information Clearinghouse 4330 East West Highway Room 504 Bethesda, Maryland 20814 SENT VIA FEDEX

RE: 030701CCN0667, 030710CCN506, H0370020A, H0370053A October 22, 2003

Dear Ms. DeTemple:

Thank you for your letter dated August 29, 2003 regarding the above referenced incidents allegedly involving our products. In regards to Claims #030710CCN0706, we did receive a report from the customer, but the customer has not returned the unit so that we may conduct a failure analysis. In regards to Claims #030710CCN0706, we did receive a report from the customer and have received and reviewed the unit. Our analysis to date indicates a external overvolatge event to the surge unit was the root cause of the unit failure. We have offered to replace the customer's unit. We have very little information regarding Claim #H0370053A and have not received the unit for evaluation, however, it is our understanding that a new unit was sent to the customer. Finally, we have not, to the best of our knowledge, receive any claims or information related to Claim # 030701CCN0667.

We appreciate the Consumer Products Safety Commission contacting us regarding these matters. Please contact us immediately if there are any further developments in any of these cases. If there is anything else we can do, please do not hesitate to contact me directly at (401) 789-5735 x2255.

Once again, thank you for your letter.

Peter Wexler Associate General Counsel American Power Conversion Corporation

American Power Conversion Corporation

P0 Bux 278	Call 401 789 5735
132 Fairgrounds Road	Fox: 401 789 3710
West Kingston, R ⁱ 02892	Visit www.apcc.com
400 C	

APD is an equal opportantly annough which values workforce diversity APD's gos ity system is ISU 2002 centilied

Pulley, Autumn S	ISBUE	4 0		1 2003				
From:	Pucciarelli, Ellen M							
Sent:	Monday, June 30, 2003 4:57 PM							
То:	Emerging Hazards; Hazard; Internet Incident Reports, Clearinghouse; Incident Reports							
Cc:	Cohn, Murray S.							
Subject:	Internet Form Complaint - Doc #10360461							

1111

1 2000

6/30/2003 2:49:57 PM

Name = (b)(6) Address City = Lincoln State = NE Zip = 68522 Email = (b)(6) Telepho Name of Victim = Victim's Address = Victim's City = Victim's State = Victim's Zip = Victim's Telephone =

Incident Description: We have approximately 18 American Power Conversion "Uninterruptable Power Supplies" (UPS's) installed in our network wiring closets and server racks, and in general I've been very satisfied with them. Recently, one of them (a Smart-UPS 1400RM) indicated it needed to have the batteries replaced. We've done several before, but when we tried to remove the batteries from this unit, they wouldn't budge, not even when pulled on quite hard. Over the weekend, I had my network administrator come in and replace the faulty unit with a working one. When we opened up the failed UPS, we found that the plastic cases of all four of the batteries had swollen up and/or melted to the point they would no longer slide out of the UPS. Some of them have the caps partially popped off, and some electrolyte (acid) has oozed out. I had a similar incident (whose batteries were no more than 6 months old at the rime) on a non-rack-mount Smart-UPS at my home. We smelled sulphur one morning when we got up, and eventually tracked it down to the Smart-UPS. The batteries had swollen up and were hissing and sputtering acid out the caps and the whole unit was almost too hot to touch. I wrote to APC about that incident some time ago, and was told that I would need to buy another unit since it was out of warranty. I explained that I had been under the assumption that since the UPS measures its internal temperature, voltage, current draw, etc, it should have detected whatever the problem condition was and shut down or given an alarm, but I have never received what I consider to be a satisfactory answer from the company. The issue is not buying a new UPS. The issue is the fact that this unit might well have started a fire, burning down my house and killing my pets if we hadn't been home, noticed the problem, and disconnected the UPS. We were so frightened by this incident that we have not been using a UPS at home for the past year, simply because we're terrified of what might happen while we're gone. The recent failure of one of the products at my company in what appears to be a similar manner has led me to think that what happened with the unit at home is not an isolated

1

incident. How would you suggest we proceed on this issue? Victim's age at time of incident = Victim's sex = Date of incident = June, 2003 Product involved = Smart-UPS (Uninterruptable Power Supply) Product brand name/manufacturer = American Power Conversion Place where manufactured (City and State) = USA/Unknown Product involved still available = Yes Product model and serial number = Smart UPS 1400RM, s/n S95035753705 Date product purchased = unknown Name Release = Release name to manufacturer only

						Ø,	
1. Task Number			2. Investigator's ID			EPIDEMIOLOGIC	
040720CNE1669			9094		E		
3. Office Code	4. Date of Accide	ent 5. Da	ate initiated		7	INVESTIGATION	
	YR MO DAY	() () () () () () () () () ()	YR MO DAY		- }	REPORT	
810	2004 07 18	20	004 07 26				
Synopsis of Accident An adult female (age u battery back-up units t	inknown) reporte		g from battery back				
battery back-up unit w unit involved in the inci		hen she checke	ad. There were na i	njuries, :		age was confined to the	
7. Location (Home, School, etc)			8. City			9. State	
	1-HOME		FORT WALTON BEACH			FL	
0 A. First Product 557 - Computers (equ	i mana a sel El se	-	de/Brand Name			10C. Model Number 1500	
132 Fairgrou West Kingsto							
11A. Second Product			de/Brand Name			11C. Model Number	
0		NONE				NONE	
11D. Manufacturer Nan NONE	ne and Address						
12. Age of Victim	13. \$ex		14. Disposition [1		1!	5. Injury Diagnosis	
43	2 - Female		0 - No Injury			70 - No Injury	
16. Body Part(s) Involved 99 - NO INJURY	17. Respond	lent omplainant	18. Type of Investigation 2 - Telephone		19	9. Time Spent (Operational / Travel) 21 / 0	
20. Attachment(s)	I2	1. Case Sourc			22. Sam	ple Collection Number	
9 - Multiple Attachmer			umer Complaint				
3. Permission to Discl	lose Name (Non I	NEISS Cases O	nly)				
🔿 Yes	No	O Ve	erbal				
24. Review Date	25. Reviewed B	y		26. Re	gional O	ffice Director	
09/01/2004	8169				- d J. Nay		
27. Distribution Deppa, Roy W.; Pigot	t, Mary K.; Dobbii	ns, Allen C.; Lar	nsing, Joseph W	1	urce Do)345A	cument Number	

•

· ·

~ ~ ~ ~ ~ ~ ~

CPSC FORM 182 (12/96) Approved for use through 09/30/2006 OMB NO. 30410029

040720CNE1669

This investigation was initiated from a consumer internet complaint form.

Initial contact was made by this investigator on July 26, 2004. At this time, the complainant was unavailable for an interview. However, the complainant's spouse indicated that the incident product was no longer available, as it had been returned to the manufacturer for a replacement.

Since no sample was available for photographing or collecting, a telephone interview was conducted with the complainant on August 2, 2004. During this interview, the complainant provided the information contained in this report. The complainant also indicated that she would provide photographs of the area in which the incident product was located. However, these photographs were not received.

The complainant involved in this incident is a female. She did not provide her age, height, or weight during the interview.

The product involved is an uninterruptible power source (UPS) battery unit for use with computers. The complainant stated that she used this UPS as one of four battery back-ups for seven computers that she uses in her consulting business. She stated that she has used three different models of battery back-up units, and has had trouble with this model twice. She has never experienced problems with the other models.

The incident occurred at the complainant's place of business. The complainant stated that the UPS battery unit was located in a room with three other UPS units, stacked two deep and two wide (Attachment 2, Page 1). All four units operated off house current and were on the same circuit.

The temperature inside the room was 74° F, according to a thermometer adjacent to the battery back-up units.

The incident reported to CPSC occurred July 18, 2004. However, the consumer stated in the telephone interview that she had experienced a similar incident with an identical unit in March or April of 2004.

The complainant stated that the unit involved in the second (reported) incident was obtained from the manufacturer as a replacement for the unit involved in the earlier incident. The unit involved in the second incident had been in use continually for four or five months prior to the second incident. The unit involved in the earlier incident had been in use for a year prior to the first incident. (An identical model unit--not involved in either incident--has been in use for eighteen months with no problems.)

The complainant stated that she did not read the instructions that accompanied the unit involved in the second incident, since she had the m previously with the original units. She placed the incident unit on top of another unit of the same model (Attachment 2,

040720CNE1669

Page 1). These two units were placed on the outside of a stack of four UPS battery units (Attachment 2, Page 1).

At approximately 10:00 a.m. on July 18, 2004, the complainant was in the room where four UPS battery units were located. She said that she heard a "pop" and smelled something funny. Then she saw smoke coming out of the incident unit. She said that the inside of the incident unit was glowing red when she looked at it.

The complainant unplugged the incident unit and discontinued its use immediately. She reported the incident to CPSC on the day it occurred.

On July 19, 2004, the complainant contacted the manufacturer by telephone. She said that the manufacturer's representative with whom she spoke told her that they had not received any other complaints about similar incidents with this model unit.

The complainant said that the manufacturer's representative told her that there are modules in the top of the unit that are designed to pop if the unit overheats. The manufacturer's representative told the complainant that the unit is not supposed to catch fire, though.

The complainant stated that the point of origin in both incidents was at the top of the unit near the back. Although there were no flames involved in the second incident, the complainant said that flames spread outside the unit involved in the previous incident.

The complainant further stated that the manufacturer's representative told her that she should place the UPS battery unit twelve inches away from everything else. The complainant indicated that she does not follow this advice.

PRODUCT IDENTIFICATION:

The product involved in both incidents is an **APC Smart UPS 1500**. Identifying information about the product and the manufacturer is included below:

Brand Name:	APS Smart UPS				
Model Number:	1 500				
Serial Number:	Unknown				
Manufacturer:	American Power Conversion Corp				
Address:	132 Fairground Road				
	West Kingston, RI 02892				
Place of Manufacture:	Unknown				

The product operates off house current. It was on the same circuit as another APC Smart UPS 1500 unit, an APC Smart UPS 1400 unit, and an APC Smart UPS 500 unit. The complainant has not had any problems with the other three units on the circuit. However, she has experienced the same problem twice with APC Smart UPS 1500 units.

040720CNE1669

As the incident unit was not photographed or collected, no information about labeling is available.

SAMPLE:

No sample was collected.

ATTACHMENTS:

Attachment 1 – Contact Sheet Attachment 2 – Diagram of Units at Incident Location Attachment 3 – Missing Documents Form .

List of Contacts

Name:	(b)(6)
Title:	
Address:	
	Fort Walton Beach, FL 32547
Phone:	(b)(6)
Interviewed	August 2, 2004
	Follow-up on August 26, 2004 (via e-mail)

Information from interview is contained in narrative. Photographs were requested but were not provided.

Name:	(b)(6)
Title:	
Address:	
	Fort Walton Beach, FL 32547
Phone:	(b)(6)
Interviewed:	July 26, 2004 and August 26, 2004


On both occasions, the complainant's spouse indicated that the complainant was too busy to talk to the investigator.

.

Diagram of Product Positioning

(Drawn by Investigator, based on information provided by complainant)

÷



•

Page 1 of 1 MKP .

Task No:040720CNE1669 Date: 08/31/2004

STATUS OF MISSING DOCUMENT(S)

The official records below were request for this investigation report, but could not be obtained.

1.	Photographs of incident location (requested from complainant)
2.	Records of correspondence with manufacturer (not available)
3	
4	
5	· · · · · · · · · · · · · · · · · · ·

Date: 08/31/2004		Investigation No.	9094
Regional Office:	FOER	Supervisor No:	



February 11, 2005

Ann DeTemple, Director United States Consumer Product Safety Commission National Injury Information Clearinghouse 4330 East West Highway Room 504 Bethesda, Maryland 20814

SENT VIA FEDEX

040720CNE1669 /

Dear Ms. DeTemple:

RE:

Thank you for your letter dated October 29, 2004 regarding the above referenced incident ("Claim") involving our product APC Smart UPS SUA 1500. We have read the report in detail and we reviewed our support center files regarding the two incidents claimant reported. In both instances, claimant's units were returned to APC for review and were replaced with new units. On both occasions, we reviewed the units and we were able to repair the units that were, otherwise, in good operating condition. It is our determination that the consecutive incidents were purely coincidental.

We appreciate the Consumer Products Safety Commission contacting us regarding these matters. Please contact us immediately if there are any further developments in any of these cases. If there is anything else we can do, please do not hesitate to contact me directly at (401) 789-5735 x2255.

Once again, thank you for your letter.

Very truly hour

Peter Wexter Associate General Counsel American Power Conversion Corporation

American Power Conversion Corporation PO Box 273 Call 401 789 5735 132 Forrgrounds Road Fax: 401 789 3710 West Kingston, Ri 02902

Visit www.apue.com LPC is an equili apportative employer while it was service to real diversity APUS give its existent is ISO 0.902 carlined. Doc No: 10470345A

07/18/20	004 10:32:53		
	(b)(6)		
Name =	(
Address	i		
City = I	Fort Walton E	Beach	
State =	Florida		
Zip = 32			
Email =	(b)(6)		
Telepho		i se T	
Name o		1	
Victim's			X
Victim's	City = Fort	Walton Bea	ch
Victim's	State = Flor	ida	
	Zip = 32547		
Victim's	Telephone =	(b)(6)	

Incident Description: An APC Smart UPS 1500 was smoken and was on fire. Approxiametly 4 months ago we had another unit do the same thing. We

contacted APC and they sent a replacement unit. The replacement unit is the item that was on fire again. We have three models of APC

and this is the only model that we are having this problem with.

Victim's age at time of incident = 43 Victim's sex = Female Date of incident = 7/18/04 Product involved = APC Smart UPS Product brand name/manufacturer = APC Place where manufactured (City and State or Country) = Product involved still available = Yes Product model and serial number, manufacture date = SUA 1500 Date product purchased = Less than 4 months Name Release = Release name to manufacturer only

.

057415-

		2. 10	vestigator's ID 9048			EPIDEMIOLOGIC
3. Office Code	4. Date of Acci YR MO D		Date Initiated YR MO DAY 2004 12 01			
840	2004 11 1	3 2				
8. Synopsis of Acci	dent or Complaint	UPO	C na			
began to smoke a	ind produce an odo	r of burning plast	ic. She immediatel red it from its recep	у ійгле	d off the 0 minute	y back-up unit when it o unit angunplugged all es later, it was still warm
7. Location (Home,	School, etc)	8. C		0		9. State
	<u> </u>					10C. Model Number
10A. First Product	(equipment And EL		10B. Trade/Brand Name APC BACK-UPS OFFICE 500 VA			BF500
	AN POWER CONVI	RSION				
132 Fair	grounds Road ston, RI 02892	11B. Trade/B	rand Name			11C. Model Number
132 Fair W. King 11A. Second Produ	grounds Road ston, RI 02892	11B. Trade/B	rand Name			11C. Model Number
132 Fair W. King 11A. Second Produ	grounds Road ston, RI 02892 uct	11B. Trade/B	rand Name			11C. Model Number
132 Fair W. King 11A. Second Produ 11D. Manufacturer	grounds Road ston, RI 02892 uct Name and Addres	11B, Trade/B				
132 Fair W. King 11A. Second Produ 11D. Manufacturer 12. Age of Victim 44 16. Body Part(s) (nvolved	rgrounds Road ston, RI 02892 uct Name and Addres 13. Sex 2 - Fema 17. Respo	11B. Trade/B s le ndent	14. Disposition 0 - No Injury 18. Type of Inves	tigatio	n	15. Injury Diagnosis 70 - No Injury 19. Time Spent (Operational / Trave
132 Fair W. King 11A. Second Produ 11D. Manufacturer 12. Age of Victim 44 16. Body Part(s) (nvolved 99 - NO INJURY 20. Attachment(s)	grounds Road ston, RI 02892 uct Name and Addres 13. Sex 2 - Fema 17. Respo 1 - Victim	11B. Trade/B s le ndent /Complainant 21. Case Source	14. Disposition 0 - No Injury 18. Type of Inves 1 - On-Site	tigatio	22. Sa	15. Injury Diagnosis 70 - No Injury 19. Time Spent {Operational / Trave 19 / 1 mple Collection Numbe
132 Fair W. King 11A. Second Produ 11D. Manufacture 11D. Manufacture 12. Age of Victim 44 16. Body Part(s) (nvolved 99 - NO INJURY 20. Attachment(s) 9 - Multiple Attacl	grounds Road ston, RI 02892 uct Name and Addres 13. Sex 2 - Fema 17. Respo 1 - Victim	11B. Trade/B s le ndent /Complainant 21. Case Sourc 07 - Consume	14. Disposition 0 - No Injury 18. Type of Inves 1 - On-Site se r Complaint	tigatio	22. Sa	15. Injury Diagnosis 70 - No Injury 19. Time Spent {Operational / Trave 19 / 1
132 Fair W. King 11A. Second Produ 11D. Manufacture 11D. Manufacture 12. Age of Victim 44 16. Body Part(s) (nvolved 99 - NO INJURY 20. Attachment(s) 9 - Multiple Attacl	grounds Road ston, RI 02892 uct Name and Addres 13. Sex 2 - Fema 17. Respo 1 - Victim	11B, Trade/B 11B, Trade/B s le ndent /Complainant 21. Case Sourc 07 - Consume n NEISS Cases (14. Disposition 0 - No Injury 18. Type of Inves 1 - On-Site se r Complaint	tigatio	22. Sa	15. Injury Diagnosis 70 - No Injury 19. Time Spent {Operational / Trave 19 / 1 mple Collection Numbe
132 Fair W. King 11A. Second Produ 11D. Manufacturer 11D. Manufacturer 12. Age of Victim 44 16. Body Part(s) (nvolved 99 - NO INJURY 20. Attachment(s) 9 - Multiple Attach 23. Permission to	grounds Road ston, RI 02892 uct Name and Addres 13. Sex 2 - Fema 17. Respo 1 - Victim hments Disclose Name (No	11B. Trade/B s le ndent /Complainant 21. Case Sourc 07 - Consume n NEISS Cases (V	14. Disposition 0 - No Injury 18. Type of Inves 1 - On-Site ce r Complaint Daly)	26. R	22. Sa 058	15. Injury Diagnosis 70 - No Injury 19. Time Spent (Operational / Trave 19 / 1 mple Collection Numbe 407248

•

CPSC FORM 182 (12/96) As proved for use through 09/30/2006 OME . O. 30410029

IDI #041201CWE5008

NARRATIVE:

The following information was obtained from the complainant and owner of the incident product during an in-person interview at the military base where he lived.

The incident product involved a back-up battery powered supply UPS unit (refer to Exhibit 3 - photo 1) the complainant purchased new from a local air force exchange in November of 2002 for somewhere between \$70-100.

After reading the user's manual for the unit, the complainant explained that the included battery was required to be installed prior to use. This simply involved opening the battery compartment's cover on the back of the unit and inserting the positive (red) and negative (black) wires there into the corresponding terminal on the battery. The battery was then placed into the compartment and the compartment cover was reinstalled.

Since July of 2003, the complainant and his wife lived in military housing that consisted of three bedrooms and twoand-a-half baths. The two-story home was built in the 1930s. It was equipped with several smoke detectors with the closest to the incident product located in the hallway adjacent to the family room.

The back-up battery unit was stored under a desk and on top of a computer speaker in the complainant's family room. Combustibles were not stored in the vicinity of the unit. The back-up battery was the only appliance plugged into one of two receptacles of a duplex wall outlet there. A black

1

power switch on the unit turned it on when depressed. A reset button was located directly above the power switch. Three communication ports were located on the back of the unit allowing the capability to use a telephone, modem/fax or high speed internet.

The back-up battery unit was equipped with six receptacles that provided full time surge protection. Its battery provided back-up power to three of the six receptacles. The complainant said the family's home computer and monitor were plugged into two of the three receptacles with back-up power while the computer printer and speakers were plugged into two receptacles with only surge protection and no back-up power. He added that the incident product has been powered on continuously since it was plugged into the wall outlet while the computer components plugged into it are typically powered on daily from 7:00 a.m. until 11:00 p.m. The unit has never been modified and no problems were ever experienced with it until the incident date.

The incident occurred during the afternoon of November 13, 2004, Saturday. The weather that day was typically warm and dry. The complainant said the home computer was turned on at about 7:00 a.m. At 10:00 a.m., his 44-year-old wife began working on the computer. Nothing unusual was observed during this time. His wife is 5'4" in height and in good health, with no mental or physical disabilities. She does not smoke and was not taking any medications that day. She is a college graduate and has taken post-graduate courses. Their annual household income exceeds \$35,000. The complainant has owned two other back-up power supply units previously and both he and his wife were

2

knowledgeable of the hazards associated with these products.

At approximately 1:00 p.m., the complainant's wife was sitting at the desk and working on the computer when she smelled an odor of burning plastic. Further investigation revealed smoke was coming from the incident back-up power supply unit. The complainant said the unit's circuit breaker did not shut off power to it automatically and that it continued to supply power to all components that were plugged into it. The amount of smoke from the unit increased until the complainant's wife turned it off manually. However, this amount was not sufficient enough to activate the nearby smoke detector.

Although she subsequently unplugged all components connected to the APS unit, the complainant's wife left the incident product plugged into its electrical outlet since it was located behind a piece of furniture, making it inaccessible. She immediately telephoned her husband and reported the incident to him and at 1:20 p.m., he returned home and unplugged the incident product from its electrical outlet. He said the odor of burning plastic still lingered in the room and the unit was still warm to the touch.

No injuries resulted from the incident and although no visible damage was observed to the incident back-up power supply unit, the complainant discontinued using it due to the fire hazard it presented.

Shortly after, the complainant contacted the manufacturer's customer service department to inform them of the incident

and offer the return of the defective product to have the problem investigated. He was not asking for any compensation in return. However, the representative responded by informing him the product was no longer under warranty. They instructed him not to return the product since they were not interested in it and asked if they could sell him another unit instead.

Because the complianant feared that the defective unit would have started a fire if his wife was not present when it began to smoke, he reported the incident to the Commission in an attempt to prevent other incidents from occurring.

On February 7, 2004, the complainant voluntarily turned custody of the incident product and its battery over to CPSC (refer to Exhibit 1 - Receipt for Samples and Exhibit 2 - Affidavit). The unit was shipped to the Sample Storage Facility as an official sample (05-840-7248). However, its battery was not shipped due to its lead content and the hazard it presents.

Research of CPSC's website revealed the manufacturer previously conducted a recall of two different model backup power supply devices (CPSC Release #03-068) due to the fire hazard they posed.

PRODUCT IDENTIFICATION:

The incident product was an **APC** 500 VA Back-UPS Office 500 VA (refer to photo 3) power supply unit the complainant had purchased new sometime in November of 2002, from his local Air Force Exchange for somewhere between \$70-100. Its

model number was BF500 while the serial number was NB0042320470 (refer to photo 8). The manufacturer is located at 132 Fairgrounds Road, W. Kingston, RI 02892. Their customer service number in the USA is (800)800-4APC and their web site is www.apcc.com.

An examination of the incident unit revealed no visible damage to the unit. The product was dark gray in color and was constructed of plastic (refer to photos 2). It measured 17" long, 6" wide, and 2 ½" tall. It was equipped with a 1 ¾" long, 3-pronged plug that was labeled in part, "WELL SHIN WS-001 E115330 T-3/XXX." This plug was attached to a 70" long electrical cord that was labeled, "(UL)SJT E90165 75°C VW-1 16AWGX3C SHIELDED WELL SHIN CSA TYPE SJT 60°c 16AWGX3C SHIELDED FT2 LL57855 (refer to photo 4)."

A black power push switch was located on the top right of the unit while a black push reset button was located above it (refer to photo 5). Full time surge protection was provided to the six grounded receptacles on the top panel while back-up battery power was supplied to the three receptacles on the left end. Battery light indicators were located below these receptacles (refer to photo 6).

The bottom of the unit was labeled with the following specifications: "Input: 120V~, 10A, 60Hz / Output, UPS Outlets/350: 120V~, 2.9A, 60Hz, 225W / Output, UPS Outlets/500: 120V~, 4.2A, 60Hz, 325W / Output, Surge Protected Outlets: 120V~, 10A, 60Hz / Total Output Current: 10A/XXX." Caution statements were also noted here (refer to photos 7, 9, 11). Labeling here also indicated that the unit met FCC Reg. No. 1XHUSA-25571-XP-N standards and that

5

it was UL LISTED 42C2 / E95463 and CSA listed LR63938 (refer to photo 10).

A cover located on the bottom enclosed a compartment that housed the unit's lead battery. This cover was opened by depressing its two tabs, then sliding the cover to the right. A black (negative terminal) and red (positive terminal) wire there supplied power to the unit when connected to the battery (refer to photos 12-14).

Three ports were located on the back of the unit. These allowed a phone, phone/fax/modem, and high speed line to be connected here (refer to photo 15-16).

The lead battery measured 5 ½" in length, 1-13/16" wide, and 4" in height. Its red colored labeling stated in part, "Sealed Lead Battery. / CSB BATTERY CO., LTD. / HC 1221W / MADE IN TAIWAN / Pb NONSPILLABLE /XXX." The positive (+) and negative (-) were located on the top while a CAUTION label was located on its side (refer to photos 17-19).

EXHIBITS:

- 1. Receipt for Samples (1 page).
- 2. Affidavit (1 page).
- 3. Photographs (19 photos taken by this investigator).

CONTACTS

.

Complainant:

Lynn Broome 303-A Signer Boulevard Honolulu, HI 96818 Ph. 808-448-1063 (work) Ph. 808-291-0662 (cell)

Interviewed at Air Force base: February 7, 2005

			······································
HIBIT 1 - RECEIPT FOR SAMPLE			#041201CWE5008
U.S. CONSUMER PROD SAFETY COMMISSIO	UCT 579	office address 5 CODKC Str molulu, 14	eet-surte A: #2: 9/813
2. NAME OF WOWDUTSY DOMO	3. THE OF INDIVID		4 02-07-200
5. FIRM NAME MA-			6. SAMPLE NUMBER
7. NUMBER AND STREET 303A- SUDDER Blvd.	8. CITY A	ND STATE (Include Zip) Co Molulu, H	^(de) 9(818
9. SAMPLES COLLECTED (Describe fully, List lot, se			
Product Safety Act (15 U.S.C. 2076(f) and/or Sect tions 5(c) and (d) of the Flammable Fabrics Ac Cosmetic Act (21 U.S.C. 374(e)) LAuthority for sa: 1970 (15 U.S.C. 1471 et seq.)], and receipt for said this form. (1) APC brattery Stral wumber: Model: Back-up	t (15 U.S.C. 1194(c) and (d) an mple collections made in conne samples is hereby acknowledg	d/or Section 704(c) of the ction with the Poison Prev ed. Sections cited are quot	Federal Food Drug and ention Packaging Act of ed on the reverse side of
,		,	
2			
		·	
10. SAMPLES	11. SAMPLES WERE	12.	COLLECTOR
a. AMOUNT SECEIVED FOR SAMPLE		a. NAME Ther "Chief	71/a
b. SIGNATURE (Person from whom sumple received)		b. SIGNATURE	
Rom b. Bronne	BORROWED (To be returned)		ein

٠

EXHIBIT 2 - AFFIDAVIT	IDI # 041201CWE5008
AFFIDAVIT	SAMPLE NO. 05-840- 7248
STATE OF HAWAII	COUNTY OF HONOLULU
being first duly sworn, deposes and says: T AW LUNN POLOTOWL OF BOSA 81	ed by the Chairman of said Commission fety Act (sec. 27 (b) (2), 86 Stat. 1228; s, affirmations, and affidavits, n the county and State aforesaid, who, MACY BIVA., Honolulu. Hi 96818
Sometime about November of APC lorand computer battery I AIR Force exchange at Hickn. I paid somewhere between #75	2002, I Johrshafed a new loackup whit from the local am Ain Force Base in Hawaii 5-100 for the whit.
The battery backup whit was installation until the inciden when it started to poroduce si plastic white my wife used the into it.	e computer that was plutated
on February 7, 2005, Envestigate the incident battery backup us credentials to me. The unit voluntarily and at no cost as hereby relinquisting all rights of of this battery backup unit as returned to me.	of control and supership
AFFIANT'S SIGNATURE & TITLE Mynn W. Drown Consul FIRM (Name and address, include ZIP' Code) (400) WI Mne.	mer
FIRM (Name and address, include ZIP' Code) Lynn Brome 303 A. Signer BIVA. Hondulu, Ht 96818	
Subscribed and sworn before me at	H-onolulu , HAWAII (City and State)
this day of F	ebruary, 2005.
(Employee's Sig	mature)

EMPLOYEE OF THE CONSUMER PRODUCT SAFETY COMMISSION ACTING IN ACCORDANCE WITH AUTHORITY GRANTED IN THE ABOVE STATED DECLARATION.

CPSC FORM NO. 158

.




Photo 1: Incident computer back-up power supply unit.




Photo 2: Top view of unit.




Photo 4: Power was supplied to it via a 3-pronged grounded electrical plug.

IDI#041201CWE5008




Photo 5: A black push-button supplied power to the unit while a black reset button was above it.




Photo 6: The unit was equipped with six surge-protected receptacles. The back-up battery supplied power to three of these.




Photo 8: The unit's model was BF500 and its serial number was NB0042320470.




Photo 10: The unit was listed with UL, CSA, and the FCC standards.




Photo 12: Battery compartment cover.




Photo 13: Battery compartment was opened by depressing two plastic tabs and sliding cover to the right.




Photo 14: A red colored wire connected to the battery's positive terminal while the black wire connected to the negative terminal.




Photo 15: Back side of unit.





Photo 17: Front side labeling of lead battery.






Photo 19: Top of battery with female terminal ports.



May 20, 2005

Ann DeTemple Director United States Consumer Product Safety Commission National Injury Information Clearinghouse 4330 East West Highway Room 504 Bethesda, Maryland 20814 SENT VIA FEDEX

RE: 041201CWE008

Dcar Ms. DeTemple:

Thank you for your letter dated April 15, 2005 regarding the above referenced incident ("Claim") allegedly involving one of our products. We have read the report in detail and despite the indication in the documents accompanying the Claim that the customer contacted APC, we have not, to the best of our knowledge, receive any claims or information related to such Claim. Absent review of the unit we cannot, at this time, evaluate the basis of the Claim or provide any potential root cause analysis. However, from a review of the materials provided by you, it appears, at this time, that the unit functioned in accordance with its specifications.

We appreciate the Consumer Products Safety Commission contacting us regarding this matter. Please contact us immediately if there are any further developments in this case. If there is anything else we can do, please do not hesitate to contact me directly at (401) 789-5735 x2255.

Once again, thank you for your letter.

Peter Wexler Associate General Counsel American Power Conversion Corporation

> American Power Conversion Corporation PO Box 278 Call 401 789

 PO Box 278
 Cali 401 189 5735

 132 Fairgrounds Road
 Fax 401 789 3710

 West Kingston, RI 02892
 Visit www.apcc.com

 APC is an equal opportunity ensacyer which series workforce civersity.

 APCs quality system is 150 9002 contrad.

Doc No: 104B0412A

11/24/2004 05:07:03

Name = Lynn Broome Address = 303A Signer Blvd City = Honolulu State = Hawaii Zip = 96818 Email = Ibroome@hawaii.rr.com Telephone = 808 291-0662 Name of Victim = Lynn Broome Victim's Address = 303A Signer Blvd Victim's City = Honolulu Victim's State = Hawaii Victim's Zip = 96818 Victim's Telephone = 808 291-0662

Incident Description: While working on our home computer, smoke started coming out of the back-up power supply the computer was plugged into. The smoke continued to increase until the unit was manually turned off. The unit continued to supply power to all connected equipment, and its circuit breaker did not trip. Once the unit was turned off, the smoke disapated. It is likely that a fire would have ensued had no one been at the computer and noticed smoke pouring out of the unit, then quickly shut down the the unit. None of the equipment plugged into the back-up power supply malfunctioned to cause the unit to overheat. Victim's age at time of incident = 44

Victim's sex = Male Date of incident = 13 Nov 04 Product involved = 500 VA Back-up Power Supply Product brand name/manufacturer = APC Place where manufactured (City and State or Country) = Laguna, Philippines Product involved still available = Yes Product model and serial number, manufacture date = Back-UPS Office 500 VA, BF500, S/N NB0042320470 Date product purchased = nOV 2002 Name Release = Release name to manufacturer only If you have any changes, additions, or comments you wish to make concerning your attached report, please make them in the space below.

I contacted APC customer service and offered to return the unit to them so they could investigate the problem (if they paid for the shipping). They were not interested in my offer. APC has recalled other models of their back-up power supplies. The failure of my unit could indicate additional needs are necessary.

I confirm that the information in the attached report (including any changes, additions, or comments I have made) is accurate to the best of my knowledge and belief.

6 Dec 04



i request that you do not release my name.



You may release my name to the manufacturer but I request that you not release it to the general public.

You may release my name to the manufacturer and to the public.

Doc No: 107B0682A

1	S	su	e	:	9
---	---	----	---	---	---

11/27/2007

11/24/2007 15:59:08

10.000				
Name = ^{(b)(6)}				
Address				
City = K				
State = Texa	IS			
Zip = 77491				
Email =1(b)(6) 			1
Telephor	>	20		
Name of	· · · ·		· .	
Victim's			<i>4</i> .	,
Victim's City	= Katy			
Victim's Stat	-			
Victim's Zip	= 77491			
Victim's Tele		(6)		
	L			····-

DE LOERYL	_/ .
CCmiller, C S.	8/20/08
A	
ANGUIONS FULLE	6 2
- Elimona	(· · · · · · · · · · · · · · · · · · ·
RENOTEY	

Incident Description = I smelled a strong sulfur in my office. In searching for the source of the smell, I discovered the product was very hot and making a sizzling sound. Afraid that it might explode, I unplugged the product and prepared to carry it outside. The bottom of the product was so hot, it burned my hand. I then used hotpads to lift and carry the product to our back porch. When I opened the battery compartment, I discovered they were extremely hot and the cases were swollen and gas seemed to be coming out of them. I feel I was lucky I was home when the product decided to fail, also that it didn't melt the carpet under the UPS. I assume something went wrong with the charging circuit, and am disappointed the charger doesn't seem to have any sort of thermal protection. Finally, I only had two LCD monitors connected to this product, so I know it was not overloaded.

Pictures of the batteries, once cooled and removed, are here: http://www.flickr.com/photos/21229337@N06/

Victim's age at time of incident = 41 Victim's sex = female Date of incident = 10/2/2007 Product involved = Back up power supply for a computer Product brand name/manufacturer = APC (American Power Conversion) Manufacturer street address = 132 Fairgrounds Road, W. Kingston, RI 02892 Place where manufactured (City and State or Country) = unknown Product involved still available = yes Product model and serial number, manufacture date = Model: BP1100, Serial: QB0415211263 Date product purchased = unknown Name Release = Release name to manufacturer only

11/24/2007 15:59:08							
					1. A.		
				· .			
. ·			•			na Markettine	
(b)(6)							
Kaly TX 77491]						
					e te se te	· · · · ·	
	a na manta ata			ana 1915-1916 - Andreas Brandski, 1917			
in the second	and a second second Second second	ni Maria	na San Angera I			n de la companya de Nataria de la companya	
			aran na Santa. Ng Santa			an gana an ing gana ang sang sang sang sang sang san	5
		•					
				n an			
Email = (b)(6)							
Telepho							
Name o Victim's		. ' •• •					
Victim's City = Katy		:					
Victim's State ≃ Texa Victim's Zip = 77491		94 - L.					
Victim's Telephone =	(b)(6)						
Incident Description	= I smelled a stroi	ng sulfur in i	my office.	in searching for I	the source of the	smeil, l	
discovered the produ							
unplugged the produc	a ano prepareo u					the	
unplugged the produce my hand. I then used	d holpads to lift an						
my hand. I then used battery compartment	d hotpads to lift an	y were extre	mely hot a	nd the cases we	re swollen and g		
my hand. I then used battery compartment seemed to be coming that it didn't melt the	d holpads to lift ar , I discovered the g out of them. I fe carpet under the I	y were extre sel I was luc UPS: I assu	imely hot a ky I was ho ime somet	nd the cases we ome when the pri hing went wrong	re swollen and g oduct decided to with the chargin	fail, also g circuit,	
my hand. I then used battery compartment seemed to be coming	d holpads to lift ar , I discovered they g out of them. I fe carpet under the I the charger does	y were extre eel I was luc UPS. I assu on't seem to	imely hot a ky I was ho ime somet have any s	nd the cases we ome when the pro hing went wrong ort of thermal pr	re swollen and g oduct decided to with the chargin rotection. Finally	fail, also g circuit,	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed had two LCD monitor	d hotpads to lift ar , I discovered they g out of them. I for carpet under the I the charger does is connected to th	y were extre eel I was luc UPS. I assu in't seem to is product,	mely hot a ky I was ho ime somet have any s so I know il	nd the cases we ome when the pro- hing went wrong ort of thermal pro- was not overloa	re swollen and g oduct decided to with the chargin rotection. Finally	fail, also g circuit,	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed	d hotpads to lift ar , I discovered the g out of them. I fe carpet under the I the charger does rs connected to th les, once cooled a	y were extre eel I was luc UPS. I assu on't seem to is product, and remove	mely hot a ky I was ho ime somet have any s so I know il	nd the cases we ome when the pro- hing went wrong ort of thermal pro- was not overloa	re swollen and g oduct decided to with the chargin rotection. Finally	fail, also g circuit,	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed had two LCD monitor Pictures of the batter	d hotpads to lift ar , I discovered the g out of them. I fe carpet under the I the charger does rs connected to th les, once cooled a	y were extre eel I was luc UPS. I assu on't seem to is product, and remove	mely hot a ky I was ho ime somet have any s so I know il	nd the cases we ome when the pro- hing went wrong ort of thermal pro- was not overloa	re swollen and g oduct decided to with the chargin rotection. Finally	fail, also g circuit,	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed had two LCD monitor Pictures of the batter http://www.flickr.com Victim's age at time c	d hotpads to lift ar , I discovered the g out of them. I fe carpet under the I the charger does rs connected to th les, once cooled a /photos/21229337 of incident = 41	y were extre eel I was luc UPS. I assu on't seem to is product, and remove	mely hot a ky I was ho ime somet have any s so I know il	nd the cases we ome when the pro- hing went wrong ort of thermal pro- was not overloa	re swollen and g oduct decided to with the chargin rotection. Finally	fail, also g circuit,	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed had two LCD monitor Pictures of the batter http://www.flickr.com	d hotpads to lift ar , I discovered the g out of them. I fe carpet under the I the charger does rs connected to th les, once cooled a /photos/21229337 of incident = 41	y were extre eel I was luc UPS. I assu on't seem to is product, and remove	mely hot a ky I was ho ime somet have any s so I know il	nd the cases we ome when the pro- hing went wrong ort of thermal pro- was not overloa	re swollen and g oduct decided to with the chargin rotection. Finally	fail, also g circuit,	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed had two LCD monitor Pictures of the batter http://www.flickr.com Victim's age at time of Victim's sex = female Date of incident = 10 Product involved = Bi	d hotpads to lift ar , I discovered the g out of them I fe carpet under the I the charger does rs connected to th les, once cooled a /photos/21229337 of incident = 41 /2/2007 ack up power sup	y were extra ed I was luc UPS: I assu- in't seem to is product, i and remove 7@N06/	imely hot a ky I was ho ime somet have any s so I know I d, are here Ma mputer	nd the cases we ome when the pri- hing went wrong ort of thermal pr was not overloa	re swollen and g oduct decided to with the chargin rotection. Finally	fail, also g circuit,	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed had two LCD monitor Pictures of the batter http://www.flickr.com Victim's age at time of Victim's sex = female Date of incident = 10 Product involved = Bi Product brand name/ Manufacturer street a	d hotpads to lift ar , I discovered the g out of them I fe carpet under the I the charger does rs connected to th les, once cooled a /photos/21229337 of incident = 41 /2/2007 ack up power sup manufacturer = A address = 132 Fai	y were extre eel I was luc UPS: I assu in't seem to is product, and remove 7@N06/ 7@N06/ 90006/ 90000000000000000000000000000	imely hot a ky I was ho ime somet have any s so I know I d, are here d, are here M d mputer an Power (oad, W, Kir	nd the cases we me when the pri- hing went wrong ort of thermal pr was not overloa	re swollen and g oduct decided to with the chargin ofection. Finally ided	fail, also g circuit,	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed had two LCD monitor Pictures of the batter http://www.flickr.com Victim's age at time of Victim's sex = female Date of incident = 10 Product involved = Bi Product brand name/ Manufacturer street a Place where manufacturer	d hotpads to lift ar , I discovered the g out of them I fe carpet under the I the charger does rs connected to th les, once cooled a /photos/21229337 of incident = 41 /2/2007 ack up power sup manufacturer = A address = 132 Fai ctured (City and S	y were extre eel I was luc UPS: I assu in't seem to is product, and remove 7@N06/ 7@N06/ 90006/ 90000000000000000000000000000	imely hot a ky I was ho ime somet have any s so I know I d, are here d, are here M d mputer an Power (oad, W, Kir	nd the cases we me when the pri- hing went wrong ort of thermal pr was not overloa	re swollen and g oduct decided to with the chargin ofection. Finally ided	fail, also g circuit,	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed had two LCD monitor Pictures of the batter http://www.flickr.com Victim's age at time of Victim's sex = female Date of incident = 10 Product involved = Bi Product brand name/ Manufacturer street a Place where manufai Product involved still Product model and si	d hotpads to lift ar , I discovered the g out of them I fe carpet under the I the charger does 's connected to th les, once cooled a /photos/21229337 of incident = 41 /2/2007 ack up power sup manufacturer = A address = 132 Fai ctured (City and S available = yes erfal number, mar	y were extre eel I was luc UPS: I assu in't seem to is product, and remove 7@N06/ 7@N06/ apply for a con PC (Americ Irgrounds R state or Cou	imely hot a ky I was ho ime somet have any s so I know I d, are here d, are here M d mputer an Power oad, W. Kin ntry) = unk	nd the cases we me when the pri- hing went wrong ort of thermal pr was not overloa (re swollen and g oduct decided to with the chargin ofection. Finally ided	fail, also g circuit, ; l only	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed had two LCD monitor Pictures of the batter http://www.flickr.com Victim's age at time of Victim's sex = female Date of incident = 10 Product involved = Bi Product brand name/ Manufacturer street a Place where manufac Product involved still Product involved still Product model and si Date product purchas	d hotpads to lift ar , I discovered the g out of them I fe carpet under the I the charger does rs connected to th les, once cooled a /photos/21229337 of incident = 41 /2/2007 ack up power sup manufacturer = A address = 132 Fai ctured (City and S available = yes erfal number, mar sed = unknown	y were extre eel I was luc UPS: I assu in't seem to is product, and remove 7@N06/ *@N06/ *@N06/ *@N06/ * * * * * * * * * * * * * * * * * * *	imely hot a ky I was ho ime somet have any s so I know I d, are here d, are here an Power cad, W. Kir ntry) = unk he = Model	nd the cases we me when the pri- hing went wrong ort of thermal pr was not overloa (re swollen and g oduct decided to with the chargin ofection. Finally ided	fail, also g circuit, ; l only	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed had two LCD monitor Pictures of the batter http://www.flickr.com Victim's age at time of Victim's sex = female Date of incident = 10 Product involved = Bi Product brand name/ Manufacturer street a Place where manufai Product involved still Product model and si	d hotpads to lift ar , I discovered the g out of them I fe carpet under the I the charger does rs connected to th les, once cooled a /photos/21229337 of incident = 41 /2/2007 ack up power sup manufacturer = A address = 132 Fai ctured (City and S available = yes erfal number, mar sed = unknown	y were extre eel I was luc UPS: I assu in't seem to is product, and remove 7@N06/ *@N06/ *@N06/ *@N06/ * * * * * * * * * * * * * * * * * * *	imely hot a ky I was ho ime somet have any s so I know I d, are here d, are here an Power cad, W. Kir ntry) = unk he = Model	nd the cases we me when the pri- hing went wrong ort of thermal pr was not overloa (re swollen and g oduct decided to with the chargin ofection. Finally ided	fail, also g circuit, ; l only	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed had two LCD monitor Pictures of the batter http://www.flickr.com Victim's age at time of Victim's sex = female Date of incident = 10 Product involved = Bi Product brand name/ Manufacturer street a Place where manufac Product involved still Product involved still Product model and si Date product purchas	d hotpads to lift ar , I discovered the g out of them I fe carpet under the I the charger does rs connected to th les, once cooled a /photos/21229337 of incident = 41 /2/2007 ack up power sup manufacturer = A address = 132 Fai ctured (City and S available = yes erfal number, mar sed = unknown	y were extre eel I was luc UPS: I assu in't seem to is product, and remove 7@N06/ *@N06/ *@N06/ *@N06/ * * * * * * * * * * * * * * * * * * *	imely hot a ky I was ho ime somet have any s so I know I d, are here d, are here an Power cad, W. Kir ntry) = unk he = Model	nd the cases we me when the pri- hing went wrong ort of thermal pr was not overloa (re swollen and g oduct decided to with the chargin ofection. Finally ided	fail, also g circuit, ; l only	
my hand. I then used battery compartment seemed to be coming that it didn't melt the and am disappointed had two LCD monitor Pictures of the batter http://www.flickr.com Victim's age at time of Victim's sex = female Date of incident = 10 Product involved = Bi Product brand name/ Manufacturer street a Place where manufac Product involved still Product involved still Product model and si Date product purchas	d hotpads to lift ar , I discovered the g out of them I fe carpet under the I the charger does rs connected to th les, once cooled a /photos/21229337 of incident = 41 /2/2007 ack up power sup manufacturer = A address = 132 Fai ctured (City and S available = yes erfal number, mar sed = unknown	y were extre eel I was luc UPS: I assu in't seem to is product, and remove 7@N06/ *@N06/ *@N06/ *@N06/ * * * * * * * * * * * * * * * * * * *	imely hot a ky I was ho ime somet have any s so I know I d, are here d, are here an Power cad, W. Kir ntry) = unk he = Model	nd the cases we me when the pri- hing went wrong ort of thermal pr was not overloa (re swollen and g oduct decided to with the chargin ofection. Finally ided	fail, also g circuit, ; l only	



April 23, 2008

VIA E-Mail Pamela McDonald Lead, Technical Information Specialist United States Consumer Product Safety Commission National Injury Information Clearinghouse 4330 East West Highway Room 502 Bethesda, Maryland 20814

RE: 107B0682A

Dear Ms. McDonald:

Thank you for your letter dated February 29, 2008 regarding the above referenced incident ("Claim") involving one of our products. We have read the report in detail and carefully reviewed our records. Mr. Sembroski did contact American Power Conversion Corporation's ("APC") customer support hotline which allowed APC to evaluate the basis of the Claim and provide potential root cause analysis. After a review of the unit, APC determined that the swelling of the batteries had reached the end of their life and were in need of replacement. A replacement product was then sent to Mr. Sembroski.

We appreciate the Consumer Products Safety Commission contacting us regarding these matters. Please contact us immediately if there are any further developments in this claim. If there is anything else we can do, please do not hesitate to contact me directly at (401) 789-5735 x2902.

Once again, thank you for your letter.

Very truly yours,

Paula Steele

Senior Legal Counsel American Power Conversion Corporation



107B0682A

If you have any changes, additions, or comments you wish to make concerning your attached report, please make them in the space below.

I confirm that the information in the attached report (including any changes, additions, or comments I have made) is accurate to the best of my knowledge and belief.

Signature /2/

(b)(6)

I request that you do not release my name.

You may release my name to the manufacturer but I request that you not release it to the general public.

You may release my name to the manufacturer and to the public.

18SUE 10 CARS 0 2003

Pulley, Autumn S

_	
From:	Pucciarelli, Ellen M
Sent:	Thursday, January 30, 2003 8:41 AM
To:	Emerging Hazards; Hazard; Internet Incident Reports; Clearinghouse
Cc:	Cohn, Murray S.
Subject:	Internet Form Complaint - Doc #10310440

1/30/03 2:04.44 AM

	(b)(6)		
Name =	(0)(0)	1	
Address			
City = S	· .		
State = C	R		
$Zip = 9\pi$	6		
Zip = 9 77 Email <u>1</u>			
Teleph	1		
Name of	Victim =	<u>. (6.9</u>	 <u></u>
Victim's /	Address	=	
Victim's (City =		
Victim's \$	State =		
Victim's 2	Zip =		
	Telephon	e =	

No Com Commands attached गैंs made Excisions/Revisions-Firm has not requested further notice

Incident Description: I believe the recall just issued for two specific APC models may be more widespread among other models - as well. See text below.

John,

Thanks for your reply. The model number is SU700NET and the serial number is NS9750000412. I am the original owner. The unit is used in my home, has plenty of ventilation and is on a wooden base on the floor. Regardless of whether you find the UPS is under "warranty" I believe that any product should be warranted indefinitely against burning your house down! Perhaps the Consumer Product Safety Commission

should also be notified that this model too has the potential to catch fire as well. My feeling is that as the batteries start to get old the unit attempts to overcharge them. There obviously is no thermal protection in the UPS otherwise it would have shutdown due to the extremely high temperature inside.

Regards, Chris Taylor

--- esupport@apc.com wrote:

> Recently you requested personal assistance from our > on-line Support

> Center. Below is a summary of your request and our > response.

>

> We will assume your issue has been resolved if we do

> not hear from you

> within 7 days.

> Thank you for allowing us to be of service to you.

>

03033

 You may also update this question by replying to this message. Because your reply will be automatically processed, you MUST anter your reply. 	
 > enter your reply > in the space below. TEXT ENTERED INTO ANY OTHER PART > OF THIS MESSAGE > WILL BE DISCARDED. 	
 > [===> Please enter your reply below this line. <===] > [===> Please be sure that your reply does not go 	
 > beyond this line. <===] > If your issue remains unresolved, please update this 	
<pre>> question at > http://nam-en.apc.com/cgi-bin/nam_en.cfg/php/enduser</pre>	
<pre>/mtp://mani-ent.apc.com/cg=bin/nam_ent.crg/pin/renduser /acct_login.php?p_userid=ctaylor_1@yahoo.com&p_ne xt_page=myq_upd.php&p_refno=030117-000523&p_cr eated=1042787880 ></pre>	
> Subject	
> UPS overheating >	
> Discussion Thread	
> Response (John Erikson) - 01/17/2003 11:24 AM > Dear Chris;	
 Thank you for your inquiry. What is the environment like where your unit is located? Is it temperature controlled? Also, do you have the serial number, and model number for that unit, and we can determine 	
<pre>> if it is under warranty? > (b)(6)</pre>	
 Custom - 01/17/2003 02:18 AM I have a SmartUPS 700 that on two occasions has overheated to the point of severly distorting the 	
 > batteries and releasing a chemical smell. The first > time it happened I replaced the batteries thinking > it was just a bad battery. It again occurred about > 12 months later. Fortunately I was at home at the 	
 > time because it happened rather suddenly and the > case became too hot to fouch. Neither time was the > unit in use when this happened. I have since 	
 > discontinued using it. I just noticed that you had a > recall on some other models. I think you may have a > problem with this model as well. I will be glad to 	
<pre>> send it to you for evaluation. > (b)(6) ></pre>	
> + 000E22	
> Question Reference #030117-000523 >(b)(6)	
> Category: > Contact Informati	2
	E.

ï

Date Created: 01/17/2003 02:18 AM > > Lasl Updated: 01/17/2003 11:24 AM > Status: Waiting Serial: > Software: > Version: > Operating System: > > > > > John Erikson > APC Customer Solutions Team Representative > > How are we doing? Please take a moment to fill out a > quick survey. The survey is localed at the > following URL: > http://surveys.apcc.com/wi/p0056897/ctl.asp?l=9&conc e=WK&conme=W&open=qs > > Victim's age at time of incident = Victim's sex = Male Date of incident = 12-15-2002 Product involved = APC SU700NET (Computer UPS) Product brand name/manufacturer = APC Place where manufactured (City and State) = Phillipines Product involved still available = Yes Product model and serial number = Ser#: NS9750000412

Date product purchased = 1998?

Name Release = Do not release name

3

If you have any changes, additions, or comments you wish to make concerning your attached report, please make them in the space below.

I contacted the non-facturer and they seemed to think that the reason for over heating was dure to ald betteries. My reports to this is the unit should detect it a short ocurs or if high intrund bettery registance is present and shot down the unit. This happened very quickly and shot down the unit. This happened very quickly and had I not been home I'm sore it would have caused a fire. They said the unit is designed to shot off if the temperature rises to 160. I can assure you it way hatter, and still operating.

I confirm that the information in the attached report (including any changes, additions, or comments I bays made) is accurate to the best of my knowledge and belief.

(b)(6)



I request that you do not release my name.



You may release my name to the manufacturer but I request that you not release it to the general

~...]

public.

You may release my name to the manufacturer and to the public.

I0310440 18



Ann DeTemple Director United States Consumer Product Safety Commission National Injury Information Clearinghouse 4330 East West Highway Room 504 Bethesda, Maryland 20814 SENT VIA FEDEX

RE: 030129CCN0301, To 310 312H H0310215A, 1031312A, C0325001A, II0310361A, I0310440

April 11, 2003

Dear Ms. DeTemple:

Thank you for your letter dated March 31, 2003 regarding the above referenced incidents allegedly involving our products. In regards to Claims #030129CCN0301 and #C0325001A, we have been notified by the customers of the incidents and our respective insurance companies are conducting formal investigations. With regard to Claim #II0310215A, it is our understanding that this issue has been resolved to the customer's satisfaction. Finally, we have not, to the best of our knowledge, receive any claims or information related to Claims #I031312A, #H0310361A and #I0310440.

American Power Conversion Corporation takes the design and manufacture of its products extremely seriously. We appreciate the Consumer Products Safety Commission contacting us regarding this matter. If there is anything else we can do, please do not hesitate to contact me directly at (401) 789-5735 x2255.

Once again, thank you for your letter.

Peter, Wexler Senior Counsel American Power Conversion Corporation

 American Power Conversion Corporation

 PO Box 278
 Call 401 789 5735

 132 Fairgrounds Road
 Fax 401 789 3710

 West Kingston, Ri 02892
 Visit www.apcc.com

 APC is an equal opportunity employer which values workforce dwarstly APC is an equal opportunity employer which values workforce dwarstly
 .

320717 BMD 51 FO

140

Hi Todd, I was given your name to follow up with regarding requesting information relating to complaints on the APC (American Power Conversion) Back-UPS product. Ours ignited causing a fire.

- - - - -----

The model we have is 8K350.

Thanks Tim Jacques fax:207-396-2688 email: tjacques@hannaford.com

Tim Jacques 7 Heritage Lane Windham, ME 04062

slc


32 **ISGUE** 3 2002 MAY

HFR/PRVIBA NOTIFIED No comments made Comments attached Excisions/Revisions Firm has not request further D

-205

94%





TO: TS

FROM: Tim Jacques

DATE: Monday, May 06, 2002 2:25:28 PM

PAGES: 02 including cover sheet

Notes:

Attention Todd Stevenzon

This facsimile transmission may contain proprietary and/or privileged information that is intended only for the use of the individual(s) named on the transmission sheet. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, or the taking of any action in reliance on the contents of this facsimile transmission is strictly prohibited. If you have received this communication in error, please immediately notify the sending party by telephone and return the original message to the sender via U.S. Postal Service at the address identified above.



U.S. CONSUMER PRODUCT SAFETY COMMISSION WASHINGTON, DC 20207

Todd A. Stevenson Deputy Secretary and Freedom of Information Officer Office of the Secretary Tel: 301-504-0785X1239 Fax: 301-504-0127 Email: tstevenson@cpsc.gov

May 7, 2002

Mr. Tim Jacques 7 Heritage Lane Windham, ME 04062

Freedom of Information Act Request Number : Consumer Product Incident Report Number : S-2002050034 C0255005 (American Power Conversion)

Dear Mr. Jacques:

Thank you for your recent letter to the U.S. Consumer Product Safety Commission (CPSC). We have assigned two tracking numbers, because your letter requests information from the CPSC and also reports an incident or complains about a product. Refer to those numbers if you need to contact us. As to the FOIA request, be assured that every effort is being made to process your request as promptly as possible and the records you requested which can be released will be made available to you at the earliest possible date.

Regarding your complaint or reported incident, our staff will review the information you provided and add it to the CPSC databases or the appropriate agency project file. This type of information allows us to focus on cases that pose the greatest degree of risk to consumers. In determining whether to take action, the Commission considers a number of factors including the likelihood of injury, the nature and degree of injury, and whether action by the Commission can correct the problem.

Our staff will contact you if we need additional information. The Commission appreciates the interest you have shown in helping us to reduce the unreasonable risk of injury from consumer products.

Sincerely,

Todo A Stan

Todd A. Stevenson

CPSC Hotline: 1-800-638-CPSC(2772) ★ CPSC's Web Site: http://www.cpsc.gov

Document Number: C0255005A Issue Number: 32 If you have any changes, additions, or comments you wish to make concerning your attached report, please make them in the space below. I confirm that the information in the attached report (including any changes, additions, or comments I have made) is accurate to the best of my knowledge and belief. 4/8/2002 Signa/ I request that you do not release my name. You may release my name to the manufacturer but I request that you not release it to the general public. You may release my name to the manufacturer and to the public.

CONSUMER PRODUCT INCIDENT REPORT

Region: EASTERN

1. NAME OF RESPONDENT	2. PHONE NO. (HOME)	(WORK)
3. STREET ADDRESS	4. CITY Hunts Valley	STATE ZIP CODE MD 21030

4a. E-MAIL ADDRESS: not given

5. DESCRIBE INCIDENT OR HAZARD, INCLUDING DATA ON INJURIES Computer was plugged into a battery-power box when consumer noticed a strange odor which she thought was coming from her halogen light fixture, so -cont-

OF OY/N	RIBE INJURY: MERLER COMMEN	ALBE NOTIFIED (0) 11 hone NTS:YES: NO _OVERRULED: ATTACHED NONE COVERRULED: ATTACHED NONE INFONSFORE AS 35C Revisions 1.0. BRANI	PONDENT	, PROVIDE NAME
11. MFR/DISTRIBUTOR NAME, American Power Conversion 132 Fairgrounds Road West Kingston, RI 02892 800-800-4272 Dellware 5700 East Port Richmond, VA 23231		12. MODEL, SERIAL M# 420 PNP 13. DEALER'S NAME unknown		
14. WAS THE PRODUCT DAMAG MODIFIED? YES NO X OR AFTER THE INCIDENT?		15. PRODUCT PURCHA DATE PURCHASED 5/2 16. DOES PRODUCT H IF SO, NOTE: none	24/1996	
17. HAVE YOU CONTACTED TH MANUFACTURER? YES X IF NOT, DO YOU PLAN TO CO THEM?	NO AVAILABLE	E PRODUCT STILL ? YES X NO TS DISPOSITION		19. MAY WE USE YOUR NAME WITH THIS REPORT? YES X NO
		ISTRATION USE		
20. DATE RECEIVED 09/21/2000				DCUMENT NO. 235A
23. FOLLOW-UP ACTION			24. Pl 4068	RODUCT CODE(S)
25. DISTRIBUTION	2.6	. ENDORSER'S NAME SLT 09/25/2000	& TITL	Ξ
CPSC FORM 175 (08/1998)			OMB	3041-0029

CONSUMER PRODUCT INCIDENT REPORT H0090235A

Narrative Continued

she turned light fixture off, however the odor did not subside.

Consumer awoke to the same odor around 2:00am and unplugged everything in her room where the computer was located. The fumes disappeared one hour later.

(Next Day) Consumer contacted manufacturer's rep. (name unknown) and explained incident. Rep. took a report and told consumer to ventilate the area, handle product with rubber gloves, place it in a strong hefty bag, use baking soda to neutralize the sulphuric acid fumes and place bag in an area outside of the house. Rep. also offered to send consumer a manufacturer's data safety sheet and a new, replacement battery. Consumer followed rep.'s instructions and odor disappeared.

Battery's UL listing unknown.

Distributor phone #: 800-624-9897

CPSC Source: L/S GOVT

If you have any changes, additions, or comments you wish to make concerning your attached report, please make them in the space below.

3. Street Address: 44 Iron Mill Garth 4. City: Hunt Valley

5. Describe Incident or Hazard: The fumes disappeared one hour later. (Next Day) Consumer determined which office machine was causing the odor by sniffing each one. The "rotten egg" smell was still slightly emanating from the product 9 hours after being unplugged......

7. If Injury or Near Miss Obtain Age/Sex: Age 55 Female. Moderate sinus infection started after the first day. Felt fatigued and weak. Took several weeks with medical treatment to completely feel strong again.

I confirm that the information in the attached report (including any changes, additions, or comments I have made) is accurate to the best of my knowledge and belief.

Virida ferance October 26, 2000 Signature Date



I request that you do not release my name.



You may release my name to the manufacturer but I request that you not release it to the general public.

You may release my name to the manufacturer and to the public.