
#### **South Texas Project Unit 1**



Bottom Mounted Instrument Penetration Condition Resolution

#### **STP Participants**

Joe Sheppard President & CEO

Tom Jordan VP, Engineering & Tech

Services


Gary Parkey VP, Generation

Ed Halpin Plant General Manager





#### **STP Used Worldwide Experts**



#### **External Support**

Framatome ANP

Westinghouse - PCI

**Dominion Engineering** 

Performance Improvement International

**Exponent Failure Analysis Associates** 

V. C. Summer Nuclear Power Plant

Comanche Peak Steam Electric Station

Arkansas Nuclear One Power Plant

Japanese loanee to Institute of Nuclear Power Operations (INPO)

Electric Power Research Institute (EPRI)

Electricite de France

Tractabel (Belgium)

Harfang Industries

Altran

#### Full-Sized Mock-up at STP






## EXTENT of CONDITION, CAUSE, CORRECTIVE ACTION

Tom Jordan
Vice President,
Engineering & Technical Services

#### **BMI Guide Tube Penetration**



#### **Our Inspection Process Works**

We inspect the exterior of our vessels every time we shutdown for a refueling outage. Previous inspections did not reveal indications of seepage.



## **Evidence of Very Small Leakage Found in Routine Inspection**






#### **Actual Amount of Residue**





#### **Looking Down into Reactor Cavity**



# Extensive NDE Using State-of-the-Art Techniques and the Most Experienced People in the World








#### **Examination Scope**

- Ultrasonic examination (UT) from penetration tube ID
- Enhanced visual exam of J-groove weld surface
- Volumetrically interrogate vessel base metal for wastage
- Eddy current examination (ET) from penetration tube ID
- ET of J-groove weld surface
- Profilometry [tube inside roundness / ovality]
- Borescope [tube inside visual] examinations
- Helium tests
- Metallurgical analyses of removed nozzle remnants
- Boat sample analyses


#### **Examination Results**

- Penetration #1
  - Three axial indications, one leak path
- Penetration #46
  - Two axial indications, one leak path

#### **Investigation Results**



#### Permanent Half-Nozzle Repair



#### **Completed Repair**



### Condition Limited to the Two Identified Nozzles

- Routine inspection identified very low leakage
- Extensive NDE confirmed condition limited to two penetrations
  - Axial cracks in tubes
  - No wastage
- Substantial safety margin existed
- Repairs are complete
- Monitoring / inspection plan developed

# MONITORING / INSPECTION PLAN and RETURN to SERVICE

## Ed Halpin Plant General Manager

## Monitoring / Inspection Plan Confirms Effective Corrective Action

- Continue bare metal visual inspections under boric acid control program
- Perform UT and EVT of penetrations at next Unit 1 vessel inservice inspection
- Perform periodic UT of vessel base material around repaired penetrations
- Perform volumetric examination of Unit 2 penetrations at next refueling outage with core barrel removal
- Online monitoring plan developed

#### **Outage Philosophy**

Three-phase outage approach for long-term focus on nuclear safety and reliability

Phase One: Discovery

Phase Two: Repair

Phase Three: Return to Service

#### **Return to Service**

- Plant readiness
  - Comprehensive communications plan
  - PORC reviewed selected activities
  - Just-in-time training for plant operators
  - Weekly plant walkdowns with key station management to assess readiness
  - Increase in staff and manning onshift
  - Specific readiness reviews including
    - Integrated schedule review
    - Refuel project readiness review
    - Secondary plant startup review

#### Return to Service (cont'd)

