

would be of interest to our constituents and stakeholders. The update is communicated via Listserv, a free e-mail subscription service consisting of industry, trade, and farm groups, consumer interest groups, allied health professionals, scientific professionals, and other individuals who have requested to be included. The update is also available on the FSIS Web page. Through Listserv and the web page, FSIS is able to provide information to a much broader, more diverse audience.

Done in Washington, DC, on April 15, 2004.

Linda M. Swacina,

Deputy Administrator.

[FR Doc. 04-8948 Filed 4-15-04; 4:15 pm]

BILLING CODE 3410-DM-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2004-NE-07-AD; Amendment 39-13579; AD 2004-08-10]

RIN 2120-AA64

Airworthiness Directives; Engine Components Incorporated (ECi) Reciprocating Engine Cylinders

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Teledyne Continental Motors (TCM) models 520 and 550 series engines with certain ECi cylinders installed. This AD requires replacing certain serial-numbered (SN) cylinders supplied by ECi before further flight. This AD results from reports of 34 failures of cylinder heads marketed by ECi. We are issuing this AD to prevent loss of engine power due to cracks in the cylinder head and possible engine failure caused by separation of a cylinder head.

DATES: This AD becomes effective May 5, 2004.

We must receive any comments on this AD by June 21, 2004.

ADDRESSES: Use one of the following addresses to submit comments on this AD:

- By mail: The Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2004-NE-07-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

- By fax: (781) 238-7055.

- By e-mail: 9-ane-adcomment@faa.gov.

You can get the service information referenced in this AD from Engine Components, Inc., 9503 Middlex, San Antonio, TX 78217; Phone (210) 820-8100; fax (210) 820-3103.

You may examine the AD docket at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT: Fred Stellar, Branch Manager, Special Certification Office, FAA, Rotorcraft Directorate, 2601 Meacham Blvd., Fort Worth, TX 76193; telephone (817) 222-5199; fax (817) 222-5785.

SUPPLEMENTARY INFORMATION: On February 1, 2003, we received a report of an ECi cylinder head, part number (P/N) AEC65385, that separated from the barrel at the head-to-barrel junction. Since that report, we have received reports of 27 additional ECi cylinder heads that had the same condition. We also received reports of six cylinder heads that had a crack between the 9th and 10th head fin from the head-to-barrel junction. All of the reported separations and cracks were located between the ninth and tenth head fin from the head-to-barrel junction. All of the cracks started on the exhaust side of the head. The ECi cylinder head, P/N AEC65385, is part of ECi cylinder, P/N AEC631397. RAM Series III, IV, and VII reciprocating engines are the primary users of these cylinders. The RAM series engines are TCM TSI0-520-NB, -VB, and -WB engines that are modified by supplemental type certificate (STC) SE4327SW, STC SE09104SC, or STC SE09261SC for operation at 325 HP or greater. In addition, we approved the engine cylinders, ECi P/N AEC631397 for use on TCM models 520 and 550 series reciprocating engines under a Parts Manufacturer Approval (PMA). The Airmotive Engine Division of ECi holds the PMA. ECi markets the parts as ECi parts.

Results of Manufacturer's Investigation

An investigation by ECi revealed that cylinder heads, P/N AEC65385, manufactured between September 1, 2002, and May 12, 2003, SNs 1044 through 7708, are susceptible to an over-hardened condition, which reduces the fatigue strength of the cylinder. It also increases the chance that the cylinder will crack.

Relevant Service Information

We reviewed and approved the technical contents of RAM Aircraft Mandatory Service Bulletin (MSB) MSB2003-02, dated August 8, 2003, and

ECi MSB S.I. No. 04-1, Revision 1, dated March 11, 2004, that describe procedures for identifying, inspecting, and replacing affected cylinders.

Differences Between This AD and the Service Information

RAM Aircraft MSB MSB2003-02, dated August 8, 2003, requires replacing only the No. 6 cylinder, ECi P/N AEC631397, on RAM Series III, IV, and VII engines. ECi MSB S.I. No. 04-1, Revision 1, dated March 11, 2004, requires identifying the suspect cylinders on TCM models 520 and 550 engines and inspecting them for cracks. This AD requires replacing all cylinders, ECi P/N AEC631397, on all RAM Series III, IV, and VII engines; and all TCM model 520, and 550 series engines.

FAA's Determination and Requirements of This AD

The unsafe condition described previously is likely to exist or develop on other RAM Series III, IV, and VII engines; and TCM model 520, and 550 series engines of the same type design. We are issuing this AD to prevent loss of engine power due to cracks in the cylinder head and possible engine failure caused by separation of a cylinder head. This AD requires:

- Performing a check to identify cylinders, ECi P/N AEC631397, S/Ns 1044 through 7708, within 50 hours time-in-service after the effective date of this AD, and
- If a cylinder has an affected P/N and SN, replacing the cylinder before further flight if it was not inspected at ECi.

FAA's Determination of the Effective Date

Since an unsafe condition exists that requires the immediate adoption of this AD, we have found that notice and opportunity for public comment before issuing this AD are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any written relevant data, views, or arguments regarding this AD. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. 2004-NE-07-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket

number written on it; we will date-stamp your postcard and mail it back to you. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify it. If a person contacts us verbally, and that contact relates to a substantive part of this AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend the AD in light of those comments.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications with you. You can get more information about plain language at <http://www.faa.gov/language> and <http://www.plainlanguage.gov>.

Examining the AD Docket

You may examine the AD Docket (including any comments and service information), by appointment, between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. See **ADDRESSES** for the location.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2004-NE-07-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2004-08-10 Engine Components

Incorporated (ECi): Amendment 39-13579. Docket No. 2004-NE-07-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective May 5, 2004.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Teledyne Continental Motors (TCM) TSIO-520-NB, -VB, and -WB engines that are modified by supplemental type certificate (STC) SE4327SW, STC SE09104SC, or STC SE09261SC for operation at 325 HP or greater, (the so-called RAM TSIO-520-NB, -VB, or -WB Series III, IV, and VII reciprocating engines; and Teledyne Continental Motors (TCM) model 520 and 550 series reciprocating engines with certain ECi reciprocating engine cylinders, part number (P/N) AEC631397, installed. These engines are installed on, but not limited to the airplanes listed in the following Table 1:

TABLE 1.—LIST OF AIRPLANES THAT USE THE AFFECTED ENGINES

Airplane manufacturer and model	Engine model
AERFER/AERMECCHI AM, 3.	GTSIO-520-C
AERO COMMANDER: 200D	IO-520-A
500A COLEMILL CONVERSION.	IO-520-E
685	GTSIO-520-K
AISA: F20, PEGASO	IO-520-K
AMBROSIN MF-151	IO-520-F
AVIONES PIHAO	IO-520-D
BEAGLE (U.K.): B206S	GTSIO-520-C
BEECHCRAFT BARON: C55	IO-520-CB, -C
D55	IO-520-CB, -C
E55	IO-520-CB, -C
58	IO-520-CB
58P	TSIO-520-LB
58P	TSIO-520-L
58P	TSIO-520-WB
58TC	TSIO-520-LB
58TC	TSIO-520-L

TABLE 1.—LIST OF AIRPLANES THAT USE THE AFFECTED ENGINES—Continued

Airplane manufacturer and model	Engine model
58TC	TSIO-520-WB
BEECHCRAFT BONANZA: A36	IO-550-B
E33A	IO-520-BA
E33A	IO-520-BB
E33B	IO-520-B
F33	IO-520-BB
F33A	IO-520-B
F33A	IO-520-BA
F33A	IO-520-BB
S35	IO-520-B
ST35	TSIO-520-D
V35	IO-520-BB
V35A	IO-520-B
V35A-TC	TSIO-520-D
V35B	IO-520-B
V35B	IO-520-BA
V35B	IO-520-BB
A36	IO-520-B
A36	IO-520-BA
A36	IO-520-BB
A36-TC	TSIO-520-UB
BEECHCRAFT DEBONAIR: C33A.	IO-520-B
VIKING 300	IO-520-A
	IO-520-D
	IO-520-K
BONNAIRE 185	IO-520-D
BONNAIRE 188 CONVERSION.	IO-520-D
BURNS BA42	IO-520-D
CESSNA: SUPER SKYLANE A, B, C, D, E.	IO-520-A
TURBO SUPER SKYLANE.	TSIO-520-C
SKYWAGON A185 E,F ..	IO-520-D
SKYWAGON A185FII	IO-520-D
AG SPRAYER 188-300	IO-520-D
A188-230	IO-520-D
AG TRUCK (A 188B) -300.	IO-520-D
AG HUSKEY (A 188C) -310.	TSIO-520-T
AG WAGON (A 188B) ...	IO-520-D
SUPER SKYWAGON U206, A.	IO-520-A
U206B, C, D, E, F	IO-520-F
TURBO SKYWAGON TU206 A.	IO-520-C
TU206B, C, D, E, F	TSIO-520-C
STATIONAIR U206	IO-520-F
TU206	TIOS-520-C
U206FII-300	IO-520-F
U206G-300	IO-520-F
U206GII-300	IO-520-L
TU206G-310	TSIO-520-M
SUPER SKYLANE P206A.	IO-520-A
P206B, C, D, E	IO-520-A
TURBO P 206 A, B, C, D, E.	TSIO-520-C
SKYWAGON 207	IO-520-F
TURBO 207	TSIO-520-G
STATIONAIR 207A, 207AII.	IO-520-F
STATIONAIR 8, 811	IO-520-F
T-STATIONAIR 811	TSIO-520-M

TABLE 1.—LIST OF AIRPLANES THAT USE THE AFFECTED ENGINES—Continued

Airplane manufacturer and model	Engine model
210 CENTURION D, E, F, G, H.	IO-520-A
210 CENTURION J	IO-520-J
210 CENTURION K, L, M, N, R.	IO-520-L
210 CENTURION TURBO.	TSIO-520-C
210 CENTURION TURBO.	TSIO-520-H
210 CENTURION TURBO K, L.	TSIO-520-H
TURBO 210 J, K, L	TSIO-520-H
TURBO 210 MII, NII	TSIO-520-R
TURBO 210R	TSIO-520-R
PRESSURIZED CENTURION P210N.	TSIO-520-P
PRESSURIZED CENTURION P210NII.	TSIO-520-AF
PRESSURIZED CENTURION P210R.	TSIO-520-CE
T303 CRUSADER	TSIO-520-AE
T303 CRUSADER	LTSIO-520-AE
310R	IO-520-MB
310R	IO-520-M
TURBO 310 P, Q	TSIO-520-B
TURBO 310 R	TSIO-520-BB
TURBO 310 R	TSIO-520-B

TABLE 1.—LIST OF AIRPLANES THAT USE THE AFFECTED ENGINES—Continued

Airplane manufacturer and model	Engine model
EXECUTIVE SKYKNIGHT D, E, F.	TSIO-520-B
335	TSIO-520-EB
340	TSIO-520-K
340A	TSIO-520-NB, -N
401 A, 401 B	TSIO-520-E
402 A, 402 B	TSIO-520-E
402C	TSIO-520-VB
404 TITAN	GTSIO-520-M
411, 411A	GTSIO-520-C
414	TSIO-520-J
414, 414 A	TSIO-520-NB, -N
421A	GTSIO-520-D
421B	GTSIO-520-H
421C	GTSIO-520-L
421C	GTSIO-520-N
JANOX JAVILON	IO-520-B
NAVION:	
RANGEMASTER MODEL H.	IO-520-B
RANGEMASTER MODEL H.	IO-520-BA
PIPER: MALIBU	TSIO-520-BE
PRINAIR:	
DE HAVILLAND HERON	IO-520-E
WINDECKER EAGLE	IO-520-C

Unsafe Condition

(d) This AD results from reports of 34 failures of ECi cylinder head. We are issuing this AD to prevent loss of engine power due to cracks in the cylinder head and possible engine failure caused by separation of a cylinder head.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Identifying Suspect Cylinders

(f) Within 50 hours time-in-service (TIS) after the effective date of this AD, identify, and if necessary replace cylinders, ECi P/N AEC631397 as follows:

(1) Identify the cylinder serial number (SN) as follows:

(i) Determine the SN of the cylinder by looking in the engine records or by inspecting the cylinder for a SN on the intake port boss (see Figure 1) or on the flat area next to the head to barrel junction (see Figure 2). Disregard any dash numbers that might follow the four digit SN.




Figure 1.




Figure 2.

(ii) If the SN is 1043 or lower, or if it is 7709 or higher, no further action is required.
 (2) If the cylinder SN is 1044 through 7708, do the following:

(i) Remove the rocker box cover from the cylinder.
 (ii) Look at the left-front cylinder casting.

(iii) If the casting has AEC65385, and an "O" under the ECI logo, the cylinder is P/N AEC631397. See Figure 3.



Figure 3.

(iv) If the cylinder is not ECI P/N AEC631397, no further action is required.

(3) If the cylinder is ECI P/N AEC631397, do the following:

(i) Look at the flange of the rocker box.

(ii) If there is a letter "A," "B," or "X" stamped on the flange of the rocker box, no further action is required. See Figure 4.




Figure 4.

(iii) If there is no letter "A," "B," or "X" stamped on the flange of the rocker box, replace the cylinder before further flight.

Alternative Methods of Compliance

(g) The Manager, Special Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Material Incorporated by Reference

(h) None.

Related Information

(i) EGi Mandatory Service Bulletin S.I. No. 04-1, revision 1, dated March 11, 2004, also pertains to this subject of this AD.

Issued in Burlington, Massachusetts, on April 9, 2004.

Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.
[FR Doc. 04-8877 Filed 4-19-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 73

[Docket No. FAA-2003-16438; Airspace Docket No. 03-ASW-02]

RIN 2120-AA66

Modification of Restricted Areas 3801A, 3801B, and 3801C, Camp Claiborne, LA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action revises Restricted Area's 3801A (R-3801A), 3801B (R-3801B), and 3801C (R-3801C), Camp Claiborne, LA. This action responds to a request from the United States Air Force (USAF) to eliminate the area currently designated as R-3801A; expand the vertical limits of the areas currently designated as R-3801B and R-3801C; and reconfigure R-3801B and R-3801C into a new R-3801A, R-3801B, and R-3801C. Additionally, this action changes the controlling agency for R-3801A, B, and C from the FAA, Houston Air Route Traffic Control Center (ARTCC) to the U.S. Army, Fort Polk Approach Control. The FAA is taking this action to assist the USAF in

fulfilling their training requirements for high altitude release bombing.

DATES: *Effective Date:* 0901 UTC, June 10, 2004.

FOR FURTHER INFORMATION CONTACT:

Steve Rohring, Airspace and Rules, Office of System Operations and Safety, ATO-R, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Background

On January 6, 2004, the FAA proposed to revise R-3801A, R-3801B, and R-3801C, Camp Claiborne, LA, and change the controlling agency to assist the USAF in meeting new USAF training requirements for high altitude release bombing (69 FR 552). Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on this proposal to the FAA. In response to the proposal, the FAA received two comments. The comments and our responses are discussed below.

In response to the proposal, the Aircraft Owners and Pilots Association (AOPA) supports the elimination of the current R-3801A, but expressed concern that raising the ceiling of R-3801B and R-3801C would reduce the availability of Federal Airway 212 (V-212) for use