

By order of the Maritime Administrator.  
**Joel C. Richard**,  
*Secretary, Maritime Administration.*  
 [FR Doc. 04-23895 Filed 10-25-04; 8:45 am]  
**BILLING CODE 4910-81-P**

## DEPARTMENT OF TRANSPORTATION

### National Highway Traffic Safety Administration

[Docket No. NHTSA-2004-18556; Notice 2]

#### General Motors Corporation, Mootness of Petition for Decision of Inconsequential Noncompliance

General Motors Corporation (GM) has determined that certain 2004 model year Saab 9-3 Sport Sedans and Convertibles do not comply with S4.2(b) of 49 CFR 571.114, Federal Motor Vehicle Safety Standard (FMVSS) No. 114, "Theft protection." Pursuant to 49 U.S.C. 30118(d) and 30120(h), GM has petitioned for a determination that this noncompliance is inconsequential to motor vehicle safety and has filed an appropriate report pursuant to 49 CFR part 573, "Defect and Noncompliance Reports." Notice of receipt of a petition was published, with a 30-day comment period, on July 14, 2004, in the **Federal Register** (69 FR 42240). NHTSA received one comment.

Out of a population of approximately 4032 model year 2004 Saab 9-3 Sport Sedans and Convertibles equipped with a manual transmission, approximately 11 are affected. S4.2(b) of FMVSS No. 114 requires that "[e]ach vehicle shall have a key-locking system which, whenever the key is removed, prevents either steering or forward self-mobility of the vehicle or both." The affected vehicles were produced with an ignition key locking system that contains a center spring plate switch that can bind in the closed position. This switch communicates to certain vehicle systems that the ignition key has been inserted or removed. When this switch binds in the closed position, certain systems will read that the ignition key is still in the ignition switch, even after ignition key removal. One of the systems using the input from this switch is the electronic steering column lock to meet the S4.2 requirement of FMVSS No. 114. If a vehicle has the aforementioned condition, the steering column will not lock upon ignition key removal.

However, all Saab 9-3 vehicles are equipped with an electronic engine immobilizer system that prevents engine operation in the absence of the vehicle's ignition key from the ignition switch module. The immobilizer remains fully

operational on vehicles with the aforementioned condition present. Although a vehicle could be steered with this condition, the engine could not be started, even through hot-wiring or other vehicle manipulation. The one comment to the **Federal Register** notice was from a private individual and did not address the specific issue concerning S4.2(b).

NHTSA has determined that the vehicles in question are in compliance with the requirements of S4.2(b) because the electronic engine immobilizer system prevents vehicle forward self-mobility when the key is not in the ignition switch module. Therefore, this petition is moot.

**Authority:** 49 U.S.C. 30118, 30120; delegations of authority at CFR 1.50 and 501.8.

Issued on: October 20, 2004.

**Kenneth N. Weinstein**,  
*Associate Administrator for Enforcement.*  
 [FR Doc. 04-23874 Filed 10-25-04; 8:45 am]  
**BILLING CODE 4910-59-P**

## DEPARTMENT OF TRANSPORTATION

### National Highway Traffic Safety Administration

[Docket No. NHTSA 2004-18972; Notice 2]

#### Michelin North America, Inc., Grant of Petition for Decision of Inconsequential Noncompliance

Michelin North America, Inc. (Michelin) has determined that the sidewall markings on certain tires that it manufactured in 2000 through 2003 do not comply with S4.2.1(c) of 49 CFR 571.109, Federal Motor Vehicle Safety Standard (FMVSS) No. 109, "New pneumatic tires." Pursuant to 49 U.S.C. 30118(d) and 30120(h), Michelin has petitioned for a determination that this noncompliance is inconsequential to motor vehicle safety and has filed an appropriate report pursuant to 49 CFR part 573, "Defect and Noncompliance Reports." Notice of receipt of a petition was published, with a 30-day comment period, on September 14, 2004, in the **Federal Register** (69 FR 55492). NHTSA received one comment.

A total of approximately 60,729 Michelin Symmetry P195/60R15 87S tires manufactured during 8/29/00 to 10/19/03 and approximately 12,633 Michelin Symmetry P205/60R15 90S tires manufacturing during 8/6/00 to 9/22/00 and 7/27/03 to 8/23/03 are affected. S4.2.1 of FMVSS No. 109 requires that each tire shall conform to the requirement that "(c) Its load rating

shall be that specified in \* \* \* one of the publications described in S4.4.1(b)."

The sidewall markings on the affected tires do not comply with S4.2.1(c) because the sidewall markings understate the actual carrying capacity of the tires. The Max Load value indicated is less than the actual load carry capability of the tires at the marked air pressure value of 240 kPa (35 psi). The P195/60R15 tires are incorrectly marked MAX LOAD 470 kg (1036 Lbs) and should have been marked Max Load 540 kg (1190 Lbs). The P205/60R15 tires are incorrectly marked MAX LOAD 510 kg (1124 Lbs) and should have been marked Max Load 590 kg (1301 Lbs).

Michelin believes that the noncompliance is inconsequential to motor vehicle safety and that no corrective action is warranted. Michelin stated that at the indicated maximum pressure value of 35 psi the P195/60R15 tire will carry an extra 151 pounds per tire and the P205/60R15 tire will carry an additional 177 pounds per tire, thus consumers relying upon the carrying capacity values marked on the tires will put less load on the tires than they are capable of carrying. Michelin further stated that all of the performance requirements of FMVSS No. 109 are met or exceeded, and the tires are marked with the correct maximum pressure value of 35 psi.

NHTSA received one comment on the petition from a private individual that did not address the effect on motor vehicle safety of this noncompliance.

NHTSA agrees that the noncompliance is inconsequential to motor vehicle safety. At the indicated maximum pressure value, the tire will carry an additional load, therefore there is no likelihood of creating an unsafe condition. In addition, all FMVSS No. 109 performance requirements are met, and all other informational markings as required by FMVSS No. 109 are present. Michelin has corrected the problem.

In consideration of the foregoing, NHTSA has decided that the petitioner has met its burden of persuasion that the noncompliance described is inconsequential to motor vehicle safety. Accordingly, Michelin's petition is granted and the petitioner is exempted from the obligation of providing notification of, and a remedy for, the noncompliance.

**Authority:** 49 U.S.C. 30118, 30120; delegations of authority at CFR 1.50 and 501.8.

Issued on: October 20, 2004.

**Kenneth N. Weinstein,**

*Associate Administrator for Enforcement.*

[FR Doc. 04-23875 Filed 10-25-04; 8:45 am]

BILLING CODE 4910-59-P

## DEPARTMENT OF TRANSPORTATION

### National Highway Traffic Safety Administration

[Docket No. NHTSA 2004-18973; Notice 2]

#### Michelin North America, Inc., Grant of Petition for Decision of Inconsequential Noncompliance

Michelin North America, Inc. (Michelin) has determined that the sidewall markings on certain tires that it manufactured in 1993 through 2004 do not comply with S6.5(d) of 49 CFR 571.119, Federal Motor Vehicle Safety Standard (FMVSS) No. 119, "New pneumatic tires for vehicles other than passenger cars." Pursuant to 49 U.S.C. 30118(d) and 30120(h), Michelin has petitioned for a determination that this noncompliance is inconsequential to motor vehicle safety and has filed an appropriate report pursuant to 49 CFR part 573, "Defect and Noncompliance Reports." Notice of receipt of a petition was published, with a 30-day comment period, on September 14, 2004, in the **Federal Register** (69 FR 55491). NHTSA received one comment.

A total of approximately 97,468 tires are affected. This includes approximately 68,950 Michelin tires consisting of 24,644 LT215/85R16XPS Rib; 35,934 LT225/75R16 XPS Rib; 5,348 LT215/85R16 XPS Traction; and 3,024 8.75R16.5 XPS Rib tires manufactured from May 1, 2003 through the week beginning July 12, 2004. It also includes 28,518 Michelin 8.75R16.5 XPS Rib tires manufactured from approximately mid-1993 through the week beginning July 12, 2004. The sidewall load and inflation markings of these two groups of tires do not comply with S6.5(d), "Tire markings." S6.5(d) requires that each tire shall be marked on each sidewall with "[t]he maximum load rating and corresponding inflation pressure of the tire" in both metric and English units.

The sidewall load and inflation markings on the 68,950 tires manufactured from May 1, 2003 through the week beginning July 12, 2004 are in English units only and do not have the metric units required by S6.5(d). The sidewall load and inflation markings on the 28,518 tires manufactured from approximately mid-1993 through the week beginning July 12, 2004 are incorrect for the Max. Load Dual

category; the tires are marked "2550 lbs at 75 psi" when they should be marked "2405 lbs at 80 psi."

Michelin believes that the noncompliance is inconsequential to motor vehicle safety and that no corrective action is warranted. With regard to the tires that are marked in English units only, Michelin stated that the tires are manufactured for sale in the U.S. replacement market where the English system is universally comprehended, and the maximum load expressed in "lbs." and air pressure expressed in "psi" will not confuse U.S. vehicle owners, nor result in unsafe use of the tires in terms of load or inflation values. With regard to the tires that are marked with the incorrect Max. Load Dual load and inflation, Michelin asserted that

"[w]hen both single and dual loads are marked on the tire (as is the case here), FMVSS No. 119 requires that performance compliance testing be done based on the single (higher, more punishing) tire load. Accordingly, the incorrect dual load marking is inconsequential for this tire. \* \* \* Even at the lower, more punishing pressure of 75 psi, the tire meets all FMVSS No. 119 minimum performance requirements."

NHTSA received one comment on this petition from a private individual that did not address the effect on motor vehicle safety of this noncompliance.

NHTSA agrees that the noncompliance is inconsequential to motor vehicle safety because the maximum load expressed in "lbs." and air pressure expressed in "psi" will not confuse U.S. vehicle owners, nor result in unsafe use of the tires in terms of load or inflation values. The agency also agrees that safety will not be compromised for the tires marked with the incorrect "max load dual" since the more severe "max load single" load is marked correctly. In addition, these tires meet or exceed all of the performance requirements of FMVSS No. 119, and all other informational markings as required by FMVSS No. 119 are present. Michelin has corrected the problem.

In consideration of the foregoing, NHTSA has decided that the petitioner has met its burden of persuasion that the noncompliance described is inconsequential to motor vehicle safety. Accordingly, Michelin's petition is granted and the petitioner is exempted from the obligation of providing notification of, and a remedy for, the noncompliance.

**Authority:** (49 U.S.C. 30118, 30120; delegations of authority at CFR 1.50 and 501.8).

Issued on: October 20, 2004.

**Kenneth N. Weinstein,**

*Associate Administrator for Enforcement.*

[FR Doc. 04-23876 Filed 10-25-04; 8:45 am]

BILLING CODE 4910-59-P

## DEPARTMENT OF TRANSPORTATION

### National Highway Traffic Safety Administration

[Docket No. NHTSA 2004-18923; Notice 2]

#### CCI Manufacturing IL Corporation, Grant of Petition for Decision of Inconsequential Noncompliance

CCI Manufacturing IL Corporation (CCI) has determined that certain brake fluid containers manufactured by its supplier, Gold Eagle, do not comply with S5.2.2.2(d) of 49 CFR 571.116, Federal Motor Vehicle Safety Standard (FMVSS) No. 116, "Motor vehicle brake fluids." Pursuant to 49 U.S.C. 30118(d) and 30120(h), CCI has petitioned for a determination that this noncompliance is inconsequential to motor vehicle safety and has filed an appropriate report pursuant to 49 CFR Part 573, "Defect and Noncompliance Reports." Notice of receipt of a petition was published, with a 30-day comment period, on August 31, 2004, in the **Federal Register** (69 FR 53130). NHTSA received no comments.

A total of approximately 21,204 units of brake fluid containers manufactured in March 2004 are affected. S5.2.2.2 of FMVSS No. 116 requires that:

Each packager of brake fluid shall furnish the information specified in [paragraph d] of this S5.2.2.2 by clearly marking it on each brake fluid container or on a label (labels) permanently affixed to the container \* \* \* After being subjected to the operations and conditions specified in S6.14, the information required by this section shall be legible. \* \* \*

The information specified in paragraph (d) of S5.2.2.2 is "[a] serial number identifying the package lot and date of packaging." With regard to the noncompliant brake fluid containers, the lot and date codes required by S5.2.2.2(d) are not legible after the containers are subjected to the test conditions of S6.14.

CCI believes that the noncompliance is inconsequential to motor vehicle safety and that no corrective action is warranted. CCI stated:

NHTSA has identified only one purpose for [the lot and date code] marking: namely, "to facilitate determination of the extent of defective brake fluid should such be discovered." \* \* \* While it is clearly in the manufacturer's interest to be able to limit the "extent of defective brake fluid should such