PART 145—NATIONAL POULTRY IMPROVEMENT PLAN

■ 1. The authority citation for part 145 continues to read as follows:

Authority: 7 U.S.C. 8301–8317; 7 CFR 2.22, 2.80, and 371.4.

§ 145.53 [Amended]

■ 2. In § 145.53, paragraph (e)(2)(ii) is amended by removing the words "unvaccinated sentinel".

Done in Washington, DC, this 12th day of February, 2004.

Kevin Shea.

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 04–3594 Filed 2–18–04; 8:45 am]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-330-AD; Amendment 39-13437; AD 2004-02-02]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135 and -145 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document corrects information in an existing airworthiness directive (AD) that applies to certain EMBRAER Model EMB-135 and EMB-145 series airplanes. That AD currently requires relocating the pitot 1 and pitot 2 drain valves from the nose landing gear compartment to the forward electronic compartment, and accomplishing follow-on actions. This document corrects a missing reference to the AD number in a certain section of the AD. This correction is necessary to ensure that operators have the correct AD number when referring to the AD or when performing corrective actions.

DATES: Effective March 3, 2004.

The incorporation by reference of certain publications listed in the regulations was approved previously by the Director of the Federal Register as of March 3, 2004 (69 FR 4057, January 28, 2004).

FOR FURTHER INFORMATION CONTACT:

Todd Thompson, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone 425–227–1175; fax 425–227–1149.

SUPPLEMENTARY INFORMATION: On January 14, 2004, the Federal Aviation Administration (FAA) issued AD 2004-02-02, amendment 39-13437 (69 FR 4057, January 28, 2004), which applies to certain EMBRAER Model EMB-135 and EMB-145 series airplanes. That AD requires relocating the pitot 1 and pitot 2 drain valves from the nose landing gear compartment to the forward electronic compartment, and accomplishing follow-on actions. That AD was prompted by reports that water accumulates in the pitot 1 and pitot 2 drain valves in the nose landing gear (NLG) compartment where they are subjected to freezing temperatures. Frozen water in the drain valve can expand and cause the pitot drain valves to fail so that the airspeed indication system tubing is open to ambient pressure. The actions required by that AD are intended to prevent ice from damaging the pitot drain valves, which could cause airspeed indication errors, resulting in display of erroneous or misleading information to the flight

Need for the Correction

Information obtained recently by the FAA indicates that the AD number is missing from the PART 39—AIRWORTHINESS DIRECTIVES section, paragraph 2., of the AD.

The FAA has determined that a correction to AD 2004–02–02 is necessary. The correction will add the AD number to paragraph 2.

Correction of Publication

This document corrects the error and correctly adds the AD as an amendment to section 39.13 of the Federal Aviation Regulations (14 CFR 39.13).

The AD is reprinted in its entirety for the convenience of affected operators. The effective date of the AD remains March 3, 2004.

Since this action only adds the AD number to a certain paragraph of the AD, it has no adverse economic impact and imposes no additional burden on any person. Therefore, the FAA has determined that notice and public procedures are unnecessary.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Correction

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration

amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§39.13 [Corrected]

■ 2. Section 39.13 is amended by correctly adding the following airworthiness directive (AD):

2004-02-02 Empresa Brasileira De Aeronautica S.A. (EMBRAER):

Amendment 39–13437. Docket 2002–NM–330–AD.

Applicability: Model EMB–135 and –145 series airplanes; as listed in EMBRAER Service Bulletin 145–34–0070, Change 03, dated July 16, 2003; and EMBRAER Service Bulletin 145LEG–34–0002, dated September 23, 2002; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent ice from damaging the pitot drain valves, which could cause airspeed indication errors, resulting in display of erroneous or misleading information to the flight crew, accomplish the following:

Relocation

(a) Within 2,000 flight hours or 12 months after the effective date of this AD, whichever occurs first: Relocate the pitot 1 and pitot 2 drain valves from the nose landing gear compartment to the forward electronic compartment; and install a plug, washers, and a nut to close the hole in the structure where the pitot 1 and pitot 2 drain valves were removed; per the Accomplishment Instructions of EMBRAER Service Bulletin 145–34–0070, Change 03, dated July 16, 2003; or EMBRAER Service Bulletin 145LEG–34–0002, dated September 23, 2002; as applicable.

Installation

(b) After accomplishment of paragraph (a) of this AD but prior to further flight: Install a new placard and apply sealant on the placard per the Accomplishment Instructions of EMBRAER Service Bulletin 145–34–0070, Change 03, dated July 16, 2003; or EMBRAER Service Bulletin 145LEG—34–0002, dated September 23, 2002; as applicable.

Actions Accomplished Per Previous Issue of Service Bulletin

(c) Actions accomplished before the effective date of this AD per EMBRAER Service Bulletin 145–34–0070, original issue, dated April 23, 2002; EMBRAER Service Bulletin 145–34–0070, Change 01, dated September 23, 2002; and EMBRAER Service Bulletin 145–34–0070, Change 02, dated December 2, 2002; are considered acceptable for compliance with the corresponding action specified in this AD.

Alternative Methods of Compliance

(d) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(e) Unless otherwise specified in this AD, the actions shall be done in accordance with EMBRAER Service Bulletin 145-34-0070, Change 03, dated July 16, 2003; or EMBRAER Service Bulletin 145LEG-34-0002, dated September 23, 2002; as applicable. This incorporation by reference was approved by the Director of the Federal Register as of March 3, 2004 (69 FR 4057, January 28, 2004). Copies may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAÉR), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 1: The subject of this AD is addressed in Brazilian airworthiness directive 2002–06–01R1, dated November 8, 2002.

Effective Date

(f) The effective date of this amendment remains March 3, 2004.

Issued in Renton, Washington, on February 10, 2004.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 04–3492 Filed 2–18–04; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2003-16504; Airspace Docket No. 03-ACE-88]

Modification of Class E Airspace; Greenfield, IA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; confirmation of

effective date.

SUMMARY: This document confirms the effective date of the direct final rule which revises Class E airspace at Greenfield, IA.

EFFECTIVE DATE: 0901 UTC, April 15, 2004

FOR FURTHER INFORMATION CONTACT:

Kathy Randolph, Air Traffic Division, Airspace Branch, ACE–520C, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas City, MO 64106; telephone: (816) 329–2525.

SUPPLEMENTARY INFORMATION: The FAA published this direct final rule with a request for comments in the **Federal Register** on December 9, 2003 (68 FR

68507) and subsequently published a correction to the direct final rule in the Federal Register on February 3, 2004 (69 FR 5012). The FAA uses the direct final rulemaking procedure for a noncontroversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, were received within the comment period, the regulation would become effective on April 15, 2004. No adverse comments were received, and thus this notice confirms that this direct final rule will become effective on that date.

Issued in Kansas City, MO on February 3, 2004

Anthony D. Roetzel,

Acting Manager, Air Traffic Division, Central Region.

[FR Doc. 04–3631 Filed 2–18–04; 8:45 am] **BILLING CODE 4910–13–M**

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2003-16083; Airspace Docket No. 03-AAL-19]

Establishment of Class E Airspace; Manokotak, AK

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: This action corrects a final rule in the **Federal Register** on Monday, December 15, 2003 (68 FR 69598). The final rule established Class E airspace at Manokotak, AK.

EFFECTIVE DATE: 0901 UTC, February 19, 2004.

FOR FURTHER INFORMATION CONTACT:

Jesse Patterson, AAL–538G, Federal Aviation Administration, 222 West 7th Avenue, Box 14, Anchorage, AK 99513–7587; telephone number (907) 271–5898; fax: (907) 271–2850; email: Jesse.CTR.Patterson@faa.gov. Internet address: http://www.alaska.faa.gov/at.

SUPPLEMENTARY INFORMATION:

History

Federal Register document 03–30908 published Monday, December 15, 2003 (68 FR 69598), established Class E airspace at Manokotak, AK. The Class E airspace was incorrectly defined as the Manokotak/New Airport and should be changed to the Manokotak Airport.

■ Accordingly, pursuant to the authority delegated to me, the name of the airport at Manokotak, AK is corrected as follows:

PART 71—[AMENDED]

§71.1 [Corrected]

■ On page 69598, Column 3 and page 69599, column 1 change all references to Manokotak/New Airport to read Manokotak Airport.

Issued in Anchorage, AK, on February 9, 2004

Judith G. Heckl,

Manager, Air Traffic Division, Alaskan Region.

[FR Doc. 04–3627 Filed 2–18–04; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 106

[USCG-2003-14759]

Outer Continental Shelf Facility Security

AGENCY: Coast Guard, DHS. **ACTION:** Notice of agency policy.

SUMMARY: On Wednesday, October 22, 2003, the Coast Guard published a series of final rules for maritime security requirements mandated by the Maritime Transportation Security Act of 2002, including provisions for mobile offshore drilling units (MODUs) not subject to the International Convention for the Safety of Life at Sea, 1974, and certain fixed and floating facilities on the Outer Continental Shelf (OCS) other than deepwater ports. This Notice of agency policy clarifies which fixed and floating OCS facilities are subject to regulation under Title 33 CFR part 106. This Notice also clarifies how the Coast Guard establishes applicability to Title 33 CFR part 106.

DATES: This policy is effective as of November 21, 2003.

FOR FURTHER INFORMATION CONTACT: For further information on the subject of this Notice, contact Lieutenant Commander Eric Walters (G–MOC) U.S. Coast Guard by telephone at (202) 267–0499 or by electronic mail at ewalters@comdt.uscg.mil.

SUPPLEMENTARY INFORMATION: The requirements of 33 CFR part 106 apply to owners and operators of any fixed or floating facility, including MODUs not subject to 33 CFR part 104, operating on the Outer Continental Shelf (OCS) of the United States for the purposes of