

public meeting, and need no additional time to comply with these percentages; and (4) this interim final rule provides a 60-day comment period, and all comments timely received will be considered prior to finalization of this rule.

List of Subjects in 7 CFR Part 989

Grapes, Marketing agreements, Raisins, Reporting and recordkeeping requirements.

■ For the reasons set forth in the preamble, 7 CFR part 989 is amended to read as followed:

PART 989—RAISINS PRODUCED FROM GRAPES GROWN IN CALIFORNIA

■ 1. The authority citation for 7 CFR part 989 continues to read as follows:

Authority: 7 U.S.C. 601–674.

■ 2. Section 989.257 is added to Subpart—Supplementary Regulations to read as follows:

§ 989.257 Final free and reserve percentages for the 2003–04 crop year.

The final percentages for standard Natural (sun-dried) Seedless raisins acquired by handlers during the crop year beginning on August 1, 2003, which shall be free tonnage and reserve tonnage, respectively, are designated as follows:

Varietal type	Free percentage	Reserve percentage
Natural (sun-dried) Seedless	70	30

Dated: April 16, 2004.

Kenneth C. Clayton,

Acting Administrator, Agricultural Marketing Service.

[FR Doc. 04–9098 Filed 4–21–04; 8:45 am]

BILLING CODE 3410–02–P

FARM CREDIT ADMINISTRATION

12 CFR Parts 609, 611, 612, 614, 615, and 617

RIN 3052–AB69

Electronic Commerce; Organization; Standards of Conduct and Referral of Known or Suspected Criminal Violations; Loan Policies and Operations; Funding and Fiscal Affairs, Loan Policies and Operations, and Funding Operations; Borrower Rights; Effective Date

AGENCY: Farm Credit Administration.

ACTION: Notice of effective date.

SUMMARY: The Farm Credit Administration (FCA) published a final rule under parts 609, 611, 612, 613, 614, 615, and 617 on March 9, 2004 (69 FR 10901). This final rule clarifies the rights provided in the Farm Credit Act of 1971, as amended, for loan applicants and borrowers of the Farm Credit System (System). The final rule further explains the responsibilities of the System in providing these rights, responds to comments, and places all borrower rights provisions in one part of our regulations. In accordance with 12 U.S.C. 2252, the effective date of the interim final rule is 30 days from the date of publication in the **Federal Register** during which either or both Houses of Congress are in session. Based on the records of the sessions of Congress, the effective date of the regulations is April 19, 2004.

DATES: Effective Date: The regulation amending 12 CFR parts 609, 611, 612, 614, 615, and 617 published on March 9, 2004 (69 FR 15045) is effective April 19, 2004.

FOR FURTHER INFORMATION CONTACT: Mark L. Johansen, Policy Analyst, Office of Policy and Analysis, Farm Credit Administration, McLean, VA 22102–5090, (703) 883–4498, TTY (703) 883–4434; or Joy Strickland, Senior Counsel, Office of General Counsel, Farm Credit Administration, McLean, VA 22102–5090, (703) 883–4020, TTY (703) 883–2020.

(12 U.S.C. 2252(a)(9) and (10))

Dated: April 16, 2004.

Jeanette C. Brinkley,

Secretary, Farm Credit Administration Board.

[FR Doc. 04–9096 Filed 4–21–04; 8:45 am]

BILLING CODE 6705–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003–CE–59–AD; Amendment 39–13581; AD 2004–08–12]

RIN 2120–AA64

Airworthiness Directives; Schempp-Hirth Flugzeugbau GmbH Models Ventus-2a, Ventus-2b, Discus-2a, and Discus-2b Sailplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA adopts a new airworthiness directive (AD) for all Schempp-Hirth Flugzeugbau GmbH (Schempp-Hirth) Models Ventus-2a,

Ventus-2b, Discus-2a, and Discus-2b sailplanes. This AD requires you to inspect and modify the elevator mass balance. For Models Discus-2a and Discus-2b sailplanes only, this AD also requires you to replace the elevator pushrod. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Germany. We are issuing this AD to detect and correct problems within the sailplane elevator control system before they lead to flutter and sailplane instability. This could eventually result in loss of sailplane control.

DATES: This AD becomes effective on June 4, 2004.

As of June 4, 2004, the Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation.

ADDRESSES: You may get the service information identified in this AD from Schempp-Hirth Flugzeugbau GmbH, Postfach 14 43, D–73230 Kirchheim/Teck, Germany; telephone : 011 49 7021 7298–0; facsimile: 011 49 7021 7298–199.

You may view the AD docket at FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003–CE–59–AD, 901 Locust, Room 506, Kansas City, Missouri 64106. Office hours are 8 a.m. to 4 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Greg Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4130; facsimile: (816) 329–4090.

SUPPLEMENTARY INFORMATION:

Discussion

What events have caused this AD?

The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, recently notified FAA that an unsafe condition may exist on Schempp-Hirth Models Ventus-2a, Ventus-2b, Discus-2a, and Discus-2b sailplanes. The LBA reports that the potential exists for elevator mass balance problems on the referenced sailplanes.

What is the potential impact if FAA took no action? Elevator mass balance problems, if not detected and corrected, could lead to flutter and sailplane instability. This could eventually result in loss of sailplane control.

Has FAA taken any action to this point? We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all Schempp-Hirth Flugzeugbau GmbH (Schempp-

Hirth) Models Ventus-2a, Ventus-2b, Discus-2a, and Discus-2b sailplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on February 17, 2004 (69 FR 7380). The NPRM proposed to require you to inspect and modify the elevator mass balance. For Models Discus-2a and Discus-2b sailplanes only, this proposed AD would also require you to replace the elevator pushrod.

Comments

Was the public invited to comment? We provided the public the opportunity to participate in developing this AD. We received no comments on the proposal or on the determination of the cost to the public.

Conclusion

What is FAA's final determination on this issue? We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed except for minor editorial corrections. We have determined that these minor corrections:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Changes to 14 CFR Part 39—Effect on the AD

How does the revision to 14 CFR part 39 affect this AD? On July 10, 2002, the FAA published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs the FAA's AD system.

This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Costs of Compliance

How many sailplanes does this AD impact? We estimate that the actions specified in Schempp-Hirth Technical Note No. 360–19 would affect 15 sailplanes in the U.S. registry and the actions specified in Schempp-Hirth Technical Note No. 349–28 would affect 51 sailplanes in the U.S. registry.

What is the cost impact of this AD on owners/operators of the affected sailplanes? We estimate the following costs to accomplish the following actions:

Affected technical note	Labor cost	Parts cost	Total cost per sailplane	Total cost U.S. operators
No. 360–19	17 workhours at \$65 per hour = \$1,105	\$135 per sailplane	\$1,240	\$18,600
No. 349–28	4 workhours at \$65 per hour = \$260	No cost for parts	260	13,260

Regulatory Findings

Will this AD impact various entities? We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

Will this AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include “AD Docket No. 2003–CE–59–AD” in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. FAA amends § 39.13 by adding a new AD to read as follows:

2004–08–12 Schempp-Hirth Flugzeugbau GmbH: Amendment 39–13581; Docket No. 2003–CE–59–AD.

When Does This AD Become Effective?

(a) This AD becomes effective on June 4, 2004.

What Other ADs Are Affected by This Action?

(b) None.

What Sailplanes Are Affected by This AD?

(c) This AD affects the following model and serial number sailplanes that are certificated in any category:

Group	Models	Serial Nos.
(1) Group 1 Sailplanes	Discus-2a and Discus-2b sailplanes that do not have Shempp-Hirth Technical Note No. 360–16 incorporated.	13 through 22, 24, 27, 30 through 48, 50, 51, 53, 54, 55, 57 through 63, 65, 67, 68, 71 through 79, 81, and 82.
(2) Group 2 Sailplanes	Ventus-2a, Ventus-2b, Discus-2a, and Discus-2b sailplanes.	<i>Ventus-2a and Ventus-2b:</i> 1, 2, 31, 32, 48, 54, 71, 117, 124 through 151, and 153; and all serial numbers that incorporate Modification Bulletin 349–42 or are equipped with a new tail unit per Shempp-Hirth Technical Note No. 349–27. <i>Discus-2a and Discus-2b:</i> 1 through 185, 187, 188, and 189.

What Is the Unsafe Condition Presented in This AD?

(d) This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for

Germany. The actions of this AD are intended to detect and correct problems within the sailplane elevator control system before they lead to flutter and sailplane instability. This could eventually result in loss of sailplane control.

What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) <i>For Group 1 sailplanes:</i> Add a mass balance to the elevators and install an elevator pushrod in the vertical fin. (2) <i>For Group 2 sailplanes:</i> Modify the mass balance weights.	Within the next 25 hours time-in-service (TIS) after June 4, 2004 (the effective date of this AD), unless already done. Within the next 25 hours TIS after June 4, 2004 (the effective date of this AD), unless already done.	Follow Schempp-Hirth Technical Note No. 360-19, dated December 20, 2002 (LBA-approved January 18, 2003). Follow Schempp-Hirth Technical Note No. 349-28, No. 360-20, and No. 863-8 (including appendix), dated September 16, 2003 (LBA-approved September 23, 2003).

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Standards Office, Small Airplane Directorate, FAA. For information on any already approved alternative methods of compliance, contact Greg Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; facsimile: (816) 329-4090.

Does This AD Incorporate Any Material by Reference?

(g) You must do the actions required by this AD following the instructions in Schempp-Hirth Technical Note No. 360-19, dated December 20, 2002 (LBA-approved January 18, 2003); and Schempp-Hirth Technical Note No. 349-28, No. 360-20, and No. 863-8 (including appendix), dated September 16, 2003 (LBA-approved September 23, 2003). The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You may get a copy from Schempp-Hirth Flugzeugbau GmbH, Postfach 14 43, D-73230 Kirchheim/Teck, Germany; telephone: 011 49 7021 7298-0; facsimile: 011 49 7021 7298-199. You may review copies at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Is There Other Information That Relates to This Subject?

(h) German AD No. 2003-048, effective date: March 6, 2003, and German AD No. 2003-280, effective date: October 2, 2003, also address the subject of this AD.

Issued in Kansas City, Missouri, on April 13, 2004.

James E. Jackson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-8793 Filed 4-21-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2000-CE-73-AD; Amendment 39-13585; AD 2004-05-01 R1]

RIN 2120-AA64

Airworthiness Directives; Bombardier Inc. Model Otter DHC-3 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is revising Airworthiness Directive (AD) 2004-05-01, which applies to certain Bombardier Inc. (formerly deHavilland Inc.) Model Otter DHC-3 airplanes that have turbine engines installed per one of three supplemental type certificates (STC). AD 2004-05-01 currently prohibits you from operating any affected airplane with these engine and propeller configurations unless a new STC for an elevator servo-tab with a redundant control linkage is installed. The FAA has since evaluated concerns, comments, and technical information related to all three STC configurations. Based on that evaluation, we have determined that further evaluation is necessary for the STCs owned by Texas Turbines Conversions, Inc., and Canada Turbine Conversions, Inc. Therefore, we are removing reference to these STCs from the AD, and the AD will only apply to those Bombardier Inc. airplanes that incorporate STC No. SA3777NM (A.M. Luton installation of Pratt and Whitney PT6A-34/-135 engine). After further evaluation, we may initiate rulemaking action regarding airplanes with the Texas Turbines Conversions, Inc., and Canada Turbine Conversions, Inc., STC configurations.

DATES: This AD becomes effective on May 25, 2004.

On April 20, 2004 (69 FR 9523, March 1, 2004), the Director of the Federal Register previously approved the incorporation by reference of certain publications listed in the regulation.

We must receive any comments on this AD by June 29, 2004.

ADDRESSES: Use one of the following to submit comments on this AD:

- *By mail:* FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-CE-73-AD, 901 Locust, Room 506, Kansas City, Missouri 64106.

- *By fax:* (816) 329-3771.

- *By e-mail:* 9-ACE-7-

Docket@faa.gov. Comments sent electronically must contain "Docket No. 2000-CE-73-AD" in the subject line. If you send comments electronically as attached electronic files, the files must be formatted in Microsoft Word 97 for Windows or ASCII.

You may get the service information identified in this AD A.M. Luton 3025 Eldridge Avenue, Bellingham, Washington, 98225; telephone (360) 671-7817; facsimile (360) 671-7820.

You may view the AD docket at FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2000-CE-73-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. Office hours are 8 a.m. to 4 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: *For Technical Questions Relating to STC No. SA3777NM or STC No. SA01059SE:* Richard Simonson, Aerospace Engineer, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue, SW., Renton, Washington 98055; telephone: (425) 917-6507; facsimile: (425) 917-6590. *For Administrative Questions Relating to This AD ACTION:* Larry Werth, AD Coordinator, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4147; facsimile: (816) 329-4149.

SUPPLEMENTARY INFORMATION: *Has FAA taken any action to this point? Several*