

not include any entity that is consolidated with a savings association on the Consolidated Statement of the Condition of the Thrift Financial Report.

(b) The Director assesses fees for processing notices, applications, securities filings, and requests, and for providing other services.

5. Revise § 502.75(b) to read as follows:

§ 502.75 What will happen if I do not pay my fees on time?

* * * * *

(b) *Failure to pay.* If you are a savings association and your holding company, affiliate, or subsidiary fails to pay any fee within 60 days of the date specified in a bill, the Director may assess and collect that fee, with interest, from you. If the holding company, affiliate, or subsidiary is related to more than one savings association, the Director may assess the fee against and collect it from each savings association as the Director may prescribe.

Dated: February 4, 2004.

By the Office of Thrift Supervision.

Richard M. Riccobono,

Deputy Director.

[FR Doc. 04-2846 Filed 2-9-04; 8:45 am]

BILLING CODE 6720-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-SW-38-AD]

RIN 2120-AA64

Airworthiness Directives; Eurocopter Deutschland Model MBB-BK 117 A-1, A-3, A-4, B-1, B-2, and C-1

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes adopting a new airworthiness directive (AD) for the specified Eurocopter Deutschland (ECD) model helicopters. This proposal would require inspecting the vertical fin skin paneling to determine if it was manufactured with the correct wall thickness. This proposal is prompted by a report from the manufacturer that some vertical fins may have been produced with the wrong vertical fin skin thickness. The actions specified by this proposed AD are intended to prevent failure of the vertical fin and subsequent loss of control of the helicopter.

DATES: Comments must be received on or before April 12, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 2003-SW-38-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. You may also send comments electronically to the Rules Docket at the following address: 9-asw-adcomments@faa.gov. Comments may be inspected at the Office of the Regional Counsel between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Richard Monschke, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0110, telephone (817) 222-5116, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments will be considered before taking action on the proposed rule. The proposals contained in this document may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their mailed comments submitted in response to this proposal must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 2003-SW-38-AD." The postcard will be date stamped and returned to the commenter.

Discussion

The Luftfahrt-Bundesamt (LBA), the airworthiness authority for the Federal Republic of Germany, notified the FAA that an unsafe condition may exist on ECD Model MBB-BK117 helicopters,

Model A-1 up to B-2, serial number (S/N) all, and Model C-1, S/N 7500 up to 7545. The LBA advises that during tail boom production, metal sheeting of 0.6-millimeter (mm) thickness was found instead of the specified 0.8-mm thickness for the skin paneling of several tail booms.

ECD has issued Alert Service Bulletin No. ASB-MBB-BK117-30-109, Revision 1, dated July 3, 2003, which specifies measuring the wall thickness of the skin paneling of the vertical fin to determine the thickness. The LBA classified this service bulletin as mandatory and issued AD No. 2003-219, dated August 21, 2003, to ensure the continued airworthiness of these helicopters in the Federal Republic of Germany.

This helicopter model is manufactured in the Federal Republic of Germany and is type certificated for operation in the United States under the provisions of 14 CFR 21.29 and the applicable bilateral agreement. Pursuant to the applicable bilateral agreement, the LBA has kept the FAA informed of the situation described above. The FAA has examined the findings of the LBA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

This previously described unsafe condition is likely to exist or develop on other helicopters of the same type design registered in the United States. Therefore, the proposed AD would require, within 100 hours time-in-service, using external calipers, measuring the wall thickness, including primer coating, of the skin paneling of the vertical fin. If the wall thickness, including the primer coating, of the paneling is less than 0.778 millimeter (0.03063 inch) at any of the measured locations, this proposed AD would also require replacing the vertical fin with an airworthy part before further flight.

The FAA estimates that this proposed AD would affect 132 helicopters of U.S. registry and the proposed actions would take approximately 1 hour per helicopter to accomplish at an average labor rate of \$65 per work hour. Based on these figures, we estimate the total cost impact of the proposed AD on U.S. operators to be \$8580 assuming no vertical fins will need to be replaced.

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal

would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

Eurocopter Deutschland: Docket No. 2003–SW–38–AD.

Applicability: Model MBB–BK 117 A–1, A–3, A–4, B–1, and B–2, all serial numbers (S/N), and Model C–1, S/N 7500 through 7545, certificated in any category.


Compliance: Required within 100 hours time in service, unless accomplished previously.

To prevent failure of the vertical fin and subsequent loss of control of the helicopter, do the following:

(a) Using external calipers, measure the wall thickness, including primer coating, of the skin paneling of the vertical fin at the locations shown in Figure 1 of this AD.

Note 1: Eurocopter Deutschland (ECD) Alert Service Bulletin No. ASB–MBB–BK117–30–109, Revision 1, dated July 3, 2003, pertains to the subject of this AD.

BILLING CODE 4910–13–P



- △ 1 Measurements are to be taken at at least three locations on the skin panel of the vertical fin. Care has to be taken that the external calipers are held squarely to the skin panel wall while measurements are being taken, since tilting of the calipers can lead to false results. If the panel thickness, including the primer coating, is at least 0.778 mm (0.03063 inch) at every measured location, no further action is necessary.

Vertical Fin-Skin Panelling
Figure 1

(b) If the wall thickness, including the primer coating, of the panelling is less than 0.778 millimeter (0.03063 inch) at any of the measured locations, replace the vertical fin with an airworthy part before further flight.

(c) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Safety Management Group, Rotorcraft Directorate, FAA, for information about previously approved alternative methods of compliance.

Note 2: The subject of this AD is addressed in Luftfahrt-Bundesamt (Federal Republic of Germany) AD 2003-219, dated August 21, 2003.

Issued in Fort Worth, Texas, on
January 30, 2004.

David A. Downey,

*Manager, Rotorcraft Directorate, Aircraft
Certification Service.*

[FR Doc. 04-2783 Filed 2-9-04; 8:45 am]

BILLING CODE 4910-13-C

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Parts 60 and 121

[Docket No. FAA-2002-12461; Notice No.
02-11]

RIN 2120-AH07

**Flight Simulation Device Initial and
Continuing Qualification and Use**

AGENCY: Federal Aviation
Administration (FAA), DOT.

ACTION: Proposed rule; reopening of
comment period.

SUMMARY: On September 25, 2002, the
FAA published a Notice of Proposed
Rulemaking (NPRM) to establish a new