

certification of the lapbelt, the FAA finds that good cause exists for making these amended special conditions effective upon issuance.

Conclusion

This action affects only certain novel or unusual design features on the Boeing Model 777 series airplanes. It is not a rule of general applicability, and it affects only Model 777 series airplanes listed on Type Certificate Data Sheet T00001SE.

List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

Authority Citation

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

The Amended Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following amended special conditions are issued as part of the type certification basis for the Boeing Model 777 series airplanes with inflatable lapbelts installed.

1. *Seats With Inflatable Lapbelts.* It must be shown that the inflatable lapbelt will deploy and provide protection under crash conditions where it is necessary to prevent serious head injury. The means of protection must take into consideration a range of stature from a two-year-old child to a ninety-fifth percentile male. The inflatable lapbelt must provide a consistent approach to energy absorption throughout that range. In addition, the following situations must be considered:

- a. The seat occupant is holding an infant.
- b. The seat occupant is a child in a child restraint device.
- c. The seat occupant is a child not using a child restraint device.
- d. The seat occupant is a pregnant woman.

2. The inflatable lapbelt must provide adequate protection for each occupant regardless of the number of occupants of the seat assembly, considering that unoccupied seats may have active seatbelts.

3. The design must prevent the inflatable lapbelt from being either incorrectly buckled or incorrectly installed such that the inflatable lapbelt would not properly deploy. Alternatively, it must be shown that such deployment is not hazardous to the occupant and will provide the required head injury protection.

4. It must be shown that the inflatable lapbelt system is not susceptible to inadvertent deployment as a result of wear and tear, or inertial loads resulting from in-flight or ground maneuvers (including gusts and hard landings), likely to be experienced in service.

5. Deployment of the inflatable lapbelt must not introduce injury mechanisms to the seated occupant, or result in injuries that could impede rapid egress. This assessment should include an occupant who is in the brace position when it deploys and an occupant whose belt is loosely fastened.

6. It must be shown that an inadvertent deployment that could cause injury to a standing or sitting person is improbable.

7. It must be shown that inadvertent deployment of the inflatable lapbelt during the most critical part of the flight will either not cause a hazard to the airplane or is extremely improbable.

8. It must be shown that the inflatable lapbelt will not impede rapid egress of occupants 10 seconds after its deployment.

9. The system must be protected from lightning and HIRF. The threats specified in Special Condition No. 25-ANM-78 are incorporated by reference for the purpose of measuring lightning and HIRF protection. For the purposes of complying with HIRF requirements, the inflatable lapbelt system is considered a "critical system" if its deployment could have a hazardous effect on the airplane; otherwise it is considered an "essential" system.

10. The inflatable lapbelt must function properly after loss of normal aircraft electrical power, and after a transverse separation of the fuselage at the most critical location. A separation at the location of the lapbelt does not have to be considered.

11. It must be shown that the inflatable lapbelt will not release hazardous quantities of gas or particulate matter into the cabin.

12. The inflatable lapbelt installation must be protected from the effects of fire such that no hazard to occupants will result.

13. There must be a means for a crewmember to verify the integrity of the inflatable lapbelt activation system prior to each flight or it must be demonstrated to reliably operate between inspection intervals.

14. The inflatable material may not have an average burn rate of greater than 2.5 inches/minute when tested using the horizontal flammability test as defined in 14 CFR part 25, appendix F, part I, paragraph (b)(5).

Issued in Renton, Washington, on October 29, 2004.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-24847 Filed 11-5-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19559; Directorate Identifier 2004-NE-03-AD; Amendment 39-13858; AD 2004-23-03]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce plc RB211 Trent 700 Series Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Rolls-Royce plc (RR) RB211 Trent 700 series turbofan engines. This AD requires initial and repetitive borescope inspections of the high pressure-and-intermediate pressure (HP-IP) turbine internal and external oil vent tubes for coking and carbon buildup, and cleaning or replacing the vent tubes if necessary. This AD results from a report of a RB211 Trent 700 series engine experiencing a disk shaft separation, overspeed of the IP turbine rotor, and multiple blade release of IP turbine blades. Preliminary findings suggest these events resulted from an internal oil fire in the HP-IP turbine oil vent tubes due to coking and carbon buildup. This fire led to a second fire in the internal air cavity below the IP turbine disk drive shaft. We are issuing this AD to prevent internal oil fires due to coking and carbon buildup, that could cause uncontained engine failure and damage to the airplane.

DATES: Effective November 23, 2004. The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of November 23, 2004.

We must receive any comments on this AD by January 7, 2005.

ADDRESSES: Use one of the following addresses to comment on this AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov>

and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001.

- Fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Rolls-Royce plc, PO Box 31, Derby, England; telephone: 011-44-1332-249428; fax: 011-44-1332-249223 for the service information referenced in this AD. You may examine the comments on this AD in the AD docket on the Internet at <http://dms.dot.gov>.

FOR FURTHER INFORMATION CONTACT: Ian Dargin, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7178; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: As a member of the National Transportation Safety Board (NTSB) investigation team, we are investigating an incident event and possible unsafe condition on RR RB211 Trent 700 series engines. The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom (UK) is helping us investigate. A report was received of a RB211 Trent 700 series engine experiencing a disk shaft separation, overspeed of the IP turbine rotor, and multiple blade release of IP turbine blades. Preliminary findings suggest these events resulted from an internal oil fire in the HP-IP turbine oil vent tubes due to coking and carbon buildup. This fire led to a second fire in the internal air cavity below the IP turbine disk drive shaft. Because the oil vent tubes on the event engine were destroyed, the partner engine on the same airplane was inspected. That inspection revealed heavy coking and carbon buildup, with partial blockage of the HP-IP turbine oil vent tubes. Both engines had the same on-wing life of 15,169 hours with 2,344 cycles-since-new. Both engines contained Mobil Jet Oil 291, which also is suspect and will be removed from the list of approved oils for these engines. The NTSB investigation is ongoing and a finding of probable cause has not yet been made. The fire, disk overspeed, and blade release appear to be the result of the coking and carbon buildup, evident in the sister engine and linked by cycles and oil use to the event engine.

Relevant Service Information

We have reviewed and approved the technical contents of RR Alert Service Bulletin (ASB) No. RB.211-72-AE302, Revision 1, dated May 25, 2004, that describes procedures for:

- Initial and repetitive borescope inspections for coking and carbon buildup in the HP-IP turbine oil vent tubes; and
- Cleaning the tubes if necessary, and removing the engine from service to clean or replace the tubes.

This ASB requires that all operators submit inspection data to the manufacturer. The CAA classified this ASB as mandatory and issued AD G-2004-0016, dated June 20, 2004, in order to ensure the airworthiness of these RB211 Trent 700 series engines in the UK.

Bilateral Airworthiness Agreement

These engine models are manufactured in the UK and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Under this bilateral airworthiness agreement, the CAA kept the FAA informed of the situation described above. As a member of the NTSB investigation team, we have examined the findings with the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

FAA's Determination and Requirements of This AD

Although no airplanes that are registered in the United States use these engines, the possibility exists that the engines could be used on airplanes that are registered in the United States in the future. The unsafe condition described previously is likely to exist or develop on other RB211 Trent 700 series turbofan engines of the same type design. We are issuing this AD to prevent internal oil fires due to coking and carbon buildup, that could cause uncontained engine failure and damage to the airplane. This AD requires:

- Initial and repetitive borescope inspections of the HP-IP turbine oil vent tubes for coking and carbon buildup; and
- Cleaning or replacing the oil vent tubes if they fail the inspection.

FAA's Determination of the Effective Date

Since there are currently no domestic operators of this engine model, notice

and opportunity for public comment before issuing this AD are unnecessary. A situation exists that allows the immediate adoption of this regulation.

Interim Action

These actions are interim actions and we may take further rulemaking actions in the future.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any written relevant data, views, or arguments regarding this AD. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. FAA-2004-19559; Directorate Identifier 2004-NE-03-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify it.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this AD. Using the search function of the DMS Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78) or you may visit <http://dms.dot.gov>.

Examining the AD Docket

You may examine the docket that contains the AD, any comments received, and any final disposition in person at the DMS Docket Offices between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone (800) 647-5227) is located on the plaza level of the Department of Transportation Nassif Building at the street address stated in **ADDRESSES**. Comments will be available in the AD docket shortly after the DMS receives them.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that the regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Under the authority delegated to me by the Administrator, the FAA amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2004-23-03 Rolls-Royce plc: Amendment 39-13858. Docket No. FAA-2004-19559; Directorate Identifier 2004-NE-03-AD.

Effective Date

(a) This AD becomes effective November 23, 2004.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Rolls-Royce plc (RR) RB211 Trent 768-60, RB211 Trent 772-60, and RB211 Trent 772B-60 series turbofan engines. These engines are installed on, but not limited to, Airbus A330-243, -341, -342 and -343 series airplanes.

Unsafe Condition

(d) This AD results from a report of a RB211 Trent 700 series engine experiencing a disk shaft separation, overspeed of the IP turbine rotor, and multiple blade release of IP turbine blades. Preliminary findings suggest these events resulted from an internal oil fire in the HP-IP turbine oil vent tubes due to coking and carbon buildup. This fire led to a second fire in the internal air cavity below the IP turbine disk drive shaft. We are issuing this AD to prevent internal oil fires

due to coking and carbon buildup, that could cause uncontained engine failure and damage to the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Initial Visual Inspection

(f) Using the inspection schedule in Table 1 of this AD, perform an initial borescope inspection of the high pressure-and-intermediate pressure (HP-IP) turbine internal and external oil vent tubes for coking and carbon buildup as follows:

(1) Insert an 8 mm diameter flex borescope to see if it will pass along the full length of the vent tube into the bearing chamber.

(2) If the vent tube prevents an 8 mm diameter flex borescope from passing along the full length of the tube into the bearing chamber, repeat the action using a 6mm flex borescope.

(3) If the 6 mm diameter flex borescope passes through to the bearing chamber, continue using the engine in service, and perform the repetitive inspections in this AD at the required intervals.

(4) If the vent tube prevents the 6 mm diameter flex borescope from passing along the full length of the tube into the bearing chamber, clean or replace the vent tube. Information on oil vent tube cleaning or replacement can be found in Rolls-Royce plc Alert Service Bulletin No. RB.211-72-AE302, Revision 1, dated May 25, 2004.

TABLE 1.—INITIAL INSPECTION SCHEDULE

If the engine or the 05 module:	Then initially inspect:
Has reached 10,000 hours time-since-new (TSN) or reached 2,500 cycles-since-new (CSN) on the effective date of this AD.	Within 3 months after the effective date of this AD.
Has fewer than 10,000 hours TSN or fewer than 2,500 CSN on the effective date of this AD.	Within 3 months after reaching 10,000 hours TSN or 2,500 CSN, whichever occurs first.

Repetitive Visual Inspections

(g) Using the inspection schedule in Table 2 of this AD and paragraphs (f)(1) through

(f)(4) of this AD, perform repetitive borescope inspections of the HP-IP turbine internal and

external oil vent tubes for coking and carbon buildup.

TABLE 2.—REPETITIVE INSPECTION SCHEDULE

If at the previous inspection, before any cleaning was performed:	Then:
(1) There was no coking and carbon buildup of a visible thickness; or an 8 mm diameter flex borescope could pass along the full length of the internal vent tube into the bearing chamber.	Reinspect within 6,400 hours time-since-last-inspection (TSLI) or within 1,600 cycles-since-last-inspection (CSLI), whichever occurs first.
(2) The coking or carbon buildup prevented an 8 mm diameter flex borescope from passing through the internal vent tube, but a 6 mm diameter flex borescope could pass along the full length of the internal vent tube into the bearing chamber.	Reinspect within 1,600 hours TSLI or within 400 CSLI, whichever occurs first.
(3) The coking or carbon buildup prevented the 6 mm diameter flex borescope from passing through the full length of the internal vent tube and into the bearing chamber.	Clean or replace the vent tubes within 10 CSLI. Information on oil vent tube cleaning or replacement can be found in Rolls-Royce plc Alert Service Bulletin No. RB.211-72-AE302, Revision 1, dated May 25, 2004.

Alternative Methods of Compliance

(h) The Manager, Engine Certification Office, has the authority to approve

alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Material Incorporated by Reference

(i) None.

Related Information

(j) CAA airworthiness directive No. G-2004-0016, dated June 20, 2004, also addresses the subject of this AD.

Issued in Burlington, Massachusetts, on November 1, 2004.

Peter A. White,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 04-24817 Filed 11-5-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2004-19404; Airspace Docket No. 2004-ASW-13]

Modification to Class D Airspace; Alamogordo, NM

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; request for comments.

SUMMARY: This action modifies the Class D airspace area at Holloman Air Force Base, Alamogordo, NM (HMN). The closure of Midway Airport, Alamogordo, NM has made this rule necessary. The intended effect of this rule is to modify the controlled airspace to include that area within the 4.8-mile radius of Holloman Air Force Base originally excluded because of Midway Airport.

DATES: Effective 0901 UTC, March 17, 2005.

Comments for inclusion in the Rules Docket must be received on or before December 15, 2004.

ADDRESSES: Send comments on the rule to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket number, FAA-2004-19404/Airspace Docket No. 2004-ASW-13, at the beginning of your comments. You may also submit comments on the Internet at <http://dms.dot.gov>. Anyone can find and read the comments received in this docket, including the name, address and any other personal information placed in the docket by a commenter. You may review the public docket containing any comments received and this Direct Final Rule in person at the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is located on the plaza level of the Department of Transportation Nassif

Building at the street address stated previously.

An informal docket may also be examined during normal business hours at the office of the Air Traffic Division, Airspace Branch, Federal Aviation Administration, Southwest Region, 2601 Meacham Boulevard, Fort Worth, TX. Call the manager, Airspace Branch, ASW-520, telephone (817) 222-5520; fax (817) 222-5981, to make arrangements for your visit.

FOR FURTHER INFORMATION CONTACT:

Joseph R. Yadouga, Air Traffic Division, Airspace Branch, Federal Aviation Administration, Southwest Region, Fort Worth, TX 76193-0520; telephone: (817) 222-5597.

SUPPLEMENTARY INFORMATION: This amendment to 14 CFR Part 71 modifies the Class D airspace designation for an airspace area from the surface up to but not including 6,600 feet MSL at Holloman Air Force Base, Alamogordo, NM and will be published in paragraph 5000 of FAA Order 7400.9M, dated August 30, 2004, and effective September 16, 2004, which is incorporated by reference in 14 CFR 71.1.

The Direct Final Rule Procedure

The FAA anticipates that this regulation will not result in an adverse or negative comment, and, therefore, issues it as a direct final rule. The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Unless a written adverse or negative comment, or a written notice of intent to submit an adverse or negative comment is received within the comment period, the regulation will become effective on the date specified. After the close of the comment period, the FAA will publish a document in the **Federal Register** indicating that no adverse or negative comments were received and confirming the date on which the final rule will become effective. If the FAA does receive, within the comment period, an adverse or negative comment, or written notice of intent to submit such a comment, a document withdrawing the direct final rule will be published in the **Federal Register**, and a notice of proposed rulemaking may be published with a new comment period.

Comments Invited

Although this action is in the form of a direct final rule, and was not preceded by a notice of proposed rulemaking, interested persons are invited to

comment on this rule by submitting such written data, views, or arguments as they may desire. Communications must identify both docket numbers. All communications received on or before the closing date for comments will be considered, and this rule may be amended or withdrawn in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of this action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this action will be filed in the Rules Docket.

Agency Findings

This rule does not have federalism implications, as defined in Executive Order No. 13132, because it does not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with State authorities prior to publication of this rule.

The FAA has determined that this regulation is noncontroversial and unlikely to result in adverse or negative comments. For the reasons discussed, I certify that this regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as these routine matters will only affect air traffic procedures and air navigation. I certify that this rule will not have significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration amends part 71 of the