

Hawaii accounted for about 3 percent of production. There are no U.S. mango exports.

The Regulatory Flexibility Act requires that agencies consider the economic effects of their rules on small entities. Whether affected entities may be considered small in this case depends on their annual gross receipts. Annual receipts of \$750,000 or less is the small entity criterion set by the Small Business Administration for establishments primarily engaged in "other noncitrus fruit farming" (NAICS code 111339). As noted previously, Florida accounted for about 97 percent of mango production in 1997, thus mango producers in that State are the entities most likely to be affected by this proposed rule. Most, if not all, mango producers in Florida are small entities. According to information provided by the University of Florida's Institute of Food and Agricultural Sciences (IFAS), about 10 to 15 growers manage the bulk of the producing mango acreage in Florida. According to IFAS, about 25 percent of Florida growers produce mangoes alone, while the remaining 75 percent are diversified operations growing other tropical fruits in addition to mangoes. Florida growers occupy niche markets in the State by providing green fruit for processing into chutney and other products and by providing fresh, untreated, tree-ripened fruit for consumption. The availability of larger mangoes from Mexico and Central America in the larger U.S. market is expected to have little to no impact on Florida producers who occupy those niche markets, as producers in Mexico and Central America are not expected to be shipping green fruit for processing and would be unable to provide untreated, tree-ripened fruit to U.S. markets.

The availability of a treatment for larger mangoes of the rounded varieties is not expected to significantly affect U.S. mango producers, as the amount of those larger mangoes likely to be imported from Mexico and Central America would represent a fraction of current import levels. Moreover, much of Florida's harvest (the source of about 97 percent of domestic production in 1997) is consumed within that State or is processed into chutney and other products; these markets are unlikely to be affected by the availability of larger mangoes from Mexico and Central America. Therefore, we do not expect that the economic effects of this proposed rule on U.S. entities, large or small, would be significant.

Under these circumstances, the Administrator of the Animal and Plant Health Inspection Service has

determined that this action would not have a significant economic impact on a substantial number of small entities.

Executive Order 12988

This proposed rule has been reviewed under Executive Order 12988, Civil Justice Reform. If this proposed rule is adopted: (1) All State and local laws and regulations that are inconsistent with this rule will be preempted; (2) no retroactive effect will be given to this rule; and (3) administrative proceedings will not be required before parties may file suit in court challenging this rule.

Paperwork Reduction Act

This rule contains no new information collection or recordkeeping requirements under the Paperwork Reduction Act of 1995 (44 U.S.C. 3501 *et seq.*).

List of Subjects in 7 CFR Part 300

Incorporation by reference, Plant diseases and pests, Quarantine.

Accordingly, 7 CFR part 300 is amended as follows:

PART 300—INCORPORATION BY REFERENCE

1. The authority citation for part 300 continues to read as follows:

Authority: 7 U.S.C. 7701–7772; 7 CFR 2.22, 2.80, and 371.3.

2. In § 300.1, paragraph (a) would be amended as follows:

a. In paragraph (a)(4), by removing the word "and".

b. In paragraph (a)(5), by removing the period and adding the word "; and" in its place.

c. By adding a new paragraph (a)(6) to read as follows:

§ 300.1 Plant Protection and Quarantine Treatment Manual.

(a) * * *

(6) Treatment T102-a, dated _____.

* * * * *

Done in Washington, DC, this 23rd day of December 2002.

Kevin Shea,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 02–33049 Filed 12–31–02; 8:45 am]

BILLING CODE 3410–34–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 96–ANE–40–AD]

Airworthiness Directives; Hartzell Propeller Inc. ()HC–() (2,3)(X,V)()–() Series and HA–A2V20–1B Series Propellers with Aluminum Blades

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The Federal Aviation Administration (FAA) proposes to revise an existing airworthiness directive (AD), applicable to Hartzell Propeller Inc. ()HC–() (2,3)(X,V)()–() series and HA–A2V20–1B series propellers with aluminum blades. That AD currently requires initial and repetitive dye penetrant and eddy current inspections of the blade and an optical comparator inspection of the blade retention area, and, if necessary, replacement with serviceable parts. In addition, that AD currently requires initial and repetitive visual and magnetic particle inspection of the blade clamp, dye penetrant inspection of the blade internal bearing bore, and, if necessary, replacement with serviceable parts. Also, for all HC–(1,4,5,8)(2,3)(X,V)()–() steel hub propellers, that AD currently requires an additional initial and repetitive visual and magnetic particle inspection of the hub, and, if necessary, replacement with serviceable parts. This proposal would revise that AD by introducing as an optional terminating action for the initial and repetitive inspections of that AD, replacement of affected propellers with Hartzell Propeller Inc. model "MV" series propellers. This proposal is prompted by type certification approval of the Hartzell "MV" series propellers that are direct replacements for the affected propellers, and service bulletin approval to allow modification of affected propellers to the "MV" type design configuration. The Hartzell "MV" series propellers were certified as Hartzell propeller models ()HC–() (2,3)MV()–() and HA–A2MV20–1B. The actions specified by the proposed AD are intended to prevent blade separation due to cracked blades, hubs, or blade clamps, which can result in loss of control of the airplane.

DATES: Comments must be received by March 3, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation

Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 96-ANE-40-AD, 12 New England Executive Park, Burlington, MA 01803-5299. Comments may be inspected at this location, by appointment, between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. Comments may also be sent via the Internet using the following address: *9-ane-adcomment@faa.gov*. Comments sent via the Internet must contain the docket number in the subject line.

The service information referenced in the proposed rule may be obtained from Hartzell Propeller Inc., One Propeller Place, Piqua, OH 45356-2634, ATTN: Product Support; telephone (937) 778-4200, fax (937) 778-4321. This information may be examined, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT: Tomaso DiPaolo, Aerospace Engineer, Chicago Aircraft Certification Office, FAA, Small Airplane Directorate, 2300 East Devon Ave., Des Plaines, IL 60018; telephone (847) 294-7031, fax (847) 294-7834.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to

Docket Number 96-ANE-40-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRM's

Any person may obtain a copy of this NPRM by submitting a request to the FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 96-ANE-40-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

Discussion

On August 15, 1997, the Federal Aviation Administration (FAA) issued airworthiness directive (AD) 97-18-02, Amendment 39-10112 (62 FR 45309, August 27, 1997), applicable to Hartzell Propeller Inc. ()HC-()(2,3)(X,V)()-() series propellers and HA-A2V20-1B series propellers, to require initial and repetitive dye penetrant and eddy current inspections of the blade and an optical comparator inspection of the blade retention area, and, if necessary, replacement with serviceable parts. In addition, that AD was issued to require initial and repetitive visual and magnetic particle inspections of the blade clamp, dye penetrant inspections of the blade internal bearing bore, and, if necessary, replacement with serviceable parts. Also, that AD was issued to require for all HC-(1,4,5,8)(2,3)(X,V)()-() steel hub propellers, an additional initial, and repetitive visual and magnetic particle inspections of the hub and, if necessary, replacement with serviceable parts. That action was prompted by reports of cracked blades, blade clamps, and hubs and reports of blade separations. That condition, if not corrected, could result in loss of control of the airplane.

Hartzell Certification Efforts To Create Optional Terminating Action To Address AD 97-18-02

Since issuance of that AD, Hartzell Propeller Inc. has received type certification approval of the Hartzell "MV" series of propellers that are direct replacements for the affected propellers. The Hartzell "MV" series propellers were certified as Hartzell propeller models ()HC-()(2,3)MV()-() and HA-A2MV20-1B. Also, Hartzell Propeller Inc. service bulletins (SB's) HC-SB-61-232, dated March 20, 1998, and HC-SB-61-233, dated April 17, 1998, have been approved to allow modification of affected propellers to the "MV" type design configuration. This proposal would introduce as an optional terminating action, for the initial and repetitive inspections of this proposal, replacement of affected propellers with

Hartzell Propeller Inc. model "MV" series propellers.

Manufacturer's Service Information

The FAA has reviewed and approved the technical contents of Hartzell Propeller Inc. SB No. HC-SB-61-217, Revision 1, dated July 11, 1997, that describes procedures for fluorescent dye penetrant and eddy current inspections of the blade and an optical comparator inspection of the blade retention area, and, if necessary, replacement with serviceable parts. In addition, this SB describes procedures for visual and magnetic particle inspection of the blade clamp, dye penetrant inspection of the blade internal bearing bore and, if necessary, replacement with serviceable parts. For all HC-(1,4,5,8)(2,3)(X,V)()-() steel hub propellers, this SB describes an additional visual and magnetic particle inspection of the hub, and, if necessary, replacement with serviceable parts.

FAA's Determination of an Unsafe Condition and Proposed Actions

Since an unsafe condition has been identified that is likely to exist or develop on other Hartzell Propeller Inc. ()HC-()(2,3)(X,V)()-() series and HA-A2V20-1B series propellers of this same type design, the proposed AD would revise AD 97-18-02 to continue to require:

- Initial and repetitive dye penetrant and eddy current inspections of the blade and an optical comparator inspection of the blade retention area, and, if necessary, replacement with serviceable parts.
- Initial and repetitive visual and magnetic particle inspection of the blade clamp, and, if necessary, replacement with serviceable parts.
- Initial and repetitive dye penetrant inspection of the blade internal bearing bore, and, if necessary, replacement with serviceable parts.
- For all HC-(1,4,5,8)(2,3)(X,V)()-() steel hub propellers, an additional initial and repetitive visual and magnetic particle inspection of the hub, and, if necessary, replacement with serviceable parts.
- A reporting requirement to obtain additional data and determine if adjustment can be made to the repetitive inspection intervals, with possible relief.

This proposal also adds as an optional terminating action for the initial and repetitive inspections of this proposal, replacement of affected propellers with Hartzell Propeller Inc. model MV propellers.

Economic Analysis

Since the proposed revision to AD 97-18-02 is to add an optional terminating action, the total cost of the proposed revised AD on U.S. operators can be estimated to be \$0.

Regulatory Analysis

This proposed rule does not have federalism implications, as defined in Executive Order 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this proposed rule.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT

Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption

ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-10112 (62 FR 45309, August 27, 1997), and by adding a new airworthiness directive, to read as follows:

Hartzell Propeller Inc.: Docket No. 96-ANE-40-AD. Revises AD 97-18-02, Amendment 39-10112.

Applicability: This airworthiness directive (AD) is applicable to Hartzell Propeller Inc. ()HC-() (2,3)(X,V) ()-() series and HA-A2V20-1B series propellers with aluminum blades. These propellers are installed on but not limited to the aircraft listed in the following Table 1:

TABLE 1.—AFFECTED AIRCRAFT

Manufacturer	Aircraft model
Aero Commander (Twin Commander)	500 500A 500B, 500S, and 500U 520 560 560A, 560E 680, 680E, 720 680F, 680FP, 680FL, 680FLR B1 (Callair)
Aeromere	Falco F.8.L
Aeronautica Macchi	AL60-F5 AM-3
Bauger	Sail Plane
Beech	35 Series Bonanza 35-C33 Debonair 35-C33A, E33A, F33A 50 Series Twin Bonanza 58P, 58TC Baron 95-55, 95-A55, 95-B55 Baron 65, A65, 65-(B)80, 65-A80, A65-8200, 70
Bellanca	14-13 14-19 14-19-2 14-19-3 7GCA, 7GCB, 7GCC DW-1 Eagle
Camair	480
Cessna	170 170A 172 Skyhawk 175 180, A, B, C, D, E, F, G, H 182, A, B, C, D, E, G, H, J, K, L, M 210, A, B, C, 5, 5A 310, A, B, C, D, E, F, G, H, E310H 320, 320-1 Skyknight 320A, 320B 402 Businessliner 411 Wren 460 Wren 460H, J, K, L, M
deHavilland	DH104 Dove DH114 Heron

TABLE 1.—AFFECTED AIRCRAFT—Continued

Manufacturer	Aircraft model
Dornier	DO27Q-6 DO28A-1 DO28B-1
Fuji	T-3, LM-2
GAF—Gov't. Aircraft Factories	N22B, N24A, N22S, N22C
Goodyear	(Loral) GA22A Goodyear Blimp GZ19, 19A Goodyear Blimp
Great Lakes	2T-1A-2
Grumman	G44, G44A Widgeon G21C, D Goose
Helio	H-391 Courier H-391B Courier H-395A Courier
Luscombe	11
Mooney	11A
Multitech (Temco)	M20
Nardi	D16 Twin Navion
Navion	D16A Twin Navion
Pacific Aerospace (Fletcher)	FN-333
Piaggio	Navion B
Piper	Navion, Navion A
Pilatus	FU-24, FU-24A
Prop Jets Inc.	P-149D
Republic (STOL Amphibian)	P136-L1 Royal Gull
Scottish Aviation (BAE)	P136-L2 Royal Gull
Stinson	P149D
Sud Aviation (SOCATA)	P166 Royal Gull
Swift	PC-3
Taylorcraft	PC-6
Texas Bullet	PC-6-H1, -H2 Porter
Windecker	PA-E23-250 Aztec
.....	PA14 Family Cruiser
.....	PA18(A)(S)-150 Super Cub
.....	PA18A-150 Super Cub
.....	PA22-150, PA22S-150
.....	Tripacer
.....	PA23 Series Apache
.....	PA23-160 Apache
.....	PA23-235 Aztec
.....	PA23-250 Aztec
.....	PA24-250 Comanche
.....	PA24-400 Comanche
.....	PA24S Comanche
.....	PA28 Cherokee
.....	PA28-140 Cherokee
.....	200
.....	200A,B,C
.....	RC3 Seabee
.....	B.206 Series 2 Beagle
.....	L-5
.....	108, -1, -2, -3
.....	108-2-3
.....	GY.80-150 Gardan
.....	GY.80-160 Gardan Horizon
.....	GC-1B
.....	20
.....	205
.....	Eagle

Note 1: The above is not a complete list of aircraft which may contain the affected Hartzell Propeller Inc. ()HC-() (2,3)(X,V)()-() series and HA-A2V20-1B series propellers with aluminum blades because of installation approvals made by, for example, Supplemental Type Certificate or field approval under FAA Form 337 "Major Repair and Alteration." It is the responsibility of the owner, operator, and person returning the

aircraft to service to determine if an aircraft has an affected propeller.

Note 2: The parentheses that appear in the propeller models indicate the presence or absence of additional letter(s) which vary the basic propeller hub model designation. This airworthiness directive is applicable regardless of whether these letters are present

or absent on the propeller hub model designation.

Note 3: This AD applies to each propeller identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For propellers that have been modified, altered, or repaired so that the performance of the

requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (h) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Compliance with this AD is required as indicated, unless already done.

To prevent blade separation due to cracked blades, hubs, or blade clamps, which can result in loss of control of the airplane, accomplish the following:

(a) On Hartzell propeller models with hub models ()HC-(1,4,5,8)(2,3)(X,V)()-() perform initial and repetitive inspections and, if necessary, replace with serviceable parts in accordance with Hartzell Propeller Inc. Service Bulletin (SB) No. HC-SB-61-217, Revision 1, dated July 11, 1997, as follows:

(1) Initially perform a fluorescent dye penetrant and eddy current inspection of the blade, an optical comparator inspection of the blade retention area, a dye penetrant inspection of the blade internal bearing bore, and a visual and magnetic particle inspection of the blade clamp and of the hub. The initial inspection is required within the following:

(i) 1,000 hours time since new (TSN) for propellers with less than 900 hours TSN on September 11, 1997, provided that the initial inspections are performed within 60 calendar months TSN or 24 calendar months after September 11, 1997, whichever calendar time occurs later, or

(ii) 100 hours time in service (TIS) for propellers with 900 or more hours TSN, or unknown TSN, on September 11, 1997, provided that the initial inspections are performed within 24 calendar months after September 11, 1997.

(2) Thereafter, perform repetitive fluorescent dye penetrant and eddy current inspection of the blade, an optical comparator inspection of the blade retention area, and a visual and magnetic particle inspection of the blade clamp. The repetitive inspection is required at intervals not to exceed 500 hours TIS or 60 calendar months, whichever occurs first, since last inspection.

(3) Thereafter, perform a repetitive visual and magnetic particle inspection of the hub. This repetitive hub inspection is required at intervals not to exceed 250 hours TIS or 60 calendar months, whichever occurs first, since last inspection.

(4) Thereafter, perform repetitive dye penetrant inspections of the blade internal bearing bore. This repetitive blade internal bearing bore inspection is required at intervals not to exceed 60 calendar months since last inspection.

(b) On Hartzell propeller models with hub models ()HC-(A,D)(2,3)(X,V)()-(), and HA-A2V20-1B, except HC-A3VF-7(), perform initial and repetitive inspections and, if necessary, replace with serviceable parts in accordance with Hartzell SB No. HC-SB-61-217, Revision 1, dated July 11, 1997, as follows:

(1) Initially perform a fluorescent dye penetrant and eddy current inspection of the blade, an optical comparator inspection of

the blade retention area, a visual and magnetic particle inspection of the blade clamp, and a dye penetrant inspection of the blade internal bearing bore. The initial inspection is required within the following:

(i) 1,000 hours TSN for propellers with less than 800 hours TSN on September 11, 1997, provided that the initial inspections are performed within 60 calendar months TSN or 24 calendar months after September 11, 1997, whichever calendar time occurs later; or

(ii) 200 hours TIS for propellers with 800 or more hours TSN, or unknown TSN, on September 11, 1997, provided that the initial inspections are performed within 24 calendar months after September 11, 1997.

(2) Thereafter, perform repetitive fluorescent dye penetrant and eddy current inspection of the blade, an optical comparator inspection of the blade retention area, and a visual and magnetic particle inspection of the blade clamp. The repetitive inspection is required at intervals not to exceed 500 hours TIS or 60 calendar months, whichever occurs first, since last inspection.

(3) Thereafter, perform repetitive dye penetrant inspections of the blade internal bearing bore. This repetitive blade internal bearing bore inspection is required at intervals not to exceed 60 calendar months since last inspection.

(c) On Hartzell propeller models with hub models HC-A3VF-7() perform initial and repetitive inspections and, if necessary, replace with serviceable parts in accordance with Hartzell SB No. HC-SB-61-217, Revision 1, dated July 11, 1997, as follows:

(1) Initially perform a fluorescent dye penetrant and eddy current inspection of the blade, an optical comparator inspection of the blade retention area, a visual and magnetic particle inspection of the blade clamp, and a dye penetrant inspection of the blade internal bearing bore. The initial inspection is required within the following:

(i) 3,000 hours TSN for propellers that have never been overhauled and have less than 2,500 hours TSN on September 11, 1997, provided that the initial inspections are performed within 60 calendar months TSN or 24 calendar months after September 11, 1997, whichever calendar time occurs later, or

(ii) 3,000 hours TIS since last overhaul for propellers that have been overhauled but have less than 2,500 hours TIS since last overhaul on the September 11, 1997, provided that the initial inspections are performed within 60 calendar months TIS since last overhaul or 24 calendar months after September 11, 1997, whichever calendar time occurs later, or

(iii) 500 hours TIS, for propellers that have never been overhauled and have 2,500 or more hours TSN on September 11, 1997, or propellers which have been overhauled and have 2,500 or more hours TIS since last overhaul on September 11, 1997, or propellers with unknown TSN, provided that the initial inspections were performed within 24 calendar months after September 11, 1997.

(2) Thereafter, perform repetitive fluorescent dye penetrant and eddy current inspection of the blade, an optical comparator inspection of the blade retention area, and a visual and magnetic particle inspection of the blade clamp. The repetitive

inspection is required at intervals not to exceed 3,000 hours TIS or 60 calendar months, whichever occurs first, since last inspection.

(3) Thereafter, perform repetitive dye penetrant inspections of the blade internal bearing bore. This repetitive blade internal bearing bore inspection is required at intervals not to exceed 60 calendar months since last inspection.

(d) The initial inspection of the internal blade bearing bore required by paragraphs (a)(1), (b)(1), or (c)(1) of this AD need not be done again if previously done in accordance with page 4 of Hartzell SB No. HC-SB-61-217, Revision 1, dated July 11, 1997.

(e) If not previously done, shotpeen the propeller blade shank area during the initial inspection required by paragraphs (a)(1), (b)(1), or (c)(1) of this AD, as appropriate, and perform the shot peening in accordance with Hartzell SB No. HC-SB-61-217, Revision 1, dated July 11, 1997. Re-shot peening of the propeller blade shank area during the initial or repetitive inspections required by paragraphs (a)(1), (b)(1), or (c)(1) or (a)(2), (b)(2), or (c)(2) of this AD, as appropriate, is required only if the propeller blade shank area has been repaired or has excessive wear or damage in accordance with Hartzell SB No. HC-SB-61-217, Revision 1, dated July 11, 1997.

Reporting Requirements

(f) Report inspection results to the Manager, Chicago Aircraft Certification Office, FAA, Small Airplane Directorate, 2300 East Devon Ave., Des Plaines, IL 60018, within 15 working days of the inspection. Reporting requirements have been approved by the Office of Management and Budget (OMB) and assigned OMB control number 2120-0056.

Optional Terminating Action

(g) Replacement of affected propellers with, or modification to Hartzell Propeller Inc. model "MV" series propellers constitutes terminating action for the initial and repetitive inspections specified in paragraphs (a) through (e) of this AD. The Hartzell "MV" series of propellers were certified as Hartzell propeller models ()HC-() (2,3)MV()-() and HA-A2MV20-1. Modification of affected propellers to "MV" series propellers must be done in accordance with Hartzell SB No.'s HC-SB-61-232, dated March 20, 1998, and HC-SB-61-233, dated April 17, 1998.

Alternative Methods of Compliance

(h) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Chicago Aircraft Certification Office. The request should be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Chicago Aircraft Certification Office. Compliance with Hartzell SB No. HC-SB-61-217, Revision 2, dated October 7, 1999, is an alternative method of compliance to Hartzell SB No. HC-SB-61-217, Revision 1.

Note 4: Information concerning the existence of approved alternative methods of

compliance with this airworthiness directive, if any, may be obtained from the Chicago Aircraft Certification Office.

Special Flight Permits

(i) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be done.

Issued in Burlington, Massachusetts, on December 24, 2002.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 02-33074 Filed 12-31-02; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 62

[DC051-7002b; FRL-7434-8]

Approval and Promulgation of State Air Quality Plans for Designated Facilities and Pollutants; the District of Columbia; Control of Emissions From Existing Hospital/Medical/ Infectious Waste Incinerator (HMIWI) Units

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA is proposing to approve the HMIWI section 111(d)/129 negative declaration submitted by the District of Columbia Department of Health, Environmental Health Administration. The negative declaration certifies that HMIWI units, which are subject to the requirements of sections 111(d) and 129 of the Clean Air Act (CAA), do not exist in the District of Columbia air pollution control jurisdiction. If no adverse comments are received in response to this action, no further activity is contemplated. If EPA receives adverse comments, the direct final rule will be withdrawn and all public comments received will be addressed in a subsequent final rule based on this proposed rule. EPA will not institute a second comment period. Any parties interested in commenting on this action should do so at this time.

DATES: Comments must be received in writing by February 3, 2003.

ADDRESSES: Written comments should be mailed to Walter Wilkie, Deputy Chief, Air Quality Planning and Information Services Branch, Mailcode 3AP21, U.S. Environmental Protection Agency, Region III, 1650 Arch Street, Philadelphia, Pennsylvania 19103.

Copies of the documents relevant to this action are available for public inspection during normal business hours at the Air Protection Division, U.S. Environmental Protection Agency, Region III, 1650 Arch Street, Philadelphia, Pennsylvania 19103.

FOR FURTHER INFORMATION CONTACT: James B. Topsale at (215) 814-2190, or by e-mail at topsale.jim@epa.gov. Please note that while questions may be posed via phone and e-mail, formal comments must be submitted in writing, as indicated in the **ADDRESSES** section of this document.

SUPPLEMENTARY INFORMATION: For further information, please see the information provided in the direct final action, with the same title, that is located in the "Rules and Regulations" section of this **Federal Register** publication.

Dated: December 20, 2002.

Thomas C. Voltaggio,

Acting Regional Administrator, Region III.

[FR Doc. 02-33099 Filed 12-31-02; 8:45 am]

BILLING CODE 6560-50-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 62

[DC051-7003b; DE068-7003b; PA187-7003b, PA186-7003b; FRL-7434-6]

Approval and Promulgation of State Air Quality Plans for Designated Facilities and Pollutants; Delaware, the District of Columbia, Allegheny County and Philadelphia, Pennsylvania; Control of Emissions From Existing Small Municipal Waste Combustion Units

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA is proposing to approve the section 111(d)/129 negative declarations submitted by the District of Columbia, the State of Delaware, Allegheny County and the City of Philadelphia, Pennsylvania. Each negative declaration certifies that small municipal waste combustion (MWC) units, which are subject to the requirements of sections 111(d) and 129 of the Clean Air Act (CAA), do not exist within its air pollution control jurisdiction. If no adverse comments are received in response to this action, no further activity is contemplated. If EPA receives adverse comments, the direct final rule will be withdrawn and all public comments received will be addressed in a subsequent final rule

based on this proposed rule. EPA will not institute a second comment period. Any parties interested in commenting on this action should do so at this time.

DATES: Comments must be received in writing by February 3, 2003.

ADDRESSES: Written comments should be mailed to Walter Wilkie, Deputy Chief, Air Quality Planning and Information Services Branch, Mailcode 3AP21, U.S. Environmental Protection Agency, Region III, 1650 Arch Street, Philadelphia, Pennsylvania 19103. Copies of the documents relevant to this action are available for public inspection during normal business hours at the Air Protection Division, U.S. Environmental Protection Agency, Region III, 1650 Arch Street, Philadelphia, Pennsylvania 19103.

FOR FURTHER INFORMATION CONTACT: James B. Topsale at (215) 814-2190, or by e-mail at topsale.jim@epa.gov. Please note that while questions may be posed via phone and e-mail, formal comments must be submitted in writing, as indicated in the **ADDRESSES** section of this document.

SUPPLEMENTARY INFORMATION: For further information, please see the information provided in the direct final action, with the same title, that is located in the "Rules and Regulations" section of this **Federal Register** publication. Please note that if EPA receives adverse comment on an amendment, paragraph, or section of this rule and if that provision may be severed from the remainder of the rule, EPA may adopt as final those provisions of the rule that are not the subject of an adverse comment.

Dated: December 20, 2002.

Thomas C. Voltaggio,

Acting Regional Administrator, Region III.

[FR Doc. 02-33097 Filed 12-31-02; 8:45 am]

BILLING CODE 6560-50-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 62

[DC051-7001b; PA186-7001b; FRL-7435-1]

Approval and Promulgation of State Air Quality Plans for Designated Facilities and Pollutants; the District of Columbia, and the City of Philadelphia, Pennsylvania; Control of Emissions From Existing Municipal Solid Waste Landfills

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.