

Detailed Inspection and Corrective Actions if Necessary

(c) Within 150 flight hours after the effective date of this AD, do a detailed inspection to detect damage of the four WAI ducts and to determine if the external shrouds of the WAI ducts are open or cracked, per the alert service bulletin.

(1) If no discrepancy is found, no further action is required by this AD.

(2) If any external shroud of a WAI duct is found open or cracked, before further flight, inspect the surrounding equipment and structure per a method approved by the Manager, New York Aircraft Certification Office, FAA, or Transport Canada Civil Aviation (TCCA) (or its delegated agent).

(3) If any damaged WAI duct is found, before further flight, replace the WAI duct with a new duct or a duct with the same part number (P/N) that is free of any dent, crease, or other handling damage, per the alert service bulletin.

Note 1: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Optional Terminating Action

(d) Replacement of all four WAI ducts with new ducts having P/N GG670-80504-5 or -6, or P/N GG670-80312-3 or -4, as applicable, per the service bulletin, terminates the requirements of this AD. After doing the replacement, the AFM revision required by paragraph (b) of this AD may be removed.

Reporting Requirement

(e) Submit a report of the results of the inspection required by paragraph (c) of this AD per the alert service bulletin specified in paragraph (c) of this AD. Information collection requirements contained in this AD have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

(1) If the inspection was done after the effective date of this AD: Submit the report within 14 days after the inspection.

(2) If the inspection was accomplished prior to the effective date of this AD: Submit the report within 14 days after the effective date of this AD.

Alternative Methods of Compliance

(f) In accordance with 14 CFR 39.19, the Manager, New York ACO, FAA, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(g) Unless otherwise specified in this AD, the actions must be done per CRJ 700/900 Series Regional Jet (Bombardier) Alert Service Bulletin A670BA-30-007, Revision A, dated April 15, 2003, including

Appendices A and B, dated March 18, 2003. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 2: The subject of this AD is addressed in Canadian airworthiness directive CF-2003-07, effective on March 25, 2003.

Effective Date

(h) This amendment becomes effective on June 27, 2003.

Issued in Renton, Washington, on June 5, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-14676 Filed 6-11-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 97-ANE-06-AD; Amendment 39-13190; AD 2003-12-05]

RIN 2120-AA64

Airworthiness Directives; McCauley Propeller Systems 1A103/TCM Series Propellers

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), that is applicable to McCauley Propeller Systems 1A103/TCM series propellers. That AD currently requires an initial inspection for cracks in the propeller hub in accordance with a dye penetrant inspection procedure, replacement of propellers with cracks that do not meet acceptable limits, rework of propellers with cracks that meet acceptable limits, and repetitive inspections of all affected propellers. This amendment allows additional rework operations to be performed at more than one bolt hole location. This amendment is prompted by the need to clarify the requirement to use a steel backing plate and Mylar gasket during installation of the propeller, and to relax the replacement requirements. The actions specified in

the proposed AD are intended to prevent propeller separation due to hub fatigue cracking, which can result in loss of control of the airplane.

DATES: Effective July 17, 2003. The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of July 17, 2003.

ADDRESSES: The service information referenced in this AD may be obtained from McCauley Propeller Systems, 3535 McCauley Drive, PO Drawer 5053, Vandalia, OH 45377-5053; telephone: 937-890-5246; fax: 937-890-6001. This information may be examined, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Timothy Smyth, Aerospace Engineer, Chicago Aircraft Certification Office, FAA, Small Airplane Directorate, 2350 East Devon Avenue, Room 323, Des Plaines, IL 60018; telephone: (847) 294-7132; fax: (847) 294-7834.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 97-06-16, Amendment 39-9973 (62 FR 16064, April 4, 1997), which is applicable to McCauley Propeller Systems 1A103/TCM series propellers, was published in the **Federal Register** on September 27, 2002 (67 FR 61043). That action proposed to require:

- An initial inspection for cracks in the propeller hub in accordance with a dye penetrant inspection procedure.
- Replacement of propellers with cracks that do not meet acceptable limits.
- Rework of propellers with cracks that meet acceptable limits.
- Painting of the propeller hub before installation of the propeller.
- Repetitive inspections of all affected propellers.
- Installation of a steel backing plate and Mylar gasket during installation of the propeller.

These actions must be done in accordance with McCauley Propeller Systems Alert Service Bulletin (ASB) 221C, dated September 7, 1999.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

One commenter agrees with the NPRM as written.

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Economic Analysis

There are approximately 6,100 propellers of the affected design in the worldwide fleet. The FAA estimates that approximately 3,000 propellers installed on airplanes of U.S. registry will be affected by this AD. The FAA also estimates that it will take approximately 3 work hours per propeller to perform the required actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$17 per propeller. Based on these figures, the total cost of the AD to U.S. operators is estimated to be \$591,000 per year.

Regulatory Analysis

This final rule does not have federalism implications, as defined in Executive Order 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this final rule.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by removing Amendment 39–9973 (62 FR 16064, April 4, 1997) and by adding a new airworthiness directive, Amendment 39–13190, to read as follows:

2003–12–05 McCauley Propeller Systems:
Amendment 39–13190. Docket No. 97–ANE–06–AD. Supersedes AD 97–06–16, Amendment 39–9973.

Applicability: This airworthiness directive (AD) is applicable to McCauley Propeller Systems 1A103/TCM series propellers with numeric serial numbers 770001 through 777390; and propellers with alphanumeric serial numbers BC001 up to, but not including KC001. These propellers are installed on but not limited to Cessna 152, Cessna A152, Reims F152, and Reims FA152 series airplanes. All alphanumeric serial number propellers beginning with the letters "B" through "J" are affected by this AD.

Note 1: This AD applies to each propeller identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For propellers that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Compliance with this AD is required as indicated below, unless already done.

To prevent propeller separation due to hub fatigue cracking, which can result in loss of control of the airplane, do the following:

Inspection and Rework Requirements

(a) Inspect propellers, rework or replace with a serviceable propeller, as necessary, and install in accordance with Sections II, III, IV, and V of McCauley Propeller Systems Alert Service Bulletin (ASB) No. 221C, dated September 7, 1999, as follows:

(1) For propellers with 3,000 or more hours time-in-service (TIS), or unknown TIS, on the effective date of this AD, as follows:

(i) If not already done, perform an initial dye penetrant inspection in accordance with Section II of the ASB before further flight.

(ii) Thereafter, perform repetitive dye penetrant inspections in accordance with Section IV of the ASB at intervals not to exceed 800 hours TIS, or 12 calendar months since last dye penetrant inspection, whichever occurs first.

(iii) If cracks are discovered that are not within the rework limits described in Section III of the ASB, before further flight remove the propeller from service and replace with a serviceable propeller.

(iv) If cracks are discovered that are within the rework limits described in Section III of the ASB, before further flight rework the propeller in accordance with Section III of the ASB, and resume inspecting repetitively in accordance with paragraph (a)(1)(ii) of this AD.

(2) For propellers with less than 3,000 hours TIS on the effective date of this AD, upon accumulating 3,000 hours TIS perform the steps required by paragraph (a)(1)(i) through (a)(1)(iv) of this AD.

(b) Paint camber side of the propeller in accordance with Section II or Section III of the ASB.

(c) Install propeller in accordance with Section V of the ASB.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Chicago Aircraft Certification Office (CHIACO). Operators must submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, CHIACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the CHIACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be done.

Documents That Have Been Incorporated by Reference

(f) The inspections, rework and replacement must be done in accordance with McCauley Propeller Systems Alert Service Bulletin (ASB) No. 221C, dated September 7, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from McCauley Propeller Systems, 3535 McCauley Drive, PO Drawer 5053, Vandalia, OH 45377–5053; telephone: 937–890–5246; fax: 937–890–6001. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(g) This amendment becomes effective on July 17, 2003.

Issued in Burlington, Massachusetts, on June 4, 2003.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 03-14675 Filed 6-11-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-88-AD; Amendment 39-13189; AD 2003-12-04]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135 and -145 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain EMBRAER Model EMB-135 and -145 series airplanes, that requires replacing the four Gamah clamp/sleeve joints on an engine bleed air duct with new threaded coupling assemblies. For certain airplanes, this AD also requires replacing the two supports for the engine bleed air duct with two new supports. The actions specified by this AD are intended to prevent hot air leaks from the bleed air duct due to disconnection of the duct joint, which could result in heat damage to components near the duct, and consequent increased risk of fire in the rear baggage compartment. This action is intended to address the identified unsafe condition.

DATES: Effective July 17, 2003. The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of July 17, 2003.

ADDRESSES: The service information referenced in this AD may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), PO Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA,

Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain EMBRAER Model EMB-135 and -145 series airplanes was published in the **Federal Register** on January 30, 2003 (68 FR 4725). That action proposed to require replacing the four Gamah clamp/sleeve joints on an engine bleed air duct with new threaded coupling assemblies. For certain airplanes, that action also proposed to require replacing the two supports for the engine bleed air duct with two new supports.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

Support for the Proposed AD

One commenter has no objections to the proposed AD.

Requests To Cite Recent Service Bulletin Versions

The proposed AD cited EMBRAER Service Bulletin 145-36-0024, dated May 31, 2001, as the appropriate source of service information for the proposed requirements. Several commenters request that the FAA revise the proposed AD to reflect the most current revision levels of the service bulletin revisions. (Change 01 of the service bulletin was issued August 7, 2002, and Change 02 was issued December 13, 2002.) One commenter requests that the proposed AD be revised to also allow future revisions of the service bulletin for compliance with the AD to avoid the need for requests and approvals of alternative methods of compliance.

The FAA partially agrees with the requests. Because the actions in both revisions are essentially the same as those in the original service bulletin, paragraph (a) in this final rule has been revised to cite Change 02 and to provide credit for work accomplished in accordance with the original or Change 01 of the service bulletin. However, to use a later revision of the cited service bulletin, affected operators must request approval of an alternative method of compliance under the provisions of paragraph (c) of this final rule. In an AD, use of the phrase "or later FAA-approved revisions" in reference to a specific service bulletin violates Office of the Federal Register regulations for

approving materials that are incorporated by reference.

Request To Revise Applicability of Proposed AD

One commenter notes that in Change 02 of the service bulletin the effectivity of the proposed AD excluded certain airplanes listed in the original version of the service bulletin, the commenter requests that the applicability of the proposed AD be revised to refer to Change 02 of the service bulletin.

The FAA agrees. Certain airplanes were removed from the effectivity of the revised service bulletin. Therefore, the applicability statement of this final rule has been revised accordingly.

Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the changes described previously. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Changes to 14 CFR Part 39/Effect on the AD

On July 10, 2002, the FAA issued a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs the FAA's airworthiness directives system. The regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. However, for clarity and consistency in this final rule, we have retained the language of the NPRM regarding that material.

Cost Impact

The FAA estimates that 346 airplanes of U.S. registry will be affected by this AD, that it will take approximately 3 work hours per airplane to accomplish the replacement, and that the average labor rate is \$60 per work hour. Required parts will cost approximately between \$1,978 and \$2,007 per airplane. Based on these figures, the cost impact of the AD on U.S. operators of these airplanes is estimated to be between \$746,668 and \$756,702; or between \$2,158 and \$2,187 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time