

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**2007-04-09 Empresa Brasileira De Aeronautica S.A. (Embraer):** Amendment 39-14941. FAA-2006-25892; Directorate Identifier 2006-NM-120-AD.

#### Effective Date

(a) This AD becomes effective March 23, 2007.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to all EMBRAER Model EMB-135BJ, -135ER, -135KE, -135KL, and -135LR airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes; certificated in any category.

#### Unsafe Condition

(d) This AD results from reports of smoke on the flight deck caused by damage from poor electrical contact due to loosening of the attaching hardware of the power cables of certain windshield temperature controllers. We are issuing this AD to prevent overheating of the power cable terminals of the windshield temperature controllers, which could result in smoke on the flight deck.

#### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

#### Inspection of Part Number (P/N) of Contoller

(f) Within 5,000 flight hours after the effective date of this AD, inspect to determine the part number of the left- and right-hand windshield temperature

controllers. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number of the subject controller can be conclusively determined from that review. If any windshield temperature controller is found to have a part number other than Goodrich P/N 3801D2( ), no further action is required by this AD for that controller.

#### Replacement of Attaching Hardware, Further Inspection, and Corrective Actions

(g) Before further flight after performing the inspection required by paragraph (f) of this AD, for all windshield temperature controllers having Goodrich P/N 3801D2( ) or any controller for which the part number cannot be conclusively determined: Replace the attaching hardware of the power cable terminals of the controllers with new, improved attaching hardware having new part numbers. Concurrently, perform a detailed inspection for signs of melting or damage of the plastic crimping ring, cable insulation, or terminals of the power cables, and, before further flight, perform applicable corrective actions. Perform all the actions in accordance with the Accomplishment Instructions of EMBRAER Service Bulletin 145-30-0043, Revision 02, dated May 25, 2006; or EMBRAER Service Bulletin 145LEG-30-0013, dated June 28, 2005; as applicable.

#### Credit for Actions Accomplished Using Previous Issue of Service Bulletin

(h) Actions accomplished before the effective date of this AD in accordance with EMBRAER Service Bulletin 145-30-0043, dated June 28, 2005; or Revision 01, dated April 7, 2006; are considered acceptable for compliance with the applicable corresponding actions required by this AD.

#### Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 FR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

#### Related Information

(j) Brazilian airworthiness directive 2006-05-01, effective May 23, 2006, also addresses the subject of this AD.

#### Material Incorporated by Reference

(k) You must use EMBRAER Service Bulletin 145-30-0043, Revision 02, dated May 25, 2006; or EMBRAER Service Bulletin 145LEG-30-0013, dated June 28, 2005; as applicable; to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil, for a copy

of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, S.W., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 6, 2007.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-2510 Filed 2-15-07; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2006-25470; Directorate Identifier 2006-NM-090-AD; Amendment 39-14942; AD 2007-04-10]

RIN 2120-AA64

#### Airworthiness Directives; Boeing Model 747-400 Series Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is superseding an existing airworthiness directive (AD), which applies to certain Boeing Model 747-400 series airplanes. That AD currently requires replacement of the decompression panels that are located in the smoke barrier between the passenger and main deck cargo compartment with new panels of an improved design. This new AD requires modification of the decompression panels on the smoke barrier in the main deck cargo compartment, or replacement of the smoke barrier with an improved smoke barrier, as applicable. This new AD also requires repetitive inspections of the decompression (vent) panels on the smoke barrier and corrective actions if necessary. This new AD also adds airplanes to the applicability. This AD results from reports of decompression panels on the smoke barrier opening in flight and on the ground without a decompression event. We are issuing this AD to prevent inadvertent opening or tearing of decompression panels, which could result in degraded cargo fire detection and suppression capability, smoke penetration into an occupied compartment, and an uncontrolled cargo fire, if a fire occurs in the main deck cargo compartment.

**DATES:** This AD becomes effective March 23, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of March 23, 2007.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for service information identified in this AD.

**FOR FURTHER INFORMATION CONTACT:** Susan Letcher, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6474; fax (425) 917-6590.

**SUPPLEMENTARY INFORMATION:**

**Examining the Docket**

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

**Discussion**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 96-24-03, amendment 39-9829 (61 FR 59319, November 22, 1996). The existing AD applies to certain Boeing Model 747-400 series airplanes. That NPRM was published in the **Federal Register** on August 1, 2006 (71 FR 43390). That NPRM proposed to require modification of the decompression panels on the smoke barrier in the main deck cargo compartment or replacement of the smoke barrier with an improved smoke barrier, as applicable. That NPRM also proposed to require repetitive inspections of the decompression (vent) panels on the smoke barrier and corrective actions if necessary. That NPRM also proposed to add airplanes to the applicability.

**Comments**

We provided the public the opportunity to participate in the development of this AD. We have

considered the comments that have been received on the NPRM.

**Support for the NPRM**

Boeing supports the NPRM.

**Request To Publish Service Information**

The Modification and Replacement Parts Association (MARPA) states that, typically, ADs are based on service information originating with the type certificate holder or its suppliers. MARPA adds that manufacturer service documents are privately authored instruments generally having copyright protection against duplication and distribution. MARPA notes that when a service document is incorporated by reference into a public document, such as an AD, it loses its private, protected status and becomes a public document. MARPA adds that if a service document is used as a mandatory element of compliance, it should not simply be referenced, but should be incorporated into the regulatory document; by definition, public laws must be public, which means they cannot rely upon private writings. MARPA adds that service documents incorporated by reference should be made available to the public by publication in the Docket Management System (DMS), keyed to the action that incorporates them. MARPA notes that the stated purpose of the incorporation by reference method is brevity, to keep from expanding the **Federal Register** needlessly by publishing documents already in the hands of the affected individuals; traditionally, "affected individuals" means aircraft owners and operators, who are generally provided service information by the manufacturer. MARPA adds that a new class of affected individuals has emerged, since the majority of aircraft maintenance is now performed by specialty shops instead of aircraft owners and operators. MARPA notes that this new class includes maintenance and repair organizations, component servicing and repair shops, parts purveyors and distributors, and organizations manufacturing or servicing alternatively certified parts under section 21.303 ("Replacement and modification parts") of the Federal Aviation Regulations (14 CFR 21.303). MARPA adds that the concept of brevity is now nearly archaic as documents exist more frequently in electronic format than on paper. Therefore, MARPA asks that the service documents deemed essential to the accomplishment of the NPRM be incorporated by reference into the regulatory instrument and published in the DMS.

We understand MARPA's comment concerning incorporation by reference. The Office of the Federal Register (OFR) requires that documents that are necessary to accomplish the requirements of the AD be incorporated by reference during the final rule phase of rulemaking. This final rule incorporates by reference the document necessary for the accomplishment of the requirements mandated by this AD. Further, we point out that while documents that are incorporated by reference do become public information, they do not lose their copyright protection. For that reason, we advise the public to contact the manufacturer to obtain copies of the referenced service information.

In regard to the commenter's request to post service bulletins on the Department of Transportation's DMS, we are currently in the process of reviewing issues surrounding the posting of service bulletins on the DMS as part of an AD docket. Once we have thoroughly examined all aspects of this issue and have made a final determination, we will consider whether our current practice needs to be revised. No change to the final rule is necessary in response to this comment.

**Request To Allow Use of Parts Manufacturer Approval (PMA) Parts**

MARPA states that the practice of requiring the replacement of a defective part with a certain part conflicts with 14 CFR 21.303. MARPA asserts that requiring installation of a certain part prevents installation of other good parts and prohibits the development of new parts. MARPA also states that the practice of requiring an alternative method of compliance (AMOC) to install a PMA part should be stopped. MARPA concludes that this practice presumes that all PMA parts are inherently defective and require an additional layer of approval. MARPA further states the NPRM does not comply with FAA Order 8040.2; that order states that replacement or installation of certain parts could have replacement parts approved under 14 CFR 21.303 based on a finding of identity. That order also states that any parts approved under this regulation and installed should be subject to the actions of the AD and included in the applicability. MARPA states that if a PMA part is defective, then it must be addressed in an AD and not just simply implied by an AMOC requirement. MARPA suggests that we adopt language used in ADs issued by directorates other than the Transport Airplane Directorate, which specify installing an "FAA-approved equivalent

part number” or “airworthy parts.” MARPA contends that the mandates contained in Section 1, paragraph (b)(1) of Executive Order 12866 are not being met because the directorates differ in their treatment of this issue. MARPA, therefore, requests that we revise the NPRM to allow use of PMA parts.

We do not agree to revise this AD. The NPRM did not address PMA parts, as provided in draft FAA Order 8040.2, because the Order was only a draft that was out for comment at the time. After issuance of the NPRM, the Order was revised and issued as FAA Order 8040.5 with an effective date of September 29, 2006.

FAA Order 8040.5 does not address PMA parts in ADs. We acknowledge the

need to ensure that unsafe PMA parts are identified and addressed in ADs related to Mandatory Continuing Airworthiness Information (MCAI). We are currently examining all aspects of this issue, including input from industry. Once we have made a final determination, we will consider how our policy regarding PMA parts in ADs needs to be revised. We consider that to delay this AD action would be inappropriate, since we have determined that an unsafe condition exists and that replacement of certain parts must be accomplished to ensure continued safety. Therefore, no change has been made to the final rule in this regard.

**Conclusion**

We have carefully reviewed the available data, including the comments that have been submitted, and determined that air safety and the public interest require adopting the AD as proposed.

**Costs of Compliance**

There are about 63 airplanes of the affected design in the worldwide fleet. The following table provides the estimated costs, at an average labor rate of \$80 per hour, for U.S. operators to comply with the AD. The estimated work hours and cost of parts for the modification in the table below depend on the configuration of an airplane.

ESTIMATE COSTS

Action	Work hours	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Modification (new action) .....	16–17	\$12,064–15,362	\$13,344–16,722	2	\$26,688–33,444.
Replacement (new action) .....	4	48,647	48,967	2	97,934.
Inspection (new action) .....	2	None	160	2	320, per inspection cycle.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866;
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39–9829 (61

FR 59319, November 22, 1996) and by adding the following new airworthiness directive (AD):

**2007–04–10 Boeing:** Amendment 39–14942. Docket No. FAA–2006–25470; Directorate Identifier 2006–NM–090–AD.

**Effective Date**

(a) This AD becomes effective March 23, 2007.

**Affected ADs**

(b) This AD supersedes AD 96–24–03.

**Applicability**

(c) This AD applies to Boeing Model 747–400 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 747–25A3353, dated December 9, 2004.

**Unsafe Condition**

(d) This AD results from reports of decompression panels on the smoke barrier opening in flight and on the ground without a decompression event. We are issuing this AD to prevent inadvertent opening or tearing of decompression panels, which could result in degraded cargo fire detection and suppression capability, smoke penetration into an occupied compartment, and an uncontrolled cargo fire, if a fire occurs in the main deck cargo compartment.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**New Requirements of This AD***Modification or Replacement, as Applicable*

(f) Within 48 months after the effective date of this AD: Modify the decompression panels on the smoke barrier or replace the smoke barrier with an improved smoke barrier, by accomplishing all of the actions specified in Work Package 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-25A3353, dated December 9, 2004, as applicable.

*Repetitive Inspection*

(g) Within 20 months or 6,000 flight hours after accomplishing the actions in paragraph (f) of this AD, whichever occurs first: Do a general visual inspection of the decompression (vent) panels on the smoke barrier for any changes from their installed condition, and do all corrective actions before further flight after the inspection, by accomplishing all of the actions specified in Work Package 2 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747-25A3353, dated December 9, 2004, as applicable. Repeat the inspection thereafter at intervals not to exceed 20 months or 6,000 flight hours, whichever occurs first.

**Note 1:** For the purposes of this AD, a general visual inspection is: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

**Alternative Methods of Compliance (AMOCs)**

(h)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

**Material Incorporated by Reference**

(i) You must use Boeing Alert Service Bulletin 747-25A3353, dated December 9, 2004, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration

(NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 6, 2007.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-2511 Filed 2-15-07; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2006-26049; Directorate Identifier 2006-NM-177-AD; Amendment 39-14949; AD 2007-04-17]**

**RIN 2120-AA64**

**Airworthiness Directives; McDonnell Douglas Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, and DC-10-30F (KC-10A and KDC-10) Airplanes; Model DC-10-40 and DC-10-40F Airplanes Equipped With Pratt & Whitney JT9-20 or JT9-20J Engines; and Model MD-10-10F and MD-10-30F Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for the McDonnell Douglas airplanes previously described. This AD requires replacing the control modules of the fire detection systems of the propulsion engines with new, improved control modules. This AD results from a report of broken or severed wiring between engine fire detectors and the fire detection system control module, which caused the fire detection system to become non-functional without flightcrew awareness. We are issuing this AD to prevent unannounced fire in a propulsion engine, which could cause injury to flightcrew and passengers or loss of the airplane.

**DATES:** This AD becomes effective March 23, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of March 23, 2007.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Meggitt Safety Systems, 1915 Voyager Avenue, Simi Valley, California 93063, for service information identified in this AD.

**FOR FURTHER INFORMATION CONTACT:**

Samuel Lee, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5262; fax (562) 627-5210.

**SUPPLEMENTARY INFORMATION:****Examining the Docket**

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

**Discussion**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to all McDonnell Douglas Model DC-10-10, DC-10-10F, DC-10-15, DC-10-30, and DC-10-30F (KC-10A and KDC-10) airplanes; Model DC-10-40 and DC-10-40F airplanes equipped with Pratt & Whitney JT9-20 or JT9-20J engines; and all Model MD-10-10F and MD-10-30F airplanes. That NPRM was published in the **Federal Register** on October 13, 2006 (71 FR 60448). That NPRM proposed to require replacing the control modules of the fire detection systems of the propulsion engines with new, improved control modules.

**Comments**

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

**Support for the NPRM**

FedEx concurs with the NPRM as written and states its intent to also modify the fire detection systems of the auxiliary power units of subject FedEx airplanes, as described in the service information mandated by the AD.

**Request To Clarify Service Information Requirement**

Hawaiian Airlines requests that we revise the NPRM to clarify what service information is acceptable for compliance with the AD. The commenter asserts that the NPRM states that the use of Meggitt Safety Systems Service Bulletin 26-34, Revision 2,