

**PART 948—IRISH POTATOES GROWN IN COLORADO**

1. The authority citation for 7 CFR part 948 continues to read as follows:

**Authority:** 7 U.S.C. 601–674.

2. Section 948.386 is amended by revising paragraph (a)(2) to read as follows:

**§ 948.386 Handling Regulation.**

\* \* \* \* \*

(a) \* \* \*

(2) *All other varieties.* U.S. No. 2, or better grade, 2 inches minimum diameter or 4 ounces minimum weight.

\* \* \* \* \*

Dated: December 4, 2007.

**Lloyd C. Day,**

*Administrator, Agricultural Marketing Service.*

[FR Doc. E7–23839 Filed 12–10–07; 8:45 am]

**BILLING CODE 3410–02–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2007–0308; Directorate Identifier 2007–NM–160–AD]

RIN 2120–AA64

**Airworthiness Directives; Boeing Model 747–100, 747–100B, 747–100B SUD, 747–200B, 747–200C, 747–200F, 747–300, 747–400, 747–400D, 747–400F, and 747SR Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 747 airplanes identified above. This proposed AD would require modifying the outboard flap track and transmission attachments. This proposed AD results from a joint Boeing and FAA multi-model study (following in-service trailing edge flap structure and drive system events) on the hazards posed by skewing and failed flaps. This study identified the safety concerns regarding the transmission attachment design and the potential loss of an outboard trailing edge flap. We are proposing this AD to prevent certain discrepancies associated with this design (for example, a flap skew or lateral control asymmetry that can cause collateral damage to adjacent hydraulic tubing and subsequent loss of a

hydraulic system), which could result in the asymmetric flight control limits being exceeded, and could adversely affect the airplane's continued safe flight and landing.

**DATES:** We must receive comments on this proposed AD by January 25, 2008.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:**

Doug Tsuji, Aerospace Engineer, Systems and Equipment Branch, ANM–130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 917–6487; fax (425) 917–6590.

**SUPPLEMENTARY INFORMATION:****Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2007–0308; Directorate Identifier 2007–NM–160–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this

proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

**Discussion**

A report has been completed about a joint Boeing and FAA multi-model study (following in-service trailing edge flap structure and drive system events) on the hazards posed by skewing and failed flaps. The study identified safety concerns with the transmission attachment design, which does not meet the single failure condition analysis criteria. Three bolts attach the transmission to the flap track. The fracture of one of the transmission attachment bolts in flight could lead to an overload failure of the two remaining bolts and subsequent loss of the transmission. In addition, a support housing with an undetected fracture could lead to the loss of the transmission. Loss of the flap transmission could lead to a flap skew or lateral control asymmetry. Loss of a transmission could lead to possible collateral damage to adjacent hydraulic tubing and the loss of a hydraulic system. A flap skew or asymmetry combined with collateral hydraulic system damage could result in the asymmetric flight control limits being exceeded, and could adversely affect the airplane's continued safe flight and landing.

**Relevant Service Information**

We have reviewed Boeing Alert Service Bulletins 747–27A2398 and 747–27A2421, both dated April 19, 2007. The service bulletins describe the following procedures for modifying the outboard trailing edge flaps, including the following “airplane work”:

- Replacing the flap tracks and flap transmissions with a new configuration (flap tracks and flap transmissions 1, 2, 7, and 8);
- Reversing the bolt direction on the flap track side load fitting; and
- Installing new flap track fairing hinge braces. The service bulletins describe the following component work:
  - Replacing the upper forward and the upper aft flap transmission attachment bolt hole bushings;
  - Replacing the support housing;
  - Machining the track and installing the larger diameter bolt hole bushings, at the upper forward and upper aft flap transmission attachment locations (flap track assemblies 1 and 8) and at the

upper aft flap transmission attachment location (flap track assemblies 2 and 7); and

- Replacing the existing support housing with the new support housing (flap transmission assemblies 1, 2, 7, and 8).

The compliance time is 6 years for airplanes known to have fewer than 20,000 total flight cycles, and 3 years for all other airplanes.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

**FAA’s Determination and Requirements of the Proposed AD**

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same

type design. For this reason, we are proposing this AD, which would require the actions specified in the service information described previously.

**Costs of Compliance**

There are about 990 airplanes of the affected design in the worldwide fleet. The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Work hours	Average labor rate per hour	Parts	Cost per air-plane	Number of U.S.-registered airplanes	Fleet cost
150 .....	\$80	\$80,023	\$92,023	141	\$12,975,243

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the ADDRESSES section for a location to examine the regulatory evaluation.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**Boeing:** Docket No. FAA–2007–0308; Directorate Identifier 2007–NM–160–AD.

**Comments Due Date**

- (a) The FAA must receive comments on this AD action by January 25, 2008.

**Affected ADs**

- (b) None.

**Applicability**

- (c) This AD applies to Boeing Model 747–100, 747–100B, 747–100B SUD, 747–200B, 747–200C, 747–200F, 747–300, 747–400, 747–400D, 747–400F, and 747SR series airplanes, certificated in any category; as identified in Boeing Alert Service Bulletin 747–27A2398 or 747–27A2421, both dated April 19, 2007.

**Unsafe Condition**

(d) This AD results from a joint Boeing and FAA multi-model study (following in-service trailing edge flap structure and drive system events) on the hazards posed by skewing and failed flaps. This study identified the safety concerns regarding the transmission attachment design and the potential loss of an outboard trailing edge flap. We are issuing this AD to prevent certain discrepancies associated with this design (for example, a flap skew or lateral control asymmetry that can cause collateral damage to adjacent hydraulic tubing and subsequent loss of a hydraulic system), which could result in the asymmetric flight control limits being exceeded, and could adversely affect the airplane’s continued safe flight and landing.

**Compliance**

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**Modification**

- (f) Do the following, as applicable: At the time specified in paragraph 1.E. of Boeing Alert Service Bulletin 747–27A2421 or 747–27A2398, both dated April 19, 2007, except as provided by paragraph (g) of this AD, modify the outboard flap track and transmission attachments by doing all actions specified in the Accomplishment Instructions of the service bulletin.

- (g) Where Boeing Alert Service Bulletins 747–27A2421 and 747–27A2398, both dated April 19, 2007, specify compliance times relative to the date on the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

**Parts Installation**

- (h) As of the effective date of this AD, no person may install a part identified in Table 1 of this AD on any airplane.

TABLE 1.—PARTS PROHIBITED FROM INSTALLATION

Part	Part No.
Hinge brace for Tracks 1 and 8 .....	65B15515-1 65B15515-2 65B15515-9 65B15515-10
Hinge brace for Tracks 2 and 7 .....	65B15525-1 65B15525-2 65B15525-7 65B15525-8 65B17092-1 65B17092-2
Support assembly for Tracks 1 and 8 .....	65B81982-( )
Support assembly for Tracks 2 and 7 .....	65B81950-( )

**Alternative Methods of Compliance (AMOCs)**

(i)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on November 13, 2007.

**Ali Bahrami,**

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-23955 Filed 12-10-07; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2007-0300; Directorate Identifier 2007-NM-191-AD]

**RIN 2120-AA64**

**Airworthiness Directives; Fokker Model F.28 Mark 0070 and 0100 Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of

another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Reports have been received from Fokker 100 (F28 Mark 0100) operators where the crew experienced difficulties with roll control. Analysis suggests that these phenomena are due to frozen water on the aileron pulleys that are installed on the Center Wing Spar and located in the Main Landing Gear (MLG) wheel bays. Investigation has confirmed that improper closure of the aerodynamic seals of the wing-to-fuselage fairings above the MLG wheel bays can cause rainwater, wash-water or de-icing fluid to leak onto the affected aileron pulleys. This condition, if not corrected, can lead to further incidents of frozen water on aileron pulleys during operation of the aircraft, resulting in restricted roll control and/or higher control forces. \* \* \*

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by January 10, 2008.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:****Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2007-0300; Directorate Identifier 2007-NM-191-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

**Discussion**

The Civil Aviation Authority—The Netherlands (CAA-NL), which is the aviation authority for the Netherlands, has issued Dutch Airworthiness Directive NL-2005-013, dated October 17, 2005 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Reports have been received from Fokker 100 (F28 Mark 0100) operators where the crew experienced difficulties with roll control. Analysis suggests that these phenomena are due to frozen water on the aileron pulleys that are installed on the Center Wing Spar and located in the Main Landing Gear (MLG) wheel bays. Investigation has confirmed that improper closure of the aerodynamic seals of the wing-to-fuselage fairings above the MLG wheel bays can cause rainwater, wash-water or de-icing fluid to leak onto the affected aileron pulleys. [The aileron pulleys on Model F.28 Mark 0070 airplanes are identical to those installed on the Model F.28 Mark 0100 airplanes. Therefore, those Model F.28 Mark 0070 airplanes may be subject to the unsafe condition revealed on the Model F.28 Mark 0100 airplanes.] This condition, if not corrected, can lead to further incidents of frozen water on aileron pulleys during operation of the aircraft, resulting in restricted roll control and/or higher control forces. Since an unsafe condition has been identified that is likely to exist or develop on other aircraft of the same type design, this Airworthiness Directive requires the inspection of the wing-to-fuselage fairings and, if necessary, the accomplishment of appropriate corrective action(s).

The inspection is intended to find indications of incorrect fit, damage, or wear. Corrective actions include a related investigative action (inspecting for incorrect fit, damage, or wear of the aerodynamic seal of the fairings, and inspecting for damage or wear of the