

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

This Airworthiness Directive (AD) is published subsequent to the detection of cracks on multiple aircraft in lower skin panel No. 2 forward of access panel 575FB/675FB held on the rear dummy spar, inboard of rib 9, fuselage side, aft of the rear spar.

This area of structure has been subjected to several repairs and modifications in previous years.

The AIRBUS Service Bulletins (SB) A300-57-0177 at Revision 3 and A300-57-6029 at Revision 4 define the various configurations for the mandatory inspections to be conducted in order to control or correct the development of cracks which could affect the structural integrity of the aircraft.

The MCAI requires doing repetitive inspections (detailed visual, high frequency eddy current, x-ray) of the wing lower skin panel and associated internal support structure for cracking and, if necessary, doing corrective measures (modifying the lower panel inboard of rib 9 aft of the rear spar and repairing cracks).

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Except as provided by paragraphs (f)(1)(i), (f)(1)(ii), (f)(1)(iii), and (f)(1)(iv) of this AD: At the threshold specified in paragraph 1.E.(2) of Airbus Service Bulletin A300-57-0177, Revision 05, dated March 23, 2007; or A300-57-6029, Revision 06, dated March 23, 2007; as applicable; perform the inspection of the wing lower skin panel and associated internal support structure aft of the rear spar and inboard of rib 9 and apply applicable corrective measures in accordance with Airbus Service Bulletin A300-57-0177, Revision 05, dated March 23, 2007; or A300-57-6029, Revision 06, dated March 23, 2007; as applicable. All applicable corrective measures must be done at the applicable times specified in paragraph 1.E.(2) and the Accomplishment Instructions of the applicable service bulletin.

(i) Where the tables in paragraph 1.E.(2), "Accomplishment Timescale," of the service bulletins specify a grace period for doing the actions, this AD requires that the action be done within the specified grace period relative to the effective date of this AD.

(ii) Where the tables in paragraph 1.E.(2)(e), "config 04," of Airbus Service Bulletin A300-57-0177, Revision 05, specify an inspection interval but not an initial threshold, this AD requires that the actions be done within the specified interval after inspecting in accordance with Table 1A or 1B, as applicable, for configuration 01 of the service bulletin and thereafter at the inspection interval specified in the tables in paragraph 1.E.(2)(e), "config 04," of Airbus Service Bulletin A300-57-0177, Revision 05.

(iii) Where the tables in paragraph 1.E.(2)(f), "config 05," of A300-57-6029, Revision 06, specify an inspection interval but not an initial threshold, this AD requires that the actions be done within the specified interval after inspecting in accordance with Table 1A or 1B, as applicable, for configuration 01 of the service bulletin and

thereafter at the inspection interval specified in the tables in paragraph 1.E.(2)(f), "config 05," of A300-57-6029, Revision 06.

(iv) All crack lengths specified in Airbus Service Bulletin A300-57-0177, Revision 05, and A300-57-6029, Revision 06, are considered "not to exceed" lengths.

(2) Repeat the inspection at the intervals in, and according to the instructions defined in, Airbus Service Bulletin A300-57-0177, Revision 05, dated March 23, 2007; or A300-57-6029, Revision 06, dated March 23, 2007; as applicable.

(3) Report to Airbus the first inspection results, whatever they may be, at the applicable time specified in paragraph (e)(3)(i) or (e)(3)(ii) of this AD.

(i) If the inspection was done after the effective date of this AD, submit the report within 30 days after the inspection.

(ii) If the inspection was accomplished prior to the effective date of this AD, submit the report within 30 days after the effective date of this AD.

(4) Actions accomplished before the effective date of this AD in accordance with Airbus Service Bulletin A300-57-0177, Revision 03, dated May 29, 2006; Airbus Service Bulletin A300-57-0177, Revision 04, dated January 5, 2007; Airbus Service Bulletin A300-57-6029, Revision 04, dated May 29, 2006; or A300-57-6029, Revision 05, dated October 23, 2006; are considered acceptable for compliance with the corresponding action specified in this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2006-0282, dated September 12, 2006; and the service information in Table 1 of this AD; for related information.

TABLE 1.—SERVICE INFORMATION

Airbus Service Bulletin	Revision level	Date
A300-57-0177	05	March 23, 2007.
A300-57-0222	01	March 13, 2006.
A300-57-6029	06	March 23, 2007.
A300-57-6064	04	March 9, 2006.

Issued in Renton, Washington, on July 31, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-16097 Filed 8-15-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2007-28943; Directorate Identifier 2007-NM-011-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767-300F Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 767-300F series airplanes. This proposed AD would require replacing the rotomolded duct(s) of the mix manifold system with new duct(s). This proposed AD results from a report of failures of the duct joint seal of the mix manifold system. We are proposing this AD to prevent air conditioning leakage into the mix manifold bay. Such leakage could decrease the air flow to the flight compartment and main cabin or could allow smoke into the flight compartment in the event of a fire in the main cabin or forward cargo compartment.

DATES: We must receive comments on this proposed AD by October 1, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

• **DOT Docket Web site:** Go to <http://dms.dot.gov> and follow the

instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room W12-140 on the ground floor of the West Building, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for the service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT:

Jeffrey S. Palmer, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6481; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "FAA-2007-28943; Directorate Identifier 2007-NM-011-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located on the ground level of the West Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

We have received a report of more than ten failures of the duct joint seal of the mix manifold system on Boeing Model 767-300F series airplanes. The seal failures resulted in air conditioning leakage into the mix manifold bay, which consequently decreased the air flow to the flight compartment and main cabin. The failed ducts were made from rotomolded nylon and were between 7 and 9 inches in diameter. Service history has shown that the ducts made from rotomolded nylon material that are larger than 6.5 inches in diameter can fail as a result of joint seal failures, loose clamps, and duct deformation due to insufficient rigidity. This condition, if not corrected, could result in air conditioning leakage into the mix manifold bay. Such leakage could decrease the air flow to the flight compartment and main cabin or could allow smoke into the flight compartment in the event of a fire in the main cabin or forward cargo compartment.

Relevant Service Information

We have reviewed Boeing Special Attention Service Bulletin 767-21-0192, dated March 23, 2006. The service information describes procedures for replacing the rotomolded duct(s) of the mix manifold system with new duct(s). Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. For this reason, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

There are about 40 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 32 airplanes of U.S. registry. The proposed actions would take about 2 or 8 work hours per airplane, at an average labor rate of \$80 per work hour. Required parts would cost about \$4,123 or \$42,825 per airplane. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$4,283 or \$43,465 per airplane. (The estimated work hours and costs depend on the airplane configuration).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section

for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

BOEING: Docket No. FAA-2007-28943; Directorate Identifier 2007-NM-011-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by October 1, 2007.

Affected ADS

(b) None.

Applicability

(c) This AD applies to Boeing Model 767-300F series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 767-21-0192, dated March 23, 2006.

Unsafe Condition

(d) This AD results from a report of failures of the duct joint seal of the mix manifold system. We are issuing this AD to prevent air conditioning leakage into the mix manifold bay. Such leakage could decrease the air flow to the flight compartment and main cabin or could allow smoke into the flight compartment in the event of a fire in the main cabin or forward cargo compartment.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Replacement

(f) Within 36 months after the effective date of this AD, do the applicable action specified in Table 1 of this AD in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 767-21-0192, dated March 23, 2006.

TABLE 1.—REPLACEMENT

For airplanes identified in the service bulletin as—	Do the following action—
(1) Group 1 airplanes.	Replace the rotomolded duct between the transition duct of the right cooling pack and the mix manifold with a new duct made of aluminum.
(2) Group 2 airplanes.	Replace the rotomolded ducts of the mix manifold system with new ducts made from Kevlar® and aluminum.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on July 30, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-16095 Filed 8-15-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-25658; Directorate Identifier 2006-NM-054-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A318, A319, A320, and A321 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: The FAA is revising an earlier supplemental NPRM for an airworthiness directive (AD) that applies to certain Airbus Model A318, A319, A320, and A321 airplanes. The first supplemental NPRM would have superseded an existing AD that currently requires repetitive detailed

inspections of the inboard flap trunnions for any wear marks and of the sliding panels for any cracking at the long edges, and corrective actions if necessary. These actions resulted from reports of wear damage to the inboard flap trunnions after incorporation of the terminating modification, and certain airplanes were inadvertently excluded from the applicability in the original NPRM. This new action revises the first supplemental NPRM by adding airplanes that were recently added to the type certificate data sheet. We are proposing this second supplemental NPRM to detect and correct wear of the inboard flap trunnions, which could lead to loss of flap surface control and consequently result in the flap detaching from the airplane. A detached flap could result in damage to the tail of the airplane.

DATES: We must receive comments on this supplemental NPRM by September 10, 2007.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room W12-140 on the ground floor of the West Building, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information identified in this second supplemental NPRM.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposal. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number “Docket No. FAA-2006-25658;