

Decontamination of NA2 Nozzles at PNNL

Dr. Steve Doctor, PNNL Program Manager Dr. William Cullen, NRC Program Manager




General Decontamination Procedure

- Ship from Envirocare, receive & survey
- Develop Procedure with EPRI/MRP Assistance
- Construct decontamination enclosure, cradles for CRDMs
- Install dry ice blaster, Microset applicator & other tools
- Checkout on dummy pieces of steel
- Decon four (of six) CRDMs
 - Repeated applications of Microset
 - Dry ice blasting
 - Repeated wipedowns
 - Painting to fix contamination on flame-cut surfaces
- Move to NDE test stands



Sketch of Decontamination Enclosure





CRDM #10 is shown being received in its shipping container.






CRDM #39 being removed from its shipping container.





CRDM #39 being transported to the decontamination chamber.





CRDM #31 is shown inside of the decontamination chamber.





Wetted Surface of CRDM #59 after application and removal of the Microset molding material to the entire wetted surface.





CRDM #10 is shown being removed from the decontamination chamber.





CRDM #31 is shown being removed from the decontamination chamber and readied for transport to the NDE area. A protective paint is applied to the flame cut surface.





Smearable Contamination Levels at Different Locations of CRDM #39

Location	Initial Contamination (dpm/100 cm ²)	Contamination After First Microset & DI Water Brushing (dpm/100 cm ²)	Contamination After CO ₂ Blast and 2nd Microset (dpm/100 cm ²)
Inside the Nozzle	600,000	150,000	11,000
Wetted, Clad Surface	150,000	80,000	25,000
J-groove weld	200,000	70,000	18,000
Dry surface	35,000	<5,000	<5,000