

Special Attention Service Bulletin 737-53-1267, dated November 28, 2006.

**Preventive Modification**

(h) At the compliance time specified in paragraph 1.E. of Boeing Special Attention Service Bulletin 737-53-1267, dated November 28, 2006, except as provided by paragraph (j) of this AD: Do the preventive modification in accordance with the Accomplishment Instructions of Boeing

Special Attention Service Bulletin 737-53-1267, dated November 28, 2006. Doing the preventive modification terminates the repetitive inspections required by paragraph (f) of this AD.

**Modification or Repair Done in Accordance With AD 92-25-09**

(i) Inspections described in paragraph (f) of this AD are not required for areas of the STA 259.5 circumferential butt splice that have

been modified in accordance with the service information specified in Table 1 of this AD. (Boeing Service Bulletin 737-53-1076, Revision 2, dated February 8, 1990; and Revision 4, dated September 26, 1991; are cited as appropriate sources of service information for doing certain requirements of AD 92-25-09.)

TABLE 1.—SERVICE INFORMATION

Boeing Service Bulletin—	Revision level—	Date—
737-53-1076 .....	4 .....	September 26, 1991.
737-53-1076 .....	3 .....	September 20, 1990.
737-53-1076 .....	2 .....	February 8, 1990.
737-53-1076 .....	1 .....	November 23, 1988.
737-53-1076 .....	Original .....	October 30, 1986.

**Compliance Times**

(j) Where Boeing Special Attention Service Bulletin 737-53-1267, dated November 28, 2006, specifies compliance times relative to the release date of the service bulletin, this AD requires compliance at compliance times relative to the effective date of this AD.

**Alternative Methods of Compliance (AMOCs)**

(k)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

**Material Incorporated by Reference**

(l) You must use Boeing Special Attention Service Bulletin 737-53-1267, dated November 28, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601

Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on December 10, 2007.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-24335 Filed 12-14-07; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA-2007-28924; Directorate Identifier 2007-NM-051-AD; Amendment 39-15305; AD 2007-26-03]**

**RIN 2120-AA64**

**Airworthiness Directives; Boeing Model 747-200C and -200F Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Boeing Model 747-200C and -200F series airplanes. This AD requires, among other actions, installing mounting brackets, support angles, and moisture curtains in the main equipment center. This AD results from reports of water contamination in the electrical/electronic units in the main equipment center. We are issuing this AD to prevent water contamination of

the electrical/electronic units, which could cause the electrical/electronic units to malfunction, and as a consequence, could adversely affect the airplane's continued safe flight.

**DATES:** This AD becomes effective January 22, 2008.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of January 22, 2008.

**ADDRESSES:** For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Marcia Smith, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6484; fax (425) 917-6590.

**SUPPLEMENTARY INFORMATION:**

**Discussion**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would

apply to certain Boeing Model 747–200C and –200F series airplanes. That NPRM was published in the **Federal Register** on August 16, 2007 (72 FR 45954). That NPRM proposed to require, among other actions, installing mounting brackets, support angles, and moisture curtains in the main equipment center.

**Comments**

We provided the public the opportunity to participate in the development of this AD. We have considered the comment received.

**Request To Refer to Earlier Revision of a Referenced Service Bulletin**

Boeing requests that paragraph (g) of the NPRM be revised to include Boeing Alert Service Bulletin 747–38A2073, Revision 1, dated June 21, 1990; and Revision 2, dated April 26, 2001; as additional sources of service information for accomplishing the prior or concurrent requirements. Boeing states that this will align the NPRM with Boeing Alert Service Bulletin 747–38A2073, Revision 3, dated May 22,

2003 (referred to in the NPRM as an appropriate source of service information for accomplishing the prior or concurrent requirements).

We partially agree. We agree with Boeing that accomplishing the actions specified in Revisions 1 and 2 of Boeing Alert Service Bulletin 747–38A2073 is acceptable for compliance with the corresponding actions required by paragraph (g) of this AD. However, we do not agree that a change to the final rule is necessary. As mentioned in the Relevant Service Information section of the NPRM, AD 2001–24–30, amendment 39–12547 (66 FR 64104, December 12, 2001), requires installing drip shields in accordance with Boeing Alert Service Bulletin 747–38A–2073, Revision 2; or in accordance with Revision 1 or Original Release, dated November 30, 1989, if done before the effective date of that AD. In addition, paragraph (h) of this AD states, “Installation of drip shields before the effective date of this AD in accordance with paragraph (a) and Note 2 of AD 2001–24–30, amendment 39–12547, is acceptable for

compliance with the corresponding actions in paragraph (g) of this AD.” We have made no change to the final rule in this regard.

**Conclusion**

We have carefully reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD as proposed.

**Interim Action**

This is considered to be interim action. The manufacturer has advised that it currently is developing another modification that will address the unsafe condition identified in this AD. Once this modification is developed, approved, and available, the FAA might consider additional rulemaking.

**Costs of Compliance**

There are about 79 airplanes of the affected design in the worldwide fleet. The following table provides the estimated costs for U.S. operators to comply with this AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Installation .....	3	\$80	\$8,960	\$9,200	25	\$230,000
Prior or concurrent requirements of AD 2001–24–30 .....	32	80	4,497	7,057	25	176,425

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We have determined that this AD will not have federalism implications under

Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866;
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**2007–26–03 Boeing:** Amendment 39–15305. Docket No. FAA–2007–28924; Directorate Identifier 2007–NM–051–AD.

**Effective Date**

(a) This AD becomes effective January 22, 2008.

**Affected ADs**

(b) None.

**Applicability**

(c) This AD applies to Boeing Model 747–200C and –200F series airplanes, certificated in any category; as identified in Boeing Alert Service Bulletin 747–25A3430, dated February 15, 2007.

**Unsafe Condition**

(d) This AD results from reports of water contamination in the electrical/electronic units in the main equipment center. We are issuing this AD to prevent water contamination of the electrical/electronic units, which could cause the electrical/electronic units to malfunction, and as a consequence, could adversely affect the airplane’s continued safe flight.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**Installations**

(f) Within 24 months after the effective date of this AD, install mounting brackets, support angles, and moisture curtains in the main equipment center, in accordance with the Accomplishment Instructions of Boeing

Alert Service Bulletin 747–25A3430, dated February 15, 2007.

**Prior or Concurrent Requirements**

(g) For airplanes identified as Group 1 and Group 3 airplanes in Boeing Alert Service Bulletin 747–25A3430, dated February 15, 2007: Prior to or concurrently with the requirements of paragraph (f) of this AD, install drip shields (including a drip pan assembly, drain tubing, and attaching hardware) over the forward, outboard halves of the E1–1 and E3–1 shelves in the main equipment bay, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747–38A2073, Revision 3, dated May 22, 2003.

(h) Installation of drip shields before the effective date of this AD in accordance with paragraph (a) and Note 2 of AD 2001–24–30, amendment 39–12547, is acceptable for compliance with the corresponding actions specified in paragraph (g) of this AD.

**Alternative Methods of Compliance (AMOCs)**

(i)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

**Material Incorporated by Reference**

(j) You must use the service bulletins identified in Table 1 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

TABLE 1.—MATERIAL INCORPORATED BY REFERENCE

Service Bulletin	Revision level	Date
Boeing Alert Service Bulletin 747–25A3430 .....	Original .....	February 15, 2007.
Boeing Alert Service Bulletin 747–38A2073 .....	3 .....	May 22, 2003.

Issued in Renton, Washington, on December 10, 2007.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7–24340 Filed 12–14–07; 8:45 am]

BILLING CODE 4910–13–P

**DEPARTMENT OF COMMERCE**

**Bureau of Economic Analysis**

**15 CFR Part 806**

[Docket No. 07 0301041–7802–03]

RIN 0691–AA63

**Direct Investment Surveys: BE–11, Annual Survey of U.S. Direct Investment Abroad**

**AGENCY:** Bureau of Economic Analysis, Commerce.

**ACTION:** Final rule.

**SUMMARY:** This final rule amends regulations concerning the reporting requirements for the BE–11, Annual Survey of U.S. Direct Investment Abroad. The BE–11 survey is conducted annually and is a sample survey that obtains financial and operating data

covering the overall operations of U.S. parent companies and their foreign affiliates. BEA is expanding the reporting requirements on the BE–11 annual survey so that U.S. parent companies that are banks, foreign affiliates of bank parents, and bank foreign affiliates of nonbank parents are reportable. A few minor changes are required to the instructions on Form BE–11A, Report for U.S. Reporter, so it can be used to collect bank as well as nonbank data. BEA is implementing a new, specialized Form BE–11B(FN) for foreign affiliates of bank parents and bank foreign affiliates of nonbank parents.

**DATES:** This final rule will be effective January 16, 2008.

**FOR FURTHER INFORMATION CONTACT:** David H. Galler, Chief, Direct Investment Division (BE–50), Bureau of Economic Analysis, U.S. Department of Commerce, Washington, DC 20230; phone (202) 606–9835 or e-mail ([david.galler@bea.gov](mailto:david.galler@bea.gov)).

**SUPPLEMENTARY INFORMATION:** In the September 13, 2007, **Federal Register**, 72 FR 52316–52319, BEA published a notice of proposed rulemaking setting forth revised reporting requirements for

the BE–11, Annual Survey of U.S. Direct Investment Abroad. No comments on the proposed rule were received. Thus, the proposed rule is adopted without change. This final rule amends 15 CFR Part 806.14 to set forth the reporting requirements for the BE–11, Annual Survey of U.S. Direct Investment Abroad.

**Description of Changes**

The BE–11 survey is a mandatory survey and is conducted annually by BEA under the International Investment and Trade in Services Survey Act (22 U.S.C. 3101–3108), hereinafter, “the Act.” BEA will send the survey to potential respondents in March of each year; responses will be due by May 31.

This final rule expands the reporting requirements on the BE–11 annual survey so that U.S. parent companies that are banks and their foreign affiliates and bank foreign affiliates of nonbank U.S. parent companies will now be reportable. Until now, collection of data on the BE–11 annual survey has been limited to that of nonbank U.S. parent companies and their nonbank foreign affiliates. Data for bank U.S. parent companies and their bank and nonbank foreign affiliates and data for bank