

match Social Security Administration records; or

(C) Written notice to the employer from the Department of Homeland Security that the immigration status document or employment authorization document presented or referenced by the employee in completing Form I-9 is assigned to another person, or that there is no agency record that the document has been assigned to any person.

(2)(i) An employer who receives written notice from the Social Security Administration as described in paragraph (l)(1)(iii)(B) of this section will be considered by the Department of Homeland Security to have taken reasonable steps—and receipt of the written notice will therefore not be used as evidence of constructive knowledge—if the employer takes the following actions:

(A) The employer must check its records to determine whether the discrepancy results from a typographical, transcription, or similar clerical error. If the employer determines that the discrepancy is due to such an error, the employer must correct the error and inform the Social Security Administration of the correct information (in accordance with the written notice's instructions, if any). The employer must also verify with the Social Security Administration that the employee's name and social security account number, as corrected, match Social Security Administration records. The employer should make a record of the manner, date, and time of such verification, and then store such record with the employee's Form I-9(s) in accordance with 8 CFR 274a.2(b). The employer may update the employee's Form I-9 or complete a new Form I-9 (and retain the original Form I-9), but the employer should not perform a new Form I-9 verification. The employer must complete these steps within thirty days of receiving the written notice.

(B) If the employer determines that the discrepancy is not due to an error in its own records, the employer must promptly request that the employee confirm that the name and social security account number in the employer's records are correct. If the employee states that the employer's records are incorrect, the employer must correct, inform, verify, and make a record as set forth in paragraph (l)(2)(i)(A) of this section. If the employee confirms that its records are correct, the employer must promptly request that the employee resolve the discrepancy with the Social Security Administration (in accordance with the written notice's instructions, if any). The employer must advise the employee

of the date that the employer received the written notice from the Social Security Administration and advise the employee to resolve the discrepancy with the Social Security Administration within ninety days of the date the employer received the written notice from the Social Security Administration.

(C) If the employer is unable to verify with the Social Security Administration within ninety days of receiving the written notice that the employee's name and social security account number matches the Social Security Administration's records, the employer must again verify the employee's employment authorization and identity within an additional three days by following the verification procedure specified in paragraph (l)(2)(iii) of this section.

(ii) An employer who receives written notice from the Department of Homeland Security as described in paragraph (l)(1)(iii)(C) of this section will be considered by the Department of Homeland Security to have taken reasonable steps—and receipt of the written notice will therefore not be used as evidence of constructive knowledge—if the employer takes the following actions:

(A) The employer must contact the local Department of Homeland Security office (in accordance with the written notice's instructions, if any) and attempt to resolve the question raised by the Department of Homeland Security about the immigration status document or employment authorization document. The employer must complete this step within thirty days of receiving the written notice.

(B) If the employer is unable to verify with the Department of Homeland Security within ninety days of receiving the written notice that the immigration status document or employment authorization document is assigned to the employee, the employer must again verify the employee's employment authorization and identity within an additional 3 days by following the verification procedure specified in paragraph (l)(2)(iii) of this section.

(iii) The verification procedure referenced in paragraphs (l)(2)(i)(B) and (l)(2)(ii)(B) of this section is as follows:

(A) The employer completes a new Form I-9 for the employee, using the same procedures as if the employee were newly hired, as described in section 274a.2(a) and (b) of this part, except that—

(1) The employer must complete Section 1 ("Employee Information and Verification") and the employer must complete Section 2 ("Employer Review

and Verification") of the new Form I-9 within ninety-three days of the employer's receipt of the written notice referred to in paragraph (l)(1)(iii)(B) or (C) of this section;

(2) The employer must not accept any document referenced in any written notice described in paragraph (l)(1)(iii)(C) of this section, any document that contains a disputed social security account number or alien number referenced in any written notice described in paragraphs (l)(1)(iii)(B) or (l)(1)(iii)(C) of this section, or any receipt for an application for a replacement of such document, to establish employment authorization or identity or both; and

(3) The employee must present a document that contains a photograph in order to establish identity or both identity and employment authorization.

(B) The employer must retain the new Form I-9 with the prior Form(s) I-9 in accordance with 8 CFR 274a.2(b).

(3) Knowledge that an employee is unauthorized may not be inferred from an employee's foreign appearance or accent. Nothing in this definition should be interpreted as permitting an employer to request more or different documents than are required under section 274A(b) of the Act or to refuse to honor documents tendered that on their face reasonably appear to be genuine and to relate to the individual, except a document about which the employer has received written notice described in paragraph (l)(1)(iii) of this section and with respect to which the employer has received no verification as described in paragraphs (l)(2)(i)(C) or (l)(2)(ii)(B) of this section.

Michael Chertoff,
Secretary.

[FR Doc. E7-16066 Filed 8-14-07; 8:45 am]

BILLING CODE 4410-10-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 23

[Docket No. CE270; Special Condition No. 23-210-SC]

Special Conditions: Adam Aircraft, Model A700; Fire Extinguishing for Aft Fuselage Mounted Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final special conditions.

SUMMARY: These special conditions are issued for the Adam Aircraft, Model A700 airplane. This airplane will have

a novel or unusual design feature(s) associated with aft mounted engine fire protection. The applicable airworthiness regulations do not contain adequate or appropriate safety standards for this design feature. These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

DATES: *Effective Date:* August 6, 2007

FOR FURTHER INFORMATION CONTACT:

Leslie B. Taylor, Regulations & Policy Branch, ACE-111, Federal Aviation Administration, Small Airplane Directorate, Aircraft Certification Service, 901 Locust, Kansas City, MO 64106; telephone (816) 329-4134; facsimile (816) 329-4090, e-mail at leslie.b.taylor@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

On April 12, 2004, Adam Aircraft applied for a type certificate for their new Model A700. The Model A700 is a 6 to 8 seat, pressurized, retractable-gear, composite structure airplane with two turbofan engines mounted on pylons on either side of the aft fuselage.

14 CFR part 23 has historically addressed fire protection through prevention, identification, and containment. Prevention has been provided through minimizing the potential for ignition of flammable fluids and vapors. Identification has been provided by locating engines within the pilots' primary field of view and/or with the incorporation of fire detection systems. This has provided both rapid detection of a fire and confirmation when it was extinguished. Containment has been provided through the isolation of designated fire zones, through flammable fluid shutoff valves, and firewalls. This containment philosophy also ensures that components of the engine control system will function effectively to permit a safe shutdown of an engine. However, containment has only been demonstrated for 15 minutes. If a fire occurs in traditional part 23 airplanes, the appropriate corrective action is to land as soon as possible. For a small, simple airplane originally envisioned by part 23, it is possible to descend and land within 15 minutes; thus, the occupants can safely exit the airplane before the firewall is breached. These simple airplanes normally have the engine located away from critical flight control systems and primary structure. This has ensured that, throughout a fire event, a pilot can continue safe flight, and it has made the prediction of fire

effects relatively easy. Other design features of these simple aircraft, such as low stall speeds and short landing distances, ensure that even in the event of an off-field landing, the potential for the outcome being catastrophic has been minimized.

Title 14 CFR part 23 did not envision the type of configuration of the Model A700 airplane. The Model A700 incorporates two turbofan engines located on pylons on either side of the aft fuselage. These engines are not in the pilots' field of view. With the location in the aft fuselage, the ability to visually detect a fire is minimal.

Type Certification Basis

Under 14 CFR part 21, § 21.17, Adam Aircraft must show that the Model A700 meets the applicable provisions of part 23, as amended by Amendments 23-1 through 23-55, thereto.

If the Administrator finds that the applicable airworthiness regulations in 14 CFR part 23 do not contain adequate or appropriate safety standards for the Model A700 because of a novel or unusual design feature, special conditions are prescribed under § 21.16.

In addition to the applicable airworthiness regulations and special conditions, the Model A700 must comply with the fuel vent and exhaust emission requirements of 14 CFR part 34 and the noise certification requirements of 14 CFR part 36, and the FAA must issue a finding of regulatory adequacy under section 611 of Public Law 92-574, the "Noise Control Act of 1972."

Discussion

The FAA issues special conditions, as defined in § 11.19, under § 11.38, and they become part of the type certification basis under § 21.17(a)(2).

Special conditions are initially applicable to the model for which they are issued. Should the type certificate for that model be amended later to include any other model that incorporates the same or similar novel or unusual design feature, the special conditions would also apply to the other model under § 21.101.

Novel or Unusual Design Features

The Model A700 will incorporate the following novel or unusual design features: The Model A700 incorporates two turbofan engines located on pylons on either side of the aft fuselage. These engines are not in the pilots' field of view. The effects of a fire in such a compartment are more varied and adverse than the typical engine fire in a simple part 23 airplane. With the location in the aft fuselage, the ability to

visually detect a fire is minimal. However, the ability to extinguish an engine fire becomes extremely critical with the Model A700 engine location.

While the certification basis for the Model A700 requires that a fire detection system be installed due to the engine location, fire extinguishing is also considered a requirement. A sustained fire could result in loss of control of the airplane and damage to primary structure before an emergency landing could be made. Because of the location of critical structures and flight controls, a means to minimize the probability of re-ignition from occurring is necessary. One acceptable method to minimize re-ignition is to install a two-shot system. The effects of a fire emanating from an enclosed engine installation are more varied, adverse, and more difficult to predict than an engine fire envisioned for typical part 23 airplanes.

Discussion of Comments

A notice of proposed special conditions, Notice No. 23-07-02-SC, for the Adam Aircraft Model A700 was published in the **Federal Register** on June 25, 2007 (72 FR 34644). No comments were received, and the special conditions are adopted as proposed.

Applicability

As discussed above, these special conditions are applicable to the Model A700. Should Adam Aircraft apply later for a change to the type certificate to include another model incorporating the same novel or unusual design feature, the special conditions would apply to that model as well.

Conclusion

This action affects only certain novel or unusual design features on one model of airplane. It is not a rule of general applicability, and it affects only the applicant who applied to the FAA for approval of these features on the airplane.

List of Subjects in 14 CFR Part 23

Aircraft, Aviation safety, Signs and symbols.

Citation

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(g), 40113, and 44701; 14 CFR 21.16 and 21.17; and 14 CFR 11.38 and 11.19.

The Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special

conditions are issued as part of the type certification basis for Adam Aircraft, Model A700 airplanes.

Aft fuselage mounted engines need to protect the airplane from fires that were not envisioned in the development of part 23. Therefore, special conditions for a fire extinguishing system are required for airplanes with this engine configuration.

Regulations requiring and defining engine compartment fire extinguishing systems already exist for part 23 commuter category airplanes. These regulations will provide an adequate level of safety for the normal category Model A700 aircraft with its aft pylon mounted engines.

As the extinguishing agent is subject to change during the service life of the airplane, the certification basis needs to include 14 CFR part 23, § 23.1197 in its entirety.

Each fire zone should be ventilated to prevent the accumulation of flammable vapors. It must also be designed such that it will not allow entry of flammable fluids, vapors, or flames from other fire zones. It must be designed such that it does not create an additional fire hazard from the discharge of vapors or fluids.

1. SC 23.1195—Add the requirements of § 23.1195 while deleting “For commuter category airplanes.”

23.1195, Fire Extinguishing Systems

(a) Fire extinguishing systems must be installed and compliance shown with the following:

(1) Except for combustor, turbine, and tailpipe sections of turbine-engine installations that contain lines or components carrying flammable fluids or gases for which a fire originating in these sections is shown to be controllable, a fire extinguisher system must serve each engine compartment;

(2) The fire extinguishing system, the quantity of extinguishing agent, the rate of discharge, and the discharge distribution must be adequate to extinguish fires. An individual “one-shot” system may be used except for embedded engines where a “two-shot” system is required.

(3) The fire extinguishing system for a nacelle must be able to simultaneously protect each compartment of the nacelle for which protection is provided.

(b) If an auxiliary power unit is installed in any airplane certified to this part, that auxiliary power unit compartment must be served by a fire extinguishing system meeting the requirements of paragraph (a)(2) of this section.

2. SC 23.1197—Add the requirements of § 23.1197 while deleting “For commuter category airplanes.”

23.1197, Fire Extinguishing Agents

The following applies:

(a) Fire extinguishing agents must—

(1) Be capable of extinguishing flames emanating from any burning fluids or other combustible materials in the area protected by the fire extinguishing system; and

(2) Have thermal stability over the temperature range likely to be experienced in the compartment in which they are stored.

(b) If any toxic extinguishing agent is used, provisions must be made to prevent harmful concentrations of fluid or fluid vapors (from leakage during normal operation of the airplane or as a result of discharging the fire extinguisher on the ground or in flight) from entering any personnel compartment, even though a defect may exist in the extinguishing system. This must be shown by test except for built-in carbon dioxide fuselage compartment fire extinguishing systems for which—

(1) Five pounds or less of carbon dioxide will be discharged under established fire control procedures into any fuselage compartment; or

(2) Protective breathing equipment is available for each flight crewmember on flight deck duty.

3. SC 23.1199—Add the requirements of § 23.1199 while deleting “For commuter category airplanes.”

23.1199, Extinguishing Agent Containers

The following applies:

(a) Each extinguishing agent container must have a pressure relief to prevent bursting of the container by excessive internal pressures.

(b) The discharge end of each discharge line from a pressure relief connection must be located so that discharge of the fire-extinguishing agent would not damage the airplane. The line must also be located or protected to prevent clogging caused by ice or other foreign matter.

(c) A means must be provided for each fire extinguishing agent container to indicate that the container has discharged or that the charging pressure is below the established minimum necessary for proper functioning.

(d) The temperature of each container must be maintained, under intended operating conditions, to prevent the pressure in the container from—

(1) Falling below that necessary to provide an adequate rate of discharge; or

(2) Rising high enough to cause premature discharge.

(e) If a pyrotechnic capsule is used to discharge the fire extinguishing agent, each container must be installed so that

temperature conditions will not cause hazardous deterioration of the pyrotechnic capsule.

4. SC 23.1201—Add the requirements of § 23.1201 while deleting “For commuter category airplanes.”

23.1201, Fire Extinguishing System Materials

The following apply:

(a) No material in any fire extinguishing system may react chemically with any extinguishing agent so as to create a hazard.

(b) Each system component in an engine compartment must be fireproof. Issued in Kansas City, Missouri on August 6, 2007.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-15973 Filed 8-14-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 25

[Docket No. NM373; Special Conditions No. 25-360-SC]

Special Conditions: Boeing Model 787-8 Airplane; Composite Fuselage In-Flight Fire/Flammability Resistance

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final special conditions.

SUMMARY: These special conditions are issued for the Boeing Model 787-8 airplane. This airplane will have novel or unusual design features when compared to the state of technology envisioned in the airworthiness standards for transport category airplanes. The fuselage of the Boeing Model 787-8 series airplane will be made of composite materials rather than conventional aluminum. While the regulations include flame propagation standards for some materials commonly found in inaccessible areas of the airplane, they do not yet incorporate standards for materials used to construct the fuselage. Therefore, special conditions are needed to address this design feature. These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing standards. Additional special conditions will be issued for other novel or unusual design features of the Boeing Model 787-8 airplanes.