

devices using digital logic or other complex design technologies must provide a level of assurance for the encoded logic commensurate with the hazard associated with the failure or malfunction of the systems in which the devices are located. The applicant must design, implement, and verify all associated logic to minimize the existence of errors by using a method, approved by the FAA, that is consistent with the criticality of the performed function.

6. Amend § 33.29 by adding new paragraphs (e) through (h) to read as follows:

§ 33.29 Instrument connection.

* * * * *

(e) The applicant must make provision for the installation of instrumentation necessary to ensure operation in compliance with engine operating limitations. Where, in presenting the safety analysis, or complying with any other requirement, dependence is placed on instrumentation that is not otherwise mandatory in the assumed aircraft installation, then the applicant must specify this instrumentation in the engine installation instructions and declare it mandatory in the engine approval documentation.

(f) As part of the System Safety Assessment of § 33.28(e), the applicant must assess the possibility and subsequent effect of incorrect fit of instruments, sensors, or connectors. Where necessary, the applicant must take design precautions to prevent incorrect configuration of the system.

(g) The sensors, together with associated wiring and signal conditioning, must be segregated, electrically and physically, to the extent necessary to ensure that the probability of a fault propagating from instrumentation and monitoring functions to control functions, or vice versa, is consistent with the failure effect of the fault.

(h) The applicant must provide instrumentation enabling the flight crew to monitor the functioning of the turbine cooling system unless appropriate inspections are published in the relevant manuals and evidence shows that:

(1) Other existing instrumentation provides adequate warning of failure or impending failure;

(2) Failure of the cooling system would not lead to hazardous engine effects before detection; or

(3) The probability of failure of the cooling system is extremely remote.

7. Amend § 33.53 by revising the section heading and paragraph (a) to read as follows:

§ 33.53 Engine system and component tests.

(a) For those systems and components that cannot be adequately substantiated in accordance with endurance testing of § 33.49, the applicant must conduct additional tests to demonstrate that systems or components are able to perform the intended functions in all declared environmental and operating conditions.

* * * * *

§ 33.67 [Amended]

8. Remove paragraph (d) from § 33.67.

9. Amend § 33.91 by revising the section heading and paragraph (a) to read as follows:

§ 33.91 Engine system and component tests.

(a) For those systems or components that cannot be adequately substantiated in accordance with endurance testing of § 33.87, the applicant must conduct additional tests to demonstrate that the systems or components are able to perform the intended functions in all declared environmental and operating conditions.

* * * * *

Issued in Washington, DC, on March 26, 2007.

John J. Hickey,

Director, Aircraft Certification Service.

[FR Doc. E7-6535 Filed 4-10-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-27532; Directorate Identifier 2007-CE-021-AD]

RIN 2120-AA64

Airworthiness Directives; Piaggio Aero Industries S.p.A. P-180 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct

an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

One P-180 aircraft experienced a jamming of its longitudinal flight control cables. Investigations revealed that its fuselage drain holes were plugged, and water was trapped in the lower fuselage.

As a consequence of plugged drain holes, water can accumulate and freeze when the aircraft reaches and holds altitudes where temperature is below the freezing point. If not corrected this may cause the loss of control of the airplane.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by May 11, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4145; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI

safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2007-27532; Directorate Identifier 2007-CE-021-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No. 2007-0031, dated February 9, 2007 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products.

One P-180 aircraft experienced a jamming of its longitudinal flight control cables. Investigations revealed that its fuselage drain holes were plugged, and water was trapped in the lower fuselage.

As a consequence of plugged drain holes, water can accumulate and freeze when the aircraft reaches and holds altitudes where temperature is below the freezing point. If not corrected this may cause the loss of control of the airplane.

The MCAI requires:

* * * Check for proper operation, fuselage drain holes and the passenger evaporator drain line and to introduce a temporary revision of the Aircraft Maintenance Manual.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Piaggio Aero Industries S.p.A. has issued Mandatory Service Bulletin SB-80-0220, dated August 8, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a Note within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 60 products of U.S. registry. We also estimate that it would take about 5 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$24,000, or \$400 per product.

In addition, we estimate that any necessary follow-on actions would take about 13 work-hours and require parts costing \$125 for a cost of \$1,165 per product. We have no way of

determining the number of products that may need these actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Piaggio Aero Industries S.P.A.: Docket No. FAA-2007-27532; Directorate Identifier 2007-CE-021-AD.

Comments Due Date

(a) We must receive comments by May 11, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to P-180 airplanes, serial numbers 1004 through 1112, certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 53: Fuselage.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

One P 180 aircraft experienced a jamming of its longitudinal flight control cables. Investigations revealed that its fuselage drain holes were plugged, and water was trapped in the lower fuselage.

As a consequence of plugged drain holes, water can accumulate and freeze when the aircraft reaches and holds altitudes where temperature is below the freezing point. If not corrected this may cause the loss of control of the airplane.

Actions and Compliance

(f) Unless already done, do the following actions:

(1) At the next scheduled maintenance inspection or 1 month after the effective date of the AD, whichever occurs later, and repetitively thereafter at intervals not to exceed every 12 months, inspect fuselage drain holes and the passenger evaporator drain line for proper operation and do all the necessary corrective actions, following the accomplishment instructions of the Piaggio Aero Industries S.p.A. Mandatory SB-80-0220, dated August 8, 2006.

Note 1: We have established the repetitive inspection times of this AD so that they may coincide with annual inspections.

Note 2: We encourage you to update your maintenance program by inserting the Temporary Revision of the Piaggio P 180 Avanti Maintenance Manual (AMM) attached to the Piaggio Aero Industries S.p.A. Mandatory SB-80-0220, dated August 8, 2006.

FAA AD Differences

Note 3: This AD differs from the MCAI and/or service information as follows: We have added repetitive inspection requirements in the AD to coincide with the

Piaggio P 180 Avanti Maintenance Manual temporary revision referenced in the Piaggio Aero Industries S.p.A. Mandatory Service Bulletin SB-80-0220, dated August 8, 2006.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Staff, FAA, ATTN: Sarjapur Nagarajan, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4145; fax: (816) 329-4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI EASA AD No. 2007-0031, dated February 9, 2007; and Piaggio Aero Industries S.p.A. Mandatory SB-80-0220, dated August 8, 2006, for related information.

Issued in Kansas City, Missouri, on April 4, 2007.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-6721 Filed 4-10-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF DEFENSE**Office of the Secretary****32 CFR Part 232**

[DOD-2006-OS-0216]

RIN 0790-AI20

Limitations on Terms of Consumer Credit Extended to Service Members and Dependents

AGENCY: Department of Defense (DoD).

ACTION: Notice of proposed rulemaking and request for comment.

SUMMARY: The Department of Defense (the Department or DoD) proposes to

amend our regulations by adding a new part to implement the consumer protections covered by Public Law 109-364, the John Warner National Defense Authorization Act for Fiscal Year 2007, section 670, "Limitations on Terms of Consumer Credit Extended to Service Members and Dependents" (October 17, 2006). Section 670 of Public Law 109-364 created 10 U.S.C. 987 and requires the Secretary of Defense to prescribe regulations to carry out the new section. The proposed regulation is intended to regulate the terms of consumer credit extended by creditors to active duty service members and their dependents.

DATES: Comments must be received no later than June 11, 2007.

ADDRESSES: You may submit comments, identified by docket number and or Regulatory Information Number (RIN) and title, by any of the following methods:

—*Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

—*Mail:* Federal Docket Management System Office, 1160 Defense Pentagon, Washington, DC 20301-1160.

Instructions: All submissions received must include the agency name and docket number or RIN for this **Federal Register** document. The general policy for comments and other submissions from members of the public is to make these submissions available for public viewing on the Internet at <http://www.regulations.gov> as they are received without change, including any personal identifiers or contact information.

FOR FURTHER INFORMATION CONTACT: Mr. George Schaefer, (703) 588-0876.

SUPPLEMENTARY INFORMATION:**I. Background**

Today's joint force combat operations require highly trained, experienced and motivated troops. We are fortunate that the All Volunteer Force of today is comprised of individuals who fit the stringent requirements needed for success on the battlefield. The military has seen a lot of changes since it became an All Volunteer Force in 1973. The technological advances over the ensuing 34 years have made remarkable transformations to the capabilities of the Armed Forces.

These advances would not have been as easily attained if it were not for the All Volunteer Force. The members of this force have higher levels of aptitude, stay in the military longer, and as a consequence, perform better than their conscript predecessors. During the Vietnam era draft, 90 percent of