

Proposed Rules

Federal Register

Vol. 69, No. 146

Friday, July 30, 2004

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-18716; Directorate Identifier 2003-NM-240-AD]

RIN 2120-AA64

Airworthiness Directives; BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ series airplanes. This proposed AD would require repetitive external eddy current inspections of the forward fuselage skin to detect cracking due to fatigue, and repair if necessary. This proposed AD is prompted by evidence of cracking due to fatigue along the edges of the chemi-etched pockets in certain front fuselage canopy skin panels. We are proposing this AD to prevent reduced structural integrity of the airplane fuselage.

DATES: We must receive comments on this proposed AD by August 30, 2004.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.
- Government-wide rulemaking web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.
- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC 20590.
- By fax: (202) 493-2251.
- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building,

400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

You can get the service information identified in this proposed AD from British Aerospace Regional Aircraft American Support, 13850 Mclearn Road, Herndon, Virginia 20171.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer; International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1175; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Docket Management System (DMS)

The FAA has implemented new procedures for maintaining AD dockets electronically. As of May 17, 2004, new AD actions are posted on DMS and assigned a docket number. We track each action and assign a corresponding directorate identifier. The DMS AD docket number is in the form "Docket No. FAA-2004-99999." The Transport Airplane Directorate identifier is in the form "Directorate Identifier 2004-NM-999-AD." Each DMS AD docket also lists the directorate identifier ("Old Docket Number") as a cross-reference for searching purposes.

Comments Invited

We invite you to submit any written relevant data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2004-18716; Directorate Identifier 2003-NM-240-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each

substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that website, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, *etc.*). You can review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications that affect you. You can get more information about plain language at <http://www.faa.gov/language> and <http://www.plainlanguage.gov>.

Examining the Docket

You can examine the AD docket in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, notified us that an unsafe condition may exist on all BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ series airplanes. The CAA advises that evidence of cracking due to fatigue has been found along the edges of the chemi-etched pockets in certain front fuselage canopy skin panels. This condition, if not corrected, could result in reduced structural integrity of the airplane fuselage.

Relevant Service Information

BAE Systems (Operations) Limited has issued Inspection Service Bulletin ISB.53-167, including Appendices 2 and 3, all dated June 27, 2003. The ISB describes procedures for repetitive external eddy current inspections of certain front fuselage canopy skin

panels to detect cracking, and repair if necessary. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. The CAA mandated the service information and issued British airworthiness directive 007-06-2003 to ensure the continued airworthiness of these airplanes in the United Kingdom.

FAA's Determination and Requirements of the Proposed AD

These airplane models are manufactured in the United Kingdom and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. We have examined the CAA's findings, evaluated all pertinent information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Therefore, we are proposing this AD, which would require repetitive external eddy current inspections of certain front fuselage canopy skin panels to detect cracking, and repair if necessary. The proposed AD would require you to use the service information described previously to perform these actions, except as discussed under "Differences Between the Proposed AD and Referenced Service Bulletin."

Differences Between the Proposed AD and Referenced Service Bulletin

Although the referenced service bulletin describes procedures for submitting Appendix 1 of the service bulletin with inspection results to the manufacturer, this proposed AD would not require that action. We do not need this information from operators.

The service bulletin specifies that you may perform repairs in accordance with the structural repair manual (SRM), or that you may contact the manufacturer for instructions on how to repair conditions outside the limits defined in the SRM, but this proposed AD would require you to repair those conditions using a method that we or the CAA (or its delegated agent) approve. In light of the type of repair that would be required to address the unsafe condition, and consistent with existing bilateral airworthiness agreements, we have determined that, for this proposed AD, a repair we or the CAA approve would be acceptable for compliance with this proposed AD.

Costs of Compliance

This proposed AD would affect about 54 airplanes of U.S. registry. The proposed actions would take about 40 work hours per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$140,400, or \$2,600 per airplane, per inspection cycle.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

BAE Systems (Operations) Limited (Formerly British Aerospace Regional Aircraft): Docket No. FAA-2004-18716; Directorate Identifier 2003-NM-240-AD.

Comments Due Date

(a) The Federal Aviation Administration must receive comments on this AD action by August 30, 2004.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ series airplanes, certificated in any category.

Unsafe Condition

(d) This AD was prompted by evidence of cracking due to fatigue along the edges of the chemi-etched pockets in certain front fuselage canopy skin panels. We are issuing this AD to prevent reduced structural integrity of the airplane fuselage.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspections and Repair

(f) Within the applicable compliance time specified in paragraph (f)(1) or (f)(2) of this AD, perform an external eddy current inspection of the forward fuselage skin to detect cracking, in accordance with the Accomplishment Instructions of BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53-167, including Appendices 2 and 3, all dated June 27, 2003.

(1) For Model BAe 146 series airplanes: Inspect before the accumulation of 16,000 total landings, or within 4,000 landings after the effective date of this AD, whichever is later.

(i) For areas where no crack is found, repeat the inspection at intervals not to exceed 8,000 landings.

(ii) For areas where any crack is found, perform repairs in accordance with a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, or the Civil Aviation Authority (CAA) (or its delegated agent). No further inspection of any repaired area is required by this AD.

(2) For Model Avro 146-RJ series airplanes: Inspect before the accumulation of 10,000 total landings, or within 2,000 landings after the effective date of this AD, whichever is later.

(i) For areas where no crack is found, repeat the inspection at intervals not to exceed 4,000 landings.

(ii) For areas where any crack is found, perform repairs in accordance with a method approved by the Manager, International Branch, ANM-116, or the CAA (or its delegated agent). No further inspection of any repaired area is required by this AD.

No Reporting Requirement

(g) Although the service bulletin referenced in this AD specifies to submit Appendix 1 of the service bulletin with certain information to the manufacturer, this AD does not include that requirement.

Alternative Methods of Compliance (AMOCs)

(h) The Manager, International Branch, ANM-116, has the authority to approve AMOCs for this AD, if requested in

accordance with the procedures found in 14 CFR 39.19.

Related Information

(i) British airworthiness directive 007-06-2003 also addresses the subject of this AD.

Issued in Renton, Washington, on July 21, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-17224 Filed 7-29-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF JUSTICE

Drug Enforcement Administration

21 CFR Part 1309

[Docket No. DEA-211P]

RIN 1117-AA62

Security Requirements for Handlers of Pseudoephedrine, Ephedrine, and Phenylpropanolamine

AGENCY: Drug Enforcement Administration (DEA), Justice.

ACTION: Notice of proposed rulemaking.

SUMMARY: DEA is proposing to require that manufacturers, distributors, importers, and exporters of pseudoephedrine, ephedrine, and phenylpropanolamine (PPA) implement security procedures to prevent the theft and diversion of these List I chemicals. These chemicals are available in over-the-counter medications and are widely used in the illicit production of methamphetamine and amphetamine. Based on the number of reports and the size of thefts from manufacturers and distributors of these chemicals, DEA is proposing that these companies implement security measures similar to or as effective as those used for schedule III through V controlled substances. These measures will limit the opportunity for theft and diversion of these chemicals. DEA is soliciting the chemical industry for comments to describe alternate security systems that are equal to the existing controlled substances schedule III through V system.

DATES: To allow adequate time for industry to identify alternative security solutions, written comments must be postmarked, and electronic comments must be sent, on or before October 28, 2004.

ADDRESSES: To ensure proper handling of comments, please reference "Docket No. DEA-211P" on all written and electronic correspondence. Written comments being sent via regular mail

should be sent to the Deputy Assistant Administrator, Office of Diversion Control, Drug Enforcement Administration, Washington, DC 20537, Attention: DEA Federal Register Representative/CCD. Written comments sent via express mail should be sent to DEA Headquarters, Attention: DEA Federal Register Representative/CCD, 2401 Jefferson-Davis Highway, Alexandria, VA 22301. Comments may be directly sent to DEA electronically by sending an electronic message to dea.diversion.policy@usdoj.gov.

Comments may also be sent electronically through <http://www.regulations.gov> using the electronic comment form provided on that site. An electronic copy of this document is also available at the <http://www.regulations.gov> web site. DEA will accept electronic comments containing MS Word, WordPerfect, Adobe PDF, or Excel files only. DEA will not accept any file format other than those specifically listed here.

FOR FURTHER INFORMATION CONTACT: Patricia M. Good, Chief, Liaison and Policy Section, Office of Diversion Control, Drug Enforcement Administration, Washington, DC 20537, Telephone (202) 307-7297.

SUPPLEMENTARY INFORMATION:

Special Notice

Due to concerns regarding possible harmful side effects, the Food and Drug Administration (FDA) initiated action in November 2000, to remove phenylpropanolamine (PPA) from the market and requested that all drug companies discontinue marketing products containing PPA. As a result, many firms voluntarily discontinued marketing products containing phenylpropanolamine and removed them from the shelves for disposal. Phenylpropanolamine is a List I chemical, which is used in the illicit synthesis of amphetamine. Once products containing phenylpropanolamine are removed from the market, the requirements being proposed in this rule will affect mainly a few veterinary products containing phenylpropanolamine.

Background

DEA's Legal Authority for These Regulations

DEA implements the Controlled Substances Act (21 U.S.C. 801-971), as amended by the Chemical Diversion and Trafficking Act of 1988 (CDTA), the Domestic Chemical Diversion Control Act of 1993 (DCDCA), the Comprehensive Methamphetamine Control Act of 1996 (MCA) and the

Methamphetamine Anti-Proliferation Act of 2000 (MAPA) (Title XXXVI of Pub. L. 106-310), among others. DEA publishes the implementing regulations for these statutes in Title 21 of the Code of Federal Regulations pursuant to 21 U.S.C. 821 and 871(b). Regulations relating to the control of listed chemicals are found in 21 CFR parts 1309, 1310 and 1313. These regulations are designed to deter the diversion of listed chemicals to the illegal manufacture of controlled substances. Persons authorized to distribute List I chemicals are registered with the Drug Enforcement Administration, when such registration is determined to be consistent with the public interest. Among other factors used in determining the public interest is a registration applicant's maintenance of effective controls against diversion of listed chemicals into other than legitimate channels (21 U.S.C. 823(h)(1)).

Legitimate Uses of Pseudoephedrine, Phenylpropanolamine, and Ephedrine

Pseudoephedrine and ephedrine are chemicals that are widely used in over-the-counter medications. As noted above, phenylpropanolamine, although previously widely available for human consumption, is now being withdrawn from use in over-the-counter drugs and has only a few human and veterinary uses. Pseudoephedrine is a decongestant used for the temporary relief of nasal congestion due to the common cold, hay fever, or other upper respiratory allergies. Ephedrine is used for the temporary relief of shortness of breath, tightness of chest, and wheezing due to bronchial asthma. Each of the products is available in a variety of dosage forms as a single entity or in combination with antihistamines, antitussives, analgesics, expectorants, and/or vitamins.

The majority of the products containing pseudoephedrine or ephedrine purchased by the public are commonly used medications and are easily accessible at pharmacies, grocery stores, convenience stores, and a variety of other retail stores. Most of these products are available to the public without a prescription. A few products containing pseudoephedrine, phenylpropanolamine, or ephedrine require a prescription issued by a practitioner prior to being dispensed to a patient. This proposed regulation will not adversely impact the public's access to these products as it applies solely to manufacturers and wholesalers of the products. Persons unaffected by this rulemaking include retailers, practitioners, and mid-level