

Governors, however, intends to issue similar notices at least 60 days prior to the elimination of check operations at some other Reserve Bank offices, as described in the May 2003 **Federal Register** document.

**Administrative Procedure Act**

The Board has not followed the provisions of 5 U.S.C. 553(b) relating to notice and public participation in connection with the adoption of this final rule. The revisions to the appendix are technical in nature, and the routing symbol revisions are required by the statutory and regulatory definitions of "check-processing region." Because there is no substantive change on which to seek public input, the Board has determined that the § 553(b) notice and comment procedures are unnecessary.

**Paperwork Reduction Act**

In accordance with the Paperwork Reduction Act of 1995 (44 U.S.C. 3506; 5 CFR 1320 Appendix A.1), the Board has reviewed the final rule under authority delegated to the Board by the Office of Management and Budget. This technical amendment to appendix A of Regulation CC will (1) delete the reference to the Columbia office of the Federal Reserve Bank of Richmond and reassign the routing symbols listed under that office to that Reserve Bank's Charlotte office and (2) delete the reference to the Louisville office of the Federal Reserve Bank of St. Louis and reassign the routing symbols listed under that office to the Cincinnati office of the Federal Reserve Bank of Cleveland. The depository institutions that are located in the affected check processing regions and that include the routing numbers in their disclosure statements would be required to notify customers of the resulting change in availability under § 229.18(e). However, because all paperwork collection procedures associated with Regulation CC already are in place, the Board anticipates that no additional burden will be imposed as a result of this rulemaking.

**12 CFR Chapter II**

**List of Subjects in 12 CFR Part 229**

Banks, Banking, Reporting and recordkeeping requirements.

**Authority and Issuance**

■ For the reasons set forth in the preamble, the Board is amending 12 CFR part 229 to read as follows:

**PART 229—AVAILABILITY OF FUNDS AND COLLECTION OF CHECKS (REGULATION CC)**

■ 1. The authority citation for part 229 continues to read as follows:

Authority: 12 U.S.C. 4001 *et seq.*

■ 2. The Fourth, Fifth, and Eighth Federal Reserve District routing symbol lists in appendix A are revised to read as follows:

**Appendix A to Part 229—Routing Number Guide to Next-Day Availability Checks and Local Checks**

\* \* \* \* \*

**Fourth Federal Reserve District**

[Federal Reserve Bank of Cleveland]

*Head Office*

0410	2410
0412	2412
0430	2430
0432	2432
0433	2433
0434	2434

*Cincinnati Branch*

0420	2420
0421	2421
0422	2422
0423	2423
0515	2515
0519	2519
0813	2813
0830	2830
0839	2839
0863	2863

*Columbus Office*

0440	2440
0441	2441
0442	2442

**Fifth Federal Reserve District**

[Federal Reserve Bank of Richmond]

*Baltimore Branch*

0510	2510
0514	2514
0520	2520
0521	2521
0522	2522
0540	2540
0550	2550
0560	2560
0570	2570

*Charlotte Branch*

0530	2530
0531	2531
0532	2532
0539	2539

\* \* \* \* \*

**Eighth Federal Reserve District**

[Federal Reserve Bank of St. Louis]

*Head Office*

0810	2810
0812	2812
0815	2815
0819	2819
0865	2865

*Memphis Branch*

0820	2820
0829	2829
0840	2840
0841	2841
0842	2842
0843	2843

\* \* \* \* \*

By order of the Board of Governors of the Federal Reserve System, acting through the Secretary of the Board under delegated authority, June 22, 2004.

Jennifer J. Johnson,

Secretary of the Board.

[FR Doc. 04-14505 Filed 6-24-04; 8:45 am]

BILLING CODE 6210-01-P

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. 2003-SW-38-AD; Amendment 39-13686; AD 2004-13-05]

RIN 2120-AA64

**Airworthiness Directives; Eurocopter Deutschland Model MBB-BK 117 A-1, A-3, A-4, B-1, B-2, and C-1 Helicopters**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) for the specified Eurocopter Deutschland (ECD) model helicopters that requires inspecting the vertical fin skin paneling to determine if it was manufactured with the correct wall thickness. This amendment is prompted by a report from the manufacturer that some vertical fins may have been produced with the wrong vertical fin skin thickness. The actions specified by this AD are intended to prevent failure of the vertical fin and subsequent loss of control of the helicopter.

**DATES:** Effective July 30, 2004.

**FOR FURTHER INFORMATION CONTACT:** Richard Monschke, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0110, telephone (817) 222-5116, fax (817) 222-5961.

**SUPPLEMENTARY INFORMATION:** A proposal to amend 14 CFR part 39 to include an AD for the specified model helicopters was published in the **Federal Register** on February 10, 2004 (69 FR 6214). That action proposed to require inspecting the vertical fin skin paneling to determine if it was manufactured with the correct wall thickness.

The Luftfahrt-Bundesamt (LBA), the airworthiness authority for the Federal Republic of Germany, notified the FAA that an unsafe condition may exist on ECD Model MBB-BK117 helicopters, Model A-1 up to B-2, serial number (S/N) all, and Model C-1, S/N 7500 up to 7545. The LBA advises that during tail boom production, metal sheeting of 0.6-millimeter (mm) thickness was found instead of the specified 0.8-mm thickness for the skin paneling of several tail booms.

ECD has issued Alert Service Bulletin No. ASB-MBB-BK117-30-109, Revision 1, dated July 3, 2003, which specifies measuring the wall thickness of the skin paneling of the vertical fin to determine the thickness. The LBA classified this service bulletin as mandatory and issued AD No. 2003-219, dated August 21, 2003, to ensure the continued airworthiness of these helicopters in the Federal Republic of Germany.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that this AD will affect 132 helicopters of U.S. registry. The required actions will take about 1 hour per helicopter to do at an average labor rate of \$65 per work hour. Based on these figures, we estimate the total

cost impact of the AD on U.S. operators to be \$8580 assuming no vertical fins will need to be replaced.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator,

the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

#### 2004-13-05 Eurocopter Deutschland:

Amendment 39-13686. Docket No. 2003-SW-38-AD.

**Applicability:** Model MBB-BK 117 A-1, A-3, A-4, B-1, and B-2, all serial numbers (S/N), and Model C-1, S/N 7500 through 7545, certificated in any category.


**Compliance:** Required within 100 hours time in service, unless accomplished previously.

To prevent failure of the vertical fin and subsequent loss of control of the helicopter, do the following:

(a) Using external calipers, measure the wall thickness, including primer coating, of the skin paneling of the vertical fin at the locations shown in Figure 1 of this AD.

**Note 1:** Eurocopter Deutschland (ECD) Alert Service Bulletin No. ASB-MBB-BK117-30-109, Revision 1, dated July 3, 2003, pertains to the subject of this AD.

**BILLING CODE** 4910-13-P



△ Measurements are to be taken at at least three locations on the skin panel of the vertical fin. Care has to be taken that the external calipers are held squarely to the skin panel wall while measurements are being taken, since tilting of the calipers can lead to false results. If the panel thickness, including the primer coating, is at least 0.778 mm (0.03063 inch) at every measured location, no further action is necessary.

Vertical Fin-Skin Panelling  
Figure 1

(b) If the wall thickness, including the primer coating, of the panelling is less than 0.778 millimeter (0.03063 inch) at any of the measured locations, replace the vertical fin with an airworthy part before further flight.

(c) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Safety Management Group, Rotorcraft Directorate, FAA, for information about previously approved alternative methods of compliance.

(d) This amendment becomes effective on July 30, 2004.

**Note 2:** The subject of this AD is addressed in Luftfahrt-Bundesamt (Federal Republic of Germany) AD 2003-219, dated August 21, 2003.

Issued in Fort Worth, Texas, on June 16, 2004.

**David A. Downey,**  
Manager, Rotorcraft Directorate, Aircraft  
Certification Service.

[FR Doc. 04-14318 Filed 6-24-04; 8:45 am]

**BILLING CODE 4910-13-C**

**DEPARTMENT OF TRANSPORTATION  
Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. 2002-NE-19-AD; Amendment  
39-13693; AD 2004-13-11]

**RIN 2120-AA64**

**Airworthiness Directives; Rolls-Royce  
plc RB211 Trent 875-17, Trent 877-17,  
Trent 884-17, Trent 884B-17, Trent  
892-17, Trent 892B-17, and Trent 895-  
17 Series Turbofan Engines**

**AGENCY:** Federal Aviation  
Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new  
airworthiness directive (AD) for Rolls-  
Royce plc (RR) RB211 Trent 875-17,