

month in which the requirements were not met or the conditions for cancellation occurred.

(1) Milk from the milk production resources and facilities of the producer-handler, designated in paragraph (b)(1) of this section, is delivered in the name of another person as producer milk to another handler.

(2) The producer-handler handles fluid milk products derived from sources other than the milk production facilities and resources designated in paragraph (b)(1) of this section, except that it may receive at its plant, or acquire for route disposition, fluid milk products from fully regulated plants and handlers under any Federal order if such receipts do not exceed 150,000 pounds monthly. This limitation shall not apply if the producer-handler's own-farm production is less than 150,000 pounds during the month.

(3) Milk from the milk production resources and facilities of the producer-handler is subject to inclusion and participation in a marketwide equalization pool under a milk classification and pricing plan operating under the authority of a State government.

(d) *Public announcement.* The market administrator shall publicly announce:

(1) The name, plant location(s), and farm location(s) of persons designated as producer-handlers;

(2) The names of those persons whose designations have been cancelled; and

(3) The effective dates of producer-handler status or loss of producer-handler status for each. Such announcements shall be controlling with respect to the accounting at plants of other handlers for fluid milk products received from any producer-handler.

(e) *Burden of establishing and maintaining producer-handler status.* The burden rests upon the handler who is designated as a producer-handler to establish through records required pursuant to § 1000.27 that the requirements set forth in paragraph (a) of this section have been and are continuing to be met, and that the conditions set forth in paragraph (c) of this section for cancellation of the designation do not exist.

Dated: February 15, 2006.

Lloyd C. Day,

Administrator, Agricultural Marketing Service.

[FR Doc. 06-1587 Filed 2-23-06; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-23283; Directorate Identifier 2005-NM-185-AD; Amendment 39-14483; AD 2006-04-02]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135 Airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all EMBRAER Model EMB-135 airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. This AD requires repetitive inspections of the pitot static heating relay K0057 for damage to the pin-type contacts, relay enclosure, and finishing material and corrective actions if necessary. This AD also requires doing a terminating modification, which ends the repetitive inspections. This AD results from a report of a burning drain hose and smoke caused by an overheated pitot static heating relay. We are issuing this AD to prevent overheating of a certain pitot static heating relay, which could result in the burning of the windowsill drain hoses and consequent smoke or fire in the airplane cockpit.

DATES: This AD becomes effective March 31, 2006.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of March 31, 2006.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC.

Contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to all EMBRAER Model EMB-135 airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. That NPRM was published in the **Federal Register** on December 13, 2005 (70 FR 73668). That NPRM proposed to require repetitive inspections of the pitot static heating relay K0057 for damage to the pin-type contacts, relay enclosure, and finishing material and corrective actions if necessary. That NPRM also proposed to require doing a terminating modification, which ends the repetitive inspections.

Comments

We provided the public the opportunity to participate in the development of this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Inspection, per inspection cycle	1	\$65	None	\$65	651	\$42,315, per inspection cycle.
Terminating modification	2	65	270	400	651	\$260,400.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2006-04-02 Empresa Brasileira de Aeronautica S.A. (EMBRAER): Amendment 39-14483. Docket No. FAA-2005-23283; Directorate Identifier 2005-NM-185-AD.

Effective Date

(a) This AD becomes effective March 31, 2006.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all EMBRAER Model EMB-135BJ, -135ER, -135KE, -135KL, and -135LR airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes; certificated in any category.

Unsafe Condition

(d) This AD results from a report of a burning drain hose and smoke caused by an overheated pitot static heating relay. We are issuing this AD to prevent overheating of a certain pitot static heating relay, which could result in the burning of the windowsill drain hoses and consequent smoke or fire in the airplane cockpit.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Service Bulletin References

(f) The term "service bulletin," as used in this AD, means the Accomplishment Instructions of the service bulletins identified in Table 1 of this AD, as applicable:

TABLE 1.—SERVICE BULLETIN REFERENCES

For Model—	For the actions specified in—	EMBRAER Service Bulletin—
EMB-135ER, -135KE, -135KL, and -135LR airplanes and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes.	paragraph (g) of this AD	145-30-0042, dated April 18, 2005.
	paragraph (i) of this AD	145-30-0041, dated April 20, 2005.
EMB-135BJ airplanes	paragraph (g) of this AD	145LEG-30-0012, dated April 18, 2005.
	paragraph (i) of this AD	145LEG-30-0011, dated April 20, 2005.

Repetitive Inspections

(g) Within 600 flight hours or 180 days after the effective date of this AD, whichever is first: Do a general visual inspection of pitot static heating relay K0057 for damage to the pin-type contacts, relay enclosure, and

finishing material, and do the corrective action as applicable, by accomplishing all of the applicable actions specified in the applicable service bulletin; except as provided by paragraph (h) of this AD. The corrective actions must be done before

further flight. Repeat the inspection thereafter at intervals not to exceed 500 flight hours, until the terminating modification required by paragraph (i) of this AD is accomplished.

Note 1: For the purposes of this AD, a general visual inspection is: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

Service Bulletin Exceptions

(h) Although EMBRAER Service Bulletin 145-30-0042, dated April 18, 2005, and EMBRAER Service Bulletin 145LEG-30-0012, dated April 18, 2005, specify contacting the manufacturer if damage to components for the relay support is found and also specify returning any relay that fails an inspection to the airplane manufacturer, this AD does not include those requirements.

Terminating Modification

(i) Within 6,000 flight hours or 30 months after the effective date of this AD, whichever is first: Do the applicable actions specified in paragraphs (i)(1), (i)(2), and (i)(3) of this AD. Accomplishing all the applicable actions specified in this paragraph terminates the inspections required by paragraph (g) of this AD.

(1) For all airplanes, replace the direct-vision windowsill drain hoses having part number (P/N) 123-15435-401 and -403 with new, improved hoses having P/N 145-13044-001 and P/N 145-13047-001, as applicable, and replace the tiedown straps with new tiedown straps, in accordance with Figure 1 of the service bulletin.

(2) For all airplanes, rework the drain hose having P/N 123-15435-405, in accordance with Figure 1 of the service bulletin.

(3) For Model EMB-135BJ airplanes, reroute the drain hoses of the left and right cockpit horizontal linings, in accordance with Figure 2 of the service bulletin.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(k) Brazilian airworthiness directive 2005-08-04, effective September 5, 2005, also addresses the subject of this AD.

Material Incorporated by Reference

(l) You must use the service documents identified in Table 2 of this AD to perform the actions that are required by this AD, unless the AD specifies otherwise. The

Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

TABLE 2.—MATERIAL INCORPORATED BY REFERENCE

Embraer Service Bulletin	Date
145-30-0041	April 20, 2005.
145-30-0042	April 18, 2005.
145LEG-30-0011	April 20, 2005.
145LEG-30-0012	April 18, 2005.

Issued in Renton, Washington, on February 3, 2006.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 06-1409 Filed 2-23-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-23966; Directorate Identifier 2006-NM-024-AD; Amendment 39-14495; AD 2006-04-13]

RIN 2120-AA64

Airworthiness Directives; Gulfstream Model GIV-X and GV-SP Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Gulfstream Model GIV-X and GV-SP series airplanes. This AD requires revising the Limitations section of the airplane flight manual by incorporating new procedures to follow in the event that the cockpit displays go blank or malfunction. This AD results from a report that all four of the cockpit flight panel display units simultaneously went blank during flight. We are issuing

this AD to ensure that the flightcrew is advised of the appropriate procedures to follow in the event that the cockpit displays go blank or malfunction, which could result in a reduction of the flightcrew's situational awareness and possible loss of control of the airplane.

DATES: This AD becomes effective March 13, 2006.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of March 13, 2006.

We must receive comments on this AD by April 25, 2006.

ADDRESSES: Use one of the following addresses to submit comments on this AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590.

- Fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Gulfstream Aerospace Corporation, Technical Publications Dept., P.O. Box 2206, Savannah, Georgia 31402-2206, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT:

Robert Chupka, Aerospace Engineer, Systems and Equipment Branch, ACE-119A, Atlanta Aircraft Certification Office, FAA, One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, Georgia 30349; telephone (770) 703-6070; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION:

Discussion

We have received a report indicating that all four of the cockpit flight panel display units simultaneously went blank during flight on a Gulfstream Model GV-SP airplane. The displays did not recover until the flightcrew pulled circuit breakers associated with the displays; subsequently, three of the four displays returned to normal. Initial investigation revealed discrepancies with the reversion logic of the advanced graphic modules. Similar display failures occurred during ground test operations. Such conditions, if not corrected, could result in a reduction of the flightcrew's situational awareness