

Rules and Regulations

Federal Register

Vol. 71, No. 128

Wednesday, July 5, 2006

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF AGRICULTURE

Natural Resources Conservation Service

7 CFR Part 625

Healthy Forests Reserve Program; Correction

AGENCY: Natural Resources Conservation Service (NRCS), United States Department of Agriculture (USDA).

ACTION: Interim final rule with request for comments; correction.

SUMMARY: This is to correct a URL address previously published in the Rules and Regulations section on Wednesday, May 17, 2006 (71 FR 28547). The error occurred in a URL in the ADDRESSES section on page 28548. The entire ADDRESSES section with the corrected URL is published below. This interim final rule sets forth how NRCS will implement HFRP to meet the statutory objectives of the program.

DATES: This rule is effective May 17, 2006. Comments must be received by August 15, 2006.

ADDRESSES: Send comments by mail to Robin Heard, Director, Easement Program Division, Natural Resources Conservation Service, P.O. Box 2890, Washington, DC 20013-2890; or by e-mail: Rules@usda.gov; attn: Healthy Forests Reserve Program. This rule may also be accessed via Internet through the NRCS homepage at <http://www.nrcs.usda.gov/programs/HFRP/ProgInfo/Index.html>. The rule may also be reviewed and comments may be submitted via the Federal Government's centralized rulemaking Web site at <http://www.regulations.gov>. All comments, including the name and address of each commenter, will become a matter of public record, and may be viewed during normal business hours

by contacting NRCS at the address above.

FOR FURTHER INFORMATION CONTACT:

Robin Heard, Director, Easement Programs Division, NRCS, P.O. Box 2890, Washington, DC 20013-2890; telephone: (202) 720-1854; fax: (202) 720-4265; e-mail: Robin.Heard@wdc.usda.gov, Attention: Healthy Forests Reserve Program. Persons with disabilities who require alternative means for communication (Braille, large print, audiotape, etc.) should contact the USDA Target Center at (202) 720-2600 (voice and TDD).

Signed in Washington, DC, on June 29, 2006.

Teresa Davis,

Federal Register Liaison, Natural Resources Conservation Service.

[FR Doc. E6-10462 Filed 7-3-06; 8:45 am]

BILLING CODE 3410-16-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-24430; Directorate Identifier 2006-NM-048-AD; Amendment 39-14671; AD 2006-13-18]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-9-31, DC-9-32, DC-9-32F, DC-9-33F, DC-9-34, and DC-9-34F Airplanes; and Model DC-9-40 and DC-9-50 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain transport category airplanes, identified above. This AD requires installing a bonding jumper from the boost pump volute to the fuel tank structure, and related investigative/corrective actions. This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent point-contact arcing or filament heating in the fuel tank, which, in the event of a short or ground fault inside the fuel tank, could result in a fuel tank explosion and consequent loss of the airplane.

DATES: This AD becomes effective August 9, 2006.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of August 9, 2006.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, Room PL-401, Washington, DC.

Contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024), for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT:

Samuel Lee, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5262; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the ADDRESSES section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain McDonnell Douglas transport category airplanes. That NPRM was published in the **Federal Register** on April 13, 2006 (71 FR 19140). That NPRM proposed to require installing a bonding jumper from the boost pump volute to the fuel tank structure, and related investigative/corrective actions.

Comments

We provided the public the opportunity to participate in the development of this AD. We received no

comments on the NPRM or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

There are about 250 airplanes of the affected design in the worldwide fleet. This AD will affect about 152 airplanes of U.S. registry. The required actions will take about 9 work hours per airplane, at an average labor rate of \$80 per work hour. Required parts will cost about \$2,385 per airplane. Based on these figures, the estimated cost of this AD for U.S. operators is \$471,960, or \$3,105 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2006-13-18 McDonnell Douglas:

Amendment 39-14671. Docket No. FAA-2006-24430; Directorate Identifier 2006-NM-048-AD.

Effective Date

(a) This AD becomes effective August 9, 2006.

Affected ADs

(b) None.

Applicability

(c) This AD applies to McDonnell Douglas Model DC-9-31, DC-9-32, DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, DC-9-41, and DC-9-51 airplanes, certificated in any category; as identified in Boeing Service Bulletin DC9-28-214, dated December 16, 2005.

Unsafe Condition

(d) This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent point-contact arcing or filament heating in the fuel tank, which, in the event of a short or ground fault inside the fuel tank, could result in a fuel tank explosion and consequent loss of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Installation

(f) Within 60 months after the effective date of this AD, install a bonding jumper from the boost pump volute to the fuel tank structure, and do all applicable related investigative and corrective actions before further flight; by doing all the actions specified in the Accomplishment

Instructions of Boeing Service Bulletin DC9-28-214, dated December 16, 2005.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Los Angeles Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Material Incorporated by Reference

(h) You must use Boeing Service Bulletin DC9-28-214, dated December 16, 2005, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024), for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on June 22, 2006.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 06-5871 Filed 7-3-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-23704; Directorate Identifier 2006-NE-02-AD; Amendment 39-14674; AD 2006-14-03]

RIN 2120-AA64

Airworthiness Directives; Honeywell International Inc. TPE331 Series Turboprop, and TSE331-3U Model Turboshift Engines

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.