

Proposed Rules

Federal Register

Vol. 71, No. 214

Monday, November 6, 2006

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-26250; Directorate Identifier 2006-NM-104-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300 B4-600, B4-600R, and F4-600R Series Airplanes, and Model C4-605R Variant F Airplanes (Collectively Called A300-600 Series Airplanes)

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus Model A300-600 airplanes. This proposed AD would require an inspection to determine if certain spoiler actuators having certain part numbers are installed, and eventual replacement of all affected actuators. This proposed AD results from failure of a distribution block, which was detected during fatigue qualification tests of certain spoiler actuators. We are proposing this AD to prevent failure of the distribution block, which could result in leakage of the hydraulic fluid that supplies those actuators. This failure could cause failure of one of the three spoiler actuators and the associated hydraulic circuits, which could result in loss of those hydraulic circuits and consequent reduced controllability of the airplane.

DATES: We must receive comments on this proposed AD by December 6, 2006.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov>

and follow the instructions for sending your comments electronically.

- **Mail:** Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590.

- **Fax:** (202) 493-2251.

- **Hand Delivery:** Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "FAA-2006-26250; Directorate Identifier 2006-NM-104-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified us that an unsafe condition may exist on certain Airbus Model A300-600 series airplanes. The DGAC advises that during fatigue qualification tests of certain spoiler actuators a failure of the distribution block was detected. This failure could lead to a leak of the hydraulic fluid that supplies the actuator, and could cause failure of one of the three spoiler actuators and the associated hydraulic circuits, which could result in loss of those hydraulic circuits. This condition, if not corrected, could result in reduced controllability of the airplane.

Relevant Service Information

Airbus has issued Service Bulletin A300-27-6057, including Appendix 01, dated May 17, 2005. The service bulletin describes procedures for an inspection to determine if certain spoiler actuators having certain part numbers are installed, and eventual replacement of all affected actuators. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. The DGAC mandated the service information and issued French airworthiness directive F-2005-125, dated July 20, 2005, to ensure the continued airworthiness of these airplanes in France.

FAA's Determination and Requirements of the Proposed AD

These airplane models are manufactured in France and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the

applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. We have examined the DGAC's findings, evaluated all pertinent information, and determined that we need to issue an AD for airplanes of this type design that are certificated for operation in the United States.

Therefore, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

This proposed AD would affect about 1 airplane of U.S. registry.

The proposed inspection would take about 1 hour per airplane, at an average labor rate of \$80 per hour. Based on these figures, the estimated cost of the proposed inspection for U.S. operators is \$80.

The proposed replacements, if accomplished, would take about 5 work hours per airplane, at an average labor rate of \$80 per work hour. Required parts cost would be minimal. Based on these figures, the estimated cost of the proposed replacements for U.S. operators is \$400.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the National Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA-2006-26250; Directorate Identifier 2006-NM-104-AD.

Comments Due Date

- (a) The FAA must receive comments on this AD action by December 6, 2006.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Airbus Model A300-600 airplanes; certificated in any category; as identified in Airbus Service Bulletin A300-27-6057, dated May 17, 2005.

Unsafe Condition

- (d) This AD results from failure of a distribution block, which was detected during fatigue qualification tests of certain spoiler actuators. We are issuing this AD to prevent failure of the distribution block, which could result in leakage of the hydraulic fluid that supplies those actuators. This failure could cause failure of one of the three spoiler actuators and the associated hydraulic circuits, which could result in loss of those hydraulic circuits and consequent reduced controllability of the airplane.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection for Actuator Part Numbers and Corrective Action

- (f) Within 700 flight hours after the effective date of this AD: Inspect to determine if a spoiler actuator with part number P376A0002-04 or P376A0002-08 is installed, by doing all the applicable actions in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-27-6057, excluding Appendix 01, dated May 17, 2005.

- (1) If no actuator with either identified part number is installed, no further action is required by this paragraph.

- (2) If any actuator with any identified part number is installed and the three associated hydraulic circuits are affected (at least one actuator supplied by the yellow circuit and at least one actuator supplied by the blue circuit and at least one actuator supplied by the green circuit): Within 100 flight hours after accomplishing the inspection required by paragraph (f) of this AD, replace all affected actuators on one of the hydraulic circuits with new actuators in accordance with the service bulletin. Within 12 months after accomplishing that replacement, replace all the remaining affected actuators with new actuators in accordance with the service bulletin.

- (3) If any actuator with any identified part number is installed and one or two of the associated hydraulic circuits are affected: Within 12 months after accomplishing the inspection required by paragraph (f) of this AD, replace all affected actuators with new actuators in accordance with the service bulletin.

Parts Installation

- (g) After the effective date of this AD, no spoiler actuator with part number P376A0002-04 or P376A0002-08 may be installed on any airplane.

No Reporting Required

- (h) Although Airbus Service Bulletin A300-27-6057, excluding Appendix 01, dated May 17, 2005, specifies to submit an inspection report to the manufacturer, this AD does not include that requirement.

Alternative Methods of Compliance (AMOCs)

- (i)(1) The Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

- (2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

- (j) French airworthiness directive F-2005-125, dated July 20, 2005, also addresses the subject of this AD.

Issued in Renton, Washington, on October 30, 2006.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-18685 Filed 11-3-06; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA-R07-OAR-2006-0837; FRL-8239-2]

Approval and Promulgation of Implementation Plans; State of Missouri

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA proposes to approve the State Implementation Plan (SIP) revision submitted by the state of Missouri to add a test method for compliance testing to the rule that controls emissions of nitrogen oxides of major sources in the St. Louis ozone nonattainment area.

DATES: Comments on this proposed action must be received in writing by December 6, 2006.

ADDRESSES: Submit your comments, identified by Docket ID No. EPA-R07-OAR-2006-0837 by one of the following methods:

1. *http://www.regulations.gov*: Follow the on-line instructions for submitting comments.

2. *E-mail*: algie-eakin.amy@epa.gov.

3. *Mail*: Amy Algie-Eakin, Environmental Protection Agency, Air Planning and Development Branch, 901 North 5th Street, Kansas City, Kansas 66101.

4. *Hand Delivery or Courier*. Deliver your comments to: Amy Algie-Eakin, Environmental Protection Agency, Air Planning and Development Branch, 901 North 5th Street, Kansas City, Kansas 66101. Such deliveries are only accepted during the Regional Office's normal hours of operation. The Regional Office's official hours of business are Monday through Friday, 8 to 4:30, excluding legal holidays.

Please see the direct final rule which is located in the Rules section of this **Federal Register** for detailed instructions on how to submit comments.

FOR FURTHER INFORMATION CONTACT: Amy Algie-Eakin at (913) 551-7942, or by e-mail at algie-eakin.amy@epa.gov.

SUPPLEMENTARY INFORMATION: In the final rules section of the **Federal**

Register, EPA is approving the state's SIP revision as a direct final rule without prior proposal because the Agency views this as a noncontroversial revision amendment and anticipates no relevant adverse comments to this action. A detailed rationale for the approval is set forth in the direct final rule. If no relevant adverse comments are received in response to this action, no further activity is contemplated in relation to this action. If EPA receives relevant adverse comments, the direct final rule will be withdrawn and all public comments received will be addressed in a subsequent final rule based on this proposed action. EPA will not institute a second comment period on this action. Any parties interested in commenting on this action should do so at this time. Please note that if EPA receives adverse comment on part of this rule and if that part can be severed from the remainder of the rule, EPA may adopt as final those parts of the rule that are not the subject of an adverse comment. For additional information, see the direct final rule which is located in the rules section of this **Federal Register**.

Dated: October 25, 2006.

Martha Cuppy,

Acting Regional Administrator, Region 7.

[FR Doc. E6-18566 Filed 11-3-06; 8:45 am]

BILLING CODE 6560-50-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Parts 52 and 81

[EPA-R04-OAR-2006-0676-200622(b); FRL-8239-4]

Approval and Promulgation of Implementation Plans and Designation of Areas for Air Quality Planning Purposes; NC; Redesignation of the Rocky Mount 8-Hour Ozone Nonattainment Area to Attainment

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: On June 19, 2006, the State of North Carolina, through the North Carolina Department of Environment and Natural Resources, Division of Air Quality, submitted a final request: To redesignate the Rocky Mount 8-hour ozone nonattainment area to attainment for the 8-hour ozone National Ambient Air Quality Standard, and to approve a North Carolina State Implementation Plan revision containing a maintenance plan for Rocky Mount, North Carolina. The Rocky Mount 8-hour ozone nonattainment area is comprised of two

counties, Edgecombe and Nash. EPA is proposing to approve the 8-hour ozone redesignation request for the Rocky Mount 8-hour ozone nonattainment area. Additionally, EPA is proposing to approve the 8-hour ozone maintenance plan for Rocky Mount, North Carolina. This proposal is based on EPA's determination that the State of North Carolina has demonstrated that the Rocky Mount area has met the criteria for redesignation to attainment specified in the Clean Air Act, including the determination that the entire Rocky Mount 8-hour ozone nonattainment area has attained the 8-hour ozone standard. In this action, EPA is also finding adequate and proposing to approve the 2008 and 2017 motor vehicle emissions budgets (MVEBs) for nitrogen oxides (for both Edgecombe and Nash counties) that are contained in the 8-hour ozone maintenance plan for the Rocky Mount nonattainment area. North Carolina has established subarea MVEBs at the county level so each county must consider its individual subarea MVEBs for the purposes of implementing transportation conformity. Further, in this action, EPA is proposing to find adequate and to approve the insignificance determination for volatile organic compounds' contribution from motor vehicle emissions to the 8-hour ozone pollution in the Rocky Mount, North Carolina area.

DATES: Written comments must be received on or before December 6, 2006.

ADDRESSES: Submit your comments, identified by Docket ID No EPA-R04-OAR-2006-0676, by one of the following methods:

1. *http://www.regulations.gov*: Follow the online instructions for submitting comments.

2. *E-mail*: ward.nacosta@epa.gov or wood.amanetta@epa.gov.

3. *Fax*: 404-562-9019.

4. *Mail*: "EPA-R04-OAR-2006-0676", Regulatory Development Section, Air Planning Branch, Air, Pesticides and Toxics Management Division, U.S. Environmental Protection Agency, Region 4, 61 Forsyth Street, SW., Atlanta, Georgia 30303-8960.

5. *Hand Delivery or Courier*. Deliver your comments to: Nacosta C. Ward or Amanetta Wood, Regulatory Development Section, Air Planning Branch, Air, Pesticides and Toxics Management Division, U.S. Environmental Protection Agency, Region 4, 61 Forsyth Street, SW., Atlanta, Georgia 30303-8960. Such deliveries are only accepted during the Regional Office's normal hours of operation. The Regional Office's official hours of business are Monday through