Proposed Rules

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-26570; Directorate Identifier 2006-NE-39-AD]

RIN 2120-AA64

Airworthiness Directives; Turbomeca S.A. Makila 1A and 1A1 Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

The back-up mode can be activated by an electrostatic discharge or by a malfunction of the collective pitch signal. The two engines fitted on the same helicopter can therefore be frozen in this back-up position at 85% N1.

Freezing both engines in the back-up mode can lead to an inability to continue safe flight and forced landing. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI. **DATES:** We must receive comments on this proposed AD by January 18, 2007. **ADDRESSES:** You may send comments by any of the following methods:

• DOT Docket Web Site: Go to http://dms.dot.gov and follow the instructions for sending your comments electronically.

• Fax: (202) 493-2251.

• *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL–401, Washington, DC 20590– 0001. • *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

• Federal eRulemaking Portal: http:// www.regulations.gov. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at *http://dms.dot.gov*; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647– 5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Christopher Spinney, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park 01803; telephone (781) 238–7175; fax (781) 238–7199.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the Federal Register Vol. 71, No. 243 Tuesday, December 19, 2006

ADDRESSES section. Include "Docket No. FAA–2006–26570; Directorate Identifier 2006–NE–39–AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to *http:// dms.dot.gov*, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the airworthiness authority for the European Union, has issued EASA Airworthiness Directive 2006–0070, dated April 13, 2006, (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

The control system of the engines covered by this Airworthiness Directive includes an electrical back-up mode at 85% N1 (gas generator speed) activated on the detection of certain occurrences affecting engine control. The activation of the back-up mode is irreversible and freezes the engine at 85% N1.

An analysis of reported occurrences in service showed that the back-up mode can be activated by an electrostatic discharge or by a malfunction of the collective pitch signal. The two engines fitted on the same helicopter can therefore be frozen in this back-up position at 85% N1.

The present Airworthiness Directive therefore imposes the application of modification TU241 on the LPG board of the Makila 1A and 1A1 ECU, which reduces the aforementioned risk by changing the conditions in which the engines switch to and are maintained in the 85% NG back-up mode.

Freezing both engines in the back-up mode can lead to an inability to continue safe flight and forced landing.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Turbomeca has issued Mandatory Service Bulletin No. 298 73 0241, dated April 5, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information provided by the State of Design Authority and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are described in a separate paragraph of the proposed AD. These requirements, if ultimately adopted, will take precedence over the actions copied from the MCAI.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about five products of U.S. registry. We also estimate that it would take about 1.0 work-hours per product to comply with this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$3,500 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$17,900, or \$3,580 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;

2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Turbomeca S.A.: Docket No. FAA–2006– 26570; Directorate Identifier 2006–NE– 39–AD.

Comments Due Date

(a) We must receive comments by January 18, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Turbomeca Makila 1A and 1A1 turboshaft engines. These engines are used on, but not limited to Eurocopter AS 332 Super Puma helicopters.

Reason

(d) European Aviation Safety Agency (EASA) AD No. 2006–0070, dated March 30, 2006, states:

The control system of the engines covered by this Airworthiness Directive includes an electrical back-up mode at 85% N1 (gas generator speed) activated on the detection of certain occurrences affecting engine control. The activation of the back-up mode is irreversible and freezes the engine at 85% N1.

An analysis of reported occurrences in service showed that the back-up mode can be activated by an electrostatic discharge or by a malfunction of the collective pitch signal. The two engines fitted on the same helicopter can therefore be frozen in this back-up position at 85% N1.

The present Airworthiness Directive therefore imposes the application of modification TU241 on the LPG board of the Makila 1A and 1A1 ECU, which reduces the aforementioned risk by changing the conditions in which the engines switch to and are maintained in the 85% NG back-up mode.

Freezing both engines in the back-up mode can lead to an inability to continue safe flight and forced landing.

Actions and Compliance

(e) Unless already done, before January 31, 2007, apply the modification TU 241 by replacing the LPG board of the ECU in accordance with the mandatory Turbomeca Service Bulletin No. 298 73 0241, dated April 5, 2006.

FAA AD Differences

(f) None.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Engine Certification Office, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection

requirements and has assigned OMB Control Number 2120–0056.

Related Information

(h) Contact Christopher Spinney, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park 01803; telephone (781) 238–7175; fax (781) 238– 7199 for more information about this AD.

(i) Refer to MCAI EASA Airworthiness Directive 2006–0070, dated March 30, 2006, and Turbomeca Mandatory Service Bulletin No. 298 73 0241, dated April 5, 2006, for related information.

Issued in Burlington, Massachusetts, on December 13, 2006.

Peter A. White,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service. [FR Doc. E6–21586 Filed 12–18–06; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Highway Administration

23 CFR Part 630

[FHWA Docket No. FHWA-2006-25203] RIN 2125-AF10

Temporary Traffic Control Devices

AGENCY: Federal Highway Administration (FHWA), DOT. **ACTION:** Notice of proposed rulemaking; extension of comment period.

SUMMARY: The FHWA is extending the comment period for a notice of proposed rulemaking (NPRM) and request for comments, which was published on November 1, 2006, at 71 FR 64173. The original comment period is set to close on January 2, 2007. The extension is based on concern expressed by the National Committee on Uniform Traffic Control Devices (NCUTCD) that the January 2 closing date does not provide sufficient time for discussion of the issues in committee and a subsequent comprehensive response to the docket. The FHWA recognizes that others interested in commenting may have similar time constraints and agree that the comment period should be extended. Therefore, the closing date for comments is changed to February 16, 2007, which will provide the NCUTCD and others interested in commenting additional time to discuss, evaluate, and submit responses to the docket.

DATES: Comments must be received on or before February 16, 2007.

ADDRESSES: Mail or hand deliver comments to the U.S. Department of Transportation, Dockets Management Facility, Room PL–401, 400 Seventh

Street, SW., Washington, DC 20590, or submit electronically at http:// *dmses.dot.gov/submit* or fax comments to (202) 493-2251. Alternatively, comments may be submitted via the Federal eRulemaking Portal at http:// www.regulations.gov. All comments should include the docket number that appears in the heading of this document. All comments received will be available for examination at the above address from 9 a.m. to 5 p.m. e.t., Monday through Friday, except Federal holidays. Those desiring notification of receipt of comments must include a selfaddressed, stamped postcard or print the acknowledgement page that appears after submitting comments electronically. Anyone is able to search the electronic form of all comments received into any of our dockets by the name of the individual submitting the comment (or signing the comment, if submitted on behalf of an association. business, labor union, etc.). Persons making comments may review DOT's complete Privacy Act Statement in the Federal Register published on April 11, 2000 (Volume 65, Number 70, Pages 19477–78) or may visit http:// dms.dot.gov.

FOR FURTHER INFORMATION CONTACT: Mr. Chung Eng, Office of Transportation Operations, (202) 366–8043; or Mr. Raymond W. Cuprill, Office of the Chief Counsel, (202) 366–0791, U.S. Department of Transportation, Federal Highway Administration, 400 Seventh Street, SW., Washington, DC 20590. Office hours are from 7:45 a.m. to 4:15 p.m. e.t., Monday through Friday, except Federal holidays.

SUPPLEMENTARY INFORMATION:

Electronic Access and Filing

You may submit or retrieve comments online through the Document Management System (DMS) at: *http:// dmses.dot.gov/submit.* The DMS is available 24 hours each day, 365 days each year. Electronic submission and retrieval help and guidelines are available under the help section of the Web site.

An electronic copy of this document may also be downloaded from the Office of the Federal Register's home page at: http://www.archives.gov and the Government Printing Office's Web page at: http://www.access.gpo.gov/nara.

Background

On November 1, 2006, the FHWA published in the **Federal Register** an NPRM that proposes to supplement its regulation governing work zone safety and mobility in highway and street work zones. The NPRM proposes to include conditions for the appropriate use of, and expenditure of funds for, uniformed law enforcement officers, positive protective measures between workers and motorized traffic, and installation and maintenance of temporary traffic control devices during construction, utility, and maintenance operations. The proposed changes are intended to decrease the likelihood of fatalities and injuries to workers who are exposed to motorized traffic (vehicles using the highways for the purposes of travel) while working on Federal-aid highway projects.

The original comment period for the NPRM closes on January 2, 2007. The NCUTCD has expressed concern that this closing date does not provide sufficient time to review and discuss the proposed changes; and then, develop and submit complete responses to the docket. To allow time for this organization and others to submit comprehensive comments, the closing date is changed from January 2, 2007, to February 16, 2007.

Authority: 23 U.S.C. 109(c) and 112; Sec. 1110 of Pub. L. 109–59; 23 CFR 1.32; and 49 CFR 1.48(b).

Issued on: December 12, 2006.

J. Richard Capka,

Federal Highway Administrator. [FR Doc. E6–21579 Filed 12–18–06; 8:45 am] BILLING CODE 4910-22–P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-125632-06]

RIN 1545-BF83

Corporate Reorganizations; Distributions Under Sections 368(a)(1)(D) and 354(b)(1)(B)

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Notice of proposed rule making by cross-reference to temporary regulations.

SUMMARY: In the Rules and Regulations section of this issue of the **Federal Register**, the IRS is issuing temporary regulations that provide guidance regarding the qualification of certain transactions as reorganizations described in section 368(a)(1)(D) where no stock and/or securities of the acquiring corporation is issued and distributed in the transaction. These regulations affect corporations engaging in such transactions and their