

New Requirements of This AD*Terminating Action—Installation of New, Improved Part*

(l) Within 9 months after the effective date of this AD, install horizontal stabilizer trim control unit (HSTCU), part number (P/N) 601R92301-15 (vendor P/N 7060-10) or higher dash number, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A604-27-029, dated September 28, 2006 (for Model CL-600-2B16 (CL-604) airplanes); or Bombardier Service Bulletin 601R-27-147, dated September 28, 2006 (for Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes); as applicable. After doing the installation, the AFM revisions required by paragraph (f) of this AD may be removed from the applicable AFM, and the circuit breaker identification collars required by paragraph (h) of this AD may be removed. After doing the installation, the AFM revision required by paragraphs (i) and (j) of this AD may also be removed from the AFM but operators should note that the functional check of the stabilizer trim system on the airplane's first flight of the day, as described in the AFM, must still be done.

Note 4: Bombardier Service Bulletin 601R-27-147, dated September 28, 2006, refers to Sagem Service Bulletin HSTCU-27-011, dated September 22, 2006, as an additional source of service information for accomplishment of the installation.

Service Bulletin Exception

(m) Although Bombardier Alert Service Bulletin A604-27-029, dated September 28, 2006, specifies to return certain parts to the manufacturer, this AD does not include that requirement.

Alternative Methods of Compliance (AMOCs)

(n)(1) The Manager, New York Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(o) Canadian airworthiness directives CF-2006-20R1, dated October 4, 2006, and CF-2006-21R1, dated October 3, 2006, also address the subject of this AD.

Issued in Renton, Washington, on November 6, 2006.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E6-19798 Filed 11-21-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2006-26236; Directorate Identifier 2006-CE-66-AD]

RIN 2120-AA64

Airworthiness Directives; SOCATA—Groupe AEROSPATIALE Models TB 20 and TB 21 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as reports of interference between the wing spar lower boom and the wheel fairing attaching screw. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by December 22, 2006.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the

Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:**Streamlined Issuance of AD**

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. The streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2006-26236; Directorate Identifier 2006-CE-66-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No.: 2006-0123, dated May 16, 2006 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified

products. The MCAI states there are reports of interference between the wing spar lower boom and the wheel fairing attaching screw causing an unsafe condition. The interference could, if left uncorrected, reduce the fatigue life of the wing spar with potentially catastrophic results. The MCAI requires inspections and repairs as necessary to correct this unsafe condition. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

EADS SOCATA has issued TB Aircraft Mandatory Service Bulletin SB 10-148, ATA No. 57, dated December 2005. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are described in a separate paragraph of the proposed AD. These requirements, if ultimately adopted, will take precedence over the actions copied from the MCAI.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 270 products of U.S. registry. We also estimate that it would take about 15 work-hours per product to comply with the proposed AD. The

average labor rate is \$80 per work-hour. Required parts would cost about \$15,000 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$4,374,000, or \$16,200 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

SOCATA—Groupe Aerospatiale: Docket No. FAA-2006-26236; Directorate Identifier 2006-CE-66-AD.

Comments Due Date

(a) We must receive comments by December 22, 2006.

Affected ADs

(b) None.

Applicability

(c) This AD applies to SOCATA Models TB 20 and TB 21 airplanes, serial numbers 1 through 9999 without repair REP 20.031 implemented on both sides, certificated in any category.

Reason

(d) The mandatory continuing airworthiness information (MCAI) states there are reports of interference between the wing spar lower boom and the wheel fairing attaching screw causing an unsafe condition. The interference could, if left uncorrected, reduce the fatigue life of the wing spar with potentially catastrophic results. The MCAI requires inspections and repairs as necessary to correct this unsafe condition.

Actions and Compliance

(e) Unless already done, do the following actions.

(1) Within the next 100 hours time-in-service or 12 months after the effective date of this AD, whichever occurs first, perform an inspection of the wing spar lower boom and repair it as necessary, in accordance with the accomplishment instructions of the EADS SOCATA TB Aircraft Mandatory Service Bulletin SB 10-148, ATA No. 57, dated December 2005.

(2) If defect dimensions exceed the acceptable values given in the EADS SOCATA TB Aircraft Mandatory Service Bulletin SB 10-148, ATA No. 57, dated December 2005, or if the defect is not located in areas depicted in figure 2 of the EADS SOCATA TB Aircraft Mandatory Service Bulletin SB 10-148, ATA No. 57, dated December 2005, then the Type 1 or Type 2 repair solutions are not applicable. A written report shall be sent to the manufacturer as mentioned in section A.5 of the EADS

SOCATA TB Aircraft Mandatory Service Bulletin SB 10-148, ATA No. 57, dated December 2005. In this case, all flight is prohibited until EADS SOCATA provides a repair solution or otherwise agrees to further flight.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(f) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Staff, FAA, ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(g) Refer to European Aviation Safety Agency (EASA) Airworthiness Directive No.: 2006-0123, dated May 16, 2006; and EADS SOCATA TB Aircraft Mandatory Service Bulletin SB 10-148, ATA No. 57, dated December 2005, for related information.

Issued in Kansas City, Missouri, on November 14, 2006.

Steven W. Thompson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-19801 Filed 11-21-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-140379-02; REG-142599-02]

RIN 1545-BC07; 1545-BB23

General Allocation and Accounting Regulations Under Section 141; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Correction to notice of proposed rulemaking and notice of public hearing.

SUMMARY: This document contains corrections to a notice of proposed rulemaking and notice of public hearing that was published in the **Federal Register** on Tuesday, September 26, 2006 (71 FR 56072) relating to the allocation of, and accounting for, tax-exempt bond proceeds for purposes of the private activity bond restrictions that apply under section 141 of the Internal Revenue Code (Code) and that apply in modified form to qualified 501(c)(3) bonds under section 145 of the Code.

FOR FURTHER INFORMATION CONTACT: Johanna Som Som de Cerff (202) 622-3980 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

The notice of proposed rulemaking and notice of public hearing (REG-140379-02; REG-142599-02) that is the subject of these corrections are under section 141 of the Internal Revenue Code.

Need for Correction

As published, the notice of proposed rulemaking and notice of public hearing (REG-140379-02; REG-142599-02) contains errors that may prove to be misleading and are in need of clarification.

Correction of Publication

Accordingly, the notice of proposed rulemaking and notice of public hearing (REG-140379-02; REG-142599-02) that was the subject of FR Doc. 06-8202 is corrected as follows:

1. On page 56074, column 1, in the preamble under the paragraph heading, "Explanation of Provisions", first paragraph of the column, line 5 from the bottom of the paragraph, the language "uses, for example, governmental use and" is corrected to read "uses, that is, governmental use and".

§ 1.141-6 [Corrected]

2. On page 56080, column 3, § 1.141-6(d)(4)(i), line 18, the language "in this paragraph (d)(4)(ii) of this" is corrected to read "in paragraph (d)(4)(ii) of this".

La Nita VanDyke,

Chief, Publications and Regulations Branch, Legal Processing Division, Office of Associate Chief Counsel, (Procedure and Administration).

[FR Doc. E6-19789 Filed 11-21-06; 8:45 am]

BILLING CODE 4830-01-P

LIBRARY OF CONGRESS

Copyright Office

37 CFR Part 201

[Docket No. RM 2005-5]

Retransmission of Digital Broadcast Signals Pursuant to the Cable Statutory License

AGENCY: Copyright Office, Library of Congress.

ACTION: Notice of Inquiry.

SUMMARY: The Copyright Office is extending the time in which reply comments can be filed in response to its Notice of Inquiry regarding the retransmission of digital television broadcast signals by cable operators under the Copyright Act.

DATES: Reply Comments are due no later than December 18, 2006.

ADDRESSES: If hand delivered by a private party, an original and five copies of a comment or reply comment should be brought to Library of Congress, U.S. Copyright Office, 2221 S. Clark Street, 11th Floor, Arlington, Va. 22202, between 8:30 a.m. and 5 p.m. The envelope should be addressed as follows: Office of the General Counsel, U.S. Copyright Office.

If delivered by a commercial courier, an original and five copies of a comment or reply comment must be delivered to the Congressional Courier Acceptance Site ("CCAS") located at 2nd and D Streets, NE, Washington, D.C. between 8:30 a.m. and 4 p.m. The envelope should be addressed as follows: Office of the General Counsel, U.S. Copyright Office, LM 430, James Madison Building, 101 Independence Avenue, SE, Washington, DC. Please note that CCAS will not accept delivery by means of overnight delivery services such as Federal Express, United Parcel Service or DHL.

If sent by mail (including overnight delivery using U.S. Postal Service Express Mail), an original and five copies of a comment or reply comment should be addressed to U.S. Copyright Office, Copyright GC/I&R, P.O. Box 70400, Southwest Station, Washington, DC 20024.

FOR FURTHER INFORMATION CONTACT: Ben Golant, Senior Attorney, and Tanya M. Sandros, Associate General Counsel, Copyright GC/I&R, P.O. Box 70400, Southwest Station, Washington, DC 20024. Telephone: (202) 707-8380. Telefax: (202) 707-8366.

SUPPLEMENTARY INFORMATION: On September 20, 2006, the Copyright Office initiated a proceeding to address