

(a) For engines that have been modified to TU 197 standard, but have not been modified to TU 191 or TU 224 standard, do the following:

(1) Remove modification TU 197 and install modification TU 224 in accordance with Turmo IV SB 249 72 0117, dated March 11, 2000, within the next 50 cycles or six months after the effective date of the AD, whichever occurs first.

(2) Within 1,000 flight hours (FH) after the installation of modification TU 224 standard, do the following:

(i) Perform a visual inspection and an ultrasonic inspection (USI) in accordance with paragraph 2.B.(3) of Turbomeca Turmo IV SB 249 72 0100, Update 4, dated January 25, 2000.

(ii) Thereafter, perform a visual inspection and a USI at intervals not to exceed 1,000 FH in accordance with paragraph 2.B.(3) of Turbomeca Turmo IV SB 249 72 0100, Update 4, dated January 25, 2000.

(b) For engines that have not been modified to TU 191, TU 197, or TU 224 standard, do the following in accordance with Turbomeca Turmo IV SB 249 72 0100, Update 4, dated January 25, 2000:

(1) For centrifugal compressor intake wheels that, on the effective date of this AD, have been operated for more than 250 FH since the last inspection of the centrifugal compressor intake wheel blades, do the following:

(i) Perform an initial borescope inspection of the blades for evidence of corrosion within the next 50 FH, or six months after the effective date of this AD, whichever occurs first, in accordance with paragraph 2.B.(1) of the SB.

(ii) If corrosion is found, perform an ECI or USI, as applicable, of the blades for cracks within 50 FH after the borescope inspection performed in accordance with paragraph 2.B.(3) of the SB, and if necessary, replace with serviceable parts.

(iii) If corrosion is not found, perform an ECI or USI, as applicable, of the blades for cracks within 250 FH after the borescope inspection performed in accordance with paragraph (b)(1)(i) of this AD, and if necessary, replace with serviceable parts.

(iv) Thereafter, perform borescope inspections and ECI's or USI's, as applicable, of the blades for cracks and evidence of corrosion, alternating at intervals not to exceed 250 FH since the last inspection.

(v) Remove from service centrifugal compressor intake wheels found cracked and replace with serviceable parts.

(2) For centrifugal compressor intake wheels that, upon the effective date of this AD, have been operated for less than or equal to 250 FH since the last inspection of the blades, do the following:

(i) Perform an initial borescope inspection of the blades for evidence of corrosion prior to accumulating 250 FH since the last inspection of the blades in accordance with paragraph 2.B.(1) of the SB.

(ii) If corrosion is found, perform an ECI or USI, as applicable, of the blades for cracks, and, if necessary, replace with serviceable parts, within 50 FH after the borescope inspection performed in accordance with paragraph 2.B.(3) of the SB.

(iii) If corrosion is not found, perform an ECI or USI, as applicable, of the blades for cracks, and, if necessary, replace with serviceable parts, within 250 FH after the borescope inspection performed in accordance with paragraph (b)(2)(i) of this AD.

(iv) Thereafter, perform borescope inspections and ECI's or USI's, as applicable, of the blades for cracks and evidence of corrosion, alternating at intervals not to exceed 250 FH since the last inspection.

**Note 2:** Alternating intervals means that if the last inspection was an ECI or a USI, the next inspection will be a borescope inspection. If the last inspection was a borescope inspection, the next 250 FH inspection will be an ECI or a USI as applicable.

(v) Remove from service centrifugal compressor intake wheels found cracked and replace with serviceable parts.

(c) For engines not modified to TU 197 but have been modified to TU 191 or TU 224 standard, that have been operated for more than 1,000 flight hours since the last inspection of the blades, do the following in accordance with Turbomeca Turmo IV SB 249 72 0100, Update 4, dated January 25, 2000:

(1) Perform an initial ECI or USI, as applicable, of the blades for cracks, in accordance with paragraph 2.B.(3) of the SB, within the next 50 FH, or 6 months after the effective date of this AD, whichever occurs first.

(2) Thereafter, inspect at intervals not to exceed 1,000 FH.

(3) Remove from service centrifugal compressor intake wheels found cracked, and replace with a serviceable part

#### Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators must submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

#### Special Flight Permits

(f) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be done.

**Note 4:** The subject of this AD is addressed in Direction Generale de L'Aviation Civile airworthiness directive AD97-122(B), dated May 21, 1997.

Issued in Burlington, Massachusetts, on November 21, 2002.

**Jay J. Pardee,**

*Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 02-30351 Filed 11-29-02; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2002-NE-10-AD]

RIN 2120-AA64

#### Airworthiness Directives; Rolls-Royce plc Model RB211-22B Turbofan Engines

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The Federal Aviation Administration (FAA) proposes to adopt a new airworthiness directive (AD) that is applicable to Rolls-Royce plc (RR) model RB211-22B turbofan engines with intermediate pressure (IP) compressor stage 6 to 7 rotor shaft assembly part number (P/N) UL37094 installed. This proposal would require removal from service of IP compressor stage 6 to 7 rotor shaft assemblies P/N UL37094 before reaching newly reduced life limits. This proposal is prompted by the discovery of corrosion during inspection and analysis of IP compressor stage 6 to 7 rotor shaft assemblies returned from the field. The actions specified by the proposed AD are intended to prevent corrosion-induced cracking of the IP compressor stage 6 to 7 rotor shaft assembly, resulting in an uncontained engine failure and damage to the airplane.

**DATES:** Comments must be received by January 31, 2003.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2002-NE-10-AD, 12 New England Executive Park, Burlington, MA 01803-5299. Comments may be inspected at this location, by appointment, between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. Comments may also be sent via the Internet using the following address: "9-ane-adcomment@faa.gov". Comments sent via the Internet must contain the docket number in the subject line.

Information regarding this action may be examined, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

**FOR FURTHER INFORMATION CONTACT:**

Keith Mead, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299, telephone (781) 238-7744; fax (781) 238-7199.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NE-10-AD." The postcard will be date stamped and returned to the commenter.

**Availability of NPRM's**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2002-NE-10-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

**Discussion**

The manufacturer has recently analyzed the conditions of some IP compressor stage 6 to 7 rotor shaft assemblies, P/N 37094, that were returned from the field, and has determined that rotor shafts of this part number are unable to achieve currently

published life limits. This is due to the potential for corrosion-induced cracking to occur at these published life limits. As a result of this analysis, new lower life limits have been assigned to this P/N IP compressor stage 6 to 7 rotor shaft assembly. This condition, if not corrected, could result in corrosion-induced cracking of the IP compressor stage 6 to 7 rotor shaft assembly, resulting in an uncontained engine failure and damage to the airplane.

**Proposed Requirements of this AD**

Since an unsafe condition has been identified that is likely to exist or develop on other RR model RB211-22B turbofan engines of the same type design that are used on airplanes registered in the United States, the proposed AD would require removing from service IP compressor stage 6 to 7 rotor shaft assemblies, P/N UL37094, before reaching new reduced life limits. The life limits are established based on whether or not the engine has incorporated service bulletin (SB) RR SB 72-8700. That SB increases the engine thrust rating.

**Economic Analysis**

The FAA estimates that one engine installed on aircraft of U.S. registry would be affected by this proposed AD. The FAA also estimates that no additional labor cost will be incurred to remove the affected part, which will be at time of engine shop visit. Required parts would cost approximately \$33,150 per engine, based on a part life reduction estimate. Based on these figures, the total cost of the proposed AD to U.S. operators is estimated to be \$33,150.

**Regulatory Analysis**

This proposed rule does not have federalism implications, as defined in Executive Order 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this proposed rule.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory

Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Safety.

**The Proposed Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Rolls-Royce plc:** Docket No. 2002-NE-10-AD.

*Applicability:* This airworthiness directive (AD) is applicable to Rolls-Royce (RR) model RB211-22B turbofan engines with intermediate pressure (IP) compressor stage 6 to 7 rotor shaft assembly part number (P/N) UL37094 installed. These engines are installed on, but not limited to Lockheed Martin L1011 airplanes.

**Note 1:** This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

*Compliance:*

Compliance with this AD is required as indicated, unless already done.

To prevent corrosion-induced cracking of the IP compressor stage 6 to 7 rotor shaft assembly, resulting in an uncontained engine failure and damage to the airplane, do the following:

(a) For engines that have not incorporated RR service bulletin (SB) 72-8700, remove IP compressor stage 6 to 7 rotor shaft assemblies from service before accumulating 13,500 cycles-since-new (CSN).

(b) For engines that have incorporated RR service bulletin (SB) 72-8700, remove IP compressor stage 6 to 7 rotor shaft assemblies from service before accumulating 12,980 cycles-since-new (CSN).

(c) After the effective date of this AD, do not install any IP compressor stage 6 to 7 rotor shaft assembly, P/N UL37094, that has accumulated the CSN specified in paragraph (a) or (b) of this AD.

#### Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators must submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

#### Special Flight Permits

(e) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be done.

Issued in Burlington, Massachusetts, on November 20, 2002.

**Jay J. Pardee,**

*Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 02-30350 Filed 11-29-02; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2002-NM-55-AD]

RIN 2120-AA64

#### **Airworthiness Directives; Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200F, 747-200C, 747-300, 747-400, 747-400D, 747-400F, and 747SR Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the superseding of an existing airworthiness directive (AD), applicable to certain Boeing Model 747 series airplanes, that currently requires inspections for cracking of the forward end clevis lugs of the flap track, and replacement of the flap track with a new flap track, if necessary. That AD also provides for an optional modification of the forward

end clevis lugs, which terminates the required inspections. This action would expand the applicability of the existing AD, and would require new repetitive inspections for evidence of rotation or migration of the bushings or cracking of the lugs of the forward end clevis of the flap tracks that support the wing trailing edge flaps, and corrective actions if necessary. This action also would require an eventual terminating action. This action is necessary to prevent cracking and fracture of the forward end clevis of the flap track, which could result in reduced structural capability of the flap and reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

**DATES:** Comments must be received by January 16, 2003.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-55-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: [9-anm-nprmcomment@faa.gov](mailto:9-anm-nprmcomment@faa.gov). Comments sent via fax or the Internet must contain "Docket No. 2002-NM-55-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Tamara Anderson, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2771; fax (425) 227-1181.

#### **SUPPLEMENTARY INFORMATION:**

##### **Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications

received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.

- For each issue, state what specific change to the proposed AD is being requested.

- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-55-AD." The postcard will be date-stamped and returned to the commenter.

#### **Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-55-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

#### **Discussion**

The FAA has previously issued AD 90-24-09, amendment 39-6815 (55 FR 48228, November 20, 1990), applicable to certain Boeing Model 747 series airplanes. That AD requires inspections of the forward end clevis lugs of the flap track, and replacement of the flap track with a new flap track, if necessary. That AD also provides for an optional modification of the forward end clevis lugs, which terminates the required inspections. That action was prompted by reports of cracked or failed clevis lugs on two flap tracks. The requirements of that AD are intended to prevent separation of the wing trailing edge flap track from the airplane and reduction in the controllability of the airplane.