

:

TWR- 17591 VOL. VII ECS #: SS 1004

÷

QM-8 Field Joint Protection System Final Report Volume 7

June 1989

Prepared for:

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION **GEORGE C. MARSHALL SPACE FLIGHT CENTER** MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812

Contract No. NAS8-30490 DR. No. 5-3 WBS No. HQ302-10-10

MORTON THIOKOL, INC.

Space Division

P.O. Box 524, Brigham City, Utah 84302 (801) 863 3511

FORM TC 4677 (REV 8-86)

N90-13586 (NASA-CR-183748) QM-8 FIELD JOINT PROTECTION SYSTEM, VOLUME 7 Final Report (Morton Thiokol) CSCL 21H 23 p

Unclas

0231739 G3/20

MORTON THIOKOL, INC.

Space Operations

1.0

TWR-17591 VOL. VII QM-8 FIELD JOINT PROTECTION SYSTEM FINAL REPORT VOLUME 7 FINAL REPORT

PREPARED BY:

-1.0 ELGTE HALE

ELGIE HALE COMPÓNENT DESIGN

APPROVED BY:

JOHN E. OOSTYEN, SUPERVISOR COMPONENT DESIGN SECTION

5/23/59

JAMES SEILER PROJECT ENGINEERING

GDEN 5/23/89

TED OLSON CERTIFICATION PLANNING

6:

GARY STEPHENS PROGRAM MANAGER

m the R.K. WILKS, MANAGER

COMPONENTS

110 Jacober 4.775%

RON LARŚEN SAFETY

STEVE WEST

RELIABILITY

INSULATION DESIGN

PC Judick 6-19-89 RELEASE

DOC NO	TWR-17591		νοι	VII
SEC	PAGE			
		i		

REVISION

MORTON THIOKOL. INC.

Space Operations

3

ACRONYMS

DODY		c _1; d	Declet	Motor
RSRM	Redesigned	50110	ROCKEL	MOLOI
RTD	Resistance	Temper	ature	Device



REVISION

MORTON THIOKOL, INC Aerospace Group Space Operations ABSTRACT

.

This report contains the pre-launch functioning data of the Field Joint Protection System (JPS) used on QM-8. Also included is the post fire condition of the JPS components following the test firing of the motor. The JPS components are:

- 1. Field Joint Heaters
- 2. Field Joint Sensors
- 3. Field Joint Moisture Seal
- 4. Moisture Seal Kevlar Retaining Straps
- 5. Field Joint External Extruded Cork Insulation
- 6. Vent valve
- 7. Power Cables
- 8. Igniter Heater



REVISION ____

MORTON	THIOKOL.	INC

Aerospace Group

Space Operations

1.0 INTRODUCTION

Qualification Motor (QM) 8 was test fired on 20 January 1989. The three field joints of the motor were protected by the Joint Protection Systems (JPS). See Figure 1. The JPS heaters were turned on prior to the test firing to assure the joint O-ring temperature was between 85 and 122 degrees F at the time of ignition. The purpose of the moisture seal is to prevent entry of rain into the joint. The cork insulation provides thermal protection for the JPS during flight.

2.0 OBJECTIVES

The objective of this report is to document the performance of the JPS heaters and the post fire condition of the JPS components.

The following objectives of CTP-0038 are addressed in this report: (Numbers in parentheses identify CEI specification paragraphs)

- BE. Certify the igniter heater maintains the igniter gasket rubber seal at the required temperature (3.2.1.5.3)
- BL. Certify the ability of the field joint heater assembly to maintain the temperature of the field joints (3.2.1.11.a)
- BR. Certify the reliability of the RSRM design
 (3.2.3)

 $\frac{NG}{DEC} = TWR - 17591 - \frac{1}{PAGE} = \frac{1}{1} \cdot \frac{OL}{VII}$

REVISION _____

MORTON THIOKOL. INC.

Aerospace Group

ī.

Space Operations

BU. Certify that the shedding of external debris is precluded (3.2.6.5)

3.0 CONCLUSIONS AND RECOMMENDATIONS

Maintain Field Joint Temperature

The JPS heaters performed per specification and maintained the field joint temperatures within the required temperature range at the time of motor ignition (3.2.1.11.a).

Reliability of the RSRM Design

The JPS system performed its intended function without failure (3.2.3)

Shedding of External Debris is Precluded

All components of the JPS system remained bonded in place during the test. No debris was generated (3.2.6.5)

Maintain Ignitor Gasket Seals Temperature

The igniter heater performance was nominal (3.2.1.5.3)

- 4.0 RESULTS/DISCUSSIONS
- 4.1 Pre-Fire Performance
- 4.1.1 Field Joint Heater System

The heater temperature control system operated as predicted and maintained the temperature at the controlling

	1676				
REVISION	Nº 1	TWR-17591		. L. 19.	VII
	54 7 .		-AGI	2	
EORM TC 7994 310 (REV 2 88)				1_	

MORTON THIOKOL, INC.

Aerospace Group

Space Operations

RTD at 86° with a maximum deviation of -0.6° to +0.5°. The four temperature sensors at each field joint were continuously monitored and the coldest sensor was manually selected for temperature control. Figure 2 is a plot of the temperature of the controlling RTD of the three field joints. The drop in temperature at 0600 and 1000 hours was due to heater power shut off.

4.1.2 Igniter Heater System

The Igniter Heater was turned on at T-12 hours. Temperatures at the sensors was maintained at 78 plus or minus 1 degree F. Igniter heater was shut down at T-2 minutes.

4.2 POST-TEST INSPECTION

4.2.1 FJPS External Insulation

Post-test inspection was conducted prior to FJPS removal from the motor no evidence of damage was observed. See Table 1 for pre-dissasembly evaluation worksheet. All the cork appeared to be intact and bonded to the case. After the cork was stripped from the case, the bondlines were inspected for voids.

Voids were found in the leading edge cork insulation to case bondlines of all joints. These were attribuied to improperly positioning of the cork during installation and from insufficient adhesive. The improper positioning of the cork occurred with one piece of cork on the center joint. This cork was installed 1/2 inch forward of it's intended position on the moisture seal, resulting in



REVISION _____

MORTON THIOKOL INC.

Aerospace Group

Space Operations

a long narrow void between the leading edge of the moisture seal and the cork. Some of the voids resulting from insufficient adhesive extended to the leading edge of the cork. See Table 2 through 4 evaluation worksheet.

4.2.2 EPDM Moisture Seal-to-Cork Bondlines

To inspect this bondline, the moisture seal had to be peeled off the cork with considerable force. The peeled surfaces showed that the EA 934NA remained on the cork with small black EPDM particles embedded in the adhesive surface, indicating the EPDM to EA 934NA interface is the weaker of the bond surfaces.

4.2.3 Kevlar Strap-to-Cork Bondline

This bondline was difficult to peel back. In some areas, the EA 934NA was embedded in both the inside and outside straps, especially where the pin retainer band trunnions lift the Kevlar strap and allow adhesive to flow underneath the band.

4.2.4 Moisture Seal Condition

The moisture seals showed no evidence of rips or tears in the areas where the pin retainer trunnions contact the moisture seal. However, because of the excellent bond between the EA934NA and the moisture seal, an occasional piece of the moisture seal was ripped up during disassembly. See Table 5 for the evaluation worksheets.

<u>TWR-17591</u> <u>AGF 4</u> VII

REVISION _____

MORTON THIOKOL, INC.

Aerospace Group

Space Operations

4.2.5 Kevlar Strap Condition

The straps were fully intact. There was no evidence of fiber damage or adhesive cracking at the buckle interfaces. The areas where the pin retainer trunnions raise the strap showed no fiber distortion or breakage and had adhesive underneath forming a smooth surface for the Kevlar strap to ride on.

4.2.6 JPS Heater

The heaters showed no evidence of delamination, cracking, or overheating. See Table 6 for evaluation worksheet.

4.2.7 JPS Sensor

The sensor could not be observed until after the cork insulation was removed. There were no anomalies such as cracking, except that which was caused by the removal of the cork insulation. See Table 6 for the evaluation worksheet.

4.2.8 Heater Cables

The heater cables were in excellent condition following the test. No voids are missing material, debonds, or charred material were found. Table 7 is the pre disassembly and Table 8 is the post disassembly worksheets for the heater cables.

 $\frac{N_{OL}}{SEC} TWR = 17591 - \frac{1.301}{1.34} VI \cdot I$

REVISION _____

MORTON THIOKOL, INC.

Aerospace Group

Space Operations 4.2.9 <u>Vent Valves</u>

One vent valve was installed on each of the three field joints at the 135° location. All three vent valves were open to back pressure following the test. See Table 9 for the evaluation worksheet.

4.2.10 Igniter Heater

During post fire inspection the igniter heater installation and components were inspected. Igniter heater, cork insulation, T-bolt latch band clamp, and heater power cables were intact and properly secured on the igniter adapter and forward dome with no anomalies noted. There was a .030 inch air gap approximately .50 inch long between the heater and case at the location of the clamp buckle, however, no buckling or warpping of the heater was noted. After removal of the igniter heater components the heater was carefully inspected. No discoloration, charring, warpping, or buckling of the heater was noted. See Tables 10 and 11 for the evaluation worksheet.



REVISION _____



.

•

TWR-17591 VOL. V11



Figure 2

TWR-17591 Vol. VII Page 8

۰.

	Field Joint External	Insulation Co	ndition - Eval	uation Checkoff W	orksheet P	re-disassembl
Inspector(s):	Elgie Hale		_			
Motor No.: Q	M-8				Date: 1/	23/89
Field Joint:	X Forward (FWD)	X Canter	(CTR) K	Aft (AFT)		
Component: J	IPS			······································		
I. External Co	ork Insulation			.		
A. Voids o	r Missing Material (TPS	VD)?		yes	х по	
B. Debond	s (DEBND)?			yes	no no	
C. Charred	I Material (HTAFF)?			yes	x no	
If any of the at	ove conditions exist, n	ote:				
	Axial	Starting	Ending			
Condition	Location	Degree	Degree	Circumferential	Axial	Radial
(Observation	(Station)	Location	Locátion	Width	Length	Depth
Code)	(ln.)	(Deg.)	(Deg.)	(In.)	(In.)	(In.)
<u></u> ,						
				- <u> </u>		
Notes / Comme	ents					
	. «					ł

Та	h	a	1	
۱a	v		1	

DOC NO.	TWR-17591			JCVII	
SEC	·	PAGE	9	-	

REV. ____

.

ORIGINAL PAGE IS OF POOR QUALITY

Table 2

Field Joint External Insulation Condition - Evaluation Checkoff Worksheet

Inspector(s):	Elgie Hale			· · · · · · · · · · · · · · · · · · ·		
Motor No.: QM-	8				Date: 1/2	23/89
Field Joint:	Forward (FWD)	🗌 Center		Aft (AFT)		
Component: Ji	PS	-				
I. External Cork Insulation A. Voids or Missing Material (TPSVD)? yes x no B. Debonds (DEBND)? x yes no C. Charred Material (HTAFF)? yes x no						
If any of the ab	ove conditions exist, no	te:				
	Axial	Starting	Ending			
Condition	Location	Degree	Degree	Circumferential	Axial	Radial
(Observation	(Station)	Location	Location	Width	Length	Depth
Code)	(in.)	(Deg.)	(Deg.)	(In.)	(In.)	(in.)
DEBONDS	851	118	122	. <u>5 case nex</u> t <u>t</u>	<u>o M.S.</u>	
<u>DEBONDS</u>	851	258	282	. <u>5 case next t</u>	o. M.S	
DEBONDS	851 -	298	30.2	4" leading_edg	e	
DEBONDS	851	308	311	<u>l" case next f</u>	o_M.S	

Notes / Comments

INtermittant smaller voids (less than I in. D) wre observed around the joint.

DOC NO.	TWR-17591	VCL	VTI
SEC	PAGE	C	

Inspector(s):	ELGIE HALE					
Motor No.:	QM-8				Date:	2/3/89
Field Joint:	Forward (FWD)	🛛 Center	(CTR)	Aft (AFT)		
Component:	JPS					
I. External C	Cork Insulation					·
A. Voids	or Missing Material (TPS	VD)?		ves	x no	
B. Debon	ds (DEBND)?		X	ves	no	
C. Charre	d Material (HTAFF)?			ves	x no	
				· · · · · · · · · · · · · · · · · · ·		
f any of the a	bove conditions exist, n	ote:				
	Axial	Starting	Ending			
Condition	Location	Degree	Degree	Circumferential	Axial	Radial
Observation	(Station)	Location	Location	Width	Length	Depth
Code)	(ln.)	(Deg.)	(Deg.)	(In.)	(In.)	(In.)
EBND		0°	6°	3		NA ,
EBND		270°	274°	3	3	NA
EBND		25°	28°	1/4	3	NA
EBND		54°	<u> </u>	3	12	NA
EBND		90°	105°	3	12	NA
FBND		<u>180°</u>	<u>184°</u>	3	4	NA

 Table
 3

 Field Joint External Insulation Condition - Evaluation Checkoff Workshoot



ORIGINAL PAGE IS OF POOR QUALITY

		-	Table 4			
	Field Joint Externa	I Insulation Co	ndition - Eval	uation Checkoff W	orksheet	
Inspector(s):	ELGTE HALE					
Motor No.:	QM-8				Date: 2/3	3/89
Field Joint:	Forward (FWD)	Center	(CTR)	Aft (AFT)		
Component: JI	PS					
I. External Co	rk Insulation					
A. Voids or	Missing Material (TP	SVD)?		Ves	x no	
B. Debonds	(DEBND)?	·		ves		
C. Charred	Material (HTAFF)?			yes	xno	
If any of the abo	ove conditions exist, r	note:				
	Axial	Starting	Ending			
Condition	Location	Degree	Degree	Circumferential	Axial	Radial
(Observation	(Station)	Location	Location	Width	Length	Depth
Code)	(ln.)	(Deg.)	(Deg.)	(In.)	(ln.)	(In.)
DEBND	1491	48	56		6	<u>N/A</u>
DEBND	1491	259	281	1/2	20	<u>N/A</u>
DEBND	1491	214	220	<u> </u>	16	N.'A
						
Notes / Commer	nts					
	•		,			

DOC NO. TWK-1759 VOL VII PAGE 12

.

2

Table 5	
Field Joint External Insulation Condition - Evaluation Checkoff	Worksheet

Inspector(s):	Elgie Hale/Mike Wal	Lsh			· • • • • • • • • • • • • • • • • • • •
Motor No.: QI	<u>1-8</u>	Comp	oonent: JPS	Date: 1	/23/89
Field Joint:	🗙 Forward	(FWD)	🛛 Center (CTR)	🛛 Aft (AF	т)
I. Moisture S	eal				
A. Discolor	ed (DSCLR)?		yes	<u> </u>	
B. Charred	Material (HTAFF)?		yes	<u> </u>	
C. Moisture	e Under Seal (WATER)?		yes	<u> </u>	
D. Loose R	letainer Band (LOOSE)?		yes	<u>x</u> no	
f any of the ab	ove conditions exist, no	ote:			
Affected		Starting Degree	Ending Degree	Circumferential	
Part	Condition	Location	Location	Width	Degree
(1, 01 11)	(Code)	(Deg.)	(Deg.)	(ln.)	Arc
				<u></u>	
		- <u></u>	·		<u> </u>
	-				
lotes / Comme	nts				
·					

REV. ____

Table 6 Joint Heater Condition – Evaluation Checkoff Worksheet

Inspector(s): Elg	jie Hale				
Motor No.: QM-8	<u>, , , , , , , , , , , , , , , , , , , </u>		Component: JPS	Date:	2/3/89
Field Joint:	X Forward	(FWD)	Center (CTR)	k Aft (/	AFT)
I. Heater Element					
A. Delamination	(DLHTR)?		yes	<u> x no</u>	
B. Adhesive to	Case Separation (DEBND)?	yes	<u> </u>	
C. Discoloration	(DSCLR)?		yes	<u> </u>	
II. Heater Sensor /	Assembly				
A. Evidence of	Separation (DEBN	D)?	yes	<u> </u>	
B. Delamination	is (DLHTR)?		yes	<u> </u>	
If any of the above	conditions exist, r	note:			
Affected		Starting Degre	e Ending Degre	e Circumferential	
Part	Condition	Location	Location	Width	Degree
(I, II or III)	(Code)	(Deg.)	(Deg.)	(ln.)	Arc
·····					
			• • • • • • • • • • • • • • • • • • •	· · · · · · · · · · · · · · · · · · ·	
<u> </u>		·			
				· · · · · · · · · · · · · · · · · · ·	······································
	<u></u>				
				· · · · · · · · · · · · · · · · · · ·	
Notes / Comments					
Notes / Comments					

DCC CM	TWR-17591		VOVII
SEC		PAGE	
		1.1	

REV. _____

ł

	Table	7 Post	Test
Field Joint Heate	r Cable Condition -	Evaluation Ch	eckoff Worksheet

Inspector(s):	Duane Hanson					
Motor No.: Q	M-8				Date:	1/1/89
Component: TPS	S			**====		
 External Cor A. Voids or B. Debonds C. Charred 	rk Insulation Missing Material (DEBND)? (HTAFF)?	(TPSVD)?		yes yes yes	<u>х</u> по <u>х</u> по <u>х</u> по	
II. Cables Debo	onded (DEBND)?			yes	<u>x</u> no	
If any of the abo	ove conditions exis	st, note:				
Segment (FWD, FCS, ACS or AFT)	Condition (Observation Code)	Axial Location (Station) (In.)	Starting Degree Location (Deg.)	Ending Degree Location (Deg.)	Circumferential Width (In.)	Axial Length (In.)
Notes / Commen	ts					

DOC NO	TWR-17591			VII
SEC		PAGE	15	

the states of th

×,

Janes -

-

ł

		Table	8	Pre-D	isassemb	1 y
Field Joint Hea	ter Cable	Condition	– Eva	luation	Checkoff	Worksheet

Inspector(s): Elgie Hale					
Motor No.: QM-8				Date: 1	/23/89
Component: TPS					
 External Cork Insulation A. Voids or Missing Mater B. Debonds (DEBND)? C. Charred (HTAFF)? 	al (TPSVD)?		yes yes yes	<u>х</u> по <u>х</u> по <u>х</u> по	
II. Cables Debonded (DEBND)	?		yes	<u> x no</u>	
If any of the above conditions	exist, note:				
Segment Condition (FWD, FCS, (Observation ACS or AFT) Code)	Axial Location (Station) (In.)	Starting Degree Location (Deg.)	Ending Degree Location (Deg.)	Circumferent:al Width (In.)	Axial Length (In.)
Notes / Comments					

REV. ____

DOC NO VOL VII TWR-17591 PAGE SEC 15

,

÷

Table 9						
Field Joint	Vent	Valve	-	Evaluation	Checkoff	Worksheet

Inspector(s): E. HALE		
Motor No.: QM-8		Date: 2/2/89
Field Joint: X Forward (FWD) Canter (CTR)	X Aft (AFT)	Case End: Tang
Component: JPS		
 Vent Valves Open to Back Pressure (VVOBP)? A. <u>45°</u> Degrees B. <u>135°</u> Degrees 	<u>N/A</u> yes <u>N/A</u> yes	no no
Notes / Comments		
The vent on each of the three field joints was	open to back pressure.	

DOC NO. vcWll TWR-17591 SEC PAGE 17

•

,

Table 10

Igniter Heater Installation Condition - Evaluation Checkoff Worksheet

Inspector(s): Charles (Greatwood				
Motor No.: QM-8					Date: 1/27/89
Joint: Igniter (IGN)	Case End:	Igniter Adapter	(FWD)		Component: JPS
I. Igniter Heater					
A. Securely held in place	e (LOOSE)?		yes	X	no
B. Proper position (DIS)	CP)?		yes	<u>X</u>	no
II. Cork Insulation					
A. Securely held in place	e (LOOSE)?		yes	<u> </u>	no
B. Proper position (DIS)	CP)?		yes	<u>X</u>	no
III. T-Bolt Latch Band Clam	P				
A. Securely held in plac	e (LOOSE)?		yes	<u> </u>	. ^{no}
B. Proper position (DIS)	CP)?		yes	<u> </u>	no .
IV. Igniter Heater Power Ca	bles				
A. Securely held in place	e (LOOSE)?		yes	<u>x</u>	no
B. Proper position (DIS)	CP)?		yes		no
If any of the above condition	ns exist, note:				
		Starting	Ending		
Affectea Con	aition	Degree	Degree	Circumfere	ntial Axial
Part (Obse	rvation	Location	Location	Width	Length
(I, II, III or IV) Co	de)	(Deg.)	(Deg.)	(In.)	(ln.)
			<u></u>		
	<u> </u>				
			<u> </u>		
Notes Comments		······			
Overall condition of ig	niter heater	installation	is excellent	: with no	anomalies noted.
					,
					:
		^			-

203 NC	TWR-1-591		VOL	VII
SEC		PAGE		
			18	

:

<u>Morton Thiokoi Inc.</u> Space Operations

47. 47.

Table 11						
Igniter Heater	Component -	Evaluation	Checkoif	Worksheet		

Inspector(s): Charles Greatwood									
Motor No.: QM-8					Date: 1/27/89				
Joint: Igni	Igniter (IGN) Case End: Igniter Adapter (FWD)					Сотролен	Component: JPS		
I. T-Bolt Latch Band Clamp Assembly Intact (BAND)? yes no									
A. Delaminations (DLHTR)?									
B. Discolorations (DSCLR)?					x	_ no			
C. Charred	i (HTAFF)?			yes	X	no			
D. Warped	(HTAFF)?			yes	X	no			
III. Heater Pov	ver Cables								
A. Intact (LOOSE)?			yes	<u>x</u>	no			
B. Charred (HTAFF)?				yes	x	_ no	ļ		
If any of the above conditions exist, note:									
	•	Axial	Starting	Ending	-				
Affected	Condition	Location	Degree	Degree	Circu	Interential	Axial		
Part	(Ubservation	(Station)	Location	Location		Width	Length		
(I, II or III)	Code)	(in.)	(Deg.)	(Deg.)		(in.)	(In.)		
				· · · · · · · · · · · · · · · · · · ·					
<u> </u>					• •••••••••••		1		
				- <u>-</u>	·				
			<u> </u>	·	·				
					. <u></u>				
					·				

Notes Comments

Overall condition of igniter heater components is excellent.

00C NO	TWR-1759	1	VOL	VII
SEC		PAGE	19	