

Proposed Rules

Federal Register

Vol. 69, No. 6

Friday, January 9, 2004

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF AGRICULTURE

Food Safety and Inspection Service

9 CFR Part 381

[Docket No. 99-017E]

Classes of Poultry

AGENCY: Food Safety and Inspection Service, USDA.

ACTION: Proposed rule: reopening and extension of comment period.

SUMMARY: The Food Safety and Inspection Service (FSIS) is reopening and extending the comment period for the proposed rulemaking, "Classes of Poultry." The comment period for the proposed rule closed on November 28, 2003. This action responds to a request from an industry trade association to allow additional time to comment on a specific issue raised in the preamble to the proposed rule.

DATES: Comments are due February 9, 2004.

ADDRESSES: Send one original and two copies of written comments to FSIS Docket No. 99-017P, Department of Agriculture, Food Safety and Inspection Service, Room 102, 300 12th Street, SW., Washington, DC 20250-3700.

FOR FURTHER INFORMATION CONTACT: Robert C. Post, Ph.D., Director, Labeling and Consumer Protection Staff, Office of Policy and Program Development, Food Safety and Inspection Service, U.S. Department of Agriculture, Washington, DC 20250-3700; (202) 205-0279

SUPPLEMENTARY INFORMATION: On September 29, 2003, FSIS published a proposed rule, "Classes of Poultry," in the *Federal Register* (68 FR 55902). In that document, the Agency proposed to amend the definitions and standards for the official U.S. classes of poultry so that they more accurately and clearly describe the characteristics of poultry in the market today. Poultry classes are defined primarily in terms of the age and the sex of the bird. In the preamble to the proposed rule, FSIS requested, among other things, comments on

whether the Agency should establish ready-to-cook carcass weights or maximum weights for certain poultry classes.

An industry trade association submitted a comment stating that this issue would require considerable consultation with various segments of the chicken industry. The commenter requested additional time to discuss the issue with the industry and to try to arrive at a consensus of workable market weights for certain chicken classes.

FSIS has considered the request and believes that the information that the commenter is interested in providing will be useful in informing the Agency's decision on whether to establish ready-to-cook market weights for certain poultry classes, and if so, what those weights should be. Therefore, the Agency will reopen and extend the comment period for the proposed rule for an additional 30 days. The Agency believes that this will provide additional time for comments to be made, while ensuring that the rulemaking proceeds in a timely manner. As a result of this reopening and extension, the comment period for the proposed rule will close on February 9, 2004.

Additional Public Notification

Public awareness of all segments of rulemaking and policy development is important. Consequently, in an effort to better ensure that minorities, women, and persons with disabilities are aware of this notice, FSIS will announce it and make copies of this **Federal Register** publication available through the FSIS Constituent Update. FSIS provides a weekly Constituent Update, which is communicated via Listserv, a free e-mail subscription service. In addition, the update is available on-line through the FSIS Web page located at <http://www.fsis.usda.gov>. The update is used to provide information regarding FSIS policies, procedures, regulations, **Federal Register** notices, FSIS public meetings, recalls, and any other types of information that could affect or would be of interest to our constituents/stakeholders. The constituent Listserv consists of industry, trade, and farm groups, consumer interest groups, allied health professionals, scientific professionals, and other individuals that have requested to be included. Through the Listserv and Web page, FSIS is able

to provide information to a much broader, more diverse audience.

For more information contact the Congressional and Public Affairs Office, at (202) 720-9113. To be added to the free e-mail subscription service (Listserv) go to the "Constituent Update" page on the FSIS Web site at <http://www.fsis.usda.gov/oa/update/update.htm>. Click on the "Subscribe to the Constituent Update Listserv" link, then fill out and submit the form.

Done in Washington, DC on January 5, 2004.

Garry L. McKee,
Administrator.

[FR Doc. 04-402 Filed 1-8-04; 8:45 am]

BILLING CODE 3410-DM-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-204-AD]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Mystere-Falcon 50 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Dassault Model Mystere-Falcon 50 series airplanes. This proposal would require a one-time inspection for improper installation of the electrical wiring for the optional lighting in the cabin, and corrective actions if necessary. This action is necessary to prevent overheating of optional lighting wiring that was improperly installed in the cabin, and consequent smoke/fire in the cabin. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by February 9, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-204-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: *9-anm-nprmcomment@faa.gov*. Comments sent via fax or the Internet must contain "Docket No. 2002-NM-204-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact

concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-204-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-204-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Dassault Model Mystere-Falcon 50 series airplanes. The DGAC advises that due to incorrect routing, wiring for the optional lighting in the cabin may be directly connected to the direct power supply line of the battery bus instead of through a dedicated circuit breaker. In this configuration, an electrical current is generated even after the starter generators and batteries are switched off. This condition, if not corrected, could result in overheating of electrical wiring and consequent smoke/fire in the cabin.

Explanation of Relevant Service Information

Dassault has issued Service Bulletin F50-138, Revision 1, dated June 12, 2002, which describes procedures for inspecting the wiring installation for the optional lighting in the cabin, measuring the electrical current at a certain circuit breaker, and performing corrective actions if necessary. The corrective actions include installing circuit breakers, modifying the existing wiring installation, doing a detailed inspection of any modified wiring installation to ensure it matches the wiring diagram, and testing the modified wiring installation. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. The DGAC classified this service bulletin as mandatory and issued French airworthiness directive 2002-086-036(B) R1, dated March 20, 2002, to ensure the continued airworthiness of these airplanes in France.

FAA's Conclusions

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept us informed of the situation described above. We have examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed AD

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously, except as discussed below.

Cost Impact

We estimate that 175 airplanes of U.S. registry would be affected by this proposed AD.

It would take approximately 2 work hours per airplane to accomplish the proposed inspection at an average labor rate of \$65 per work hour. Based on these figures, the cost impact of the proposed inspection is estimated to be \$22,750, or \$130 per airplane.

Should an operator have to modify the optional lighting wiring, it would take approximately 60 work hours at an average labor rate of \$65 per work hour. Required parts would be provided by the manufacturer at no charge. Based on these figures, the cost impact of the proposed modification on U.S. operators is estimated to be \$682,500, or \$3,900 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Dassault Aviation: Docket 2002–NM–204–AD.

Applicability: Model Mystere-Falcon 50 series airplanes having serial numbers 2 to 270 inclusive, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent overheating of optional lighting wiring that was improperly installed in the cabin, and consequent smoke/fire in the cabin, accomplish the following:

Inspection

(a) Within 13 months after the effective date of this AD: Do a detailed inspection (including measurement of electrical current) of the electrical wiring installation for

optional lighting in the cabin to determine if any wiring is directly connected to the battery bus. Do all of the applicable actions per the Accomplishment Instructions of Dassault Service Bulletin F50–318, Revision 1, dated June 12, 2002.

Note 1: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Corrective Actions

(b) If any electrical wiring is found to be directly connected to the battery bus during the inspection required by paragraph (a) of this AD, before further flight, do all the applicable corrective actions (e.g., modifying the existing wiring, doing a detailed inspection of any modified wiring installation to ensure it matches the wiring diagram, and testing the modified wiring installation) per the Accomplishment Instructions of Dassault Service Bulletin F50–318, Revision 1, dated June 12, 2002.

Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate, is authorized to approve alternative methods of compliance for this AD.

Note 2: The subject of this AD is addressed in French airworthiness directive 2002–086–036(B) R1, dated March 20, 2002.

Issued in Renton, Washington, on December 31, 2003.

Michael J. Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04–425 Filed 1–8–04; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003–NM–74–AD]

RIN 2120–AA64

Airworthiness Directives; McDonnell Douglas Model MD–11 and –11F Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to certain McDonnell Douglas Model MD–11 and

–11F airplanes, that currently requires, among other actions, replacing the ground support bracket(s); and rerouting the ground cables of the galley external power and main external power, as applicable. This action would require replacing ground support brackets with new brackets, and replacing ground cables of the galley external power and main external power with new cables; as applicable. This action also would require an inspection to detect the presence of a fillet seal at the ground brackets and to detect excessive length and correct terminations of the ground cables of the galley and main external power, as applicable; and corrective actions if necessary. The actions specified by the proposed AD are intended to prevent arcing and heat damage to the attachment points of the main external and galley power receptacle ground wire, insulation blankets outboard and aft of the receptacle area, and adjacent power cables, which could result in smoke and fire in the forward cargo compartment. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by February 23, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 2003–NM–74–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227–1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2003–NM–74–AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1–L5A (D800–0024). This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California.