

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2002-25-02 Honeywell International Inc.: Amendment 39-12977. Docket No. 2001-NE-11-AD.

Applicability: This airworthiness directive (AD) is applicable to Honeywell International Inc. (formerly AlliedSignal Inc., Garrett Turbine Engine Company and AiResearch Manufacturing Company of Arizona) TPE331-3, -5, -6, -8, -10, and -11 series turboprop and TSE331-3 series turboshaft engines. These engines are installed on, but not limited to Ayres S-2R series; Beech 18 and 45 series and Models JRB-6, 3N, 3NM, 3TM, and B100; Cessna Model 441; Construcciones Aeronauticas, S.A. (CASA) C-212 series; De Havilland DH 104 series 7AXC (Dove); Dornier 228 series; Fairchild SA226 and SA227 series (Swearingen Merlin and Metro series); Grumman American G-164 series; Jetstream 3101; Mitsubishi MU-2B series (MU-2 series); Prop-Jets, Inc. Model 400; Rockwell Commander S-2R; Shorts Brothers and Harland, Ltd. SC7 (Skyvan); Pilatus PC-6 series (Fairchild Porter and Peacemaker); and Schweizer G-164 series; and Twin Commander Aircraft Corp. (Jetprop Commander) Models 695 and 695A airplanes; and Sikorsky S-55 series (Helitec Corp. S55T) helicopters.

Note 1: This AD applies to each engine identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Compliance with this AD is required as indicated, unless already done.

To prevent an uncontained engine failure, in-flight shutdown, and secondary damage, do the following:

Removal of Weld Repaired First Stage Compressor Impellers From Service

(a) Remove from service weld repaired first stage compressor impellers, P/N's 896223-1, -2, -3, and -7 and 3107109-2, with SN's listed in Table 1 and Table 2 of the Accomplishment Instructions in 2.A.(1) and 2.A.(2) of Honeywell Alert Service Bulletin TPE331-A72-2083, revision 1, dated May 17, 2002, in accordance with the following schedule:

(1) Remove impellers with no record of cycles since weld repair, within 3,600 cycles-in-service (CIS) or at the next engine overhaul, or at the next major Continuous Airworthiness Maintenance (CAM) compressor section inspection, after the effective date of this AD, whichever occurs first.

(2) Remove impellers with more than 8,900 cycles since "weld repair," within 3,600 CIS, or at the next engine overhaul, or at the next major CAM compressor section inspection after the effective date of this AD, whichever occurs first.

(3) After the effective date of this AD, remove impellers with 8,900 or less cycles since "weld repair," before reaching 12,500 cycles since weld repair.

(b) For purposes of this AD, weld repaired or weld repair is defined as an impeller repair which involved heat treating and that was performed from 1980 through 1997 at Honeywell Aerospace Services, Aftermarket-Phoenix Repair and Overhaul, 1944 E. Sky Harbor Circle, Phoenix, AZ. 85034 (FAA Certificate Number ZN3R030M). Former names and FAA certificate numbers for Honeywell's Repair and Overhaul Facility are listed in section 2.A. of the Accomplishment Instructions in Honeywell Alert Service Bulletin TPE331-A72-2083, revision 1, dated May 17, 2002.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO). Operators must submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be done.

Documents That Have Been Incorporated by Reference

(e) The impeller removals must be done in accordance with Honeywell International Inc. Alert Service Bulletin TPE331-A72-2083, revision 1, dated May 17, 2002. This incorporation by reference was approved by the Director of the Federal Register in

accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Honeywell Engines, Systems and Services, Technical Data Distribution, M/S 2101-201, P.O. Box 52170, Phoenix, AZ 85072-2170; telephone: (602) 365-2493 (General Aviation), (602) 365-5535 (Commercial); fax: (602) 365-5577 (General Aviation and Commercial). Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on January 21, 2003.

Issued in Burlington, Massachusetts, on December 2, 2002.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 02-31172 Filed 12-13-02; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-CE-35-AD; Amendment 39-12980; AD 2002-25-05]

RIN 2120-AA64

Airworthiness Directives; Pilatus Britten-Norman Limited BN-2 and BN2A Mk. III Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to all Pilatus Britten-Norman (Pilatus Britten-Norman) Limited BN-2 and BN2A Mk. III series airplanes. This AD requires you to inspect the universal joints on the pilot's and co-pilot's control column to determine the diameter of the shaft and replace any universal joint that is the wrong size. This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for the United Kingdom. The actions specified by this AD are intended to correct the installation of universal joints that have the wrong-sized shaft, which could result in failure of the pilot's and/or co-pilot's control column. Such failure could lead to loss of control of the airplane.

DATES: This AD becomes effective on February 3, 2003.

The Director of the Federal Register approved the incorporation by reference

of certain publications listed in the regulations as of February 3, 2003.

ADDRESSES: You may get the service information referenced in this AD from B-N Group Limited, Bembridge, Isle of Wight, United Kingdom PO35 5PR; telephone: +44 (0) 1983 872511; facsimile: +44 (0) 1983 873246. You may view this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2002-CE-35-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

What Events Have Caused This AD?

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, recently notified FAA that an unsafe condition may exist on all Pilatus Britten-Norman BN-2 and BN2A Mk. III series airplanes. The CAA reports that, during maintenance on one of the affected airplanes, an undersized universal joint was found. This installation of undersized universal joints is the result of a quality control problem.

What Is the Potential Impact if FAA Took No Action?

This condition, if not corrected, could cause failure of the pilot's and/or co-pilot's control column. Such failure could result in loss of control of the airplane.

Has FAA Taken Any Action to This Point?

We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all Pilatus Britten-Norman BN-2 and BN2A Mk. III series airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on September 18, 2002 (67 FR 58737). The NPRM proposed to require you to inspect the universal joints on the pilot's and co-pilot's control column to determine the diameter of the shaft and replace any universal joint that is the wrong size.

Was the Public Invited to Comment?

The FAA encouraged interested persons to participate in the making of this amendment. We did not receive any comments on the proposed rule or on our determination of the cost to the public.

FAA's Determination

What Is FAA's Final Determination on This Issue?

After careful review of all available information related to the subject presented above, we have determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial

corrections. We have determined that these minor corrections:

- Provide the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

What Are the Differences Between This AD, the Service Information, and the CAA AD?

The CAA AD and the service information requires inspection and, if necessary, replacement of any universal joint that is not the correct size within the next 10 hours time-in-service (TIS) after the effective date of the AD. We are requiring you to inspect and, if necessary, replace within 30 days after the effective date of this AD. We do not have justification to require this action within the next 10 hours TIS. We use compliance times such as this when we have identified an urgent safety of flight situation. We believe that 30 days will give the owners or operators of the affected airplanes enough time to have the actions accomplished without compromising the safety of the airplanes.

Cost Impact

How Many Airplanes Does This AD Impact?

We estimate that this AD affects 135 airplanes in the U.S. registry.

What Is the Cost Impact of This AD on Owners/Operators of the Affected Airplanes?

We estimate the following costs to accomplish the inspection:

Labor cost per universal joint	Parts cost	Total cost per universal joint	Total cost on U.S. operators
1 workhour × \$60 = \$60 (3 universal joints per airplane).	No parts required	\$60 (\$60 × 3 universal joints per airplane = \$180).	\$180 × 135 = \$24,300.

We estimate the following costs to accomplish any necessary replacements that will be required based on the

results of the inspection. We have no way of determining the number of

airplanes that may need such replacement:

Labor cost per universal joint	Parts cost	Total cost per universal joint
2 workhours × \$60 = \$120	\$2,000 per universal joint	\$120 + \$2,000 = \$2,120.

Compliance Time of This AD

What Is the Compliance Time of This AD?

The compliance time of this AD is “within the next 30 days after the effective date of this AD.”

Why Is the Compliance Time Presented in Calendar Time Instead of Hours Time-in-Service (TIS)?

This unsafe condition is not a result of the number of times the airplane is operated. The chance of this situation occurring is the same for an airplane with 10 hours time-in-service (TIS) as it

is for an airplane with 500 hours TIS. For this reason, the FAA has determined that a compliance based on calendar time should be utilized in this AD in order to assure that the unsafe condition is addressed on all airplanes in a reasonable time period.

Regulatory Impact

Does This AD Impact Various Entities?

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

Does This AD Involve a Significant Rule or Regulatory Action?

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the final

evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends § 39.13 by adding a new AD to read as follows:

2002-25-05 Pilatus Britten-Norman

Limited: Amendment 39-12980; Docket No. 2002-CE-35-AD.

(a) *What airplanes are affected by this AD?* This AD affects the following airplane models, all serial numbers, that are certificated in any category:

Models

BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A-27, BN-2B-20, BN-2B-21, BN-2B-26, BN-2B-27, BN-2T, BN-2T-4R, BN2A MK. III, BN2A MK. III-2, and BN2A MK. III-3

(b) *Who must comply with this AD?*

Anyone who wishes to operate any of the airplanes identified in paragraph (a) of this AD must comply with this AD.

(c) *What problem does this AD address?*

The actions specified by this AD are intended to correct the installation of universal joints that have the wrong-sized shaft, which could result in failure of the pilot's and/or co-pilot's control column. Such failure could lead to loss of control of the airplane.

(d) *What actions must I accomplish to address this problem?* To address this problem, you must accomplish the following:

Actions	Compliance	Procedures
(1) Inspect all universal joints on the pilot's and co-pilot's control columns to determine the diameter of the shaft. (i) If the universal joint diameter is 1.154 to 1.155 inches, re-install into the airplane; and. (ii) If the universal joint diameter is not 1.154 to 1.155 inches in diameter, replace with a new universal joint that has the a diameter of 1.154 to 1.155 inches.	Inspect within the next 30 days after February 3, 2003 (the effective date of this AD). Replace prior to further flight after the inspection.	In accordance with B-N Group Ltd. Service Bulletin Number SB 284, Issue 1, dated May 9, 2002.
(2) Do not install any universal joint that is not 1.154 to 1.155 inches in diameter.	As of February 3, 2003 (the effective date of this AD).	In accordance with B-N Group Ltd. Service Bulletin Number SB 284, Issue 1, dated May 9, 2002.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Standards Office, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standards Office.

Note 1: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not

eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; facsimile: (816) 329-4090.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with B-N Group Ltd. Service Bulletin Number SB 284, Issue 1, dated May 9, 2002. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You may get copies from B-N Group Limited, Bembridge, Isle of

Wight, United Kingdom PO35 5PR; telephone: +44 (0) 1983 872511; facsimile: +44 (0) 1983 873246. You may view copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 2: The subject of this AD is addressed in British AD Number 004-05-2002, dated May 30, 2002.

(i) *When does this amendment become effective?* This amendment becomes effective on February 3, 2003.

Issued in Kansas City, Missouri, on December 5, 2002.

Michael Gallagher,
Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 02-31394 Filed 12-13-02; 8:45 am]

BILLING CODE 4910-13-P