UNITED STATES DEPARTMENT OF THE INTERIOR							
MINERALS MANAGEMENT SERVICE							
GULF OF MEXICO REGION							
ACCIDENT INVESTIGATION REPORT							

1.	OCCURRED	8. CAUSE: 🕱 EQUIPMENT FAILURE					
	DATE: 19-JAN-2005 TIME: 1800 HOURS	RS HUMAN ERROR					
2	OPERATOR: Unocal Exploration	EXTERNAL DAMAGE					
2.	Corporation	SLIP/TRIP/FALL					
		WEATHER RELATED					
	REPRESENTATIVE: Lonnie Dugas		LEAK				
	TELEPHONE: (281) 287-7425	UPSET H20 TREATING					
3.	LEASE: 00827	OVERBOARD DRILLING FLUID					
	AREA: SS LATITUDE: 28.549285		OTHER				
	BLOCK: 209 LONGITUDE: -90.853494	9.	WATER DEPTH: 140 FT.				
	PLATFORM: K	10.	DISTANCE FROM SHORE: 45 MI.				
	DTO NAME	11.	WIND DIRECTION: S				
	RIG NAME		SPEED: 15 M.P.H.				
5.	ACTIVITY: EXPLORATION(POE)	12.	CURRENT DIRECTION: SW				
	X DEVELOPMENT/PRODUCTION		SPEED: 7 M.P.H.				
	(DOCD/POD)	13.	SEA STATE: <b>5</b> FT.				
6.	TYPE: X FIRE						
	BLOWOUT	16					
		10.	OPERATOR REPRESENTATIVE/ SUPERVISOR ON SITE AT TIME OF INCIDENT:				
	INJURY NO. 0		Johnathon Hargrave				
FATALITY NO. 0			CITY: Houston STATE: TX				
	POLLUTION						
	OTHER		TELEPHONE: (281) 287-6500				
7.	OPERATION: X PRODUCTION		CONTRACTOR: Unocal Exploration Corporation				
	DRILLING						
	WORKOVER		CONTRACTOR REPRESENTATIVE/				
	COMPLETION		SUPERVISOR ON SITE AT TIME OF INCIDENT:				
	MOTOR VESSEL		Bryan Oliver				
	DIPELINE SEGMENT NO.		CITY: Houston STATE: TX _ TELEPHONE: (281) 287-6500				
	□ □ OTHER		IELEFRONE. (201) 207-0500				

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

Due to vibration, the 3" nipple broke on the compressor hydraulic fan pump causing hydraulic oil to spill on the hot exhaust of the compressor. Heat from the exhaust caused the hydraulic oil to burn. The fire was extinguished with about one-third of a 150 lb. dry chemical wheel unit.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

This accident was caused by the 3" nipple cracking.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Normal vibration from the compressor and fan pump caused fatigue in the nipple resulting in the nipple cracking.

20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010 EV2010R PAGE: 2 OF 4 01-JUN-2005 21. PROPERTY DAMAGED:

1" X 3" nipple blankets on exhaust NATURE OF DAMAGE:

nipple had to be replaced blankets were ruined and shall be replaced

ESTIMATED AMOUNT (TOTAL): \$1,000

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

Due to the specific nature of this incident, the Houma District Office has no recommendation to the Regional Office.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

25. DATE OF ONSITE INVESTIGATION:

26. ONSITE TEAM MEMBERS:

Amy Gresham /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Michael J. Saucier

APPROVED

DATE: 10-FEB-2005

MMS - FORM 2010 EV2010R PAGE: 3 OF 4 01-JUN-2005

## FIRE/EXPLOSION ATTACHMENT

1. SOURCE OF IGNITION: hot exhaust

2.	TYPE	OF	FUEL:		(	GAS
					(	DIL
					I	DIESEL
					(	CONDENSATE
				x	I	HYDRAULIC
					(	OTHER

3. FUEL SOURCE: hydraulic oil leaking on the hot exhaust from the compressor

4. WERE PRECAUTIONS OR ACTIONS TAKEN TO ISOLATE KNOWN SOURCES OF IGNITION PRIOR TO THE ACCIDENT ? NO

5.	TYPE	OF	FIREFIGHTING	EQUIPMENT	UTILIZED:		HANDHELD
						x	WHEELED UNIT
							FIXED CHEMICAL
							FIXED WATER
							NONE
							OTHER