UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1.	OCCURRED DATE: 29-NOV-2006 TIME: 0830 HOURS	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER				
2.	OPERATOR: Pogo Producing Company REPRESENTATIVE: David Day TELEPHONE: (832) 615-8983 CONTRACTOR: REPRESENTATIVE: TELEPHONE:					
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:				
	LEASE: G02177 AREA: SP LATITUDE: BLOCK: 49 LONGITUDE:	X PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL				
5.	PLATFORM: A RIG NAME:	PIPELINE SEGMENT NO. OTHER				
	ACTIVITY: EXPLORATION(POE) DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE:	8. CAUSE: X EQUIPMENT FAILURE X HUMAN ERROR				
	HISTORIC INJURY REQUIRED EVACUATION LTA (1-3 days) LTA (>3 days RW/JT (1-3 days) RW/JT (>3 days)	EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER				
	Other Injury FATALITY	9. WATER DEPTH: 300 FT.				
	X POLLUTION FIRE	10. DISTANCE FROM SHORE: 10 MI.				
	LWC HISTORIC BLOWOUT UNDERGROUND	11. WIND DIRECTION: SSW SPEED: 12 M.P.H.				
	SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12. CURRENT DIRECTION: N SPEED: 7 M.P.H.				
	COLLISION HISTORIC >\$25K <=\$25K	13. SEA STATE: FT.				

MMS - FORM 2010 PAGE: 1 OF 5

- A. On the morning of 11-18-2006, the Operator was making a round on the SP 49-A platform about 07:00, a slick was discovered coming of the platform 150 ft wide and 2600 ft long by operations. Dull in color. An upset in the chem electric carried over to the Wemco Unit overflowing to the Gulf. The operator shut in the platform and proceeded to clean up the systems.
- B. 11/21/2006 There was an upset in the LPS causing a pollution incident off the Wemco Unit. On the evening of the incident the operators were trying to pig the Stone Energy, MC 109A pipeline. They had a manual valve cracked open to the vent system off the pig trap. When the Wemco Unit high leveled, the operators went to it and left the manual valve on the pig trap open and unattended. It was at this time a slug of oil from the MC 109 Pipeline hit the pig trap and flooded the vent system with oil causing oil to blow out the flare boom. Oil covered the entire platform and was left that way until 11/29/2006.
- C. 11/29/2006 There was a third pollution event discovered by New Orleans District during a routine inspection flight offshore. An inspector discovered a slick 1/4 of a mile wide by 16 miles long trailing off SP 49A platform. When the inspector landed and found the Lead Operator, they were still on line and trying to pump the oil out of the Wemco Unit straight to the Production Sump. At this point the inspector instructed the Lead to shut in the facility by ESD and was going to time the shut down. After activation of the ESD system the platform did not shut in. It was discovered that the ESD system was in by pass along with all pipelines and most of the components on the platform. They took the ESD system out of by pass and the facility did shut in at that point. By passed devices and systems were not flagged nor were they being monitored. The best answer the inspector could get at the time from the lead operator was he did not know when or who had put the devices in by passed.
- D. 12-10-2006 There was a fourth pollution event. As the operators were trying to bring the platform back on line, the vent scrubber High Leveled and filled the flare boom up with oil then it was release out the flare boom.

- 18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:
 - a. Not properly trained for the facility
 - b. Lack of supervision
 - c. Unsafe work practices
 - d. Operators being fatigued
- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
 - a. Not being properly trained for the facility
 - b. Lack of supervision
 - c. Unsafe work practices
 - d. Fatigue factor for personal

MMS - FORM 2010 PAGE: 2 OF 5

MMS - FORM 2010 PAGE: 3 OF 5
EV2010R 05-APR-2007

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None None

ESTIMATED AMOUNT (TOTAL):

Ġ

- 22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:
 - a. Have Sub part 0 audit done by Safety Management Group with emphasis on training operators on the facility they are to operate.
- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
 - a. E-100 30 CFR 250.300 (a) issued on 11-21- 2006
 - b. G-112 30 CFR 250.107 issued on 11-21- 2006
 - c. G-110 30 CFR 250.107 issued on 11-21- 2006

The following INCs were written on 11-29-2006

- a. E-100 30 CFR 250.300 (a) 16 MILE POLLUTION EVENT
- b. P-103 30 CFR 250.803(C) (1) ESD SYSTEM BEING BY PASSED
- c. P-103 30 CFR 250.803(C) (1) KAH 6678 GAS SALES P/L BY PASSED
- d. P-103 30 CFR 250.803(C) (1) MBD 1000 IP SEP BY PASSED
- e. P-103 30 CFR 250.803(C) (1) WEMCO LSH/L BY PASSED
- f. P-103 30 CFR 250.803(C) (1) KAQ 6029 P/L BY PASSED
- g. P-103 30 CFR 250.803(C) (1)KAQ 6848 P/L BY PASSED
- h. P-103 30 CFR 250.803(C) (1)KAQ 6951 TGP P/L BY PASSED
- i. P-103 30 CFR 250.803(C) (1) MBD 1003 LP SEP BY PASSED
- j. G-112 30 CFR 250.107 OIL ACCUMULATIOS ON THR DECKS
- k. P-103 30 CFR 250.300(C)(1) KAH 5625 OIL SALES P/L BY PASSED
- 25. DATE OF ONSITE INVESTIGATION:

29-NOV-2006

26. ONSITE TEAM MEMBERS:

Justin Josey / Phil McLean /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: **27-FEB-2007**

MMS - FORM 2010 PAGE: 4 OF 5

POLLUTION ATTACHMENT

1.	VOLUME:	GAL	4.8	BBL					
	29920	YARDS LONG X	1320	YARDS	WIDE				
	APPEARANCE:								
2.	TYPE OF HYDROCARB	ON RELEASED: X	OIL						
	DIESEL								
	CONDENSATE								
	HYDRAULIC								
	NATURAL GAS								
			OTHE	R					
3.	SOURCE OF HYDROCARBON RELEASED: Wemco Unit								
4.	WERE SAMPLES TAKEN? NO								
5.	WAS CLEANUP EQUIPMENT ACTIVATED? NO								
	IF SO, TYPE: SKIMMER CONTAINMENT BOOM ABSORPTION EQUIPMENT DISPERSANTS OTHER								
6.	ESTIMATED RECOVER	Υ: (GAL			BBL			
7.	RESPONSE TIME:	HOURS							
8.	IS THE POLLUTION IN THE PROXIMITY OF AN ENVIRONMENTALLY SENSITIVE AREA (CLASS I)? NO								
9.	HAS REGION OIL SPILL TASK FORCE BEEN NOTIFIED? NO								
10.	CONTACTED SHORE:	NO IF YES	, WHERE	:					
11.	WERE ANY LIVE ANIMALS OBSERVED NEAR: NO								
12.	WERE ANY OILED OR DEAD ANIMALS OBSERVED NEAR SPILL: NO								

MMS - FORM 2010 PAGE: 5 OF 5