

UNITED STATES DEPARTMENT OF THE INTERIOR  
 MINERALS MANAGEMENT SERVICE  
 GULF OF MEXICO REGION  
**ACCIDENT INVESTIGATION REPORT**

1. OCCURRED

DATE: **14-MAR-2007** TIME: **0200** HOURS

2. OPERATOR:

**Energy XXI GOM, LLC**

REPRESENTATIVE: **Kay Morgan**

TELEPHONE: **(409) 379-3739**

CONTRACTOR: **HERCULES OFFSHORE DRILLING**

REPRESENTATIVE: **Tim Youngblood**

TELEPHONE: **(409) 379-3739**

3. OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR  
 ON SITE AT TIME OF INCIDENT:

4. LEASE:

**00263**

AREA: **ST** LATITUDE:

BLOCK: **21** LONGITUDE:

5. PLATFORM:

**GA**

RIG NAME: **HERCULES 11**

6. ACTIVITY:

EXPLORATION(POE)  
 DEVELOPMENT/PRODUCTION  
 (DOCD/POD)

7. TYPE:

HISTORIC INJURY

- REQUIRED EVACUATION
- LTA (1-3 days)
- LTA (>3 days)
- RW/JT (1-3 days)
- RW/JT (>3 days)
- Other Injury **1 Slight Bruising To Foot**

FATALITY  
 POLLUTION  
 FIRE  
 EXPLOSION

LWC

HISTORIC BLOWOUT  
 UNDERGROUND  
 SURFACE  
 DEVERTER

SURFACE EQUIPMENT FAILURE OR PROCEDURES

COLLISION  HISTORIC  >\$25K  <=\$25K

STRUCTURAL DAMAGE  
 CRANE  
 OTHER LIFTING DEVICE  
 DAMAGED/DISABLED SAFETY SYS.  
 INCIDENT >\$25K  
 H2S/15MIN./20PPM  
 REQUIRED MUSTER  
 SHUTDOWN FROM GAS RELEASE  
 OTHER **Gas Bubble to Surface**

6. OPERATION:

PRODUCTION  
 DRILLING  
 WORKOVER  
 COMPLETION  
 HELICOPTER  
 MOTOR VESSEL  
 PIPELINE SEGMENT NO.  
 OTHER

8. CAUSE:

EQUIPMENT FAILURE  
 HUMAN ERROR  
 EXTERNAL DAMAGE  
 SLIP/TRIP/FALL  
 WEATHER RELATED  
 LEAK  
 UPSET H2O TREATING  
 OVERBOARD DRILLING FLUID  
 OTHER \_\_\_\_\_

9. WATER DEPTH: **40 FT.**

10. DISTANCE FROM SHORE: **3 MI.**

11. WIND DIRECTION:  
 SPEED: **M.P.H.**

12. CURRENT DIRECTION:  
 SPEED: **M.P.H.**

13. SEA STATE: **FT.**

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On 14 March 2007, at approximately 0200 hrs, rig personnel were retrieving an RTTS (Retrievable, Testing, Treating and Squeeze Tool) Packer. Unbeknownst to them a gas bubble had formed below the packer, which was set at 500ft measured depth. When the packer was retrieved (released) the trapped gas was released, pushing the 9.1ppg Calcium Chloride (CaCl) workover fluid above it through the rotary. The fluid pushed the two rotary bushings out of the rotary. One of the rotary bushings fell into the water and the other rotary bushing landed on the drill floor which tipped over onto the Floorman's steel toed boot. Additionally two service personnel were splashed with the 9.1ppg CaCl workover fluid. The Hydril was closed and the SICP was measured at 100psi. The drill pipe and casing were circulated with 9.1 CaCl workover fluids to kill the well. No pollution resulted from this incident.

The RTTS, also known as a storm packer, was set at 500ft with approximately 4000ft of drill pipe hanging below the packer to provide weight to set the packer. Prior to setting the packer the well was losing fluid at approximately 2 to 3 bbls per hour. The storm packer was set and tested to 1000psi. The existing tubing head was then changed out for a new tubing head and the BOP stack was tested to 250psi low and 5000psi high. The storm packer retrieving tool was run to 500' MD and engaged the packer with a closed TIW valve at the surface. The TIW valve was then opened and the drill pipe was observed to be on a vacuum indicating there was no pressure below the packer. The packer was released with straight pickup on the drill string and the 9.1 CaCl workover fluids immediately came up through the rotary resulting in the incident described above.

The service personnel which were splashed with the 9.1ppg CaCl took showers and suffered no injuries. The Floorman which had the rotary bushing tip over on his steel toed boot suffered minor swelling and bruising to his foot.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

The cause of the incident was a build up of gas under the set storm packer. During release/retrieval of this storm packer, rig personnel were not aware of this gas bubble that formed under the packer. If the Annular Blowout Preventers had been closed before the release (unseating) of the packer, the fluid would not have reached the rig floor, thus eliminating the incident.

It was later revealed that a Halliburton tool man was not present during the unseating of the storm packer. If a Halliburton tool man had been present, this incident may not have occurred.

Also the lack of a detailed procedure covering the unseating of this RTTS Packer may have also been a major contributing factor in this incident.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

20. LIST THE ADDITIONAL INFORMATION:

21. PROPERTY DAMAGED:

**None**

NATURE OF DAMAGE:

**N/A**

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRENCE NARRATIVE:

**This incident had only a slight injury associated with it. However this incident could have been very serious. The Houma District hereby recommends that a Safety Alert be issued.**

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: **NO**

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

25. DATE OF ONSITE INVESTIGATION:

26. ONSITE TEAM MEMBERS:

**Brad Hunter / Kelly Bouzigard /  
Darrel Griffin / Amy Wilson /**

29. ACCIDENT INVESTIGATION

PANEL FORMED: **NO**

OCS REPORT:

30. DISTRICT SUPERVISOR:

**Michael J. Saucier**

APPROVED

DATE: **18-APR-2007**

# INJURY/FATALITY/WITNESS ATTACHMENT

OPERATOR REPRESENTATIVE

INJURY

CONTRACTOR REPRESENTATIVE

FATALITY

OTHER \_\_\_\_\_

WITNESS

NAME :

HOME ADDRESS :

CITY :

STATE :

WORK PHONE : (

TOTAL OFFSHORE EXPERIENCE :

EARS

EMPLOYED BY :

BUSINESS ADDRESS :

CITY :

STATE :

ZIP CODE :