UNITED STATES DEPARTMENT OF THE INTERIOR MINERALS MANAGEMENT SERVICE GULF OF MEXICO REGION

ACCIDENT INVESTIGATION REPORT

1.	OCCURRED DATE: 15-NOV-2007 TIME: 0530 HOURS	STRUCTURAL DAMAGE CRANE OTHER LIFTING DEVICE
2.	OPERATOR: Chevron U.S.A. Inc. REPRESENTATIVE: George, Noel TELEPHONE: (504) 592-6542 CONTRACTOR: REPRESENTATIVE: TELEPHONE:	DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
	LEASE: G02185 AREA: SP LATITUDE: BLOCK: 78 LONGITUDE: PLATFORM:	PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO.
	RIG NAME:	OTHER
	ACTIVITY: EXPLORATION(POE) DEVELOPMENT/PRODUCTION (DOCD/POD) TYPE: HISTORIC INJURY REQUIRED EVACUATION 1 LTA (1-3 days) X LTA (>3 days 1 RW/JT (1-3 days) RW/JT (>3 days)	8. CAUSE: EQUIPMENT FAILURE X HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H20 TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury FATALITY POLLUTION	9. WATER DEPTH: FT.
	FIRE EXPLOSION LWC HISTORIC BLOWOUT UNDERGROUND	10. DISTANCE FROM SHORE: MI. 11. WIND DIRECTION: SPEED: M.P.H.
	SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	12. CURRENT DIRECTION: SPEED: M.P.H.
	COLLISION HISTORIC >\$25K <=\$25K	13. SEA STATE: FT.

MMS - FORM 2010 PAGE: 1 OF 3

EV2010R

17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On November 15, 2007, at 0530 hours, a crew member was injured while the Motor Vessel (MV) Pope John Paul II was maneuvering and tying-up to Lease OCS-G 2185, South Pass (SP) 78 A Platform. The Injured Person (IP) suffered fractures in both hands and legs when the rope used to tie-up the MV snapped striking both his hands and legs. The IP recovery time is expected to be greater than two months.

Sequence of Events:

The MV Pope John Paul II was trying to tie up to a Marathon platform. After the IP tied the boat up the boat captain tried moving the boat forward to take up the slack out of the rope. The IP tried to stop the captain thinking he was going to fast. The IP thought the captain did not see him because of all the equipment on deck. Before the IP could think about his position the rope snapped in two striking the IP on both legs and hand. Nabors safety coordinator flew with IP to hospital.

Update 1: 11/19/07 - Injured person went through surgery. He did have fractures in both legs and both hands. He was eating regular food and talking. IP currently in ICU and is to be upgraded.

Update 2: 12/4/07 - The injured party will possibly need recovery greater than 2 months.

18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Human Error:

Lack of communications between crew member and Captain of boat.

- 19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:
- 20. LIST THE ADDITIONAL INFORMATION:

MMS - FORM 2010 PAGE: 2 OF 3

EV2010R 31-MAR-2008

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

None None

ESTIMATED AMOUNT (TOTAL):

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

The New Orleans Distrist makes no recommendation to MMS.

- 23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO
- 24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:
- 25. DATE OF ONSITE INVESTIGATION:
- 26. ONSITE TEAM MEMBERS:

 No onsite investigation. /
- 29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Troy Trosclair

APPROVED

DATE: 28-MAR-2008

MMS - FORM 2010 PAGE: 3 OF 3

EV2010R 31-MAR-2008