### UNITED STATES DEPARTMENT OF THE INTERIOR

### MINERALS MANAGEMENT SERVICE

GULF OF MEXICO REGION

### **ACCIDENT INVESTIGATION REPORT**

	OCCURRED DATE: 22-AUG-2008 TIME: 0926 HOURS  OPERATOR: Nexen Petroleum U.S.A. Inc. REPRESENTATIVE: Miller, Karl TELEPHONE: (337) 735-2504  CONTRACTOR: REPRESENTATIVE: TELEPHONE:	STRUCTURAL DAMAGE  X CRANE OTHER LIFTING DEVICE DAMAGED/DISABLED SAFETY SYS. INCIDENT >\$25K H2S/15MIN./20PPM REQUIRED MUSTER SHUTDOWN FROM GAS RELEASE OTHER
3.	OPERATOR/CONTRACTOR REPRESENTATIVE/SUPERVISOR ON SITE AT TIME OF INCIDENT:	6. OPERATION:
	LEASE: AREA: EI LATITUDE: BLOCK: 259 LONGITUDE:  PLATFORM: C RIG NAME:	PRODUCTION DRILLING WORKOVER COMPLETION HELICOPTER MOTOR VESSEL PIPELINE SEGMENT NO. X OTHER Construction
6.	ACTIVITY: EXPLORATION(POE)	8. CAUSE:
7.	DEVELOPMENT/PRODUCTION (DOCD/POD)  TYPE:  HISTORIC INJURY  REQUIRED EVACUATION LTA (1-3 days) LTA (>3 days RW/JT (1-3 days) RW/JT (>3 days)	X EQUIPMENT FAILURE  HUMAN ERROR EXTERNAL DAMAGE SLIP/TRIP/FALL WEATHER RELATED LEAK UPSET H2O TREATING OVERBOARD DRILLING FLUID OTHER
	Other Injury	9. WATER DEPTH: <b>160</b> FT.
	FATALITY POLLUTION FIRE EXPLOSION	10. DISTANCE FROM SHORE: 58 MI.  11. WIND DIRECTION: E
	LWC HISTORIC BLOWOUT UNDERGROUND SURFACE DEVERTER SURFACE EQUIPMENT FAILURE OR PROCEDURES	11. WIND DIRECTION: E  SPEED: 10 M.P.H.  12. CURRENT DIRECTION: ENE  SPEED: 1 M.P.H.
	COLLISION   HISTORIC   >\$25K   <=\$25K	13 SEA STATE: FT

MMS - FORM 2010 PAGE: 1 OF 8

EV2010R

21-OCT-2008

#### 17. DESCRIBE IN SEQUENCE HOW ACCIDENT HAPPENED:

On the morning of August 22, 2008 at approximately 0926 hours, the crane operator at Nexen Eugene Island 259 C platform was attempting to lift a gang box from the M/V Grant (field boat). The load was to be placed on the top deck of the production platform. During the lifting process, while the load was suspended over the water, the crane operator heard a loud pop and then felt the boom jerk. He immediately noticed the boom and load falling to the water, but missed the field boat located adjacent to the platform. The crane heel boom section remained attached to the crane pedestal while hanging over the side of the production platform, with the boom tip submerged in the water. Three (3) third party contractors on the platform were standing on top of the compressor building taking measurements to fabricate handrailing, when they were struck by small fragments from the boom cable when it parted. Their injuries were limited to small pieces of wire being embedded in their skin, covering shoulder and neck areas on their upper body.

#### 18. LIST THE PROBABLE CAUSE(S) OF ACCIDENT:

Boom cable fatigue and unnecessary stress resulted in reduced strength and integrity of the boom cable, thereby resulting in boom cable failure.

19. LIST THE CONTRIBUTING CAUSE(S) OF ACCIDENT:

Sudden movement of controls during the lifting operation possibly resulting in unnecessary stress to the boom cable.

#### 20. LIST THE ADDITIONAL INFORMATION:

According to Nexen crane records, documents indicate that during annual and quarterly inspections, the boom heel section had evidence of a bent lacing. Documented evidence from Nexen records indicate that the bent lacing occurred while the boom tip section was being changed during a Quarterly inspection dated January 17, 2008. Nexen has provided documentation of a "pull test" that was performed by a manufacturer representative on that date justifying further use of the crane. After testing was completed, all boom sections were found to be sufficient for heavy lifting operations.

MMS - FORM 2010 PAGE: 2 OF 8

EV2010R 21-OCT-2008

MMS - FORM 2010 PAGE: 3 OF 8
EV2010R 21-OCT-2008

21. PROPERTY DAMAGED:

NATURE OF DAMAGE:

1-Facility Crane Boom

2-Hand rail on platform top deck

3-One light fixture, top deck.

4-One light fixture pole

5-One PSV vent line, instrument gas

ESTIMATED AMOUNT (TOTAL):

1-Destroyed from fall 2-Bent out of place

3-Broken

4-Bent out of place and broken

5-Bent out of place

22. RECOMMENDATIONS TO PREVENT RECURRANCE NARRATIVE:

Lafayette District MMS has no recommendations.

23. POSSIBLE OCS VIOLATIONS RELATED TO ACCIDENT: NO

24. SPECIFY VIOLATIONS DIRECTLY OR INDIRECTLY CONTRIBUTING. NARRATIVE:

N/A

25. DATE OF ONSITE INVESTIGATION:

23-AUG-2008

26. ONSITE TEAM MEMBERS:

/ Tom Basey / Jason Abshire /

29. ACCIDENT INVESTIGATION PANEL FORMED: NO

OCS REPORT:

30. DISTRICT SUPERVISOR:

Elliott S. Smith

APPROVED

DATE: 21-OCT-2008

MMS - FORM 2010 PAGE: 4 OF 8

EV2010R 21-OCT-2008

OPERATOR REPRESENTATIVE  CONTRACTOR REPRESENTATIVE  Total Rigger	INJURY  FATALITY  WITNESS	
NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY: BUSINESS ADDRESS: CITY: ZIP CODE:	STATE: TOTAL OFFSHORE EXPERIENCE: 2.  STATE:	<b>5</b> YEARS
OPERATOR REPRESENTATIVE CONTRACTOR REPRESENTATIVE  X OTHER Rigger  NAME:	INJURY FATALITY X WITNESS	

MMS - FORM 2010 PAGE: 5 OF 8

OPERATOR REPRESENTATIVE  CONTRACTOR REPRESENTATIVE  X OTHER Welder	INJURY  FATALITY  WITNESS
NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY: BUSINESS ADDRESS: CITY: ZIP CODE:	STATE:  TOTAL OFFSHORE EXPERIENCE: 18 YEARS  STATE:
OPERATOR REPRESENTATIVE	INJURY
CONTRACTOR REPRESENTATIVE  X OTHER OTHER  NAME:	FATALITY  WITNESS
HOME ADDRESS: CITY: WORK PHONE:	STATE: TOTAL OFFSHORE EXPERIENCE: 1 YEARS
EMPLOYED BY: BUSINESS ADDRESS: CITY:	STATE:
ZIP CODE:	

MMS - FORM 2010 PAGE: 6 OF 8

OPERATOR REPRESENTATIVE  CONTRACTOR REPRESENTATIVE  OTHER Contract Inspector	INJURY FATALITY WITNESS	
NAME: HOME ADDRESS: CITY: WORK PHONE:	STATE: TOTAL OFFSHORE EXPERIENCE:	<b>22</b> YEAR
EMPLOYED BY: BUSINESS ADDRESS: CITY: ZIP CODE:	STATE:	
OPERATOR REPRESENTATIVE  CONTRACTOR REPRESENTATIVE  OTHER Deck Hand	INJURY FATALITY WITNESS	
NAME: HOME ADDRESS: CITY: WORK PHONE: EMPLOYED BY: BUSINESS ADDRESS:	STATE: TOTAL OFFSHORE EXPERIENCE:	<b>14</b> YEAR
CITY: ZIP CODE:	STATE:	

MMS - FORM 2010 PAGE: 7 OF 8 21-OCT-2008

OPERATOR REPRESENTATIVE  CONTRACTOR REPRESENTATIVE  X OTHER Relief Captain	INJURY  FATALITY  WITNESS	
NAME: HOME ADDRESS:		
CITY:	STATE:	
WORK PHONE:	TOTAL OFFSHORE EXPERIENCE: 11 YEAF	RS
EMPLOYED BY:		
BUSINESS ADDRESS:		
CITY:	STATE:	
ZIP CODE:		

MMS - FORM 2010 PAGE: 8 OF 8