# Browns Ferry 1 3Q/2007 Plant Inspection Findings

#### **Initiating Events**

Significance: Sep 30, 2007 Identified By: Self-Revealing Item Type: FIN Finding

Unisolable Electro-hydraulic Control System Leak Due To Improperly Installed Compression Fitting Causes

**Unit 1 Reactor Scram** 

Green. A Green self-revealing finding was identified for poor work practices and inadequate licensee oversight. This allowed for the improper installation of a critical compression fitting on the Unit 1 Electro-Hydraulic Control (EHC) system that caused an unisolable EHC leak which directly resulted in a manual reactor scram. Inspections were subsequently performed to identify any other improperly installed compression fittings on EHC lines throughout the EHC system. This finding was entered into the licensee's corrective action program as Problem Evaluation Report (PER) 125288.

This finding is greater than minor because it is associated with the Initiating Event Cornerstone attributes of Human Performance, and adversely affected the cornerstone objective to limit the likelihood of those events that upset plant stability and challenge critical safety functions during at-power operations. The finding was determined to be of very low safety significance because it did not contribute to both the likelihood of a reactor trip and the likelihood that mitigating equipment or functions were not available. The cause of this finding was directly related to the crosscutting aspect of supervisory and management oversight of contractor activities in the area of Human Performance; in that inadequate oversight of contractor activities allowed for poor installation practices and a lack of communication of human error prevention techniques for maintenance on non-quality related systems like the EHC system. These less than adequate oversight and work practices resulted in the failure of a critical compression fitting which directly resulted in a reactor scram (H.4(c)). (Section 4OA3.4)

Inspection Report# : 2007004 (pdf)

#### **Mitigating Systems**

Significance: Sep 30, 2007 Identified By: Self-Revealing

Item Type: NCV NonCited Violation

Reactor Trip Function on Turbine Stop Valve Closure Not Enabled at 30% Rated Thermal Power

Green. A Green self-revealing noncited violation of Unit 1 Technical Specifications (TS) 3.3.1.1 and Table 3.3.1.1-1, Reactor Protection System Instrumentation, Function 8, Turbine Stop Valve Closure and Function 9, Turbine Control Valve Fast Closure - Trip Oil Pressure Low, was identified. During Unit 1 startup on June 3, 2007, these trips were not enabled when the reactor reached 30% Reactor Thermal Power (RTP) as required by TS. An operator workaround was established to manually enable the reactor trip on turbine trip before reactor power was increased above 30% power. This finding was entered into the licensee's corrective action program as PER 125755.

This finding was considered to be greater than minor because it was associated with the Design Control attribute of the Mitigating Systems Cornerstone and adversely affected the cornerstone objective to ensure the availability of systems that respond to initiating events. The error in the calculation of 1st Stage Turbine Pressure's relation to reactor power established a non-conservative setpoint following a modification to the high pressure turbine which inappropriately allowed bypassing of a required trip function of the reactor protection system beyond 30% RTP. This finding was determined to be of very low safety significance because the reactor trip was unavailable for only a very limited power band (30-34% RTP) and the function of the high dome pressure trip was available to mitigate the consequences of a turbine trip at low reactor power. The cause of this finding was directly related to the cross-cutting

aspect of complete, accurate and up-to-date design documentation, procedures, and work packages in the area of Human Performance; in that the work scope for conducting the necessary post maintenance testing was inadequate to ensure the set point armed the trip prior to reaching 30% RTP (H.2(c)). (Section 4OA3.6)

Inspection Report# : 2007004 (pdf)

Significance: Sep 30, 2007 Identified By: Self-Revealing

Item Type: FIN Finding

## Moisture Separator Level Control System Failure Due To Improperly Installed Compression Fitting Causes Unit 1 Reactor Scram

Green. A Green self-revealing finding was identified for poor work practices and inadequate oversight that allowed for the improper installation of a critical compression fitting on the Feedwater Heater and Moisture Separator Level Control panel that caused the 1A2 level control system to fail, directly resulting in a reactor scram. All compression fittings on the Unit 1 Main Feedwater Heater, Moisture Separator, and Main Steam control panels were subsequently checked and tightened as necessary. This finding was entered into the licensee's corrective action program as PERs 126049 and 126054.

This finding is greater than minor because it is associated with the Initiating Event Cornerstone attributes of Human Performance, and adversely affected the cornerstone objective to limit the likelihood of those events that upset plant stability and challenge critical safety functions during at-power operations. The finding was determined to be of very low safety significance because it did not contribute to both the likelihood of a reactor trip and the likelihood that mitigating equipment or functions were not available. The cause of this finding was directly related to the crosscutting aspect of supervisory and management oversight of contractor activities in the area of Human Performance; in that inadequate oversight of contractor activities allowed for poor installation practices and inadequate leak checks that resulted in the failure of a critical compression fitting which directly led to a reactor scram (H.4(c)). (Section 4OA3.7)

Inspection Report# : 2007004 (pdf)

Significance: Jun 30, 2007 Identified By: Self-Revealing

Item Type: NCV NonCited Violation

# Non-Conservative APRM/LPRM Gain Settings Result in Neutron Flux Setdown Setpoint in Excess of TS Limit (Section 1R15)

Green. A self-revealing Green noncited violation was identified for a violation of Unit 1 Technical Specifications 3.3.1.1.A.1 and Table 3.3.1.1-1, Function 2a, Reactor Protection System Instrumentation, on two separate occasions when Unit 1 entered Mode 2 on May 21 and 26, 2007, with non-conservative Average Power Range Monitor (APRM) and Local Power Range Monitor (LPRM) Gain Adjustment Factor (GAF) settings that resulted in the APRM Neutron Flux - High Setdown trip function exceeding the allowed TS setpoint limits. The nonconservative LPRM/APRM GAF settings were discovered as a result of the licensee's inability to adjust APRMs beyond the current indicated power level during a calibration, but were properly set prior to Mode 1 operation. This finding was entered into the licensee's corrective action program as PER 125408.

This finding was considered to be greater than minor because it was associated with the configuration control attribute of the Mitigating Systems Cornerstone due to loss of control of critical gain settings that adversely affected operability of the high neutron flux trip (setdown) function of the neutron monitoring system. Furthermore, this finding exceeded a Technical Specifications limit. This finding was determined to be of very low safety significance because the APRM Neutron Flux - High Setdown trip function was only a backup or secondary scram function to the Intermediate Range Monitor (IRM) Neutron Flux - High function while in Mode 2, and no safety analyses took credit for the APRM Setdown function. Consequently, the finding did not result in a loss of a safety function (high neutron flux scram at low power) for a system or train. The cause of this finding was directly related to the aspect of "appropriately coordinating work activities" in the cross-cutting area of Human Performance (Work Control component) because the LPRM work scope for conducting the necessary post maintenance testing to ensure the gain settings were properly set was deferred without considering the potential operational impact. (Section 1R15)

Inspection Report# : 2007003 (pdf)

### **Barrier Integrity**

#### **Emergency Preparedness**

#### **Occupational Radiation Safety**

**Significance:** Mar 31, 2007 Identified By: Self-Revealing

Item Type: NCV NonCited Violation

#### Two Examples of Failure to Perform Adequate Surveys.

Two examples of a Green self-revealing non-cited violation of 10 CFR 20.1501(a)(2)(i) were identified for failure to conduct surveys that were reasonable under the circumstances to evaluate the magnitude and extent of radiation levels in areas where work was performed. On February 9 and 16, 2007, investigation into electronic dosimeter dose rate alarms, received during work activities, revealed dose rates in excess of those measured during pre-job surveys. Since the new dose rates exceeded the criteria for posting as a high radiation area, the licensee immediately posted and controlled these areas as high radiation areas. This finding was entered into the licensee's corrective action program as PERs 119482 and 119829.

This finding is more than minor because it is associated with the Occupational Radiation Safety Cornerstone attribute of Program and Process, and it adversely affected the cornerstone objective because the failure to conduct adequate surveys did not ensure adequate protection of worker health and safety from exposure to radiation. Using the Occupational Radiation Safety Significance Determination Process, the finding was determined to be of very low safety significance because the failures to survey did not pose a substantial potential for over exposure and did not affect the ability to assess doses. The cause of the finding was directly related to the work activity coordination aspect of the human performance cross-cutting area because pre-job radiological surveys were inadequate to apprise personnel of plant conditions that affected work activities.

Inspection Report# : 2007002 (pdf)

#### **Public Radiation Safety**

Significance: Mar 31, 2007 Identified By: Self-Revealing

Item Type: NCV NonCited Violation

#### Failure to Properly Prepare a Radioactive Materials Package for Shipment

A Green self-revealing non-cited violation of 10 CFR 71.5 was identified for failure to properly package radiological material such that, under conditions normally incident to transportation, the radiation levels at the external surface of the package would not exceed applicable Department of Transportation (DOT) limits. When the two shipments arrived at a processing facility on April 21, 2005, the radiation dose rates measured on portions of the external surface of the packages were as high as 300 mrem/hr, which was in excess of the 200 mrem/hr limit specified by the regulation. The licensee established additional supervisory review and approval prior to shipping packages approaching DOT limits. This finding was entered into the licensee's corrective action program as PER 81364.

This finding is more than minor because it is associated with the Plant Facilities/ Equipment and Instrument attribute of the Public Radiation Safety cornerstone and adversely affected the cornerstone objective, in that, the improper transportation packaging resulted in a shipping container with external dose levels exceeding regulatory requirements. Using the Public Radiation Significance Determination Process, the finding was determined to be of very low safety

significance because the areas on the packages with elevated radiation levels were inaccessible to the public and the radiation levels were less than two times the DOT limit.

Inspection Report# : 2007002 (pdf)

## **Physical Protection**

Although the NRC is actively overseeing the Security cornerstone, the Commission has decided that certain findings pertaining to security cornerstone will not be publicly available to ensure that potentially useful information is not provided to a possible adversary. Therefore, the <u>cover letters</u> to security inspection reports may be viewed.

#### **Miscellaneous**

Last modified: December 07, 2007