adapted 4/16/90



National Transportation Safety Board

Washington, D.C. 20594

Safety Recommendation

La 2230A

Date: May 4, 1990

In reply refer to: A-90-62

Mr. Owen Miyamoto Chief, Airports Division State Department of Transportation Honolulu International Airport Gate 29 Honolulu, Hawaii 96819

On February 23, 1988, a Boeing 747-122 operated by United Airlines as flight 811 departed Los Angeles, California, as a scheduled flight to Sydney, Australia, with en route stops at Honolulu, Hawaii, and Auckland, New Zealand. The flight departed Honolulu at 0155 on February 24, 1988, with 3 flight crewmembers, 15 cabin attendants, and 337 passengers. About 20 minutes into the flight, and near 23,000 feet, a rapid decompression occurred when the forward starboard cargo door separated from part of the cabin fuselage. The airplane returned to Honolulu International Airport, landing safely on runway 8L at 0234 where an emergency evacuation was conducted. Of the 355 occupants on board when the flight departed Honolulu, 9 were lost during the decompression; and 1 crewmember, 15 flight attendants, and 22 passengers were injured during the decompression and emergency evacuation.

Before the emergency landing at Honolulu, the flightcrew requested that all available rescue and medical equipment be on hand when they landed.

Honolulu International Airport is a "joint use" airport used by the State of Hawaii; the U.S. Air Force; and general aviation, commercial, air carrier, air taxi, and military aircraft. Aircraft rescue and firefighting (ARFF) services are provided by ARFF units of the airport and Hickam Air Force Base. When the crash alarm was broadcast, all civilian and military fire units responded and were in position within 1 minute at predesignated stations on runway 8L.

The Safety Board's investigation revealed two areas of concern related to the emergency response to the accident: lack of direct radio communication procedures between the airport and Hickam ARFF vehicles, and the camouflage colors of the Hickam vehicles.

Because there were no direct radio communications, the chief of the airport's ARFF units had to drive his vehicle to the vehicle of the chief of the Hickam units to coordinate positioning of the units for the landing of flight 811. The Hickam units and the airport's units operated on their own radio networks. Thus, while on scene they could not communicate directly by

radio, as this situation required. Although the two ARFF services had a common radio frequency assigned (as specified in the airport emergency plan), procedures for use of the common frequency had not been implemented. The Safety Board believes that such communication procedures should be developed expeditiously.

Therefore, as a result of its investigation, the National Transportation Safety Board recommends that the State of Hawaii Department of Transportation:

Develop, in cooperation with the Department of Defense, procedures for direct radio communication between aircraft rescue and firefighting vehicles operated by the State of Hawaii and Hickam Air Force Base that would be used when responding to airport emergencies at Honolulu International Airport. (Class II, Priority Action) (A-90-62)

Also as a result of its investigation, the Safety Board issued safety recommendations to the Department of Defense and to the Federal Aviation Administration.

The National Transportation Safety Board is an independent Federal agency with the statutory responsibility "...to promote transportation safety by conducting independent accident investigations and by formulating safety improvement recommendations" (Public Law 93-633). The Safety Board is vitally interested in any actions taken as a result of it's safety recommendations and would appreciate a response from you regarding action taken or contemplated with respect to the recommendation in this letter. Please refer to Safety Recommendation A-90-62 in your reply.

KOLSTAD, Chairman, COUGHLIN, Acting Vice Chairman, LAUBER and BURNETT, Members, concurred in this recommendation.

y; James L. Kolstad

Chairman