

Office of Aviation Safety

Pinnacle Airlines Flight 3701 Jefferson City, Missouri Operational Factors Captain David Tew

STAL

Operational Issues

 Failure to follow climb procedures Deterioration of airspeed at FL 410 Stall recognition and reaction Double Engine Failure procedures Emergency landing preparation Lack of high altitude training



Climb Procedures

- Minimum climb speed was 250 Knots / .70 Mach
- FL370 speed was .63 Mach
- Speed deteriorated during climb to FL410
- FL410 speed was .57 Mach



Board Meeting DCA05MA003

Flight Level 410

Speed continued to deteriorate
Unable to maintain FL410
Airplane approached a stall condition

Crew failed to take corrective action

Stall Recognition and Reaction

- Airplane entered impending stall condition
- Stick shaker and stick pusher activated
- Crew countered stick pusher
- Stick pusher activated 4 times
- Crew failed to allow airplane to recover



Double Engine Failure Procedures

- Emergency checklist delayed
- Target airspeed .70 Mach or 240 knots
- Windmill start required 300 knots
- Captain failed to ensure 300 knots airspeed was obtained
- Highest airspeed momentarily reached was 236 knots



Emergency Landing Preparation

- Land at nearest suitable airport
- Crew overflew several suitable airports
- Crew did not notify ATC immediately
 When notified ATC responded
 Crew unable to reach Jefferson City




High Altitude Training

- Minimal
- Approach to stall training performed in simulators and at lower altitudes
- High altitude stall procedures are different from lower altitude stall procedures
 - Decrease pitch and descend







Primary Flight Display Pilot's and Copilot's Instrument Panels

