

# NTSB Board Meeting AA Flight 587



## Composite Materials and Wreckage Examination


Matthew R. Fox, Ph.D.




# Vertical Stabilizer and Rudder



Composite Layers





Vertical Stabilizer  
(Internal Structure)



# Examination

## Methods

- Visual and Fractographic Examination
- Nondestructive Inspection (NDI)
- Materials Testing and Microstructural Examination
- Lug Tests




# Visible Damage



Visible damage observed at rudder hinge line and lug locations.



Some lug pieces remained attached to the fuselage.




# Fractographic Examination

## Methods and Results


- Composite fractures examined at high magnification using scanning electron microscopy
- Lug area fractures photographed at more than 300 locations
- Over 500 square inches of crack surfaces examined at high magnification
- No fatigue observed




# Fracture Pattern



# Fracture Pattern




# Fracture Pattern



**Consistent with overload bending to the left**





# Right Rear Lug Fracture



- Structural analysis predicted fracture initiation at the location circled in red.
- Structural analysis was consistent with damage observed.

# Lug Tests



Fracture pattern for the accident right rear lug was as expected given the accident loads.

# Summary

- Composite structure was manufactured as expected.
- No evidence of preexisting damage was observed.
- Damage patterns were consistent with an overload failure in bending to the left.



# National Transportation Safety Board



American Airlines Flight 587  
Belle Harbor, New York  
November 12, 2001

NTSB Board Meeting  
October 26, 2004

