

VI. RECOMMENDATIONS

The National Transportation Safety Board recommends that:

- 1. The Federal Railroad Administration conclude the proposed rulemaking regarding the transportation of liquefied flammable gases in tank cars of DOT Specifications 112A and 114A having capacities exceeding 25,000 gallons. This rulemaking was initiated with the Hazardous Materials Regulations Board's "Request for Public Advice on Speed Restriction on Tank Cars," Docket No. HM-60, published in the Federal Register on October 15, 1970. *R(72-20)*
- 2. The Association of American Railroads and the Federal Railroad Administration encourage the expeditious completion of the testing of insulating materials for the coating of the outside of tanks, and, if a satisfactory material is found, require its use on all tank cars transporting flammable liquids (liquefied flammable gases). *R(72-21)*
- 3. The Federal Railroad Administration encourage the expeditious completion of the RPI-AAR Railroad Tank Car Safety Research and Test Project and take steps to insure that the results of the research are applied to enhance the safety of transportation of hazardous materials. *R(72-22)*
- 4. The Federal Railroad Administration promptly publish their current study of the failure of freight car journals, and if necessary, continue such studies so that regulations can be promulgated to establish standards for freight car journals and their maintenance. *R(72-23)*
- 5. All railroads which proposed action in response to the July 7, 1970, letter of the Chairman of the National Transportation Safety Board advise the Federal Railroad Administration of the action taken by them and that these railroads and all others who transport liquefied flammable gas in DOT Specification 112A and 114A tank cars *R(72-24)*

*R-72-20-24*

V. PROBABLE CAUSE

The National Transportation Safety Board determines that the probable cause of this accident was the breaking of the L-4 journal of CB&Q 182544, the 20th car, due to excessive overheating, which permitted the truck side to drop to the track and derail the leading wheels of the car. The cause of the overheating could not be determined.

The cause of the initial fire was the puncturing of one tank during the derailment, the jumbling of the derailed cars, and the large volume of propane released which immediately ignited and subjected the other tanks to impingement of fire.

The cause of the explosive rupture of several tanks was localized heating which weakened the steel of the tank so that it could no longer resist the pressure of the propane. Contributing to the explosive rupture were (1) the placement of a number of tank cars together in the train which permitted interaction between cars, (2) the speed of the train which tended to allow jumbling of cars to occur, and (3) the absence of heat insulation of the cars which was formerly required.

The injury to the firemen and spectators was due to the lack of appreciation by firemen of the large scope of fire and explosion which could occur in a fire of this type.

