



Report DOE/PC/90545-3
M96050293

RECEIVED

SEP 09 1996

Addendum to
OST Long-Term Testing Report

FULL-SCALE DEMONSTRATION OF LOW-NO_x CELL™ BURNER RETROFIT

September 1994 Outage:
Examination of Corrosion Test Panel
and UT Survey in DP&L Unit #4

We have no objection from a parent
standpoint to publication or
dissemination of this material.

M. D. Dwyer
Office of Intellectual
Property Counsel
DOE Field Office, Chicago

7-10-94
Date

Prepared for
The U. S. Department of Energy
Under Cooperative Agreement DE-FC22-90PC90545
(B&W CRD-1250)

Submitted by
Babcock & Wilcox
A McDermott Company

June 1995

DISCLAIMER

**Portions of this document may be illegible
in electronic image products. Images are
produced from the best available original
document.**

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

FULL-SCALE DEMONSTRATION OF LOW-NO_x CELL BURNER RETROFIT

**Addendum
to
Long-Term Testing Report**

June 1995

Report DOE/PC/90545-3

Prepared By

S. C. Kung and R. J. Kleisley

Sponsored By

The U. S. Department of Energy

Work Performed Under Cooperative Agreement DE-FC22-90PC90545
(B&W CRD-1250)

DOE Program Manager

R. Corbett

Babcock & Wilcox
Research and Development Division
Alliance Research Center
Alliance, OH 44601-2196

ACKNOWLEDGMENTS

The project organization is comprised of the following groups:

- DOE — funding co-sponsor
- Babcock & Wilcox (B&W) — prime contractor, project manager and funding co-sponsor
- Dayton Power & Light (DP&L) — host site utility, operations and construction management and funding co-sponsor
- Electric Power Research Institute (EPRI) — testing consultant and funding co-sponsor
- State of Ohio Coal Development Office (OCDO) — funding co-sponsor
- Acurex Environmental Corporation (Acurex) — testing subcontractor
- Utility funding co-sponsors:
 - Allegheny Power System
 - Centerior Energy
 - Duke Power Company
 - New England Power Company
 - Tennessee Valley Authority
 - Cincinnati Gas & Electric Company
 - Columbus and Southern Ohio Power Company

DP&L agreed to be the host utility for the full-scale demonstration of the LNCB, offering the use of J.M. Stuart Station Unit No. 4 (JMSS4) as the host site. JMSS4 is a B&W 605 MW, Universal Pressure (UP) boiler, a once-through design, originally equipped with 24, two-nozzle cell burners arranged in an opposed wall configuration.

"Legal Notice"

This report was prepared by the Babcock & Wilcox Company (B&W), pursuant to a Cooperative Agreement partially funded by the U.S. Department of Energy, and either B&W, nor any of its subcontractors, nor the U.S. Department of Energy, nor any person acting on behalf of either:

- a. makes any warranty or representation, express or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of any information, apparatus, method, or process disclosed in this report, may not infringe privately-owned rights; or
- b. assumes any liabilities with respect to the use of, or for damages resulting from the use of, any information, apparatus, method or process disclosed in this report.

Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the U.S. Department of Energy. The views and opinions of authors expressed herein do not necessarily state or reflect those of the U.S. Department of Energy.

Addendum to Long-Term Testing Report

Table of Contents

| <u>Section</u> | <u>Page</u> |
|--|-------------|
| 1.0 INTRODUCTION..... | 1 |
| 2.0 METALLURGICAL EXAMINATION OF CORROSION TEST PANEL..... | 2 |
| 2.1 Sampling Location of Corrosion Test Panel..... | 2 |
| 2.2 Determination of Tube Wastage on Corrosion Test Panel..... | 5 |
| 3.0 RESULTS AND DISCUSSION - CORROSION TEST PANEL..... | 6 |
| 3.1 Tube Wastage of Corrosion Test Panel..... | 6 |
| 3.2 Metallurgical Examination on Corrosion Test Panel..... | 15 |
| 4.0 ULTRASONIC THICKNESS MEASUREMENT OF FURNACE WALLS..... | 23 |
| 4.1 History of UT Survey..... | 23 |
| 4.2 Sampling Locations of UT Survey..... | 26 |
| 4.3 Procedures of UT Survey..... | 27 |
| 5.0 RESULTS AND DISCUSSION ON UT SURVEY..... | 27 |
| 6.0 CONCLUSION..... | 28 |
| 7.0 RECOMMENDATIONS..... | 29 |
| 8.0 REFERENCES..... | 29 |
| APPENDIX A..... | 30 |

List of Figures and Table

| | | |
|-------------|---|----|
| Figure 1 - | Drawing of the corrosion test panel remained on the west sidewall of JMSS4 prior to the Fall 1994 Outage..... | 4 |
| Figure 2 - | Measured "mean" OD thicknesses of the bare and chromized T2 tubes at the bottom elevation of the corrosion test panel..... | 7 |
| Figure 3 - | Measured "mean" wall losses of the bare and chromized T2 tubes at the bottom elevation of the corrosion test panel..... | 8 |
| Figure 4 - | Comparison of wall thickness losses on bare T2 tubes from two outages at the bottom elevation of the corrosion test panel..... | 11 |
| Figure 5 - | Variation of corrosion rates of bare T2 and chromized tubes with the tube location at the bottom elevation of the corrosion test panel..... | 13 |
| Figure 6 - | Comparison of the linear corrosion rates of bare T2 tubing with time at the bottom elevation of the corrosion test panel..... | 14 |
| Figure 7 - | Cross-sectional SEM micrograph of bare T2 from Tube 79 at the bottom elevation of the corrosion test panel..... | 16 |
| Figure 8 - | Cross-sectional SEM micrograph of Al-sprayed T2 at the bottom elevation of the corrosion test panel..... | 18 |
| Figure 9 - | Cross-sectional SEM micrograph of 309 weld-overlaid T2 at the bottom elevation of the corrosion test panel..... | 20 |
| Figure 10 - | Cross-sectional SEM micrograph of 308 weld-overlaid T2 at the bottom elevation of the corrosion test panel..... | 21 |
| Figure 11 - | Cross-sectional SEM micrograph of chromized T2 from Tube 75 at the bottom elevation of the corrosion test panel..... | 22 |
| Figure 12 - | Locations of Furnace Walls Where the Surfaces were Grit-Blasted and UT Measured for Remaining Tube Thicknesses..... | 25 |
| Table 1 - | Identification of First and Second Passes on the Corrosion Test Panel..... | 9 |

1.0 INTRODUCTION

As part of the DOE "Full-Scale Demonstration of Low NO_x Cell Burner Retrofit" program, a corrosion test panel was installed on the west sidewall of Dayton Power & Light Unit #4 at the J. M. Stuart Station (JMSS4) during the burner retrofit outage in November 1991. The test panel, with an original dimension of 12 feet long by 80 tube wide, consisted of four sections of commercial coatings separated by bare SA213-T2 tubing. Details of the test panel layout and location of installation were discussed in the Long-Term Testing Report¹ issued by B&W in March 1994. During the retrofit outage, a UT survey was performed to document the baseline wall thicknesses of the test panel, as well as several furnace wall areas outside the test panel. The purpose of the UT survey was to generate the baseline data so that the corrosion wastage associated with the operation of Low NO_x Cell Burners (LNCB[®] burner) could be quantitatively determined.

The corrosion test panel in JMSS4 was examined in April 1993 after the first 15-month operation of the LNCB[®] burners. Wall segments approximately 6 inches in height were cut out from the top and bottom portions of the test panel and sent to B&W for destructive metallurgical analysis. The corrosion wastage on the bare T2 tubes across the test panel was determined statistically, and the corrosion resistance of the four coatings was evaluated metallographically. The results revealed that the bare T2 tubing on the test panel located in areas near the front wall did not suffer any meaningful wastage; however, bare T2 positioned in areas near the center line of the west side wall showed relatively high metal losses. A maximum metal wastage of 21 mils was measured on the bare T2 tubes after the first 15 months operation, which was equivalent to a corrosion rate of approximately 17 mils per year (mpy). The aluminum-spray coating suffered localized corrosion attack underneath the coating layer due to high coating porosity introduced from the coating process. However, the chromized and the two weld-overlay coatings exhibited excellent corrosion resistance to the low-NO_x combustion environment in JMSS4. UT survey was also performed during the Spring 1993 outage; however, determination of the tube wastage based on the UT data was inconclusive. Details of the corrosion analysis and UT data were documented in the Long-Term Testing Report.¹

The second JMSS4 outage following the LNCB[®] burner retrofit took place in September 1994. Up to this point, the test panel in JMSS4 had been exposed to the corrosive combustion environment for approximately 31 months under normal boiler operation of JMSS4. This test period excluded the down time for the April 1993 outage. During the September 1994 outage, 70 tube samples of approximately one-foot length were cut from the bottom of the test panel. No samples were retrieved from the top portion of the panel due to funding constraints. These samples were evaluated by the Alliance Research Center of B&W using the same metallurgical techniques as those employed for the previous outage. In addition, UT measurements were taken on the same locations of the lower furnace walls in JMSS4 as those during the prior outages. Results of the metallurgical analyses and UT surveys from different exposure times were compared, and the long-term performance of waterwall materials was analyzed. The corrosion data obtained from the long-term field study at JMSS4 after 31 months of LNCB[®] burner operation are summarized in this stand-alone addendum report.

2.0 METALLURGICAL EXAMINATION OF CORROSION TEST PANEL

2.1 Sampling Location on Corrosion Test Panel

Because of funding constraints during the second outage, only one cross cut could be made to retrieve samples from the corrosion test panel for metallurgical examinations. It was therefore decided to select the tube samples from either the top or bottom portion of the test panel, depending upon which location had suffered more corrosion wastage. The sample analyses from the April 1993 outage after the first 15 months operation revealed that the bare T2 tubes at the bottom location of the test panel had suffered more metal losses than those at the top. With the burner operating parameters unchanged, the bottom portion of the test panel should have continued to suffer more corrosion attack during the next 16-month operation. However, to ensure the worst area being investigated, the final decision regarding the sampling location was postponed until the September 1994 outage, during which the surfaces of the test panel were visually examined.

Inspection of the corrosion test panel indeed revealed that the wastage was more severe toward the bottom location. Two major observations were noted to support this generalization. First, the color of the coal ash deposit existing on the test panel was darker at the bottom elevation, suggesting that a higher amount of unburned carbon was present in this region. The higher unburned carbon content indicates that the combustion gas in this region was more reducing. Secondly, the lower surfaces of the test panel contained a number of spots where the ash deposit and perhaps corrosion products (scale) had exfoliated before the inspection. Exfoliation is indicative of a thicker deposit/scale formation on the tube surfaces, which is more susceptible to thermal cycling and other types of physical damage associated with boiler operations. Corrosion rates can be significantly enhanced if fresh metal is constantly exposed to the combustion gases. Consequently, it was decided to remove the panel samples from the bottom location for corrosion analyses.

Figure 1 is a drawing of the corrosion test panel installed on the west sidewall of JMSS4. The panel layout is viewed from outside of the furnace wall facing east. Therefore, the assigned tube numbers increase as the tube location approaching the center line of the west sidewall. The initial length of the corrosion test panel installed in JMSS4 was 12 feet. About six inches of materials were removed from both the top and bottom portions of the test panel during the April 1993 outage. As a result, the remaining panel length during the last 16-month operation was approximately 11 feet. The shaded areas at the panel bottom represents the one-foot long tube samples that were retrieved from the September 1994 outage. Figure 1 also indicates the approximate locations of four gas sampling ports. The bare T2 tubes immediately adjacent to the sampling ports were not removed so that these ports can be used for future in-furnace gas analysis.




Figure 1 - Drawing of the corrosion test panel remained on the west sidewall of JMSS4 prior to the Fall 1994 Outage.

2.2 Determination of Tube Wastage on Corrosion Test Panel

Corrosion wastage of the sample tubes was determined statistically based on the measured changes of outer diameters (ODs) before and after the overall 31-month operation at JMSS4. The original ODs were measured from the archived tube samples cut off from the ends of the corrosion test panel prior to the panel installation. The final ODs were measured from the exposed samples retrieved from the September 1994 outage. The OD measurements were performed by first grit-blasting the tube surfaces to remove all coal ash deposit and corrosion products (scale), followed by measuring the ODs with a certified micrometer at several locations of each tube sample (without hitting the membranes). Efforts were made to achieving an identical grit-blast finish on all tube surfaces.

As demonstrated in the Long-Term Testing Report,¹ determination of the corrosion wastage based on the tube OD losses, followed by statistical analysis, is a viable approach. Variation in the tube ODs is generally much smaller than that of other types of dimensions, such as tube wall thickness and surface scale thickness. Consequently, corrosion-rate calculations based on the "mean" OD changes can generate much reliable corrosion data.

The OD measurements were performed on the same bare T2 and chromized tubes as those examined previously during the April 1993 outage, i.e., the first outage after the burner retrofit. Therefore, a direct comparison of the metal wastage as a function of exposure time at the completion of 15 months (April 1994) and 31 months (September 1994) is possible. The locations of the bottom samples retrieved from each tube during these two outages were only ~8 inches apart vertically. Therefore, due to the short distance, the bottom samples of the same tube retrieved from two different times can be assumed to have subjected to similar combustion environments. Consequently, the corrosion information obtained from these two outages can provide a trend of long-term corrosion behavior for the waterwalls of JMSS4 at the bottom elevation of the test panel.

3.0 RESULTS AND DISCUSSION - CORROSION TEST PANEL

3.1 Tube Wastage of Corrosion Test Panel

Figure 2 summarizes the "mean" OD thicknesses of bare and chromized T2 tubes from the bottom test panel after the field exposure for 31 months in JMSS4. The original mean ODs of the bare and chromized T2 tubing were 1.249 and 1.252 inches, respectively, as indicated by the horizontal lines. Cross-sectional metallographic examinations revealed that the maximum metal loss on the bare T2 outside the furnace (facing the windbox) was approximately 1 mil. This small loss was attributed primarily to oxidation of the metal with the heated air in the windbox. Therefore, the corrosion wastage of the bare T2 on the furnace fireside is equivalent to the total OD losses shown in Figure 2 minus 1 mil. Negligible wastage was found on the windbox side of the chromized tubes. Therefore, all wastage on the chromized T2 was attributed to fireside corrosion.

Figure 3 displays the mean wall losses (in mils) of the test panel on the fireside. The measurements indicate that the corrosion wastage of bare T2 increases with increasing tube number, with the highest tube loss being ~26 mils on Tube #79. This trend is consistent with the previous results from the April 1993 outage documented in the Long-Term Testing Report.¹ That is, higher corrosion wastage on the bare T2 was found near the center line of the west sidewall at the bottom elevation of the test panel.

It is also noted that the wall losses of each adjacent pair of bare T2 tubes are noticeably different, with one being higher than the other. Such a variation is again consistent with the corrosion results obtained from the April 1993 outage. It has been interpreted in the Long-Term Test Report that such variations were caused by an appreciable difference in the metal temperatures between each pair of tubing, as JMSS4 consists of two-pass furnace walls. Consequently, the metal

TUBE SAMPLES FROM BOTTOM OF TEST PANEL September 1994 Outage




Figure 2 - Measured "mean" OD thicknesses of the bare and chromized T2 tubes at the bottom elevation of the corrosion test panel.

TUBE SAMPLES FROM BOTTOM OF TEST PANEL
September 1994 Outage




Figure 3 - Measured "mean" wall losses of the bare and chromized T2 tubes at the bottom elevation of the corrosion test panel.

temperatures of the second-pass tubes would have been higher than those of adjacent first-pass, which led to higher corrosion wastage. Using the JMSS4 unit design data, the first and second passes of the waterwall tubes on the corrosion test panel were identified, which are summarized in Table 1.

Table 1 - Identification of First and Second Passes on the Corrosion Test Panel

| <u>Tube Numbers from Front Wall</u> | <u>Odd/Even Number</u> | <u>Pass</u> |
|-------------------------------------|------------------------|-------------|
| Tubes #1 - 19 | Odd | 2nd |
| Tubes #2 - 20 | Even | 1st |
| Tubes #21 - 61 | Odd | 1st |
| Tubes #22 - 60 | Even | 2nd |
| Tubes #63 - 79 | Odd | 2nd |
| Tubes #62 - 80 | Even | 1st |

Relating the wall-loss data in Figure 3 to the tube pass identifications in Table 1, the second-pass tubes indeed show higher corrosion wastage than their neighboring first-pass tubes. Therefore, this correlation agrees well with the previous interpretation, i.e., differences in the corrosion wastage of two adjacent tubes were primarily caused by their tube metal temperatures.

The measured metal wastage in Figure 3 for the bare T2 with tube numbers less than 15 scatters along the original OD thickness. Again, a similar observation was found on these tubes from the results of April 1993 outage (i.e., after the first 15-month exposure in JMSS4). Considering the standard deviation of the measurements, the scattering of wastage data signifies that negligible fireside corrosion has occurred on these bare T2 tubes at the bottom elevation of the test panel close to the front wall. The range of data scattering suggests that the standard deviation is approximately ± 2 mils.

Data of the chromized T2 tubes in Figure 3 also show no sign of wall losses at the bottom elevation of the test panel, even though they were located near the center line of the west sidewall where the corrosion attack on bare T2 was more severe. In fact, these coated tubes show "negative" wall losses compared to the archived samples. As discussed in the Long-Term Testing Report, the

negative tube losses were primarily caused by non-uniformity of the initial coating thickness on the as-chromized product. The coating thickness produced on the ends of an as-chromized tube panel, from which the archived samples were taken, was usually the thinnest. As a result, the OD thicknesses of the exposed chromized tubes which suffered negligible metal losses may appear to have increased when compared to the archived tube-end samples.

The wall thickness losses of some bare T2 tubes retrieved from both April 1993 and September 1994 outages are compared in Figure 4. Only those tubes showing meaningful amounts of corrosion wastage are plotted. As mentioned previously, the vertical distance of the bottom samples retrieved from each tube of the test panel during the two outages was only ~8 inches apart. Because no major changes in the operation of JMSS4 were incurred, the corrosive environment can be assumed to be identical on the test panel within this short vertical distance. Therefore, except for the difference in exposure time, the bottom samples from each tube would have been exposed to the same corrosive condition. Consequently, the corrosion data generated from these two outages may define the trend of metal loss with time and give a good indication of the materials long-term performance at the bottom elevation of the test panel on the west sidewall.

Two types of variations in the wall losses of bare T2 as a function of time can be deduced from Figure 4. If the standard deviation of the wall losses is taken as ± 2 mils as discussed previously, the trend of corrosion wastage on Tubes #36, 37, 43, and 80 may be considered linear with time. On the other hand, the trend for Tubes #42, 58, and 79, on which higher corrosion wastage was found, first increases sharply with time but levels off after longer exposure.

As discovered previously in the program, the primary mode of corrosion attack in the lower furnace of JMSS4 was sulfidation. The data in Figure 4 suggest that the metal wastage on bare T2 followed a linear trend when the sulfide scale formed on the tube surfaces was thin. The formation of a thin scale could have been attributed to either the combustion environment being less severe (e.g., in areas near the front wall) and/or the exposure time being insufficient (e.g., in the early stage of the sulfidation process). After the sulfide scale has grown thicker, some corrosion resistance may




Figure 4 - Comparison of wall thickness losses on bare T2 tubes from two outages at the bottom elevation of the corrosion test panel.

have eventually been established by the scale. Subsequently, the wall thickness loss deviated from the undesired linear trend.

The results presented above indicate that a thick sulfide-base scale might have caused deviation of the corrosion kinetics from linear behavior. Cross-sectional examinations of the bare T2 samples during both outages after the burner retrofit revealed that the sulfide scale on T2 was indeed dense and adherent to the metal. Such a thick sulfide scale would have acted as a diffusion barrier to impede the kinetics of the corrosion process, which in turn reduced the corrosion attack. Nevertheless, the sulfide scale formed on T2 under the reducing combustion environments of investigation should not be regarded as protective, as the corrosion rate of T2 from sulfidation is still much higher than that from oxidation when exposed to an oxygen-rich combustion gas.

Figure 5 illustrates the variation of corrosion rates in mil per year (mpy) with tube location for the bare T2 and chromized tubing. The corrosion rates were derived by linearly extrapolating the 31-month corrosion data (in Figure 3) to one year. As expected, the highest corrosion rate, ~10 mpy, occurs on the bare T2 tube of #79 at the bottom elevation of the test panel. The corrosion rate on the chromized T2 is negligible (the negative data points were caused by reasons discussed previously).

Figure 6 compares the linear corrosion rates of bare T2 tubes at the bottom location of the test panel after the 15 and 31-month exposures in JMSS4. The corrosion rates of Tubes #36, 37, 43, and 80 remain essentially constant with time. On the other hand, Tubes #42, 58, and 79 exhibit a trend of decreasing corrosion rate with exposure time. Again, the decrease is likely to have been attributed to the formation of a dense and adherent sulfide scale on T2. The highest corrosion rate observed on Tube #79 at the bottom elevation of the test panel has been reduced from 17 to 10 mpy during the total field exposure of 31 months.

TUBE SAMPLES FROM BOTTOM OF TEST PANEL September 1994 Outage




Figure 5 - Variation of corrosion rates of bare T2 and chromized tubes with the tube location at the bottom elevation of the corrosion test panel.




Figure 6 - Comparison of the linear corrosion rates of bare T2 tubing with time at the bottom elevation of the corrosion test panel.

A corrosion rate of 10 mpy is approaching a wastage level that was experienced on the furnace walls before the burner retrofit. At this level, performance of the unit would not be significantly affected if regular inspection and wall replacement are carried out during outages. If the beneficial characteristics of the sulfide scale continue to prevail, i.e., the scale being dense and adherent, the corrosion rate of bare T2 may be further decreased with time. On the other hand, if defects such as cracking and spallation are developed later on in the scale, the corrosion kinetics may change. Based on the available corrosion data, it is not possible to accurately predict longer term performance of the furnace walls beyond the current exposure period investigated. Therefore, continuing monitoring of the corrosion test panel in JMSS4 is recommended.

3.2 Metallographic Examinations on Corrosion Test Panel

Cross-sectional metallographic examinations were performed on some of the tube samples obtained from the September 1994 outage. The standard metallographic procedures were employed for cross-sectional sample preparation. The deposit and scale morphologies present on the sample surfaces, as well as their chemical compositions, were analyzed using an optical microscope and a secondary electron microscope (SEM) equipped with energy dispersive X-ray (EDS) analytical capabilities.

Similar to the metallographic analysis results from the April 1993 outage (after the first 15-month operation), the primary mode of corrosion attack on the test panel in JMSS4 was sulfidation. Sulfidation refers to the corrosion products formed on the metal surfaces being predominately sulfides. The growth rates of sulfides are generally much faster than those of corresponding oxides when formed on metals under an oxidizing environment. Therefore, the metal wastage is expected to be higher in the reducing combustion environments.

Figure 7 is an SEM micrograph of a bare T2 sample retrieved from the bottom of Tube #78. The EDX analysis indicated that the scale on the sample surface consisted of mixed corrosion products, mostly iron sulfide (presumably FeS) and some iron oxide (presumably Fe₃O₄). The scale




Figure 7 - Cross-sectional SEM micrograph of bare T2 from Tube 79 at the bottom elevation of the corrosion test panel.

exhibited a double-layered morphology, with the outer layer containing some embedded ash particles and the inner layer being essentially ash-particle free. Such a morphology implies that the growth mechanism of this corrosion product on bare T2 involved both inward and outward diffusion. The inward scale growth would have been dominated by the diffusion of sulfur from the gas/scale interface to the scale/metal interface of the sulfide layer, and the outward growth involved the diffusion of iron in the opposite direction.

A similar scale morphology was found on all bare T2 tubes across the test panel; however, thicknesses of the scales formed on the tube surfaces increased with increasing tube number. This trend is consistent with the wall-loss data in Figure 3, of which more corrosion wastage took place in areas near the center line of the west sidewall. The sulfide scale in Figure 7 is dense and adherent to the underlying metal. As discussed earlier, such a scale morphology is desirable, which has resulted in improved corrosion resistance of T2 tubing by serving as a diffusion barrier to impede the corrosion kinetics.

The cross-sectional SEM micrograph of an aluminum (Al)-spray coating on T2 is shown in Figure 8. It is noted that the Al-sprayed T2 tubes on the test panel were situated close to the front wall of JMSS4. Therefore, as illustrated by the wall-loss data, severity of the corrosion attack in this wall area was relatively mild. However, EDX analysis still revealed a large amount of sulfur existing at the coating/substrate interface. The presence of sulfur in this region suggests that sulfur has penetrated into the coating layer and consequently reacted with the surface of T2. This mode of sulfidation attack indicates that the coating was porous and unable to prevent the corrosive gases from reaching the T2 substrate. Such findings are again consistent with the results of previous laboratory studies in this program as well as the first examinations of the corrosion test panel during the April 1993 outage. The results of these previous studies were documented in the Long-Term Testing Report.¹




Figure 8 - Cross-sectional SEM micrograph of Al-sprayed T2 at the bottom elevation of the corrosion test panel.

Figures 9 and 10 are the cross-sectional SEM micrographs of 309 and 308 weld-overlay coatings on T2 tubes, respectively. The surface composition of 309 weld overlay is equivalent to that of 309SS (Fe-22Cr-12Ni), and the surface chemistry of 308 weld overlay is comparable to that of 304SS (Fe-18Cr-8Ni). After the 31-month field exposure, both coatings demonstrated excellent corrosion resistance to the sulfidation attack in JMSS4. The surfaces of these weld overlays have formed a thin corrosion scale underneath the coal ash layer. EDS analyses revealed that the scale was rich in Cr and O, and also contained some Fe, Ni, and S. These compositions suggest that the scales consist of primarily Cr-rich spinel oxide and a small amount of spinel sulfide. As mentioned previously, the formation of an oxide-base scale on metal can provide much better corrosion protection than the corresponding metal sulfide. Consequently, the good performance of these weld overlaid T2 in JMSS4 was attributed to the ability of oxide formation on these coated surfaces upon exposure to the reducing combustion gases. These findings are again in agreement with the previous field study during the April 1993 outage after the corrosion test panel had been exposed for 15 months.

On the chromized tubing, a protective scale also formed over much of the sample surfaces. EDX analysis showed that the chemical composition of this scale was rich in Fe, Cr, and O, and contained very little S. Therefore, similar to the weld overlays, the surface scale consisted primarily of spinel oxide. Figure 11(a) is a cross-sectional optical micrograph showing the typical chromized T2 surface after the 31-month exposure in JMSS4. The bright phase existing on the surface as well as along the columnar grain boundaries of the coating layer is chromium carbide formed during the chromizing treatment. The ash layer and scale were apparently lost during the cross-section preparation. The micrograph in Figure 11(a) reveals that the microstructure of the chromized tubing after the exposure remains essentially identical to that of as-coated, and no meaningful corrosion attack has occurred. Therefore, sulfidation in the lower furnace of JMSS4 has been significantly retarded by the use of chromizing coating.

Close examinations of the chromized T2 sample disclosed a few areas where the corrosion attack has penetrated into the coating layer, as shown on the right portion of the coating layer in






Figure 9 - Cross-sectional SEM micrograph of 309 weld-overlaid T2 at the bottom elevation of the corrosion test panel.



Figure 10 - Cross-sectional SEM micrograph of 308 weld-overlaid T2 at the bottom elevation of the corrosion test panel.



(a)



(b)

Figure 11 - Cross-sectional micrographs of chromized T2 from Tube 75 at the bottom elevation of the corrosion test panel.

Figure 11(b). The finger-like corrosion front apparently proceeded along the columnar grain boundaries of the coating layer. It is believed that this localized attack was initiated by the residual halide salt remained on the surfaces from the chromizing treatment, and the attack had occurred during the storage period before the test panel went into service. Removal of the halide salt from the finished surfaces would have eliminated this problem. It is noted that the chromium carbide layer on the outer surface as well as the chromium carbide precipitates within the grain boundaries were virtually unaffected by the field exposure. Therefore, without the residual halide salt, chromizing should have performed equally well as those weld-overlay coatings in the reducing combustion gases.

Furthermore, even the deepest corrosion penetration in the chromized coating terminated at the coating/substrate interface. Beyond this point, the corrosion attack proceeded laterally. The change of the attack path was probably attributed to the presence of a very thin corrosion-resistant carbide layer at the coating/substrate interface. Apparently, this interfacial carbide was very corrosion resistant and has prevented the corrosion front from penetrating into the T2 substrate

It should be mentioned that several modified chromizing processes have been recently developed by B&W, which can optimize the microstructure of the carbide precipitates in the coating layer. In addition, the chromizing/siliconizing co-diffusion coating under B&W's near-term development may eliminate the decarburized zone underneath the coating layer. Therefore, the performance of these next-generation diffusion coatings is expected to be further improved when exposed to the reducing combustion gases.

4.0 ULTRASONIC THICKNESS MEASUREMENT OF FURNACE WALLS

4.1 History of UT Survey

B&W and DP&L have performed a series of UT measurements on the lower furnace walls of JMSS4 during the last four scheduled outages that took place in April 1990, November 1991,

April 1993, and September 1994. The UT survey in Spring 1990 was performed prior to the LNCB[®] burner retrofit, the Fall 1991 outage was during the burner retrofit, and the other two were after the retrofit.

The UT data obtained from the April 1990 outage revealed that some areas of the JMSS4 furnace walls had already suffered high corrosion wastage resulting from the standard cell burner operation. The lowest remaining wall thickness from this survey was 160 mils (0.160 inch), approaching the flag point for furnace wall replacement. Consequently, some areas of the furnace walls were replaced. DP&L attributed the severe tube wastage to the existence of reducing combustion gases in the lower furnace due to improper mixing of coal and air. Because of the replacement of some furnace walls, most of the UT data obtained from the 1990 outage could no longer be used as the baseline. Nevertheless, this UT survey was imperative to selection of the location for installation of the corrosion test panel.

During the LNCB[®] burner retrofit outage in November 1991, a number of UT measurements were again taken. The survey included eight horizontal bands along the furnace walls and 12 points around each burner cell. In addition, the UT measurements were obtained from the corrosion test panel at 6 elevations ranging from 578 feet-6³/₄ inches to 590 feet-5³/₄ inches at a 2-foot interval. Figure 12 illustrates the furnace wall areas where the surfaces were grit-blasted and UT surveyed. When possible, a total of five UT readings were obtained from each sampling point, a half inch apart vertically between two adjacent points, so that an averaged wall thickness at that location could be derived. These UT results were then considered as the new baseline for calculations of the furnace wall wastage.

In the April 1993 outage, after approximately 15-month operation of the LNCB[®] burners in JMSS4, a UT survey was again performed on the lower furnace walls. Whenever accessible, the survey repeated the five UT measurements at each sampling location as those performed in November 1991. Details of all previous UT surveys and averaged readings were summarized in the Long-Term Testing Report.¹




Figure 12 - Locations of Furnace Walls Where the Surfaces were Grit-Blasted and UT Measured for Remaining Tube Thicknesses.

Because of inconsistency in the measuring techniques encountered, the UT data from the previous outages could not clearly indicate the trend of corrosion wastage with time on the furnace walls. Therefore, expansion of the UT data was needed. It was decided that the UT survey be carried out again in JMSS4 during the Fall 1994 outage.

4.2 Sampling Locations of UT Survey

The locations where the UT survey was performed on the furnace walls of JMSS4 in Fall 1994 were identical to those shown in Figure 12. However, the UT survey was carried out after several burner panels had already been replaced. In addition, some new replacement panels were hung on the furnace walls adjacent to the burners. These replacement panels hindered the accessibility of UT measurements to the areas underneath. Consequently, the UT measurements at a number of sampling points adjacent to the burners had to be omitted. These areas, either already replaced or inaccessible, include:

1. Burner Panel for 4B4L and 4B4U,
2. Burner Panel for 4D5L and 4A5U,
3. Burner panel for 4E4L and 4E4U, and
4. Burner panels for 4C1L and 4F1U.

Furthermore, the surfaces of two furnace wall areas in JMSS4 had not been grit-blasted prior to the UT measurements. As a result, a significant degree of error must have been introduced to the measured data by the presence of a coal ash layer on the tube surfaces. These non-blasted areas are:

1. Elevation 601 feet-6 inches on the RHSW, and
2. Elevation 588 feet-4 inches on the RHSW within the corrosion test panel.

4.3 Procedures of UT Survey

Personnel from B&W and DP&L collaborated in the Fall 1994 UT measurements. The equipment used for the Fall 1994 survey consisted of Sonic Mark I flow detectors and Harisonic 15 MHz transducers with a 0.25 inch contact diameter. Like the previous UT measurements, five readings were taken at each sampling point. The averaged value from each sampling location was calculated and then carefully compared to those of adjacent locations to eliminate any obvious discrepancy caused by equipment and human errors.

It should be pointed out that the data generated from UT measurement usually involve a fairly large standard deviation. There are three primary sources for this deviation:

1. Tube ID scale/deposit - The scale buildup on the ID surfaces can cause as much as ± 5 mils (0.005 inch) to the UT readings.
2. Equipment reproducibility - The flaw detector has a reproducibility limit of ± 3 mils (0.003 inch).
3. Operator inconsistency - Operator's interpretation on the UT signals introduces additional uncertainty.

As a result, the overall standard deviation associated with UT measurement can be as large as ± 15 mils. When evaluating the UT data and making comparison, the range of standard deviation must be considered.

5.0 RESULTS AND DISCUSSION ON UT SURVEY

The averaged readings of remaining wall thicknesses at various sampling locations from the last three UT surveys are summarized in Appendix A. When possible, the replacement history on these wall areas is also documented. In comparison, the readings obtained from the Spring 1993

outage appear to be high; therefore, these data are less reliable and are not used for the wastage comparison.

Based on the UT data generated from the 1991 and 1994 outages, the trend of furnace wall wastage is still difficult to be clearly defined. The difficulty is encountered by the fact that some of the UT data show tube wall "growth" from 1991 to 1994, and the others exhibit small losses compared to the range of standard deviation. The worst case of tube wastage on the left-hand sidewall is ~12 mils (0.012 inch), and the worst case on the right-hand sidewall is ~20 mils (0.020 inch) occurring on the bare T2 of the corrosion test panel. Again, due to a relatively large standard deviation involved in the UT measurement (± 15 mils), the uncertainty associated with these maximum metal losses would also be significant.

6.0 CONCLUSIONS

1. Results of the metallurgical examinations from the bottom portion of the corrosion test panel indicate that the corrosion wastage increased with increasing tube number from the front wall to the center line of right-hand sidewall. This trend is in agreement with that found in the previous analysis.
2. The sulfide scale formed on the bare T2 tubing of the corrosion panel was relatively dense and adherent, thus preventing the underlying metal from uncontrollable sulfidation attack. The maximum corrosion rate on T2 after a total exposure of 31 months in JMSS4 was ~10 mpy. This corrosion rate could be further reduced if the sulfide scale continues to remain dense and adherent to the tube surfaces.
3. The two weld-overlay coatings and chromized coating provided satisfactory protection to the T2 tubes from the corrosion attack in JMSS4. On the other hand, the aluminum-spray coating was relatively porous and unable to prevent sulfur from penetrating into the coating layer.

4. Results of the UT survey performed during the last three outages have started to show the corrosion wastage on some areas of the lower furnace walls in JMSS4. However, due to a large standard deviation associated with UT measurement, the trend of wall wastage still can not be clearly defined based on the available UT data.

7.0 RECOMMENDATIONS

It is recommended that destructive metallurgical examination of the corrosion test panel in JMSS4 be continued. Additional wastage data can be used to better define the long-term corrosion trend in JMSS4.

8.0 REFERENCES

1. C. F. Eckhart, R. F. DeVault, and S. C. Kung, "Full-Scale Demonstration of Low-NO_x Cell™ Burner Retort, Long-Term Testing," Program under DOE Cooperative Agreement DE-FC22-90PC90545, Task Report No. DOE/PC/90545-1, March 1994.

APPENDIX A

SUMMARY OF UT DATA

| | | FW UT READINGS | | | | |
|-------------|-----------|---------------------|----------|------------|----------|---------------------|
| | | TEST POINT AVERAGES | | | | |
| | | | | | | |
| | TUBE # | TEST POINT | FALL '94 | SPRING '93 | FALL '91 | COMMENTS |
| | FROM LHSW | | | | | |
| EL. 580'-3" | 424 | 1 | 244 | | 236 | |
| | 423 | 2 | 247 | | 228 | |
| | 417 | 3 | 233 | | 230 | |
| | 416 | 4 | 234 | | 227 | |
| | 410 | 5 | 237 | | 229 | |
| | 409 | 6 | 233 | | 243 | |
| | 403 | 7 | 238 | 240 | 236 | REPLACED FALL '91 |
| | 402 | 8 | 238 | 239 | 230 | REPLACED FALL '91 |
| | 396 | 9 | 227 | 237 | 235 | REPLACED FALL '91 |
| | 395 | 10 | 237 | 244 | 238 | REPLACED FALL '91 |
| | 389 | 11 | 239 | 239 | 232 | REPLACED FALL '91 |
| | 388 | 12 | 237 | 239 | 241 | REPLACED FALL '91 |
| | 384 | 13 | 242 | 243 | 248 | |
| | 383 | 14 | 240 | 247 | 232 | |
| | 364 | 15 | 235 | | 230 | |
| | 363 | 16 | 237 | | 239 | |
| | 354 | 17 | 231 | 238 | 236 | |
| | 353 | 18 | 236 | 237 | 234 | |
| | 321 | 19 | N/A | 251 | | REPLACED SPRING '93 |
| | 320 | 20 | N/A | 242 | | REPLACED SPRING '93 |
| | 293 | 21 | N/A | | | REPLACED SPRING '93 |
| | 292 | 22 | N/A | | | REPLACED SPRING '93 |

| | | RHSW UT READINGS | | | | |
|-------------|--------------------------|---------------------|----------|------------|----------|---------------------|
| | | TEST POINT AVERAGES | | | | |
| | TUBE # | TEST POINT | FALL '94 | SPRING '93 | FALL '91 | COMMENTS |
| | FROM FW | | | | | |
| EL. 601'-6" | | NOT AVAILABLE | | | | |
| EL. 577'-2" | 8 | 1 | 242 | 241 | 240 | |
| | 9 | 2 | 237 | 241 | 241 | |
| | 14 | 3 | 233 | 242 | 230 | |
| | 15 | 4 | 234 | 251 | 235 | |
| | 20 | 5 | 238 | 249 | 242 | |
| | 21 | 6 | 235 | 251 | 237 | |
| | 28 | 7 | 227 | 251 | 231 | |
| | 29 | 8 | 228 | 251 | 229 | |
| | 91 | 9 | 260 | | 250 | REPLACED SPRING '89 |
| | 92 | 10 | 253 | | 244 | REPLACED SPRING '89 |
| | Tube from FW Hopper Nose | | | | | |
| EL. 558'-0" | -2 | 1 | 231 | 240 | 234 | |
| | -1 | 2 | 225 | 240 | 236 | |
| | 6 | 3 | 234 | 238 | 228 | |
| | 7 | 4 | 237 | 237 | 225 | |
| | 13 | 5 | 236 | 239 | 229 | |
| | 14 | 6 | 237 | 239 | 232 | |
| | 20 | 7 | 237 | 243 | 235 | |
| | 21 | 8 | 236 | 242 | 236 | |
| | 25 | 9 | 238 | | 236 | |
| | 26 | 10 | 244 | | 231 | |

| | | LHSW UT READINGS | | | | |
|-------------------------|----|---------------------|----------|------------|----------|---------------------|
| | | TEST POINT AVERAGES | | | | |
| | | | | | | |
| | | TEST POINT | FALL '94 | SPRING '93 | FALL '91 | COMMENTS |
| EL. 577'-5" | 34 | 1* | 264 | 249 | 254 | REPLACED SPRING '90 |
| | 35 | 2* | 257 | 252 | 255 | REPLACED SPRING '90 |
| | 41 | 3 | 240 | 247 | 247 | REPLACED SPRING '88 |
| | 42 | 4 | 242 | 245 | 249 | REPLACED SPRING '88 |
| | 48 | 5 | 237 | | 249 | REPLACED SPRING '88 |
| | 49 | 6 | 248 | | 253 | REPLACED SPRING '88 |
| | 55 | 7 | 244 | | 252 | REPLACED SPRING '88 |
| | 56 | 8 | 248 | | 246 | REPLACED SPRING '88 |
| | 62 | 9 | 245 | | 240 | REPLACED SPRING '87 |
| | 63 | 10 | 241 | | 240 | REPLACED SPRING '87 |
| | 69 | 11* | 239 | 252 | 250 | REPLACED SPRING '87 |
| | 70 | 12* | 262 | 249 | 249 | REPLACED SPRING '87 |
| | 76 | 13 | 251 | 249 | 250 | REPLACED SPRING '87 |
| | 77 | 14 | 260 | 252 | 259 | REPLACED SPRING '87 |
| | 83 | 15 | 243 | 253 | 245 | REPLACED SPRING '87 |
| | 84 | 16 | 246 | 241 | 238 | REPLACED SPRING '87 |
| Tube # from Hopper Nose | | | | | | |
| EL. 558'-0" | 1 | 1 | 238 | 251 | 238 | |
| | 2 | 2 | 230 | 247 | 220 | |
| | 7 | 3 | 232 | 243 | 229 | |
| | 8 | 4 | 230 | 243 | 235 | |
| * - ALUMINIZED | | | | | | |

| | | RHSW TEST PANEL READINGS | | | | |
|-------------|------------------------------------|--------------------------|----------|------------|----------|------------------------|
| | | TEST POINT AVERAGES | | | | |
| | TUBE # ON TEST PANEL FROM FW | TEST POINT | FALL '94 | SPRING '93 | FALL '91 | COMMENTS |
| EL. 590'-2" | 1 | 1 | 246 | | | Bare T2 |
| | 2 | 2 | 246 | | | Bare T2 |
| | 3 | 3 | 237 | | | Bare T2 |
| | 4 | 4 | 242 | | | Bare T2 |
| | 5 | 5 | 240 | | | Bare T2 |
| | 6 | 6 | 282 | | | Aluminum Spray on T2 |
| | 7 | 7 | 284 | | | Aluminum Spray on T2 |
| | 8 | 8 | 284 | | | Aluminum Spray on T2 |
| | 9 | 9 | 254 | | | Aluminum Spray on T2 |
| | 10 | 10 | 267 | | | Aluminum Spray on T2 |
| | 11 | 11 | 242 | | | Aluminum Spray on T2 |
| | 12 | 12 | 259 | | | Aluminum Spray on T2 |
| | 13 | 13 | 243 | | | Aluminum Spray on T2 |
| | 14 | 14 | 263 | | | Aluminum Spray on T2 |
| | 15 | 15 | 260 | | | Aluminum Spray on T2 |
| | 16 | 16 | 239 | | | Bare T2 |
| | 17 | 17 | 239 | | | Bare T2 |
| | 18 | 18 | 247 | | | Bare T2 |
| | 19 | 19 | 244 | | | Bare T2 |
| | 20 | 20 | 235 | | | Bare T2 |
| | 21 | 21 | 226 | | | Bare T2 |
| | 22 | 22 | 226 | | | Bare T2 |
| | 23 | 23 | 240 | | | Bare T2 |
| | 24 | 24 | 235 | | | Bare T2 |
| | 25 | 25 | 237 | | | Bare T2 |
| | 29 | 26 | 310 | | | 309 Weld Overlay on T2 |
| | 32 | 27 | 345 | | | 309 Weld Overlay on T2 |
| | 36 | 28 | 227 | | | Bare T2 |
| | 37 | 29 | 236 | | | Bare T2 |
| | 38 | 30 | 231 | | | Bare T2 |
| | 39 | 31 | 236 | | | Bare T2 |
| | 40 | 32 | 228 | | | Bare T2 |
| | 41 | 33 | 236 | | | Bare T2 |
| | 42 | 34 | 229 | | | Bare T2 |
| | 43 | 35 | 233 | | | Bare T2 |
| | 44 | 36 | 228 | | | Bare T2 |
| | 45 | 37 | 239 | | | Bare T2 |
| | 49 | 38 | 357 | | | 308 Weld Overlay on T2 |
| | 52 | 39 | 322 | | | 308 Weld Overlay on T2 |
| | 56 | 40 | 230 | | | Bare T2 |
| | 57 | 41 | 237 | | | Bare T2 |
| | 58 | 42 | 232 | | | Bare T2 |
| | 59 | 43 | 232 | | | Bare T2 |
| | 60 | 44 | 223 | | | Bare T2 |
| | 61 | 45 | 233 | | | Bare T2 |
| | 62 | 46 | 234 | | | Bare T2 |
| | 63 | 47 | 229 | | | Bare T2 |
| | 64 | 48 | 231 | | | Bare T2 |
| | 65 | 49 | 229 | | | Bare T2 |
| | 66 | 50 | 239 | | | Chromized T2 |
| | 67 | 51 | 245 | | | Chromized T2 |
| | 68 | 52 | 245 | | | Chromized T2 |
| | 69 | 53 | 243 | | | Chromized T2 |
| | 70 | 54 | 247 | | | Chromized T2 |
| | 71 | 55 | 241 | | | Chromized T2 |
| | 72 | 56 | 242 | | | Chromized T2 |
| | 73 | 57 | 241 | | | Chromized T2 |
| | 74 | 58 | 237 | | | Chromized T2 |
| | 75 | 59 | 240 | | | Chromized T2 |
| | 76 | 60 | 235 | | | Bare T2 |
| | 77 | 61 | 229 | | | Bare T2 |
| | 78 | 62 | 226 | | | Bare T2 |
| | 79 | 63 | 226 | | | Bare T2 |
| | 80 | 64 | 233 | | | Bare T2 |

| | | RHSW TEST PANEL READINGS | | | | |
|-------------|------------------------------------|--------------------------|----------|------------|----------|------------------------|
| | | TEST POINT AVERAGES | | | | |
| | TUBE # on TEST PANEL FROM FW | TEST POINT | FALL '94 | SPRING '93 | FALL '91 | COMMENTS |
| EL. 586'-4" | 1 | 1 | 225 | 245 | | Bare T2 |
| | 2 | 2 | 229 | 246 | | Bare T2 |
| | 3 | 3 | 225 | 246 | | Bare T2 |
| | 4 | 4 | 232 | 250 | | Bare T2 |
| | 5 | 5 | 238 | 248 | | Bare T2 |
| | 6 | 6 | 239 | 250 | | Aluminum Spray on T2 |
| | 7 | 7 | 245 | 267 | | Aluminum Spray on T2 |
| | 8 | 8 | 246 | 256 | | Aluminum Spray on T2 |
| | 9 | 9 | 248 | 287 | | Aluminum Spray on T2 |
| | 10 | 10 | 244 | 255 | | Aluminum Spray on T2 |
| | 11 | 11 | 250 | 280 | | Aluminum Spray on T2 |
| | 12 | 12 | 245 | 270 | | Aluminum Spray on T2 |
| | 13 | 13 | 241 | 260 | | Aluminum Spray on T2 |
| | 14 | 14 | 238 | 249 | | Aluminum Spray on T2 |
| | 15 | 15 | 244 | 254 | | Aluminum Spray on T2 |
| | 16 | 16 | 240 | 251 | | Bare T2 |
| | 17 | 17 | 222 | 237 | | Bare T2 |
| | 18 | 18 | 231 | 245 | | Bare T2 |
| | 19 | 19 | 217 | 236 | | Bare T2 |
| | 20 | 20 | 224 | 236 | | Bare T2 |
| | 21 | 21 | 238 | 246 | | Bare T2 |
| | 22 | 22 | 222 | 234 | 239 | Bare T2 |
| | 23 | 23 | 228 | 236 | 235 | Bare T2 |
| | 24 | 24 | 219 | 230 | 233 | Bare T2 |
| | 25 | 25 | 227 | 237 | 236 | Bare T2 |
| | 29 | 26 | 292 | 295 | 292 | 309 Weld Overlay on T2 |
| | 32 | 27 | 323 | 338 | 322 | 309 Weld Overlay on T2 |
| | 36 | 28 | 210 | 231 | 242 | Bare T2 |
| | 37 | 29 | 224 | 235 | 239 | Bare T2 |
| | 38 | 30 | 217 | 229 | 237 | Bare T2 |
| | 39 | 31 | 226 | 239 | 238 | Bare T2 |
| | 40 | 32 | 203 | 230 | 233 | Bare T2 |
| | 41 | 33 | 220 | 242 | 236 | Bare T2 |
| | 42 | 34 | 214 | 234 | 232 | Bare T2 |
| | 43 | 35 | 225 | 243 | 235 | Bare T2 |
| | 44 | 36 | 212 | 228 | 237 | Bare T2 |
| | 45 | 37 | 226 | 235 | 230 | Bare T2 |
| | 49 | 38 | 326 | 336 | 336 | 308 Weld Overlay on T2 |
| | 52 | 39 | 339 | 354 | 347 | 308 Weld Overlay on T2 |
| | 56 | 40 | 214 | 238 | 235 | Bare T2 |
| | 57 | 41 | 228 | 241 | 237 | Bare T2 |
| | 58 | 42 | 213 | 235 | 232 | Bare T2 |
| | 59 | 43 | 228 | 244 | 244 | Bare T2 |
| | 60 | 44 | 213 | 239 | | Bare T2 |
| | 61 | 45 | 229 | 239 | | Bare T2 |
| | 62 | 46 | 232 | 246 | | Bare T2 |
| | 63 | 47 | 215 | 238 | 232 | Bare T2 |
| | 64 | 48 | 225 | 243 | 238 | Bare T2 |
| | 65 | 49 | 212 | 226 | 230 | Bare T2 |
| | 66 | 50 | 242 | 245 | 243 | Chromized T2 |
| | 67 | 51 | 237 | 248 | 236 | Chromized T2 |
| | 68 | 52 | 238 | 245 | 231 | Chromized T2 |
| | 69 | 53 | 242 | 246 | 244 | Chromized T2 |
| | 70 | 54 | 244 | 249 | 245 | Chromized T2 |
| | 71 | 55 | 242 | 249 | 239 | Chromized T2 |
| | 72 | 56 | 243 | 249 | 240 | Chromized T2 |
| | 73 | 57 | 252 | 251 | 249 | Chromized T2 |
| | 74 | 58 | 240 | 245 | 240 | Chromized T2 |
| | 75 | 59 | 241 | 250 | 239 | Chromized T2 |
| | 76 | 60 | 228 | 242 | 230 | Bare T2 |
| | 77 | 61 | 210 | 231 | 230 | Bare T2 |
| | 78 | 62 | 230 | 244 | 237 | Bare T2 |
| | 79 | 63 | 222 | 240 | 233 | Bare T2 |
| | 80 | 64 | 224 | 237 | 250 | Bare T2 |

| RHSW TEST PANEL READINGS | | | | | | |
|--------------------------|------------------------------------|------------|----------|------------|----------|------------------------|
| TEST POINT AVERAGES | | | | | | |
| | TUBE # ON TEST PANEL FROM FW | TEST POINT | FALL '94 | SPRING '93 | FALL '91 | COMMENTS |
| EL. 584'-4" | 1 | 1 | 235 | 240 | | Bare T2 |
| | 2 | 2 | 233 | 235 | | Bare T2 |
| | 3 | 3 | 232 | 250 | | Bare T2 |
| | 4 | 4 | 236 | 245 | | Bare T2 |
| | 5 | 5 | 236 | 240 | | Bare T2 |
| | 6 | 6 | 246 | 265 | | Aluminum Spray on T2 |
| | 7 | 7 | 248 | 275 | | Aluminum Spray on T2 |
| | 8 | 8 | 258 | 265 | | Aluminum Spray on T2 |
| | 9 | 9 | 261 | 270 | | Aluminum Spray on T2 |
| | 10 | 10 | 242 | 270 | | Aluminum Spray on T2 |
| | 11 | 11 | 248 | 280 | | Aluminum Spray on T2 |
| | 12 | 12 | 266 | 275 | | Aluminum Spray on T2 |
| | 13 | 13 | 241 | 265 | | Aluminum Spray on T2 |
| | 14 | 14 | 245 | 270 | | Aluminum Spray on T2 |
| | 15 | 15 | 244 | 260 | | Aluminum Spray on T2 |
| | 16 | 16 | 243 | 245 | | Bare T2 |
| | 17 | 17 | 236 | 230 | | Bare T2 |
| | 18 | 18 | 238 | 240 | | Bare T2 |
| | 19 | 19 | 228 | 222 | | Bare T2 |
| | 20 | 20 | 235 | 240 | | Bare T2 |
| | 21 | 21 | 229 | 237 | 238 | Bare T2 |
| | 22 | 22 | 224 | 222 | 239 | Bare T2 |
| | 23 | 23 | 230 | 227 | 232 | Bare T2 |
| | 24 | 24 | 215 | 228 | 245 | Bare T2 |
| | 25 | 25 | 225 | 239 | 237 | Bare T2 |
| | 29 | 26 | 310 | 308 | 311 | 309 Weld Overlay on T2 |
| | 32 | 27 | 327 | 314 | 328 | 309 Weld Overlay on T2 |
| | 36 | 28 | 201 | 221 | 241 | Bare T2 |
| | 37 | 29 | 219 | 231 | 236 | Bare T2 |
| | 38 | 30 | 205 | 227 | 240 | Bare T2 |
| | 39 | 31 | 228 | 236 | 237 | Bare T2 |
| | 40 | 32 | 207 | 221 | 234 | Bare T2 |
| | 41 | 33 | 231 | 239 | 238 | Bare T2 |
| | 42 | 34 | 207 | 221 | 239 | Bare T2 |
| | 43 | 35 | 210 | 232 | 239 | Bare T2 |
| | 44 | 36 | 209 | 225 | 238 | Bare T2 |
| | 45 | 37 | 233 | 235 | 243 | Bare T2 |
| | 49 | 38 | 351 | 365 | 352 | 308 Weld Overlay on T2 |
| | 52 | 39 | 351 | 345 | 329 | 308 Weld Overlay on T2 |
| | 56 | 40 | 209 | 226 | 239 | Bare T2 |
| | 57 | 41 | 226 | 239 | 233 | Bare T2 |
| | 58 | 42 | 205 | 228 | 237 | Bare T2 |
| | 59 | 43 | 220 | 237 | 238 | Bare T2 |
| | 60 | 44 | 220 | 231 | 240 | Bare T2 |
| | 61 | 45 | 226 | 242 | 246 | Bare T2 |
| | 62 | 46 | 228 | 237 | 237 | Bare T2 |
| | 63 | 47 | 218 | 235 | 244 | Bare T2 |
| | 64 | 48 | 224 | 234 | 235 | Bare T2 |
| | 65 | 49 | 216 | 232 | 240 | Bare T2 |
| | 66 | 50 | 240 | 242 | 241 | Chromized T2 |
| | 67 | 51 | 236 | 250 | 251 | Chromized T2 |
| | 68 | 52 | 241 | 247 | 251 | Chromized T2 |
| | 69 | 53 | 240 | 247 | 250 | Chromized T2 |
| | 70 | 54 | 240 | 245 | 247 | Chromized T2 |
| | 71 | 55 | 241 | 250 | 250 | Chromized T2 |
| | 72 | 56 | 234 | 245 | 241 | Chromized T2 |
| | 73 | 57 | 245 | 243 | 248 | Chromized T2 |
| | 74 | 58 | 240 | 251 | 250 | Chromized T2 |
| | 75 | 59 | 237 | 238 | 241 | Chromized T2 |
| | 76 | 60 | 232 | 240 | 242 | Bare T2 |
| | 77 | 61 | 223 | 238 | 240 | Bare T2 |
| | 78 | 62 | 228 | 242 | 227 | Bare T2 |
| | 79 | 63 | 219 | 230 | 232 | Bare T2 |
| | 80 | 64 | 232 | 237 | 240 | Bare T2 |

| | | RHSW TEST PANEL READINGS | | | | |
|-------------|------------------------------------|--------------------------|----------|------------|----------|------------------------|
| | | TEST POINT AVERAGES | | | | |
| | TUBE # ON TEST PANEL FROM FW | TEST POINT | FALL '94 | SPRING '93 | FALL '91 | COMMENTS |
| EL. 582'-4" | 1 | 1 | 230 | 246 | | Bare T2 |
| | 2 | 2 | 235 | 243 | | Bare T2 |
| | 3 | 3 | 232 | 248 | | Bare T2 |
| | 4 | 4 | 224 | 242 | | Bare T2 |
| | 5 | 5 | 239 | 242 | | Bare T2 |
| | 6 | 6 | 239 | 284 | | Aluminum Spray on T2 |
| | 7 | 7 | 238 | 289 | | Aluminum Spray on T2 |
| | 8 | 8 | 243 | 288 | | Aluminum Spray on T2 |
| | 9 | 9 | 237 | 287 | | Aluminum Spray on T2 |
| | 10 | 10 | 240 | 286 | | Aluminum Spray on T2 |
| | 11 | 11 | 236 | 280 | | Aluminum Spray on T2 |
| | 12 | 12 | 239 | 289 | | Aluminum Spray on T2 |
| | 13 | 13 | 241 | 286 | | Aluminum Spray on T2 |
| | 14 | 14 | 243 | 280 | | Aluminum Spray on T2 |
| | 15 | 15 | 240 | 287 | | Aluminum Spray on T2 |
| | 16 | 16 | 241 | 291 | | Bare T2 |
| | 17 | 17 | 227 | 278 | | Bare T2 |
| | 18 | 18 | 232 | 245 | | Bare T2 |
| | 19 | 19 | 227 | 249 | | Bare T2 |
| | 20 | 20 | 234 | 244 | | Bare T2 |
| | 21 | 21 | 224 | 244 | 237 | Bare T2 |
| | 22 | 22 | 221 | 247 | 234 | Bare T2 |
| | 23 | 23 | 226 | 240 | 234 | Bare T2 |
| | 24 | 24 | 219 | 239 | 245 | Bare T2 |
| | 25 | 25 | 233 | 241 | 247 | Bare T2 |
| | 29 | 26 | 317 | 334 | 302 | 309 Weld Overlay on T2 |
| | 32 | 27 | 322 | 342 | 315 | 309 Weld Overlay on T2 |
| | 36 | 28 | 211 | 228 | 235 | Bare T2 |
| | 37 | 29 | 224 | 238 | 236 | Bare T2 |
| | 38 | 30 | 222 | 236 | 243 | Bare T2 |
| | 39 | 31 | 231 | 240 | 247 | Bare T2 |
| | 40 | 32 | 219 | 232 | 234 | Bare T2 |
| | 41 | 33 | 234 | 237 | 236 | Bare T2 |
| | 42 | 34 | 204 | 233 | 230 | Bare T2 |
| | 43 | 35 | 230 | 241 | 238 | Bare T2 |
| | 44 | 36 | 208 | 231 | 245 | Bare T2 |
| | 45 | 37 | 230 | 240 | 236 | Bare T2 |
| | 49 | 38 | 332 | 346 | 324 | 308 Weld Overlay on T2 |
| | 52 | 39 | 331 | 339 | 320 | 308 Weld Overlay on T2 |
| | 56 | 40 | 204 | 237 | 240 | Bare T2 |
| | 57 | 41 | 233 | 245 | 247 | Bare T2 |
| | 58 | 42 | 210 | 235 | 240 | Bare T2 |
| | 59 | 43 | 229 | 237 | 233 | Bare T2 |
| | 60 | 44 | 215 | 228 | 229 | Bare T2 |
| | 61 | 45 | 231 | 245 | 237 | Bare T2 |
| | 62 | 46 | 227 | 242 | 239 | Bare T2 |
| | 63 | 47 | 215 | 238 | 238 | Bare T2 |
| | 64 | 48 | 234 | 243 | 240 | Bare T2 |
| | 65 | 49 | 214 | 239 | 234 | Bare T2 |
| | 66 | 50 | 232 | 240 | 234 | Chromized T2 |
| | 67 | 51 | 245 | 244 | 248 | Chromized T2 |
| | 68 | 52 | 242 | 245 | 247 | Chromized T2 |
| | 69 | 53 | 235 | 247 | 240 | Chromized T2 |
| | 70 | 54 | 236 | 243 | 244 | Chromized T2 |
| | 71 | 55 | 234 | 246 | 236 | Chromized T2 |
| | 72 | 56 | 238 | 255 | 250 | Chromized T2 |
| | 73 | 57 | 238 | 250 | 245 | Chromized T2 |
| | 74 | 58 | 234 | 245 | 243 | Chromized T2 |
| | 75 | 59 | 233 | 247 | 246 | Chromized T2 |
| | 76 | 60 | 223 | 241 | 237 | Bare T2 |
| | 77 | 61 | 207 | 241 | 245 | Bare T2 |
| | 78 | 62 | 234 | 245 | 238 | Bare T2 |
| | 79 | 63 | 212 | 232 | 239 | Bare T2 |
| | 80 | 64 | 226 | 242 | 244 | Bare T2 |

| RHSW TEST PANEL READINGS | | | | | | |
|--------------------------|------------------------------------|------------|----------|------------|----------|------------------------|
| TEST POINT AVERAGES | | | | | | |
| | TUBE # ON TEST PANEL FROM FW | TEST POINT | FALL '94 | SPRING '93 | FALL '91 | COMMENTS |
| EL. 580'-7" | 1 | 1 | 241 | 242 | | Bare T2 |
| | 2 | 2 | 248 | 248 | | Bare T2 |
| | 3 | 3 | 236 | 242 | | Bare T2 |
| | 4 | 4 | 238 | 238 | | Bare T2 |
| | 5 | 5 | 248 | 250 | | Bare T2 |
| | 6 | 6 | 273 | 273 | | Aluminum Spray on T2 |
| | 7 | 7 | 281 | 286 | | Aluminum Spray on T2 |
| | 8 | 8 | 271 | 275 | | Aluminum Spray on T2 |
| | 9 | 9 | 261 | 276 | | Aluminum Spray on T2 |
| | 10 | 10 | 273 | 281 | | Aluminum Spray on T2 |
| | 11 | 11 | 255 | 288 | | Aluminum Spray on T2 |
| | 12 | 12 | 267 | 271 | | Aluminum Spray on T2 |
| | 13 | 13 | 261 | 278 | | Aluminum Spray on T2 |
| | 14 | 14 | 265 | 272 | | Aluminum Spray on T2 |
| | 15 | 15 | 275 | 289 | | Aluminum Spray on T2 |
| | 16 | 16 | 250 | 243 | | Bare T2 |
| | 17 | 17 | 230 | 245 | | Bare T2 |
| | 18 | 18 | 237 | 241 | | Bare T2 |
| | 19 | 19 | 238 | 241 | | Bare T2 |
| | 20 | 20 | 231 | 245 | | Bare T2 |
| | 21 | 21 | 234 | 239 | 230 | Bare T2 |
| | 22 | 22 | 239 | 246 | 238 | Bare T2 |
| | 23 | 23 | 242 | 242 | 241 | Bare T2 |
| | 24 | 24 | 237 | 238 | 238 | Bare T2 |
| | 25 | 25 | 229 | 237 | 234 | Bare T2 |
| | 29 | 26 | 316 | 319 | 309 | 309 Weld Overlay on T2 |
| | 32 | 27 | 320 | 351 | 326 | 309 Weld Overlay on T2 |
| | 36 | 28 | 233 | 245 | 242 | Bare T2 |
| | 37 | 29 | 231 | 242 | 232 | Bare T2 |
| | 38 | 30 | 231 | 243 | 236 | Bare T2 |
| | 39 | 31 | 235 | 247 | 234 | Bare T2 |
| | 40 | 32 | 219 | 238 | 231 | Bare T2 |
| | 41 | 33 | 236 | 243 | 241 | Bare T2 |
| | 42 | 34 | 229 | 240 | 239 | Bare T2 |
| | 43 | 35 | 236 | 241 | 231 | Bare T2 |
| | 44 | 36 | 229 | 246 | 247 | Bare T2 |
| | 45 | 37 | 236 | 247 | 237 | Bare T2 |
| | 49 | 38 | 302 | 339 | 306 | 308 Weld Overlay on T2 |
| | 52 | 39 | 321 | 342 | 315 | 308 Weld Overlay on T2 |
| | 56 | 40 | 237 | 241 | | Bare T2 |
| | 57 | 41 | 233 | 241 | 242 | Bare T2 |
| | 58 | 42 | 225 | 238 | 232 | Bare T2 |
| | 59 | 43 | 236 | 243 | 236 | Bare T2 |
| | 60 | 44 | 220 | 225 | 236 | Bare T2 |
| | 61 | 45 | 234 | 242 | 234 | Bare T2 |
| | 62 | 46 | 235 | 246 | 231 | Bare T2 |
| | 63 | 47 | 226 | 249 | 248 | Bare T2 |
| | 64 | 48 | 231 | 248 | 236 | Bare T2 |
| | 65 | 49 | 222 | 239 | 230 | Bare T2 |
| | 66 | 50 | 243 | 245 | 248 | Chromized T2 |
| | 67 | 51 | 239 | 243 | 240 | Chromized T2 |
| | 68 | 52 | 230 | 241 | 238 | Chromized T2 |
| | 69 | 53 | 231 | 251 | 247 | Chromized T2 |
| | 70 | 54 | 234 | 252 | 253 | Chromized T2 |
| | 71 | 55 | 241 | 252 | 254 | Chromized T2 |
| | 72 | 56 | 243 | 242 | 238 | Chromized T2 |
| | 73 | 57 | 229 | 245 | 248 | Chromized T2 |
| | 74 | 58 | 231 | 247 | 246 | Chromized T2 |
| | 75 | 59 | 232 | 245 | 247 | Chromized T2 |
| | 76 | 60 | 234 | 249 | 238 | Bare T2 |
| | 77 | 61 | 213 | 240 | 233 | Bare T2 |
| | 78 | 62 | 231 | 240 | 238 | Bare T2 |
| | 79 | 63 | 226 | 247 | 239 | Bare T2 |
| | 80 | 64 | 234 | 249 | 250 | Bare T2 |

| FW BURNER PANEL READINGS | | | | | | |
|--------------------------|-----------|----------------|----------|------------|----------|---------------------|
| TEST POINT AVERAGES | | | | | | |
| | TUBE # | TEST POINT | FALL '94 | SPRING '93 | FALL '91 | COMMENTS |
| | FROM LHSW | | | | | |
| BURNER 4D1L | 81 | 9* | 275 | | | REPLACED SPRING '93 |
| | 80 | 10* | 273 | | | REPLACED SPRING '93 |
| | 48 | 11* | 273 | | | REPLACED SPRING '93 |
| | 47 | 12* | 275 | | | REPLACED SPRING '93 |
| BURNER 4D2L | 147 | 9* | 266 | | | REPLACED SPRING '88 |
| | 146 | 10* | 265 | | | REPLACED SPRING '88 |
| | 104 | 11* | 265 | | | REPLACED SPRING '93 |
| | 103 | 12* | 269 | | | REPLACED SPRING '93 |
| BURNER 4B3L | 186 | 1* | 250 | | | REPLACED SPRING '93 |
| | 185 | 2* | 240 | | | REPLACED SPRING '93 |
| | 171 | 3* | 285 | | | REPLACED SPRING '93 |
| | 170 | 4* | 263 | | | REPLACED SPRING '93 |
| | 204 | 5* | 246 | | | REPLACED SPRING '93 |
| | 203 | 6* | 269 | | | REPLACED SPRING '93 |
| | 202 | 9* | 270 | | | REPLACED SPRING '93 |
| | 201 | 10* | 276 | | | REPLACED SPRING '93 |
| | 171 | 11* | 280 | | | REPLACED SPRING '93 |
| | 170 | 12* | 278 | | | REPLACED SPRING '93 |
| | 186 | 13* | 268 | | | REPLACED SPRING '93 |
| | 185 | 14* | 269 | | | REPLACED SPRING '93 |
| BURNER 4D6L | 369 | 1 | 223 | 235 | 231 | |
| | 368 | 2 | 230 | 239 | 236 | |
| | 354 | 3 | 227 | 228 | 225 | |
| | 353 | 4 | 232 | 230 | 232 | |
| | 384 | 5 | 242 | 245 | 241 | |
| | 383 | 6 | 237 | 236 | 240 | |
| | 384 | 9 | 221 | 231 | 235 | |
| | 383 | 10 | 237 | | 237 | |
| | 352 | 11* | 263 | 272 | 271 | REPLACED SPRING '89 |
| | 351 | 12* | 268 | 276 | 277 | REPLACED SPRING '89 |
| | 369 | 13 | 236 | 234 | 229 | |
| | 368 | 14 | 229 | 230 | 232 | |
| | | | | | | |
| | | * - ALUMINIZED | | | | |

| RW BURNER PANEL READINGS | | | | | | | |
|--------------------------|-------------|------------|----------|------------|----------|---------------------|---------------------|
| TEST POINT AVERAGES | | | | | | | |
| | TUBE # | TEST POINT | FALL '94 | SPRING '93 | FALL '91 | COMMENTS | |
| | FROM LHSW | | | | | | |
| BURNER 4C2L | 124 | 1 | 212 | 229 | 229 | | |
| | 125 | 2 | 222 | 233 | 228 | | |
| | 140 | 3 | 228 | | 230 | | |
| | 141 | 4 | 232 | | 234 | | |
| | 108 | 5 | 238 | 244 | 238 | | |
| | 109 | 6 | 240 | 247 | 242 | | |
| | 140 | 9 | 235 | | 239 | | |
| | 141 | 10 | 233 | | 232 | | |
| | 108 | 11 | 238 | 240 | 250 | | |
| | 109 | 12 | 232 | 242 | 240 | | |
| | 123 | 13 | 235 | 242 | 241 | | |
| | 124 | 14 | 228 | 235 | 231 | | |
| | BURNER 4E3L | 169 | 3* | 266 | | | REPLACED SPRING '93 |
| | | 170 | 4* | 268 | | | REPLACED SPRING '93 |
| 203 | | 5* | 259 | | | REPLACED SPRING '93 | |
| 204 | | 6* | 265 | | | REPLACED SPRING '93 | |
| 203 | | 9* | 273 | | | REPLACED SPRING '93 | |
| 204 | | 10* | 281 | | | REPLACED SPRING '93 | |
| 169 | | 11* | 268 | | | REPLACED SPRING '93 | |
| 170 | | 12* | 267 | | | REPLACED SPRING '93 | |
| 183 | | 13* | 269 | | | REPLACED SPRING '93 | |
| 184 | | 14* | 265 | | | REPLACED SPRING '93 | |
| BURNER 4C5L | 324 | 9* | 259 | | | REPLACED SPRING '93 | |
| | 325 | 10* | 252 | | | REPLACED SPRING '93 | |
| BURNER 4C6L | 390 | 3 | 232 | | | | |
| | 391 | 4 | 234 | | | | |
| | 346 | 5* | 285 | | | REPLACED SPRING '93 | |
| | 347 | 6* | 289 | | | REPLACED SPRING '93 | |
| | 390 | 9 | 228 | | | | |
| | 391 | 10 | 235 | | | | |
| | 345 | 11* | 269 | | | REPLACED SPRING '93 | |
| | 346 | 12* | 274 | | | REPLACED SPRING '93 | |
| * - ALUMINIZED | | | | | | | |

