

## **Appendix B**

### **Corrosion Test Work**

“Heat Pipe Corrosion Test -- EPRI/NYSEG HSTC Unit,” ABB API Report to NYSEG, EPRI, and Radian Corporation, New York State Electric & Gas Corporation, Binghamton, New York, January 6, 1994.

McCoy, D. C., Weinheimer, U., Janik, G. S., and Marker, B., “Milliken Unit 2 ESP And Slipstream Heat Pipe Corrosion Tests, July 15, 1993 to May 21, 1994,” Joint NYSEG/CONSOL Final Report, Research and Development Contract No. 95-149, New York State Electric & Gas Corporation, Binghamton, New York, August 1995.

# **Heat Pipe Corrosion Test Report EPRI/NYSEG HSTC Unit**

Report prepared by ABB API for NYSEG, EPRI, and Radian Corporation.

Report transmitted by cover letter from Mr. S. F. Harting (ABB API) on January 6, 1994 to Dr. G. S. Janik (NYSEG), Mr. K. Zammit (EPRI) and Mr. A. J. Mechtenberg (Radian).

# Heat Pipe Corrosion Test

## EPRI/NYSEG HSTC Unit

### INTRODUCTION

The Electric Power Research Institute (EPRI) installed a pilot scale selective catalytic reduction (SCR) unit for nitrogen oxides (NO<sub>x</sub>) removal on the exit duct from the flue gas desulfurization (FGD) unit at New York State Electric and Gas Corporation's (NYSEG) Kintigh Station electric power plant. The purpose was to test the feasibility of NO<sub>x</sub> removal after the FGD unit. Part of the SCR system is a heat pipe unit that is used to transfer heat from the 610°F SCR exit gas to the 125°F SCR inlet gas.

Early inspections of the heat pipe unit revealed severe corrosion was occurring. This opportunity was used to test additional heat pipe materials of construction in the flue gas environment at the Kintigh Station.

ABB Air Preheater, Inc. (ABB API) fabricated two sets of three heat pipes using different materials. Carbon steel, Cor-Ten B<sup>®</sup>, and AL-6XN<sup>®</sup> were the materials selected for this limited test. CONSOL installed one set of heat pipes in front of Module 1 and one set after Module 1 in the heat pipe unit (see Figure 1) in November 1992. The set of test heat pipes installed in front of module one (Location A) were filled with Freon<sup>®</sup> 11 (see Figure 2) and the heat pipes installed after Module 1 (Location B) were filled with toluene (see Figure 3). The heat pipes were inspected during scheduled outages and inspection reports are available.

After the May 17, 1993 inspection, the two sets of test heat pipes were removed and destructively tested. The preliminary corrosion data were presented at a meeting on June 16, 1993, at the Kintigh Station. At this meeting, it was decided to destructively test one of the original alloy 2205 heat pipes. This pipe was removed and shipped to ABB API for the evaluation.

This report documents the results of the destructive testing on the two sets of test heat pipes and the one original heat pipe.

### CONCLUSIONS

1. None of the tested or original tube materials can provide a 20-year life heat pipe in the Kintigh Station environment at Location A, return side. This is predicated on a standard 0.100" wall thickness.
2. Alloy 2205 tube exhibited the lowest corrosion rates. There may have been anodic protection by the AISI 409 stainless steel fins (See Discussion).
3. AL-6XN<sup>®</sup> exhibited low corrosion rates and a localized pitting/cracking phenomena at Location A, return side.



The supply side materials exhibited little to no corrosion (see Figures 16, 17, and 18).

### 3. Alloy 2205

This heat pipe had severely corroded fins; however, the tube material appeared to have suffered little corrosion. The fins on this heat pipe were AISI 409 stainless steel. When the fins were removed from a section of return side tubing, the tube exhibited varying degrees of corrosive material removal between the fins. Figures 19, 20, 21, and 22 show this attack about the diameter of the tube.

When the fins were removed from a section of supply tubing, it was noted that there was pitting corrosion around the outer diameter of the tube. This pitting did not have a pattern around the tube, it was associated with deposits that had built upon the tube. Figure 23 shows the pitting on the tube.

#### Corrosion Measurements

The test heat pipes were drained and sectioned for corrosion measurements. Short tube lengths were cut from each test heat pipe. The thickness of each length was measured with a micrometer. These results are reported in Table 1.

The alloy 2205 heat pipe was drained and sectioned. Samples were prepared metallographically for the finned areas and underneath the mounting collar. Figure 24 shows the locations of the metallographic sections. These sections were measured optically using a microhardness tester (see Figures 25 and 26). The ends were sectioned from the heat pipe and measured with a micrometer (see Table 2),

#### Microscopic Observations

Sections of the test heat pipes were examined. No unusual microstructures or discontinuities were found in the carbon steel or Cor-Ten B<sup>®</sup> samples. The AL-6XN<sup>®</sup> material exhibited pitting and cracks emanating from the pits in the sections taken from the return side, Location A (see Figures 27 and 28). The samples from the AL-6XN<sup>®</sup> tube installed in Location B did not exhibit any unusual microstructures or discontinuities.

The return side of the alloy 2205 heat pipe showed a preferential corrosive attack between the fins (see Figure 29). The fin-to-tube braze joints were not complete and exhibited cracks (see Figure 30).

The supply side of the alloy 2205 heat pipe showed pitting attack (see Figures 31, 32, and 33). The ferrite exhibited a greater corrosion attack than the austenite in the 2205 alloy. Figures 32 and 33 show the attack. Pit depths ranged from 0.0011" to 0.005".

#### Weight Loss

The six ABB API heat pipes and their flanges were weighed prior to installation. This was to allow for a weight loss measurements after exposure.

When the tubes were installed and removed, the welding and cutting operations damaged the flanges or added significant quantities of weld metal to the heat pipes.

The removed tubes were weighed; however, the data is not reported due to the inaccuracies.

The weight of a section of bare alloy 2205 tube was determined mathematically and compared to weight of a length of corroded tube from supply side. The comparison yielded a corrosion rate of 5.6 mpy.

## **DISCUSSION**

Three different materials were exposed to a desulfurized, deNO<sub>x</sub>ed flue gas stream at the Kintigh Station. The test areas in the heat exchanger were chosen to represent the worst case in terms of dewpoint corrosion. The AL-6XN<sup>®</sup> corroded in both locations. The Cor-Ten B<sup>®</sup> corroded in Location A. The carbon steel corroded severely in Location A and slightly in Location B. Alloy 2205 corroded at both locations.

At Location A return side of the heat exchanger, the temperatures are well below the dewpoint. The two probable corrodants condensing are ammonium bisulfate (ABS) and sulfuric acid. ABS is formed from the unreacted ammonia and SO<sub>3</sub> in the flue gas. Excess ammonia is added to the gas stream to catalytically react with the nitrogen oxides. Sulfuric acid is formed by the reaction of SO<sub>3</sub> with water. Although, the flue gas has been desulfurized, quantities of SO<sub>2</sub> and SO<sub>3</sub> are present in the flue gas. The catalyst for the deNO<sub>x</sub> process will convert some of the SO<sub>2</sub> to SO<sub>3</sub>, thus increasing the quantity of SO<sub>3</sub> available to react with ammonia or water. Corrosion products from the unit indicate that ABS and sulfuric acid are actively corroding the unit.

In Location A, the carbon steel heat pipe corroded in both the deSO<sub>x</sub>-deNO<sub>x</sub> gas stream, return side, and the deSO<sub>x</sub> gas stream, supply side. The heat pipe "grooving" in the return side location appears to be the result of liquid collecting on the surface and subsequent transport on and around the heat pipe. The corrosion at the end of the carbon steel heat pipe at Location A, supply side is attributed to the build up of noncondensable gases in the end of the heat pipe (see Appendix A). The water laden mist carried over from the flue gas desulfurization unit would collect on the cold tube and cause rusting. This corrosion was exacerbated by an air leak from one of the access doors in the unit.

The Cor-Ten B<sup>®</sup> heat pipe corroded at rates up to 42.3 mpy at Location A in the return side. The corrosion was fairly uniform about the diameter of the heat pipe.

At Location A, return side the AL-6XN<sup>®</sup> heat pipe corroded at a maximum rate of 10.6 mpy. In addition, this material exhibited cracking from the bottom of pits in the material. This transgranular cracking phenomena was not thoroughly investigated but probably is stress corrosion cracking. However, due to this cracking, the material cannot be used in this service. Pit depths and crack lengths are irrelevant with type of cracking. Both pitting corrosion and stress corrosion crack mechanisms are not predictable with time.

The alloy 2205 heat pipe was taken from the face of Module 1 closest to the Location A test area, i.e., the coldest row of the return side. Sections through this heat pipe

showed corrosion rates of the tube material up to 9.7 mpy. The AISI 409 fins were corroding at rates up to 17.5 mpy. The corrosion patterns on the alloy 2205 heat pipe indicate that a flow related phenomena is affecting the tube. This could be by acid droplet impingement and collection by gravity, the effects of water washing, or crevice corrosion under a scale/deposit. Water washing effects would be expected to produce a more uniform corrosion. A combination of acid droplet impingement and a scale/deposit to hold the acid in contact with the tube is a likely cause. In any case, the 9.7 mpy corrosion rate is unacceptable for a 20-year life.

A galvanic couple is formed by the AISI 409 fins and the alloy 2205 tube. The galvanic action is further complicated by the nickel braze alloy. The AISI 409 material is the most galvanically active material and will corrode preferentially to the nickel braze alloy and the alloy 2205. This assumes that the tube and fins are covered with a liquid film to promote galvanic corrosion.

It is interesting to note that the finning vendor for ABB API experimented with an alloy 2205 fin on alloy 2205 tubing. The fin material cracked during application. Care must be exercised when selecting the finning material for alloy 2205. Ductility and galvanic corrosion must be considered.

All of the materials are unacceptable for a 20-year life in the Kintigh deSO<sub>x</sub>-deNO<sub>x</sub> environment at Location A, return side.

In Location B, return side, the test materials exhibited lower corrosion rates, in fact the visual appearance of the Cor-Ten B<sup>®</sup> sample was such that it was not necessary to section that test heat pipe because the corrosion scale that forms to protect the Cor-Ten<sup>®</sup> was intact over 95% of the pipe's surface. The maximum corrosion rates were 7.9 mpy for the carbon steel and 5.3 for the AL-6XN<sup>®</sup>. The AL-6XN<sup>®</sup> sample did not exhibit any cracking. In the Table 1 corrosion data for AL-6XN<sup>®</sup>, the data scatter indicates that the corrosion measurement may be inaccurate due to measurement inconsistencies or tube wall thickness variations.

Although the supply side corrosion results are of no concern for the design of the Kintigh Station heat pipe unit, these results will be discussed. For the supply side, the carbon steel exhibited a high corrosion rate (60.8 mpy) at Location A. The supply side of the heat pipe unit is the evaporator end. Since the noncondensable gases are forced to the condenser end of a heat pipe, corrosion suffered at the evaporator end of a heat pipe is not affected by a gas block (noncondensable gases) in the condenser end of the heat pipe.

At Location B the mill scale on the carbon steel was largely intact. The Cor-Ten B<sup>®</sup> suffered little corrosion in both locations. The AL-6XN<sup>®</sup> showed no corrosion as the mill applied line identification was readable. In general, the corrosion on the supply side was much less severe than the return side corrosion.

The alloy 2205 heat pipe exhibited pitting corrosion underneath scale deposits. These pits were 0.0011" to 0.005" deep. This information is reported but it can be misleading. Pitting corrosion is a form of localized attack which can cause rapid perforation of metal sections. When pits are actively corroding, material removal in the pit is extremely rapid. It is generally accepted in the corrosion community that

the rate of pitting attack is unpredictable. The pitting was preferential to the ferrite phase of the alloy 2205 and can be seen in figures 32 and 33. This indicates that sulfur compounds are the probable cause of the alloy 2205 pitting on the supply side as duplex stainless steels are generally resistant to corrosion by chlorides.

Several operational considerations of the heat pipes were investigated. The corrosion patterns on the AL-6XN® and the carbon steel heat pipes were suspected to be caused by operation of the heat pipes. Gas blockage in the heat pipe condenser end would allow the blocked area to operate at a colder temperature than the remainder of the heat pipe, thus, accelerating corrosion. A similar phenomena could occur in the evaporator would on start-up. The fill fluid would absorb heat and the upper section of the evaporator would heat up rapidly due to the absence of fill fluid. Therefore, the lower section would experience more corrosion on start-up. Since the problem is dewpoint corrosion, any sulfuric acid or ABS that condensed on the heat pipe would remain on the heat pipes. The gas and heat pipe temperatures would not necessarily evaporate the condensed acid so it would corrode the material until the acid was converted to corrosion products.

This information and analysis of fill fluid problems are reported in Appendix A.

The alloy 2205 heat pipe exhibited many different corrosion rates. These rates represent different conditions in the unit, for example, the ends of the heat pipes (Table 2 data) were in the tube sheet or through the tube sheet so the corrosive conditions were different for this area of the heat pipe. Also, the return side and the supply side conditions were different. On the return side, the corrosion varied about the diameter of the tube shown in Figures 19, 20, 21, and 22. The information for this area reported in Figure 25 is the area of maximum attack and the data reported in Figure 26 is an area of minimal attack.

It was noted that the corrosion was not uniform down the length of the test heat pipes or the actual heat pipe. This indicates a channeling of the gas flow in the unit. Perhaps the deposition of solids in Modules 2 and 3 altered the gas flow or for some reason, the mass flows were not uniform across the duct cross-section. Each heat pipe module should serve as a flow straightener so the nonuniform attack is difficult to explain.

When corrosion rates were evaluated for the alloy 2205 heat pipe, the original plan was to optically measure the thickness of the tube underneath the center mounting flange. In reality, it was found that the braze alloy underneath the fins had protected the original surface of the tube, this wall thickness was measured and used as the base thickness to calculate corrosion rates.

There is a tendency to statistically evaluate corrosion data by averaging. The problem with this approach is that there are not average corrosion rates in real systems. Maximum corrosion rates are the rates that must be considered, since, the maximum rate is the one that will remove the material and cause downtime in the system.



Cor-Ten B® is a registered trademark of the United States Steel Corporation.  
AL-6XN® is a registered trademark of Allegheny Ludlum Steel Corporation.

### REFERENCES

1. Harting, S. to Counterman, W.; June 1, 1992. "Evaluation of EPRI/Somerset Deposits". Report.
2. McCoy, D. to Peter, J.; January 22, 1993. "Interim Report--HSTC Heat Pipe Operation". Photocopy.
3. McCoy, D. to Janik, G.; February 8, 1993. "Trip Report--HSTC Heat Pipe Inspections 1/25/93 and 1/26/93". Photocopy.
4. McCoy, D. to Janik, G.; March 19, 1993. "Trip Report--HSTC Heat Pipe Inspections 3/3/93 and 3/4/93". Photocopy.
5. McCoy, D. To Janik, G.; May 12, 1993. "Trip Report-HSTC Heat Pipe Inspections 4/12/93 and 4/13/93". Photocopy.
6. McCoy, D. To Janik, G.; June 17, 1993. "Trip Report-HSTC Heat Pipe Inspections 5/17/93 and 5/18/93". Photocopy.
7. Fontana, M. G. & Greene, N. D.. *Corrosion Engineering*. New York:McGraw-Hill Book, 1967.

mb\HPCORTES.SAM

# HSTC Heat Pipe Exchanger





Figure 1

Figure 2


# LOCATION OF ABB HEAT PIPES (POSITION A)




View From Supply Side Duct

Figure 3

### LOCATION OF ABB HEAT PIPES (POSITION B)



View From Supply Side Duct



**Figure 4**

Showing all of the test heat pipes from Location A.

Carbon Steel      Top

Cor-Ten B<sup>®</sup>      Middle

AL-6XN<sup>®</sup>      Bottom

Magnification:    0.06X



**Figure 5**


Showing the bottom of the carbon steel test pipe. NOTE: the "grooving" on the top portion of the heat pipe as shown in the photo.

Magnification:    0.24X

# Figure 6

Showing a pencil tracing of the "grooving"  
on a section of the carbon steel heat pipe  
Location A, return side

Full size






**Figure 7**

Showing the corrosion (pitting)  
of the AL-6XN<sup>®</sup> heat pipe,  
Location A, return side.


Magnification: 0.6X



**Figure 8**

Showing the corrosion  
patterns on the AL-6XN<sup>®</sup>,  
Location A, return side.


Magnification: 0.22X



**Figure 9**

Showing the end of the carbon steel heat pipe. Location A, supply side.

Magnification: 0.25X




**Figure 10**

Showing the end of the Cor-Ten B<sup>®</sup> heat pipe. Location A, supply side.

Magnification: 0.22X






**Figure 11**

Showing the end of the AL-6XN<sup>®</sup>. Location A, supply side.

Magnification: 0.26X



**Figure 12**


Showing the three heat pipes from Location B.

Carbon steel            Top

Cor-Ten B<sup>®</sup>            Middle

AL-6XN<sup>®</sup>                Bottom


Magnification: 0.06X



**Figure 13**

Showing the end of the carbon steel heat pipe. Location B, return side.


Magnification: 0.31X



**Figure 14**

Showing the end of the Cor-Ten B<sup>®</sup> heat pipe. Location B, return side.

Magnification: 0.36X



**Figure 15**

Showing the corrosion stain on the AL-6XN® heat pipe. Location B, return side.


Magnification: 0.43X



**Figure 16**

Showing the end of the carbon steel heat pipe. Location B, supply side.


Magnification: 0.29X



**Figure 17**

Showing the end of the  
Cor-Ten B® heat pipe.  
Location B, supply side.


Magnification: 0.42X



**Figure 18**

Showing the end of the  
AL-6XN® heat pipe. NOTE the  
mill's line marking. Location B,  
supply side.


Magnification: 0.38X



**Figure 19**

Showing the corrosion attack on the bottom of the alloy 2205 tube. Return side.


Magnification: 2.8X



**Figure 20**

Showing the corrosion attack on the leading edge of alloy 2205 tube. Return side.


Magnification: 2.8X



**Figure 21**

Showing the corrosion attack  
on the bottom of the alloy  
2205 tube. Return side.

Magnification: 2.8X



**Figure 22**

Showing the corrosion attack  
on the trailing edge of the alloy  
2205 tube. Return side.

Magnification: 2.8X




**Figure 23**

Showing the pitting corrosion on the alloy 2205 tube. Supply side.

Magnification: 5.4X

**Figure 24**

Showing the locations of the metallographic samples taken from the alloy 2205 tube. Mount 1797 was examined but was not significantly different from mount 1798.



# Figure 25

Thickness and Corrosion Results - Return Side - Leading Edge of Tube  
(Alloy 2205 Tube/AISI 409 Fin Materials)

Mount #1795

All thickness measurements are in inches

**Tube - Under Fin**

<u>Covered</u>	<u>Uncovered</u>
0.0767	0.0762
0.0766	0.0738
0.0768	

**Corrosion Rate, mpy**

<u>Uncovered</u>
0.4
2.5

**Tube- Exposed**

	<u>1/4</u>	<u>midpt</u>	<u>3/4</u>
A	0.0748	0.0706	0.0716
B	0.0742	0.0711	0.0756

**Corrosion Rate, mpy**


<u>1/4</u>	<u>midpt</u>	<u>3/4</u>
1.6	5.2	4.3
2.1	4.7	0.9

**Fin**

	<u>Base</u>	<u>1/4</u>	<u>midpt</u>	<u>3/4</u>	<u>Tip</u>
1	0.044	0.038	0.035	0.032	0.03
2	0.046	0.040	0.036	0.034	0.03
3	0.047	0.039	0.037	0.034	0.027

**Corrosion Rate, mpy**

<u>1/4</u>	<u>midpt</u>	<u>3/4</u>	<u>Tip</u>
6.5	9.0	11.6	13.3
4.8	8.2	9.9	13.3
5.6	7.3	9.9	15.8



Showing the corrosion rates on a graphical representation on the examined section



# Figure 26

Thickness and Corrosion Results - Return Side - Trailing Edge of Tube  
(Alloy 2205 Tube/AISI 409 Fin Materials)

Mount #1796

All thickness measurements are in inches

### Tube - Under Fin


<u>Covered</u>	<u>Uncovered</u>	
0.0792	0.0788	
0.0783	0.0784	Average
0.0786	0.0788	0.0787
0.0788		

### Tube- Exposed

	<u>1/4</u>	<u>midpt</u>	<u>3/4</u>	<b>Corrosion Rate, mpy</b>		
				<u>1/4</u>	<u>midpt</u>	<u>3/4</u>
A	0.0788	0.0784	0.0784	-0.1	0.3	0.3
B	0.0787	0.0786	0.0784	0.0	0.1	0.3
C	0.0788	0.0787	0.0787	-0.1	0.0	0.0

### Fin

	<u>Base</u>	<u>1/3</u>	<u>2/3</u>	<u>Tip</u>	<b>Corrosion Rate, mpy</b>		
					<u>1/3</u>	<u>2/3</u>	<u>Tip</u>
1	0.0512	0.0396	0.0347		9.6	13.8	
2	0.0505	0.0384	0.0346	0.0304	10.6	13.8	17.4
3	0.0511	0.0411	0.0342	0.0303	8.3	14.2	17.5



Showing the corrosion rates on a graphical representation of the examined section.



**Figure 27**

Showing the cracking in the bottom of the pits in the AL-6XN<sup>®</sup>. Location A, return side.

Magnification: 200X

Unetched




**Figure 28**

Showing the details of the AL-6XN<sup>®</sup> cracking.

Magnification: 200X

Etchant: Mixed acids followed by electrolytic 10% Oxalic Acid




**Figure 29**

Showing the preferential corrosion attack of the leading edge of the alloy 2205 tube.

Magnification: 4.8X

Etchants: Glyceregia followed by Electrolytic 10N KOH



**Figure 30**

Showing the details of an AISI 409 fin to alloy 2205 tube braze joint.

Magnification: 75X


Etchants: Glyceregia followed by Electrolytic 10N KOH



**Figure 31**

Showing a group of pits in alloy 2205


Magnification: 100X



**Figure 32**

Showing one of the pits in Figure 31 at higher magnification. Note the corrosion product "fingers" penetrating into the material.

Magnification: 400X



**Figure 33**

Showing a large pit in the alloy 2205. The light phase is austenite and the dark phase is ferrite. This pit does not exhibit the preferential attack as does Figure 32.

Magnification: 400X

Etchants: Glyceregia followed  
by Electrolytic  
10N KOH

# TABLE 1

CORROSION RATES FOR KINTIGH STATION EXPERIMENTAL HEAT PIPES  
Based on 3310 hours of operation

20-Dec-93

LOCATION  
KEY

#1 Adiabatic section  
#2 Evaporator, 12" from center duct Return Side  
#3 Evaporator, 24" from center duct Return Side  
#4 Near Evaporator end Return Side  
#5 Condenser, 18" from center duct Supply Side  
#6 Near Condenser end Supply Side

	Location	Section	WALL THICKNESS, INCHES				CORROSION RATE, MPY				
			TOP	SIDE	BOTTOM	SIDE	TOP	SIDE	BOTTOM	SIDE	GREATEST
Carbon Steel Toluene	B	CT1	0.104	0.102	0.101	0.101					
	B	CT2	0.101	0.102	0.1	0.103	7.9	0	2.6	-5.3	
	B	CT3	0.102	0.101	0.101	0.102	5.3	2.6	0	-2.6	
	B	CT4	0.103	0.102	0.099	0.101	2.6	0	5.3	0	7.9
Carbon Steel Freon	A	CF1	0.098	0.102	0.102	0.103					
	A	CF2	0.099	0.102	0.099	0.096	-2.6	0	7.9	18.5	
	A	CF3	0.095	0.091	0.098	0.099	7.9	29.1	10.6	10.6	
	A	CF4	0.093	0.0975	0.1	0.086	13.2	11.9	5.3	45	45
	A	CF5	0.099	0.101	0.079	0.101	-2.6	2.6	60.8	5.3	
	A	CF6	0.097	0.101	0.1	0.101	2.6	2.6	5.3	5.3	60.8
			MISC FIGURE 6	0.085 0.08 0.086	0.083 0.072 0.085	0.086 0.088 0.0995	0.081 0.09 0.08	43 56.2 40.3	48.3 77.4 43	40.3 35.1 4.6	53.6 29.8 56.2
Cor-Ten Freon	A	AF1	0.257	0.255	0.252	0.252					
	A	AF2	0.246	0.247	0.246	0.243	29.1	21.2	15.9	23.8	
	A	AF3	0.246	0.247	0.246	0.246	29.1	21.2	15.9	15.9	
	A	AF4	0.241	0.253	0.252	0.246	42.3	5.3	0	15.9	42.3
AL-6XN Toluene	B	ST1	0.06	0.061	0.061	0.059					
	B	ST2	0.061	0.062	0.059	0.061	-2.6	-2.6	5.3	-5.3	
	B	ST3	0.059	0.06	0.059	0.059	2.6	2.6	5.3	0	
	B	ST4	0.06	0.06	0.06	0.06	0	2.6	2.6	-2.6	5.3
AL-6XN Freon	A	SF1	0.061	0.06	0.061	0.059					
	A	SF2	0.06	0.057	0.06	0.055	2.6	7.9	2.6	10.6	
	A	SF3	0.061	0.059	0.06	0.059	0	2.6	2.6	0	
	A	SF4	0.06	0.059	0.06	0.059	2.6	2.6	2.6	0	10.6

**Table 2**

**Thickness and Corrosion Results**

Alloy 2205 Heat Pipe

All thickness measurements are in inches

1. **Base Thickness - Under Center Collar**

0.0774	0.0771	0.0771	0.0782
0.0769	0.0772	0.0780	

Average 0.0774

2. **Thickness Supply Side of the Unfinned End**

0.057	0.0685	0.063
0.068	0.056	

**Corrosion Rate, mpy**

17.3	7.5	12.2
8.0	18.1	

**Greatest**

18.1

3. **Thickness Return Side of Unfinned End**

0.067	0.07	0.071	0.071
0.071	0.07	0.066	0.068

**Corrosion Rate, mpy**

8.8	6.3	5.4	5.4	9.7
5.4	6.3	9.7	8.0	

## **APPENDIX A**

Appendix is not included since information is confidential to ABB API.



**MILLIKEN CLEAN COAL TECHNOLOGY  
DEMONSTRATION PROJECT**

**MILLIKEN UNIT 2 ESP AND SLIPSTREAM HEAT PIPE CORROSION TESTS  
July 15, 1993 to May 21, 1994  
Final Report**

**Prepared by:**

CONSOL Inc.  
Research and Development  
4000 Brownsville Road  
Library, Pa. 15129-6613

**Principal Investigators**

CONSOL R&D  
D. C. McCoy  
U. Weinheimer


NYSEG  
G. S. Janik  
B. Marker

**Prepared for:**

New York State Electric & Gas Corporation  
Corporate Drive  
Kirkwood Industrial Park  
P. O. Box 5224  
Binghamton, NY 13902-5224

**Under Research and Development Contract No. 95-149**

**August 1995**



CONSOL Inc.  
Research & Development  
4000 Brownsville Road  
Library, PA 15129-9566

## ACKNOWLEDGEMENTS

The authors wish to thank the following persons and organizations for their cooperation and help during the testing program:

Messrs. Paul Southard and Dan Hill of New York State Electric & Gas Corporation for their help and support in making work space available, and for periodic monitoring of unattended electronic equipment; to Dr. Dave Moore of CAPCIS for his help in refurbishing the CAPCIS corrosion probes and for answering questions concerning the probe performance; and to Mr. Kent Zammit and EPRI for the loan of CAPCIS corrosion probe electronics to the project.

# TABLE OF CONTENTS

197

SUMMARY .....	1
RESULTS .....	1
Air-Cooled Corrosion Probes .....	1
CAPCIS Probes .....	2
CONCLUSIONS .....	3
INTRODUCTION .....	3
General .....	3
Probe Design .....	4
Probe Location .....	4
DISCUSSION .....	6
Air-Cooled Probe Temperatures .....	6
Air-Cooled Probe Corrosion Rates .....	7
System SO <sub>3</sub> Levels .....	8
CAPCIS Probe Corrosion Rates .....	8
ESP Outlet Results .....	8
Slipstream Heat Pipe Outlet Results .....	9
Corrosion Probe Inspections .....	11
REFERENCES .....	13
APPENDIX	

198

## LIST OF TABLES

<u>Table No.</u>		<u>Page No.</u>
1	Corrosion Rates for Air-Cooled Probes (Based on Dimension Changes)	14
2	Flue Gas SO <sub>2</sub> /SO <sub>3</sub> Levels, Milliken Station	15
3	Corrosion Rates for CAPCIS Probes (Based on Electronic Results and Dimension Changes)	16

### LIST OF FIGURES

<u>Figure No.</u>		<u>Page No.</u>
1	Corrosion Probe Tip Construction	17
2	Sensor end of CAPCIS Probe	17
3	Corrosion Probe Operating Times, Milliken Station July 1993 to May 1994	18
4	ESP Inlet Duct with Sample Ports	19
5	Unit 2 ESP Inlet Temperatures	19
6	No. 1 Air-Cooled Probe Skin Temperatures	20
7	No. 2 Air-Cooled Probe Skin Temperatures	20
8	No. 3 Air-Cooled Probe Skin Temperatures	21
9	No. 1 Air-Cooled Probe Corrosion Rates, 7/15/93 to 9/2/93	22
10	No. 1 Air-Cooled Probe Corrosion Rates, 7/15/93 to 1/14/94	22
11	No. 1 Air-Cooled Probe Corrosion Rates, 2/05/94 to 5/22/94	22
12	No. 2 Air-Cooled Probe Corrosion Rates, 7/29/93 to 9/2/93	22
13	No. 2 Air-Cooled Probe Corrosion Rates, 7/29/93 to 1/14/94	22
14	No. 2 Air-Cooled Probe Corrosion Rates, 2/05/94 to 5/22/94	22
15	No. 3 Air-Cooled Probe Corrosion Rates, 7/29/93 to 9/2/93	23
16	CAPCIS Probe Indicated Corrosion Rates, Milliken Station Unit 2 ESP Outlet	23
17	Corrosion Rate vs Gas Temperature, Milliken Station—Unit 2 ESP Outlet 8/26/93 to 1/14/94	24
18	Corrosion Rate vs Probe Temperature, Milliken Station—Unit 2 ESP Outlet 8/26/93 to 1/14/94	24
19	CAPCIS Probe Indicated Corrosion Rates	25
20	CAPCIS Probe Corrosion Rates (Original)	26
21	CAPCIS Corrosion Rates (Corrected)	26

## LIST OF FIGURES (Cont.)

22	Corrosion Rate vs Gas Temperature	27
23	Corrosion Rate vs Probe Temperature	27
24	Corrosion Rate vs Gas Temperature	28
25	Corrosion Rate Vs Probe Temperature	28
26	NH <sub>3</sub> Slip and SA-178A Corrosion Rates	29
27	NH <sub>3</sub> Slip and Cor-Ten A Corrosion Rates	29
28	Photo -- Typical installation for air-cooled probes	30
29	Photo -- Typical installation for CAPCIS probes	30
30	Photo -- No. 1 air-cooled probe upon removal from duct (1168 operating hours)	31
31	Photo -- No. 2 air-cooled probe upon removal from duct (832 operating hours)	31
32	Photo -- No. 3 air-cooled probe upon removal from duct (832 operating hours)	32
33	Photo -- No. 1 air-cooled probe after exposure to humid air	32
34	Photo -- No. 2 air-cooled probe after exposure to humid air	33
35	Photo -- No. 3 air-cooled probe after exposure to humid air	33
36	Photo -- Close-up of spalling deposits on No. 1 air-cooled probe	34
37	Photo -- Pitted surface of No. 3 air-cooled probe (2205 SS)	34
38	Photo -- Overall view of cleaned No. 1 air-cooled probe (1168 operating hours)	35
39	Photo -- Close-up of cleaned No. 1 air-cooled probe (1168 operating hours)	35
40	Photo -- Overall view of cleaned No. 2 air-cooled probe (832 operating hours)	36
41	Photo -- Close-up of cleaned No. 2 air-cooled probe (832 operating hours)	36

## LIST OF FIGURES (Cont.)

42	Photo -- Overall view of cleaned No. 3 air-cooled probe (832 operating hours)	37
43	Photo -- Close-up of cleaned No. 3 air-cooled probe (832 operating hours)	37
44	Photo -- End of test overall view of cleaned No. 1 air-cooled probe	38
45	Photo -- End of test close-up view of cleaned No. 1 air-cooled probe	38
46	Photo -- End of test overall view of cleaned No. 2 air-cooled probe	39
47	Photo -- End of test close-up view of cleaned No. 2 air-cooled probe	39
48	Photo -- Deposit covered No. 2 air-cooled probe (2664 operating hours)	40
49	Photo -- No. 2 air-cooled probe corroded area close-up	40
50	Photo -- SA-178A CS CAPCIS probe upon removal from ESP outlet duct (1609 operating hours)	41
51	Photo -- SA-178A CS CAPCIS probe upon removal from heat pipe outlet duct (2487 operating hours)	41
52	Photo -- Cor-Ten A CAPCIS probe upon removal from heat pipe outlet duct (2487 operating hours)	42
53	Photo -- Close-up of cleaned SA-178A CS CAPCIS probe	42
54	Photo -- Close-up of cleaned Cor-Ten A CAPCIS probe	43

## LIST OF ABBREVIATIONS

<b>Amp</b>	Ampere
<b>Avg</b>	Average
<b>CCT-IV</b>	Clean Coal Technology IV
<b>CS</b>	Carbon Steel
<b>ECN</b>	Electro Chemical Noise
<b>ESP</b>	Electrostatic Precipitator
<b>g</b>	Gram
<b>Mils</b>	0.001 inches
<b>MW</b>	Megawatt
<b>ppmv</b>	Parts Per Million by Volume
<b>SCR</b>	Selective Catalytic Reduction
<b>SDEV</b>	Standard Deviation
<b>SS</b>	Stainless Steel
<b>TC</b>	Thermocouple
<b>NYSEG</b>	New York State Electric & Gas
<b>OD</b>	Outside Diameter
<b>dia</b>	Diameter
<b>R</b>	Overall Corrosion Rate (Equation 1)
<b>RH</b>	Relative Humidity



### ABSTRACT

Corrosion monitoring tests were conducted at the Milliken Station to determine the performance of SA-178A carbon steel (CS), Cor-Ten™ A, and 2205 duplex stainless steel in the flue gas environment that will exist at the outlet of the new Unit 2 heat pipe air heater. Two types of probes, manual air-cooled and real-time CAPCIS electronic probes, were used to measure corrosion rates. Corrosion rates were measured in flue gas environments with and without fly ash and with fly ash and ammonia present. The 2205 SS was eliminated from the test program because of deep, rapid pitting. The test results showed that Cor-Ten A exhibited a low corrosion rate, typically about 2 mils/yr, and was a suitable material of construction for the heat pipe cold-end outlet. The test results also indicate that SA-178A CS is a suitable material for the ductwork downstream of the heat pipe. The electronic corrosion probe results showed that high corrosion rates can occur during shutdown periods, particularly for carbon steel. The off-line corrosion is likely due to wall sweating when ambient relative humidity is high. Failure to adequately sootblow fly ash deposits appears to result in severe localized metal attack on Cor-Ten A.

## SUMMARY

Two heat pipe air heaters were installed on the Milliken Station Unit 2 boiler as part of the thermal performance improvement modifications for the CCT-IV test program. Prior to installing the new heat pipes, tests were conducted at the Milliken Station to determine the corrosion rates of candidate materials of construction for the cold-ends of the air heaters. Two types of corrosion probes were used for the tests; simple air-cooled probes and electronic CAPCIS probes. The air-cooled probes required manual measurement of diameters for estimation of corrosion rates. The CAPCIS probes provided real-time corrosion rates that changed with operating conditions.

The simple air-cooled probes were made of Cor-Ten A<sup>™</sup> (two probes) and 2205 stainless steel (SS). These probes were placed in the ducts between the 2A and 2B Ljungstrom air heaters and the 2A and 2B ESPs for long term exposure to a flue gas/fly ash environment. The CAPCIS probes were made of SA-178A carbon steel (CS) (probe 1) and Cor-Ten A (probe 2). The probes were used in two locations; the outlet of the 2A ESP (SA-178A probe only), in a flue gas without fly ash environment, and the outlet of the slipstream heat pipe (both probes), in a fly ash and ammonia containing flue gas environment. The ammonia was from an upstream NO<sub>x</sub> removal process.

The test results indicate that both SA-178A CS and Cor-Ten A are suitable materials of construction for the cold-end of the heat pipe while 2205 SS is not suitable. During short-term testing, 2205 SS pitted severely when exposed to a flue gas environment. The test results indicate that SA-178A is suitable for the ductwork downstream of the heat pipe.

The test results demonstrated that high corrosion rates could occur for carbon steel during shutdown periods when humid ambient air enters the ductwork. Although not measured by the real-time probe, rapid blistering of the manual probe indicates humid air conditions also may cause increased corrosion of Cor-Ten. Controlling ductwork humidity during a shutdown is one method of limiting or eliminating this form of corrosion.

## RESULTS

Results for the corrosion test program are:

### Air-Cooled Corrosion Probes

- Flue gas environment corrosion rates are typically less than 3 mils/yr for the Cor-Ten A probes regardless of whether the probes are operated at average target temperatures of 172°F, 192°F or 202°F.
- The corrosion rates for 2205 SS operated at 170°F are less than 5 mils/yr. However, extensive surface pitting occurs where fly ash is deposited. Because pitting corrosion causes rapid penetration of tube walls with little metal loss, the test results demonstrate that 2205 SS is not suitable for use in the cold-end of the full-scale heat pipe air heater.

- Corrosion rates based on probe diameter measurements do not indicate a general trend with distance from the cold end to the hot end of the probe. However, one Cor-Ten A probe did visually appear more corroded over the bottom 4" (the coldest portion of the probe) than over the top 12".
- There is evidence that severe metal attack of Cor-Ten A may occur under fly ash deposits which are left in place for prolonged periods. The probable cause is continued acid deposition on the probes when the metal surface temperatures are below the sulfuric acid dew point. This eventually depletes any components in the fly ash which neutralize the acid. Adequate sootblowing to remove fly ash deposits before they become acid saturated should minimize this form of corrosion.

### CAPCIS Probes

- At the ESP outlet, the CAPCIS corrosion rates for SA-178A are low and do not differ significantly for the two metal surface temperatures tested. Corrosion rates are 1.9 mils/yr at 168°F and 2.3 mils/yr at 231°F. The low corrosion rates were confirmed by manual measurements of the sensing elements. This showed that the measured electronic corrosion rate was below the potential error associated with the precision or resolution of caliper measurements (i.e., 2.7 mils/yr and 2.9 mils/yr for the 168°F and 231°F tests, respectively). These results indicate that carbon steel should be a suitable material for the duct work downstream of the ESP.
- At the slipstream heat pipe outlet, the CAPCIS probes were exposed to a flue gas environment containing both fly ash and ammonia from a pilot NO<sub>x</sub> removal process. Measured corrosion rates based on sensing element diameter changes are low for both SA-178A and Cor-Ten A materials. Overall rates based on manual measurements for SA-178A are between 2.9 to 3.5 mils/yr at 176°F and for Cor-Ten A are between 1.7 to 1.9 mils/yr at 174°F. These results indicate that Cor-Ten A is the most corrosion resistant of the two materials. Either material would be suitable for cold-end heat pipe construction. Based on a corrosion rate of 3.5 mils/yr for SA-178A and 1.9 mils/yr for Cor-Ten A, minimum tube wall thicknesses are 0.085" and 0.053", respectively, assuming 20-year life and the need for 15 mils minimum metal thickness for pressure containment.
- At the slipstream heat pipe outlet, the CAPCIS corrosion rate for SA-178A averaged 3.5 mils/yr. This corrosion rate, based on the electrical response of the CAPCIS probe, was confirmed by manual diameter measurements of the sensing elements.
- Corrosion rates based on manual measurements of probe diameters indicated that the corrosion rate coefficient previously developed for Cor-Ten B over predicts by about seven times the corrosion rate for Cor-Ten A.
- Fly ash in the flue gas appears to provide some protection against SO<sub>3</sub> and/or ammonium bisulfate, (NH<sub>4</sub>)HSO<sub>4</sub>, attack. Ammonia slip during the Milliken heat pipe tests averaged about 2.5 ppmv. Corrosion rates for both SA-178A and Cor-Ten A were generally lower than experienced at the Kintigh Station for SA-178A and Cor-Ten B in a fly ash free flue gas with 2 ppmv ammonia slip. At Kintigh, corrosion

rates for SA-178A did not drop to 2-4 mils/yr until temperatures were greater than about 195°F and remained high (>10 mils/yr) for Cor-Ten B even at the highest test temperatures (up to 230°F).

## CONCLUSIONS

Based on the corrosion test results the following conclusions are made:

- Cor-Ten A appears to be an acceptable construction material for the heat pipes in the cold-end module of the Unit 2 air heater.
- Purging the ductwork with dry or heated air may reduce corrosion during downtime periods by eliminating the metal sweating which allows corrosion to occur.
- Providing cold-end sootblowing so that tube surface deposits are routinely removed in a timely fashion will likely prevent deposits from becoming acid soaked and should minimize corrosion rates.
- Visual inspections of the air-cooled corrosion probes indicate increased corrosion for metal temperatures below 170°F. To minimize corrosion, the heat pipe should be operated to maintain tube metal skin temperatures at or above 170°F.
- When using the CAPCIS probes to monitor corrosion rates, a corrosion rate coefficient of  $4.39 \times 10^8$  mils/(yr-amp) should be used for SA-178A and  $6.44 \times 10^7$  mils/(yr-amp) for Cor-Ten A.

## INTRODUCTION

### General

As part of the Clean Coal Technology IV (CCT-IV) program, a full-scale heat pipe air heater was installed at the Milliken Station to improve system thermal efficiency. A corrosion study was conducted at the Milliken Station between July 15, 1993, and May 22, 1994, to test candidate materials of construction for the air heater cold-end heat pipes and outlet ductwork.

The testing utilized two types of corrosion probes. Both types used air cooling for temperature control. In this report, to differentiate between the two probe types, the first type will be referred to simply as "air-cooled probes" and the second type as "CAPCIS probes." The air-cooled probes were used to measure overall corrosion rates based on probe diameter changes over time. The CAPCIS probes used electronic sensors and a proprietary computer code to estimate the instantaneous corrosion rates. Diameter measurements of the CAPCIS probe sensing elements were used to confirm the CAPCIS corrosion rates and to adjust the corrosion rate coefficient in the corrosion software.

## Probe Design

Figure 1 shows the general construction of the corrosion monitoring tip of the air-cooled probes. Two Cor-Ten A probes and one 2205 SS probe were constructed by CONSOL R&D for the test program.

As shown in Figure 1, the probe design consists of a 2" OD tube with a sealed base end. An external thermocouple (TC) at the probe base measures surrounding process gas stream temperatures. Three internal TCs welded to the wall of each probe provide surface metal temperatures and local gradients. Normally, the center wall TC (see view A-A) was connected to an on/off temperature controller which maintained the probe temperature to about  $\pm 5^{\circ}\text{F}$  of the set point. An air line down the center of the probe provides cooling air to the probe tip. Heated air from the tip flows in the annular space between the air line and the probe wall and vents out the back end of the probe to the atmosphere. To remove fly ash deposits from the probe surface, there are three 1/4" dia. air nozzles spaced equidistance around the circumference.

To allow accurate location of reference diameter measurement points on the probes, circumferential and axial lines were scribed in the probe surface. The circumferential lines are spaced every 2" from the bottom end and the two axial lines are  $60^{\circ}$  apart. Measurements were always taken as close as possible to the circumferential-axial line intersection points.

The second type of corrosion probe was purchased from CAPCIS March Limited by NYSEG. Two probes (one made of SA-178A and one made of Cor-Ten B) were originally purchased by NYSEG for tests at the Kintigh Station in 1993. After the Kintigh Station tests, the probe sensing elements were refurbished by CAPCIS in SA-178A and Cor-Ten A.

The sensing end of a typical probe is shown in Figure 2. The sensor element consists of thirteen nominally 2.5" diameter metal rings made of the corrosion test material. The rings are separated by Viton<sup>®</sup> spacers and are wired to corrosion monitoring electronics. Voltage, current, and resistance signals from the probes are monitored by the electronics and converted to corrosion rates by CAPCIS software. The CAPCIS probes include an external TC for measuring the gas temperature around the sensing elements. Internal TCs are used to monitor and control the sensing element temperature. An air line down the center of the probe provides cooling air to the probe tip. Heated air from the tip flows back up the probe to the open end where it is vented to the atmosphere. Like the air-cooled probes, a cooling air on/off controller maintains metal temperatures.

After exposure to the flue gas environment, manual measurement of the sensing element diameters confirmed electronic indicated corrosion rates. The elements were measured across two orthogonal radii with the location of the gas TC as a reference.

## Probe Location

The location, operating temperature, and operating period for each corrosion probe is shown in Figure 3. Start dates are different because the probes were installed as they became available.

The No. 1 Cor-Ten A air-cooled probe was installed on July 15, 1993, in Port 1 of the 2B flue gas duct (see Figure 4) running between the Milliken Station air heater outlet and the inlet to the ESP. At this location, the corrosion probe was exposed to a flue gas/fly ash/SO<sub>3</sub> environment similar to that at the cold-end outlet of the new heat pipe air heater. The probe was initially operated at target temperature of 172°F to simulate the cold-end design metal temperature for the full-scale heat pipe operating at a 250°F outlet flue gas.

During the corrosion test program, Milliken Station Units 1 and 2 operated with Ljungstrom air heaters. As shown in Figure 5, Ljungstrom air heaters generate large temperature gradients across the outlet ductwork. The No. 1 air-cooled probe was installed in a port where the flue gas temperatures were typically 240-260°F. The port location was selected based on the assumption that the severest corrosion might occur when the gas temperature is below the acid dew point.

On August 11, 1993, the first air-cooled probe was moved from Port 1 of Duct 2B to Port 9 of Duct 2A. This placed the probe in line with the No. 1 CAPCIS probe which was later installed in the 2A ESP outlet duct. In the new location, the No. 1 air-cooled probe could be used to directly compare ESP inlet/outlet corrosion rates since relatively little gas mixing occurs in ESPs. After completion of the ESP outlet corrosion monitoring program, the No. 1 air-cooled probe was moved to a high temperature region of Duct 2A because other corrosion probe tests indicated slightly higher corrosion rates for the high temperature zones.

The No. 2 air-cooled probe was also made of Cor-Ten A and was installed in a high temperature zone of Duct 2B. The probe was initially operated at a target temperature of 201°F to simulate the operating conditions for an alternate air heater design with flue gas outlet temperatures of 280°F. During the last stage of testing, the target control temperature for this probe was reduced to 172°F (174°F actual average).

The No. 3 air-cooled probe was made of 2205 duplex SS and was installed in a port next to the No. 1 air-cooled probe. Because of severe pitting attack, the probe was removed from service after only 35 days in operation.

On August 23, 1993, the No. 1 CAPCIS probe was installed in the outlet duct from the 2A ESP. This part of the program was to study corrosion in the ductwork downstream of the ESP and to monitor the corrosion in real time to see if process changes effected the corrosion rate. The flue gas temperature at the probe location was between 240°F to 250°F initially. The probe control temperature was set at about 230°F to simulate the temperature of insulated ductwork. Later, the probe temperature was set at 168°F (170°F target) to simulate a moderate cold spot which might exist due to ductwork insulation loss or to heat conduction through supports.

When the ESP tests were completed, the No. 1 CAPCIS probe was cleaned and sensing element dimensions were measured for an independent determination of corrosion rates. On February 7, 1994, the probe was relocated to the outlet duct of a pilot heat pipe. The heat pipe and a pilot NO<sub>x</sub> reduction process were installed on a flue gas slipstream between the Milliken Unit 2B air heater inlet duct and the 2B ESP inlet. The No. 2 CAPCIS probe (Cor-Ten A material) was received from the supplier and installed at the heat pipe outlet.

These two probes were then used to monitor corrosion rates in flue gas containing fly ash,  $\text{SO}_3$ , and ammonia ( $\text{NH}_3$ ); an environment which would exist downstream of the full-scale heat pipe if a  $\text{NO}_x$  reduction system was installed on Unit 2. The operating temperatures for the probes was maintained at about 172°F to simulate design cold-end temperatures in the full-scale heat pipe.

## DISCUSSION

### Air-Cooled Probe Temperatures

As shown in Figure 1, each of the air-cooled corrosion probes had three wall TCs to monitor metal temperatures. The TCs were spaced 2" apart and the center TC was normally used to control the cooling air purge rate. Figures 6, 7, and 8 show metal temperatures for corrosion probes 1, 2, and 3, respectively. The data are single point values taken once a day from locally mounted data recorder strip charts. For most of the testing, the probes were operated unattended. Gaps in the data, other than for probe inspections and dimensional measurements, are due to running out of chart paper or printer failures. Printer failures were caused by the high dust environment (above the Unit 2 ash silo) and to extreme cold temperatures. Except for a four-day period (2/7/94 to 2/10/94), the probe temperature control instrumentation was found to be functioning properly whenever printer failures were discovered. We assumed that probe temperatures remained close to desired set point temperatures during periods when data were not recorded.

The target operating temperature for the No. 1 air-cooled probe was 172°F for the 7/15/93 to 1/14/94 test period. As shown in Figure 6, the center control skin temperature normally remained within  $\pm 5$  degrees of this target. The axial temperature gradient averaged about 12°F over the 4" distance from the coldest to hottest TC and was not linear with distance from the cold end.

The second time the air-cooled probes were removed from the system for inspection and dimension measurements, the top TC connector head for the No. 1 air-cooled probe was accidentally broken. The probe was reinstalled with only the bottom and middle TCs operational. Because of faulty wiring, control was switched to the bottom TC. Although the bottom TC temperature was controlled between about 172°F and 182°F, the control point change resulted in an increase in the average probe temperature. To place the operation on a common basis with other tests, an average temperature of 192°F for the period 2/5/94 to 5/22/94 is used based on the center TC reading for reference.

The temperature data for the No. 2 air-cooled probe is presented in Figure 7. For the first test period (7/29/93 to 1/14/94), the target control temperature was 202°F. This was achieved and temperature control was stable with the middle or center control temperature remaining within about  $\pm 5$ °F of the set point. Because corrosion rates were low for 202°F operation, the target control temperature was lowered to 172°F (174°F actual value achieved) for the 2/5/94 to 5/22/94 test period. Again, temperature control was stable.

Figure 8 presents the temperature data for the No. 3 air-cooled probe. As for the other two probes, the temperature control was tight and stable.

### Air-Cooled Probe Corrosion Rates

Table 1 summarizes the corrosion data for the air-cooled probes based on diameter measurements. For each probe, diameter measurements were taken at eight locations along two axial scribe lines (see Figure 1). The probe dimensional measurements are presented in Appendix Tables 1A, 2A, and 3A. The data summarized in Table 1 are average corrosion rates taken over the length of the probe. Average rates are presented since the bulk of the data do not show a general corrosion rate trend with distance from the cold end (see Figures 9 to 15). Table 1 results show that overall corrosion rates for all temperatures investigated were low. The rate averaged generally less than 2 mils/yr. This indicates that Cor-Ten A should hold up well in the low temperature end of the full-scale heat pipe.

The results also indicate a low average corrosion rate for 2205 SS ranging from 0.9 to 2.5 mil/yr. However, as discussed in the Corrosion Probe Inspections Section, severe surface pitting corrosion occurred in areas covered by fly ash deposits. Areas where deposits were absent had smooth uncorroded surfaces. The likely cause of the corrosion is sulfuric acid attack under the deposits. Because of the pitting attack, the 2205 SS material was not tested further.

The negative corrosion rates shown in Figures 9, 10, 11, and 12 can be attributed to: (1) errors in reading the caliper correctly, (2) errors associated with not duplicating exactly the measurement locations at the beginning and end of a test, and (3) the presence of a surface deposit. Efforts were made to minimize all the aforementioned errors by: having the same technician do all the measurements with the same caliper (which was stored and not used between measuring periods), providing scribe marks on the probes for caliper positioning, and by carefully cleaning the probes. Appendix Tables 1A and 4A present data where the technician was asked to repeat measurements without reference to the original readings. Pooled standard deviations of the differences in the readings for the air-cooled probes ranged from 0.00011" to 0.00016" and for the CAPCIS probes 0.00044" to 0.00059" at 95% confidence level. These results mean that the technician was generally able to find the correct measurement location and to measure the probe or sensor element diameters to about the resolution accuracy of the calipers, which for the air-cooled probes was 0.0001" and for the CAPCIS probes was 0.0005". Due to the narrowness of the CAPCIS probe sensor elements, a second caliper with a resolution of 0.0005" had to be used for these diameter measurements.

Since corrosion rates were very low and the test times relatively short, the accuracy of the calculated rates was also low. Often, the reported rate is similar to the potential error that could occur due to caliper resolution (i.e.,  $(2 \times \text{caliper resolution} \times 8760000) / (2 \times \text{test hours}) = \text{mils/yr}$ ). In other words, the maximum measurement error would be generated if the beginning and ending diameter measurements for a point were each off in opposite directions by the caliper resolution. For the air-cooled probes, diameter changes greater than 0.0002" were required for the measured corrosion to be greater than the maximum error associated with caliper resolution. For the CAPCIS probes the actual corrosion had to be 5 times this value (i.e., exceed 0.001") due to the need to use a poorer resolution caliper.



System SO<sub>3</sub> Levels

The flue gas SO<sub>3</sub> data which were taken at various times throughout the test program are shown in Table 2. The ESP inlet data were not taken at a specific corrosion probe port location, but are average duct values based on a composite sample of ten port traverses. In all cases, the flue gas temperatures were at least slightly above the estimated acid dew points. Since corrosion probes were normally operated at 170°F-201°F, the probe temperatures were usually far below the ambient acid dew points. As a result, acid condensation on the probes was likely. The low measured corrosion rates indicate that the fly ash may provide protection by neutralizing some of the acid.

The flue gas particulate loadings were not determined for the SO<sub>3</sub> measurements. However, the SO<sub>3</sub> content of the solids collected on fiber glass filter plugs used at the inlet of the sampling probes was determined. These data show a trend of higher SO<sub>3</sub> levels on flue gas solids with declining flue gas temperature. It is likely that sulfuric acid is absorbing on the solids/filter or condensing in the pores of the solids as the dew point temperature is approached.

The ESP outlet data for the location where the SA-178A CAPCIS probe was installed shows a low level of SO<sub>3</sub> in the gas phase and a very high proportion of the total SO<sub>3</sub> on the solids collected by the probe filter plug. Again, this indicates either acid condensation or absorption on the very small amount of particulate present at this location, or the presence of an acid fog. The fact that the flue gas temperature at the ESP outlet was 8°F above the estimated acid dew point argues against acid fog formation. However, the temperatures are close; and the dew point is an estimated, not a measured, value. As a result, some fog may have formed.

CAPCIS Probe Corrosion Rates

Table 3 presents a summary of the CAPCIS probe corrosion rate data including both the manually determined corrosion rates and the integrated rates based on electro-chemical responses from the probes. Detailed data for the manually determined corrosion rates are presented in Tables 4A through 7A in the Appendix while the daily average electro-chemical signal results are presented in Appendix Tables 8A through 10A.

ESP Outlet Results. At the ESP outlet, the SA-178A CAPCIS corrosion probe was purposefully located on the side of the ESP where temperatures were low due to the operation of the upstream Ljungstrom air heater. In this location, the flue gas would be at, or near, the SO<sub>3</sub> acid dew point and the probe would be exposed to any acid fog which might be produced by the air heater operation.

The manually determined corrosion rates for SA-178A were low and ranged from 0.2 to 1.9 mils/yr for probe operation at 231°F, and 0.1 to -0.6 mils/yr for probe operation at 168°F. The corrosion rate absolute values are suspect since they fall below the maximum error due to caliper resolution (2.9-2.7 mils/yr for the two test periods, respectively). The bottom line is that the actual corrosion rates are low and are less than 2.9-2.7 mils/yr.

Figure 16 shows the continuous corrosion rate response of the SA-178A probe for two test periods. Corrosion rates were low for both test periods. No correlation was found between corrosion rate and either flue gas temperature or probe temperature (see Figures 17 and 18).

Based on CAPCIS corrosion monitoring system output, the average corrosion rate at the 231°F temperature level was 2.3 mils/yr. This compares reasonably well with the 0.2 to 1.9 mils/yr rates based on measured probe diameters. The comparison was not as good for the 168°F test where the CAPCIS system rate was 1.9 mils/yr versus -0.6 to 0.1 mils/yr for rates based on diameter measurements. However, the standard deviations for the manually measured corrosion rates are high, so the actual corrosion rate should fall between the sample estimate rate and  $\pm$  about two standard deviations with 90 to 95% confidence. For the -0.6 mils/yr calculated average, the population mean is expected to fall between 0.0 mils/yr and 5.1 mils/yr. For the 0.1 mils/yr calculated average, the population mean should fall between 0.0 mils/yr and 1.7 mils/yr. Similarly, for the probe responses, the mean corrosion rate for the 168°F operation should fall between 0.5 mils/yr to 3.3 mils/yr.

As shown in Figure 16, during the last month of testing (December 1993 to January 1994), rates tended to vary more widely, fluctuating between <1 mils/yr to about 4 mils/yr. This may have been due to changes in the probe surface deposit chemistry caused by the rather low (208°F to 230°F) and variable flue gas temperatures.

The low level of corrosion at the ESP outlet is somewhat surprising since there are few solids present which might neutralize acid. When the probe was operated at 168°F, the metal was far below the acid dew point (i.e., 218°F see Table 2). A similar situation occurred during the 1993 Kintigh Station tests with the CAPCIS probes. For probe temperatures up to 160°F, corrosion rates as high as 20 mils/yr were recorded by the carbon steel CAPCIS probe in a high SO<sub>3</sub> environment with no fly ash. However, when probe temperatures were increased to 175°F, the corrosion rate dropped to <5 mils/yr. This indicates perhaps, that the acid deposition rate on the probes decreased substantially at the higher temperatures or that the surface chemistry changed.

Slipstream Heat Pipe Outlet Results. At the slipstream heat pipe outlet, the corrosion probes were exposed to an environment containing fly ash, SO<sub>3</sub>, and ammonia (NH<sub>3</sub>). At this location, SO<sub>3</sub> and NH<sub>3</sub> levels tended to vary considerably due to changes in the outlet temperature of the heat pipe and to variable testing of the upstream pilot NO<sub>x</sub> removal process. The average CAPCIS system corrosion rate for SA-178A operated at 176°F was 4.2 mils/yr. For comparison, rates based on measured probe diameters were between 2.9 and 3.5 mils/yr (see Table 3). These manually determined values should be reasonably accurate since rates were above the expected maximum error of 1.8 mils/yr due to caliper resolution. The good agreement between the CAPCIS system rate and the rate based on diameter changes indicates that the corrosion rate coefficient, which was determined for carbon steel during tests at the Kintigh Station in 1993, still holds for the Milliken tests.

In Figure 19, the indicated probe corrosion rate for SA-178A and the flue gas and probe temperatures are plotted for the test duration. The plot shows a general low level of corrosion for most of the test period with an increase in the corrosion rate during the two

week shutdown period. The shutdown period corrosion rate increase was probably caused by changes in the chemistry of probe deposits or corrosion products. Hydration of corrosion products such as iron sulfates, or condensed sulfuric acid, may have occurred and caused the indicated corrosion rate increases. During the last week of operation, the CAPCIS system corrosion rates were higher than during the first four months of operation. However, for the last three operating days, corrosion rates declined steeply towards the previous levels.

For the general surface corrosion experienced during the Milliken tests, the corrosion rate is calculated by:

$$R = 4.39 \times 10^8 (ECN) \quad (1)$$

Where:

*ECN* = Electro Chemical Noise Signal, amps

*R* = Overall Corrosion Rate, mils/yr

Figure 20 presents the on-line indicated corrosion rate data for the Cor-Ten A probe based on this calculation. The average overall indicated rate is almost seven times the rate based on measured diameters (see Table 3). This means that the corrosion rate coefficient developed for Cor-Ten B during the 1993 Kintigh Station tests does not hold for the new Cor-Ten A probe. The current results indicate that the coefficient should be  $6.44 \times 10^7$  mils/(yr-amp). Using the new coefficient, the corrosion rates for Cor-Ten A are replotted in Figure 21.

A comparison of Figures 19 and 21 shows that switching from 1.4% S to 2.8% sulfur coal did not cause a significant change in the indicated corrosion rates of either SA-178A or Cor-Ten A materials. Both indicated corrosion rates tended to drift lower while the high sulfur coal was fired. This is a desirable result, however, the testing may not have been long enough to assess the impact of coal sulfur changes. The two figures show a difference in the corrosion responses of the two CAPCIS probes during the shutdown period (4/29/94 to 5/14/94). Higher corrosion rates were indicated for SA-178A and lower rates for Cor-Ten A. The difference is probably due to the chemistry of the protective scale which supposedly forms on the Cor-Ten material. When the two probes were placed back in service, the corrosion rate for the SA-178A probe was somewhat higher than before the shutdown; while the rate for the Cor-Ten A probe was about the same as before the shutdown.

Figures 22 and 23 present the corrosion rate data for the SA-178A CAPCIS probe plotted against flue gas temperature and probe temperature, respectively. Neither figure shows a temperature trend for corrosion. The figures do show higher rates of corrosion for the last week of operation (5/14/94 to 5/22/94). Also, erratic and high levels of corrosion are indicated during the shutdown period when hydration of surface deposits may have occurred.

Similar plots for the Cor-Ten A CAPCIS probe are provided as Figures 24 and 25. Figure 24 indicates a trend of slightly higher corrosion with decreasing flue gas temperatures in the range of about 230°F to 330°F. No trend was established for probe temperature nor would one be expected since the temperature was tightly controlled at one level. A comparison of Figures 23 and 25, however, shows that the temperature control for the Cor-Ten A probe was much better than that for the SA-178A probe. This indicates the need for equipment maintenance to improve the temperature control of the carbon steel probe. As mentioned above, Figures 23 and 25 clearly show the much lower corrosion rate for Cor-Ten A over SA-178A during the shutdown period.

The average daily  $\text{NH}_3$  slip from the upstream  $\text{NO}_x$  control process to the heat pipe and the CAPCIS probe corrosion rates are shown in Figures 26 and 27. During the Kintigh Station corrosion tests, the presence of  $\text{NH}_3$  in the flue gases appeared to increase the corrosion rate for Cor-Ten B material. At a 2 ppmv level, corrosion rates up to 60 mils/yr were recorded at temperatures up to 175°F and rates were still 15-20 mils/yr at temperatures as high as 230°F. For SA-178A ammonia appeared to provide some protection. For the current tests, the level of  $\text{NH}_3$  does not appear to increase the corrosion rate of either SA-178A or Cor-Ten A materials.

### Corrosion Probe Inspections

Typical corrosion probe installations are shown in Figures 28 and 29 for the air-cooled and CAPCIS probes, respectively. The condition of the air-cooled probes when they were removed for the first inspection are shown in Figures 30, 31, and 32. As shown in Figure 28, the air-cooled probes were installed horizontally, with flue gas flow vertically upward through the duct. For these probes, fly ash deposits tended to accumulate on the bottom or windward side with little or no deposits on the top or leeward side.

When the air-cooled probes were withdrawn from the ductwork, the surface fly ash deposits were always crusty and appeared bone dry. With exposure to ambient air, the deposits would become damp or even wet, would swell, and begin to flake off. Figures 33, 34, and 35 show the first inspection condition of the two Cor-Ten A and the 2205 SS air-cooled probes one day after removal from the Milliken ductwork. During this period, the ambient humidity was relatively high so probe sweating began quickly. As shown in the figures, the deposits became dark in color and began to spall from the probe. The 2205 SS probe became wet with a yellowish, oily liquid forming under the deposits. The water absorption by the deposits is likely due to hydration of condensed sulfuric acid or iron sulfate corrosion products. It is likely that a significant amount of corrosion occurs when this happens. In the Figure 36 close-up view of the No. 1 air-cooled Cor-Ten A corrosion probe, the deposits appear as blisters; some of which have erupted open. This indicates a high rate of corrosion with gas generation when the deposits absorbed water from the air.

Figure 37 presents a close-up view of the 2205 SS air-cooled corrosion probe before cleaning. In the figure, the area not covered by deposits is smooth and uncorroded but areas covered by deposits are corroded and highly pitted. Clearly, the presence of the fly ash deposits is a factor in the corrosion of 2205 SS.

In the book "Dew Point Corrosion,"<sup>(1)</sup> it is pointed out that fly ash deposits containing residual amounts of sulfuric acid are hygroscopic and will become damp during off-load or shutdown periods. The hydrolysis of potassium, aluminum, and iron sulfates formed from the ash and metal work will create an acidic film on metal surfaces and lead to further corrosion. However, the off-load corrosion can be essentially eliminated if the relative humidity (RH) is reduced and maintained at 33% or less<sup>(2)</sup>. Based on the current program results, it is recommended that the RH in the ductwork be controlled, if feasible, to minimize corrosion in the air heater during shutdown periods. Possible control methods are to: (1) circulate dehumidified air or, (2) slightly heated air through the flue gas side of the heat pipe and downstream ductwork. As an example, with ambient conditions at 80°F and 60% RH, heating the air with a steam coil heater to 98°F would reduce the RH to 33%.

Overall and close-up views of the cleaned air-cooled probes after the first inspection for dimensional measurements are shown in Figures 38 to 43. Figures 38 and 39 show little or no corrosion on the No. 1 air-cooled probe. The machine marks on the No. 1 probe are clearly visible in Figure 39. Because of short notice for construction, two machinists were used to manufacture the probes. This resulted in differences in the probe surface dressings with the No. 1 probe being coarse and the other two fine.

Figures 40 and 41 also show very little surface attack of the No. 2 air-cooled Cor-Ten A probe after 832 hours of service. Only a slight discoloration of the cold-end tip can be seen in Figure 41, where temperatures were below about 185°F (see Figure 7). However, for this same short test period, severe corrosion of the 2205 SS probe is clearly indicated in Figures 42 and 43. The pitting extended the entire length of the probe. The probe was not tested further because the corrosion resistance was not adequate for the test environment.

Figure 44 is an overall view of a cleaned No. 1 air-cooled Cor-Ten A probe taken at the end of all testing. The probe had been operated (middle thermocouple) at nominally 172°F for 3832 hours and at 192°F for 2474 hours. As shown in the figures, this probe suffered little corrosion. At the end of testing, the coarse machine marks were still clearly visible for this probe.

Overall and close-up views of the No. 2 air-cooled probe are shown in Figures 46 and 47, respectively. This probe had been operated at nominally 201°F for 3496 hours and at 174°F for the last 2378 hours. Generally, the probe showed little or no corrosion except for the bottom 4" and in one other area 10"-12" from the bottom end. Corrosion of the bottom end was not unexpected since temperatures were below 160°F over the last 2378 hours of operation. During the period when the No. 1 air-cooled probe was operated at 172°F, the probe was installed in an area where flue gas temperatures were low due to the operation of the upstream Ljungstrom air heater (see Figures 3 and 4). In such downstream areas from Ljungstrom units, flue gas SO<sub>3</sub> levels are often greatly reduced because of condensation in the Ljungstrom. A lower SO<sub>3</sub> flue gas level would explain why the No. 2 air-cooled probe shows less corrosion than the No. 1 probe.

The area of high localized attack for the No. 2 air-cooled probe is shown in Figures 48 and 49. The corrosive attack appeared along an interface line between a fly ash deposit

covered area and a deposit-free area. The corrosion occurred on the probe where temperatures were much higher than the control temperature so corrosion would be expected to be generally low. Figure 48 shows that the corroded area is directly downstream of one of the air sootblower nozzles. One possible explanation is that the sootblower operation did not remove the deposits, but rather cooled them momentarily allowing residual acid to absorb moisture. This briefly diluted the acid, making it more corrosive. Alternately, it may be that in this area, the neutralizing capacity of the deposits was depleted. The deposits became acid soaked and this led to attack of the underlying metal. Sootblowers must provide adequate removal of fly ash deposits before the deposits become acid soaked to prevent this form of corrosion.

The conditions of the CAPCIS probes immediately after removal from the system following the ESP and slipstream heat pipe tests are shown in Figures 50 to 52. Each time the probes were removed for sensing element dimension measurements, the elements had a uniform corrosion scale. This scale, the rust-colored coating shown in the figures, is required for proper operation. For the ESP tests, only the SA-178A probe was installed. As expected, there were never any ash deposits on the probe. The probes removed from the slipstream heat pipe outlet were, however, coated with fly ash solids.

Figures 53 and 54 are close-up views of the cleaned sensing elements for the SA-178A and Cor-Ten A probes, respectively. The photographs show the final condition of the probes at the end of the testing. The surface of the SA-178A probe appears slightly rougher than that of the Cor-Ten A probe. This is to be expected since the probe was in operation longer and the manually measured corrosion rates for the SA-178A probe are about double those of the Cor-Ten A probe.

There was one interesting observation concerning the corrosion scales on the SA-178A probe. The scale was easily removed following the ESP operations by scrubbing the sensing elements using Bon-Ami<sup>™</sup>, water, and a plastic scrub pad. The scale formed during the slipstream operations when the probe was exposed to fly ash, SO<sub>3</sub>, and NH<sub>3</sub> was extremely tight and hard. Using the plastic scrub pad and Bon-Ami only caused spotty chipping of the scale. To speed up the scale removal so that the corroded diameters of the sensing elements could be measured, inhibited HCl solution (5g/l 1,3-Dibutyle-2-thiourea) was used. This quickly removed the deposit and provided a very clean surface.

## REFERENCES

1. Holmes, D. R., ed. "Dew Point Corrosion," John Wiley & Sons, New York, N.Y., 1985, p. 64.
2. *ibid.*, pp. 69-70.

**Table 1**  
**Corrosion Rates For Air-Cooled Probes**  
**(Based On Dimension Changes)**

Probe No.	1						
Location	Unit 2 Air Heater Outlet						
Port # - Duct	#1 - 2B/#9 - 2A		#1 - 2B/#9 - 2A		#4 - 2A		
Material	Cor-Ten A						
Period	7/15/93 - 9/2/93		7/15/93 - 1/14/94		2/05/93 - 5/22/94		
Operating Hours	1168		3832		2474		
Avg Probe Control Temp, deg F	172		172		192		
Avg Gas Temp, deg F	256		243		278		
Avg Corrosion Rate, mils/yr							
Axial Scribe Line "A"	1.1	0.7	SDEV	0.6	0.2	SDEV	0.5 0.6 SDEV
Axial Scribe Line "B"	0.0	0.7	SDEV	0.1	0.1	SDEV	0.7 0.2 SDEV
Potential Rate Error Due To Caliper Resolution of 0.0001", mils/yr	0.8		0.2		0.4		
Probe No.	2						
Location	Unit 2 Air Heater Outlet						
Port # - Duct	#5 - 2B		#5 - 2B		#6 - 2B		
Material	Cor-Ten A						
Period	7/29/93 - 9/2/93		7/29/93 - 1/14/94		2/05/94 - 5/22/94		
Operating Hours	832		3496		2378		
Avg Probe Control Temp, deg F	201 (1)		201 (1)		174 (2)		
Avg Gas Temp, deg F	287		279		276		
Avg Corrosion Rate, mils/yr							
Axial Scribe Line "A"	1.8	1.1	SDEV	1.3	0.3	SDEV	0.9 0.8 SDEV
Axial Scribe Line "B"	1.3	1.7	SDEV	0.9	0.9	SDEV	0.9 0.8 SDEV
Potential Rate Error Due To Caliper Resolution of 0.0001", mils/yr	1.1		0.3		0.4		
Probe No.	3						
Location	Unit 2 Air Htr Outlet						
Port # - Duct	#2 - 2B/#8 - 2A						
Material	2205 SS						
Period	7/29/93 - 9/2/93						
Operating Hours	832						
Avg Probe Control Temp, deg F	170 (2)						
Avg Gas Temp, deg F	265						
Avg Corrosion Rate, mils/yr							
Axial Scribe Line "A"	2.5	1.5	SDEV				
Axial Scribe Line "B"	0.9	0.3	SDEV				
Potential Rate Error Due To Caliper Resolution of 0.0001", mils/yr	1.1						

(1) Temperature Control Target 202 deg F.

(2) Temperature Control Target 172 deg F.

**Table 2  
Flue Gas SO<sub>2</sub>/SO<sub>3</sub> Levels  
Milliken Station**

Date Location	09/01/93 CAPCIS Probe Port Unit 2 ESP Outlet 3		01/13/94 Slipstream Heat Pipe Outlet (1) 4		04/21/94 Slipstream Heat Pipe Outlet (1) 2		04/17/94 ESP Inlet Duct Duct 2A 2 (2)		04/17/94 ESP Inlet Duct Duct 2B 2 (2)	
Number of Samples	Avg	SDEV	Avg	SDEV	Avg	SDEV	Avg	SDEV	Avg	SDEV
Flue Gas Temp, deg F	226	12	315	1	259	16	276	1	267	1
SO <sub>2</sub> @ Duct Conditions, ppmv	671	46	1042	24	982	4	1011	3	1007	37
@ 0% Oxygen, ppmv	1125	21	1472	33	1523	11	1554	12	1525	7
SO <sub>3</sub> (Gas Phase) @ Duct Conditions, ppmv	0.5	0.12	5.7	1.00	1.3	0.78	3.4	0.21	4.4	0.28
@ 0% Oxygen, ppmv	0.9	0.21	8.1	1.41	2.0	1.20	5.2	0.21	6.6	0.71
% Total SO <sub>3</sub> on Solids	43.5	6.27	4.6	1.94	38.4	35.14	17.8	6.29	15.0	3.54
Approx Acid Dewpoint, deg F	218		262		235		251		256	

(1) Note heat pipe was located downstream of SCR catalyst beds which caused some SO<sub>2</sub> conversion to SO<sub>3</sub>.

(2) Each sample was a 10 port composite with 3 points at each port.



**Table 3**  
**Corrosion Rates For CAPCIS Probes**  
**(Based On Electronic Results and Dimension Changes)**

<b>Probe No.</b>	<b>1</b>		<b>1</b>	
Location	Unit 2 ESP Outlet		Unit 2 ESP Outlet	
Material	SA-178A		SA-178A	
Period	8/25/93 - 10/27/93		11/08/93 - 1/14/94	
Operating Hours	1501		1609	
Avg Probe Control Temp, deg F	231		168	
Avg Gas Temp, deg F	235		221	
<b>Avg Corrosion Rate, mils/yr</b>				
Probe Indicated Rate	2.3	0.6 SDEV	1.9	0.7 SDEV
Based On Measured Dimensions				
Orientation "A" (1)	0.2	2.3 SDEV	0.1	0.8 SDEV
Orientation "B" (1)	1.9	1.9 SDEV	-0.6	2.9 SDEV
Potential Rate Error Due To Caliper Resolution of 0.0005", mils/yr	2.9		2.7	
<b>Probe No.</b>	<b>1</b>		<b>2</b>	
Location	Heat Pipe Outlet		Heat Pipe Outlet	
Material	SA-178A		Cor-Ten A	
Period	2/07/94 - 5/22/94		2/07/94 - 5/22/94	
Operating Hours	2487		2487	
Avg Probe Control Temp, deg F	176		174	
Avg Gas Temp, deg F	283		282	
<b>Avg Corrosion Rate, mils/yr</b>				
Probe Indicated Rate (2)	3.4	2.6 SDEV	13.5	5.6 SDEV
Probe Indicated Overall Rate (3)	4.1	4.2 SDEV	12.3	6.3 SDEV
Based On Measured Dimensions				
Orientation "A" (1)	3.5	0.7 SDEV	1.7	0.5 SDEV
Orientation "B" (1)	2.9	1.0 SDEV	1.9	0.5 SDEV
Potential Rate Error Due To Caliper Resolution of 0.0005", mils/yr	1.8		1.8	

(1) See Appendix Tables 4A, 5A, 6A, and 7A for orientation.

(2) Corrosion rates for shutdown periods not included.

(3) Corrosion rates for shutdown periods included.

Figure 1  
Corrosion Probe Tip Construction







Figure 2. Sensor end of CAPCIS probe. External gas thermocouple and the thirteen sensing elements are shown. Sensing elements are separated by Viton spacers.

**Figure 3**  
**Corrosion Probe Operating Times**  
**Milliken Station July 1993 to May 1994**






I = Inspection  
IM = Inspection & Dimensions Measurement

**Figure 4**  
**ESP Inlet Duct With Sample Ports**










**Figure 5**  
**Unit 2 ESP Inlet Temperatures**









**Figure 8**  
**#3 Air-Cooled Probe Skin Temperatures**
























**Figure 24**  
**Corrosion Rate VS Gas Temperature**  
Milliken Station – Slipstream Heat Pipe Outlet



**Figure 25**  
**Corrosion Rate VS Probe Temperature**  
Milliken Station – Slipstream Heat Pipe Outlet






Figure 28. Typical installation for air-cooled corrosion probes.




Figure 29. Typical installation of CAPCIS corrosion monitoring probes. Location at ESP outlet.




Figure 30. Condition of No. 1 air-cooled, Cor-Ten A corrosion probe after 1168 hours in operation. Surface deposits were bone dry when probe was removed from system.




Figure 31. Condition of No. 2 air-cooled, Cor-Ten A corrosion probe after 832 hours in operation. Surface deposits were bone dry when probe was removed from system.




Figure 32. Condition of No. 3 air-cooled, 2205 SS corrosion probe after 832 hours in operation. Like for the Nos. 1 and 2 air-cooled probes, the surface deposits were bone dry when probe was removed from system.




Figure 33. View of cold-end tip of No. 1 air-cooled, Cor-Ten A corrosion probe (1168 hours in operation) after removal from system and one day exposure to humid air. Note spalling damp deposits.






Figure 34. Overall, windward side view of No. 2 air-cooled, Cor-Ten A corrosion probe (832 hours in operation) after removal from system and one day exposure to humid air. Solids are damp.




Figure 35. Overall view of No.3 air-cooled, 2205 SS corrosion probe (832 hours in operation) after removal from system and one day exposure to humid air. Solids were damp to wet and surface was partially coated with an oily liquid.




Figure 36. Close-up of spalling damp deposits on No. 1 air-cooled probe shown in Figure 33. Note deposit blisters which formed when surface became damp.




Figure 37. Close-up of 2" long scribe line demarcated section which contains center skin thermocouple for No. 3 air-cooled, 2205 SS corrosion probe. Note surface pitting in areas normally covered by deposits.




Figure 38. Overall view of cleaned No. 1 air-cooled, Cor-Ten A corrosion probe (1168 hours in service).




Figure 39. Close-up view of cleaned No. 1 air-cooled, Cor-Ten A probe (1168 hours in service). View shows surface condition of 3rd 2" long, scribe line demarcated section which contained the middle skin thermocouple. Coarse machining marks are clearly visible.




Figure 40. Overall view of cleaned No. 2 air-cooled, Cor-Ten A corrosion probe (832 hours in service).




Figure 41. Cold-end close-up view of No. 2 air-cooled, Cor-Ten A corrosion probe (832 hours in service). Finely machined surface is still smooth with minor discoloration at the tip (coldest area of probe).




Figure 42. Close-up of cold-end tip of cleaned No. 3 air-cooled, 2205 SS corrosion probe (832 hours in service). Areas which were covered by deposits are dull and pitted.




Figure 43. Close-up view of probe shown in Figure 42 between 2" division scribe lines which bracket the middle and top skin thermocouples. Note heavy pitting of surfaces which were covered by deposits.




Figure 44. End-of-test overall view of cleaned No. 1 air-cooled, Cor-Ten A corrosion probe (3832 hours at 172°F and 2474 hours at 192°F).




Figure 45. Close-up of cold-end of probe shown in Figure 44. Note presence of machine marks and lack of corrosion.




Figure 46. End-of-test overall view of cleaned No. 2 air-cooled Cor-Ten A corrosion probe (3496 hours at 201°F and 2378 hours at 174°F).




Figure 47. Close-up of cold-end of probe shown in Figure 46. Note surface roughness at cold-end tip (compare with Figure 45).




Figure 48. Top end view of No. 2 air-cooled, Cor-Ten A corrosion probe with 2664 hours at 201°F in operation between cleanings. View shows clean and deposit covered areas.




Figure 49. Close-up of corrosion probe area noted in Figure 48. Metal loss has occurred at interface between deposit covered area and deposit free areas.






Figure 50. Condition of SA-178A CAPCIS corrosion probe at end of ESP test period (1609 hours in service since last cleaning).




Figure 51. Condition of SA-178A CAPCIS corrosion probe at end of slipstream heat pipe tests (2487 hours in service at 176°F).






Figure 52. Condition of Cor-Ten A CAPCIS corrosion probe at end of slipstream heat pipe tests (2487 hours in service at 174°F).



### SA-178A CAPCIS Probe

Figure 53. Close-up, final condition of cleaned SA-178A CAPCIS corrosion probe sensing elements (2487 hours in service at slipstream heat pipe outlet). Black marks on probe are ink marks used by technician to note which elements had been measured.



## Cor-Ten A CAPCIS Probe

Figure 54. Close-up, final condition of cleaned Cor-Ten A CAPCIS corrosion probe sensing elements (2487 hours in service at slipstream heat pipe outlet). Sensing elements surfaces appear smoother than those of the SA-178A probe.

**APPENDIX**

**Table 1A**  
**Air-Cooled Probe Measurements And Corrosion Rates**  
**Milliken Station -- 7/15/93 to 9/2/93**

Probe		1		09/02/93 (removed)					
Material	Cor-Ten A Operated at 172 F								
Location	Unit 2 Air Htr Outlet Duct								
Date - Time	07/15/93 (Installed)			1188					
Operating Hours	0			70					
Meas Temp, F	70			70					
Axial Score Line>	Ring Score #	Initial Diameter inches		Final Diameter inches		Diameter Change inches		Corrosion Rate mils/yr	
		A	B	A	B	A	B	A	B
Bottom 1		1.8595	1.8501	1.8588	1.8501	0.0007	0.0000	2.6	0.0
2(1)		1.8574	1.8530	1.8572	1.8533	0.0002	-0.0003	0.7	-1.1
3(1)		1.8552	1.8561	1.8549	1.8559	0.0003	0.0002	1.1	0.7
4		1.8539	1.8559	1.8537	1.8557	0.0002	0.0002	0.8	0.8
5		1.8554	1.8522	1.8551	1.8522	0.0003	0.0000	1.1	0.0
6		1.8568	1.8509	1.8565	1.8510	0.0003	-0.0001	1.1	-0.4
7		1.8530	1.8494	1.8529	1.8496	0.0001	-0.0002	0.4	-0.7
Top 8		1.8479	1.8483	1.8476	1.8482	0.0003	0.0001	1.1	0.4
								AVG	1.1 -0.0
								SDEV	0.7 0.7

Probe		2		09/02/93 (removed)											
Material	Cor-Ten A Operated At 202 F														
Location	Unit 2 Air Htr Outlet Duct														
Date	07/29/93 (Installed)			832											
Operating Hours	0			70											
Meas Temp, F	70			70											
Axial Score Line>	Ring Score #	Initial Diameter, Inches				Measured Difference mils		Avg Initial Diameter inches		Final Diameter inches		Diameter Change inches		Corrosion Rate mils/yr	
		A	A(2)	B	B(2)	A	B	A	B	A	B	A	B	A	B
Bottom 1		1.8461	1.8461	1.8496	1.8495	0.0	0.1	1.8461	1.8496	1.8460	1.8492	0.0001	0.0003	0.5	1.8
2(1)		1.8495	1.8496	1.8493	1.8491	-0.1	0.2	1.8496	1.8492	1.8490	1.8491	0.0005	0.0001	2.9	0.5
3(1)		1.8512	1.8512	1.8479	1.8479	0.0	0.0	1.8512	1.8479	1.8509	1.8480	0.0003	-0.0001	1.6	-0.5
4		1.8533	1.8534	1.8487	1.8488	-0.1	-0.1	1.8534	1.8488	1.8529	1.8489	0.0004	-0.0002	2.4	-0.8
5		1.8467	1.8468	1.8441	1.8441	-0.1	0.0	1.8468	1.8441	1.8463	1.8439	0.0005	0.0002	2.4	1.1
6		1.8505	1.8506	1.8507	1.8505	-0.1	0.2	1.8506	1.8506	1.8500	1.8500	0.0006	0.0006	2.9	3.2
7		1.8515	1.8515	1.8535	1.8534	0.0	0.1	1.8515	1.8535	1.8511	1.8527	0.0004	0.0008	2.1	3.9
Top 8		1.8485	1.8485	1.8515	1.8513	0.0	0.2	1.8485	1.8514	1.8485	1.8512	0.0000	0.0002	0.0	1.1
						Measurement Pooled SDEV	0.08							AVG	1.8 1.3
						95 % Confidence	0.16							SDEV	1.1 1.7

Probe		3		09/02/93 (removed)											
Material	2205 SS Operated At 172 F														
Location	Unit 2 Air Htr Outlet Duct														
Date	07/29/93 (Installed)			832											
Operating Hours	0			70											
Meas Temp, F	70			70											
Axial Score Line>	Ring Score #	Initial Diameter, Inches				Measured Difference mils		Avg Initial Diameter inches		Final Diameter inches		Diameter Change inches		Corrosion Rate mils/yr	
		A	A(2)	B	B(2)	A	B	A	B	A	B	A	B	A	B
Bottom 1		1.8970	1.8970	1.8969	1.8970	0.0	-0.1	1.8970	1.8970	1.8969	1.8967	0.0001	0.0002	0.5	1.3
2(1)		1.8972	1.8972	1.8969	1.8969	0.0	0.0	1.8972	1.8969	1.8966	1.8967	0.0006	0.0002	3.2	1.1
3(1)		1.8969	1.8969	1.8971	1.8971	0.0	0.0	1.8969	1.8971	1.8965	1.8970	0.0004	0.0001	2.1	0.5
4		1.8968	1.8968	1.8971	1.8970	0.0	0.1	1.8968	1.8971	NA	1.8969	NA	0.0002	NA	0.8
5		1.8971	1.8972	1.8972	1.8971	-0.1	0.1	1.8972	1.8972	NA	1.8969	NA	0.0002	NA	1.3
6		1.8975	1.8976	1.8975	1.8975	-0.1	0.0	1.8976	1.8975	1.8967	1.8973	0.0008	0.0002	4.5	1.1
7		1.8974	1.8974	1.8973	1.8973	0.0	0.0	1.8974	1.8973	1.8967	1.8972	0.0007	0.0001	3.7	0.5
Top 8		1.8976	1.8974	1.8974	1.8974	0.2	0.0	1.8975	1.8974	1.8973	1.8973	0.0002	0.0001	1.1	0.5
						Measurement Pooled SDEV	0.05							AVG	2.5 0.9
						95 % Confidence	0.11							SDEV	1.5 0.3

(1) Controlled Temperature Located Midway Between These Two Scribe Marks.  
(2) Duplicate Measurements  
NA - Not Applicable Because Wall Scraping Taken From Area For Metal Analysis

## Table 2A

### Air-Cooled Probe Measurements And Corrosion Rates Milliken Station -- 7/15/93 to 1/14/94

**Probe** 1  
**Material** Cor-Ten A Operated at 172 F  
**Location** Unit 2 ESP Outlet Duct  
**Date** 07/15/93 (Installed) 01/14/94 (Removed)  
**Operating Hours** 0 3832  
**Meas Temp, F** 70 73

Axial Score Line > Ring Score #	Initial Diameter inches		Final Diameter inches		Diameter Change inches		Corrosion Rate mils/yr	
	A	B	A	B	A	B	A	B
Bottom 1	1.8595	1.8501	1.8589	1.8499	0.0006	0.0002	0.7	0.2
2(1)	1.8574	1.8530	1.8568	1.8531	0.0006	-0.0001	0.7	-0.1
3(1)	1.8552	1.8561	1.8546	1.8559	0.0006	0.0002	0.7	0.2
4	1.8539	1.8559	1.8536	1.8558	0.0003	0.0001	0.3	0.1
5	1.8554	1.8522	1.8550	1.8522	0.0004	0.0000	0.5	0.0
6	1.8568	1.8509	1.8564	1.8510	0.0004	-0.0001	0.5	-0.1
7	1.8530	1.8494	1.8527	1.8493	0.0003	0.0001	0.3	0.1
Top 8	1.8479	1.8483	1.8471	1.8483	0.0008	0.0000	0.9	0.0
						AVG	0.6	0.1
						SDEV	0.2	0.1

**Probe** 2  
**Material** Cor-Ten A Operated At 202 F  
**Location** Unit 2 ESP Outlet Duct  
**Date** 07/29/93 (Installed) 01/14/94 (Removed)  
**Operating Hours** 0 3496  
**Meas Temp, F** 70 73

Axial Score Line > Ring Score #	Avg Initial Diameter inches		Final Diameter inches		Diameter Change inches		Corrosion Rate mils/yr	
	A(2)	B(2)	A	B	A	B	A	B
Bottom 1	1.8461	1.8496	1.8455	1.8492	0.0006	0.0003	0.8	0.4
2(1)	1.8496	1.8492	1.8483	1.8490	0.0012	0.0002	1.6	0.3
3(1)	1.8512	1.8479	1.8502	1.8477	0.0010	0.0002	1.3	0.3
4	1.8534	1.8488	1.8523	1.8485	0.0010	0.0002	1.3	0.3
5	1.8468	1.8441	1.8458	1.8435	0.0010	0.0006	1.2	0.8
6	1.8506	1.8506	1.8495	1.8490	0.0011	0.0016	1.3	2.0
7	1.8515	1.8535	1.8502	1.8513	0.0013	0.0022	1.6	2.7
Top 8	1.8485	1.8514	1.8475	1.8511	0.0010	0.0003	1.3	0.4
						AVG	1.3	0.9
						SDEV	0.3	0.9

- (1) Controlled Temperature Located Midway Between These Two Scribe Marks.  
(2) Average of Two Measurements

## Table 3A

### Air-Cooled Probe Measurements And Corrosion Rates Milliken Station -- 2/05/93 to 5/22/94


**Probe** 1  
**Material** Cor-Ten A Operated at 192 F  
**Location** Unit 2A Air Htr Outlet Duct  
**Date** 02/05/94 (Installed) 05/22/94 (Removed)  
**Operating Hours** 0 2474  
**Meas Temp, F** 70 73

Axial Score Line> Ring Score #	Initial Diameter inches		Final Diameter inches		Diameter Change inches		Corrosion Rate mils/yr	
	A	B	A	B	A	B	A	B
Bottom 1	1.8589	1.8499	1.8590	1.8495	-0.0001	0.0004	-0.2	0.7
2(1)	1.8568	1.8531	1.8569	1.8526	-0.0001	0.0005	-0.2	0.9
3(1)	1.8546	1.8559	1.8546	1.8555	0.0000	0.0004	0.0	0.7
4	1.8536	1.8558	1.8530	1.8554	0.0006	0.0004	1.1	0.7
5	1.8550	1.8522	1.8545	1.8519	0.0005	0.0003	0.9	0.5
6	1.8564	1.8510	1.8555	1.8504	0.0009	0.0006	1.6	1.1
7	1.8527	1.8493	1.8524	1.8490	0.0003	0.0003	0.5	0.5
Top 8	1.8471	1.8483	1.8468	1.8479	0.0003	0.0004	0.5	0.7
						AVG	0.5	0.7
						SDEV	0.6	0.2

**Probe** 2  
**Material** Cor-Ten A Operated At 172 F  
**Location** Unit 2B Air Htr Outlet Duct  
**Date** 02/05/94 (Installed) 05/22/94 (Removed)  
**Operating Hours** 0 2378  
**Meas Temp, F** 70 73

Axial Score Line> Ring Score #	Initial Diameter inches		Final Diameter inches		Diameter Change inches		Corrosion Rate mils/yr	
	A	B	A	B	A	B	A	B
Bottom 1	1.8455	1.8492	1.8442	1.8480	0.0013	0.0012	2.4	2.2
2(1)	1.8483	1.8490	1.8476	1.8482	0.0007	0.0008	1.3	1.5
3(1)	1.8502	1.8477	1.8497	1.8469	0.0005	0.0008	0.9	1.5
4	1.8523	1.8485	1.8523	1.8479	0.0000	0.0006	0.0	1.1
5	1.8458	1.8435	1.8457	1.8433	0.0001	0.0002	0.2	0.4
6	1.8495	1.8490	1.8494	1.8488	0.0001	0.0002	0.2	0.4
7	1.8502	1.8513	1.8499	1.8513	0.0003	0.0000	0.6	0.0
Top 8	1.8475	1.8511	1.8472	1.8510	0.0003	0.0001	0.6	0.2
						AVG	0.8	0.9
						SDEV	0.8	0.8

(1) Controlled Temperature Located Midway Between These Two Scribe Marks.




Orientation

**Table 4A**  
**CAPCIS Probe Measurements And Corrosion Rates**  
**Milliken Station -- 8/23/93 to 10/27/93**

Probe 1  
 Material SA-178A CS Operated At 230 F  
 Location Unit 2A ESP Outlet Duct  
 Date 08/25/93 (Installed) 10/27/93 (removed)  
 Operating Hours 0 1501  
 Meas Temp, F 70 70

Orientation	Initial Diameter inches		Final Diameter, inches				Measured Difference mils		Avg Final Diameter inches		Diameter Change inches		Corrosion Rate mils/yr			
	A	B	A	A(1)	B	B(1)	A	B	A	B	A	B	A	B		
Bottom 1	2.4825	2.4855	2.4845	2.4845	2.4830	2.4835	0.0	-0.5	2.4845	2.4833	-0.0020	0.0023	-5.8	6.6		
2	2.4845	2.4850	2.4855	2.4850	2.4835	2.4835	0.5	0.0	2.4853	2.4835	-0.0007	0.0015	-2.2	4.4		
3	2.4850	2.4850	2.4845	2.4850	2.4850	2.4850	-0.5	0.0	2.4848	2.4850	0.0002	0.0000	0.7	0.0		
4	2.4835	2.4845	2.4845	2.4835	2.4840	2.4840	1.0	0.0	2.4840	2.4840	-0.0005	0.0005	-1.5	1.5		
5	2.4875	2.4805	2.4860	2.4870	2.4805	2.4805	-1.0	0.0	2.4865	2.4805	0.0010	0.0000	2.9	0.0		
6	2.4830	2.4830	2.4830	2.4825	2.4820	2.4825	0.5	-0.5	2.4828	2.4823	0.0002	0.0008	0.7	2.2		
7	2.4825	2.4840	2.4825	2.4820	2.4835	2.4835	0.5	0.0	2.4823	2.4835	0.0002	0.0005	0.7	1.5		
8	2.4805	2.4860	2.4805	2.4805	2.4855	2.4855	0.0	0.0	2.4805	2.4855	0.0000	0.0005	0.0	1.5		
9	2.4830	2.4835	2.4830	2.4825	2.4825	2.4825	0.5	0.0	2.4828	2.4825	0.0002	0.0010	0.7	2.9		
10	2.4815	2.4865	2.4810	2.4810	2.4860	2.4855	0.0	0.5	2.4810	2.4858	0.0005	0.0007	1.5	2.2		
11	2.4830	2.4850	2.4825	2.4825	2.4845	2.4845	0.0	0.0	2.4825	2.4845	0.0005	0.0005	1.5	1.5		
12	2.4820	2.4850	2.4815	2.4810	2.4845	2.4845	0.5	0.0	2.4813	2.4845	0.0008	0.0005	2.2	1.5		
Top 13	2.4875	2.4820	2.4870	2.4870	2.4820	2.4825	0.0	-0.5	2.4870	2.4823	0.0005	-0.0002	1.5	-0.7		
							Pooled Difference SDEV		0.29		AVG		0.2		1.9	
							95 % Confidence		0.59		SDEV		2.3		1.9	

(1) Duplicate Measurements



Orientation


**Table 5A**  
**CAPCIS Probe Measurements And Corrosion Rates**  
**Milliken Station -- 11/08/93 to 1/14/94**

Probe 1  
 Material SA-178A CS Operated At 168 F  
 Location Unit 2A ESP Outlet Duct  
 Date 11/08/93 (Installed) 01/14/94 (removed)  
 Operating Hours 0 1609  
 Meas Temp, F 70 73

Orientation	Avg Initial Diameter inches		Final Diameter inches		Diameter Change inches		Corrosion Rate mils/yr					
	A(1)	B(1)	A	B	A	B	A	B				
Bottom 1	2.4845	2.4833	2.4845	2.4855	0.0000	-0.0023	0.0	-6.1				
2	2.4853	2.4835	2.4850	2.4845	0.0002	-0.0010	0.7	-2.7				
3	2.4848	2.4850	2.4850	2.4845	-0.0002	0.0005	-0.7	1.4				
4	2.4840	2.4840	2.4835	2.4845	0.0005	-0.0005	1.4	-1.4				
5	2.4865	2.4805	2.4870	2.4795	-0.0005	0.0010	-1.4	2.7				
6	2.4828	2.4823	2.4825	2.4830	0.0003	-0.0008	0.7	-2.0				
7	2.4823	2.4835	2.4825	2.4840	-0.0002	-0.0005	-0.7	-1.4				
8	2.4805	2.4855	2.4805	2.4855	0.0000	0.0000	0.0	0.0				
9	2.4828	2.4825	2.4825	2.4830	0.0003	-0.0005	0.7	-1.4				
10	2.4810	2.4858	2.4810	2.4865	0.0000	-0.0007	0.0	-2.0				
11	2.4825	2.4845	2.4825	2.4845	0.0000	0.0000	0.0	0.0				
12	2.4813	2.4845	2.4815	2.4850	-0.0002	-0.0005	-0.7	-1.4				
Top 13	2.4870	2.4823	2.4865	2.4800	0.0005	0.0023	1.4	6.1				
							AVG		0.1		-0.6	
							SDEV		0.8		2.9	

(1) Average of two Measurements






Orientation

**Table 6A**  
**CAPCIS Probe Measurements And Corrosion Rates**  
**Milliken Station -- 2/07/94 to 5/22/94**

Probe 1  
 Material SA-178A CS Operated At 172 F  
 Location Unit 2A ESP Outlet Duct  
 Date 02/07/94 (Installed)  
 Operating Hours 0  
 Meas Temp, F 70

05/22/94 (removed)  
 2487  
 79

Orientation	Initial Diameter inches		Final Diameter inches		Diameter Change inches		Corrosion Rate mils/yr		
	A	B	A	B	A	B	A	B	
<b>Ring Number</b>									
Bottom 1	2.4845	2.4855	2.4825	2.4830	0.0020	0.0025	3.5	4.4	
2	2.4850	2.4845	2.4825	2.4825	0.0025	0.0020	4.4	3.5	
3	2.4850	2.4845	2.4825	2.4835	0.0025	0.0010	4.4	1.8	
4	2.4835	2.4845	2.4820	2.4830	0.0015	0.0015	2.6	2.6	
5	2.4870	2.4795	2.4845	2.4785	0.0025	0.0010	4.4	1.8	
6	2.4825	2.4830	2.4810	2.4805	0.0015	0.0025	2.6	4.4	
7	2.4825	2.4840	2.4805	2.4820	0.0020	0.0020	3.5	3.5	
8	2.4805	2.4855	2.4785	2.4840	0.0020	0.0015	3.5	2.6	
9	2.4825	2.4830	2.4805	2.4810	0.0020	0.0020	3.5	3.5	
10	2.4810	2.4865	2.4790	2.4850	0.0020	0.0015	3.5	2.6	
11	2.4825	2.4845	2.4810	2.4830	0.0015	0.0015	2.6	2.6	
12	2.4815	2.4850	2.4800	2.4830	0.0015	0.0020	2.6	3.5	
Top 13	2.4865	2.4800	2.4845	2.4795	0.0020	0.0005	3.5	0.9	
							AVG	3.5	2.9
							SDEV	0.7	1.0



Orientation

**Table 7A**  
**CAPCIS Probe Measurements And Corrosion Rates**  
**Milliken Station -- 2/07/94 to 5/22/94**

Probe 2  
 Material Cor-Ten A Operated At 172 F  
 Location Slipstream Heat Pipe Outlet  
 Date 02/07/94 (Installed)  
 Operating Hours 0  
 Meas Temp, F 70

05/22/94 (removed)  
 2487  
 79

Orientation	Initial Diameter inches				Measured Difference mils		Avg Initial Diameter inches		Final Diameter inches		Diameter Change Inches		Corrosion Rate mils/yr		
	A	A(1)	B	B(1)	A	B	A avg	B avg	A	B	A	B	A	B	
<b>Ring Number</b>															
Bottom 1	2.4970	2.4975	2.4975	2.4975	-0.5	0.0	2.4973	2.4975	2.4965	2.4965	0.0008	0.0010	1.3	1.8	
2	2.4970	2.4970	2.4970	2.4970	0.0	0.0	2.4970	2.4970	2.4965	2.4960	0.0005	0.0010	0.9	1.8	
3	2.4970	2.4975	2.4975	2.4975	-0.5	0.0	2.4973	2.4975	2.4965	2.4960	0.0008	0.0015	1.3	2.6	
4	2.4975	2.4975	2.4975	2.4970	0.0	0.5	2.4975	2.4973	2.4965	2.4960	0.0010	0.0013	1.8	2.2	
5	2.4970	2.4970	2.4975	2.4975	0.0	0.0	2.4970	2.4975	2.4960	2.4960	0.0010	0.0015	1.8	2.6	
6	2.4965	2.4965	2.4965	2.4965	0.0	0.0	2.4965	2.4965	2.4950	2.4955	0.0015	0.0010	2.6	1.8	
7	2.4965	2.4970	2.4970	2.4970	-0.5	0.0	2.4968	2.4970	2.4955	2.4960	0.0013	0.0010	2.2	1.8	
8	2.4965	2.4965	2.4975	2.4975	0.0	0.0	2.4965	2.4975	2.4955	2.4965	0.0010	0.0010	1.8	1.8	
9	2.4965	2.4970	2.4975	2.4975	-0.5	0.0	2.4968	2.4975	2.4955	2.4965	0.0013	0.0010	2.2	1.8	
10	2.4970	2.4975	2.4975	2.4970	-0.5	0.5	2.4973	2.4973	2.4965	2.4960	0.0008	0.0013	1.3	2.2	
11	2.4970	2.4975	2.4975	2.4970	-0.5	0.5	2.4973	2.4973	2.4965	2.4960	0.0008	0.0013	1.3	2.2	
12	2.4975	2.4975	2.4975	2.4980	0.0	-0.5	2.4975	2.4978	2.4965	2.4970	0.0010	0.0008	1.8	1.3	
Top 13	2.4975	2.4975	2.4975	2.4975	0.0	0.0	2.4975	2.4975	2.4965	2.4970	0.0010	0.0005	1.8	0.9	
													AVG	1.7	1.9
													SDEV	0.5	0.5
					Pooled Difference SDE		0.22								
					95 % Confidence		0.44								

(1) Duplicate Measurements

**Table 8A**  
**CAPCIS Daily Average Corrosion Rates -- SA-178A**  
**Milliken Station Unit 2 ESP Outlet**

Date	ECN	mils/yr	Probe		Gas		Date	ECN	mils/yr	Probe		Gas	
			Temp, F	Temp, F	Temp, F	Temp, F							
08/26/93	4.13E-09	1.81	237	239	10/01/93	5.03E-09	2.21	227	228				
08/27/93	3.94E-09	1.73	237	245	10/02/93	4.43E-09	1.95	235	238				
08/28/93	9.08E-09	3.99	238	248	10/03/93	5.06E-09	2.22	231	232				
08/29/93	1.08E-08	4.73	237	237	10/04/93	5.04E-09	2.21	232	233				
08/29/93	3.47E-09	1.52	235	243	10/05/93	5.52E-09	2.42	228	229				
08/30/93	4.42E-09	1.94	235	240	10/06/93	4.96E-09	2.18	231	232				
08/31/93	2.73E-09	1.20	235	246	10/07/93	3.86E-09	1.69	234	242				
09/01/93		DATA LOSS			10/08/93	3.19E-09	1.40	234	242				
09/02/93		DATA LOSS			10/09/93	5.07E-09	2.23	232	233				
09/03/93		DATA LOSS			10/10/93	5.73E-09	2.51	225	226				
09/04/93		DATA LOSS			10/11/93	4.82E-09	2.12	224	225				
09/05/93		DATA LOSS			10/12/93	5.29E-09	2.32	230	230				
09/06/93	4.82E-09	2.12	235	235	10/13/93	5.89E-09	2.59	226	226				
09/07/93	5.30E-09	2.33	235	238	10/14/93	4.41E-09	1.93	228	228				
09/08/93	4.78E-09	2.10	234	239	10/15/93	4.91E-09	2.16	231	233				
09/09/93	4.10E-09	1.80	235	241	10/16/93	4.16E-09	1.83	234	238				
09/10/93	4.02E-09	1.77	232	234	10/17/93	3.81E-09	1.67	235	236				
09/11/93	5.53E-09	2.43	232	233	10/18/93	4.99E-09	2.19	231	231				
09/12/93	5.23E-09	2.30	230	232	10/19/93	5.35E-09	2.35	225	225				
09/13/93	5.38E-09	2.36	234	246	10/20/93	6.28E-09	2.76	229	229				
09/14/93	6.08E-09	2.67	233	237	10/21/93	5.72E-09	2.51	231	232				
09/15/93	1.12E-08	4.93	233	253	10/22/93	6.00E-09	2.63	232	232				
09/16/93	7.52E-09	3.30	232	237	10/23/93	5.58E-09	2.45	231	232				
09/17/93	5.60E-09	2.46	234	239	10/24/93	4.56E-09	2.00	234	235				
09/18/93	5.54E-09	2.43	234	239	10/25/93	5.56E-09	2.44	233	233				
09/19/93	5.12E-09	2.25	233	236	10/26/93	5.37E-09	2.36	223	235				
09/20/93	3.76E-09	1.65	226	227	10/27/93	5.31E-09	2.33	198	235				
09/21/93	5.44E-09	2.39	228	229	10/28/93	INSPECTION -- PROBE REMOVED							
09/22/93	5.13E-09	2.25	230	232	10/29/93	INSPECTION -- PROBE REMOVED							
09/23/93	5.47E-09	2.40	233	238	10/30/93	INSPECTION -- PROBE REMOVED							
09/24/93	5.57E-09	2.44	233	238	10/31/93	INSPECTION -- PROBE REMOVED							
09/25/93	4.59E-09	2.02	233	235									
09/26/93	4.44E-09	1.95	234	236									
09/27/93	5.27E-09	2.31	232	232									
09/28/93	5.75E-09	2.52	229	229									
09/29/93	4.80E-09	2.11	226	227									
09/30/93	4.58E-09	2.01	225	225									

**Table 8A (Continued)**  
**CAPCIS Daily Average Corrosion Rates -- SA-178A**  
**Milliken Station Unit 2 ESP Outlet**

Date	ECN	Probe mils/yr	Gas Temp, F	Temp, F	Date	ECN	Probe mils/yr	Gas Temp, F	Temp, F
11/01/93		INSPECTION -- PROBE REMOVED			12/16/93	2.75E-09	1.21	168	222
11/02/93		INSPECTION -- PROBE REMOVED			12/17/93	2.69E-09	1.18	167	230
11/03/93		INSPECTION -- PROBE REMOVED			12/18/93	2.65E-09	1.16	168	229
11/04/93		INSPECTION -- PROBE REMOVED			12/19/93	3.05E-09	1.34	169	229
11/05/93		INSPECTION -- PROBE REMOVED			12/20/93	3.19E-09	1.40	169	224
11/06/93		INSPECTION -- PROBE REMOVED			12/21/93	3.79E-09	1.66	169	223
11/07/93		INSPECTION -- PROBE REMOVED			12/22/93	3.14E-09	1.38	169	222
11/08/93	5.85E-09	2.57	172	228	12/23/93	4.31E-09	1.89	166	217
11/09/93	4.42E-09	1.94	171	226	12/24/93	5.97E-09	2.62	164	211
11/10/93	4.49E-09	1.97	171	226	12/25/93	3.17E-09	1.39	165	215
11/11/93	5.45E-09	2.39	172	227	12/26/93	6.11E-09	2.68	165	208
11/12/93	4.99E-09	2.19	172	226	12/27/93	8.78E-09	3.86	164	207
11/13/93	4.01E-09	1.76	171	223	12/28/93	5.83E-09	2.56	165	212
11/14/93	4.74E-09	2.08	174	232	12/29/93	8.20E-09	3.60	164	211
11/15/93	5.35E-09	2.35	174	232	12/30/93	2.84E-09	1.25	166	214
11/16/93	4.99E-09	2.19	172	226	12/31/93	3.85E-09	1.69	166	220
11/17/93	4.19E-09	1.84	171	224					
11/18/93	4.93E-09	2.16	172	225	01/01/94	2.83E-09	1.24	167	224
11/19/93	3.69E-09	1.62	171	226	01/02/94	2.96E-09	1.30	167	224
11/20/93	3.67E-09	1.61	171	219	01/03/94	5.78E-09	2.54	165	217
11/21/93	4.04E-09	1.77	170	217	01/04/94	5.21E-09	2.29	165	217
11/22/93	5.22E-09	2.29	168	230	01/05/94	4.08E-09	1.79	166	214
11/23/93	5.12E-09	2.25	166	227	01/06/94	8.50E-09	3.73	164	209
11/24/93	3.05E-09	1.34	168	227	01/07/94	7.67E-09	3.37	164	210
11/25/93	4.12E-09	1.81	167	222	01/08/94	5.55E-09	2.44	165	210
11/26/93	3.51E-09	1.54	168	226	01/09/94	5.99E-09	2.63	165	211
11/27/93	5.21E-09	2.29	170	228	01/10/94	7.40E-09	3.25	165	209
11/28/93	4.88E-09	2.14	170	229	01/11/94	3.03E-09	1.33	165	218
11/29/93	2.94E-09	1.29	169	222	01/12/94	2.29E-09	1.01	166	224
11/30/93	3.05E-09	1.34	169	221	01/13/94	1.86E-09	0.82	166	224
					01/14/94	2.82E-09	1.24	166	219
12/01/93	3.42E-09	1.50	168	222					
12/02/93	4.14E-09	1.82	169	225					
12/03/93	5.36E-09	2.35	170	225					
12/04/93	4.85E-09	2.13	170	224					
12/05/93	4.33E-09	1.90	170	222					
12/06/93	4.05E-09	1.78	169	222					
12/07/93	4.25E-09	1.87	169	223					
12/08/93	3.15E-09	1.38	169	222					
12/09/93	3.89E-09	1.71	168	188					
12/10/93	3.34E-09	1.46	169	219					
12/11/93	3.35E-09	1.47	168	216					
12/12/93	3.31E-09	1.45	167	210					
12/13/93	2.91E-09	1.28	167	218					
12/14/93	2.26E-09	0.99	168	226					
12/15/93	3.08E-09	1.35	168	224					

**Table 9A**  
**CAPCIS Daily Average Corrosion Rates -- SA-178A**  
**Milliken Station -- Slipstream Heat Pipe Outlet**

Date	ECN	mils/yr	Probe Temp, F	Gas Temp, F	Date	ECN	mils/yr	Probe Temp, F	Gas Temp, F
02/07/94	7.17E-09	3.15	154	313	04/01/94	5.74E-09	2.52	180	257
02/08/94	4.51E-09	1.98	158	308	04/02/94	6.42E-09	2.82	181	253
02/09/94	5.86E-09	2.57	166	314	04/03/94	5.56E-09	2.44	179	260
02/10/94	1.01E-08	4.45	172	321	04/04/94	3.99E-09	1.75	177	263
02/11/94	1.19E-08	5.23	175	300	04/05/94	5.53E-09	2.43	181	261
02/12/94	1.32E-08	5.81	180	295	04/06/94	5.57E-09	2.45	179	270
02/13/94	1.41E-08	6.20	181	296	04/07/94	5.67E-09	2.49	176	274
02/14/94	1.51E-08	6.61	178	294	04/08/94	3.71E-09	1.63	176	279
02/15/94	1.40E-08	6.14	181	294	04/09/94	6.74E-09	2.96	179	276
02/16/94	1.35E-08	5.94	181	294	04/10/94	3.13E-09	1.37	180	282
02/17/94	1.05E-08	4.60	184	291	04/11/94	3.35E-09	1.47	177	285
02/18/94	8.39E-09	3.68	186	291	04/12/94	SYSTEM SHUTDOWN FOR WASH OUT			
02/19/94	6.95E-09	3.05	189	279	04/13/94	2.41E-09	1.06	184	260
02/20/94	6.42E-09	2.82	187	293	04/14/94	2.87E-09	1.26	172	268
02/21/94	7.20E-09	3.16	182	293	04/15/94	3.04E-09	1.33	174	272
02/22/94	8.25E-09	3.62	177	296	04/15/94	3.04E-09	1.33	174	272
02/23/94	8.51E-09	3.74	174	304	04/16/94	2.44E-09	1.07	172	271
02/24/94	9.78E-09	4.29	174	308	04/17/94	2.97E-09	1.30	170	266
02/25/94	8.42E-09	3.70	172	314	04/18/94	2.28E-09	1.00	172	261
02/26/94	8.60E-09	3.78	171	315	04/19/94	1.92E-09	0.84	174	259
02/27/94	8.78E-09	3.85	171	321	04/20/94	3.20E-09	1.41	170	267
02/28/94	8.78E-09	3.86	176	308	04/21/94	3.80E-09	1.67	168	263
					04/22/94	DATA LOSS			
03/01/94	1.04E-08	4.57	179	303	04/23/94	DATA LOSS			
03/02/94	1.15E-08	5.06	181	291	04/24/94	DATA LOSS			
03/03/94	1.24E-08	5.44	182	296	04/25/94	DATA LOSS			
03/04/94	1.08E-08	4.75	182	292	04/26/94	1.48E-09	0.65	175	266
03/05/94	8.39E-09	3.68	178	291	04/27/94	1.24E-09	0.55	176	265
03/06/94	8.30E-09	3.64	176	299	04/28/94	3.81E-09	1.67	170	264
03/07/94	6.74E-09	2.96	178	298	04/29/94	7.73E-09	3.40	70	65
03/08/94	7.61E-09	3.34	178	305	04/30/94	9.63E-09	4.23	59	54
03/09/94	5.96E-09	2.62	177	307					
03/10/94	6.95E-09	3.05	177	307	05/01/94	1.82E-08	7.99	62	58
03/11/94	4.94E-09	2.17	175	316	05/02/94	3.48E-09	1.53	66	61
03/12/94	5.14E-09	2.26	171	330	05/03/94	2.39E-09	1.05	59	54
03/13/94	4.94E-09	2.17	176	318	05/04/94	2.39E-09	1.05	67	62
03/14/94	5.50E-09	2.41	179	308	05/05/94	1.37E-08	6.01	73	69
03/15/94	4.41E-09	1.94	183	291	05/06/94	3.89E-08	17.08	56	51
03/16/94	3.17E-09	1.39	179	297	05/07/94	3.80E-08	16.68	57	53
03/17/94	3.01E-09	1.32	177	307	05/08/94	9.58E-09	4.21	57	53
03/18/94	3.27E-09	1.44	178	303	05/09/94	4.36E-08	19.14	61	57
03/19/94	3.22E-09	1.41	181	298	05/10/94	6.08E-08	26.68	57	52
03/20/94	3.17E-09	1.39	182	292	05/11/94	DATA LOSS AND SHUTDOWN			
03/21/94	4.57E-09	2.01	165	287	05/12/94	DATA LOSS AND SHUTDOWN			
03/22/94	3.21E-09	1.41	167	282	05/13/94	DATA LOSS AND SHUTDOWN			
03/23/94	2.67E-09	1.17	168	262	05/14/94	2.26E-08	9.93	173	250
03/24/94	3.16E-09	1.39	160	284	05/15/94	1.93E-08	8.47	173	241
03/25/94	3.37E-09	1.48	173	288	05/16/94	1.71E-08	7.51	174	239
03/26/94	5.48E-09	2.41	172	280	05/17/94	2.09E-08	9.18	171	241
03/27/94	8.47E-09	3.72	174	277	05/18/94	1.76E-08	7.73	171	241
03/28/94	7.15E-09	3.14	174	273	05/19/94	DATA LOSS			
03/29/94	7.00E-09	3.07	176	260	05/20/94	3.39E-08	14.88	175	250
03/30/94	5.19E-09	2.28	174	280	05/21/94	2.65E-08	11.63	175	244
03/31/94	3.57E-09	1.57	175	272	05/22/94	1.84E-08	8.08	175	244
						SHUTDOWN			

**Table 10A**  
**CAPCIS Daily Average Corrosion Rates -- Cor-Ten A**  
**Milliken Station -- Slipstream Heat Pipe Outlet**

Date	ECN	mils/yr	Probe		Gas		Date	ECN	mils/yr	Probe		Gas	
			Temp, F	Temp, F	Temp, F	Temp, F							
02/07/94	2.17E-09	0.14	186	320	04/01/94	4.17E-08	2.68	173	253				
02/08/94	2.27E-08	1.46	182	314	04/02/94	4.58E-08	2.95	173	249				
02/09/94	2.12E-08	1.36	174	323	04/03/94	4.48E-08	2.88	173	256				
02/10/94	1.76E-08	1.14	175	333	04/04/94	3.48E-08	2.24	173	257				
02/11/94	2.54E-08	1.64	175	311	04/05/94	4.84E-08	3.12	173	253				
02/12/94	2.21E-08	1.42	173	302	04/06/94	3.36E-08	2.16	174	260				
02/13/94	2.48E-08	1.60	175	303	04/07/94	2.95E-08	1.90	174	264				
02/14/94	2.40E-08	1.55	176	301	04/08/94	3.32E-08	2.14	174	270				
02/15/94	3.65E-08	2.35	174	302	04/09/94	4.85E-08	3.13	174	272				
02/16/94	2.54E-08	1.64	174	302	04/10/94	5.10E-08	3.29	174	274				
02/17/94	2.18E-08	1.41	174	299	04/11/94	3.51E-08	2.26	175	274				
02/18/94	2.51E-08	1.61	174	299	04/12/94	SYSTEM SHUTDOWN FOR WASH OUT							
02/19/94	4.49E-08	2.89	173	287	04/13/94	4.48E-08	2.88	173	245				
02/20/94	5.94E-08	3.82	173	298	04/14/94	5.04E-08	3.24	173	252				
02/21/94	3.14E-08	2.02	173	297	04/15/94	3.93E-08	2.53	173	256				
02/22/94	2.80E-08	1.67	175	303	04/15/94	2.77E-10	0.02	174	256				
02/23/94	2.73E-08	1.76	174	311	04/16/94	3.70E-08	2.38	175	258				
02/24/94	2.34E-08	1.51	174	316	04/17/94	4.27E-08	2.75	174	258				
02/25/94	2.08E-08	1.34	174	321	04/18/94	4.95E-08	3.19	173	258				
02/26/94	2.65E-08	1.71	175	318	04/19/94	4.21E-08	2.71	174	258				
02/27/94	2.48E-08	1.60	176	324	04/20/94	3.79E-08	2.44	174	258				
02/28/94	2.35E-08	1.52	175	310	04/21/94	2.94E-08	1.89	174	258				
03/01/94	3.07E-08	1.98	174	307	04/22/94	DATA LOSS							
03/02/94	2.97E-08	1.92	173	295	04/23/94	DATA LOSS							
03/03/94	2.42E-08	1.56	173	301	04/24/94	DATA LOSS							
03/04/94	2.55E-08	1.64	173	296	04/25/94	DATA LOSS							
03/05/94	3.01E-08	1.94	173	297	04/26/94	2.94E-08	1.89	174	253				
03/06/94	3.04E-08	1.96	173	303	04/27/94	3.37E-08	2.17	174	251				
03/07/94	3.29E-08	2.12	173	302	04/28/94	3.18E-08	2.05	174	250				
03/08/94	2.87E-08	1.85	173	307	04/29/94	7.15E-09	0.46	58	57				
03/09/94	2.05E-08	1.32	174	315	04/30/94	6.25E-09	0.40	49	47				
03/10/94	3.48E-09	0.22	173	314	05/01/94	5.04E-09	0.32	51	50				
03/11/94	4.20E-09	0.27	172	321	05/02/94	8.58E-09	0.55	58	56				
03/12/94	3.48E-09	0.22	173	325	05/03/94	1.03E-08	0.66	52	50				
03/13/94	1.40E-09	0.09	172	297	05/04/94	8.95E-09	0.58	59	57				
03/14/94	1.63E-08	1.05	172	290	05/05/94	2.72E-08	1.75	51	50				
03/15/94	1.95E-08	1.26	172	287	05/06/94	3.35E-09	0.22	46	45				
03/16/94	1.24E-08	0.80	173	296	05/07/94	2.98E-09	0.19	46	45				
03/17/94	2.08E-08	1.34	173	301	05/08/94	1.49E-08	0.96	47	46				
03/18/94	1.60E-08	1.03	174	301	05/09/94	1.54E-09	0.10	50	49				
03/19/94	2.32E-08	1.49	172	293	05/10/94	1.21E-09	0.08	47	45				
03/20/94	2.85E-08	1.83	172	286	05/11/94	DATA LOSS AND SHUTDOWN							
03/21/94	3.09E-08	1.99	182	284	05/12/94	DATA LOSS AND SHUTDOWN							
03/22/94	3.44E-08	2.22	173	276	05/13/94	DATA LOSS AND SHUTDOWN							
03/23/94	4.42E-08	2.85	172	261	05/14/94	6.55E-08	4.22	174	246				
03/24/94	2.96E-08	1.91	173	283	05/15/94	5.10E-08	3.29	174	237				
03/25/94	2.85E-08	1.83	173	288	05/16/94	4.50E-08	2.90	172	237				
03/26/94	3.04E-08	1.96	173	279	05/17/94	3.47E-08	2.23	172	235				
03/27/94	3.19E-08	2.05	172	274	05/18/94	3.47E-08	2.23	172	239				
03/28/94	3.08E-08	1.98	173	272	05/19/94	DATA LOSS							
03/29/94	3.16E-08	2.03	172	259	05/20/94	3.85E-08	2.48	172	244				
03/30/94	3.32E-08	2.14	173	276	05/21/94	3.70E-08	2.38	172	243				
03/31/94	3.92E-08	2.52	173	268	05/22/94	4.83E-08	3.11	172	243				
						SHUTDOWN							