



# National Weather Service

## Storm Data and Unusual Weather Phenomena



November 2005

Location	Date	Time Local/ Standard	Path Length (Miles)	Path Width (Yards)	Number of Persons Killed	Number of Persons Injured	Estimated Damage Property	Estimated Damage Crops	Character of Storm
----------	------	----------------------------	---------------------------	--------------------------	--------------------------------	---------------------------------	---------------------------------	------------------------------	--------------------

### GULF OF MEXICO

GMZ235 Port O'Connor	Pt O'Connor To Aransas Pass 15	1730CST 1806CST			0	0			Marine Tstm Wind (MG45)
Thunderstorm wind gusts between 36 knots and 45 knots recorded at Port O'Connor TCOON site. Peak gust of 45 knots recorded at 1736 CST.									
GMZ230 Corpus Christi	Corpus Christi To Baffin Bay 15	1754CST			0	0			Marine Tstm Wind (MG38)
Measured by White Point TCOON site.									
GMZ230 Port Aransas	Corpus Christi To Baffin Bay 15	1840CST 2050CST			0	0			Marine Tstm Wind (MG45)
Thunderstorm wind gusts between 34 knots and 45 knots recorded at PTAT2 CMAN station. Peak gust of 45 knots recorded at 2050 CST.									
GMZ255 Port Aransas	Matagorda Ship Chnl To Pt Aransas Out 20Nm 15	1840CST 2050CST			0	0			Marine Tstm Wind (EG45)
See above...estimated from nearby PTAT2.									
GMZ250 Port Aransas	Pt Aransas To Baffin Bay Tx Out 20Nm 15	1840CST 2050CST			0	0			Marine Tstm Wind (EG45)
See above...estimated from nearby PTAT2.									
GMZ235 Port Aransas	Pt O'Connor To Aransas Pass 15	1840CST 2050CST			0	0			Marine Tstm Wind (EG45)
See above...estimated from nearby PTAT2.									
GMZ230 Bob Hall Pier	Corpus Christi To Baffin Bay 15	1842CST 1930CST			0	0			Marine Tstm Wind (MG50)
Thunderstorm wind gusts between 36 knots and 50 knots recorded at Bob Hall Pier TCOON site. Peak gust of 50 knots recorded at 1854 CST.									
GMZ230 South Bird Island	Corpus Christi To Baffin Bay 15	1900CST 2047CST			0	0			Marine Tstm Wind (MG44)
Thunderstorm wind gusts between 36 knots and 44 knots recorded at Port O'Connor TCOON site. Peak gust of 44 knots recorded at 1930 CST.									
GMZ275 90 E Port Aransas	Matagorda Ship Chnl To Pt Aransas Tx 20 To 60Nm 15	1955CST			0	0			Marine Tstm Wind (EG41)
Recorded by nearby Buoy 42019.									
GMZ230 Baffin Bay	Corpus Christi To Baffin Bay 15	2000CST			0	0			Marine Tstm Wind (MG43)
Measured by Baffin Bay TCOON site.									
GMZ270 45 ESE Baffin Bay to 45 E Baffin Bay	Pt Aransas To Baffin Bay Tx 20 To 60Nm 15	2047CST			0	0			Marine Tstm Wind (EG47)
Recorded by nearby Buoy 42020.									



# National Weather Service

## Storm Data and Unusual Weather Phenomena



November 2005

Location	Date	Time Local/ Standard	Path Length (Miles)	Path Width (Yards)	Number of Persons		Estimated Damage		Character of Storm
					Killed	Injured	Property	Crops	

**GULF OF MEXICO**

**TEXAS, Mid - South**

**TXZ242**

**Kleberg**

**15 1100CST**  
**17 1200CST**

**0      0**

**Wildfire**

Lightning sparked four fires on the Padre Island National Seashore around 11 am, Nov 15th. Strong southerly winds and dry fuels resulted in extreme fire behavior during the afternoon hours of the 15th. A strong cold front complicated fire fighting efforts during the evening hours, when winds shifted to the north and gusted to between 50 and 60 mph. Light rain with the cold front helped with controlling the fires on the night of the 15th, however one fire remained uncontained and spread quickly south down the island on the 16th, due to the strong northerly winds behind the cold front. Eventually the fires were controlled by the morning of the 17th. A total of 10,259 acres were burned, however no structures were lost and fire officials were able to protect several oil and gas wells

**Nueces County**

**(Ngp)Nas Corpus Chri**

**15 1837CST**

**0      0**

**Thunderstorm Wind (MG51)**

Measured by NGP ASOS. Wind damage also observed on the JFK causeway, where four illumination heads on the illumination poles were damaged, including one completely blown off. Unable to confirm exact wind speed over the causeway, and structural integrity of illumination heads were in question according to engineers