

WO 59 - University of Miami Ramp Boom

Test Number	1	2	3	4	5	6	7	8	9
Oil Type	None	Calsol	None	Calsol	Calsol	Hydrocal 300	Hydrocal 300	Hydrocal 300	Hydrocal 300
Tow Speed	1	1	1.5	2	1.5	2	1.5	1.5	1.5
Summary of Events	Dry Run Towed to 1 knot seemed ok.	1 knot not fast enough for oil to travel down plane	Towed at 1.5 knots to observe what happens with oil present in first collection area. Oil stayed in first area only.	Encountered Oil did travel down ramp but did not accumulate in first and third collection areas. Estimated oil volume collected was 27 - 35 gal. (Oil too viscous to recover with pumps)	Oil appeared to travel down ramp and did accumulate in first and third collection areas. Total of 16 gal was estimated as collected.	Oil appeared to travel down ramp and did accumulate in first and third collection areas. Some oil traveled down ramp. Some entered collection areas through opening between pontoon and side booms.	Oil encountered stacked in front of pontoon. Some oil traveled down ramp. Some entered collection areas through opening between pontoon and side booms	Oil encountered stacked in front of pontoon. Some oil traveled down ramp. Some entered collection area through opening between pontoon and side booms	Pontoon and ramp appeared to conform to wave condition.
Volume Distributed	67.00		49.70	49.30	44.50	55.90	68.80	72.00	
Tank Number						3	4	5	
Recovery Tank Depth (in)						11.50	8.00	4.00	
Gross Volume Recovered						65.32	43.68	22.12	
Lab Analysis - % Oil						74.00	82.00	88.00	
Total Volume of Oil Recovered						48.34	35.82	19.47	
Throughput Efficiency						88.47	52.06	27.04	

Test Oil Data

Test Oils	Specific Gravity	Interfacial Tension (dynes / cm <sup>2</sup> )	Surface Tension (dynes / cm <sup>2</sup> )	Water Temperature (F)	Viscosity @ Water Temperature (cPs)
Calsol 8240	0.83	32.50	36.50	34.80	20400.00
Hydrocal 300	0.88	26-28	29-32	34.80	1000.00