SECOND FIVE-YEAR REVIEW FOR THE HIGHLANDS ACID PIT HIGHLANDS, HARRIS COUNTY, TEXAS

This memorandum documents approval by the U.S. Environmental Protection Agency (EPA) of the Highland Acid Pit Second Five-Year Review Report.

Summary of Five-Year Review Findings

The source control soil remedy called for excavation and off-site disposal of industrial waste sludge and surface capping to control erosion offsite. Remedial Activities were completed in 1987, and Operation and Maintenance activities were conducted from July 1988 to September 1999. Site maintenance includes mowing, gate and fence repairs or replacement, defective or damaged well replacement, and appropriate follow-up response to site theft, vandalism and flooding events.

The site's ground water remedy was a no action ROD. EPA conducted additional ground water sampling from December 1997 to September 1999. The Operational and Functional (O&F) Activities Report documented concentrations of site contaminants above Maximum Contaminant Levels (MCLs) in the middle and deep aquifers. The 1987 ground water Record of Decision identified MCLs as applicable or relevant and appropriate requirements for the middle and deep aquifers, although these contaminants were not present above the MCLs in 1987.

An Operation and Maintenance (O&M) manual for the Highlands Acid Pit site has been written by the State of Texas Natural Resource Conservation Commission (TNRCC) and approved by EPA. TNRCC selected a contractor and issued notice to proceed in February with O&M activities. TNRCC's contractor conducted the field O&M activities in February and March 2002. The TNRCC contractor received the laboratory analytical data results, and the results were entered into the model for tracking the data trend analysis. In addition, the TNRCC and the EPA have selected which wells to plug and abandon, and the EPA's contractor is to begin final O&F Activities in September 2002.

Actions Needed

The presence of site contaminants above the MCLs in the middle and deep aquifers must be addressed. In addition, the O&F Work will consist of plugging and abandoning five or six on-site monitoring wells: MA-04, UA-13, UA-03, MA-08 and DA-08 have been identified to plug and abandon. The protective bollards and cluster fencing from the plugged and abandoned wells will be reused in the replacement wells. Two new down gradient wells are to be installed with well pads, relocated protective bollards and fencing. Well DA-01 is to have a bailer plug removed and well integrity confirmed or it shall be replaced.

Determinations

The remedy at the Highlands Acid Pit Superfund site currently protects human health and the environment because: 1) the source control remedy has been implemented and is functioning as intended, 2) the contamination found in the middle and deep aquifers has not affected nearby area water supply wells, and 3) based on the comparison of field data to sediment screening levels, EPA concludes that site related contaminants are not affecting sediments near the site. However, in order for the remedy to be protective in the long-term, the following actions need to be taken: 1) continue to monitor the shallow, middle, and deep aquifers to assess changes in the concentration of site-related



contaminants; 2) model the movement of site-related contaminants in the middle and deep aquifers to determine the direction of plume movement and potential for exposure from future ground water use; and 3) address whether MCLs are applicable or relevant and appropriate requirements for the middle and deep aquifers, and if they are, whether a waiver is appropriate.

Myron O. Knudson, P.E.

Director, Superfund Division U.S. Environmental Protection Agency Region 6

<u>9-27-02</u> Date

CONCURRENCES:

SECOND FIVE-YEAR REVIEW FOR

HIGHLANDS ACID PIT

EPA ID# TX980514996

By:

Ernest R. Franke, PE, RPLS, **Remedial Project Manager**

NA By:

Gustavo T. Chavarria, Chief AR/OK/TX Project Management Section

By: liam K. Honker. Chief

AR/OK/TX Branch

By: Con

Site Attorney

By:

Mark Peycke, Chief Superfund Branch, Office of Regional Counsel

Date: 926 02

Date: 09/26/02

Pam Phillips Superfund Deputy Division Director Date:

Date: 1/30/01 / 2/15/02 her 9/24/102

Date: ______8/2/0/

Anne Foster

By:

SECOND FIVE-YEAR REVIEW REPORT FOR THE HIGHLANDS ACID PIT HIGHLANDS, HARRIS COUNTY, TEXAS

SEPTEMBER 2002

U.S. ENVIRONMENTAL PROTECTION AGENCY 1445 Ross Avenue Dallas, TX 75202-2733

CONTENTS

Section

Page [

ACRO	ONYMS	S AND ABBREVIATIONS iv		
EXEC	EXECUTIVE SUMMARY ES-1			
1.0	INTR	ODUCTION 1		
2.0	SITE	CHRONOLOGY 1		
3.0	BACK	GROUND 1		
4.0	REMEDIAL ACTIONS			
	4.1 4.2 4.3	REMEDIES SELECTED4REMEDY IMPLEMENTATION6SYSTEM OPERATIONS6		
5.0	FIVE-	YEAR REVIEW PROCESS 7		
6.0	FIVE-	YEAR REVIEW FINDINGS 8		
	6.1 6.2 6.3 6.4	SURVEYS8SITE INSPECTION9ARAR REVIEW10DATA REVIEW10		
7.0	ASSE	SSMENT		
8.0	DEFIC	CIENCIES		
9.0	RECOMMENDATIONS AND FOLLOW-UP ACTIONS			
10.0	PROTECTIVENESS STATEMENTS			
11.0	NEXT REVIEW			
12.0	OTHER COMMENTS			

Appendices

A DOCUMENTS REVIEWED

- B SITE VISIT REPORT
- C SURVEYS

TABLES

	Table	<u>Page</u>
1	CHRONOLOGY OF SITE EVENTS	2
2	IDENTIFIED DEFICIENCIES	12
3	RECOMMENDATIONS AND FOLLOW-UP ACTIONS	14
	FICIDES	

FIGURES

Figure			'age
1	SITE LOCATION MAP	•••••••••••••••••••••••••	5

ACRONYMS AND ABBREVIATIONS

ARAR	Applicable or relevant and appropriate requirement
ASTDR	Agency for Toxic Substances and Disease Registry
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
CFR	Code of Federal Regulations
COC	Contaminant of Concern
EPA	Environmental Protection Agency
HAP	Highlands Acid Pit
ШW	Investigation-derived waste
GPM	Gallons per minute
HASP	Health and Safety Plan
IRM	Initial Remedial Measure
MCL	Maximum contaminant level
μg/kg	Micrograms per kilogram (parts per billion or ppb)
μg/L	Micrograms per liter (ppb)
mg/kg	Milligrams per kilogram (parts per million or ppm)
mg/L	Milligrams per liter (ppm)
MSL	Mean sea level
NCP	National Oil and Hazardous Substances Pollution Contingency Plan
NPL	National Priorities List
O&FAR	Operational and Functional Activities Report
O&M	Operations and maintenance
OU	Operable unit
RA	Remedial Action
RAL	Risk action levels
RCRA	Resource Conservation and Recovery Act
RD	Remedial Design
RI/FS	Remedial investigation/feasibility study
ROD	Record Of Decision
SARA	Superfund Amendments and Reauthorization Act
SOW	Statement of work
TAC	Texas Administrative Code
TDWR	Texas Department of Water Resources
Tetra Tech	Tetra Tech EM Inc.
TNRCC	Texas Natural Resource Conservation Commission
TRRP	Texas Risk Reduction Program
VOC	Volatile organic compound
Weston	Roy F. Weston

EXECUTIVE SUMMARY

The U.S. Environmental Protection Agency (EPA), Region 6, conducted a Second Five-Year Review of the Remedial Actions implemented at the Highlands Acid Pit Superfund Site (HAP site). This report documents the methods, findings, and conclusions of the review conducted from March 2001 to September 2002. The purpose of this review is to determine whether the remedy chosen for the site is protective of human health and the environment.

During the early 1950s, the HAP site was used for the disposal of an unknown quantity of industrial waste sludge, believed to be spent sulfuric acid from oil/gas refining processes. The site is a 6-acre peninsula within the San Jacinto River 10-year flood plain. The HAP site is located in Harris County, 16 miles east of Houston, Texas, and 1.4 miles west of Highlands, Texas, at the end of Clear Lake Road and adjacent to the east side of the San Jacinto River. The site is bordered by two adjacent active oil and gas wells and a petroleum distribution center north of the site, flooded sand pits to the east, Clear Lake to the south, and Grennel Slough to the west.

In September 1983, the HAP site was put on the National Priorities List. The source control Record of Decision (ROD) was signed in June 1984, with the remedy being excavation and off-site disposal. The no-action ground water ROD was signed in June 1987. The source control Remedial Action contract was awarded to Chemical Waste Management in September 1986, and the Post-Closure Report, documenting that the Remedial Action had been completed, was finalized in December 1987.

Operation and maintenance (O&M) have been performed at the HAP site from July 1988 to July 1996 by the Texas Natural Resource Conservation Commission (TNRCC). In June 1993, the TNRCC assumed all responsibility for continuing the 30 years of O&M at the HAP site.

Ground water sampling of private wells in August 1994 determined that the water quality was excellent (compared with drinking water standards). The Operational and Functional (O&F) Activities Report determined that ground water flow is to the west, away from the private wells that were sampled in 1994.

ES-1

The first Five-Year Review was completed in June 1996. In 1997, EPA and the TNRCC felt it necessary to perform O&F activities to determine if the ground water was (1) traveling in the same direction it was when the ROD was written and (2) if migrating laterally or downward. Since all of the monitoring wells were within the contaminant plume, EPA and the TNRCC concluded that additional monitoring wells needed to be installed outside of the plume and that an aquifer pump test was necessary to determine the possibility of vertical migration between distinct water-bearing units.

EPA conducted the O&F activities, a tidal study and aquifer testing from December 1997 to September 1999. During these activities, monitoring wells were added, and the site trends were addressed. Also, since the site fencing had been damaged due to flooding, it was necessary to repair the site and cluster fencing during O&F activities. The site was made more functional by landscaping the contours to minimize flood damage in the future. Finally, EPA evaluated the analytical data and provided recommendations on delisting the site. The O&F Activities Report, dated November 2000, summarized the site activities and performance evaluation of the selected remedy and ground water monitoring system. The report documented eight sampling events and addressed HAP exposure pathways and direction of ground water flow. The report documented that site contaminants had migrated into the middle and deep aquifer in concentrations above the MCLs.

An Operation and Maintenance Manual for the Highlands Acid Pit site has been written by TNRCC and approved by EPA. The TNRCC selected a contractor and issued notice to proceed in February with the O&M activities. TNRCC's contractor conducted the field O&M activities in February and March 2002. The TNRCC contractor received the laboratory analytical data results, and the results were entered into the model for tracking the data trend analysis. In addition, the TNRCC and EPA have selected the wells to plug and abandon, and the EPA's contractor is to begin final O&F Activities in September 2002.

Documents reviewed for this second Five-Year Review included the (1) 1984 source control operable unit Record of Decision (ROD), (2) 1987 ground water operable unit ROD, (3) 1996 Five-Year Review, (4) 1996 annual monitoring report, and (5) November 2000 O&F Activities Report. This Second Five-Year Review also included a site inspection and interviews with residents and state personnel. The monitoring wells appeared to be in good shape during the site inspection; however, the vegetative cover is overgrown and site mowing will be needed in the preventative site maintenance program. An oil and gas facility (not associated with the HAP site) is adjacent to and north of the HAP site, and two production wells have been completed and are operational at this time.

Comments from the site surveys included: (1) a local business owner's overall impression that the project is acceptable and that site operations have cleaned up the surrounding community; and, (2) TNRCC stated that surface conditions are reflective of the source control ROD but that the ground water conditions in the middle and deep ground water zones require monitoring, analysis, and Five-Year Reviews. The need for O&M for ground water monitoring to begin as soon as possible was discussed with Mr. Jim Feeley, Project Manager for TNRCC.

Recommendations and follow-up actions include: (1) monitoring of surface water, sediment, and ground water, (2) off-site ground water monitoring to confirm the effectiveness of the remedy, (3) monitoring wells MA-08 and DA-08 should be plugged and abandoned due to questions related to well integrity, (4) Well DA-01 should be unplugged or replaced with a new well, (5) vegetative and grass mowing, and repairs to the gate and fence should be included as a part of regular site maintenance, and (6) modeling the movement of site-related contaminants in the middle and deep aquifers to determine the direction of plume movement and potential for exposure from future ground water use.

Ecological risk assessment guidance was not available at the time the Remedial Investigation was conducted. However, EPA risk assessors have compared analytical data from the sediment samples collected in the area of the site to Region 6 contaminant screening levels for fresh water sediments established in June 2002. These samples were collected from December 1997 until September 1998. Screening levels are not regulatory standards or cleanup levels, but guidelines to be used to determine if further study of the sediments is warranted.

The results of this comparison indicate that site-related contaminants are not affecting sediments in the area of the site and that the concentrations of these contaminants have decreased since December 1997. In one sample, collected in September 1998, the concentration of lead was slightly above the screening level (42.6 mg/kg vs. 35 mg/kg). In four previous and four subsequent samples at the same location,

ES-3

lead concentrations were found to be below the sediment screening level. Also, the concentration of arsenic in a sample collected in April 1999 was above the screening level (0.82 mg/kg vs 0.6 mg/kg). In five previous and two subsequent samples, arsenic concentrations were below the sediment screening level. Based on the comparison of field data to sediment screening levels, EPA concludes that site related contaminants are not affecting sediments near the site.

The remedy at the Highlands Acid Pit Superfund site currently protects human health and the environment because: 1) the source control remedy has been implemented and is functioning as intended, 2) the contamination found in the middle and deep aquifers has not affected nearby area water supply wells, and 3) based on the comparison of field data to sediment screening levels, EPA concludes that site related contaminants are not affecting sediments near the site. However, in order for the remedy to be protective in the long-term, the following actions need to be taken: 1) continue to monitor the shallow, middle, and deep aquifers to assess changes in the concentration of site-related contaminants , 2) model the movement of site-related contaminants in the middle and deep aquifers to determine the direction of plume movement and potential for exposure from future ground water use, and 3) address whether MCLs are applicable or relevant and appropriate requirements for the middle and deep aquifers, and if they are, whether a waiver is appropriate.

ES-4

Five-Y'ear Re	view Summary Form			
SITE IDENTIFICATION				
Site Name (from WasteLAN): Highlands A	cid Pit Superfund Site			
EPA ID (from WasteLAN): TX980514996				
Region: 6 State: TX City/County: Highlands, Texas/Harris County				
SIT	TE STATUS			
NPL Status: Final 🗆 Deleted 🖾 Other (sp	ecify) Second Five-Year Review			
Remediation Status (choose all that apply):	□ Under Construction ⊠ Operating □ Complete			
Multiple OUs?* 🛛 YES 🗆 NO	Construction Completion Date: July 1987			
Has site been put into reuse? 🗆 YES 🛛 N	0			
REVI	EW STATUS			
Reviewing Agency: 🛛 EPA 🗆 State 🗆 T	ribe Other Federal Agency			
Author Name: Tetra Tech EM Inc.				
Author Title: N/A Author Affiliation: Environmental Contractor				
Review Period:** <u>6/13/96</u> to <u>8/2002</u>				
Date(s) of Site Inspection: May 8, 2001				
Type of review:***Ø Statutory □ Policy □ Post-SARA □ Pre-SARA □ NPL-Removal only □ Non-NPL Remedial Action Site □ NPL State/Tribe-lead □ Regional Discretion				
Review Number: \Box 1 (first) \boxtimes 2 (second) \Box 3 (third) \Box Other (specify)				
Triggering Action:**** Actual RA Onsite Construction at OU1 Construction Completion Other (specify)	 Actual RA Start at OU # Previous Five-Year Review Report 			
Triggering Action Date (from WasteLAN)	: <u>6/13/96</u>			
Due Date (Five Years After Triggering Act	ion Date): <u>6/13/01</u>			

Five-Year Review Summary Form

Deficiencies:

- The ground cover at the Highlands A.cid Pit site is overgrown and should be cut for preventative site maintenance.
- Monitoring wells MA-08 and DA-08 should be plugged and abandoned because of questions related to well integrity.

Recommendations and Follow-up Actions:

The presence of site contaminants above the MCLs in the middle and deep aquifers must be addressed. Monitoring wells MA-08 and DA-08 should be plugged and abandoned due to questions related to their integrity. In addition, the well DA-01 is to be unplugged, or P&A and replaced with a new well. The well pad at DA-07 should be demolished and the protective bollards and cluster fencing and gate removed and reused.

Protectiveness Statement(s):

The remedy at the Highlands Acid Pits Superfund site currently protects human health and the environment because: 1) the source control remedy has been implemented and is functioning as intended, 2) the contamination found in the middle and deep aquifers has not affected nearby area water supply wells, and 3) based on the comparison of field data to sediment screening levels, EPA concludes that site related contaminants are not affecting sediments near the site. However, in order for the remedy to be protective in the long-term, the following actions need to be taken: 1) continue to monitor the shallow, middle, and deep aquifers to assess changes in the concentration of site-related contaminants, 2) model the movement of site-related contaminants in the middle and deep aquifers to determine the direction of plume movement and potential for exposure from future ground water use, and 3) address whether MCLs are applicable or relevant and appropriate requirements for the middle and deep aquifers, and if they are, whether a waiver is appropriate. **Other Comments:**

None.

1.0 INTRODUCTION

The Five-Year Reviews determine whether the remedy at a site is protective of human health and the environment. The second Five-Year Review for the Highlands Acid Pit (HAP) Superfund site, is required by the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) because the Remedial Actions at the site do not allow for unlimited use and unrestricted exposure. A Record of Decision (ROD) for the source control operable unit was signed in June 1984, and a ROD for the ground water operable unit was signed in June 1987.

2.0 SITE CHRONOLOGY

Table 1 lists the chronology of events for the HAP site.

3.0 BACKGROUND

During the early 1950s, the HAP site was used for disposal of an unknown quantity of industrial waste sludge, believed to be spent sulfuric acid from a refinery process. The site is a 6-acre peninsula within the 10-year flood plain of the San Jacinto River. The HAP site is located in Harris County, 16 miles east of Houston, Texas, and 1.4 miles west of Highlands, Texas, at the end of Clear Lake Road and adjacent to the east side of the San Jacinto River. The site is bordered by a two adjacent active oil and gas wells and a petroleum distribution center north of the site, flooded sand pits to the east, Clear Lake to the south, and Grennel Slough to the west.

TABLE 1

CHRONOLOGY OF SITE EVENTS

Date	Event
May 1978	TDWR— now the TNRCC—received a telephone complaint concerning the site.
September 1978	Sludge, sediment, and storm water samples were analyzed, revealing low pH, low concentrations of metals, high chemical oxygen demand, and high total organic carbon.
October 1981	Ground water samples were analyzed, revealing VOCs and heavy metals.
June 1982	HAP was proposed for the NPL with a Hazard Ranking System score of 37.77.
September 1982	EPA and TDWR (TNRCC) entered into a Cooperative Agreement for a state-led RI/FS. The RI/FS contract was awarded to EH&A, with Weston as the primary subcontractor.
September 1983	HAP was included on the NPL.
December 1983	EH&A submitted the <i>Site Investigation Report</i> , which indicated extensive contamination by heavy metals and VOCs across much of the site.
December 1983	EH&A completed the RI/FS.
June 1984	The ROD for the Source Control Operable Unit was signed, selecting excavation and off-site disposal as the remedy.
January 1985	EH&A and Weston completed the Remedial Action Design and Site Safety Plan.
December 1985	The Source Control RD was approved.
September 1986	The Source Control RA was awarded to Chemical Waste Management.
June 1987	The ROD for the Ground Water Operable Unit was signed, selecting no action as the remedy.
November 1987	EH&A submitted the Final Report Volumes I and II - Source Control Remedial Construction.

TABLE 1 (Continued)

CHRONOLOGY OF SITE EVENTS

Date	Event
December 1987	EH&A completed the Final Report of the Ground Water Sampling Event for Post Closure.
July 1988 to July 1996	O&M began at the HAP site.
May 1989	EH&A submitted the Post Closure Operation and Maintenance Plan, and subsequent sampling events and reports followed.
June 1993	TNRCC assumed all responsibility for continuing the 30 years of O&M at the HAP site.
August 1994	TNRCC collected ground water samples from the private well for the Baytown Boat Club and concluded that the water quality was excellent based on analyzed constituents.
May 1996	EPA and TNRCC agreed on a revised well-development plan, which proposed 10 additional monitoring wells with a revised monitoring strategy, and an expansion of the sampling and analysis program.
June 1996	EPA completed the first Five-Year Review for the HAP site.
December 1997 to September 1999	Tetra Tech conducted Operational and Functional activities at the HAP site.

Notes:

EH&A	Epsey Houston & Associates, Inc.
EPA	U.S. Environmental Protection Agency
HAP	Highlands Acid Pit
NPL	National Priorities List
O&M	Operations and maintenance
RA	Remedial action
RD	Remedial design
RI/FS	Remedial investigation and feasibility study
ROD	Record of decision
TDWR	Texas Division of Water Resources
TNRCC	Texas National Resources Commission
VOC	Volatile organic compound

The site lies within the Jessie White Survey A-83 of Harris County, Texas, within the Coast Prairie and East Texas Timberlands (Figure 1). The HAP site also lies within Federal/State Census Tract Number 25901 and is within the planning jurisdiction of the Baytown, Texas Planning Commission. The census tract encompasses most of the City of Highlands and adjacent unincorporated areas near the site. There are no known zoning or land use restriction ordinances in effect or planned within the jurisdiction of the Baytown Planning Commission. Little development is foreseen in the site area due to its location within the 100-year flood plain of the San Jacinto River. The site peninsula itself lies within the 10-year flood plain of the San Jacinto River. The flow of the San Jacinto River is controlled by the dam at Lake Houston, local meteorological events, and tides (Tetra Tech 2000).

4.0 REMEDIAL ACTIONS

The following sections discuss the remedies selected, remedy implementation, and system operations.

4.1 REMEDY SELECTED

The selected remedy for source control was excavation and off-site disposal. The selected remedy included:

- Excavation of waste material to an approximate depth of 8 feet
- Transportation of waste to a permitted Class I hazardous waste disposal facility
- Backfilling the excavated area with clean fill
- Constructing a temporary site perimeter fence with warning signs
- Installing a ground water monitoring system
- Performing ground water monitoring and site maintenance for a 30-year period

EPA and the Texas Natural Resource Conservation Commission (TNRCC) agreed that the selected remedy met the criteria outlined in Section 300.430(f) of the National Contingency Plan (NCP). In addition, the Centers for Disease Control reviewed and concurred with the recommended remedy since it would adequately alleviate any public health threat that might result from the site (EPA 1984). The Source Control ROD was signed on June 25, 1984, and the Remedial Design (RD) was completed in December 1985.

The ground water ROD was signed on June 26, 1987. The selected remedy was no action, with a recommendation for monitoring the surface environment (surface water and sediments), and ground water. However, the 1987 ROD selected no action because sampling prior to the ROD did not detect contaminants of concern in the middle or deep aquifer. The applicable or relevant and appropriate requirements identified for the middle and deep aquifers were MCLs.

4.2 REMEDY IMPLEMENTATION

Construction activities for the source control remedy began in February 1987 and were completed by July 1987. These activities included excavating the contaminated soil, conveying the contaminated soil to the Chemical Waste Management disposal site in Carlyss, Louisiana, and backfilling the excavation with clean soil. Although the ROD for the ground water remedy called for no action, monitoring wells were installed for 30 years of monitoring at the HAP site pursuant to the recommendation in the ROD for monitoring.

4.3 SYSTEM OPERATIONS

EH&A and Woodward Clyde conducted operations and maintenance (O&M) monitoring activities from July 21, 1988, to July 31, 1996.

In 1997, EPA and the TNRCC felt it necessary to perform O&F activities to determine if the ground water was (1) traveling in the same direction contemplated in the ROD, and (2) not

migrating laterally or downward. Since all of the monitoring wells were within the contaminant plume, EPA and the TNRCC concluded that additional monitoring wells needed to be installed outside of the plume and that an aquifer pump test was necessary to determine the possibility of vertical migration between distinct water-bearing units.

EPA conducted the O&F activities, a tidal study and aquifer testing from December 1997 to September 1999. During these activities, monitoring wells were added, and the site trends were addressed. Also, since the site fencing had been damaged due to flooding, it was necessary to repair the site and cluster fencing during O&F activities. The site was made more functional by landscaping the contours to minimize flood darnage in the future. Finally, EPA evaluated the analytical data and provided recommendations on delisting the site. The O&F Activities Report, dated November 2000, summarized the site activities and performance evaluation of the selected remedy and ground water monitoring system. The report documented eight sampling events and addressed HAP exposure pathways and direction of ground water flow. The report documented that site contaminants had migrated to the midclle and deep aquifers in concentrations above MCLs.

5.0 FIVE-YEAR REVIEW PROCESS

The Five-Year Review for the HAP site consisted of the following activities: (1) a review of relevant documents, (2) a review for changes in risk assessment methods or standards bearing on the protectiveness of the remedy, (3) surveys of individuals with technical knowledge of the site, (4) surveys of individuals living near the site, and (5) a site inspection.

6.0 FIVE-YEAR REVIEW FINDINGS

The following sections present the findings of this second Five-Year Review.

6.1 SURVEYS

Interview questionnaires were completed by (1) Mr. Bubba Crawford, owner of the Baytown Boat Club, (2) Mr. Jim Feeley, the TNRCC project manager, and (3) Mr. Jared Fuqua, a project contractor and consultant. The completed questionnaires are provided in Appendix B of the inspection report, which is attached to this Five-Year Review Report.

Mr. Crawford's overall impression is that the project is acceptable, and that site operations have cleaned up the surrounding community. Mr. Crawford also stated that he feels well informed about the site's activities and progress.

Mr. Feeley stated that surface conditions are reflective of the source control ROD, but that the ground water conditions require further monitoring followed-up by Five-Year Reviews, specifically the middle and deep ground water zones. Mr. Feeley also stated that TNRCC has actively participated in the O&F Activities Report, and is resuming the role of lead agency for post closure operation and maintenance. Mr. Feeley did not know of any complaints or violations within the last five years and feels well informed about site activities and progress. Mr. Feeley stated that the only potentially relevant change in state laws or regulations is the Texas Risk Reduction Program (TRRP); however, he understood that the RODs would have to be reopened for TRRP to be applicable. Mr. Feeley also commented that (1) there appears to be a cross-contamination problem with one or two of the nested wells completed in the middle and deep zones, and TNRCC supports EPA's desire to abandom these wells; (2) TNRCC believes that further monitoring is required to determine the conditions in the middle and lower zones; and

(3) TNRCC is revising the O&M plan and will then retain a contractor to begin monitoring activities.

Mr. Fuqua stated that Tetra Tech performed activities at the HAP site including (1) installing additional ground water monitoring wells; (2) performing eight quarters of monitoring; and (3) completing a tidal study and aquifer testing, which can be found in the O&F Activities Report (Tetra Tech, dated November 2000). The O&F project was successful in determining ground water flow direction, collecting monitoring data for analysis, evaluation, and remedy assessment. Mr. Fuqua does not know of any complaints regarding the site and feels well informed about the site's activities and progress. Mr. Fuqua recommended that O&M activities be initiated.

6.2 SITE INSPECTION

The site inspection was conducted on May 8, 2001. Attendees were (1) Mr. Ernest Franke of EPA, (2) Mr. Jim Feeley of TNRCC, and (3) Mr. Jared Fuqua of Tetra Tech. The site inspection report is found in Appendix B of this document. An oil and gas plant (that is not associated with the HAP site) is currently built adjacent to the HAP site, and two production wells have been completed at this time and are operational.

The exterior and cluster fences, gates, roads, and locks were in satisfactory condition. Each well enclosure was inspected and photographed. One plugged and abandoned well, DA-07, needs the wellpad demolishing, protective bollards and cluster fencing and gate removed, and reused. It was noted that there was no sign displaying the site name and identifying it as a Superfund site. TNRCC agreed to have a sign posted with the appropriate site and contact information. The vegetative cover is overgrown and should be mowed to ensure adequate visibility, well access, and general safety. Proper site maintenance will help ensure the longevity of the wells and fencing, and will increase the level of prevention or detection of theft, vandalism, or sabotage.

6.3 ARAR REVIEW

A review of the federal standards, requirements, criteria, or limitations, which were determined to be applicable or relevant and appropriate requirements (ARARs), indicated that the HAP site activities are in compliance with ARARs identified in the ROD, with the exception of the MCLs identified as ARARs for the middle and deep aquifers. There have been no changes in ARARs that bear on the protectiveness of the remedy.

6.4 DATA REVIEW

.-

Data reviewed in the O&F Activities Report revealed: (1) net ground water flow is to the west away from the private wells; (2) benzene bio-degradation is limited by the low pH environment; (3) benzene concentrations above maximum contaminant levels (MCL) have been detected in the middle aquifer and deep aquifer;(4) arsenic was detected in the middle aquifer wells above MCLs;(5) some samples showed lead, chromium, cadmium and selenium above MCLs in the middle aquifer and arsenic and lead above MCLs in the deep aquifer; (6) benzene in surface water is continuing to be detected; and (7) contaminants of concern (COC), benzene, and arsenic have been detected in HAP sediments (Tetra Tech, O&FA Report, November 2000).

Although benzene continues to be detected in ground water, the ground water flow both in the original ROD and in the findings of the O&F Activities Report is to the west, and thus any apparent potential for migration is away from any sources of drinking water (such as, water wells). Tetra Tech evaluated biodegradation in the aquifer system to assess whether natural attenuation was occurring. The results of the evaluation concluded that biodegradation did not have a significant impact on the attenuation of the site contaminants.

-

Ecological risk assessment guidance was not available at the time the Remedial Investigation was conducted. However, EPA risk assessors compared analytical data from the sediment samples collected in the area of the site to Region 6 contaminant screening levels for fresh water sediments

established in June 2002. These samples were collected from December 1997 until September 1998. Screening levels are not regulatory standards or cleanup levels, but guidelines to be used to determine if further study of the sediments is warranted.

The results of this comparison indicate that site-related contaminants are not affecting sediments in the area of the site and that the concentrations of these contaminants have decreased since December 1997. In one sample, collected in September 1998, the concentration of lead was slightly above the screening level (42.6 mg/kg vs. 35 mg/kg). In four previous and four subsequent samples at the same location, lead concentrations were found to be below the sediment screening level. Also, the concentration of arsenic in a sample collected in April 1999 was above the screening level (0.82 mg/kg vs 0.6 mg/kg). In five previous and two subsequent samples, arsenic concentrations were below the sediment screening level.

Based on the comparison of field data to sediment screening levels, EPA concludes that site related contaminants are not affecting sediments near the site.

7.0 ASSESSMENT

The following conclusions support the conclusion of this second Five-Year Review.

Question A: Is the remedy functioning as intended by the decision documents?

- System Operations/O&M—O&M ground water monitoring activities should resume as soon as possible.
- Cost of System Operations/O&M—O&M costs were not available for review.
- **Opportunities for Optimization**—O&M ground water monitoring activities should resume as soon as possible.
- Early Indicators of Potential Remedy Failure—O&M ground water monitoring activities should resume for evaluation of potential remedy failure.

Question B: Are the assumptions used at the time of remedy selection still valid?

- Changes in Standards and To Be Considered—No changes that bear on the protectiveness of the remedy.
- Changes in Exposure Pathways—No changes that bear on the protectiveness of the remedy.
- Changes in Toxicity and Other Contaminant Characteristics—No changes that bear on the protectiveness of the remedy.
- Changes in Risk Assessment Methodologies—No changes that bear on the protectiveness of the remedy.

Question C: Has any other information come to light that could call into question the protectiveness of the remedy?

No information other than the information documented above has been identified to question the protectiveness of the remedy.

8.0 **DEFICIENCIES**

Deficiencies that were discovered during the Five-Year Review are noted in Table 2.

TABLE 2

IDENTIFIED DEFICIENCIES

Deficiencies	Currently Affects Protectiveness (Y/N)		
Monitoring Wells Require Maintenance			
TNRCC expressed concern that there may be cross contamination between the middle and deep zones. The integrity of monitoring wells MA-08 and DA-08 was questioned (Tetra Tech 2000), and plugging and abandoning of MA-08 and DA-08 is recommended.	Unknown		
Security Measures Required			
None	N		
Surface Condition	15		
The ground cover is overgrown and should be cut for preventative maintenance.	N		
Surface Water			
None	N		
Ground Water			
Benzene levels exceeding the MCL have been detected (Tetra Tech 2000) in the middle and upper aquifers	Unknown		

Notes:

MCL Maximum contaminant level

.

9.0 RECOMMENDATIONS AND FOLLOW-UP ACTIONS

Monitoring of surface water, sediment, and ground water should resume as soon as possible. In addition, the O&F Activities Report recommended that monitoring wells MA-08 and DA-08 should be plugged and abandoned due to questions related to well integrity. This activity should be completed at the earliest convenience.

The vegetative ground cover should be cut as part of regular site maintenance. The well pad should be demolished, and the protective bollards and cluster fencing and gate should be properly removed from well DA-07. The presence of site contaminants above MCLs in the middle and deep aquifers must be addressed.

Table 3 lists recommendations and follow-up actions for the HAP site.

10.0 PROTECTIVENESS STATEMENTS

The remedy at the Highlands Acid Pit Superfund site currently protects human health and the environment because: 1) the source control remedy has been implemented and is functioning as intended, 2) the contamination found in the middle: and deep aquifers has not affected nearby area water supply wells, and 3) based on the comparison of field data to sediment screening levels, EPA concludes that site related contaminants are not affecting sediments near the site. However, in order for the remedy to be protective in the long-term, the following actions need to be taken: 1) continue to monitor the shallow, middle, and deep aquifers to assess changes in the concentration of site-related contaminants; 2) model the movement of site-related contaminants in the middle and deep aquifers to determine the direction of plume movement and potential for exposure from future ground water use; and 3) address whether MCLs are applicable or relevant and appropriate requirements for the middle and deep aquifers, and if they are, whether a waiver is appropriate.

11.0 NEXT REVIEW

This is a site that requires ongoing Five-Year Reviews. The next review will be conducted within the next five years, but no later than five years from the signature date of this review.

12.0 OTHER COMMENTS

None.

TABLE 3

RECOMMENDATIONS AND FOLLOW-UP ACTIONS

Deficiencies	Recommendations /Follow-up Actions	Party Responsible	Oversight Agency	Milestone Date	Follow-up Actions: Affects Protectiveness (Y/N)
O&M ground water monitoring	Complete the O&M manual as soon as possible and resume ground water monitoring activities	N/A	TNRCC	February 2002	N
Overgrown ground cover	Set a regular maintenance schedule for grass mowing	N/A	TNRCC	February 2002	N
Monitoring well integrity	Plug and abandon MA-08 and DA-08	N/A	EPA	September 2002	N
Monitoring well DA-01 plugged	Unplug well or New replacement well	EPA	EPA	September 2002	N

Notes:

N/A Not applicable

APPENDIX A

DOCUMENTS REVIEWED

DOCUMENTS REVIEWED

Tetra Tech EM Inc. October 2000. "Operational and Functional Activities Report."

- U.S. Environmental Protection Agency (EPA). June 1984. Record of Decision (ROD) Source Control Operable Unit.
- EPA. June 1987. "Abbreviated ROD Ground Water Operable Unit."
- EPA. August 1988. "CERCLA Compliance with Other Laws Manual."
- EPA. June 1996. 'First Five-Year Review, Highlands Acid Pit Superfund Site, Harris County, Texas."
- EPA. October 1999. "Comprehensive Five-Year Guidance." EPA/540R/R-98/050. Office of Emergency and Remedial Response. OSWER Directive 9355.7-03B-P. Washington, DC. Draft.
- Woodward-Clyde Consultants (WWC). 1996. "Annual Monitoring Report FY 1996, Highlands Acid Pit Superfund Site, Highlands, Texas."

APPENDIX B

SITE VISIT REPORT

(33 Pages)

SITE VISIT REPORT

HIGHLANDS ACID PIT SUPERFUND SITE HIGHLANDS, HARRIS COUNTY, TEXAS

July 2001

U.S. ENVIRONMENTAL PROTECTION AGENCY 1445 Ross Avenue Dallas, TX 75202-2733

CONTENTS

<u>Sect</u>	ion Page
1.0	INTRODUCTION B-1
2.0	BACKGROUND B-1
3.0	SITE INSPECTION ACTIVITIES B-2
4.0	FINDINGS B-3
<u>Exhib</u>	its
A	PHOTOGRAPHS

B SITE INSPECTION CHECKLIST

1.0 INTRODUCTION

The U.S. Environmental Protection Agency (EPA) is hereby conducting a Five-Year Review of the effectiveness of the remedy employed at the Highlands Acid Pit (HAP) site to protect human health and the environment.

A site inspection was conducted as part of the requirements for a Five-Year Review, to verify that all components of the selected remedy are operating in accordance with criteria established in the 1984 Source Control Record of Decision (ROD). This report summarizes the results of the site inspection at the HAP site.

2.0 BACKGROUND

The HAP site was used for the disposal of an unknown quantity of industrial waste sludge, believed to be spent sulfuric acid from a refinery process, during the early 1950s. The HAP site is located in Harris County, 16 miles east of Houston, Texas, and 1.4 miles west of Highlands, Texas, at the end of Clear Lake Road and adjacent to the east side of the San Jacinto River. The site is bordered by a wooded area to the north, flooded sand pits to the east, Clear Lake to the south, and Grennel Slough to the west. The site is a 6-acre peninsula within the 10-year flood plain of the San Jacinto River.

The site lies within the Jessie White Survey A-83 of Harris County, Texas, within the Coast Prairie and East Texas Timberlands. The HAP site lies within Federal/State Census Tract Number 25901 and is within the planning jurisdiction of the Baytown, Texas Planning Commission. The census tract encompasses most of the City of Highlands and adjacent unincorporated areas near the site. There are no known zoning or land use restriction ordinances in effect or planned within the jurisdiction of the Baytown Planning Commission. Little development is foreseen in the site area due to its location within the 100-year flood plain of the

B-1

San Jacinto River. The flow of the San Jacinto River is controlled by the dam at Lake Houston, local meteorology events, and tides.

The selected remedy from the ROD was excavation and off-site disposal. The selected remedy included:

- excavation of waste material to an approximate depth of 8 feet
- transportation of waste to a permitted Class I hazardous waste disposal facility
- backfilling the excavated area with clean fill
- constructing a temporary site perimeter fence with warning signs
- installing a ground water monitoring system
- performing ground water monitoring and site maintenance for a 30-year period

The selected ground water remedy was no action, with a recommendation for monitoring the surface environment (surface water and sediments) and ground water.

3.0 SITE INSPECTION ACTIVITIES

Tetra Tech conducted the site inspection on May 8, 2001. The objective was to assess site conditions for the second Five-Rear Review. Photographic documentation of the site inspection is presented in Exhibit A. The site inspection checklist is presented in Exhibit B.

The following individuals were present during the site visit:

- Mr. Ernest Franke, EPA
- Mr. Jim Feeley, TNRCC
- Mr. Jared Fuqua, Tetra Tech
4.0 FINDINGS

TNRCC is preparing an update for the O&M Manual for the HAP site so that O&M activities can resume. The O&M will include a contingency or emergency response plan, and O&M and Occupational Safety and Health Administration (OSHA) training records. As part of the development of the O&M manual, TNRCC agreed to compile ground water monitoring records and install a project sign for the HAP site.

The fencing and roads were in good condition, and the site locks were in place. High vegetation covered the site, and was growing inside the enclosed well clusters fencing. No recent flooding at the HAP site was apparent. A visual inspection of the monitoring wells noted good conditions with no apparent damage or vandalism.

An oil and gas production plant was installed at the entrance to the adjacent fenced property (approximately 200 feet east on Clear Lake Road) at the time of the inspection. Two wells for the production plant have been drilled.

EXHIBIT B

SITE VISIT CHECKLIST

(13 Pages)

FIVE-YEAR REVIEW SITE INSPECTION CHECKLIST

Information may be completed by hand and attached to the Five-Rear Review report as supporting documentation of site status. "N/A" refers to "not applicable."

I. SITE INFORM	ATION
Site Name: Highlands Acid Pit	Date of Inspection: 05/08/01
Location and Region: Highlands, Texas Region 6	EPA ID: 034-FRFF-06ZZ
Agency, office, or company leading the five-year review: EPA	Weather/temperature: Overcast/windy 85-90 °F
Remedy Includes: (Check all that apply) □ Landfill cover/containment Ø Access controls □ Institutional controls □ Ground water pump and treatment □ Surface water collection and treatment Ø Other Ground water monitoring and site mainter	nance
Attachments: Inspection team roster attached	⊠ Site map attached
II. INTERVIEWS (Checl	k all that apply)
1. O&M Site Manager <u>N/A</u> Name	Title Date
Interviewed: at site at office by phone Problems, suggestions: Report attached	Phone no
2. O&M Staff N/A Name	Title Date
Interviewed: at site at office by phone Problems, suggestions: Report attached	Phone no

3.	Local regulatory authorized response office, police d record of deeds, or other	epartment, office of public hear r city and county offices, etc.).	(i.e.; State and Tribal of alth or environmental he Fill in all that apply.	offices, emergency ealth, zoning office,
	Agency <u>TNRCC</u> Contact <u>Jim Feeley</u> Name	<u>Project Manager</u> Title	<u>April 27, 2001</u> Date	<u>(512)239-2462</u> Phone no.
	Problems, suggestions:	☑ Report attached		
	Agency Contact Name	Title	Date	Phone no.
	Problems, suggestions:	Report attached		
	Agency Contact			
	Name	Title	Date	Phone no.
	Agency Contact			·····
	Name Problems suggestions:	Title	Date	Phone no.
			· · · · · · · · · · · · · · · · · · ·	
4.	Other interviews (optio	nal): 🛛 Report attached.		
	Mr. Bubba Crawford, ov	vner of the Baytown Boat Clu	b	
	Mr. Jared Fuqua, HAP s	ite contractor and consultant		

	III. ONSITE DOCUMENTS &	& RECORDS VERIFIED (C	Thec	k all that apply)
1.	O&M Documents Ø O&M manual □ As-built drawings □ Maintenance logs Remarks <u>TNRCC O&M Manual prepar</u>	 Readily available Readily available Readily available ation is in progress 		Up to date ⊠ N/A Up to date □ N/A Up to date □ N/A
2.	Site-Specific Health and Safety Plan Contingency plan/emergency response Remarks Both plans should be included	☐ Readily available se plan ☐ Readily available in the O&M Manual		Up to date ⊠ N/A Up to date ⊠ N/A
3.	O&M and OSHA Training Records Remarks Should be included in the O&I	Readily available Manual		Up to date ⊠ N/A
4.	Permits and Service Agreements Air discharge permit Effluent discharge Waste disposal, POTW Other permits Remarks	 Readily available Readily available Readily available Readily available Readily available 		Up to date ⊠ N/A Up to date ⊠ N/A Up to date ⊠ N/A Up to date ⊠ N/A
5.	Gas Generation Records Remarks	Readily available		Up to date ⊠ N/A
6.	Settlement Monument Records Remarks	□ Readily available		Up to date ⊠ N/A
7.	Ground Water Monitoring Records Remarks_TNRCC_will compile	Readily available		☐ Up to date⊠ N/A
8.	Leachate/Condensate Extraction Rec Remarks	ords 🗌 Readily available		□ Up to date⊠ N/A
9.	Discharge Compliance Records Air Water (effluent)	 Readily available Readily available 		Up to date Ø N/A Up to date Ø N/A
10.	Daily Access/Security Logs Remarks	Readily available		Up to date 🛛 N/A

			IV. O&M COSTS	
1.	O&M Organization State in-house PRP in-house Other		⊠ Contractor for St. □ Contractor for P	State P'RP
2.	O&M Cost Records Readily available Funding mechanism Original O&M cost est To	Not Availab agreement in p imate tal annual cost	ble/HAP Not Started Up to da blace by year for review peri	late Breakdown attached riod, if available
	From Prom From From Date From Date Date	to Date to Date to Date to Date to Date	Total cost Total cost Total cost Total cost Total cost	Breakdown attached Breakdown attached Breakdown attached Breakdown attached Breakdown attached Breakdown attached
3. V. A.	Unanticipated or Unu Describe costs and reas ACCESS AND INSTI Fencing	sually High O ons: <u>N/A</u> TUTIONAL (&M Costs During Re	Applicable IN/A
1.	Fencing damaged Remarks <u>All locks in p</u>	Locatio	on shown on site map	⊠ Gates secured □ N/A

÷

B.	Other Access Restrictions
1.	Signs and other security measures □ Location shown on site map □ N/A Remarks TNRCC will construct and install □
C.	Institutional Controls
1.	Implementation and enforcement Site conditions imply ICs not properly implemented Implemented Yes No N/A Site conditions imply ICs not being fully enforced Implemented Yes No N/A
	Frequency
	Responsible party/agency TNRCC
	Contact Jim Feeley Project Manager (918) 437-7773
	Name Title Date Phone no.
	Reporting is up-to-dateImage: YesNoN/AReports are verified by the lead agencyImage: YesNoN/A
	Specific requirements in deed or decision documents have been met □ Yes No N/A Violations have been reported □ Yes No N/A Other problems or suggestions: □ Report attached
2.	Adequacy ICs are adequate ICs are inadequate ICs are inadequate Remarks Monitoring has not been initiated by TNRCC
D.	General
1.	Vandalism/trespassing Location shown on site map No vandalism evident Remarks
2.	Land use changes on site Remarks Additional well (oil/gas) has been drilled (on adjacent property)
3.	Land use changes offsite IN/A Remarks Oil and gas production plant was being installed at the entrance to the fenced property (approximately 200 feet east, down Clear Lake Road adjacent to the HAP site)

	VI.	GENERAL SITE CONDITIONS	;
A.	Roads 🛛 Applie	cable 🗌 N/A	
1.	Roads damaged Location Remarks	a shown on site map 🛛 Roads	adequate 🗆 N/A
B.	Other Site Conditions		
	Remarks <u>High vegetation cover</u> (fenced enclosures)	ing site and growing inside well clust	ter compounds
	VII. LANDFILL COVER	RS 🗆 Applica	able 🛛 N/A
А.	Landfill Surface (Site Cover C	nly)	
1.	Settlement (Low spots)	□ Location shown on site map	Settlement not evident
	Areal extent Remarks	Depth	
2.	Cracks Lengths Remarks	Location shown on site map Widths	 Cracking not evident Depths
3.	Erosion Areal extent Remarks	Location shown on site map Depth	Erosion not evident
4.	Holes Areal extent Remarks	Location shown on site map Depth	⊠ Holes not evident
5.	Vegetative Cover ⊠ Grass □ Trees/Shrubs (indicate size a Remarks_The ground cover nee	Cover properly established and locations on a diagram) ads to be cut.	No signs of stress
6.	Alternative Cover (armored ro Remarks Access road in good of	ck, concrete, etc.)	

7.	Bulges Areal extent Remarks	□ Location shown on site map ⊠ Bulges not evident Depth
8.	Wet Areas/Water Damage Uet areas Ponding Seeps Soft subgrade Remarks	 Wet areas/water damage not evident Location shown on site map Areal extent
9.	Slope Instability Slides Areal extent Remarks	Location shown on site map I No evidence of slope instability
В.	Benches Applicat (Horizontally constructed mount the slope in order to slow runoff to a lined channel.)	ble IN/A ds of earth placed across a steep landfill side slope to interrupt down the velocity of surface runoff and intercept and convey the
1.	Flows Bypass Bench Remarks	□ Location shown on site map ⊠ N/A □ Okay
2.	Bench Breached Remarks	□ Location shown on site map ⊠ N/A □ Okay
3.	Bench Overtopped Remarks	□ Location shown on site map ⊠ N/A □ Okay
C.	Letdown Channels	oplicable 🛛 N/A
1.	Settlement Areal extent Remarks	Cation shown on site map Depth
2.	Material Degradation Lo Material type Remarks	Areal extent

3.	Erosion Areal extent Remarks	Location shown Depth	on site map
4.	Undercutting Areal extent Remarks	Location shown of Depth	on site map
5.	Obstructions Location shown on site map Size Remarks	Type Areal extent	No obstructions
6.	Excessive Vegetative Growth No evidence of excessive gro Vegetation in channels does a Location shown on site map Remarks	Type owth not obstruct flow Areal extent	
_			
D.	Cover Penetrations		⊠ N/A
D. 1.	Gas Vents Properly secured/locked Evidence of leakage at penetra Remarks	Applicable Active Functioning ration	 ☑ N/A □ Passive □ Routinely sampled □ Good condition □ Needs O&M □ N/A
D. 1.	Gas Vents Properly secured/locked Evidence of leakage at penetr Remarks	Applicable Active Functioning ration	 ☑ N/A □ Passive □ Routinely sampled □ Good condition □ Needs O&M □ N/A
D. 1. 2.	Gas Vents Properly secured/locked Evidence of leakage at penetr Remarks	Applicable Active Functioning Functioning Functioning ration	 N/A Passive □ Routinely sampled □ Good condition □ Needs O&M □ N/A □ Routinely sampled □ Good condition □ Needs O&M □ N/A
D. 1. 2.	Gas Vents Properly secured/locked Evidence of leakage at penetr Remarks Gas Monitoring Probes Properly secured/locked Evidence of leakage at penetr Remarks Monitoring Wells (within surface)	Applicable Active Active Functioning ration Functioning ration ce area of landfill)	 N/A Passive □ Routinely sampled □ Good condition □ Needs O&M □ N/A □ Routinely sampled □ Good condition □ Needs O&M □ N/A
D. 1. 2. 3.	Gas Vents Properly secured/locked Evidence of leakage at penetr Remarks	Applicable Active Functioning ration Functioning ration ce area of landfill) Functioning	 N/A Passive Routinely sampled Good condition Needs O&M N/A Routinely sampled Good condition Needs O&M N/A Needs O&M N/A Routinely sampled Good

-				
4.	Leachate Extraction Wells Properly secured/locked 	Functioning	Routinely sampled	Good
	Evidence of leakage at pener Remarks	tration	Needs O&M	□ N/A
5.	Settlement Monuments Remarks		utinely surveyed] N/A
E.	Gas Collection and Treatmen	t 🗆 Applicable 🛛 N/A	A	
1.	Gas Treatment Facilities Flaring Good condition Remarks	 Thermal destruction Needs O&M 	on 🗆 Collection	n for reuse
2.	Gas Collection Wells, Manifol	ds, and Piping		
3.	Gas Monitoring Facilities (e.g. Good condition Remarks	., gas monitoring of adja □ Needs O&M	acent homes or buildings)
F.	Cover Drainage Layer		⊠ N/A	
1.	Outlet Pipes Inspected Remarks	Functioning	C] N/A
2.	Outlet Rock Inspected Remarks	Functioning	□ N/A	
G.	Detention/Sedimentation Pone	ds 🗌 Applicable	⊠ N/A	
1.	Siltation Areal extent Siltation not evident Remarks	······································	Depth	0
2.	Erosion Areal extent Erosion not evident Remarks		Depth	

3.	Outlet Works Remarks	□ Functioning	□ N/A	
4.	Dam Remarks	□ Functioning	□ N/A	
Н.	Retaining Walls		× N/A	
1.	Deformations Horizontal displacement Rotational displacement Remarks	Location shown on Vertical	site map Deformation not displacement	evident
2.	Degradation Remarks	□ Location shown on	site map 🗌 Degradation not e	evident
I.	Perimeter Ditches/Off-Site I	Discharge 🗌 Applicable	× N/A	
1.	Siltation Areal extent Remarks	Location shown on Depth	site map	
2.	Vegetative Growth Uegetation does not imped Areal extent Remarks	Location shown on Ie flow Type	site map 🛛 N/A	
3.	Erosion Areal extent Remarks	Location shown on Depth	site map	nt
4.	Discharge Structure Remarks	☐ Functioning	□ N/A	
	VIII. VERTICAI	BARRIER WALLS	🗌 Applicable 🛛 N/A	
1.	Settlement Areal extent Remarks	Location shown onDepth	site map Settlement not evi	ident

_`

2.	Performance Monitoring Performance not monitored Frequency Head differential Remarks	Type of monitoring Evidence	e of br	reaching	
	X. GROUND WATER/SURFACE WATER	REMEDIES	Ø	Applicable	□ N/A
А.	Ground Water Extraction Wells, Pumps, and	d Pipelines		Applicable	Ø N/A
1.	Pumps, Wellhead Plumbing, and Electrical Good condition All requ Remarks	uired wells located		Needs O&M	⊠ N/A
Ļ					
2.	Extraction System Pipelines, Valves, Valve B Good condition Needs O& Remarks N/A	oxes, and Other Ap M		Pances	·
3.	Spare Parts and Equipment Image: Constraint of the second structure Image: Constraint of the second stru	C Requires upgrad	le	D Needs provided	to be
Ļ	C A Wester Collection Standards Dumma	De-sking [1* 1.9.	
Б.	Surface Water Conection Structures, rumps,	, and Pipennes	l Abl		M N/A
1.	Collection Structures, Pumps, and Electrical Good condition I Needs O&M Remarks				
2.	Surface Water Collection System Pipelines, V Good condition INeeds O&M Remarks	/alves, Valve Boxes,	, and	Other Appurt	enances
	• • • • • • • • • • • • • • • • • • •				
3.	Spare Parts and Equipment Readily available Good condition Remarks	Requires upgrad	.e	D Needs provided	to be
 					
C.	Treatment System Applicable	🛛 N/A			

1.	Treatment Train (Check components that apply) Metals removal Oil/water separation Air stripping Carbon adsorbers Filters
2.	Electrical Enclosures and Painels (Properly rated and functional) N/A Good condition Remarks
3.	Tanks, Vaults, Storage Vessels N/A Good condition Proper secondary containment Needs O&M Remarks
4.	Discharge Structure and Appurtenances N/A Good condition Needs O&M Remarks
5.	Treatment Building(s) C N/A Good condition (esp. roof and doorways) Needs repair C C N/A Good condition (esp. roof and doorways) Needs repair C C N/A Remarks Condition (esp. roof and doorways) Condition (esp. roof and doorways)
5.	Treatment Building(s) C N/A □ Good condition (esp. roof and doorways) □ Needs repair □ Chemicals and equipment properly stored Remarks
5.	Treatment Building(s) C N/A Good condition (esp. roof and doorways) Needs repair C C N/A Good condition (esp. roof and doorways) Needs repair C C N/A Good condition (esp. roof and doorways) Needs repair C C N/A Good condition (esp. roof and doorways) Needs repair C C N/A Good condition (esp. roof and doorways) Needs repair C C N/A Monitorials and equipment properly stored Remarks Monitoring Wells (Pump and treatment remedy) Routinely sampled Good condition Properly secured/locked Functioning Routinely sampled Good condition All required wells located Needs O&M N/A N/A
5. 6. D.	Treatment Building(s) C N/A Good condition (esp. roof and doorways) Chemicals and equipment properly stored Remarks Monitoring Wells (Pump and treatment remedy) Properly secured/locked Functioning Routinely sampled Good condition Good condition All required wells located Needs O&M N/A Monitored Natural Attenuation
5. 6. 1.	Treatment Building(s) C N/A Good condition (esp. roof and doorways) Needs repair C chemicals and equipment properly stored Remarks

If there are remedies applied at the site which are not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.

XI. OVERALL OBSERVATIONS

A. Implementation of the Remedy

Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is to accomplish (i.e., to contain contaminant plume, minimize infiltration and gas emission, etc.).

No Action. Ground Water Record of Decision

B. Adequacy of O&M

Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy.

O&M has not been initiated. O&M plan is in progress by TNRCC contractor.

C. Early Indicators of Potential Remedy Failure

Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs, that suggest that the protectiveness of the remedy may be compromised in the future.

Could not evaluate.

D. Opportunities for Optimization

Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy.

Could not evaluate.

APPENDIX C

SURVEYS

(Seven Pages)

TABLE 3

RECOMMENDATIONS AND FOLLOW-UP ACTIONS

Deficiencies	Recommendations /Follow-up Actions	Party Responsible	Oversight Agency	Milestone Date	Follow-up Actions: Affects Protectiveness (Y/N)
O&M ground water monitoring	Complete the O&M manual as soon as possible and resume ground water monitoring activities	N/A	TNRCC	February 2002	Ν
Overgrown ground cover	Set a regular maintenance schedule for grass mowing	N/A	TNRCC	February 2002	Ν
Monitoring well integrity	Plug and abandon MA-08 and DA-08	N/A	EPA	September 2002	N
Monitoring well DA-01 plugged	Unplug well or New replacement well	EPA	EPA	September 2002	N

Notes:

N/A Not applicable

APPENDIX A

DOCUMENTS REVIEWED

DOCUMENTS REVIEWED

Tetra Tech EM Inc. October 2000. "Operational and Functional Activities Report."

- U.S. Environmental Protection Agency (EPA). June 1984. Record of Decision (ROD) Source Control Operable Unit.
- EPA. June 1987. "Abbreviated ROD Ground Water Operable Unit."
- EPA. August 1988. "CERCLA Compliance with Other Laws Manual."
- EPA. June 1996. 'First Five-Year Review, Highlands Acid Pit Superfund Site, Harris County, Texas."
- EPA. October 1999. "Comprehensive Five-Year Guidance." EPA/540R/R-98/050. Office of Emergency and Remedial Response. OSWER Directive 9355.7-03B-P. Washington, DC. Draft.
- Woodward-Clyde Consultants (WWC). 1996. "Annual Monitoring Report FY 1996, Highlands Acid Pit Superfund Site, Highlands, Texas."

(33 Pages)

SITE VISIT REPORT

APPENDIX B

SITE VISIT REPORT

HIGHLANDS ACID PIT SUPERFUND SITE HIGHLANDS, HARRIS COUNTY, TEXAS

July 2001

U.S. ENVIRONMENTAL PROTECTION AGENCY 1445 Ross Avenue Dallas, TX 75202-2733

CONTENTS

SectionPage1.0INTRODUCTIONB-12.0BACKGROUNDB-13.0SITE INSPECTION ACTIVITIESB-24.0FINDINGSB-3ExhibitsAPHOTOGRAPHS

B SITE INSPECTION CHECKLIST

1.0 INTRODUCTION

The U.S. Environmental Protection Agency (EPA) is hereby conducting a Five-Year Review of the effectiveness of the remedy employed at the Highlands Acid Pit (HAP) site to protect human health and the environment.

A site inspection was conducted as part of the requirements for a Five-Year Review, to verify that all components of the selected remedy are operating in accordance with criteria established in the 1984 Source Control Record of Decision (ROD). This report summarizes the results of the site inspection at the HAP site.

2.0 BACKGROUND

The HAP site was used for the disposal of an unknown quantity of industrial waste sludge, believed to be spent sulfuric acid from a refinery process, during the early 1950s. The HAP site is located in Harris County, 16 miles east of Houston, Texas, and 1.4 miles west of Highlands, Texas, at the end of Clear Lake Road and adjacent to the east side of the San Jacinto River. The site is bordered by a wooded area to the north, flooded sand pits to the east, Clear Lake to the south, and Grennel Slough to the west. The site is a 6-acre peninsula within the 10-year flood plain of the San Jacinto River.

The site lies within the Jessie White Survey A-83 of Harris County, Texas, within the Coast Prairie and East Texas Timberlands. The HAP site lies within Federal/State Census Tract Number 25901 and is within the planning jurisdiction of the Baytown, Texas, Planning Commission. The census tract encompasses most of the City of Highlands and adjacent unincorporated areas near the site. There are no known zoning or land use restriction ordinances in effect or planned within the jurisdiction of the Baytown Planning Commission. Little development is foreseen in the site area due to its location within the 100-year flood plain of the

B-1

San Jacinto River. The flow of the San Jacinto River is controlled by the dam at Lake Houston, local meteorology events, and tides.

The selected remedy from the ROD was excavation and off-site disposal. The selected remedy included:

- excavation of waste material to an approximate depth of 8 feet
- transportation of waste to a permitted Class I hazardous waste disposal facility
- backfilling the excavated area with clean fill
- constructing a temporary site perimeter fence with warning signs
- installing a ground water monitoring system
- performing ground water monitoring and site maintenance for a 30-year period

The selected ground water remedy was no action, with a recommendation for monitoring the surface environment (surface water and sediments) and ground water.

3.0 SITE INSPECTION ACTIVITIES

Tetra Tech conducted the site inspection on May 8, 2001. The objective was to assess site conditions for the second Five-Rear Review. Photographic documentation of the site inspection is presented in Exhibit A. The site inspection checklist is presented in Exhibit B.

The following individuals were present during the site visit:

- Mr. Ernest Franke, EPA
- Mr. Jim Feeley, TNRCC
- Mr. Jared Fuqua, Tetra Tech

B-2

4.0 FINDINGS

TNRCC is preparing an update for the O&M Manual for the HAP site so that O&M activities can resume. The O&M will include a contingency or emergency response plan, and O&M and Occupational Safety and Health Administration (OSHA) training records. As part of the development of the O&M manual, TNRCC agreed to compile ground water monitoring records and install a project sign for the HAP site.

The fencing and roads were in good condition, and the site locks were in place. High vegetation covered the site, and was growing inside the enclosed well clusters fencing. No recent flooding at the HAP site was apparent. A visual inspection of the monitoring wells noted good conditions with no apparent damage or vandalism.

An oil and gas production plant was installed at the entrance to the adjacent fenced property (approximately 200 feet east on Clear Lake Road) at the time of the inspection. Two wells for the production plant have been drilled.

3. Local regulatory authorities and response agencies (i.e.; State and Tribal offices, emergency response office, police department, office of public health or environmental health, zoning office, record of deeds, or other city and county offices, etc.). Fill in all that apply.

Agency <u>TNRCC</u> Contact <u>Jim Feeley</u> Name	<u>Project Manager</u> Title	<u>April 27, 2001</u> Date	<u>(512)239-2462</u> Phone no.
Problems, suggestions:	☑ Report attached		
Agency Contact			
Name	Title	Date	Phone no.
Problems, suggestions:	Report attached		
Agency			
Contact			
Name	Title	Date	Phone no.
Agency			
Contact			
Name	Title	Date	Phone no.
Problems, suggestions:	Report attached		
4. Other interviews (opti	ional): 🛛 Report attache	ed.	
Mr. Bubba Crawford, c	owner of the Baytown Boat	Club	
Mr. Jared Fuqua, HAP	site contractor and consulta	Int	

	III. ONSITE DOCUMENTS &	& REC	ORD	S VERIFIED (C	'hec	k all	that a	oply)
1.	O&IM Documents ☑ C)&M manual □ A.s-built drawings □ Maintenance logs Remarks <u>TNRCC O&M Manual prepara</u>	□ Re □ Re □ Re ation is	adily a adily a adily a in pro	available available available ogress		Up 1 Up 1 Up 1	to date to date to date		N/A N/A N/A
2.	Site-Specific Health and Safety Plan Contingency plan/emergency respons Remarks Both plans should be included	□ Re se plan in the (eadily □ F C&M	available Readily available Manual		Up Up	to date to date	;⊠ ;⊠	N/A N/A
3.	O&M and OSHA Training Records Remarks Should be included in the O&N	□ Re <u>M Man</u> u	eadily and the second sec	available		Up	to date	. 🛛	N/A
4.	Permits and Service Agreements Air discharge permit Effluent discharge Waste disposal, POTW Other permits Remarks	Re Re Re Re Re	eadily a cadily a cadily a cadily a	available available available available		Up Up Up Up	to date to date to date to date		N/A N/A N/A N/A
5.	Gas Generation Records Remarks	🗆 Re	adily	available		Up	to date	; 🛛	N/A
6.	Settlement Monument Records Remarks	🗆 Re	adily a	available		Up	to date	, 🛛	N/A
7.	Ground Water Monitoring Records Remarks	□ R	Readily	v available			□ Uj N/A	p to	date⊠
8.	Leachate/Condensate Extraction Rec Remarks	ords		Readily available			🗆 U	p to	date⊠ N/A
9.	Discharge Compliance Records Air Water (effluent) Remarks	🗆 Re	eadily :	available Readily available		Up	to date	;⊠ to (N/A date ⊠ N/A
10.	Daily Access/Security Logs Remarks	🗆 Re	adily a	available		Up	to date	; 🛛	N/A

Γ]	V. O&M COSTS		
1.	O&M Organization State in-house PRP in-house Other		☑ Contractor for State □ Contractor for PR	te P .	
2.	O&M Cost Records Readily available Funding mechanism Original O&M cost est To	Not Available agreement in pl imate otal annual cost 1	e/HAP Not Started Up to date ace by year for review period	e Breakdown attached d, if available	
	From From From From From Date From Date From	to Date to Date to Date to Date to Date to	Total cost Total cost Total cost Total cost Total cost	 Breakdow attached Breakdow attached Breakdow attached Breakdow attached Breakdow attached Breakdow attached 	n n n
3. V.	Unanticipated or Unit Describe costs and reas ACCESS AND INSTI	sons: <u>N/A</u>	&M Costs During Revi	iew Period	
A. 1.	Fencing Fencing damaged Remarks <u>All locks in p</u>	□ Locatio lace	n shown on site map	⊠ Gates secured □ N/A	A

B.	Other Access Restrictions
1.	Signs and other security measures □ Location shown on site map □ N/A Remarks TNRCC will construct and install
C.	Institutional Controls
1.	Implementation and enforcementSite conditions imply ICs not properly implementedImplementedVesNoM/ASite conditions imply ICs not being fully enforcedImplementedVesNoM/A
	Type of monitoring (e.g., self-reporting, drive by) Ground water sampling/post flooding inspection Frequency
	Responsible party/agency TNRCCContact Jim FeeleyProject Manager(918) 437-7773NameTitleDatePhone no.
	Reporting is up-to-dateImage: YesImage: NoImage: N/AReports are verified by the lead agencyImage: YesImage: NoImage: N/A
	Specific requirements in deed or decision documents have been met □ Yes ℕo ℕ/A Violations have been reported □ Yes ℕo ℕ/A Other problems or suggestions: □ Report attached
2.	Adequacy ICs are adequate ICs are inadequate N/A Remarks Monitoring has not been initiated by TNRCC
D.	General
1.	Vandalism/trespassing Location shown on site map No vandalism evident Remarks
2.	Land use changes on site Remarks Additional well (oil/gas) has been drilled (on adjacent property)
3.	Land use changes offsite Ø N/A Remarks Oil and gas production plant was being installed at the entrance to the fenced property (approximately 200 feet east, down Clear Lake Road adjacent to the HAP site)

.

Γ	VI.	GENERAL SITE CONDITIONS	
A.	Roads 🛛 Applic	able 🗆 N/A	
1.	Roads damaged Location Remarks	shown on site map ⊠ Roads adeq	uate 🗆 N/A
В.	Other Site Conditions		
	Remarks High vegetation covering (fenced enclosures)	ng site and growing inside well cluster co	ompounds
	VII. LANDFILL COVER	S 🗆 Applicable	⊠ N/A
A.	Landfill Surface (Site Cover O	nly)	
1.	Settlement (Low spots)	□ Location shown on site map	Settlement not
	Areal extent Remarks	Depth	
	Curaliz		
4.	Lengths Remarks	Widths	_ Depths
3.	Erosion Areal extent Remarks	LI Location shown on site map Depth	Erosion not evident
4.	Holes Areal extent	Location shown on site map Depth	Holes not evident
	Remarks		· · · · · · · · · · · · · · · · · · ·
5.	Vegetative Cover ⊠ Grass □ Trees/Shrubs (indicate size a Remarks_The ground cover nee	Cover properly established nd locations on a diagram) ds to be cut.	□ No signs of stress
6.	Alternative Cover (armored ro Remarks Access road in good c	ck, concrete, etc.)	

7.	Bulges Areal extent Remarks	□ Location shown on site map
8.	Wet Areas/Water Damage Uet areas Ponding Seeps Soft subgrade Remarks	 Wet areas/water damage not evident Location shown on site map Areal extent
9.	Slope Instability Slides Areal extent Remarks	□ Location shown on site map ⊠ No evidence of slope
В.	Benches Application (Horizontally constructed mount the slope in order to slow runoff to a lined channel.)	Ne N/A ds of earth placed across a steep landfill side slope to interrupt down the velocity of surface runoff and intercept and convey the
1.	Flows Bypass Bench Remarks	□ Location shown on site map
2.	Bench Breached Remarks	□ Location shown on site map ⊠ N/A □ Okay
3.	Bench Overtopped Remarks	□ Location shown on site map ⊠ N/A □ Okay
C.	Letdown Channels	plicable 🛛 N/A
1.	Settlement Lc Areal extent Remarks	cation shown on site map Depth
2.	Material Degradation 🛛 Lo Material type Remarks	Areal extent

3.	Erosion Areal extent Remarks	Location shown of Depth	on site map
4.	Undercutting Areal extent Remarks	Location shown of Depth	on site map
5.	Obstructions Location shown on site map Size Remarks	Type Areal extent	No obstructions
6.	Excessive Vegetative Growth No evidence of excessive gro Vegetation in channels does Location shown on site map Remarks	Type owth not obstruct flow Areal extent	
D.	Cover Penetrations	Applicable	\bowtie N/A
<u> </u>		rr	
1.	Gas Vents Properly secured/locked Evidence of leakage at penet Remarks 	Active Functioning ration	 Passive Routinely sampled Good condition Needs O&M N/A
1.	Gas Vents Properly secured/locked Evidence of leakage at penet Remarks Gas Monitoring Probes Properly secured/locked Evidence of leakage at penet Remarks	Active Functioning Functioning Functioning ration	 Passive Routinely sampled Good condition Needs O&M N/A Routinely sampled Good condition Needs O&M N/A

4.	Leachate Extraction Wells Image: Description of the second descri	Functioning ration	 Routinely sample Needs O&M 	ed Good condition N/A
5.	S'ettlement Monuments R'emarks		outinely surveyed	□ N/A
E.	Gas Collection and Treatmen	t 🗆 Applicable 🛛 N	/A	
1.	Gas Treatment Facilities Gas Treatment Facilities	 Thermal destruct Needs O&M 	ion 🗌 Collec	tion for reuse
2.	Gas Collection Wells, Manifol	ds, and Piping	······································	
3.	Gas Monitoring Facilities (e.g Good condition Remarks	., gas monitoring of ac	ljacent homes or buildir	ıgs)
F.	Cover Drainage Layer	Applicable	⊠ N/A	
1.	Outlet Pipes Inspected Remarks	Functioning		□ N/A
2.	Outlet Rock Inspected Remarks	Functioning	□ N/A	
G.	Detention/Sedimentation Pon	ds 🗌 Applicabl	e 🛛 N/Á	
1.	SiltationAreal extent[] Siltation not evidentRemarks		Depth	0

2.	Erosion Areal ext	ent Depth	
3.	Outlet Works Remarks	□ Functioning	□ N/A
4.	Dam Remarks	□ Functioning	□ N/A
Н.	Retaining Walls	□ Applicable ⊠ 1	N/A
1.	Deformations Horizontal displacement Rotational displacement Remarks	Location shown on site m Vertical displa	ap Deformation not evident
2.	Degradation Remarks	Location shown on site m	ap 🗌 Degradation not evident
I.	Perimeter Ditches/Off-Site	Discharge 🗌 Applicable 🛛 🕅	N/A
1.	Siltation Areal extent Remarks	Location shown on site m Depth	ap 🗆 Siltation not evident
2.	Vegetative Growth Uegetation does not impe Areal extent Remarks	Location shown on site m de flow Type	⊔ap □ N/A
3.	Erosion Areal extent Remarks	Location shown on site m Depth	ap 🗆 Erosion not evident
4.	Discharge Structure Remarks	□ Functioning	□ N/A

	VIII. VERTICAL BARRIER WALLS Applicable N/A
1.	Settlement □ Location shown on site map □ Settlement not evident □ Depth Remarks
2.	Performance Monitoring Type of monitoring □ Performance not monitored □ Evidence of breaching Frequency □ Evidence of breaching Head differential Remarks
I	X. GROUND WATER/SURFACE WATER REMEDIES Applicable D N/A
А.	Ground Water Extraction Wells, Pumps, and Pipelines Applicable N/A
1.	Pumps, Wellhead Plumbing, and Electrical Good condition All required wells located Remarks
2.	Extraction System Pipelines, Valves, Valve Boxes, and Other Appurtenances □ Good condition □ Needs O&M Remarks N/A
3.	Spare Parts and Equipment Readily available Good condition Remarks N/A
В.	Surface Water Collection Structures, Pumps, and Pipelines Applicable N/A
1.	Collection Structures, Pumps, and Electrical Good condition Needs O&M Remarks
2.	Surface Water Collection System Pipelines, Valves, Valve Boxes, and Other Appurtenances Good condition Needs O&M Remarks

1.	Treatment Train (Check components that apply) Metals removal Oil/water separation Air stripping Carbon adsorbers Filters
2.	Electrical Enclosures and Panels (Properly rated and functional) N/A Good condition Remarks
3.	Tanks, Vaults, Storage Vessels N/A Good condition Proper secondary containment Needs O&M Remarks
4.	Discharge Structure and Appurtenances N/A Good condition Needs O&M Remarks
5.	Treatment Building(s) C N/A □ Good condition (esp. roof and doorways) □ Needs repair □ Chemicals and equipment properly stored Remarks
6.	Monitoring Wells (Pump and treatment remedy) Properly secured/locked Functioning Good condition
	All required wells located Needs O&M N/A Remarks
D.	Monitored Natural Attenuation
1.	Monitoring Wells (Natural attenuation remedy) □ Properly secured/locked □ Functioning □ Routinely sampled □ Good condition □ All required wells located ⊠ Needs O&M □ N/A Remarks
	X. OTHER REMEDIES

~
D.	Monitored Natural Attenuation					
1.	Monitoring Wells (Natural attenuation remedy) Properly secured/locked Functioning All required wells located Needs O&M N/A					
	X. OTHER REMEDIES					
	If there are remedies applied at the site which are not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.					
	XI. OVERALL OBSERVATIONS					
A .	Implementation of the Remedy					
	Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is to accomplish (i.e., to contain contaminant plume, minimize infiltration and gas emission, etc.).					
	No Action. Ground Water Record of Decision					
B.	Adequacy of O&M					
	Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy.					
	O&M has not been initiated. O&M plan is in progress by TNRCC contractor.					
C.	Early Indicators of Potential Remedy Failure					
	Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs, that suggest that the protectiveness of the remedy may be compromised in the future.					
	Could not evaluate.					
D.	Opportunities for Optimization					
	Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy.					
	Could not evaluate					
	Could not evaluate.					

EXHIBIT B

SITE VISIT CHECKLIST

(13 Pages)

FIVE-YEAR REVIEW SITE INSPECTION CHECKLIST

Information may be completed by hand and attached to the Five-Rear Review report as supporting documentation of site status. "N/A" refers to "not applicable."

I. SITE INFORMATION						
Site Name: Highlands Acid Pit	Date of Inspection: 05/08/01					
Location and Region: Highlands, Texas Region 6	EPA ID: 034-FRFF-06ZZ					
Agency, office, or company leading the five-year review: EPA	Weather/temperature: Overcast/windy 85-90 °F					
Remedy Includes: (Check all that apply) □ Landfill cover/containment ⊠ Access controls □ Institutional controls □ Ground water pump and treatment □ Surface water collection and treatment ⊠ Other Ground water monitoring and site maintenance						
Attachments: Inspection team roster attached	☑ Site map attached					
II. INTERVIEWS (Check	c all that apply)					
1. O&M Site Manager <u>N/A</u> Name	Title Date					
Interviewed: at site at office by phone Problems, suggestions: Report attached	Phone no					
2. O&M Staff N/A Name	Title Date					
Interviewed: at site at office by phone Problems, suggestions: Report attached	Phone no.					

3.	Local regulatory authorities and response agencies (i.e.; State and Tribal offices, emergency response office, police department, office of public health or environmental health, zoning office, record of deeds, or other city and county offices, etc.). Fill in all that apply.									
	Agency <u>TNRCC</u> Contact <u>Jim Feeley</u> Name	<u>Project Manager</u> Title	<u>April 27, 2001</u> Date	<u>(512)239-2462</u>						
-	Problems, suggestions:	Report attached		· · · · · · · · · · · · · · · · · · ·						
	Agency Contact									
	Name	Title	Date	Phone no.						
	Problems, suggestions:	Report attached								
	Agency Contact									
	Name Agency	Title	Date	Phone no.						
	Contact Name	Title	Date	Phone no.						
	Problems, suggestions:	Report attached								
4.	Other interviews (optic	onal): 🛛 Report attached								
	Mr. Bubba Crawford, or	wner of the Baytown Boat C	lub							
	Mr. Jared Fugua, HAP site contractor and consultant									
			- 							
	<u></u>									

	III. ONSITE DOCUMENTS & RECORDS VERIFIED (Check all that apply)							
1.	O&M Documents Ø O&M manual □ As-built drawings □ Maintenance logs Remarks <u>TNRCC O&M Manual prepar</u>	 Readily available Readily available Readily available ation is in progress 	□ Up to date ⊠ N/A □ Up to date □ N/A □ Up to date □ N/A					
2.	Site-Specific Health and Safety Plan Contingency plan/emergency response Remarks Both plans should be included	Readily available plan Readily available in the O&M Manual	□ Up to date ⊠ N/A □ Up to date ⊠ N/A					
3.	O&M and OSHA Training Records Remarks Should be included in the O&M	Readily available Manual	□ Up to date ⊠ N/A					
4.	Permits and Service Agreements Air discharge permit Effluent discharge Waste disposal, POTW Other permits	 Readily available Readily available Readily available Readily available 	 □ Up to date ⊠ N/A 					
5.	Gas Generation Records Remarks	Readily available	□ Up to date ⊠ N/A					
6.	Settlement Monument Records Remarks	Readily available	□ Up to date ⊠ N/A					
7.	Ground Water Monitoring Records Remarks	Readily available	☐ Up to date⊠ N/A					
8.	Leachate/Condensate Extraction Rec Remarks	ords 🗌 Readily available	□ Up to date⊠ N/A					
9.	Discharge Compliance Records Air Water (effluent)	□ Readily available □ Readily available	□ Up to date ⊠ N/A □ Up to date ⊠ N/A					
10.	Daily Access/Security Logs Remarks	□ Readily available	□ Up to date ⊠ N/A					

	IV. O&M COSTS									
1.	O&M Organization State in-house Image: Contractor for State PRP in-house Image: Contractor for PRP Other Other									
2.	O&M Cost Records Not Available/HAP Not Started Readily available									
	From Date From Date From Date From Date Date	to Date to Date to Date to Date to Date	Total cost Total cost Total cost Total cost Total cost	 Breakdown attached Breakdown attached Breakdown attached Breakdown attached Breakdown attached Breakdown attached 						
3. V.	3. Unanticipated or Unusually High O&M Costs During Review Period Describe costs and reasons: N/A									
A. 1.	Fencing Fencing damaged Remarks <u>All locks in p</u>	□ Location	n shown on site map 🛛	Gates secured D N/A						

B.	Other Access Restrictions
1.	Signs and other security measures □ Location shown on site map □ N/A Remarks TNRCC will construct and install □
C.	Institutional Controls
1.	Implementation and enforcementImplementedYesNoN/ASite conditions imply ICs not being fully enforcedImplementedVesNoN/A
	Type of monitoring (e.g., self-reporting, drive by) <u>Ground water sampling/post flooding inspection</u> Frequency
	Contact Jim Easley Project Manager (018) 437 7773
	Name Title Date Phone no.
	Reporting is up-to-dateImage: YesImage: NoImage: N/AReports are verified by the lead agencyImage: YesImage: NoImage: N/A
	Specific requirements in deed or decision documents have been met Image: Yes Violations have been reported Image: Yes Other problems or suggestions: Image: Report attached
2.	Adequacy ICs are adequate ICs are inadequate Ø N/A Remarks Monitoring has not been initiated by TNRCC
D.	General
1.	Vandalism/trespassing □ Location shown on site map ⊠ No vandalism evident Remarks
2.	Land use changes on site Remarks Additional well (oil/gas) has been drilled (on adjacent property)
3.	Land use changes offsite Ø N/A Remarks Oil and gas production plant was being installed at the entrance to the fenced property (approximately 200 feet east, down Clear Lake Road adjacent to the HAP site)

	VI. GENERAL SITE CONDITIONS						
A.	Roads 🛛 Applic	able	N/A				
1.	Roads damaged Location Remarks	shown on site map	⊠	Roads ade	quate	e 🗆 N/A	
В.	Other Site Conditions						
	Remarks High vegetation coveri (fenced enclosures)	ing site and growing	inside w	<u>ell cluster co</u>		ounds	
	VII. LANDFILL COVER	LS		Applicable		⊠ N/A	
A.	Landfill Surface (Site Cover O	nly)					
1.	Settlement (Low spots)	□ Location shown	1 on site	map	⊠ evia	Settlement not	
	Areal extent Remarks	Depth					
2.	Cracks Lengths Remarks	□ Location shown Widths	1 on site	тар		Cracking not evident Depths	
3.	Erosion Areal extent Remarks	Location shown Depth	on site	map 		Erosion not evident	
4.	Holes Areal extent Remarks	Location shown Depth	1 on site	map —		Holes not evident	
5.	Vegetative Cover ⊠ Grass □ Trees/Shrubs (indicate size an Remarks_The ground cover nee	Cover properly nd locations on a dia ds to be cut.	y establis gram)	shed		No signs of stress	
6.	Alternative Cover (armored roo Remarks <u>Access road in good c</u>	ck, concrete, etc.)		I/A			

7.	Bulges Areal extent Remarks	□ Location shown on site map ⊠ Bulges not evident Depth
8.	Wet Areas/Water Damage Uet areas Ponding Seeps Soft subgrade Remarks	 Wet areas/water damage not evident Location shown on site map Areal extent
9.	Slope Instability Slides Areal extent Remarks	□ Location shown on site map ⊠ No evidence of slope
В.	Benches Applicat (Horizontally constructed mount the slope in order to slow runoff to a lined channel.)	ble IMA Inds of earth placed across a steep landfill side slope to interrupt or down the velocity of surface runoff and intercept and convey the
1.	Flows Bypass Bench Remarks	□ Location shown on site map ⊠ N/A □ Okay
2.	Bench Breached Remarks	□ Location shown on site map ⊠ N/A □ Okay
3.	Bench Overtopped Remarks	□ Location shown on site map ⊠ N/A □ Okay
C.	Letdown Channels	pplicable 🛛 N/A
1.	Settlement La Areal extent Remarks	Depth
2.	Material Degradation 🛛 La Material type Remarks	Occation shown on site map No evidence of degradation Areal extent

3.	Erosion Areal extent Remarks	□ Location shown on site map □ No evidence of erosion Depth					
4.	Undercutting Areal extent Remarks	Location shown of Depth	on site map				
5.	Obstructions Location shown on site map Size Remarks	Type Areal extent	No obstructions				
6.	Excessive Vegetative Growth No evidence of excessive gro Vegetation in channels does Location shown on site map Remarks	Type owth not obstruct flow Areal extent					
D.	Cover Penetrations	□ Applicable	⊠ N/A				
1.	Gas Vents Properly secured/locked Evidence of leakage at penetr Remarks 	□ Active □ Functioning ration	 Passive Routinely sampled Good condition Needs O&M N/A 				
2.	Gas Monitoring Probes Properly secured/locked Evidence of leakage at penetr Remarks 	Functioning ration	 Routinely sampled Good condition Needs O&M N/A 				
3.	Monitoring Wells (within surface) Properly secured/locked	ce area of landfill)	□ Routinely sampled □ Good				

4.	Leachate Extraction Wells Properly secured/locked Evidence of leakage at pener Remarks	L tratio	Functioning		outinely sample eds O&M	ed Good condition N/A
5.	Settlement Monuments Remarks			utinely s	urveyed	□ N/A
E.	Gas Collection and Treatment	t 🗆	Applicable Ø N/A	4		
1.	Gas Treatment Facilities Flaring Good condition Remarks		Thermal destruction Needs O&M	ac		ion for reuse
2.	Gas Collection Wells, Manifol Good condition Remarks	ds, a	and Piping Needs O&M		·····	
3.	Gas Monitoring Facilities (e.g Good condition Remarks	., ga	s monitoring of adj Needs O&M	acent hor	mes or building □ N/A	gs)
F.	Cover Drainage Layer		Applicable		⊠ N/A	
1.	Outlet Pipes Inspected Remarks		Functioning			□ N/A
2.	Outlet Rock Inspected Remarks		Functioning		□ N/A	
G.	Detention/Sedimentation Pone	ds	Applicable		⊠ N/A	
1.	Siltation Areal extent Siltation not evident Remarks			Depth _		0
2.	Erosion Areal extent Erosion not evident Remarks			Depth _		

3.	Outlet Works Remarks	Functioning		N/A
4.	Dam Remarks	Functioning		N/A
Н.	Retaining Walls	Applicable	⊠ N/A	L
1.	Deformations Horizontal displacement Rotational displacement Remarks	Location shown on Vertica	site map 1 displacer	Deformation not evident nent
2.	Degradation Remarks	□ Location shown on	site map	Degradation not evident
I.	Perimeter Ditches/Off-Site D	Discharge Applicable	⊠ N/A	
1.	Siltation Areal extent Remarks	Location shown on Depth	site map	□ Siltation not evident
2.	Vegetative Growth Uegetation does not impeded Areal extent Remarks	Location shown on e flow Type	site map	□ N/A
3.	Erosion Areal extent Remarks	Location shown on Depth	site map	Erosion not evident
4.	Discharge Structure Remarks	Functioning		□ N/A
	VIII. VERTICAL	BARRIER WALLS	🗆 Арр	licable 🛛 N/A
1.	Settlement Areal extent Remarks	 Location shown on Depth 	site map	□ Settlement not evident

2.	Performance Monitoring Performance not monitored Frequency Head differential Remarks	Type of monitoring Evidence	e of bro	eaching	
	X. GROUND WATER/SURFACE WATER	REMEDIES		Applicable	□ N/A
А.	Ground Water Extraction Wells, Pumps, an	d Pipelines		Applicable	⊠ N/A
1.	Pumps, Wellhead Plumbing, and Electrical Good condition Remarks	uired wells located		Needs O&M	⊠ N/A
2.	Extraction System Pipelines, Valves, Valve F Good condition INeeds O& Remarks N/A	Soxes, and Other Aj M	ppurte	папсез	
3.	Spare Parts and Equipment Readily available Good condition Remarks N/A	□ Requires upgrad	le	D Needs provided	to be
В.	Surface Water Collection Structures, Pumps	s, and Pipelines [] Арр	licable	⊠ N/A
1.	Collection Structures, Pumps, and Electrical Good condition I Needs O&M Remarks				
2.	Surface Water Collection System Pipelines, '	Valves, Valve Boxes	, and (Other Appurt	епапсез
3.	Spare Parts and Equipment Readily available Good condition Remarks	□ Requires upgrad	le 	D Needs provided	to be
C.	Treatment System Applicable	; 🛛 N/A			

.

1.	Treatment Train (Check components that apply) Bioremediation Metals removal Oil/water separation Bioremediation Air stripping Carbon adsorbers Bioremediation Filters
ļ	
2.	Electrical Enclosures and Panels (Properly rated and functional) N/A Good condition Remarks
3.	Tanks, Vaults, Storage Vessels N/A Good condition Proper secondary containment Needs O&M Remarks
4.	Discharge Structure and Appurtenances N/A Good condition Remarks
5.	Treatment Building(s) C N/A Good condition (esp. roof and doorways) C hemicals and equipment properly stored Remarks
6.	Monitoring Wells (Pump and treatment remedy) Properly secured/locked Functioning Routinely sampled Good condition
÷	All required wells located Needs O&M N/A Remarks
D.	Monitored Natural Attenuation
1.	Monitoring Wells (Natural attenuation remedy) □ Properly secured/locked □ Functioning □ Routinely sampled □ Good condition □ All required wells located ⊠ Needs O&M □ N/A Remarks
	X. OTHER REMEDIES

If there are remedies applied at the site which are not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.

XI. OVERALL OBSERVATIONS

A. Implementation of the Remedy

Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is to accomplish (i.e., to contain contaminant plume, minimize infiltration and gas emission, etc.).

No Action. Ground Water Record of Decision

B. Adequacy of O&M

Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy.

O&M has not been initiated. O&M plan is in progress by TNRCC contractor.

C. Early Indicators of Potential Remedy Failure

Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs, that suggest that the protectiveness of the remedy may be compromised in the future.

Could not evaluate.

D. Opportunities for Optimization

Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy.

Could not evaluate.

APPENDIX C

SURVEYS

(Seven Pages)

APPENDIX A

DOCUMENTS REVIEWED

DOCUMENTS REVIEWED

Tetra Tech EM Inc. October 2000. "Operational and Functional Activities Report."

- U.S. Environmental Protection Agency (EPA). June 1984. Record of Decision (ROD) Source Control Operable Unit.
- EPA. June 1987. "Abbreviated ROD Ground Water Operable Unit."
- EPA. August 1988. "CERCLA Compliance with Other Laws Manual."
- EPA. June 1996. "First Five-Year Review, Highlands Acid Pit Superfund Site, Harris County, Texas."
- EPA. October 1999. "Comprehensive Five-Year Guidance." EPA/540R/R-98/050. Office of Emergency and Remedial Response. OSWER Directive 9355.7-03B-P. Washington, DC. Draft.

Woodward-Clyde Consultants (WWC). 1996. "Annual Monitoring Report FY 1996, Highlands Acid Pit Superfund Site, Highlands, Texas."

APPENDIX B

SITE VISIT REPORT

(33 Pages)

SITE VISIT REPORT

HIGHLANDS ACID PIT SUPERFUND SITE HIGHLANDS, HARRIS COUNTY, TEXAS

July 2001

U.S. ENVIRONMENTAL PROTECTION AGENCY 1445 Ross Avenue Dallas, TX 75202-2733

CONTENTS

<u>Sect</u>	ion <u>Page</u>
1.0	INTRODUCTION B-1
2.0	BACKGROUND B-1
3.0	SITE INSPECTION ACTIVITIES
4.0	FINDINGS
<u>Exhib</u>	its
A	PHOTOGRAPHS

•

B SITE INSPECTION CHECKLIST

1.0 INTRODUCTION

The U.S. Environmental Protection Agency (EPA) is hereby conducting a Five-Year Review of the effectiveness of the remedy employed at the Highlands Acid Pit (HAP) site to protect human health and the environment.

A site inspection was conducted as part of the requirements for a Five-Year Review, to verify that all components of the selected remedy are operating in accordance with criteria established in the 1984 Source Control Record of Decision (ROD). This report summarizes the results of the site inspection at the HAP site.

2.0 BACKGROUND

The HAP site was used for the disposal of an unknown quantity of industrial waste sludge, believed to be spent sulfuric acid from a refinery process, during the early 1950s. The HAP site is located in Harris County, 16 miles east of Houston, Texas, and 1.4 miles west of Highlands, Texas, at the end of Clear Lake Road and adjacent to the east side of the San Jacinto River. The site is bordered by a wooded area to the north, flooded sand pits to the east, Clear Lake to the south, and Grennel Slough to the west. The site is a 6-acre peninsula within the 10-year flood plain of the San Jacinto River.

The site lies within the Jessie White Survey A-83 of Harris County, Texas, within the Coast Prairie and East Texas Timberlands. The HAP site lies within Federal/State Census Tract Number 25901 and is within the planning jurisdiction of the Baytown, Texas Planning Commission. The census tract encompasses most of the City of Highlands and adjacent unincorporated areas near the site. There are no known zoning or land use restriction ordinances in effect or planned within the jurisdiction of the Baytown Planning Commission. Little development is foreseen in the site area due to its location within the 100-year flood plain of the

B-1

San Jacinto River. The flow of the San Jacinto River is controlled by the dam at Lake Houston, local meteorology events, and tides.

The selected remedy from the ROD was excavation and off-site disposal. The selected remedy included:

- excavation of waste material to an approximate depth of 8 feet
- transportation of waste to a permitted Class I hazardous waste disposal facility
- backfilling the excavated area with clean fill
- constructing a temporary site perimeter fence with warning signs
- installing a ground water monitoring system
- performing ground water monitoring and site maintenance for a 30-year period

The selected ground water remedy was no action, with a recommendation for monitoring the surface environment (surface water and sediments) and ground water.

3.0 SITE INSPECTION ACTIVITIES

Tetra Tech conducted the site inspection on May 8, 2001. The objective was to assess site conditions for the second Five-Rear Review. Photographic documentation of the site inspection is presented in Exhibit A. The site inspection checklist is presented in Exhibit B.

The following individuals were present during the site visit:

- Mr. Ernest Franke, EPA
- Mr. Jim Feeley, TNRCC
- Mr. Jared Fuqua, Tetra Tech

4.0 FINDINGS

TNRCC is preparing an update for the O&M Manual for the HAP site so that O&M activities can resume. The O&M will include a contingency or emergency response plan, and O&M and Occupational Safety and Health Administration (OSHA) training records. As part of the development of the O&M manual, TNRCC agreed to compile ground water monitoring records and install a project sign for the HAP site.

The fencing and roads were in good condition, and the site locks were in place. High vegetation covered the site, and was growing inside the enclosed well clusters fencing. No recent flooding at the HAP site was apparent. A visual inspection of the monitoring wells noted good conditions with no apparent damage or vandalism.

An oil and gas production plant was installed at the entrance to the adjacent fenced property (approximately 200 feet east on Clear Lake Road) at the time of the inspection. Two wells for the production plant have been drilled.

EXHIBIT B

SITE VISIT CHECKLIST

(13 Pages)

FIVE-YEAR REVIEW SITE INSPECTION CHECKLIST

Information may be completed by hand and attached to the Five-Rear Review report as supporting documentation of site status. "N/A" refers to "not applicable."

I. SITE INFORMATION			
Site Name: Highlands Acid Pit	Date of Inspection: 05/08/01		
Location and Region: Highlands, Texas Region 6	EPAID: 034-FRFF-06ZZ		
Agency, office, or company leading the five-year review: EPA	Weather/temperature: Overcast/windy 85-90 °F		
Remedy Includes: (Check all that apply) Image: Landfill cover/containment Access controls Institutional controls Ground water pump and treatment Surface water collection and treatment Other Ground water monitoring and site maintenance			
Attachments: Inspection team roster attached	☑ Site map attached		
II. INTERVIEWS (Chec	k all that apply)		
1. O&M Site Manager <u>N/A</u> Name	Title Date		
Interviewed: at site at office by phone Problems, suggestions: Report attached	Phone no		
2. O&M Staff Name	Title Date		
Interviewed: at site at office by phone Problems, suggestions: Report attached	Phone no.		

3.	3. Local regulatory authorities and response agencies (i.e.; State and Tribal offices, emergency response office, police department, office of public health or environmental health, zoning office, record of deeds, or other city and county offices, etc.). Fill in all that apply.			
	Agency <u>TNRCC</u> Contact <u>Jim Feeley</u> Name	Project Manager	<u>April 27, 2001</u> Date	<u>(512)239-2462</u> Phone no.
	Problems, suggestions:	Ø Report attached		
	Agency Contact			
	Name Problems, suggestions:	Title Report attached	Date	Phone no.
	Agency			
	Contact Name	Title	Date	Phone no.
	Agency Contact Name	Title	Date	Phone no.
	Problems, suggestions:	Report attached	- <u>-</u>	
4.	Other interviews (option	onal): 🛛 Report attached.		
	Mr. Bubba Crawford, ov	wner of the Baytown Boat Clu	ıb	
	Mr. Jared Fuqua, HAP s	ite contractor and consultant		
	<u> </u>			
_				-

	III. ONSITE DOCUMENTS & RECORDS VERIFIED (Check all that apply)				
1.	O&M Documents Ø O&M manual □ As-built drawings □ Maintenance logs Remarks <u>TNRCC O&M Manual prepar</u>	 Readily available Readily available Readily available ration is in progress 	□ Up to date ⊠ N/A □ Up to date □ N/A □ Up to date □ N/A		
2.	Site-Specific Health and Safety Plan Contingency plan/emergency responses Remarks Both plans should be included	□ Readily available se plan □ Readily available in the O&M Manual	□ Up to date ⊠ N/A □ Up to date ⊠ N/A		
3.	O&M and OSHA Training Records Remarks Should be included in the O&	□ Readily available M Manual	□ Up to date ⊠ N/A		
4.	Permits and Service Agreements Air discharge permit Effluent discharge Waste disposal, POTW Other permits Remarks	 Readily available Readily available Readily available Readily available Readily available 	 □ Up to date ⊠ N/A 		
5.	Gas Generation Records	Readily available	□ Up to date ⊠ N/A		
	Remarks				
6.	Remarks Settlement Monument Records Remarks	Readily available	□ Up to date ⊠ N/A		
6. 7.	Remarks	 Readily available Readily available 	□ Up to date ⊠ N/A □ Up to date⊠ N/A		
6. 7. 8.	Remarks	 Readily available Readily available cords Readily available 	□ Up to date ⊠ N/A □ Up to date⊠ N/A □ Up to date⊠ N/A		
6. 7. 8. 9.	Remarks	 Readily available Readily available Readily available Readily available Readily available Readily available 	□ Up to date ⊠ N/A □ Up to date⊠ N/A □ Up to date⊠ N/A □ Up to date ⊠ N/A □ Up to date ⊠ N/A		

	IV. O&M COSTS					
1.	O&M Organization State in-house PRP in-house Other		 ☑ Contractor for State ☐ Contractor for PRP 			
2.	O&M Cost Records Readily available Funding mechanism Original O&M cost es T	Not Availabl Nagreement in pl timate otal annual cost	e/HAP Not Started Up to date lace by year for review period, if av	reakdown attached vailable		
	From From Date From Date Date Date Date Date	to Date to Date to Date to Date to Date to	Total cost Total cost Total cost Total cost Total cost	 Breakdown attached Breakdown attached Breakdown attached Breakdown attached Breakdown attached Breakdown attached 		
3. V. A.	Unanticipated or United Describe costs and rea	usually High O sons: <u>N/A</u> ITUTIONAL C	&M Costs During Review Po	Applicable D N/A		
1.	Fencing damaged Remarks <u>All locks in p</u>	□ Locatio place	n shown on site map 🛛	Gates secured D N/A		

B.	Other Access Restrictions
1.	Signs and other security measures □ Location shown on site map □ N/A Remarks TNRCC will construct and install □
C.	Institutional Controls
1.	Implementation and enforcement Site conditions imply ICs not properly implemented Implemented Site conditions imply ICs not being fully enforced Implemented Site conditions imply ICs not being fully enforced Implemented Site conditions imply ICs not being fully enforced Implemented Site conditions imply ICs not being fully enforced Implemented Site conditions imply ICs not being fully enforced Implementer compliance
	Frequency
	Responsible party/agency_TNRCC
	Contact Jim Feeley Project Manager (918) 437-7773
	Name The Date Thone no.
	Reporting is up-to-dateImage: YesNoN/AReports are verified by the lead agencyImage: YesNoN/A
	Specific requirements in deed or decision documents have been met Image: Yes Violations have been reported Image: Yes Other problems or suggestions: Image: Report attached
2.	Adequacy □ ICs are adequate □ ICs are inadequate ⊠ N/A Remarks Monitoring has not been initiated by TNRCC
D.	General
1.	Vandalism/trespassing Location shown on site map No vandalism evident Remarks
2.	Land use changes on site Remarks Additional well (oil/gas) has been drilled (on adjacent property)
3.	Land use changes offsite Ø N/A Remarks Oil and gas production plant was being installed at the entrance to the fenced property (approximately 200 feet east, down Clear Lake Road adjacent to the HAP site)

	VI. GENERAL SITE CONDITIONS					
А.	Roads 🛛 Ap	plicable	□ N/A			
1.	Roads damaged Locat Remarks	tion shown on site n	nap 🛛	Roads ade	quat	e 🗆 N/A
В.	Other Site Conditions					
	Remarks <u>High vegetation co</u> (fenced enclosures)	vering site and grov	ving inside w	vell cluster co	omp	ounds
	VII. LANDFILL COV	/ERS	0	Applicable		⊠ N/A
А.	Landfill Surface (Site Cove	er Only)				
1.	Settlement (Low spots)	□ Location sl	nown on site	map		Settlement not
	Areal extent Remarks	Depth				
	~ -		<u> </u>			
2.	Cracks Lengths Remarks	U Location sl Widths	own on site	map	-	Cracking not evident Depths
	T					
3.	Erosion Areal extent Remarks	Depth	nown on site		ы	Erosion not evident
4.	Holes Areal extent Remarks	Location sh Depth	nown on site	map 	⊠	Holes not evident
<u> </u>						
5.	Vegetative Cover ⊠ Gra ☐ Trees/Shrubs (indicate siz Remarks_The ground cover	ass \Box Cover prozections on a needs to be cut.	perly establi a diagram)	shed		No signs of stress
6.	Alternative Cover (armored Remarks_Access road in goo	l rock, concrete, etc od condition	.) 🗆 N	ί/A		

7.	Bulges Areal extent Remarks	□ Location shown on site map ⊠ Bulges not evident Depth
8.	Wet Areas/Water Damage Uet areas Ponding Seeps Soft subgrade Remarks	 Wet areas/water damage not evident Location shown on site map Areal extent
9.	Slope Instability Slides Areal extent Remarks	□ Location shown on site map ⊠ No evidence of slope
В.	Benches Applica (Horizontally constructed mou the slope in order to slow runoff to a lined channel.)	ble
1.	Flows Bypass Bench Remarks	□ Location shown on site map ⊠ N/A □ Okay
2.	Bench Breached Remarks	□ Location shown on site map
3.	Bench Overtopped Remarks	□ Location shown on site map ⊠ N/A □ Okay
C.	Letdown Channels A	pplicable 🛛 N/A
1.	Settlement I Areal extent Remarks	ocation shown on site map No evidence of settlement Depth
2.	Material Degradation Material type Remarks	ocation shown on site map No evidence of degradation Areal extent

3.	Erosion Areal extent Remarks	Location shown of Depth	on site map
4.	Undercutting Areal extent Remarks	Location shown of Depth	on site map
5.	Obstructions Location shown on site map Size Remarks	Type Areal extent	No obstructions
6.	Excessive Vegetative Growth No evidence of excessive gro Vegetation in channels does Location shown on site map Remarks	Type owth not obstruct flow Areal extent	
D.	Cover Penetrations		⊠ N/A
1.	Gas Vents Properly secured/locked Evidence of leakage at penetr Remarks 	□ Active □ Functioning ration	 Passive Routinely sampled Good condition Needs O&M N/A
<u> </u>			
2.	Gas Monitoring Probes Properly secured/locked	□ Functioning	□ Routinely sampled □ Good
	Evidence of leakage at penetr	ration	condition
3.	Monitoring Wells (within surface Properly secured/locked Evidence of leakage at penetre Properly secured/locked	ce area of landfill) □ Functioning ration	 Routinely sampled Good condition Needs O&M N/A

4.	Leachate Extraction Wells Properly secured/locked Evidence of leakage at pene Remarks	□ Functioning □ Routinely sampled □ Good condition tration □ Needs O&M □ N/A
5.	Settlement Monuments Remarks	□ Located □ Routinely surveyed □ N/A
Е.	Gas Collection and Treatmen	t 🗆 Applicable 🛛 N/A
1.	Gas Treatment Facilities Flaring Good condition Remarks	 ☐ Thermal destruction ☐ Collection for reuse ☐ Needs O&M
2.	Gas Collection Wells, Manifol	ds, and Piping
3.	Gas Monitoring Facilities (e.g Good condition Remarks	., gas monitoring of adjacent homes or buildings) Needs O&M N/A
F.	Cover Drainage Layer	□ Applicable ⊠ N/A
1.	Outlet Pipes Inspected Remarks	Functioning N/A
2.	Outlet Rock Inspected Remarks	□ Functioning □ N/A
G.	Detention/Sedimentation Pon	ds □ Applicable ⊠ N/A
1.	Siltation Areal extent Siltation not evident Remarks	Depth □
2.	Erosion Areal extent	Depth

3.	Outlet Works Remarks	□ Functioning □ N/A
4.	Dam Remarks	□ Functioning □ N/A
Н.	Retaining Walls	□ Applicable ⊠ N/A
1.	Deformations Horizontal displacement Rotational displacement Remarks	Location shown on site map Deformation not evident Vertical displacement
2.	Degradation Remarks	□ Location shown on site map □ Degradation not evident
I.	Perimeter Ditches/Off-Site Di	scharge 🗌 Applicable 🛛 N/A
1.	Siltation Areal extent Remarks	Location shown on site map Siltation not evident Depth
2.	Vegetative Growth Uegetation does not impede Areal extent Remarks	Location shown on site map N/A flow Type
3.	Erosion Areal extent Remarks	Location shown on site map Erosion not evident Depth
4.	Discharge Structure Remarks	Functioning N/A
	VIII. VERTICAL	BARRIER WALLS
1.	Settlement Areal extent Remarks	 Location shown on site map Depth

2.	Performance Monitoring Performance not monitored Frequency Head differential Remarks	Type of monitoring				
I	IX. GROUND WATER/SURFACE WATER REMEDIES Applicable D N/A					
А.	Ground Water Extraction Wells, Pumps, and Pipelines			Applicable	⊠ N/A	
1.	Pumps, Wellhead Plumbing, and Electrical Good condition All red Remarks	quired wells located		Needs O&M	⊠ N/A	
2.	Extraction System Pipelines, Valves, Valve Boxes, and Other Appurtenances □ Good condition □ Needs O&M Remarks N/A					
3.	pare Parts and Equipment Readily available Good condition Requires upgrade Provided Remarks N/A				to be	
В.	Surface Water Collection Structures, Pumps, and Pipelines Applicable N/A					
1.	Collection Structures, Pumps, and Electrical Good condition Needs O&M Remarks					
2.	Surface Water Collection System Pipelines, Valves, Valve Boxes, and Other Appurtenances Good condition Needs O&M Remarks					
3.	Spare Parts and Equipment Readily available Good condition Remarks					
C.	Treatment System	le 🛛 N/A				
1.	Treatment Train (Check components that apply) Metals removal Oil/water separation Bioremediation Air stripping Carbon adsorbers Filters					
----	---					
2.	Electrical Enclosures and Panels (Properly rated and functional) N/A Good condition Remarks					
3.	Tanks, Vaults, Storage Vessels N/A Good condition Proper secondary containment Needs O&M Remarks					
4.	Discharge Structure and Appurtenances N/A Good condition Remarks					
5.	Treatment Building(s) C N/A Good condition (esp. roof and doorways) Needs repair C hemicals and equipment properly stored Remarks					
6.	Monitoring Wells (Pump and treatment remedy) Properly secured/locked Functioning Routinely sampled Good condition					
	All required wells located Needs O&M N/A Remarks					
D.	Monitored Natural Attenuation					
1.	Monitoring Wells (Natural attenuation remedy) Properly secured/locked Functioning All required wells located Needs O&M N/A					
	X. OTHER REMEDIES					

If there are remedies applied at the site which are not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction.

XI. OVERALL OBSERVATIONS

A. Implementation of the Remedy

Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is to accomplish (i.e., to contain contaminant plume, minimize infiltration and gas emission, etc.).

No Action. Ground Water Record of Decision

B. Adequacy of O&M

Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy.

O&M has not been initiated. O&M plan is in progress by TNRCC contractor.

C. Early Indicators of Potential Remedy Failure

Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs, that suggest that the protectiveness of the remedy may be compromised in the future.

Could not evaluate.

D. Opportunities for Optimization

Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy.

Could not evaluate.

APPENDIX C

SURVEYS

(Seven Pages)

HIGHLANDS ACID PIT SITE SURVEY			
Site Name: Highlands Acid Pit Sit	te	EPA Work Assignment No.: 034-FRFE-06ZZ	
Subject: Five-Year Review Backg Information Survey	round	Dund Date: 04/17/01	
	Contact	Made By:	
Name: Ernest Franke	Title: Work Assignment Project Manager		Organization: EPA
Telephone No.: (214) 665-8521 E-Mail: franke.ernest@epamail.epa.gov	Street Address: U.S. EPA 1455 Ross Avenue, Suite 1200 City, State, Zip: Dallas, Texas 75202		
Name: Tim Startz	Title: Project Manager		Organization: Tetra Tech EM Inc.
Telephone No.: (214) 740-2064 E-Mail: startzt@ttemi.com	Street Address: 350 N. St. Paul, Suite 2600 City, State, Zip: Dallas, Texas 75201		
	Individua	l Contacted:	
Name: Bubba Crawford	Title: Owner, Baytown Boat Club		Organization:
Telephone No.:	Street Address: City, State, Zip:		
E-Mail Address:	Signature:		
	Survey (Questions	
Please return your survey in the enclosed envelope to Tim Startz by May 1, 2001.			
 What is your overall impression of the project (general sentiment)? Response: Acceptable 			
. What effect have site operations had on the surrounding community?			
Response: Cleaned area			

HIGHLANDS ACID PIT SITE SURVEY			
Site Name: Highlands Acid Pit Site EPA Work Assignment No.: 034-FRFE-06ZZ			
Subject: Five-Year Review Background InfoDate: 04/27/01Survey			
	Survey Questi	ons (Cont.)	
3.	. Are you aware of any community concerns regarding the site or its operation and administration? If so, please give details.		
	Response: None		
4.	Are you aware of any events, incidents, or activities at the site such as dumping, vandalism, trespassing, or emergency responses from local authorities? If so, please give details.		
	Response: None		
5.	Do you feel well informed about the site's acti	ivities and progress?	
	Response: Yes		
6.	Do you have any comments, suggestions, or re or operation?	commendations regarding the site's management	
	Response: None		
	•		

Page 2 of 2

HIGH	ILANDS ACID PI	T SITE SU	JRVEY
Site Name: Highland Acid Pit Sit	e	EPA Work Assignment No.: 034-FRFE- 06ZZ	
Subject: Five-Year Review Opera Maintenance Survey	ation and	Date: 04/27/01	
	Contact Ma	de By:	
Name: Ernest Franke	Title: Work Assignt Manager	ment	Organization: EPA
'elephone No.: (214) 665-8521Street Address: U.S. EPA 1455 Ross Avenue, Suite 1200C-Mail: ranke.ernest@epamail.epa.govCity, State, Zip: Dallas, Texas 75202			
Name: Tim Startz	Title: Project Manager		Organization: Tetra Tech EM Inc.
Telephone No.: (214) 740-2064 E-Mail: startzt@ttemi.com	Street Address: 350 N. St. Paul, Suite 2600 City, State, Zip: Dallas, Texas 75201		
	Individual Co	ntacted:	
Name: Jim Feeley	Title: Project Manager		Organrization: Texas Natural Resource Conservation Commission
Telephone No.: (512)239-2462	Street Address: P. O. Box 13087 City, State, Zip: Austin, TX 78711-3087		
E-Mail Address: jfeeley@tnrcc.state.tx.us	Signature:		
	Survey Que	stions	

Please return your survey to Tim Startz by May 1, 2001.

1. What is your impression of the project (general sentiment)?

Surface conditions at the site are stable and generally reflect the conditions established in source control ROD. The conditions in the ground water require further study.

2. Has your office conducted routine communications or activities (site visits, inspections, reporting activities, etc.) regarding the site? If so, please give purpose and results.

The TNRCC has been actively involved as support agency to EPA in conducting the Operational and Functional (O&F) study of ground water at the site. This has involved report review, meetings, site visits, and other activities. With the completion of the O&F study, TNRCC is resuming the role of lead agency for post closure Operation and Maintenance (O&M).

Page 1 of 2

HIGHLANDS ACID PIT SITE SURVEY			
Site Name: Highlands Acid Pit Site EPA Work Assignment No.: 034-FRFE-06ZZ			
Subje	ect: Five-Year Review Operation and Maintenance Survey	Date: 04/27/01	
	Survey Questi	ions (Cont.)	
3.	Have there been any complaints, violations, or other incidents related to the site requiring a response by your office? If so, please give details of the events and results of the responses.		
	Not in the last five years.		
4.	Do you feel well informed about the site's activ	vities and progress?	
	Yes. As a participant in the O&F study, the TNRCC has had access to all reports and activities. However, determining the actual conditions at the site regarding the middle and deep ground water will require further study.		
5.	 Have there been any changes in State laws and regulations that may impact the protectiveness of the ground water or soil remedies? 		
	While there have been significant changes in State laws and regulations, in particular the promulgation of the Texas Risk Reduction Program rules, these rules would not come into play unless the Record of Decision were to be reopened.		
6.	Has the site been in compliance with permitting	g and reporting requirements?	
	NA.		
7.	Do you have any comments, suggestions, or reconstruction?	commendations regarding the site's management or	
	At this point, it appears there is a cross-contam nested wells completed in the middle and deep wells need to be removed and planning is unde further monitoring is required to determine the TNRCC is revising the O&M plan and will the	ination problem with one or possibly both of two zones. Both EPA and TNRCC agree these rway to do so. It is the TNRCC's belief that actual conditions in the middle and lower zones. In contract for monitoring services.	

Page 2 of 2

HIGHLANDS ACID PIT SITE SURVEY				
Site Name: Highland Acid Pit Sit	e	EPA Work Assignment No.: 034-FRFE- 06ZZ		
Subject: Five-Year Review Opera Maintenance Survey	ntion and	ion and Date: 05/08/01		
	Contact Mac	de By:		
Name: Ernest FrankeTitle: Work Mana		ment	Organization: EPA	
Telephone No.: (214) 665-8521 E-Mail: franke.ernest@epamail.epa.gov	Street Address: U.S. EPA 1455 Ross Avenue, Suite 1200 City, State, Zip: Dallas, Texas 75202			
Name: Tim Startz	Title: Project Manager		Organization: Tetra Tech EM Inc.	
Telephone No.: (214) 740-2064 E-Mail: startzt@ttemi.com	Street Address: 350 N. St. Paul, Suite 2600 City, State, Zip: Dallas, Texas 75201			
	Individual Co	ntacted:		
Name: Jared Fuqua	Title: Project Manager		Organization: Tetra Tech EM Inc.	
Telephone No.: (214)740-2053	Street Address: 350 N. St. Paul Street, Suite 2600 City, State, Zip: Dallas, TX 75201			
E-Mail Address: fuquaj@ttemi.com	Signature:			
	Survey Questions			
Please ret	urn your survey to Tir	n Startz by M	lay 1, 2001.	
1. What is your impression of	1. What is your impression of the project (general sentiment)?			
The project was successful in determining ground water flow direction and the acquisition of monitoring data for evaluation.				
2. Has your office conducted routine communications or activities (site visits, inspections, reporting activities, etc.) regarding the site? If so, please give purpose and results.				
Historical site activities included installing additional ground water monitor wells. Performed eight quarters of monitoring, completed a tidal study and aquifer testing. Activities were summarized in the Operational and Functional Activities Report.				

HIGHLANDS ACID PIT SITE SURVEY			
Site I	Site Name: Highlands Acid Pit Site EPA Work Assignment No.: 034-FRFE-06Z2		
Subject: Five-Year Review Operation and Maintenance Survey		Date: 05/08/01	
	Survey Q	uestions (Cont.)	
3.	3. Have there been any complaints, violations, or other incidents related to the site requiring a response by your office? If so, please give details of the events and results of the responses.		
	No.		
4.	activities and progress?		
	Yes.		
5.	and regulations that may impact the protectiveness of		
	Pre-SARA ROD.		
6.	Has the site been in compliance with perm	itting and reporting requirements?	
	Yes.		
7.	Do you have any comments, suggestions, operation?	or recommendations regarding the site's management or	
	Initiate O&M activities.		
		Page 1 of 1	

•