

the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2007-19-04 Airbus: Amendment 39-15194. Docket No. FAA-2007-28372; Directorate Identifier 2007-NM-080-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective October 23, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Airbus Model A300F4-605R and A300F4-622R airplanes; certificated in any category; all serial numbers; on which Airbus Modifications 12088 and 12403 have been embodied during production, or which incorporated Airbus Service Bulletin A300-32-6085 in service, except airplanes on which Airbus Modification 12618 has been embodied during production, or which incorporated Airbus Service Bulletin A300-32-6100 in service.

Subject

(d) Air Transport Association (ATA) of America Code 32: Landing Gear.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: Further to cases of parking brake loss at the gate, a pressure switch system had been introduced on some A300-600 aircraft. The aim of this modification was to recover pedals braking authority if parking brake is not efficient, without having to set the parking brake handle to OFF.

However, it appears that in case of failure of the pressure switch system, there is the risk of double (normal and alternate) pressurization of the brakes potentially leading to undetected residual braking, which may lead to a loss of performances of the aircraft at Take-Off.

This new AD requires accomplishment of a wiring modification that will inhibit the effect of modifications 12088 and 12403. The loss of performance could result in runway overrun or impact with obstacles or terrain during takeoff.

Actions and Compliance

(f) Within 3 months after the effective date of this AD unless already done: Modify the wiring in the right electronics rack 90VU (volt unit), in accordance with the instructions of Airbus Service Bulletin A300-32-6100, dated September 18, 2006.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2007-0068, dated March 14, 2007; and Airbus Service Bulletin A300-32-6100, dated September 18, 2006; for related information.

Material Incorporated by Reference

(i) You must use Airbus Service Bulletin A300-32-6100, dated September 18, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 31, 2007.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-18050 Filed 9-17-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28308; Directorate Identifier 2007-NM-016-AD; Amendment 39-15195; AD 2007-19-05]

RIN 2120-AA64

Airworthiness Directives; Hawker Beechcraft Model 400, 400A, and 400T Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Hawker Beechcraft Model 400, 400A, and 400T series airplanes. This AD requires modifying the attachment fasteners on the engine cowling panels. This AD results from several reports of loose attachment fasteners found on the engine cowling panels, and subsequently the panels either peeling back or separating from the airplane during flight. We are issuing this AD to prevent failure of the attachment fasteners on the engine cowling panels, which could result in separation of a panel from the airplane, and consequent damage to airplane structure. These conditions could adversely affect continued safe flight and landing of the airplane, or cause injury to people or damage to property on the ground.

DATES: This AD becomes effective October 23, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of October 23, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

Contact Hawker Beechcraft Corporation, 9709 East Central, Wichita, Kansas 67206, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: William Griffith, Aerospace Engineer,

Airframe and Services Branch, ACE-118W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4116; fax (316) 946-4107.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located on the ground floor of the West Building at the DOT street address stated in the ADDRESSES section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Raytheon (Beech) Model 400, 400A, and 400T series airplanes. That NPRM was published in the **Federal Register** on May 29, 2007 (72 FR 29446). That NPRM proposed to require modifying the attachment fasteners on the engine cowling panels.

Comments

We provided the public the opportunity to participate in the development of this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Explanation of Change to Applicability

We have revised the applicability of the existing AD to match the most recent type certificate data sheet for the affected models.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD with the change described previously. We have determined that this change will neither increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

There are about 757 airplanes of the affected design in the worldwide fleet. This AD affects about 575 airplanes of U.S. registry. The required actions take about 10 work hours per airplane, at an average labor rate of \$80 per work hour. Required parts cost about \$400 per airplane. Based on these figures, the estimated cost of this AD for U.S. operators is \$690,000, or \$1,200 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the ADDRESSES section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2007-19-05 Hawker Beechcraft Corporation (Formerly Raytheon Aircraft Company): Amendment 39-15195. Docket No. FAA-2007-28308; Directorate Identifier 2007-NM-016-AD.

Effective Date

(a) This AD becomes effective October 23, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Hawker Beechcraft Model 400, 400A, and 400T series airplanes, certificated in any category; as identified in Raytheon Service Bulletin SB 54-3788, dated December 2006.

Unsafe Condition

(d) This AD results from several reports of loose attachment fasteners found on the engine cowling panels, and subsequently the panels either peeling back or separating from the airplane during flight. We are issuing this AD to prevent failure of the attachment fasteners on the engine cowling panels, which could result in separation of a panel from the airplane, and consequent damage to airplane structure. These conditions could adversely affect continued safe flight and landing of the airplane, or cause injury to people or damage to property on the ground.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Modification

(f) Within 200 flight hours after the effective date of this AD: Modify the attachment fasteners on the engine cowling panels by doing all the actions in accordance with the Accomplishment Instructions of Raytheon Service Bulletin SB 54-3788, dated December 2006.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Wichita Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(h) You must use Raytheon Service Bulletin SB 54-3788, dated December 2006,

to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Hawker Beechcraft Corporation, 9709 East Central, Wichita, Kansas 67206, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 31, 2007.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-18048 Filed 9-17-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-25239; Directorate Identifier 2006-NE-23-AD; Amendment 39-15196; AD 2007-19-06]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Aircraft Engine Group (GEAE) CF6-45A Series, CF6-50A, CF6-50C Series and CF6-50E Series Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for GEAE CF6-45A, -45A2, -50A, -50C, -50CA, -50C1, -50C2, -50C2B, -50C2D, -50C2F, -50C2R, -50E, -50E1, -50E2, and -50E2B turbofan engines. This AD requires replacing the compressor discharge pressure (CDP) restoring spring assembly on certain main engine controls (MECs) or re-marking MECs that already incorporate GEAE Service Bulletin (SB) No. CF6-50 S/B 73-0119, dated March 21, 2005. This AD results from reports of five events involving fractured CDP restoring spring assemblies. We are issuing this AD to prevent loss of engine thrust control that could lead to loss of control of the airplane.

DATES: This AD becomes effective October 23, 2007. The Director of the Federal Register approved the incorporation by reference of certain

publications listed in the regulations as of October 23, 2007.

ADDRESSES: You can get the service information identified in this AD from General Electric Company via GE-Aviation, Attn: Distributions, 111 Merchant St., Room 230, Cincinnati, Ohio 45246; telephone (513) 552-3272; fax (513) 552-3329.

The Docket Operations office is located at U.S. Department of Transportation, Docket Operations, M-30, West Building, Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tara Chaidez, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; telephone (781) 238-7773; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR part 39 with a proposed AD. The proposed AD applies to GEAE CF6-45A, -45A2, -50A, -50C, -50CA, -50C1, -50C2, -50C2B, -50C2D, -50C2F, -50C2R, -50E, -50E1, -50E2, and -50E2B turbofan engines. We published the proposed AD in the *Federal Register* on May 31, 2007 (74 FR 30300). That action proposed to require replacing the CDP restoring spring assembly on certain MECs and re-marking MECs that already incorporate GEAE SB No. CF6-50 S/B 73-0119, dated March 21, 2005 or GEAE SB No. CF6-50 S/B 73-0119, Revision 01, dated May 26, 2006.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is provided in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received. The commenters support the proposal.

Conclusion

We have carefully reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

We estimate that this proposed AD would affect 756 GEAE CF6-45A, -50C, and -50E series turbofan engines installed on airplanes of U.S. registry. We also estimate that it would take about 40 work-hours per engine to perform the proposed actions, and that the average labor rate is \$80 per work-hour. Required parts would cost about \$1,787 per engine. Based on these figures, we estimate the total cost of the proposed AD to U.S. operators to be \$3,770,172.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary at the address listed under **ADDRESSES**.