

In 2005 a lateral runway excursion occurred on an A320 aircraft. Such excursions are classified as hazardous, with a large reduction in safety margins. Investigation has shown that the aircraft landed with the nose wheels rotated nearly 20 degrees from center. During subsequent tests on the removed BSCU [Braking and Steering Control Unit], a BSCU hardware failure was found, affecting the monitoring function, including the system reconfiguration management, and leading to a runaway of [the] Nose Wheel Steering [uncommanded steering].

DGAC [Direction Générale de l'Aviation Civile] Airworthiness Directive (AD) F-1992-117-025(B), Revision 1 [which corresponds to FAA AD 94-24-07], mandated the BSCU upgrade in order to improve the steering logic, but this modification has shown not to be sufficient to address the identified failure mechanism.

A software modification is now implemented in BSCU standard 10 which improves the system reconfiguration management when this failure mechanism is detected.

BSCU standard 10 also includes other improvements—as detailed in the associated Service Bulletin.

This AD therefore mandates the modification or replacement of the BSCU standard 7, 9 or 9.1, by the BSCU standard 10.

This AD also requires replacement of certain DUNLOP tires that are not compatible with BSCU standard 10. An uncommanded steering condition during takeoff or landing could result in departure of the airplane from the runway.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 18 months after the effective date of this AD: Modify or replace the BSCU in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A320-32-1336, Revision 01, dated January 10, 2008; and inspect the airplane to determine if DUNLOP tires 46x16-20 having part number (P/N) 11659 T or 11661 T are installed. If those tires are installed, before further flight, replace with acceptable tires using a method approved by either the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA) (or its delegated agent). Accomplishment of the applicable requirements in this paragraph terminates the requirements of AD 94-24-07, amendment 39-9080.

(2) Previous accomplishment of the modification or replacement of the BSCU before the effective date of this AD in accordance with Airbus Mandatory Service Bulletin A320-32-1336, dated September 19, 2007, meets the requirements of paragraph (f)(1) of this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: Although the MCAI and service information do not provide procedures for replacing the tires as specified in paragraph (f)(1) of this AD, this

AD requires that you replace the tires using a method approved by either the Manager, International Branch, ANM-116, FAA, or the EASA (or its delegated agent).

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *Attn:* Tim Dulin, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2141; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI EASA Airworthiness Directive 2008-0048, dated February 28, 2008, and Airbus Mandatory Service Bulletin A320-32-1336, Revision 01, dated January 10, 2008, for related information.

Issued in Renton, Washington, on December 18, 2008.

Stephen P. Boyd,

Assistant Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-30 Filed 1-6-09; 8:45 am]

BILLING CODE 4910-13-P

LIBRARY OF CONGRESS

Copyright Office

37 CFR Part 201

[Docket No. RM 2008-8]

Exemption to Prohibition on Circumvention of Copyright Protection Systems for Access Control Technologies

AGENCY: Copyright Office, Library of Congress.

ACTION: Notice of proposed rulemaking; correction.

SUMMARY: The Copyright Office published in the Federal Register on December 29, 2008, a notice pertaining to its triennial rulemaking proceeding in accordance with a provision of the Copyright Act which was added by the Digital Millennium Copyright Act and which provides that the Librarian of Congress may exempt certain classes of works from the prohibition against circumvention of technological measures that control access to copyrighted works. This document makes technical corrections to clarify the record of the proposed rulemaking.

FOR FURTHER INFORMATION CONTACT: Rob Kasunic, Principal Legal Advisor, Office of the General Counsel, Copyright GC/I&R, P.O. Box 70400, Washington, DC 20024-0400. Telephone (202) 707-8380; telefax (202) 707-8366.

SUPPLEMENTARY INFORMATION: The Copyright Office published in the Federal Register on December 29, 2008, a notice of proposed rulemaking pertaining to the fourth triennial rulemaking proceeding required by § 1201(a)(1)(C) of the Copyright Act. The notice contained a list of the proposed classes of work that the Office will consider for exemption from the prohibition against circumvention of technological measures that control access to copyrighted works. As published, the notice contained errors which could be misleading and/or require clarification.

Correction

In the Federal Register of December 29, 2008, in Docket No. RM 2008-8, make the following corrections:

1. On page 79425, in the third column, in the "ADDRESSES" section, line 12, the website address is corrected to read "<http://www.copyright.gov/1201/comment-forms>".

2. On page 79427, in the first column, paragraph 7 is corrected to read:

"Computer programs" [for forensic analysis]. Proponent: Glenn Pannenberg.

3. On page 79427, in the third column, the third paragraph, line 6, the word "proceeding" is corrected to read "preceding".

Dated: January 2, 2009.

David O. Carson,

General Counsel.

[FR Doc. E9-61 Filed 1-6-09; 8:45 am]

BILLING CODE 1410-30-S